
UNCLASSIFIED

AD NUMBER
AD873490
NEW LIMITATION CHANGE
TO Approved for public release, distribution unlimited
FROM Distribution authorized to U.S. Gov't. agencies and their contractors; Critical Technology; MAY 1970. Other requests shall be referred to Army Missile Command, ATTN: AMSMI-RD, Redstone Arsenal, AL 35898.
AUTHORITY
AMSMI ltr dtd 15 Nov 1972

ITS FILE COPY



REPORT NO. RD-TM-70-3

EXPERIMENTAL INVESTIGATION OF REACTION JETS ON A BODY OF REVOLUTION WITH AND WITHOUT FINS IN SUPERSONIC FLOW

DATA REPORT

by

Troy A. Street

May 1970

SEP 2 1970

This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of this Command, ATTN: AMSMI-RD.



U.S. ARMY MISSILE COMMAND

Redstone Arsenal, Alabama

This Document Contains Missing Page/s That Are Unavailable In The Original Document


OR are
Blank pgs.
that have
Been Romoves

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed. Do not return it to the originator.

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.



EXPERIMENTAL INVESTIGATION OF REACTION JETS ON A BODY OF REVOLUTION WITH AND WITHOUT FINS IN SUPERSONIC FLOW

DATA REPORT

by

Troy A. Street

DA Project No. IM2623xxA206 AMC Management Structure Code No. 522C.11.148

This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of this Command, ATTN: AMSMI-RD.

Advanced Systems Laboratory
Research and Engineering Directorate
U. S. Army Missile Command
Redstone Arsenal, Alabama 35809

Abstract

An experimental investigation of a sonic, underexpanded, transverse jet ejecting from a body of revolution into free streams of Mach number range 1.75 to 4.5 has been conducted. The jet was rolled, in 15-degree increments, into the yaw plane for an angle of attack range of -4 to +10 degrees with a jet total-to-free stream static pressure ratio variations up to 100. Forces and moments were measured and the tabulated data are presented in the appendices.

Contents

	Page
1. 2. 3. 4. Append	
	Mustrations
Table	Page
I II A-I B-·I	Schedule of Selected Photographic Data from Test I
Figure	
1 2 3 A-1	Ballistics Research Laboratory Tunnel No. 1 Test Section
A-2	$M_{\infty} = 1.75$ and Configuration 0.69
A -3	Shadowgraph and Schlierens from Test I, $P_{0j}/P_{\infty} = 10$
A-4	Shadowgraph and Schlierens from Test I, $P_{oj}/P_{\infty} = 20$
A-5	Shadowgraph and Schlierens from Test I, $P_{oj}/P_{\infty} = 4030$
A-6	Shadowgraph and Schlierens from Test I, $P_{oj}/P_{\infty} = 100 \dots 32$
B-1 B-2	Jet Normal Force Coefficient Variation with Pressure Ratio 268 Shadowgraph from Test II, $P_{oj}/P_{\infty} = 10$ 269
B-3	Shadowgraph from Test II, $P_{oj}/P_{\infty} = 15$
B-4	Shadowgraph from Test II, $P_{oj}/P_{\infty} = 20$

Illustrations (Concluded)

rigure	9	
		Page
B-5	Shadowgraph from Test II,	$P_{\text{oj}}/P_{\infty} = 40 \dots 272$
B-6	Shadowgraph from Test II	$0/\infty \qquad \cdots \qquad 272$
B-7	Shadowgraph from Took II	$\begin{array}{c} \text{Oj/}^{2} \otimes & \text{10} & \dots & $
	- B- april 1011 168t II,	$ \begin{array}{c} \text{oj/}^{\infty} & \text{oj.} \\ \text{Poj/}^{\infty} & \text{poj.} \end{array} $ $ \begin{array}{c} \text{273} \\ \text{274} \end{array} $

Symbols

Text	Computer Printout	Definition	Units
b		fin span	in.
c		fin chord	in.
$^{\rm C}_{ m A}$	CAF	Axial force coefficeint	dimensionless
C _{AT}	CAT	Calculated total axial force coefficient	dimensionless
C _e	CR	Rolling moment coefficient	dimensionless
C _m	CM	Pitching moment coefficient	dimensionless
$c_N^{}$	CN	Normal force coefficient	dimensionless
C _n	CY	Yawing moment coefficient	dimensionless
$^{c}_{p_{b}}$	СРВ	Base pressure coefficient	dimensionless
Cq		Any aerodynamic coefficient	dimensionless
Cy	CS	Side force coefficient	dimensionless
M_{∞}	MACH	Mach number	dimensionless
Po	PO	Total pressure	cm Hg
P _{oj}	POJ	Jet total pressure	psf
p_{∞}	PTS	Tunnel free stream pressure	psf
X		Distance from model nose	in.
α	ALPHA	Angle of attack	deg
φ	PHI	Angle of roll from the pitch plane clockwise	deg
	RE	Reynolds number	per inch
	Q	Free stream dynamic pressure	psi
	то	Tunnel total temperature	°F

1. Introduction

The results of two experimental investigations of a single transversjet used as a control device on a body of revolution are described. Previously, Spring conducted tests with the jet located in the pitch plane only to determine the effects of the transverse jet on the body aerodynamics. The purpose of these tests was to determine the transverse jet interference effects on missile configuration aerodynamics with the jet rolled into the yaw plane.

The model configurations tested consist of a single slot jet and a single circular jet, both sonic, at one forward jet location on an ogive-cylinder without fins and with three sets of fins located at the model base to determine the fin effectiveness in the jet wake.

The Test I conditions include Mach numbers 1.75, 2.0, 3.0, 4.0, and 4.5. Two angle of attack ranges were tested: -4 to +4 degrees was the primary range while for a few selected model configurations and tunnel conditions the range was -4 to +10 degrees to check interference nonlinearity effects. The jet total-to-free stream static pressure ratios were 0, 10, 20, 40, and 100 while the test Reynolds number was 0.48×10^6 per inch. The model, and consequently the jet, and balance were rolled together from the pitch into the yaw plane in seven 15-degree increments.

The Test II conditions were for Mach numbers 1.75, 2.0, 2.5, 3.0, 3.5. 4.0, and 4.5, angle of attack range from -4 to +4 degrees, pressure ratios of 0, 10, 15, 20, 40, 70, and 100, and single circular jet in the pitch plane. Neither was the model in Test II rolled nor did it contain fins.

From Test I, the data for body alone and body with fins were obtained for both the jet-on and jet-off conditions. Test II was conducted primarily to obtain more accurate jet-alone calibration data, but some repeat conditions of Test I were made for checking purposes. Also some new data were collected on Test II to fill in between data areas not tested in Test I. The data collected from both tests are presented in tabulated coefficients in the appendices along with representative plots of the data.

¹Spring, D. J., "An Experimental Investigation of the Interference Effects due to a Lateral Jet Issuing from a Body of Revolution Over the Mach Number Range of 0.8 to 4.5," U. S. Army Missile Command, Redstone Arsenal, Alabama, Report No. RD-TR-68-10, August 1968.

2. Apparatus

The wind tunnel facility used for both tests was the Ballistics Research Laboratory Wind Tunnel No. 1. This is a continuously operated, variable density, closed circuit, single return wind tunnel with a rectangular test section 15 inches high by 13 inches wide. Figure 1 is a schematic of the tunnel test section. The test section Mach number can be varied from 1.5 to 5.0. A more complete wind tunnel description is given by McMullen. ²

The wind tunnel test conditions were as follows:


Free stream Mach	Tunnel Total Pressure, P (cm Hg)	Tunnel Total Temperature (°F)
4.5	400	90
4.0	321	90
3,5	251	90
3, 0	193	90
2.5	150	90
2.0	118	90
1.75	107	90

The test Reynolds number was 0.48×10^6 per inch. No difficulty was experienced in maintaining these conditions throughout the tests.

The model used was a 4-caliber tangent ogive on a 5-caliber cylindrical afterbody 1.375 inches in diameter. The jet mainly used was 0.11-inch diameter circular jet located 6 inches from the ogive apex and immediately downstream of the ogive-cylinder juncture (Figure 2). For one model configuration a 0.0345-inch longitudinal slot located 6 inches from the ogive apex was used. Both single, sonic jet nozzles exhausted perpendicularly to the model surface.


Each of the three sets of fins was tested in two angular positions relative to the jet center line as shown in the following sketch.

²McMullen, J. C., "Wind Tunnel Testing Facilities at the Ballistic Research Laboratories," Ballistics Research Laboratories, Aberdeen Proving Ground, Maryland, Memorandum Report No. 1292, July 1960.



BALLISTICS RESEARCH LABORATORY TUNNEL NO. 1 TEST SECTION FIGURE 1.

and the second distriction of the second second



NOTES:

- I. All dimensions are in inches, except as noted,
- ë

CIRCULAR

6.250

1.375

CIRCULAR

NO FINS ON THE BODY

JET TYPE

c/p

b, in

c, ii

CONFIGURATION 0.00 <u>.0</u> 1.45 2.00 2.45 3.00 3.45 4.00

CONFIGURATION NOMENCLATURE AND FIN DIMENSIONS

CIRCULAR

CIRCULAR

0.500

CIRCULAR

0.250 0.500

0.342 0.342

> 1,375 1,375 1.375

0.687 0.687 CIRCULAR

0.675 0.675

0.928

1,375

0.928


1.375

CIRCULAR

SLOT

Fin leading edge radius is 0.0135 inches.
All four fins in a set are identical and are oriented at various angles from e = 0 deg.
Two digits after the decimal in the fin number indicates the fin orientation, in degrees, rolative to the jet center line. 4

TEST MODEL SCHEMATIC FIGURE 2.



Jet-fin aligned

Jet interdigitated at 45 degrees between the fins

As the jet was rolled through $0 \le \phi \le 90$ degrees in 15-degree increments, the fins were rolled in like manner to maintain the aforementioned fin-jet relationships. The fin sizes and configuration nomenclature is given in Figure 2.

A photograph of the model with the largest fins is presented in Figure 3.

A six-component internal balance was used to measure the forces and moments on the model. The balance capabilities and accuracies were as follows:

Component	Full Scale	Accuracy, Percent of the Maximum Reading
Normal force	±20 pounds	±1
Pitching moment	±25 inch-pounds	±1
Side force	±10 pounds	±1
Yawing moment	±12.5 inch-pounds	±1
Rolling moment	±10 inch-pounds	±1
Axial forces	+ 20 pounds	±2

The test section Mach number was accurate to $\pm\,0.01$ and the tunnel total pressure was accurate to five millimeters of mercury.

3. Procedure and Results

Experimental evaluation of the interference effects of the jet on a body requires three conditions.

FIGURE 3. PHOTOGRAPH OF THE MODEL MOUNTED IN THE TUNNEL

- a) The body aerodynamic properties measured with the jet on, $\begin{array}{c} C \\ q \\ b+j \end{array}$
- b) The body aerodynamic properties measured without the jet, ${}^{\text{C}}_{q_{\text{b}}}$
- c) The jet force only, $C_{q_{\hat{j}}}$

The aerodynamic interference properties, \mathbf{C}_{q_i} , can then be solved from the equation

$$C_{q_i} = C_{q_{b+j}} - C_{q_b} - C_{q_j}$$
, (1)

where subscript q indicates any of the measured aerodynamic coefficients, C. From the above equation it is apparent that inaccuracies in the measured quantities may appear to be interference contributions caused by the jet-free stream interaction. Therefore, it becomes important to have accurately measured aerodynamic properties.

The jet force was calibrated by pumping down the test section to the pressure that exists at each Mach number and measuring the jet thrust via the strain gage balance. In Test I the above procedure was used with the jet force measured on the 20-pound force gages. The jet force coefficient was nonlinear as a function of jet total pressures. Because of this fact, Test II was initiated in an effort to acquire more accurate jet alone force data. In Test II the model was mounted on the balance with the 10-pound gages and the jet in the pitch plane. This technique produced a very linear jet force coefficient variation with pressure ratio (Figure B-1).

The jet injectant was unheated air supplied from an external source through the sting and across the balance. A base pressure orifice was mounted on the sting and a $\frac{1}{4}$ -inch transition strip was applied an inch from the model ogive apex.

The specific test conditions, model configurations, and run number identification for Tests I and II are presented in Tables A-I and B-I, respectively.

The force and moment tabulated data are presented in Appendix A for Test I and in Appendix B for Table II. The data were reduced to coefficient form by using the body axis system with the origin at the nose. Since the jet was not rolled in Test II, only the normal force, pitching moment and axial force components were reduced.

Sample data are presented in Figure A-1 from Test I for $M_{\infty}=1.75$ without fins for the model rolled to jet angular positions of $\phi=0$, 45, and 90 degrees. Figure B-1 shows the calibrated jet force coefficients for various tunnel-off test section environments that correspond to tunnel static pressures for the tunnel-on case.

In addition to the force and moment data, photographic data were taken. The schedule of selected shadowgraphs and Schlieren prints are presented in Tables I and II for Tests I and II, respectively. The photographic data are presented in Figures A-2 through A-6 for Test I and B-2 through B-7 for Test II.

TABLE I. SCHEDULE OF SELECTED PHOTOGRAPHIC DATA FROM TEST I

Run No.	${ m M}_{\infty}$	Config- uration*	α (deg)	φ (deg)	P _{oj} /P _∞	Shadow- graph No.	Shadow- graph Figure No.	Schlie- ren No.	Schlieren Figure No.
440	4.5	1.00	0 4 -4	0	0	4950	A-2a	A-2b A-2c A-2d	117 118 119
441	4.5	1.00	0 4 -4	0	10	4949	A-3a	A-3b A-3c A-3d	120 121 122
442	4.5	1.00	0 4 -4	0	20	4948	A-4a	A-4b A-4c A-4d	123 124 125
443	4.5	1.00	0 4 -4	0	40	4947	A-5a	A-5b A-5c A-5d	126 127 128
444	4.5	1.00	0 4 -4	0	100	4946	A-6a	A-6b A-6c A-6d	129 130 131

TABLE II. SCHEDULE OF SELECTED SHADOWGRAPHS FROM TEST II

Run No.	M _∞	Configuration*	α (deg)	φ (deg)	P _{oj} /P _∞	Shadowgraph No.	Figure No.
14	2.50	0.00	O	0	10	5180	B-2
15	2.50	0.00	0	0	15	5179	B - 3
16	2.50	0.00	0	0	20	5178	B-4
17	2.50	0.00	9	0	40	5177	B-5
18	2.50	0.00	0	0	70	5176	B-6
19	2,50	0.00	0	0	100	5175	B-7

^{*}Figure 2 gives configuration nomenclature,

4. Conclusion

The data presented are for a wide range of variables in tunnel conditions and model geometry. To the author's knowledge these experiments are the first conducted for a transverse jet as a control device rolled incrementally into the yaw plane. The experimental data, based upon an initial examination, provide a substantial body of data for use in missile preliminary design and also support the verification of existing or newly developed prediction techniques.

Appendix A Data from Test 1

TABLE A-I. SCHEDULE FOR TEST I

Run No.	M _∞	Configuration ¹	α (deg)	φ (deg)	P _{oj} /P _∞
1-5	1.75	1.00	Range α (1) ²	0	Range PR (1)3
6-10	1	1.00		45	
11-15		1.00		90	
16-20		1.45		0	+
21-25	İ	1.45		45	Range PR (1)3
26-29	•	1.45		90	Range PR (2)4
30-34		2.00		0	Range PR (1)
35-39	1	2.00		45	1
40-44		2.00		15	
45-49		2.00		30	
50-54		2.00		60	
55-59		2.00		75	
60-64		2.00		90	
65-69		2.45		0	
70-74		2.45		15	
74-79		2.45		30	
80-84		2.45		45	
85-89		2.45		60	
90-94		2.45		75	
95-99		2.45		90	
100-104		3.00		0	
105-109		3.00		45	
110-114		3.00		90	
115-119		3.45		0	,
120-124		3,45		45	
125-129		3.45		90	
130-134		0.00		0	
135-139	†	0.00	•	15	+
140-144	1.75	0, 00	Range α (1) ²	30	Range PR (1)

¹ Figure 2 gives Configuration Nomenclature

 $^{^2}Range \; \alpha$ (1) is -4, -3, -2, -1.5, -1, -0.5, 0, 0.5, 1, 1.5, 2, 3, and 4 degrees.

³Range PR(1) is for $P_{oj}/P_{\infty} = 0$, 10, 20, 40, and 80.

⁴ Range PR(2) is for $P_{oj}/P_{\infty} = 0$, 10, 20 and 40.

TABLE A-I. SCHEDULE FOR TEST (Continued)

Run No.	${ m M}_{\infty}$	Configuration	დ (deუ)	φ (deg)	P _{oj} /P _∞
145~149	1,75	0.00	Range α (1)	45	Range PR (1)
150-154	1	1	1	60	1
155-159	1			75	
160-164	1.75			90	
165~1.69	2.0			0	
170-174	1			15	
175-179				30	
180-184				45	
185-189				60	
190-194	+		\rightarrow	75	†
194-199	2.0		Range α (1)	90	Range PR (1)
200-204	3.0		Range α (2) ⁵	0	Range PR (3) ⁶
205-209	1		Range α (1)	15	1
210-124			Range α (1)	30	
215-219			Range α (2)	45	
220-224			Range α (1)	60	
225-229	†		Range α (1)	75	
230-234	3.0		Range α (2)	90	
235-239	4.0		Range α (1)	0	
240-244	1		.	15	
245-249				30	
250-254				45	
255-259				50	
260-264				75	
265-269	*			90	
270-274	4.0			60	
275-279	4.5			0	
280-284				15	
285-289				30	
290-294				45	
295-299				60	
300-304	(+	†		75	
305-309	4.5	0.00		90	
310-314	3.0	3.00		0	
315-319	3.0	3.00	Range α (1)	45	Range PR (3)

 $^{^5 \}rm Range ~\alpha$ (2) is -4, -3, -2, -1.5, -1, -0.5, 0, 0.5, 1, 1.5, 2, 3, 4, 5, 6, 7, 8, 9, and 10 degrees.

⁶Range PR (3) is for P_{oj}/P_{∞} = 0, 10, 20, 40, and 100.

TABLE A-I. SCHEDULE FOR TEST I (Concluded)

Run No.	M _∞	Configuration	α (deg)	φ (deg)	P _{oj} /P _∞
320-324	3. 0	3.00	Range α (1)	90	Range PR (3)
325-329	1	2.45		0	ļ
330-334		2.45	ļ	45	
335-339		2.45	Range α (1)	90	Range PR (3)
340-344		2.00	Range α (2)	0	1
345-349			Range α (1)	15	
350-354			Range α (1)	30	
355-359			Range α (2)	45	
360-364				60	
365-369	ŧ		Į.	75	
370-374	3.0		Range α (2)	90	
375-379	4.5		Range α (1)	0	
380-384	1			15	
385-389	ļ			30	
390-394				45	
395-399				60	
400-404		+		75	
405-409		2.00		90	
410-414		2.45		0	
415-419		2.45		45	
420-424		2.45		90	
425-429		3.00		0	
430-434		3.00		45	ļ
435-439		3.00		90	
440-444		1.00		0	
445-449*		1.00		45	
449*-453		1.00		90	
454-458		4.00		0	
459-463	\	4.00		45	
463-468	4.5	4.00	Range α (1)	90	Range PR (3)

^{*}Because of an unavoidable error, two runs were designated as 449.

The conditions under which these two were run, however, will show the poignant differences in the two tests.




FIGURE A-1a. NORMAL FORCE COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1b. PITCHING MOMENT COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1c. SIDE FORCE COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1d. YAWING MOMENT COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1e. ROLLING MOMENT COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1f. TOTAL AXIAL FORCE COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1g. BASE PRESSURE COEFFICIENT VARIATION WITH ANGLE OF ATTACK




FIGURE A-1h. AXIAL FORCE COEFFICIENT VARIATION WITH ANGLE OF ATTACK

FIGURE A-2a. SHADOWGRAPH FROM TEST I, P $_{
m oj}/P_{\infty}=0$



FIGURE A-2b. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty} = 0, \ \alpha = 0 \ \text{DEGREES}$




FIGURE A-2c. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty}=0,\ \alpha=4\ \mathrm{DEGREES}$



FIGURE A-2d. SCHLIEREN FROM TEST I, P $/P_{\infty} = 0$, $\alpha = -4$ DEGREES

FIGURE A-3a. SHADOWGRAPH FROM TEST I, P $_{\rm oj}/{\rm P_{\infty}}=10$




FIGURE A-3b. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty} = 10 \,, \, \alpha = 0 \, \text{DEGREES}$




FIGURE A-3c. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty}=10,~\alpha=4~\mathrm{DEGREES}$



FIGURE A-3d. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty} = 10$, $\alpha = -4$ DEGREES

on the forest of the second of

FIGURE A-4a. SHADOWGRAPH FROM TEST I, $P_{oj}/P_{oc} = 20$



FIGURE A-4b. SCHLIEREN FROM TEST I, $P_{\rm oj}/P_{\infty}=20$, $\alpha=0$ DEGREES



FIGURE A-4c. SCHLIEREN FROM TEST I, P / P $_{\odot} = 20$, $\alpha \approx 4$ DEGREES




FIGURE A-4d. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty}=20$, $\alpha=-4$ DEGREES

FIGURE A-5a. SHADOWGRAPH FROM TEST I, $P_{oj}/P_{\infty} = 40$

Secretary of the secretary secretary and a secretary of the secretary of t




FIGURE A-5b. SCHLIEREN FROM TEST I, $P_{\rm oj}/P_{\infty}=40,~\alpha=0$ DEGREES




FIGURE A-5c. SCHLIEREN FROM TEST I $P_{oj}/P_{\infty} = 40, \, \alpha = 4$ DEGREES




FIGURE A-5d. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty}=46$, $\alpha=-4$ DEGREES

如果,我们是一个时间,我们是一个时间,我们是一个时间,我们是一个时间,我们是一个时间,我们是一个时间,我们是一个时间,我们是一个时间,我们也可以是一个时间,我们

FIGURE A-6a. SHADOWGRAPH FROM TEST I, P /P = 100




FIGURE A-6b. SCHLIEREN FROM TEST I, $P_{oj}/P_{\infty}=100$, $\alpha=0$ DEGREES




FIGURE A-6c. SCHLIEREN FROM TEST I, $P_{\rm oj}/P_{\infty}=100,~\alpha=4~{\rm DEGREES}$



FIGURE A-6d. SCHLIEREN FROM TEST I, P $_{\rm oj}/{\rm P_{\infty}}=100$, $\alpha=-4$ DEGREES

MUDEL 946.2	CONFI	G. 1.000	MA	CH 1.75	;	PHI =	•	
Q= 8.29 PSI	RE PER I	N.= .48E06	T 0≈	90, DE	G.F	POJ/P1	rs =	c
PO= 107.0 CMH	G PTS= 3	.8665 PSI			RUN NO.	019026	9105	
ALPHA CH	CM	CS	CY	CR	CAT	843	CAF	RUN
4.07 0.3205	-2.6128 -		0.0686-					
	-1.8937 -		0.1166-					
	-1.2248 -		0.0909~					
	-0.8790 -		0.0096-					
	-0.5665 - -0.2615 -		0.0647- 0.0489-					
-0.05 -0.0031	-0.2615 - 0.0248 -		0.0469- 0.0778-					
-0.56 -0.0406	0.3213 -		0.0721-					
-1.08 -0.0788	0.6277 -		0.0697-					
-1.60 -0.1170	0.9314 -		0.0737-					
-2.09 -0.1539	1.2302 -	0.0073	0.0476-	0.0001	0.3542	0.1580	0.1962	1.
-3.13 -0.2348	1.8901 -	0.0070	0.0488	0.0006	0.3563	0.1604	0.1959	1.
-4.18 -0.3288	2.6743 -		0.0378					
-4.15 -0.3288	2.6807. ~	0.0103	0.0729	0.0009	0.3600	0.1659	0.1940	1.
MODEL 946.2 G= 8.29 PSI	CONFI	G. 1.000 No= .48E06		CH 1.75		PHI =	• rs =	10.
	RE PER I	N.= .48E06				P0J/P1	rs =	10.
G= 8.29 PSI	RE PER I	N.= .48E06			G•F	P0J/P1	rs =	10. RUN
G= 8.29 PSI PO= 107.0 CMH ALPHA CN	RE PER I G PTS= 3	N.= .48E06 .8665 PSI CS 0.0085	T0= CY 0.0645	90. DE CR 0.9006	G.F RUN NO. CAT G.3690	POJ/P1 019026 CP8	TS = 59106 CAF 0.1978	RUN 2•
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204	RE PER I G PTS= 3 CM -2.5728 - -1.6162 -	No= .48E06 0.8665 PSI CS 0.0085 0.0065	T0= CY 0.0645 0.0445	90. DE CR 0.9006 0.0005	G.F RUN NO. CAT G.3690 O.3638	POJ/P1 019026 CPB 0-1712 0-1657	TS = 59106 CAF 0.1978 0.1981	RUN 2 • 2 •
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376	RE PER I G PTS= 3 CM -2.57281.61621.1341 -	N.= .48E06 0.8665 PSI CS 0.0085 0.0065	TO= CY 0.0645 0.0445 0.0393	90. DE CR 0.9006 0.0005 0.0001	CAT 0.3690 0.3638 0.3585	POJ/P1 019026 CPB 0.1712 0.1657 0.1614	CAF 0.1978 0.1978 0.1971	RUN 2 • 2 • 2 •
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949	RE PER I G PTS = 3 CM -2.57281.61621.13410.7390 -	N.= .48E06 3.8665 PSI CS 0.0085 0.0065 0.0060 0.0088	T0= CY 0.0645 0.0445 0.0393 0.0678	90. DE CR 0.9006 0.0005 0.0001 0.	CAT 0.3690 0.3638 0.3585 0.3566	POJ/P1 019026 CPB 0-1712 0-1657 0-1614 0-1593	S = 59106 CAF 0.1978 0.1981 0.1971 0.1973	RUN 2 • 2 • 2 • 2 •
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554	RE PER I G PTS = 3 CM -2.57281.61621.13410.73900.4692 -	N.= .48E06 3.8665 PSI CS 0.0085 0.0065 0.0060 0.0088	TO= CY 0.0645 0.0445 0.0393 0.0678 0.0801-	90. DE CR 0.9006 0.0005 0.0001 0.	CAT 0.3690 0.3638 0.3585 0.3566 0.3547	POJ/P1 019026 CPB 0-1712 0-1657 0-1614 0-1593 0-1580	CAF 0.1978 0.1981 0.1971 0.1973 0.1966	RUN 2. 2. 2. 2. 2.
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185	RE PER I G PTS = 3 CM -2.57281.61621.13410.73900.46920.1744 -	N.= .48E06 .8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093	TO= CY 0.0645 0.0445 0.0393 0.0678 0.0801- 0.0719-	90. DE CR 0.9006 0.0005 0.0001 0. 0.0004 0.0009	CAT 0.3690 0.3638 0.3585 0.3566 0.3547 0.3526	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1580 0.1565	CAF 0.1978 0.1981 0.1971 0.1973 0.1960	RUN 2. 2. 2. 2. 2.
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177	RE PER I G PTS = 3 CM -2.57281.81621.13410.73900.46920.1744 - 0.1132 -	N.= .48E06 .8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093 0.0086	TO= CY 0.0645 0.0445 0.0393 0.0678 0.0801- 0.0719- 0.0676-	90. DE CR 0.9006 0.0005 0.0001 0. 0.0004 0.0009 0.0005	CAT 0.3690 0.3638 0.3585 0.3566 0.3547 0.3525	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1580 0.1565 0.1562	CAF 0.1978 0.1978 0.1971 0.1973 0.1960 0.1960	RUN 2. 2. 2. 2. 2. 2.
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177 -0.57 -0.0546	RE PER I G PTS = 3 CM -2.57281.81621.13410.73900.46920.1744 - 0.1132 - 0.4052 -	N.= .48E06 .8665 PSI CS .0.0085 .0.0065 .0.0060 .0.0088 .0.0102 .0.0086 .0.0086	TO= CY 0.0645 0.0445 0.0393 0.0678 0.0801- 0.0719- 0.0676- 0.0955-	90. DE CR 0.9006 0.0005 0.0001 0.0004 0.0009 0.0005 0.0012	CAT 0.3690 0.3638 0.3585 0.3566 0.3526 0.3525 0.3525	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1580 0.1565 0.1562 0.1566	CAF 0.1978 0.1978 0.1971 0.1973 0.1960 0.1960	RUN 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 ·
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177 -0.57 -0.0546 -1.09 -0.0934	RE PER I G PTS = 3 CM -2.57281.81621.13410.76900.46920.1744 - 0.1132 - 0.4052 - 0.7150 -	N.= .48E06 .8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093 0.0086 0.0115 0.0143	TO= CY 0.0645 0.0393 0.0678 0.0801- 0.0719- 0.0676- 0.0955- 0.1206-	90. DE CR 0.9006 0.0005 0.0001 0. 0.0004 0.0009 0.0005 0.0012 0.0012	CAT 0.3690 0.3638 0.3585 0.3567 0.3525 0.3525 0.3525	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1585 0.1565 0.1562 0.1566	CAF 0.1978 0.1978 0.1981 0.1973 0.1960 0.1963 0.1966	RUN 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 ·
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177 -0.57 -0.0546 -1.09 -0.0934 -1.60 -0.1336	RE PER I G PTS = 3 CM -2.57281.61621.13410.78900.46920.1744 - 0.1132 - 0.4052 - 0.7150 - 1.0389 -	N.= .48E06 .8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093 0.0086 0.0115 0.0143	T0= CY 0.0645 0.0445 0.0393 0.0678 0.0801- 0.0676- 0.0676- 0.0955- 0.1206- 0.0824-	90. DE CR 0.9006 0.0005 0.0001 0.0009 0.0005 0.0012 0.0010	CAT 0.3690 0.3638 0.3585 0.3566 0.3525 0.3525 0.3526 0.3526	POJ/P1 019026 CP8 0.1712 0.1657 0.1614 0.1593 0.1580 0.1565 0.1566 0.1571 0.1577	CAF 0.1978 0.1981 0.1971 0.J973 0.1966 0.1963 0.1968 0.1964	RUN 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 ·
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177 -0.57 -0.0546 -1.09 -0.0934	RE PER I G PTS = 3 CM -2.57281.61621.13410.73900.46920.1744 0.1132 0.4052 0.7150 1.0389 1.3265	N.= .48E06 0.8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093 0.0086 0.0115 0.0143 0.0094 0.0127	TO= CY 0.0645 0.0393 0.0678 0.0801- 0.0719- 0.0676- 0.0955- 0.1206-	90. DE CR 0.0006 0.0005 0.0001 0.0009 0.0005 0.0012 0.0012 0.0010 0.0010	CAT 0.3690 0.3638 0.3585 0.3566 0.3526 0.3526 0.3526 0.3526 0.3526	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1580 0.1565 0.1562 0.1562 0.1571 0.1577	CAF 0.1978 0.1981 0.1971 0.1966 0.1968 0.1968 0.1969 0.1969	RUN 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 ·
G= 8.29 PSI PO= 107.0 CMH ALPHA CN 4.07 0.3104 3.04 0.2204 2.01 0.1376 1.49 0.0949 0.97 0.0554 0.46 0.0185 -0.06 -0.0177 -0.57 -0.0546 -1.09 -0.0934 -1.60 -0.1336 -2.11 -0.1691	RE PER I G PTS = 3 CM -2.57281.61621.13410.78900.46920.1744 - 0.1132 - 0.4052 - 0.7150 - 1.0389 -	N.= .48E06 3.8665 PSI CS 0.0085 0.0065 0.0060 0.0088 0.0102 0.0093 0.0086 0.0115 0.0143 0.0094 0.0127	T0= CY 0.0645 0.0445 0.0393 0.0678 0.0801- 0.0719- 0.0676- 0.0925- 0.1206- 0.0824- 0.1095-	90. DE CR 0.0006 0.0005 0.0001 0.0009 0.0005 0.0010 0.0010 0.0010	CAT 0.3690 0.3638 0.3585 0.3566 0.3526 0.3525 0.3526 0.3526 0.3526	POJ/P1 019026 CPB 0.1712 0.1657 0.1614 0.1593 0.1585 0.1565 0.1566 0.1577 0.1584 0.1606	CAF 0.1978 0.1971 0.1973 0.1960 0.1963 0.1964 0.1949 0.1941	RUN 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 · 2 ·

MODFL 946.2	CONI	FIG. 1.000	HAC	H 1.75	• 1H9	
Q= 8.29 PSI	KE PER	IN.= .48E0	6 T0=	90. DEG.F	POJ/PTS = 20.	
PO= 107.0 C	HG PTS=	3.8665 PSI		RUN NO	. 0190269107	
ALPHA CN	CM	cs	CY	CR CAT	CPB CAF	RUN
4.05 0.2878		-0.0060			0.1765 0.1996	3.
3.03 0.2004		-0.0063			0.1720 0.1987	3.
2.00 0.1170		-0.0086	0.0545 0		0.1669 0.1965	3.
1.47 0.0716		-0.0097			0.1641 0.1976	3.
0.96 0.0322		-0.0072			0.1619 0.1978	3.
0.44 -0.0034		-0.0098			0.1595 0.1974	3.
-0.07 -0.0422		-9.0074			0.1584 0.1965	3. 3.
-3.58 -0.0797		-0.0081			0.1577 0.1958 0.1579 0.1957	3.
-1.10 -0.1172 -1.62 -0.1574	-	-0.0188 -0.0124			0.1582 0.1954	3.
-2.12 -0.1962		-0.0124			0.1588 0.1955	3.
~3.14 -0.2764		-0.0154			0.1612 0.1938	3.
-4.17 -0.3631		-0.0201			0.1669 0.1922	3.
MODEL 946.2		FIG. 1.000		Н 1.75	PHI = .	
MODEL 946.2 Q= 8.29 PSI		FIG. 1.000 IN.= .48E0		H 1.75	PHI = . POJ/PTS = 40.	
	RE PER	IN.= .48E0	6 10=	90. DEG.F		
Q= 8.29 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	POJ/PTS = 40.	RUN
C= 8.29 PSI PO= 107.0 CF ALPHA CN	RE PER 44G PTS=	IN.= .48E0 3.8665 PSI	6 TO=	90. DEG.F RUN NO CR CAT	POJ/PTS = 40 0190269108 CPB CAF	RUN 4.
Q= 8.29 PSI PO= 107.0 C	RE PER 44G PTS= CM -2.1375	IN.= .48E0	6 TO= CY 0∙0365 0	90. DEG.F RUN NO CR CAT 2.0011 0.3828	POJ/PTS = 40. . 0190269108	RUN 4. 4.
G= 8.29 PSI PO= 107.0 CF ALPHA CN 4.03 0.2452	RE PER 44G PTS= CM -2.1375 -1.3663	IN.= .48E0 3.8665 PSI CS -0.0056	6 TO= CY 0.0365 0 0.0251 0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3776	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029	4.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546	RE PER 44G PTS= CM -2.1375 -1.3663 -0.6338	IN -= .48E0 3.8665 PSI CS -0.0056 -0.0040	6 TO= CY 0.0365 0 0.0251 0 0.1028 0	90. DEG.F RUN NO CR CAT 3.0011 0.3828 3.0012 0.3776 3.0015 0.3717	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022	4.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674	RE PER 44G PTS= CM -2.1375 -1.3663 -0.6338 -0.2703	IN.= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0	90. DEG.F RUN NO CR CAT 8.0011 0.3828 1.0012 0.3776 1.0015 0.3717 1.0013 0.3678	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010	4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233	RE PER MHG PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813	IN -= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0877 0 0.0624 0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3776 0.0015 0.3717 0.0013 0.3678 0.0014 0.3645 0.0009 0.3618	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2000 0.1651 0.1994 0.1626 0.1991	4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029	RE PER MHG PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655	IN -= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0877 0 0.0624 0 0.0749-0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3776 0.0015 0.3717 0.0013 0.3678 0.0014 0.3645 0.0009 0.3618 0.0004 0.3606	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2000 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002	4. 4. 4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029 -0.62 -0.1365	RE PER MHG PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655 1.0215	IN -= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101 -0.0230	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0877 0 0.0624 0 0.0749-0 0.1781 0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3776 0.0015 0.3717 0.0013 0.3678 0.0014 0.3645 0.0004 0.3666 0.0008 0.3586	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2000 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002 0.1594 0.1992	4. 4. 4. 4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029 -0.62 -0.1365 -1.12 -0.1741	RE PER MHG PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655 1.0215 1.3233	IN.= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101 -0.0230 -0.0124	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0624 0 0.0749-0 0.1781 0 0.0935 0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3717 0.0015 0.3717 0.0013 0.3678 0.0014 0.3645 0.0014 0.3645 0.0004 0.3606 0.0008 0.3586 0.0005 0.3571	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2000 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002 0.1594 0.1992 0.1590 0.1981	4. 4. 4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029 -0.62 -0.1365 -1.12 -0.1741 -1.64 -0.2174	RE PER MHG PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655 1.0215 1.3233 1.6783	IN.= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101 -0.0230 -0.0124 -0.0092	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0624 0 0.0749-0 0.1781 0 0.0935 0 0.0710 0	90. DEG.F RUN NO CR CAT 0.0011 0.3828 0.0012 0.3776 0.0015 0.3717 0.0013 0.3678 0.0014 0.3645 0.0009 0.3618 0.0004 0.3586 0.0008 0.3586 0.0005 0.3571 0.0003 0.3559	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2010 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002 0.1594 0.1992 0.1590 0.1981 0.1589 0.1970	4. 4. 4. 4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029 -0.62 -0.1365 -1.12 -0.1741 -1.64 -0.2174 -2.14 -0.2536	RE PER 44G PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655 1.0215 1.3233 1.6783 1.9689	IN.= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101 -0.0230 -0.0124 -6.0092 -0.0124	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0624 0 0.0749-0 0.1781 0 0.0935 0 0.0710 0	90. DEG.F RUN NO CR CAT 8.0011 0.3828 1.0012 0.3776 1.0013 0.3678 1.0014 0.3645 1.0009 0.3618 1.0004 0.3606 1.0008 0.3586 1.0005 0.3571 1.0003 0.3559 1.0003 0.3572	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2000 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002 0.1594 0.1992 0.1590 0.1981 0.1589 0.1970 0.1595 0.1977	4. 4. 4. 4. 4. 4.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 4.03 0.2452 3.00 0.1546 1.98 0.0674 1.45 0.0233 0.94 -0.0181 0.42 -0.0569 -0.10 -0.1029 -0.62 -0.1365 -1.12 -0.1741 -1.64 -0.2174	RE PER 44G PTS= CM -2.1375 -1.3663 -0.6338 -0.2703 0.0689 0.3813 0.7655 1.0215 1.3233 1.6783 1.9689 2.6388	IN.= .48E0 3.8665 PSI CS -0.0056 -0.0040 -0.0135 -0.0093 -0.0118 -0.0087 -0.0101 -0.0230 -0.0124 -0.0092	CY 0.0365 0 0.0251 0 0.1028 0 0.0625 0 0.0624 0 0.0749-0 0.1781 0 0.0935 0 0.0710 0 0.0992 0 0.1224-0	90. DEG.F RUN NO CR CAT 8.0011 0.3828 8.0012 0.3776 9.0015 0.3717 8.0013 0.3678 9.0014 0.3645 9.0004 0.3666 9.0008 0.3571 9.0005 0.3571 9.0003 0.3559 9.0001 0.3572	POJ/PTS = 40. . 0190269108 CPB CAF 0.1799 0.2029 0.1754 0.2022 0.1707 0.2010 0.1677 0.2010 0.1651 0.1994 0.1626 0.1991 0.1604 0.2002 0.1594 0.1992 0.1590 0.1981 0.1589 0.1970	4. 4. 4. 4. 4. 4.

HOD	EL 946.2	CONF	IG. 1.000	МА	CH 1.75	PHI =	•	
Q=	8.29 PS1	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS	= 80.	
P0=	107.0 CM	HG PTS=	3.8665 PSI		RUN NO	. 0190269	109	
ALPHA	CN	СН	CS	CY	CR CAT	СРВ	CAF	RUN
3.98	0.1457	-1.4422	-0.0010		0.0011 0.3886			5.
	0.0487		-0,0037		0.0015 0.3828			5.
-	-0.0431		-0.0093		0.0020 0.3770			5.
	-0.0898		-0.0111		0.0019 0.3752			5.
	-0.1311		-0.0091		0.0016 0.3724			5.
	-0.1765		-0.0102		0.0012 0.3713			5.
	-0.2153		-0.0092		0.0010 0.3672			<u>5</u> .
	-0.2574		-0.0063		0.0002 0.3653			5.
	-0.2976		-0.0042		0.0011 0.3647			5.
	-0.3409		-0.0085		-0.0004 0.3628			5.
	-0.3810		-0.0118		-0.0002 0.3635			5.
	-0.4625		-0.0157		-0.0003 0.3656			5.
-4.26	-0.5462	4.3013	-0.0190	0.1628	-0.0020 0.3711	0.1690	2022	5.
	0EL 9≈6.2 8.29 PSI		FIG. 1.000 IN.= .48E0		ACH 1.75 90. DEG.F	PHI = POJ/PTS	45 . 5 = .	
Q=	8.29 PSI	RE PER		6 10=	90. DEG.F		5 = .	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	POJ/PTS	5 = .	RUN
Q= PO= Alpha	8.29 PSI = 107.0 CM	RE PER HG PTS= CM	IN.= .48E0	CY	90. DEG.F RUN NO	POJ/PTS • 0190269 CPB	5 = . 9110 CAF	RUN 6.
Q= P0=	8.29 PSI = 107.0 CM	RE PER HG PTS= CM -2.5246	IN.= .48E0 3.8665 PSI	6 TO= CY 0.1673	90. DEG.F RUN NO CR CAT	POJ/PTS - 0190269 - CPB - 0-1708 (5 = . 9110 CAF 0.1828	_
Q= PO= ALPHA 4.15	8.29 PSI = 107.0 CM CN 0.3151	RE PER HG PTS= CM -2.5246 -1.8937	IN.= .48E0 3.8665 PSE CS -0.0206	CY 0.1673 0.1223	90. DEG.F RUN NO CR CAT 0.0010 0.3536	POJ/PTS - 0190269 - CPB - 0.1708 (5 = . 9110 CAF 0.1828 0.1842	6.
Q= PO= ALPHA 4.15 3.13	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160	CY 0.1673 0.1223 0.1343	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496	POJ/PTS - 0190269 - CPB - 0.1708 (0.1654 (0.1615 (5 = . 9110 CAF 0.1828 0.1842 0.1849	6.
Q= PO= ALPHA 4.15 3.13 2.10	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341 -0.9159	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169	CY 0.1673 0.1223 0.1343 0.1270	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464	POJ/PTS - 0190269 - CPB - 0.1708 (0.1654 (0.1615 (0.1598 (5 = . 9110 CAF 0.1828 0.1842 0.1849 0.1860	6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152	RE PER CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164	CY 0.1673 0.1223 0.1343 0.1270 0.1258	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458	POJ/PTS - 0190269 CPB 0-1708 (0-1654 (0-1615 (0-1598 (0-1584 (5 = . 9110 CAF 0.1828 0.1842 0.1849 0.1860 0.1861	6. 6. 5.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381	RE PER HG PTS= CM -2.5246 -1.8341 -0.9159 -0.5961 -0.2997	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445	POJ/PTS - 0190269 - CPB - 0.1708 (0.1654 (0.1615 (0.1598 (0.1598 (0.1571 (5 = . 9110 CAF 0.1828 0.1842 0.1849 0.1860 0.1861 0.1868	6. 6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0151	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0961 0.0975	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3445 0.0023 0.3445	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1518 (0.1571 (0.1561 (0.1563 (0.156	CAF 0.1828 0.1842 0.1849 0.1860 0.1861 0.1868 0.1868	6. 6. 6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02 -0.48	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381 0.0018	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131 0.2639	IN.= .48E0 3.8665 PSE CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0151 -0.0125	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0961 0.0975	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3445	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1518 (0.1571 (0.1561 (0.1563 (0.156	CAF 0.1828 0.1842 0.1849 0.1860 0.1861 0.1868 0.1868	6. 6. 6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02 -0.48 -1.01	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381 0.0018 -0.0335	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131 0.2639 0.5854	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0151 -0.0125 -0.0128	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0961 0.0975	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3445 0.0023 0.3445	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1518 (0.1571 (0.1561 (0.1563 (0.1569 (CAF 0.1828 0.1842 0.1849 0.1860 0.1861 0.1868 0.1876	6. 6. 6. 6. 6.
Q= P0= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02 -0.48 -1.01 -1.52	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381 0.0018 -0.0335 -0.0739	RE PER HG PTS= CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131 0.2639 0.5854 0.8647	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0151 -0.0125 -0.0128 -0.0126	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0961 0.0975 0.0965 0.1075	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3468 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3445 0.0023 0.3445 0.0023 0.3445	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1658 (0.1598 (0.1571 (0.1561 (0.1563 (0.1569 (0.1564 (0.156	CAF 0.1828 0.1842 0.1842 0.1860 0.1861 0.1868 0.1885 0.1876 0.1878	6. 6. 6. 6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02 -0.48 -1.01 -1.52 -2.03	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381 0.0018 -0.0335 -0.0739 -0.1093	RE PER CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131 0.2639 0.5854 0.8647	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0151 -0.0125 -0.0126 -0.0136	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0965 0.0975 0.1052 0.0841	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3445 0.0023 0.3445 0.0023 0.3474 0.0026 0.3488 0.0025 0.3522	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1615 (0.1598 (0.1571 (0.1561 (0.1563 (0.1569 (0.156	CAF 0.1828 0.1842 0.1849 0.1861 0.1868 0.1868 0.1876 0.1876 0.1878 0.1891 0.1894	6. 6. 6. 6. 6.
Q= PO= ALPHA 4.15 3.13 2.10 1.58 1.06 0.54 0.02 -0.48 -1.01 -1.52 -2.03 -3.05	8.29 PSI = 107.0 CM CN 0.3151 0.2364 0.1551 0.1152 0.0756 0.0381 0.0018 -0.0335 -0.0739 -0.1093 -0.1093	RE PER CM -2.5246 -1.8937 -1.2341 -0.9159 -0.5961 -0.2997 -0.0131 0.2639 0.5854 0.8647 1.1613 1.7963	IN.= .48E0 3.8665 PSI CS -0.0206 -0.0160 -0.0169 -0.0164 -0.0160 -0.0125 -0.0128 -0.0126 -0.0136	CY 0.1673 0.1223 0.1343 0.1270 0.1258 0.1159 0.0965 0.0975 0.1052 0.0841	90. DEG.F RUN NO CR CAT 0.0010 0.3536 0.0010 0.3496 0.0012 0.3464 0.0018 0.3458 0.0017 0.3445 0.0026 0.3439 0.0023 0.3447 0.0026 0.3488	POJ/PTS - 0190269 CPB 0.1708 (0.1654 (0.1615 (0.1598 (0.1571 (0.1561 (0.1563 (0.1569 (0.156	CAF 0.1828 0.1842 0.1849 0.1861 0.1868 0.1868 0.1876 0.1876 0.1878 0.1891 0.1894	6. 6. 6. 6. 6. 6.

HOD	EL 946.2	CONI	FIG. 1.000	H	ACH 1.75	5	PHI =	45.	
Q=	6.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	G.F	P0J/P	rs =	10.
P0=	107.0 CM	HG PTS=	3.8665 PSI			RUN NO	01902	69111	
ALPHA	CN	CM	CS	CY	CR	CAT	СРВ	CAF	RUN
	0.3050	-2.4602	-0.0440		0.0055				
	0.2262		-0.0330		0.0043				
2.09	0.1428	-1.1525	-0.0345		0.0028				
	0.0698		-0.0291		0.0019				
	0.1046		-0.0311		0.0025				
	0.0292		-0.0296		0.0016				
	-0.0084		-0.0249		0.0013				
	-0.0502		-0.0233		0.0036				
	-0.0891		-0.0183		0.0041				
		1.0346			0.0046				
	-0.1677		-0.0155		0.0052				
			-0.0204		0.0037				
-4.09	-0.3289	2.6211	-0.0207	0 - 1545	0.0045	0.3593	0.1891	0.1401	. 7.
	EL 946.2 8.29 PSI		FIG. 1.000 IN.= .48E0		ACH 1.75		PKI =		20•
Q=	8-29 PSI	RE PER		6 T0=		EG.₽		rs =	20.
Q=	8-29 PSI	RE PER	IN.= .48E0	6 T0=		EG.₽	P0J/P	rs =	20• RUN
Q= PO= ALPHA	8-29 PSI 107-0 CM	RE PER HG PTS=	IN.= .48E0 3.8665 PSI	6 T0=	90. DE	EG.F RUN NO	POJ/P 019020 CPB	TS = 59112 CAF	RUN
Q= PO= ALPHA	8.29 PSI 107.0 CM	RE PER HG PTS= CH -2.3941	IN.= .48E0 3.8665 PSI CS	6 T0= CY 0.4328	90. DE	EG.F RUN NO CAT 0.3650	POJ/P 019020 CPB	TS = 59112 CAF 0.1929	RUN 8•
Q= P0= ALPHA 4.13 3.11	8.29 PSI 107.0 CM CN 0.2952	RE PER HG PTS= CH -2.3941 -1.7321	IN.= .48E0 3.8665 PSI CS -0.0597	6 T0= CY 0.4328 0.3604	90. DE CR 0.0101	EG.F RUN NO CAT 0.3650 0.3589	POJ/P 019020 CPB 0.1721 0.1682	TS = 59112 CAF 0.1929 0.1907	RUN 8 • 8 •
Q= PO= ALPHA 4.13 3.11 2.08	8.29 PSI 107.0 CM CN 0.2952 0.2127	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513	6 T0= CY 0.4328 0.3604 0.3454	90. DE CR 0.0101 0.0080	CAT 0.3650 0.3589 0.3556	POJ/P 019020 CPB 0.1721 0.1682 0.1646	TS = 59112 CAF 0.1929 0.1907 0.1910	RUN 8 • 8 • 8 •
Q= PO= ALPHA 4.13 3.11 2.08 1.55	8.29 PSI 107.0 CM CN 0.2952 0.2127 0.1305	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486	CY 0.4328 0.3604 0.3454 0.3421	90. DE CR 0.0101 0.0080 0.0047	CAT 0.3650 0.3589 0.3556 0.3545	POJ/P 019020 CPB 0.1721 0.1682 0.1646 0.1628	TS = 59112 CAF 0.1929 0.1907 0.1910 0.1917	RUN 8 • 8 • 8 •
Q= PO= ALPHA 4.13 3.11 2.08 1.55 1.04	8.29 PSI 107.0 CM CN 0.2952 0.2127 0.1305 0.0862	RE PER HG PTS= CH -2.3941 -1.7321 -1.0689 -0.7166 -0.4167	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473	CY 0.4328 0.3604 0.3454 0.3421 0.3407	90. DE CR 0.0101 0.0080 0.0047 0.0038	CAT 0.3650 0.3589 0.3556 0.3545 0.3531	POJ/P . 019020 CPB 0.1721 0.1682 0.1646 0.1628 0.1613	TS = 59112 CAF 0.1929 0.1907 0.1910 0.1917	RUN 8 • 8 • 8 • 8 •
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53	8.29 PSI 107.0 CM CN 0.2952 0.2127 0.1305 0.0862 0.0487	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464	CY 0.4328 0.3604 0.3454 0.3451 0.3407 0.3045 0.3381	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023	CAT 0.3650 0.3556 0.3545 0.3531 0.3531 0.3492	POJ/P 01902 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584	TS = 59112 CAF 0.1929 0.1907 0.1910 0.1917 0.1918 0.1933 0.1908	RUN 8 • 8 • 8 • 8 • 8 • 8 • 8 • 8 • 8 •
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53 0.01	8.29 PSI 107.0 CM CN 9.2952 0.2127 0.1305 0.0862 0.0487 0.0125	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357 0.2384	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464 -0.0421	CY 0.4328 0.3604 0.3454 0.3421 0.3407 0.3045 0.3381 0.3173	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023 0.0025 0.0034	CAT 0.3650 0.3556 0.3555 0.3531 0.3531 0.3492 0.3499	POJ/P . 01902 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584 0.1584	TS = 59112 CAF 0.1929 0.1907 0.1910 0.1918 0.1933 0.1908 0.1915	RUN 8. 8. 8. 8. 8. 8.
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53 0.01 -0.50 -1.02	8.29 PSI 107.0 CM CN 0.2952 0.2127 0.1305 0.0862 0.0487 0.0125 -0.0329 -0.0683 -0.1048	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357 0.2384 0.5213 0.8085	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464 -0.0421 -0.0451 -0.0435 -0.0372	CY 0.4328 0.3604 0.3454 0.3421 0.3045 0.3381 0.3173 0.2534	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023 0.0025 0.0034 0.0042	CAT 0.3650 0.3589 0.3556 0.3543 0.3531 0.3492 0.3499 0.3511	POJ/P . 01902 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584 0.1584	TS = 59112 CAF 0.1929 0.1907 0.1918 0.1918 0.1933 0.1908 0.1915	RUN 8. 8. 8. 8. 8. 8.
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53 0.01 -0.50 -1.02 -1.54	8-29 PSI 107.0 CM CN 0.2952 0.2127 0.1305 0.0862 0.0487 0.0125 -0.0329 -0.0683 -0.1048 -0.1463	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357 0.2384 0.5213 0.8085 1.1402	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464 -0.0421 -0.0451 -0.0435 -0.0372 -0.0341	CY 0.4328 0.3604 0.3454 0.3421 0.3407 0.3045 0.3381 0.21534 0.2263	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023 0.0025 0.0034 0.0042 0.0042	CAT 0.3650 0.3589 0.3556 0.3545 0.3531 0.3531 0.3492 0.3491 0.3505	POJ/P O19020 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584 0.1586 0.1595	TS = 59112 CAF 0.1929 0.1907 0.1918 0.1918 0.1908 0.1918 0.1918 0.1918	RUN 8. 8. 8. 8. 8. 8.
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53 0.01 -0.50 -1.02 -1.54 -2.04	8.29 PSI 107.0 CM CN 9.2952 0.2127 0.1305 0.0862 0.0487 0.0125 -0.0329 -0.0683 -0.1048 -0.1463 -0.1848	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357 0.2384 0.5213 0.8085 1.1402	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464 -0.0421 -0.0451 -0.0435 -0.0372 -0.0341 -0.0339	CY 0.4328 0.3604 0.3454 0.3421 0.3407 0.3045 0.3381 0.21534 0.2263 0.2276	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023 0.0025 0.0034 0.0042 0.0048 0.0056	CAT 0.3650 0.3589 0.3556 0.3545 0.3531 0.3531 0.3492 0.3491 0.3505 0.3518	POJ/P O19020 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584 0.1586 0.1595 0.1603	CAF 0.1929 0.1907 0.1910 0.1918 0.1933 0.1908 0.1918 0.1918 0.1919 0.1919	RUN 8. 8. 8. 8. 8. 8. 8.
Q= P0= ALPHA 4.13 3.11 2.08 1.55 1.04 0.53 0.01 -0.50 -1.02 -1.54 -2.04 -3.07	8-29 PSI 107.0 CM CN 0.2952 0.2127 0.1305 0.0862 0.0487 0.0125 -0.0329 -0.0683 -0.1048 -0.1463	RE PER HG PTS= CM -2.3941 -1.7321 -1.0689 -0.7166 -0.4167 -0.1357 0.2384 0.5213 0.882 1.1402 1.4543 2.0661	IN.= .48E0 3.8665 PSI CS -0.0597 -0.0513 -0.0486 -0.0473 -0.0464 -0.0421 -0.0451 -0.0435 -0.0372 -0.0341	CY 0.4328 0.3604 0.3454 0.3421 0.3407 0.3045 0.3381 0.3173 0.2534 0.2263 0.2276 0.2204	90. DE CR 0.0101 0.0080 0.0047 0.0038 0.0023 0.0023 0.0025 0.0034 0.0042 0.0042	CAT 0.3650 0.3589 0.3556 0.3545 0.3531 0.3492 0.3499 0.3591 0.3505 0.3518 0.3533	POJ/P O19020 CPB 0.1721 0.1682 0.1646 0.1628 0.1613 0.1598 0.1584 0.1584 0.1584 0.1595 0.1603 0.1628	CAF 0.1929 0.1907 0.1910 0.1917 0.1918 0.1933 0.1908 0.1915 0.1915 0.1915	RUN 8. 8. 8. 8. 8. 8. 8.

MODEL 9+6.2	CONFIG.	1.000 M	ACH 1.75	PHI = 4	5.
g= 8.29 PSI	RE PER IN.	.48E06 TO=	90. DEG.F	POJ/PTS =	= 40 .
PO= 107.0 CM	HG PTS= 3.86	65 PSI	RUN NO	. 019026911	13
ALPHA CN	CH C	S CY	CR CAT	CP8 CA	LF RUN
4.12 0.2522	-2.0408 -0.0	909 0.6169	0.0158 0.3650	0.1742 0.1	1908 9.
3.10 0.1698	-1.3795 -0.0	854 0.5773	0.0117 0.3650	0.1718 C.1	1932 9.
2.07 0.0928	-0.7770 -0.0	· · · - · · -	0.0064 0.3630		
1.54 0.0489	-0.4259 -0.0		0.0046 0.3619		
1.02 0.0092	-0.1163 -0.0		0.0026 0.3587		
0.51 -0.0310	0.2077 -0.0		0.0008 0.3568		
-0.01 -0.0715	0.5322 -0.0		0.0025 0.3569		
-0.53 -0.1129	0.8681 -0.0		0.0022 0.3562		
-1.04 -0.1466	1.1251 -0.0		0.0036 0.3561		
-1.55 -0.1870	1.4556 -0.0		0.0045 0.3556		
-2.06 -0.2276	1.7884 -0.0		0.0047 0.3562		
-3.09 -0.3120 -4.12 -0.3989	2.4721 -0.0 3.1765 -0.0		0.0058 0.3583 0.0056 0.3619		
-4.12 -0.3757	3.1163 -0.0	159 0.5051	0.0030 0.3613	0.1094 0.1	1925 9.
					_
HODEL 946.2	CONFIG.	1.000 M	ACH 1.75	PHI = 4	•5•
Q= 8.29 PSI	RE PER IN.	.48E06 TO=	90. DEG.F	POJIPTS =	· 80 ₂
PO= 107.0 CM	HG PTS= 3.86	65 PSI	ี่ สบท ทอ	. 019026911	.4
ALPHA CN	см с	S CY	CR CAT	CPB CA	AF RUN
4.08 0.1852	-1.5495 -0.1	672 1.1434	0.0249 0.3774	9.1765 0.2	2009 10.
3.06 0.1004	-0.8697 -0.1	566 1.0658	0.0181 0.3766	0.1738 0.2	2028 10.
2.03 0.0099	-0.1422 -0.1		0.0104 0.3764		
1.00 -0.0716	0.5059 -0.1	729 1.2860	0.0046 0.3715	0.1668 0.2	046 10.
-0.04 -0.1516	1.1399 -0.1	714 1.2864	0.0025 0.3669	0.1620 0.2	2050 10.
-1.07 -0.2382	1.8429 -0.1	744 1.3201	0.0033 0.3646	0.1613 0.2	032 10.
1.50 -0.0329	0.1964 -0.1	642 1.1873	0.0066 0.3739	0.1691 0.2	1049
0.47 -0.1148	0.8492 -0.1		0.0023 0.3689	0.1640 0.2	1049 10.
-0.57 -0.1972	1.5115 -0.1		0.0030 0.3651		
-1.60 -0.2808	2.1851 -0.1		0.0050 0.3653		
-2.10 -0.3201	2.5018 -0.1	700 1 200/	0.0058 0.3654	0 1/10 0 2	036 10.
3 13 0 / 650			V. UUDB U.3694	A-1018 A-5	.030 20•
-3.13 -0.4029 -4.15 -0.4876	3.1758 -0.1	689 1.2699	0.0083 0.3688 0.0091 0.3716	0.1653 0.2	035 10.

H	ODEL 946.2	CONI	FIG. 1.000	H	CH 1.75	5	PHI =	90.	
C	= 8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	EG.F	4\r03	rs =	•
P	0= 107.0 C	MHG PTS=	3.8665 PSI			RUN NO.	01902	59120	
ALPH	A Cii	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
4 1	7 0.3340	-2 7200	-0.0247	0 2174	0	0 ≈ 3560	0.1650	0 1909	11.
3.1			-0.0078			0.3521			ii.
2.1			-0.0226			0.3495			11.
	9 0.1196		-0.0170			0.3492			11.
1.0			-0.0250			0.3490			11.
	6 0.0413		-0.0180			0.3485			ii.
	5 0.0039		-0.0227			0.3476			11.
	7 -0.0346		-0.0138			0.3471			ii.
	8 -0.0724		-0.0205			0.3476			11.
	0 -0.1123	0.8942				0.3479			11.
	0 -0.1486	1.1857	-0.0202			0.3496			11.
	2 -0.2304	1.8540	-0.0181			0.3515			11.
	5 -0.3179		-0.0226			0.3541			11.
H	ODEL 946.2	CON	=IG. 1.000	м	ACH 1.75	5	PHI =	90.	
C	= 8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. DE	:G.F	POJ/P	rs = _ 10	0.
ρ	0= 107.0 C	HG PTS=	3.8665 PSI			RUN NO.	01902	59121	
ALPH	A CN	СМ	CS	CY	CR	CAT	CPB	CAF	RUN
4.1	7 0.3356	-2-7354	-0.0413	0.3221	0-0014	0.3521	0-1638	0-1883	12.
3.1			-0.0400			0.3519			12.
2.1			-0.0380			0.3504			12.
1.5			-0.0407			0.3494			12.
1.0			-0.0370			0.3484			12.
0.5			-0.0418			0.3495			12.
0.0			-0.0433			0.3492			12.
	6 -0.0414	0.3458				0.3520			12.
	8 -0.0817		-0.0385			0.3490			12.
-	9 -0.1198	0.9658				0.3480			12.
-	0 -0.1573		-0.0448			0.3498			12.
	3 -0.2398		-0.0407			0.3510			12.
							0.1649		

A STATE OF THE PROPERTY OF THE

800	EL 946.2	CONS	FIG. 1.000	M	ACH 1.7	5	PHI =	90.	
Ŭ=	8.29 PS1	RE PER	IN.= .48E0	6 TO=	90. D	EG.F	901/6	rs =	20.
PD≈	107.0 CM	HG PTS≖	3.8665 PS1			RUN NO	01902	69122	
ALPHA	CN	СН	cs	CY	CR	CAT	СРВ	CAF	RUN
4.18			-0.0756	0.5932	0.0041	0.3567	0.1659	0.1907	13.
3.16		-1.9889	-0.0593	0.4279	0.0027	0.3541	0.1635	0.1707	13.
2.13		-1.2942	-0.0637	0.4770	0=0013	0.3501	0.1612	0.1888	13.
1.59	0.1193	-0.9499	-0.0646	0.4854	9.0004	0.3504	0.1600	0.1904	13.
1.09	0.0830	-0.6631	-0.0609			0.3507			
0.57	9.0427	-0.3457	-0.0623	0.4636	-0.0004	0.3518	0.1585	0.1932	13.
0.05	-0.0007	0.0079	-0.0639	0.4823	-0.0005	0.3521	0.1581	0.1939	13.
	-0.0416	0.3421	-0.0582	G.4238	0.0010	0.3502	0.1580	0.1922	13.
-9.98	-0.0809	0.6517	-0.0675	0.5162	0.0007	0.3488	0.1581	0.1907	13.
	-0.1201	0.9619	-0.0605	0-4461	0.0008	0.3496	0.1585	0.1911	13.
-2.01	-0.1589	1.2678	-0.0640	0.4811	-0.0004	0.3501	0.1598	0.1902	13.
-3.03	-0.2415	1.9399	-0.0645	0.4860	-0.0018	0.3553	0.1640	0.1914	13.
-4.06	-0.3328	2.6948	-0.0704	0.5498	-0.0036	C-3593	0.1676	0.1917	13.
	EL 946.2	CONF			ACH 1.7		PHI =	90.	
	EL 946.2 8.29 PSI		FIG. 1.000 IN.= .48E0		90. D		PHI =		40.
Çz	8.29 PSI	RE PER				EG.F	-	TS =	40.
Çz	8.29 PSI	RE PER	IN.= .48E0			EG.F	P0J/P	TS =	40. RUN
С= РО= Alpha	8.29 PSI 107.0 CM CN	RE PER HG PTS=	IN.= .48E0 3.8665 PSI CS	6 f0=	90. D	EG.F RUN NO. CAT	POJ/P • 019020 CPB	TS = 69123 CAF	RUN
C= PO= ALPHA 4.18	8.29 PSI 107.0 CM CN 0.3394	RE PER HG PTS= CH -2.7350	IN.= .48E0 3.8665 PSI CS -0.1208	6 f0= CY 0.9041	90. D CR 0.0068	EG.F RUN NO CAT 0.3593	POJ/P • 019020 CPB 0•1691	TS = 69123 CAF 0.1903	RUN 3 14.
С= РО= Alpha	8.29 PSI 107.0 CM CN	RE PER HG PTS= CH -2.7350 -1.9512	IN.= .48E0 3.8665 PSI CS	6 TO= CY 0.9041 0.8642	90. D CR 0.0068 0.0033	EG.F RUN NO. CAT 0.3593 0.3556	POJ/P • 019020 CPB 0.1691 0.1656	TS = 69123 CAF 0.1903 0.1900	RUN 3 14.
C= PO= ALPHA 4.18 3.16	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141	6 f0= CY 0.9041 0.8642 0.8417	90. D CR 0.0068 0.0033 0.0027	EG.F RUN NO. CAT 0.3593 0.3556 0.3555	POJ/P . 019020 CPB 0.1691 0.1656 0.1633	TS = 69123 CAF 0.1903 0.1900 0.1922	RUN 3 14. 3 14. 2 14.
C= PO= ALPHA 4.16 3.16 2.13	8.29 PSI 107.0 CM CN 0.3394 0.2460	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141	6 10= CY 0.9041 0.8642 0.8417 0.8621	90. D CR 0.0068 0.0033 0.0027 -0.0002	EG.F RUN NO. CAT 0.3593 0.3556	POJ/P . 019020 CPB 0.1691 0.1656 0.1633 0.1621	TS = 69123 CAF 0.1903 0.1900 0.1922 0.1928	RUN 3 14. 9 14. 2 14. 3 14.
C= PO= ALPHA 4.15 3.15 2.13 1.10	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610 0.0826 0.1200	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141 -0.1158	6 10= CY 0.9041 0.8642 0.8417 0.8621- 0.8944	90. D CR 0.0068 0.0033 0.9027 -0.0002 0.0010	CAT 0.3593 0.3556 0.3555 0.3549	POJ/P . 019020 CPB 0.1691 0.1656 0.1633 0.1621 0.1631	TS = 69123 CAF 0.1903 0.1900 0.1922 0.1928 0.1915	RUN 14. 14. 14. 14. 14.
PO= ALPHA 4.16 3.16 2.13 1.10 1.60	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610 0.0826 0.1200	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141 -0.1158 -0.1195	6 T0= CY 0.9041 0.8642 0.8417 0.8621- 0.8944 0.8131	90. D CR 0.0068 0.0033 0.9027 -0.0002 0.0010 0.0002	CAT 0.3593 0.3556 0.3555 0.3549 0.3546	POJ/P . 019020 CPB 0.1691 0.1656 0.1633 0.1621 0.1631 0.1620	TS = 59123 CAF 0.1903 0.1903 0.1922 0.1928 0.1915	RUN 14. 14. 14. 14. 14. 14.
C= PO= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610 0.0826 0.1200 0.0440	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1159 -0.1141 -0.1158 -0.1195 -0.1106	6 T0= CY 0.9C41 0.8642 0.8417 0.8621 0.8621 0.8934	90. D CR 0.0068 0.0033 0.0027 -0.0002 0.0010 0.0002 0.0004	CAT 0.3593 0.3556 0.3549 0.3546 0.3538	POJ/P . 019020 CPB 0.1691 0.1656 0.1633 0.1621 0.1631 0.1620 0.1617	TS = 69123 CAF 0.1903 0.1903 0.1928 0.1928 0.1918 0.1928	RUN 3 14. 4 14. 5 14. 6 14. 6 14.
C= PO= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57 0.05 -0.47	8.29 PSI 107.0 CM CN 0.3394 9.2460 0.1610 0.0826 0.1200 0.0440 9.0031	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201 0.3377	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1159 -0.1141 -0.1158 -0.1195 -0.1106 -0.1187	6 T0= CY 0.9C41 0.8642 0.8417 0.8621- 0.8621- 0.8131 0.8932 0.9164	90. D CR 0.0068 0.0033 0.9027 -0.0002 0.0010 0.6002 6.0004 0.0015	CAT 0.3593 0.3556 0.3555 0.3549 0.3546 0.3538 0.3543	POJ/P . 019020 CPB 0.1691 0.1650 0.1633 0.1621 0.1620 0.1617 0.1617	TS = 69123 CAF 0.1903 0.1902 0.1922 0.1925 0.1918 0.1926 0.1928	RUN 3 14. 14. 14. 14. 14. 14. 14. 14.
C= PO= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57 0.05 -0.47 -0.98	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610 0.0826 0.1200 0.0440 0.0031 -0.0414	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201 0.3377 0.6433	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1159 -0.1141 -0.1158 -0.1195 -0.1106 -0.1187 -0.1209	6 T0= CY 0.9C41 0.8642 0.8417 0.8621- 0.8131 0.8932 0.9164 0.8316	90. D CR 0.0068 0.0033 0.9027 -0.0002 0.0010 0.0002 6.0004 0.0015	CAT 0.3593 0.3556 0.3555 0.3549 0.3548 0.3543 0.3538	POJ/P O19020 CPB O.1691 O.1650 O.1633 O.1621 O.1631 O.1620 O.1617 O.1620	TS = 69123 CAF 0.1903 0.1900 0.1928 0.1918 0.1928 0.1928 0.1928	RUN 3 14. 14. 14. 14. 14. 14. 14. 14. 14.
C= PO= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57 0.05 -0.47 -0.98 -1.49	8.29 PSI 107.0 CMI CN 0.3394 0.2460 0.1610 0.0826 0.1200 0.0440 0.0031 -0.0414 -0.0893	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201 0.3377 0.6433 0.9302	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1159 -0.1141 -0.1158 -0.1195 -0.1106 -0.1187 -0.1209 -0.1126	6 T0= CY 0.9C41 0.8642 0.8417 0.8621 0.8944 0.8131 0.8932 0.9164 0.8316 0.8951	90. D CR 0.0068 0.0033 0.0027 -0.0002 0.0010 0.0015 0.0010	CAT 0.3593 0.3556 0.3555 0.3549 0.3548 0.3548	POJ/P O19020 CPB O.1691 O.1656 O.1633 O.1621 O.1630 O.1617 O.1617 O.1620 O.1622	TS = 69123 CAF 0.1903 0.1900 0.1928 0.1918 0.1928 0.1928 0.1928	RUN 3 14. 14. 14. 14. 14. 14. 14. 14. 14.
C= P0= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57 0.055 -0.47 -0.98 -1.49 -2.00	8.29 PSI 107.0 CMI CN 0.3394 0.2460 0.16i0 0.0826 0.1200 0.0440 0.0031 -0.0414 -0.0803 -0.1170	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201 0.3377 0.6433 0.9302 1.2278	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141 -0.1158 -0.1195 -0.1106 -0.1187 -0.1209 -0.1126 -0.1192	CY 0.9041 0.8642 0.8417 0.8621 0.8944 0.8131 0.8932 0.9164 0.8316 0.8951 0.8337	90. D CR 0.0068 0.0033 0.0027 -0.0002 0.0010 0.0015 0.0010 0.0010	CAT 0.3593 0.3556 0.3555 0.3549 0.3548 0.3538 0.3548 0.3548 0.3548	POJ/P O19020 CPB 0.1691 0.1656 0.1633 0.1621 0.1631 0.1620 0.1617 0.1617 0.1620 0.1622 0.1625	TS = 69123 CAF 0.1903 0.1903 0.1928 0.1918 0.1928 0.1928 0.1928 0.1928	RUN 3 14. 14. 14. 14. 14. 14. 14. 14. 14. 14.
PO= ALPHA 4.16 3.16 2.13 1.10 1.60 0.57 0.057 -0.47 -0.98 -1.49 -2.00 -3.03	8.29 PSI 107.0 CM CN 0.3394 0.2460 0.1610 0.0826 0.1200 0.0440 0.0031 -0.0414 -0.0803 -0.1170 -0.1555	RE PER HG PTS= CH -2.7350 -1.9512 -1.2648 -0.6539 -0.9435 -0.3534 -0.0201 0.3377 0.6433 0.9302 1.2278 1.8972	IN.= .48E0 3.8665 PSI CS -0.1208 -0.1169 -0.1141 -0.1158 -0.1195 -0.1106 -0.1187 -0.1209 -0.1126 -0.1192	CY 0.9C41 0.8642 0.8417 0.8621 0.8944 0.8131 0.8932 0.9164 0.8316 0.8951 0.8337	90. D CR 0.0068 0.0033 0.0027 -0.0002 0.0010 0.0010 0.0010 0.0010 0.0002	CAT 0.3593 0.3556 0.3555 0.3549 0.3546 0.3538 0.3543 0.3543 0.3547 0.3542	POJ/P O19020 CPB 0.1691 0.1656 0.1633 0.1621 0.1631 0.1620 0.1617 0.1617 0.1622 0.1622 0.1625 0.1653	TS = 69123 CAF 0.1903 0.1900 0.1928 0.1918 0.1928 0.1928 0.1928 0.1928 0.1928	RUN 3 14. 14. 14. 14. 14. 14. 14. 14. 14. 14.

•	ООН	EL 946.2	CON	FIG.	1.000	H	ACH 1.7	'5	PHI =	90.	
Ċ	Q=	8.29 PSI	RE PER	IN.=	.48E08	T0=	90. 0	EG.F	POJ/P	TS =	.03
f	P0=	107.0 CM	HG PTS=	3.86	129 26			RUN NO	. 02002	69102	
ALP	НÁ	CN	СМ	Ċ	s	CY	CR	CAT	СРВ	CAF	RUN
4.1	19	0.3488	-2.7857	-0.2	371	1.7711	0.0115	0.3680	0.1688	0.1992	15.
3.1	6	0.2548	-2.0064	-0.2	351	1.7676	0.0071	0.3656	0.1640	0.2015	15.
2.1	13	0.1609	-1.2345	-0.2	312	1.7237	0-0047	0-3640	0.1621	0.2019	15.
1.6	61	0-1181	-0.8972	-0.2	373	1.7821	0.0041	0-3652	0.1619	0.2033	15.
1.0		0.0790	~0.5931	-0.2	309			0.3646			
		0.0406	-0.3000					0.3618			
0.0	05	-0.0010	0.0285					0.3643			
-0.4	46	-0.0420	0.3531	-0.2	424			0.3640			
-C-9	98	-0.0834	0.6757	-0.2	406	1.8254	0.0029	0.3663	0.1604	0.2059	15.
-1.4	49	-0-1209	0.9631	-0.2	369	1.7875	0.0021	0.3673	0.1612	0.2060	15.
	_	-0.1592	1.2518					0.3657			
		-0-2471	1.9621	-0.2	339			0.3689			
-4.6	07	-0.3399	2.7189	-0.2	350	1.7574	-0.0052	0.3722	0.1685	0.2037	15.
1	HOD	EL 946.2	CON	FIG.	1.450	H	ACH 1.7	'5	PHI =	•	
(Q=	8.29 PSI	RE PER	IN.=	.48E06	T0=	90. D	EG.F	POJ/P	rs =	•
		8.29 PSI					90. D		POJ/P	-	•
	P0=				65 PSI		90. D			-	
í	P0= HA	107.0 CM	HG PTS=	3.86 C	65 PSI.	CY	CR	RUN NO	. 02002	69103 CAF	· RUN
ALPI	PO= HA 11	107.0 CM	HG PTS=	3.86 C	65 PSI [.] S 205	CY 0.1741-	CR -0.0012	RUN NO	. 020020 CPB 0.1667	69103 CAF 0.1883	· RUN
ALPI	PO= HA 11	107.0 CM CN 0.3118	HG PTS= CM -2.5007	3.86 C -0.0	65 PSI S 205 167	CY 0.1741- 0.1369-	CR -0.0012 -0.0010	RUN NO. CAT 0.3550	. 020026 CPB 0.1667 0.1609	69103 CAF 0.1883 0.1881	RUN 16. 16.
ALPI 4.: 3.0	PO= HA 11 09	107.0 CM CN 0.3118 0.2308	CH -2.5007	3.86 C -0.0 -0.0	65 PSI' S 205 167 189	CY 0.1741- 0.1369- 0.1544-	CR -0.0012 -0.0010 -0.0007	RUN NO. CAT 0.3550 0.3490	. 020026 CPB 0.1667 0.1609 0.1573	69103 CAF 0.1883 0.1881 0.1897	RUN 16. 16.
4.: 3.0 2.0	PO= HA 11 09 06 53	107.0 CM CN 0.3110 0.2308 0.1525	CH -2.5007 -1.8437 -1.2143	3.86 C -0.0 -0.0 -0.0 -0.0	65 PSI ' S 205 167 189 153	CY 0.1741- 0.1369- 0.1544- 0.1239-	CR -0.0012 -0.0010 -0.0007	RUN NO. CAT 0.3550 0.3490 0.3470	CPB 0.1667 0.1609 0.1573 0.1557	69103 CAF 0.1883 0.1881 0.1897 0.1907	RUN 16. 16. 16.
4.1 3.0 2.0 1.1	PO= HA 11 09 06 53	107.0 CM CN 0.3110 0.2308 0.1525 0.1097	CH -2.5007 -1.8437 -1.2143 -0.8711	3.86 C -0.0 -0.0 -0.0 -0.0	65 PSI ' S 205 167 189 153 147	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164-	CR -0.0012 -0.0010 -0.0007 -0.0006	RUN NO. CAT 2 0.3550 0 0.3490 7 0.3470 0 0.3465	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548	69103 CAF 0.1883 0.1881 0.1897 0.1907	RUM 16. 16. 16. 16.
4.: 3.0 2.0 1.:	PO= HA 11 09 06 53 02	107.0 CM CN 0.3110 0.2308 0.1525 0.1097 0.0715	CH -2.5007 -1.8437 -1.2143 -0.8711 -0.5660	3.86 -0.0 -0.0 -0.0 -0.0 -0.0	65 PSI TS	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205-	CR -0.0012 -0.0010 -0.0007 -0.0006 -0.0005	RUN NO. CAT 2 0.3550 0.3490 7 0.3470 0.3465 0.3444	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548 0.1543	69103 CAF 0.1883 0.1881 0.1897 0.1907 0.1896	RUN 16. 16. 16. 16.
4.5 3.6 2.6 1.5 1.6	PO= HA 11 09 06 53 02 50	107.0 CM CN 0.3118 0.2308 0.1525 0.1097 0.0715 0.0340	CH -2.5007 -1.8437 -1.2143 -0.8711 -0.5660 -0.2709	3.86 C -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	65 PSI S 205 167 189 153 147 151	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205- 0.1171-	CR -0.0012 -0.0010 -0.0006 -0.0005 -0.0004	RUN NO. CAT 2 0.3550 0.3490 7 0.3470 0.3465 0.3444 0.3431	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548 0.1543 0.1540	CAF 0.1883 0.1881 0.1897 0.1896 0.1888 0.1913	RUN 16. 16. 16. 16. 16.
ALPI 4.: 3.(2.(1.: 1.(0.:	PO= HA 11 09 06 53 02 50 02 53	0.3118 0.2308 0.1525 0.1097 0.0715 0.0340 -0.0089	CM -2.5007 -1.8437 -1.2143 -0.8711 -0.5660 -0.2709 0.0762	3.86 C -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	65 PSI S 205 167 189 153 147 151 147	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205- 0.1171- 0.1372- 0.1218	CR -0.0012 -0.0010 -0.0006 -0.0006 -0.0001 -0.0001	RUN NO. CAT 2 0.3550 0.3490 7 0.3465 0.3464 0.3453 0.3464 0.3453	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548 0.1543 0.1545 0.1545	CAF 0.1883 0.1881 0.1897 0.1896 0.1888 0.1913 0.1899	RUN 16. 16. 16. 16. 16. 16.
4.5 3.6 2.6 1.5 1.6 0.5 -0.6	PO= HA 11 09 06 53 02 50 02	107.0 CM CN 0.3118 0.2308 0.1525 0.1097 0.0715 0.0340 -0.0089 -0.0398	CM -2.5007 -1.8437 -1.2143 -0.5660 -0.2709 0.0762 0.3158	3.86 C -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	65 PSI S 205 167 189 153 147 151 147 170	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205- 0.1171- 0.1372- 0.1218	CR -0.0012 -0.0010 -0.0006 -0.0006 -0.0001 -0.0001	RUN NO. CAT 2 0.3550 0.3490 0.3470 0.3465 0.3444 0.3453 0.3453	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548 0.1543 0.1545 0.1545	CAF 0.1883 0.1881 0.1897 0.1896 0.1888 0.1913 0.1899	RUN 16. 16. 16. 16. 16. 16.
ALPI 4.: 3.0 2.0 1.: 1.0 0.: -0.: -1.0	PO= HA 11 09 06 53 02 50 02 53	107.0 CM CN 0.3118 0.2308 0.1525 0.1097 0.0715 0.0340 -0.0089 -0.0398 -0.0767	CM -2.5007 -1.8437 -1.2143 -0.8711 -0.5660 -0.2709 0.0762 0.3158 0.6062	3.86 C -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0	65 PSI 3 205 167 189 153 147 151 147 170 152	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205- 0.1271- 0.1372- 0.1218- 0.1496- 0.1462	CR -0.0012 -0.0010 -0.0007 -0.0005 -0.0001 -0.0001 0.0001	RUN NO. CAT 2 0.3550 0 0.3490 0 0.3465 0 0.3464 0 0.3453 0 0.3453 0 0.3453 0 0.3456 0 0.3456	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1548 0.1543 0.1545 0.1549 0.1560 0.1565	CAF 0.1883 0.1881 0.1897 0.1903 0.181888 0.1913 0.1899 0.1908	RUN 16. 16. 16. 16. 16. 16. 16.
ALPH 4.: 3.0 2.0 1.: 1.0 0.: -0.: -1.: -2.0	PO= HA 11 109 06 53 02 50 05 53 05 64 06 09	107.0 CM CN 0.3118 0.2308 0.1525 0.1097 0.0715 0.0340 -0.0089 -0.0398 -0.0767 -0.0951	CM -2.5007 -1.8437 -1.2143 -0.8711 -0.5660 -0.2709 0.0762 0.3158 0.6062 0.7518	3.86 C -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0	65 PSI 3 205 167 189 153 147 151 147 170 152 184 176 172	CY 0.1741- 0.1369- 0.1544- 0.1239- 0.1164- 0.1205- 0.1171- 0.1372- 0.1218 0.1496 0.1462 0.1439	CR -0.0012 -0.0010 -0.0006 -0.0004 -0.0011 -0.0001 0.0003	RUN NO. CAT 0.3550 0.3490 0.3465 0.3464 0.3451 0.3453 0.3454 0.3457	. 020020 CPB 0.1667 0.1609 0.1573 0.1557 0.1543 0.1543 0.1545 0.1545 0.1545 0.1560 0.1565 0.1593	CAF 0.1883 0.1881 0.1897 0.1907 0.1888 0.1818 0.1899 0.1908 0.1890	RUN 16. 16. 16. 16. 16. 16. 16.

MODEL 946.2	CONFIG. 1.4	50 MACH 1.75	• = IH9	
Q= 8.29 PSI	RE PER IN.= .48	E06 TO= 90. DEG.F	+01/PTS = 10.	
PO= 107.0 CH	HG PTS= 3.8665 P	SI RUN M	0. 0200269104	
ALPHA CN	CM CS	CY CR CAT	CPB CAF	RUN
4.10 0.2877	-2.3529 -0.0193	0.1664-0.0002 0.367	0 0.1705 0.1965	17.
3.06 0.1713	-1-4110 -0.0170	0.1473-0.0001 0.360		17.
2.04 0.1193	-0.9843 -0.0145	0.1176-0.0003 0.354		17.
1.52 0.0936	-0.7769 -0.0141	0.1147 0.0001 0.352		17.
1.01 0.0561	-0.4780 -0.0148	0.1215-0.0001 0.352		17.
0.49 0.0186	-0.1801 -0.0138	0.1129 0.0006 0.350		17.
-0.63 -0.0177	0.1099 -0.0150	0.1188-0.0012 0.350		17.
-0.51 0.0133	-0.1461 -0.0108	0.0881 0.0001 0.347		17.
-1.03 -0.0519	0.3732 -0.0143	0.1162 0.0003 0.349		17.
-1.57 -0.1283	0.9803 -0.0130	0.1045 0.0006 0.349		17.
-2.07 -0.1646	1.2705 -0.0120	0.0972 0.0007 0.349		17.
-3.10 -0.2435	1.9044 -0.0142	0.1170 0.0009 0.351		17.
-4.12 -0.3114	2.4553 -0.0137	0.1134 0.0011 0.357	4 0.1650 0.1924	17.
MODEL 946.2	CONFIG. 1.4	EA HACU 3 75	PHI = .	
			· · · · · ·	
Q= 8.29 PSI	RE PER IN.= .48		POJ/PTS = 20.	
		E06 T0= 90. DEG.F	· · · · · ·	
	RE PER IN.= .48	E06 T0= 90. DEG.F	POJ/PTS = 20.	RUN
PO= 107.0 CM	RE PER IN.= .48 HG PTS= 3.8665 P	E06 T0= 90. DEG.F SI RUN N	POJ/PTS = 20. IO. 0200269105 CPB CAF	RUN 18•
PO= 107.0 CM ALPHA CN	RE PER IN.= .48 HG PTS= 3.8665 P CM CS	E06 TO= 90. DEG.F SI RUN N CY CR CAT	POJ/PTS = 20. 10. 0200269105 CPB CAF 2. 0.1762 0.1963	
PO= 107.0 CM ALPHA CN 4.08 0.2690	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.372	POJ/PTS = 20. 10. 0200269105 CPB CAF 13. 0.1762 0.1963 12. 0.1705 0.1938	18.
PO= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.372 0.1395 0.0001 0.364	POJ/PTS = 20. 10. 0200269105 CPB CAF 13. 0.1762 0.1963 12. 0.1705 0.1938 10. 0.1655 0.1954	18.
PO= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.374 0.1395 0.0001 0.364 0.1350 0.0004 0.361	POJ/PTS = 20. 10. 0200269105 CPB CAF 1. 0.1762 0.1963 12 0.1705 0.1938 10 0.1655 0.1954 17 0.1629 0.1948	18. 18.
PO= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.372 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.357	POJ/PTS = 20. 0. 0200269105 CPB CAF 0.1762 0.1963 22 0.1705 0.1938 0 0.1655 0.1954 0 0.1629 0.1948 0 0.1611 0.1926	18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342	RE PER IN.= .48 HG PTS= 3.8665 P CH CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.372 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.353 0.1017 0.9006 0.353	POJ/PTS = 20. CPB CAF CO.1762 0.1963 CO.1765 0.1938 CO.1655 0.1954 CO.1629 0.1948 CO.1611 0.1926 CO.1597 0.1919	18. 18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342 0.48 -0.0007	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125 -0.0480 -0.0144	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.372 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.357 0.1017 0.0006 0.353 0.1163 0.0008 0.351	POJ/PTS = 20. CPB CAF CO.1762 0.1963 CO.1765 0.1938 CO.1655 0.1954 CO.1629 0.1948 CO.1611 0.1926 CO.1597 0.1919 CO.1584 0.1918	18. 18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342 0.48 -0.0007 -0.04 -0.0369	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125 -0.0480 -0.0144 0.2352 -0.0137	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.374 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.355 0.1017 0.0006 0.352 0.1113 0.0008 0.351 0.1113 0.0009 0.356 0.0941 0.0013 0.348 0.1049-0.0003 0.348	POJ/PTS = 20. CPB CAF CO.1762 0.1963 CO.1765 0.1938 O 0.1655 0.1954 CO.1629 0.1948 CO.1697 0.1919 CO.1584 0.1918 CO.1576 0.1912 CO.1573 0.1909	18. 18. 18. 18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342 0.48 -0.0007 -0.04 -0.0369 -0.55 -0.0745	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125 -0.0480 -0.0144 0.2352 -0.0137 0.5315 -0.0120	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.374 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.355 0.1163 0.0008 0.351 0.1113 0.0009 0.356 0.0941 0.0013 0.348	POJ/PTS = 20. CPB CAF CO.1762 0.1963 CO.1765 0.1938 O 0.1655 0.1954 CO.1629 0.1948 CO.1697 0.1919 CO.1584 0.1918 CO.1576 0.1912 CO.1573 0.1909	18. 18. 18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342 0.48 -0.0007 -0.04 -0.0369 -0.55 -0.0745 -1.06 -0.1140	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125 -0.0480 -0.0144 0.2352 -0.0137 0.5315 -0.0120 0.8468 -0.0130	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.374 0.1395 0.0001 0.364 0.1350 0.0004 0.361 0.1146-0.0009 0.357 0.1017 0.0006 0.352 0.1163 0.0008 0.351 0.1113 0.0009 0.350 0.0941 0.0013 0.348 0.1049-0.0003 0.348 0.1049-0.0003 0.348 0.1115-0.0001 0.347 0.0875-0. 0.347	POJ/PTS = 20. 10. 0200269105 CPB CAF 13. 0.1762 0.1963 12. 0.1705 0.1938 10. 0.1655 0.1954 17. 0.1629 0.1948 17. 0.1611 0.1926 15. 0.1597 0.1919 12. 0.1584 0.1918 18. 0.1576 0.1912 19. 0.1573 0.1909 19. 0.1572 0.1903 10.1573 0.1908	18. 18. 18. 18. 18. 18.
P0= 107.0 CM ALPHA CN 4.08 0.2690 3.07 0.1948 2.03 0.1139 1.51 0.0730 1.00 0.0342 0.48 -0.0007 -0.04 -0.0369 -0.55 -0.0745 -1.06 -0.1140 -1.58 -0.1509	RE PER IN.= .48 HG PTS= 3.8665 P CM CS -2.2303 -0.0160 -1.6223 -0.0162 -0.9637 -0.0160 -0.6369 -0.0139 -0.3255 -0.0125 -0.0480 -0.0144 0.2352 -0.0137 0.5315 -0.0120 0.8468 -0.0130 1.1389 -0.0138	E06 T0= 90. DEG.F SI RUN N CY CR CAT 0.1326-0.0001 0.374 0.1350 0.0004 0.361 0.1146-0.0009 0.353 0.1017 0.0006 0.353 0.1013 0.0008 0.351 0.1113 0.0009 0.356 0.0941 0.0013 0.348 0.1049-0.0003 0.348 0.1049-0.0001 0.347	POJ/PTS = 20. 10. 0200269105 CPB CAF 13. 0.1762 0.1963 12. 0.1705 0.1938 10. 0.1655 0.1954 17. 0.1629 0.1948 17. 0.1611 0.1926 15. 0.1597 0.1919 12. 0.1584 0.1918 18. 0.1576 0.1912 12. 0.1573 0.1909 15. 0.1573 0.1908 12. 0.1573 0.1908 12. 0.1593 0.1908	18. 18. 18. 18. 18. 18. 18.

мог	DEL 946.2	CUM	FIG. 1.450) н.	ACH 1.75		PHI ≃	•	
Q=	8.29 PSI	RE PER	IN.= .4820	6 TO×	90. DE	G.F	4/104	TS = 40.	•
20=	= 107.0 CH	HG PTS=	3.8665 PSI		1	KUN NO.	02002	691 06	
ALPHA	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.06	0.2293		<0.0195	J.1689	-0.			0.1986	19.
3.04			-0.0175		0.0007				19.
2.02	0.0649		-0.0135		0.0009				19.
1.48	0.0228		-0.0180		0.0011				19.
	-0.0154		-0.0163		0.0001				19.
	-0.0542		-0.0168		0.0005				19.
_	-0.0918		-0.0140		0.0003				19.
	-0.1307		-0.0140		0.0004				19.
	-0.1695		-0.0122		0.0008				19.
	-0.2051		-0.0137		0.0021				19.
	-0.2420		-0,0138		0.0008				19.
	-0.3197		-0.0138		0.0026				19.
-4.17	-0.3987	3.0739	-0.0134	0-1097	C. 0028	0.3553	0.1647	Q.1906	19.
	946.2 8.29 PSI		FIG. 1.450 IN.= .48E0	•	4CH 1.75		PHI =	TS = 80.	
P0=	107.0 CM	HG PTS=	3.8665 P\$I		í	RUN NO.	02002	69107	
ALPHA	CN	'CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.00	0.1240	-1.1981	-0.0202	0.1695	0.0014	0.3797	0.1761	0-2036	20.
2.99	0.0412		-0.0194		0.0013				20.
1.96	-0.0449		-0.0181		0.0015				20.
1.43	-0.0942	0.6086	-0.0135		0.0019				20.
0.91	-0.1305		-0.0111		0.0017				20.
0.40	-0.1699		-0.0140		0.0022				20.
	-0.2088		-0.0126		0.0017				20.
	-0.2483		-0.0126		0.0024				20.
	-0.2885		-0.0105		0.0025				20.
	-0.3254		-0.0087		0.0021				20.
	-0.3590		-0.0109		0.0028				20.
	-0.4342		-0.0092		0.0025				20.
	-0.5101	_	-0.0080		0.0031				20.

MO	DEL 946.	2 CONI	FIG450	MA	CH 1.7	5	PHI =	45.	
0=	8.29 PS	I RE PER	IN.= .48E0	5 TO=	90° DI	EG.F	POJ/P	rs =	•
PO	= 107.0	CMHG PTS=	3.8665 PSI			RUN NO.	024026	59102	
ALPHA	CN	СМ	CS	CY	CR	CAT	CP8	CAF	RUN
4.03	0.3262	-2.6658	-0.0225	0.1749-	-0.0025	Q.3492	0.1633	0.1859	21.
3.01		-1.7806	-0.0362			0.3433			21.
1.98	0.1395	-1.1183	-0.0339	0.2681-	-0.0015	0.3419	0.1577	0.1842	21.
1.45	0.0973	-0.7727	-0.0357	0-2880-	-0.0010	0.3421	0.1565	0.1856	21.
0,94	0.0590	-0.4646	-0.0321	0.2548-	-0.0013	0.3420	0.1555	0.1865	21.
0.42	0.0275	-0.2188	-0.0268	0.2100-	-0.0008	0.3398	0-1551	0.1848	21.
-0.08	0.0070	-0.0594	-0.0093	0.0685-	-0.0005	0.3404	0.1551	0.1853	21.
-0.60	-0.0414	0.3350	-0.0151	0.1186-	-0.0009	0.3407	0.1551	0-1857	21.
-1.11	-0.0733	0.5732	-0.9105	0.0747-	-0.0003	0.3400	0.1552	0.1848	21.
-1.63	-0.1177	0.9370	-0.0110	0.0829-	-0.0020	0.3408	0.1559	0.1849	21.
	-0.1532		-0.0111	0.0851-	-0.0023	0.3421	0.1567	0.1854	21.
	-D.2342		-0.0078			0.3441			21.
-4.19	-0.3219		-0.0053	0.0334	0.0001	0.3469	0.1640	0.1829	21.
мо	IDFL 946.	S CON	FIG. 1.450	H	ACH 1.7	ș.	PHI =	45.	
	DFL 946. 8.29 PS		FIG. 1.450 IN.= .43E0		ACH 1.7		PHI =		10.
Q=	8.29 PS	I RE PER				EG•F		rs = :	10.
Q=	8.29 PS	I RE PER	IN.= .43E0			EG•F	P03/P	rs = :	10. RUN
Q= Po Alpha	8.29 PS = 107.0	I RE PER CMHG PTS= CM	IN.= .48E00 3.8665 PSI CS	6 TO=	90. D	EG.F RUN NO: CAT	PO3/P	TS = : 69103 CAF	RUN
Q= PC ALPHA 4.03	8.29 PS = 107.0 CN 0.3213	I RE PER CMHG PTS= CM -2.6619	IN.= .48E00 3.8665 PSI CS -0.0401	6 TO= CY 0.2910	90. Di	EG.F RUN NO CAT 0.3562	POJ/P • 024020 CPB 0•1649	rs = 69103 CAF 0.1913	RUN 22 *
Q= PO ALPHA 4.03 3.01	8.29 PS = 107.0 CN 0.3213 0.2313	I RE PER CMHG PTS= CM -2.6619 -1.9046	IN.= .43E00 3.8665 PSI CS -0.0401 -0.0354	6 TO= CY 0.2910 0.2487	90. Di	EG.F RUN NO CAT 0.3562 0.3541	POJ/P . 024020 CPB 0.1649 0.1617	TS =	RUN 22 * 22 •
Q= F0 ALPHA 4.03 3.01 1.98	8.29 PS R= 107.0 CN B 0.3213 0.2313 0.1462	I RE PER CMHG PTS= CM -2.6619 -1.9046 -1.2028	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299	CY 0.2910 0.2487 0.2082	90. Di CR 0.0012 0.0007 0.0003	EG.F RUN NO. CAT 0.3562 0.3541 0.3501	POJ/P . 024020 CPB 0.1649 0.1617 0.1593	TS =	RUN 22 * 22 • 22 •
Q= F0 ALPHA 4.03 3.01 1.98 1.45	8.29 PS = 107.0 CN 0.3213 0.2313 0.1462 0.1015	I RE PER CMHG PTS= CM -2.6619 -1.9046 -1.2028 -0.8366	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301	CY 0.2910 0.2487 0.2082 0.2103-	90. Di CR 0.0012 0.0007 0.0003 -0.0001	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 9.3489	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580	TS = 69103 CAF 0.1913 0.1924 0.1907 0.1908	RUN 22 * 22 • 22 •
Q= F0 ALPHA 4.03 3.01 1.98 1.45 0.93	8.29 PS = 107.0 CN 0.3213 0.2313 0.1462 0.1015 0.0626	I RE PER CMHG PTS= CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276	CY 0.2910 0.2487 0.2082 0.2103- 0.1904	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 9.3489 0.3475	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570	TS = 69103 CAF 0.1913 0.1924 0.1907 0.1908 0.1905	RUN 22 * 22 • 22 • 22 • 22 •
Q= PO ALPHA 4.03 3.01 1.98 1.45 0.93 0.42	8.29 PS = 107.0 CN 0.3213 0.2313 0.1462 0.1015 0.0626 0.0274	I RE PER CMHG PTS= CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 0.0005	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3489 0.3475 0.3468	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564	TS = 69103 CAF 0.1913 0.1924 0.1907 0.1908 0.1905 0.1904	RUN 22 * 22 • 22 • 22 • 22 • 22 •
Q= PO ALPHA 4.03 3.01 1.98 1.45 0.93 0.42	8.29 PS = 107.0 CN 3 0.3213 0.2313 0.1462 5 0.1015 6 0.0626 2 0.0274	I RE PER CMHG PTS= CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244 -0.0206	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309-	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 -0.0013	EG.F RUN NO. CAT 0.3562 0.3501 0.3501 0.3489 0.3475 0.3468 0.3468	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564 0.1562	CAF 0.1913 0.1924 0.1907 0.1908 0.1905 0.1904 0.1906	RUN 22 * 22 * 22 * 22 * 22 * 22 * 22 * 22
Q= PO ALPHA 4.03 3.01 1.98 0.42 0.42 -0.09	8.29 PS = 107.0 CN 0.3213 0.2313 0.1462 0.01015 0.0626 0.0626 0.0274 0.0092 -0.0557	I RE PER CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384 0.4249	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244 -0.0206 -0.0281	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309- 0.2110-	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 -0.0013	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3489 0.3468 0.3468 0.3468	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564 0.1562 0.1559	CAF 0.1913 0.1924 0.1907 0.1908 0.1908 0.1904 0.1906 0.1912	RUN 22 * 22 * 22 * 22 * 22 * 22 * 22 * 22
Q= PO ALPHA 4.03 3.01 1.98 1.45 0.42 -0.09 -0.61 -1.12	8.29 PS = 107.0 CN 0.3213 0.2313 0.1462 0.01015 0.0626 0.0274 0.0092 -0.0557 2.00923	I RE PER CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384 0.4249 0.7096	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0276 -0.0281 -0.0261	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309- 0.2110- 0.1945-	90. Di CR 0.0012 0.0007 0.0003 -0.0011 0.0005 -0.0013 -0.0013	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3489 0.3475 0.3468 0.3470 0.3464	POJ/P. . 024020 . CPB 0.1649 0.1617 0.1593 0.1580 0.1564 0.1562 0.1559 0.1556	CAF 0.1913 0.1924 0.1907 0.1908 0.1904 0.1906 0.1912 0.1909	RUN 22 * 22 * 22 * 22 * 22 * 22 * 22 * 22
Q= P0 ALPHA 4.03 3.01 1.98 1.45 0.93 -0.61 -1.12 -1.64	8.29 PS 107.0 CN 0.3213 0.2313 0.1462 0.01015 0.0626 0.0274 0.0092 -0.0557 20.0923 -0.1238	I RE PER CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384 0.4249 0.7096 0.9446	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244 -0.0206 -0.0281 -0.0261 -0.0201	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309- 0.2110- 0.1945- 0.1372-	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 0.00013 -0.0013	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3468 0.3468 0.3468 0.3464 0.3464	POJ/P. . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564 0.1559 0.1556 0.1556	CAF 0.1913 0.1924 0.1907 0.1908 0.1905 0.1904 0.1906 0.1912 0.1909 0.1923	RUN 22 * 22 * 22 * 22 * 22 * 22 * 22 * 22
Q= P0 ALPHA 4.03 3.01 1.98 1.45 0.93 0.42 -0.09 -0.61 -1.64 -2.14	8.29 PS R= 107.0 CN S	I RE PER CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384 0.4249 0.7096 0.9446 1.2633	IN.= .43E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244 -0.0206 -0.0281 -0.0261 -0.0201 -0.0191	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309- 0.2110- 0.1945- 0.1372- 0.1291-	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 0.00013 -0.0013 -0.0013	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3489 0.3475 0.3468 0.3468 0.3464 0.3483 0.3470	POJ/P. . 024020 . CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564 0.1559 0.1556 0.1561 0.1572	CAF 0.1913 0.1924 0.1907 0.1908 0.1905 0.1904 0.1906 0.1912 0.1909 0.1923 0.1898	RUN 22 * 22 • 22 • 22 • 22 • 22 • 22 • 22 •
Q= P0 ALPHA 4.03 3.01 1.98 1.45 0.93 0.42 -0.09 -0.61 -1.16 -2.14	8.29 PS 107.0 CN 0.3213 0.2313 0.1462 0.01015 0.0626 0.0274 0.0092 -0.0557 20.0923 -0.1238	I RE PER CM -2.6619 -1.9046 -1.2028 -0.8366 -0.5247 -0.2458 0.0384 0.4249 0.7096 0.9446 1.2633 1.8446	IN.= .48E00 3.8665 PSI CS -0.0401 -0.0354 -0.0299 -0.0301 -0.0276 -0.0244 -0.0206 -0.0281 -0.0261 -0.0201	CY 0.2910 0.2487 0.2082 0.2103- 0.1904 0.1636 0.1309- 0.2110- 0.1945- 0.1372- 0.1291- 0.1414-	90. Di CR 0.0012 0.0007 0.0003 -0.0001 0.0005 -0.0013 -0.0013 -0.0013 -0.0013	EG.F RUN NO. CAT 0.3562 0.3541 0.3501 0.3468 0.3468 0.3468 0.3464 0.3464	POJ/P . 024020 CPB 0.1649 0.1617 0.1593 0.1580 0.1570 0.1564 0.1562 0.1556 0.1561 0.1572 0.1608	CAF 0.1913 0.1924 0.1907 0.1908 0.1905 0.1904 0.1906 0.1912 0.1923 0.1898 0.1917	RUN 22 * 22 * 22 * 22 * 22 * 22 * 22 * 22

1	HOD	EL 9	46.2		CO	WFIG.	1.4	50		HAC	H 1.7	75	PHI	=	45.		
(Q=	8.29	PSI	R	E PER	R IN.=	. 48	E06	TO	= '	90. 1	DEG.F	POJ/	PT:	S =	20.	
i	P0=	107	.o c	NHG	PTS:	= 3.86	65 P	SI				RUN NO	. 0240	269	9104		
ALPI	НА	С	N	(CH	С	s		CY		CR	CÂT	СРВ	,	CAF		RUN
4.0	02	0.3	093	-2	-5869	5 -0.0	661	0	-501	0 0	. 0051	0.3608	0.167	2 (0.1936	5	23.
3.0		0.2				5 -0.7						0.3572					23.
		0.1				5 -0.0						0.3545					23 ^
1.4		0.0		_		3 -0.0						0.3538					23.
0.9		0.0	-			-0.0						0.3525					23.
	-	0.0		-		-0.0						0.3505					23.
		-0.0				-0.0						0.3512					23.
		-0.0				-0.0						0.3499					23.
		-0.1				-0.0						3 0.3494					23.
-1.0	64	-0.1	395	1.	.052	L -0.0	380					0.3494					23.
-2.	16	-0.1	782	1	.3539	-0.0	396					0.3502					23.
-3.	18	-0.2	512	1.	9246	-0.0	387					0.3523					23.
-4.	21	-0.3	254	. 2	.493	-0.0	377					0.3566					23.
1	MOD	EL 9	46.2		CO	IFIG.	1.4	50	i	MACI	H 1.7	75	PHI	=	45.		
1	Q=	8.29	PSI	R	E PEF	R IN.=	- 48	E06	TO	= !	90. [EG.F	P0 J/	PT:	S =	40•	
1	P0=	107	.0 C	MHG	PTS=	3.86	65 P	SI				RUN NO	. 0240	269	9105		
ALPI	HA	С	N	(CM	C	S		CY		CR	CAT	СРВ		CAF		RUN
4.0	00	0.2	888	-2	.4639	-0.1	110	0	.837	5 0.	. 0067	0.3664	0.171	5 (0.1969)	24.
2.9		0.1				-0.0						0.3641					24.
1.9		0.1				-0.0						0.3612					24.
1.4		0.0		-0	.5138	3 -0.0	848					0.3594					24.
0.9	91	0.0	131	-		-0.0						0.3574					24.
		-0.0	258			-0.0						0.3582					24.
		-0.0				-0.0						0.3564					24.
		-0.0				-0.0						0.3534					24.
		-0.1				-0.0						0.3543					24.
-1.6	67	-0.1	797		_	-0.0						0.3545					24.
		-0.2				7 -0.0						0.3537					24.
-3.	20	-0.2	872	2.	.1783	-0.0	793					0.3567					24.
		-0.3				-0.0						0.3596					24.

MODEL 946.2	CONF	IG. 1.450	MACH 1.	75	PHI =	45.	
Q= 8.29 PSI	RE PER	IN.= .48E0	6 FO= 90.	DEG.F	POJ/P1	rs = 8	30•
PO= 107.0 CM	HG PTS=	3.8665 PSI		RUN NO.	024026	69106	
ALPHA CN	CH	cs	CY CR	CAT	CPB	CAF	RUN
3.97 0.2292	-2.0653		1.4886 0.010				25.
2.95 0.1212	-1.1251		1.3442 0.007				25.
1.92 0.0232	-0.2959		1.2417 0.004				25.
1.39 -0.0257		-0.1667	1.2121 0.002				25. 25.
0.87 -0.0700 0.36 -0.1104		-0.1636 -0.1634	1.1913 0.002		-		25.
-0.16 -0.1475		-0.1646	1.2129 0.002				25. 25.
-0.67 -0.1905		-0.1654	1.2285 0.000				25.
-1.19 -0.2224		-0.1607	1.1863-0.		0.1598		25.
-1.71 -0.2620		-0.1613	1.2048-0.001				25.
-2.21 -0.2978		-0.1620	1.2184-0.003				25.
-3.24 -0.3721		-0.1606	1.2158-0.007				25.
-4.27 -0.4450	_	~0.1563	1.1815-0.013				25.
MUDEL 946.2	CONF	IG. 1.450	MACH 1.	75	= 1H9	90.	
MUDEL 946.2 Q= 8.29 PSI		FIG. 1.450 IN.= .48E0			= 1H9		•
	RE PER	IN.= .48E0	6 TO= 90.	DEG.F		rs =	
Q= 8.29 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	P01/P1	rs =	• RUN
Q= 8.29 PSI PO= 107.0 CM	RE PER HG PTS=	IN.= .48E0	6 TO= 90.	DEG.F RUN NO.	POJ/P1 024626 CP8	TS = 59107 CAF	• RUN 26•
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER HG PTS=	IN.= .48E0 3.8665 PSI CS -0.0178	6 TO= 90.	DEG.F RUN NO. CAT 2 0.3523	POJ/P1 024G26 CPB 0-1646	TS = 59107 CAF 0.1875	26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268	RE PER HG PTS= CM -2.6202	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001	CAT 2 0.3523 1 0.3469 3 0.3442	POJ/PT . 024G26 . CPB 0.1648 0.1595 0.1565	TS = 59107 CAF 0.1875 0.1873 0.1876	26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000	DEG.F RUN NO. CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444	POJ/PT . 024G26 . CPB 0.1648 0.1595 0.1565 0.1555	TS = 59107 CAF 0.1875 0.1873 0.1876 0.1889	26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001	DEG.F RUN NO. CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449	POJ/PI 024626 CPB 0.1646 0.1595 0.1565 0.1555 0.1546	TS = 59107 CAF 0.1875 0.1873 0.1876 0.1889 0.1903	26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001	DEG.F RUN NO. CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449 7 0.3431	POJ/PT . 024626 . CPB 0.1648 0.1595 0.1565 0.1555 0.1546 0.1544	CAF 0.1875 0.1873 0.1876 0.1889 0.1903 0.1887	26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669 -0.0734	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001	DEG.F RUN NO. CAT 2 0.3523 1 0.3469 3 0.3444 1 0.3444 1 0.3449 7 0.3431 2 0.3432	POJ/PT 024626 CPB 0.1648 0.1595 0.1595 0.1555 0.1546 0.1544	CAF 0.1875 0.1873 0.1876 0.1889 0.1903 0.1887 0.1889	26. 26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092 -0.39 -0.0286	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669 -0.0734 0.2270	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009 -0.0149	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001 0.1186 0.000	CAT 2 0.3523 1 0.3462 7 0.3444 1 0.3449 7 0.3443 2 0.3432 3 0.3432	POJ/PT . 024G26 . CPB 0.1648 0.1595 0.1565 0.1556 0.1544 0.1542 0.1540	CAF 0.1875 0.1875 0.1876 0.1879 0.1889 0.1903 0.1887 0.1889	26. 26. 26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092 -0.39 -0.0286 -0.90 -0.0656	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669 -0.0734 0.2270 0.5188	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009 -0.0149	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001 0.1186 0.000 0.1464 0.001	CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449 7 0.3431 2 0.3432 3 0.3432	POJ/P3 024626 CPB 0.1646 0.1595 0.1555 0.1556 0.1544 0.1542 0.1540 0.1539	CAF 0.1875 0.1875 0.1876 0.1889 0.1889 0.1889 0.1889 0.1892	26. 26. 26. 26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092 -0.39 -0.0286 -0.90 -0.0656 -1.42 -0.1052	RE PER HG PTS= CM -2.6202 -1.9365 -1.3046 -0.9755 -0.3669 -0.3669 -0.0734 0.2270 0.5188 0.8337	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009 -0.0149 -0.0170 -0.0133	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001 0.1186 0.000 0.1464 0.001 0.1071 0.001	CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449 7 0.3431 2 0.3432 3 0.3432 2 0.3452 5 0.3451	POJ/P3 024626 CPB 0.1646 0.1595 0.1565 0.1555 0.1544 0.1544 0.1542 0.1540 0.1539 0.1541	CAF 0.1875 0.1875 0.1876 0.1889 0.1889 0.1887 0.1889 0.1892 0.1923 0.1911	26. 26. 26. 26. 26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092 -0.39 -0.0286 -0.90 -0.0656 -1.42 -0.1052 -1.95 -0.1633	RE PER CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669 -0.0734 0.2270 0.5188 0.8337 1.1374	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009 -0.0149 -0.0170 -0.0133 -0.0121	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001 0.1186 0.000 0.1464 0.001 0.1071 0.001 0.0934 0.001	CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449 7 0.3431 2 0.3432 3 0.3452 5 0.3451 8 0.3455	POJ/PI 024G26 CPB 0.1646 0.1595 0.1565 0.1556 0.1544 0.1542 0.1549 0.1541 0.1550	CAF 0.1875 0.1875 0.1876 0.1889 0.1903 0.1887 0.1889 0.1923 0.1911 0.1905	26. 26. 26. 26. 26. 26. 26. 26. 26.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.26 0.3268 3.23 0.2425 2.20 0.1641 1.67 0.1228 1.15 0.0854 0.64 0.0466 0.12 0.0092 -0.39 -0.0286 -0.90 -0.0656 -1.42 -0.1052	RE PER CM -2.6202 -1.9365 -1.3046 -0.9755 -0.6760 -0.3669 -0.0734 0.2270 0.5188 0.8337 1.1374 1.7651	IN.= .48E0 3.8665 PSI CS -0.0178 -0.0176 -0.0199 -0.0136 -0.0184 -0.0146 0.0009 -0.0149 -0.0170 -0.0133	6 T0= 90. CY CR 0.1429-0.000 0.1413 0.000 0.1650 0.001 0.1019 0.000 0.1501 0.001 0.1139 0.001 -0.0395 0.001 0.1186 0.000 0.1464 0.001 0.1071 0.001	CAT 2 0.3523 1 0.3469 3 0.3442 7 0.3444 1 0.3449 7 0.3443 2 0.3432 3 0.3452 5 0.3451 8 0.3455 6 0.3480	POJ/P3 O24G26 CPB 0.1646 0.1595 0.1565 0.1556 0.1544 0.1542 0.1540 0.1541 0.1550 0.1572	CAF 0.1875 0.1875 0.1876 0.1889 0.1903 0.1887 0.1889 0.1992 0.1991 0.1905 0.1908	26. 26. 26. 26. 26. 26. 26. 26. 26.

но	DEL 946.2	CON	FIG. 1.450	м	ACH 1.7	5	PHI =	90.	
0=	8.29 PSI	RE PER	IN.= .48E0	6 10=	90. Di	EG.F	POJ/P	TS = 10.	
Pυ	= 107.0 CM	HG PTS=	3.8065 PSI			RUN NO.	02402	69108	
ALPHA	CN	СМ	cs	CY	CR	CAT	CPB	CAF	RUN
4.25	0.3179		-0.0321	0.2028	0.0069	U.3524	0.1668	0.1855	27.
3.23	0.2364	~1.8491	-0.0293	0.1778	0.0063	0.3482	0,1625	0.1858	27.
2.20	0.1598	-1.2516	-0.0315	0.2089	0.0038	0.3449	0.1584	0.1865	27.
1.67	0.1192		-0.0232		0.0026				27.
1.16			-0.0299		0.0001				27.
0.64			-0.0222		0.0016				27.
0.12			-0.0282		0.0016				27.
	-0.0313		-0.0277		0.0002				27.
	-0.0701		-0.0324		-C. 0001				27.
	-0.1086		-0.0247		0.0002				27.
	-0.1457		-0.0250		-0,0018				27.
	-0.2210		-0.0227		-0.0040				27.
-3.99	-0.3012	2.3698	-0.0199	0.0971-	-0.0048	0.3543	0.1637	0.1906	27.
_	DEL 946.2		FIG. 1.450		ACH 1.75		PHI =		
Q=	8.29 PSI	RE PER	IN.= .48E0	6 10=	90. Di	EG . F	POJ/91	rs = 20.	
PO	= 107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	02402	69109	
ALPHA	CN	CM	CS	CY	CR	CAT	CP8	CAF	RUN
4.25	0.3220	-2.5295	-0.0611	0.4275	0.0108	0.3541	0.1682	0.1859	28.
3.23									28.
2.20		-120012	-0.0595	0.4201	0.0079	0.3500	0.1630	0.1010	
1.68	0.1599		-0.0595	0.4201					28.
1.00		-1.2453		0.3467	0.0079 0.0045 0.0033	0.3479	0.1598	0.1880	28. 28.
1.16	0.1197	-1.2453 -0.9311	-0.0521	0.3467	0.0045	0.3479 0.3468	0.1598	0.1880 0.1880	28.
	0.1197	-1.2453 -0.9311 -0.6326	-0.0521 -0.0516	0.3467 0.3496 0.3045	0.0045 0.0033	0.3479 0.3468 0.3471	0.1598 0.1588 0.1582	0.1880 0.1880 0.1889	
1.16	0.1197 0.0815 0.0434	-1.2453 -0.9311 -0.6326 ~0.3352	-0.0521 -0.0516 -0.0472	0.3467 0.3496 0.3045 0.4302 0.3913	0.0045 0.0033 0.0025 0.0008 0.0017	0.3479 0.3468 0.3471 0.3477 0.3446	0.1598 0.1588 0.1582 0.1577 0.1575	0.1880 0.1880 0.1889 0.1900 0.1871	28. 28.
1.16 0.65 0.12	0.1197 0.0815 0.0434	-1.2453 -0.9311 -0.6326 ~0.3352 -0.0472	-0.0521 -0.0516 -0.0472 -0.0591	0.3467 0.3496 0.3045 0.4302 0.3913 0.5011	0.0045 0.0033 0.0025 0.0008 0.0017	0.3479 0.3468 0.3471 0.3477 0.3446 0.3466	0.1598 0.1588 0.1582 0.1577 0.1575 0.1574	0.1880 0.1880 0.1889 0.1900 0.1871 0.1892	28. 28. 28.
1.16 0.65 0.12 -0.38 -0.90	0.1197 0.0815 0.0434 0.0063 -0.0315 -0.0704	-1.2453 -0.9311 -0.6326 ~0.3352 -0.0472 0.2470	-0.0521 -0.0516 -0.0472 -0.0591 -0.0553	0.3467 0.3496 0.3045 0.4302 0.3913 0.5011	0.0045 0.0033 0.0025 0.0008 0.0017	0.3479 0.3468 0.3471 0.3477 0.3446 0.3466	0.1598 0.1588 0.1582 0.1577 0.1575 0.1574	0.1880 0.1880 0.1889 0.1900 0.1871 0.1892	28. 28. 28.
1.16 0.65 0.12 -0.38 -0.90 -1.42	0.1197 0.0815 0.0434 0.0063 -0.0315 -0.0704 -0.1082	-1.2453 -0.9311 -0.6326 ~0.3352 -0.0472 0.2470 0.5505	-0.0521 -0.0516 -0.0472 -0.0591 -0.0553 -0.0665	0.3467 0.3496 0.3045 0.4302 0.3913 0.5011- 0.3109- 0.3273-	0.0045 0.0033 0.0025 0.0008 0.0017 -0.0009 -0.0014	0.3479 0.3468 0.3471 0.3477 0.3446 0.3466 0.3465	0.1598 0.1582 0.1577 0.1575 0.1574 0.1577 0.1584	0.1880 0.1889 0.1900 0.1871 0.1892 0.1888 0.1912	28. 28. 28. 28. 28.
1.16 0.65 0.12 -0.38 -0.90 -1.42 -1.93	0.1197 0.0815 0.0434 0.0063 -0.0315 -0.0704 -0.1082 -0.1463	-1.2453 -0.9311 -0.6326 ~0.3352 -0.0472 0.2470 0.5505 0.8466 1.1453	-0.0521 -0.0516 -0.0472 -0.0591 -0.0553 -0.0665 -0.0472 -0.0486 -0.0475	0.3467 0.3496 0.3045 0.4302 0.3913 0.5011- 0.3109- 0.3273- 0.3142-	0.0045 0.0033 0.0025 0.0008 0.0017 -0.0009 -0.0014 -0.0002	0.3479 0.3468 0.3471 0.3477 0.3446 0.3466 0.3465 0.3496	0.1598 0.1588 0.1582 0.1577 0.1575 0.1574 0.1577 0.1584 0.1588	0.1880 0.1880 0.1889 0.1900 0.1871 0.1892 0.1888 0.1912 0.1898	28. 28. 28. 28. 28. 28.
1.16 0.65 0.12 -0.38 -0.90 -1.42 -1.93 -2.96	0.1197 0.0815 0.0434 0.0063 -0.0315 -0.0704 -0.1082	-1.2453 -0.9311 -0.6326 ~0.3352 -0.0472 0.2470 0.5505 0.8466 1.1453 1.7627	-0.0521 -0.0516 -0.0472 -0.0591 -0.0553 -0.0665 -0.0472 -0.0486	0.3467 0.3496 0.3045 0.4302 0.3913 0.5011- 0.3109- 0.3273- 0.3142- 0.3490-	0.0045 0.0033 0.0025 0.0008 0.0017 -0.0009 -0.0014	0.3479 0.3468 0.3471 0.3477 0.3446 0.3466 0.3465 0.3496 0.3486	0.1598 0.1588 0.1582 0.1577 0.1575 0.1574 0.1577 0.1584 0.1588 0.1612	0.1880 0.1880 0.1889 0.1900 0.1871 0.1892 0.1888 0.1912 0.1898 0.1929	28. 28. 28. 28. 28. 28. 28.

HOD	EL 446.2	CONF	IG. 1.450	МА	CH 1.75	•	PHI =	90.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TQ=	90. DE	G.F	P0J/P1	'S = 40.	
P0=	107.0 CH	HG PTS=	3.8665 PSL			RUN NO.	024026	9110	
ALPHA	CN	CM	cs	ΣY	CR	CAT	CPB	CAF	RUN
4.26	0.3290		-0.1030			0.3595			29.
3.23	0-2446		-0.1047			0.3554			29.
2.20	0.1617		-0.1103			ປ.354 8			29.
1.68	0.1200		-0.1046			0.3550			29.
	0.0833		-0.1105			0.3535			29.
	0.0444		-0.1022			0.3503			29.
	0.0073		-0.1056			0.3501			29.
	-0.0312		-0.1057			0.3505			29.
	-0.0694		-0.1065			0.3515	-	-	29.
	-0.1097		-0.1126			0.3520			29 •
	-0.1465		-0.1030			0.3535			29.
	-0.2288		-0.0976			0.3601			29.
-3.99	-0.3136	2.4673	-0.1007	0.7033	-0.0066	C.3608	0.1686	0.1923	29.
	EL 946.2 8.29 PSI		FIG. 2.000 IN.= .48E0		ACH 1.75		= 1H9	•	
Q=	8.29 PSI	KE PEK	1W-= -4VEO	5 10-	90. D	:0.F	PU3/P	1\$ = n	
P0=	107.0 CH	HG PTS=	3.8665 PSI			RUN NO.	. 024026	59114	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.10	0.5120	-4.8542	-0.0186	0.1530	0.0066	0.3895	0.1603	0.2293	30.
3.09	0.3814		~0.0200			U.3864		· .	30.
2.07	0.2527		-0.0169		0.0050				30.
1.55									
	0.1867					0.3862		-	30.
	0.1867	-1.7641	-0.0119	0.0875	0.0051	0.3862	0.1620	0.2242	30. 30.
1.03	0.1215	-1.7641 -1.1475	-0.0119 -0.0151	0.0875 0.1178	0.0051 0.0036	0.3862 0.3858	0.1620 0.1611	0.2242 0.2247	
1.03	0.1215	-1.7641 -1.1475 -0.5676	-0.0119	0.0875 0.1178 0.1049	0.0051 0.0036 0.0041	0.3862	0.1620 0.1611 0.1604	0.2242 0.2247 0.2234	30.
1.03 0.52 0.02	0.1215	-1.7641 -1.1475 -0.5676 -0.0029	-0.0119 -0.0151 -0.0140 -0.0112	0.0875 0.1178 0.1049 0.0827	0.0051 0.0036 0.0041 0.0037	0.3862 0.3858 0.3838	0.1620 0.1611 0.1604 0.1598	0.2242 0.2247 0.2234 0.2273	30. 30.
1.03 0.52 0.02 -0.50	0.1215 0.0601 0.0006	-1.7641 -1.1475 -0.5676 -0.0029 0.5421	-0.0119 -0.0151 -0.0140	0.0875 0.1178 0.1049 0.0827 0.0931	0.0051 0.0036 0.0041 0.0037 0.0036	0.3862 0.3858 0.3838 0.3872	0.1620 0.1611 0.1604 0.1598 0.1597	0.2242 0.2247 0.2234 0.2273 0.2249	30. 30. 30.
1.03 0.52 0.02 -0.50 -1.00	0.1215 0.0601 0.0006 -0.0575 -0.1176	-1.7641 -1.1475 -0.5676 -0.0029 0.5421 1.1103	-0.0119 -0.0151 -0.0140 -0.0112 -0.0126	0.0875 0.1178 0.1049 0.0827 0.0931 0.1162	0.0051 0.0036 0.0041 0.0037 0.0036 0.0035	0.3862 0.3858 0.3838 0.3872 0.3846	0.1620 0.1611 0.1604 0.1598 0.1597 0.1600	0.2242 0.2247 0.2234 0.2273 0.2249 0.2246	30. 30. 30. 30.
1.03 0.52 0.02 -0.50 -1.00	0.1215 0.0601 0.0006 -0.0575	-1.7641 -1.1475 -0.5676 -0.0029 0.5421 1.1103 1.7088	-0.0119 -0.0151 -0.0140 -0.0112 -0.0126 -0.0151	0.0875 0.1178 0.1049 0.0827 0.0931 0.1162 0.0843	0.0051 0.0036 0.0041 0.0037 0.0036 0.0035 0.0031	0.3862 0.3858 0.3838 0.3872 0.3846 0.3846	0.1620 0.1611 0.1604 0.1598 0.1597 0.1600 0.1607	0.2242 0.2247 0.2234 0.2273 0.2249 0.2246 0.2248	30. 30. 30. 30.
1.03 0.52 0.02 -0.50 -1.00 -1.52 -2.02	0.1215 0.0601 0.0006 -0.0575 -0.1176 -0.1810	-1.7641 -1.1475 -0.5676 -0.0029 0.5421 1.1103 1.7088 2.2607	-0.0119 -0.0151 -0.0140 -0.0112 -0.0126 -0.0151 -0.0115	0.0875 0.1178 0.1049 0.0827 0.0931 0.1162 0.0843 0.0622	0.0051 0.0036 0.0041 0.0037 0.0036 0.0035 0.0031 0.0030	0.3862 0.3858 0.3838 0.3872 0.3846 0.3846	0.1620 0.1611 0.1604 0.1598 0.1597 0.1600 0.1607 0.1609	0.2242 0.2247 0.2234 0.2273 0.2249 0.2246 0.2248 0.2248	30. 30. 30. 30. 30. 30.
1.03 0.52 0.02 -0.50 -1.00 -1.52 -2.02 -3.04	0.1215 0.0601 0.0006 -0.0575 -0.1176 -0.1810 -0.2391	-1.7641 -1.1475 -0.5676 -0.0029 0.5421 1.1103 1.7088 2.2607 3.4865	-0.0119 -0.0151 -0.0140 -0.0112 -0.0126 -0.0151 -0.0115 -0.0091	0.0875 0.1178 0.1049 0.0827 0.0931 0.1162 0.0843 0.0622 0.0853	0.0051 0.0036 0.0041 0.0037 0.0036 0.0035 0.0031 0.0030 0.0031	0.3862 0.3858 0.3838 0.3872 0.3846 0.3854 0.3854	0.1620 0.1611 0.1604 0.1598 0.1597 0.1600 0.1607 0.1609 0.1611	0.2242 0.2247 0.2234 0.2273 0.2249 0.2246 0.2248 0.2245 0.2245	30. 30. 30. 30. 30.

MOE	DEL 946.2	2 CONI	FIG. 2.0	00 , M	ACH 1.75	PHI =	•	
Q=	8.29 PS	RE PER	IN.= .48	E06 T0=	9C. DEG.F	POJ/PT	S = 1	0.
P0=	= 107.0 (CHHC PTS=	3,8665 P	SI	RUN	NO. 024026	9115	
ALPHA	CN	CH	cs	CY	CR CAT	СРВ	CAF	RUN
4.09			-0.0224		0.0071 0.39			31.
3.08			-0.0211		0.0063 0.39			31.
2.06	0.2407		-0.0197		0.0058 0.39			31.
1.54		•	-0.0190		0.0045 0.39			31.
	0.1107		-0.0180		0.0047. 0.38			31.
0.51	0.0513		-0.0176		0.0040 0.38			31.
-0.	-0.0094		-0.0166		0.0036 0.38			31.
	-0.0695		-0.0148		0.0035 0.38			31.
	-0.1316		-0.0141		0.0034 0.38			31.
	-0.1949		-0.0152		0.0033 0.39			31,
	-0.2530		-0.0145		0.0032 0.38			31.
	-0.3816	3.5575	_		0.0032 0.38			31.
-4.07	-0.5142	4.3179	-0.0103	0.0818	0.0035 0.38	02 U.1518	0.2244	31.
	PEL 946.		FIG. 2.0		ACH 1.75	PHI =	• 5 = 2	0.
Q=	8.29 PS	RE PER	IN.= .48	E06 T0=	90. DEG.F	POJ/PT	_	o .
Q=	8.29 PS		IN.= .48	E06 T0=	90. DEG.F		_	o .
Q=	8.29 PS	RE PER	IN.= .48	E06 T0=	90. DEG.F	POJ/PT	_	0. RUN
Q= 90=	8.29 PS	RE PER CMHG PTS=	IN.= .48 3.8665 P	E06 TO=	90. DEG.F	POJ/PT NO. 024026 CPB	9116 CAF	
Q= PO= ALPHA	8.29 PS	RE PER CMHG PTS= CM -4.6726	IN.= .48 3.8665 P	E06 T0= SI CY 0.1412	90. DEG.F RUN CR CAT	POJ/PT NO. 024026 CPB	9116 CAF 0-2355	RUN
Q= P0= ALPHA 4.08	8.29 PS: = 107.0 (CN 0.4791	RE PER CMHG PTS= CM -4.6726 -3.4261	IN.= .48 3.8665 P CS -0.0166	E06 T0= . SI CY 0.1412 0.1933	90. DEG.F RUN CR CAT 0.0081 0.40	POJ/PT NO. 024026 CPB 66 0.1714 45 0.1710	9116 CAF 0.2355 0.2335	RUN 32 o
Q= PO= ALPHA 4.08 3.07	8.29 PS: = 107.0 (CN 0.4791 0.3487	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024	IN.= .48 3.8665 P CS -0.0166 -0.0219	E06 T0= . SI CY 0.1412 0.1933 0.1610	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40	POJ/PT NO. 024026 CPB 666 0.1714 45 0.1710	9116 CAF 0-2355 0-2335 0-2305	RUN 32 . 32 .
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01	8.29 PS = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192 -0.0206	E06 T0= . SI CY 0.1412 0.1933 0.1610 0.1661 0.1804	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39	POJ/PT NO. 024026 CPB 66 0.1714 45 0.1710 00 0.1695 68 0.1658 90 0.1647	9116 CAF 0-2355 0-2335 0-2305 0-2309 0-2343	RUN 32. 32. 32. 32. 32.
Q= PO= ALPHA 4.08 3.07 2.04 1.52	8.29 PS = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192	E06 T0= . SI CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39 0.0030 0.39	POJ/PT NO. 024026 CPB 666 0.1714 455 0.1710 000 0.1695 68 0.1658 90 0.1647 37 0.1638	9116 CAF 0-2355 0-2335 0-2305 0-2309 0-2343 0-2299	RUN 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01	8.29 PS: = 107.0 (CN 0.4791 0.3487 0.2200 0.1561 0.0908 0.0294 -0.0320	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192 -0.0206 -0.0184 -0.0167	E06 T0= . SI CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39 0.0030 0.39 0.0029 0.39	POJ/PT NO. 024026 CPB 666 0.1714 45 0.1710 000 0.1695 68 0.1658 90 0.1647 37 0.1638 18 0.1633	9116 CAF 0.2355 0.2335 0.2305 0.2309 0.2343 0.2299 0.2285	RUN 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01 -0.52	8.29 PS = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908 0.0294 -0.0320 -0.0914	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874 0.7499	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0167 -0.0177	CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486 0.1569	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0047 0.39 0.0030 0.39 0.0029 0.39 0.0036 0.39	POJ/PT NO. 024026 CPB 66 0.1714 45 0.1710 00 0.1695 68 0.1658 90 0.1647 37 0.1638 18 0.1633 12 0.1628	9116 CAF 0.2355 0.2335 0.2305 0.2309 0.2343 C.2299 0.2285 0.2283	RUN 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01 -0.52 -1.03	8.29 PS = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908 0.0294 -0.0320 -0.0914 -0.1534	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874 0.7499 1.3341	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0197 -0.0177	CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486 0.1569 0.1516	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0047 0.39 0.0037 0.39 0.0030 0.39 0.0029 0.39 0.0030 0.39	POJ/PT NU. 024026 CPB 66 0.1714 45 0.1710 00 0.1695 68 0.1658 90 0.1647 37 0.1638 18 0.1633 12 0.1628 06 0.1631	9116 CAF 0.2355 0.2335 0.2305 0.2309 0.2343 0.2299 0.2285 0.2283 0.2276	RUN 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01 -0.52 -1.03 ~1.54	8.29 PS: = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908 0.0294 -0.0320 -0.0914 -0.1534 -0.2214	RE PER CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874 0.7499 1.3341 1.9808	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192 -0.0184 -0.0157 -0.0177 -0.0170 -0.0124	CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486 0.1569 0.1516 0.1071	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39 0.0030 0.39 0.0029 0.39 0.0030 0.39 0.0030 0.39	POJ/PT NU. 024026 CPB 66 0.1714 45 0.1710 00 0.1695 68 0.1647 37 0.1638 18 0.1633 12 0.1628 06 0.1631 08 0.1636	9116 CAF 0.2355 0.2335 0.2305 0.2343 0.2243 0.2285 0.2283 0.2276 0.2271	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01 -0.52 -1.03 -1.54 -2.04	8.29 PS: 	CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874 0.7499 1.3341 1.9808 2.4947	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192 -0.0167 -0.0177 -0.0170 -0.0124 -0.0136	CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486 0.1569 0.1516 0.1071 0.1187	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39 0.0039 0.39 0.0039 0.39 0.0039 0.39 0.0039 0.39 0.0030 0.39 0.0030 0.39 0.0030 0.39	POJ/PT NO. 024026 CPB 666 0.1714 45 0.1710 00 0.1695 68 0.1658 90 0.1647 37 0.1638 18 0.1633 12 0.1628 06 0.1631 08 0.1636	9116 CAF 0.2355 0.2335 0.2305 0.2343 0.2249 0.2285 0.2283 0.2276 0.2271 0.2259	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 4.08 3.07 2.04 1.52 1.01 0.50 -0.01 -0.52 -1.53 -2.04 -3.06	8.29 PS: = 107.0 (CN 0.4791 0.3487 9.2200 0.1561 0.0908 0.0294 -0.0320 -0.0914 -0.1534 -0.2214	CMHG PTS= CM -4.6726 -3.4261 -2.2024 -1.5944 -0.9752 -0.3923 0.1874 0.7499 1.3341 1.9808 2.4947 3.7311	IN.= .48 3.8665 P CS -0.0166 -0.0219 -0.0184 -0.0192 -0.0167 -0.0177 -0.0170 -0.0124 -0.0136	CY 0.1412 0.1933 0.1610 0.1661 0.1804 0.1641 0.1486 0.1569 0.1516 0.1071 0.1187 0.1444	90. DEG.F RUN CR CAT 0.0081 0.40 0.0067 0.40 0.0047 0.40 0.0044 0.39 0.0037 0.39 0.0030 0.39 0.0029 0.39 0.0030 0.39 0.0030 0.39	POJ/PT NO. 024026 CPB 666 0.1714 45 0.1710 00 0.1695 68 0.1658 90 0.1647 37 0.1638 18 0.1638 12 0.1628 06 0.1631 08 0.1636 93 0.1635 70 0.1633	9116 CAF 0.2355 0.2335 0.2305 0.2343 0.2299 0.2285 0.2283 0.2276 0.2271 0.2259 0.2237	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.

A CALL CONTRACTOR OF THE PROPERTY OF THE PROPE

THE THE PROPERTY OF THE PROPER

MODEL 946.2	CONFI	G. 2.000	MA	CH 1.75	PHI =	•
Q= 8.29 PS1	RE PER I	N.= .48E08	5 TO=	90. DEG.F	POJ/PTS =	40.
90= 107.0 CH	IHG PTS= 3	.8665 PS1		RUN NO	. 0240269117	
ALPHA CN	CH	cs	CY	CR CAT	CPB CAF	RUN
4.05 0.4373	-4.3990 -	0.0231		0.0113 0.4177		
3.04 0.3042	-3.1223 -			0.0099 0.4126		
2.02 0.1716	-1.8564 -			0.0062 0.4068		
1.49 0.1044	-1.2177 -			0.0055 0.4037		
0.98 0.0424	-0.6319 -			0.0048 0.4011		
0.47 -0.0209	-0.0314 -			0.0030 0.3993		
-0.04 -0.0816	0.5413 -			0.0012 0.3981		
-0.55 -0.1463	1.1560 -			0.0008 0.3982		
-1.06 -0.2090	1.7461 -			0.0010 0.3977 0.0008 0.3965		
-1.57 -0.2710 -2.07 -0.3311	2.3333 - 2.9043 -			0.0007 0.3965		
-3.10 -0.4590	4.1140 -			0.0015 0.3935		-
~4.11 -0.5916	5.3730 -			0.0003 0.3931		
MODEL 946.2	CONF I	G. 2.000	МА	CH 1.75	PHI =	•
MODEL 946.2 Q≈ 8.29 PSI		G. 2.000 N.= .48E06		CH 1.75	PHI = . POJ/PTS =	80.
	RE PER I	N.= .48E06		90. DEG.F	•	
Q= 8.29 PSI	RE PER I	N.= .48E06		90. DEG.F	POJ/PTS =	
Q= 8.29 PSI PO= 107.0 CH ALPHA CN	RE PER III HG PTS= 3	N.= .48E06 .8665 PSI CS	5 TO=	90. DEG.F RUN NO	POJ/PTS = - 0240269118 - CP8 CAF	RUN
Q= 8.29 PSI PO= 107.0 CM	RE PER I	N.= .48E06 :.8665 PSI CS 0.0242	CY 0.2030	90. DEG.F RUN NO CR CAT	POJ/PTS = - 0240269118 - CP8 CAF - 0.1853 0.24	RUN 49 34. 23 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404	RE PER 11 HG PTS= 3 CH -3.7301 -	N.= .48E06 .8665 PSI CS 0.0242 0.0204	CY 0.2030	90. DEG.F RUN NO CR CAT 0.0131 0.4302	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24	RUN 49 34. 23 34. 34 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008	RE PER III HG PTS= 3 CH -3.7301 -1 -2.3876 -1	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194	CY 0.2030 0.1705 0.1627 0.1122	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1726 0.24	RUN 49 34. 23 34. 34 34. 37 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657	RE PER III IHG PTS= 3 CM -3.73012.38761.09360.4031 0.2120	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163	CY 0.2030 0.1705 0.1627 0.1122 0.1316	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0067 0.4139	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24	RUN 49 34. 23 34. 34 34. 37 34. 42 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069	RE PER III CM -3.73012.38761.09360.4031	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1675 0.24	RUN 49 34. 23 34. 34 34. 37 34. 42 34. 33 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013	RE PER III HG PTS= 3 CM -3.73012.38761.09360.4031 0.2120 0.8787 1.4483	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163 0.0198 0.0202	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108 0.0023 0.4069	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1675 0.24 0.1649 0.24	RUN 49 34. 23 34. 34 34. 37 34. 42 34. 33 34. 19 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013 -0.60 -0.2660	RE PER III HG PTS= 3 CM -3.73012.38761.0936 0.4031 0.2120 0.8787 1.4483 2.0614	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163 0.0198 0.0202 0.0152	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712 0.1297	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108 0.0023 0.4069 0.0010 0.4057	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1675 0.24 0.1649 0.24 0.1633 0.24	RUN 49 34. 23 34. 34 34. 37 34. 42 34. 33 34. 19 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013 -0.60 -0.2660 -1.11 -0.3299	RE PER III HG PTS= 3 CM -3.7301 -1 -2.3876 -1 -0.4031 -1 0.2120 -1 0.8787 -1 1.4483 -1 2.0614 -1 2.6637 -1	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0141 0.0163 0.0198 0.0202 0.0152 0.0166	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712 0.1297 0.1456	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4164 0.0057 0.4108 0.0023 0.4069 0.0023 0.4069 0.0010 0.4057	POJ/PTS = . 0240269118 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1697 0.24 0.1693 0.24 0.1633 0.24 0.1629 0.24	RUN 49 34. 23 34. 34. 37 34. 42 34. 33 34. 19 34. 24 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013 -0.60 -0.2660 -1.11 -0.3299 -1.63 -0.3939	RE PER III HG PTS= 3 CM -3.7301 -1 -2.3876 -1 -0.4031 -1 0.2120 0.8787 -1 1.4483 -1 2.6637 -1 3.2698 -1	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163 0.0198 0.0202 0.0152 0.0166 0.0144	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712 0.1297 0.1456 0.1286	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108 0.0023 0.4069 0.0010 0.4057 0.0009 0.4038 0.0008 0.4040	POJ/PTS = . 0240269118 CP8	RUN 49 34. 23 34. 34. 37 34. 42 34. 33 34. 19 34. 24 34. 10 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013 -0.60 -0.2660 -1.11 -0.3299 -1.63 -0.3939 -2.13 -0.4553	RE PER III CH -3.73012.38761.09360.4031 0.2120 0.8787 1.4483 2.0614 2.6637 3.2698 3.8523	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163 0.0198 0.0202 0.0152 0.0152 0.0166 0.0144 0.0159	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712 0.1297 0.1286 0.1286 0.1378-	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108 0.0023 0.4069 0.0010 0.4057 0.0009 0.4038 0.0008 0.4040 0.0007 0.4027	POJ/PTS = . 0240269113 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1675 0.24 0.1633 0.24 0.1633 0.24 0.1639 0.24 0.1639 0.24 0.1649 0.24 0.1649 0.24	RUN 49 34. 23 34. 34. 37 34. 42 34. 33 34. 19 34. 24 34. 10 34. 00 34. 84 34.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.99 0.3404 2.98 0.2008 1.96 0.0657 1.44 -0.0069 0.92 -0.0715 0.42 -0.1412 -0.09 -0.2013 -0.60 -0.2660 -1.11 -0.3299 -1.63 -0.3939	RE PER III HG PTS= 3 CM -3.7301 -1 -2.3876 -1 -0.4031 -1 0.2120 0.8787 -1 1.4483 -1 2.6637 -1 3.2698 -1	N.= .48E06 .8665 PSI CS 0.0242 0.0204 0.0194 0.0141 0.0163 0.0198 0.0202 0.0152 0.0152 0.0166 0.0144 0.0159 0.0162	CY 0.2030 0.1705 0.1627 0.1122 0.1316 0.1670 0.1712 0.1297 0.1297 0.1286 0.1378 0.1424	90. DEG.F RUN NO CR CAT 0.0131 0.4302 0.0114 0.4238 0.0074 0.4195 0.0063 0.4164 0.0057 0.4139 0.0038 0.4108 0.0023 0.4069 0.0010 0.4057 0.0009 0.4038 0.0008 0.4040	POJ/PTS = - 0240269113 CP8 CAF 0.1853 0.24 0.1816 0.24 0.1761 0.24 0.1728 0.24 0.1697 0.24 0.1675 0.24 0.1633 0.24 0.1633 0.24 0.1643 0.24 0.1643 0.23 0.1643 0.23	RUN 49 34. 23 34. 34. 37 34. 42 34. 33 34. 19 34. 10 34. 00 34. 84 34.

MO	DEL 94	6.2	CONF	IG.	2.000	MA	CH 1.79	5	PHI =	45.	
Çs	2.29	PSI RE	FER	IN.=	-48E06	T0=	90. DE	G.F	POJ/P	rs =	•
PO	= 167.	O CHHG	PTS=	3.866	SS PSI			RUN NO.	024026	59119	
ALPHA	. CN	С	M	CS	5	CY	CR	CAT	CPB	CAF	RUN
4.12	0.50	29 -4.	7531	-0.03	312	0.2819	0.0056	0.3987	0.1660	0.2327	35.
3.11		_	_	-0.02				0.3962			
2.06				-0.02				0.3925			
1.56				-0.01				0.3907			
1.05				-0.01	_			0.3879			
0.54				-0.01				0.3883			
0.03				-0.01				0.3861			
	-0.05			-0.01				0.3851			
	-0.12			-0.01			_	0.3842			
	-0.18			-0.01				0.3847			
	-0.24			-0.01				0.3851			
	-0.50	-		-0.00				0.3839			
-7.04	-0.50	or 4.	1000	-0.00	101	0.0447	0.0048	U.3040	0.1003	0.2119	33.
ма	DEL 94	6.2	CONF	IG.	2.000	MA	ICH 1.75	j	PHI =	45.	
	DEL 94	-			2.000 .48E06		ACH 1.75		PHI =		10.
Ç=	8.29	-	PER	[N.=	.48E06			G.F		rs =	10.
Ç=	8.29 H	PSI RE O CMHG	PER PTS=	[N.=	.48E06			G.F	P0J/P1	rs =	10. RUN
Q= P0	8.29 = 107.6	PSI RE O CMHG	PER PTS=	IN.= 3.866	•48E06 55 PSI	T0=	90. DE	EG.F R. NO.	POJ/P1 024026 CP8	rs = 59120 Caf	RUN
Q= PO Alpha	8.29 = 107.6 CN	PSI RE 0 CMHG C 55 -4.	PER PTS= M	IN.= 3.866 CS	•48E06 65 PSI 6	T0= CY 0.3287	90. DE CR 0.0137	G.F R. NO. Cat	POJ/P1 024026 CP8 0-1655	TS = 59120 CAF 0.2334	RUN 36•
Q= PO ALPHA 4.11	8.29 = 107.6 CN 0.50 0.36	PSI RE 0 CMHG C 55 -4. 73 -3.	PER PTS= M 8231 5135	IN.= 3.866 CS	•48E06 65 PSI 6 623	CY 0.3287 0.3770	90. DE CR 0.0137 0.0108	G.F R. NO. CAT 0.3989	POJ/P1 024026 CPB 0.1655 0.1649	TS = 59120 CAF 0.2334 0.2317	RUN 36. 36.
Q= PO ALPHA 4.11 3.10	8.29 = 107.6 CN 0.50 0.36 0.24	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2.	PER PTS= M 8231 5135 3936	IN.= 3.866 CS -0.04	•48E06	CY 0.3287 0.3770 0.3000	90. DE CR 0.0137 0.0108 0.0063	CAT 0.3989 0.3966	POJ/P1 . 024026 . CPB 0.1655 0.1649 0.1663	rs = 59120 CAF 0.2334 0.2317 0.2264	RUN 36. 36. 36.
G= PO ALPHA 4.11 3.10 2.08	8.29 = 107.4 CN 0.50 0.36 0.24 0.18	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1.	PER PTS= M 8231 5135 3936 7786	IN.= 3.866 CS -0.04 -0.04	.48E06 55 PSI 623 663 881 883	CY 0.3287 0.3770 0.3000 0.3090	90. DE CR 0.0137 0.0108 0.0063 0.0032	CAT 0.3989 0.3966 0.3926	POJ/P1 . 024026 . CPB 0.1655 0.1649 0.1663 0.1658	rs = 59120 CAF 0.2334 0.2317 0.2264 0.2260	RUN 36. 36. 36.
Q= PO ALPHA 4.11 3.10 2.08 1.55 1.05 0.53	8.29 I	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0.	PER PTS = M 8231 5135 3936 7786 1842 6377	IN.= 3.866 CS -0.04 -0.03 -0.03 -0.03	•48E06 55 PSI •23 •63 •88 •88 •88	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885	POJ/PT . 024026 . CPB 0.1655 0.1649 0.1663 0.1658 0.1630 0.1623	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262	RUN 36. 36. 36. 36. 36.
Q= PO ALPHA 4.11 3.10 2.08 1.55 1.05 0.53	8.29 = 107.4 CN 0.50 0.36 0.24 0.18 0.11	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0.	PER PTS = M 8231 5135 3936 7786 1842 6377	IN.= 3.866 CS -0.04 -0.03 -0.03 -0.03	•48E06	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018 0.0035	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885	POJ/PT . 024026 CP8 0.1655 0.1649 0.1663 0.1658 0.1630 0.1623 0.1617	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262 0.2239	RUN 36. 36. 36. 36. 36. 36.
Q= P0 ALPHA 4.11 3.10 2.08 1.05 0.53 0.02 -0.49	8.29 I	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0. 60 0. 33 0.	PER PTS = M 8231 5135 3936 7786 1842 6377 0096 6562	IN.= 3.866 CS -0.04 -0.03 -0.03 -0.03 -0.02 -0.02	•48E06	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050 0.1464	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018 0.0035 0.0055	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885 0.3856 0.3856	POJ/PT . 024026 CP8 0.1655 0.1649 0.1663 0.1658 0.1630 0.1623 0.1617 0.1616	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262 0.2239	RUN 36. 36. 36. 36. 36. 36.
Q= P0 ALPHA 4.11 3.10 2.08 1.55 1.05 0.53 0.02 -0.49 -1.00	8.29 I	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0. 60 0. 33 0. 93 1.	PER PTS = M 8231 5336 7786 1842 6377 0096 6562 2890	IN.= 3.866 CS -0.04 -0.03 -0.03 -0.03 -0.02 -0.02 -0.02	•48E06 65 PSI 623 663 681 883 888 995 275 223 155	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050 0.1464 0.0736	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018 0.0035 0.0055 0.0070	CAT 0.3989 0.3966 0.3926 0.3928 0.3885 0.3856 0.3852 0.3841	POJ/PT . 024026 CPB 0.1655 0.1649 0.1663 0.1658 0.1630 0.1623 0.1617 0.1616 0.1607	CAF 0.2334 0.2317 0.2264 0.2260 0.2262 0.2262 0.2239 0.2242	RUN 36. 36. 36. 36. 36. 36. 36.
Q= P0 ALPHA 4.11 3.10 2.08 1.55 1.05 0.53 0.02 -0.49 -1.00 -1.50	8.29 = 107.4 	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0. 60 0. 33 0. 93 1.	PER PTS = M 8231 5135 3936 7786 1842 6377 6562 2890 8758	1N.= 3.866 -0.04 -0.03 -0.03 -0.02 -0.02 -0.01 -0.01	.48E06 55 PSI 623 663 381 383 389 275 223 155	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050 0.1464 0.0736 0.0374	90. DE CR 0.0137 0.0108 0.0063 0.0017 0.0018 0.0035 0.0055 0.0070	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885 0.3852 0.3851 0.3818	POJ/PI . 024026 CPB 0.1655 0.1649 0.1663 0.1658 0.1630 0.16161 0.1616 0.16161 0.16161	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262 0.2239 0.2242 0.2234 0.2206	RUN 36. 36. 36. 36. 36. 36. 36.
Q= P0 ALPHA 4.11 3.10 2.08 1.55 1.05 0.53 0.02 -0.49 -1.50 -1.50 -2.01	8.29 = 107.50 	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0. 60 0. 33 0. 93 1. 168 2.	PER PTS = M 8231 5135 3936 7786 1842 6377 0096 6562 2890 8758 4989	IN.= 3.866 CS -0.04 -0.03 -0.03 -0.02 -0.02 -0.01 -0.01	.48E06 55 PSI 623 663 881 883 888 295 223 1255 115	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050 0.1464 0.0736 0.0374 0.0871	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018 0.0035 0.0055 0.0070 0.0070	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885 0.3856 0.3854 0.3818 0.3830	POJ/PI . 024026 CPB 0.1655 0.1649 0.1663 0.1658 0.1630 0.16167 0.1616 0.16160 0.1612 0.1625	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262 0.2242 0.2234 0.2206 0.2206	RUN 36. 36. 36. 36. 36. 36. 36. 36.
Q= P0 ALPHA 4.11 3.10 2.08 1.55 1.05 0.53 0.02 -0.49 -1.50 -2.01 -3.03	8.29 = 107.4 	PSI RE 0 CMHG C 55 -4. 73 -3. 82 -2. 29 -1. 98 -1. 15 -0. 60 0. 33 0. 93 1. 15 1. 68 2. 20 3.	PER PTS = M 8231 5135 3936 7786 1842 6377 0096 6589 8758 4989 6731	1N.= 3.866 -0.04 -0.03 -0.03 -0.02 -0.02 -0.01 -0.01	.48E06 55 PSI 623 663 381 388 388 275 223 125 115 163	CY 0.3287 0.3770 0.3000 0.3090 0.3216 0.2302 0.2050 0.1464 0.00374 0.0871 0.0711	90. DE CR 0.0137 0.0108 0.0063 0.0032 0.0017 0.0018 0.0035 0.0055 0.0070 0.0065	CAT 0.3989 0.3966 0.3926 0.3918 0.3903 0.3885 0.3852 0.3851 0.3818	POJ/P1 . 024026 . CPB 0.1655 0.1649 0.1663 0.1658 0.1630 0.16167 0.1616 0.1612 0.1625 0.1659	CAF 0.2334 0.2317 0.2264 0.2260 0.2273 0.2262 0.2239 0.2242 0.2234 0.2206 0.2173	RUN 36. 36. 36. 36. 36. 36. 36. 36.

HOUFL 946.	2 CONI	FIG. 2.000	HA	ICH 1.75	PHI = 45.	
Q= 8.29 PS	I RE PER	IN.= .48E0	5 104	90. DEG.F	POJ/PTS =	20.
PO= 107.0	CMHG PTS=	3.8665 PSI		RUN NO	0. 0240269121	
ALPHA CN	СМ	CS	CY	CR CAT	CPB CAF	RUN
4.10 0.4935	-4.7387	-0.0630	0.4702	0.0205 0.3980	0.1639 0.234	1 37.
3.09 0.3618	-3.4986	-0.0624	0.4812	0.0133 0.3969	0.1649 0.232	0 37.
2.07 0.2377	-2.3389	-0.0592	0.4713	0.0045 0.397	0.1672 0.229	9 37.
1.55 0.1785	-1.7930	-0.0591	0.4810-	0.0018 0:394	3 0.1659 0.228	. 37.
1.03 0.1084		-0.0655			5 0.1640 G.227	
0.52 0.0489	-0.5693	-0.0560			2 0.1636 0.227	
0.02 -0.0183		-0.0435			3 0.1635 0.225	
-0.49 -0.0937		-0.0311			7 0.1631 0.223	
-1.00 -0.1632		-0.0218			9 0.1634 0.221	
-1.51 -0.2303		-0.0213			0.1635 0.218	
-2.02 -0.2888		-0.0208			0.1639 0.219	
-3.04 -0.4145					2 0.1656 0.216	
-4.06 -0.5416	5.0507	-0.0263	0.1511	0.0050 0.3829	5 0.1714 0.211	1 37.
MUDEL 946. Q= 8.29 PS		FIG. 2.000 IN.= .48E0		ACH 1.75	PHI = 45. POJ/PTS =	40.
Q= 8.29 PS	I RE PER			90. DEG.F		
Q= 8.29 PS	I RE PER	IN.= .48E0		90. DEG.F	POJ/PTS =	
Q= 8.29 PS PO= 107.0 ALPHA CN	I RE PER CMHG PTS=	1N.= .48E00 3.8665 PSI CS	5 TO=	90. DEG.F RUN NO CR CAT	POJ/PTS = 0. 0240269122 CPB CAF	40. RUN
Q= 8.29 PS PO= 107.0	I RE PER CMHG PTS= CM -4.5558	IN.= .48E0	5 TO= CY 0.7470	90. DEG.F RUN NO CR CAT 0.0252 0.4042	POJ/PTS =	40. RUN 6 38.
Q= 8.29 PS PO= 107.0 ALPHA CN 4.09 0.4663	I RE PER CMHG PTS= CM -4.5558 -3.3438	IN.= .48E00 3.8665 PSI CS -0.1021	CY 0.7470 0.7383	90. DEG.F RUN NO CR CAT 0.0252 0.4042 0.0140 0.4044	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.237	40. RUN 6 38. 0 38.
Q= 8.29 PS PO= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987	CY 0.7470 0.7383 0.8127	90. DEG.F RUN NO CR CAT 0.0252 0.4042 0.0140 0.4044 0.0023 0.4023	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.2374 4 0.1695 0.235	40. RUN 6 38. 0 38. 6 38.
Q= 8.29 PS PO= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031	CY 0.7470 0.7383 0.8127 0.8876-	90. DEG.F RUN NO CR CAT 0.0252 0.4043 0.0140 0.4044 0.0023 0.4021 -0.0060 0.4003	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.237 4 0.1695 0.235 3 0.1682 0.234	80. RUN 6 38. 0 38. 6 38.
Q= 8.29 PS PO= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089	CY 0.7470 0.7383 0.8127 0.8876- 0.8328-	90. DEG.F RUN NO CR CAT 0.0252 0.4042 0.0140 0.4044 0.0023 0.4023 -0.0060 0.4002 -0.0069 0.4006	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.237 4 0.1695 0.235 3 0.1682 0.234 2 0.1671 0.233	8UN 6 38. 0 38. 6 38. 1 38. 3 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865	1 RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1025	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587	90. DEG.F RUN NO CR CAT 0.0252 0.4043 0.0140 0.4044 0.0023 0.4028 -0.0060 0.4000 -0.0089 0.4000 -0.0062 0.3999 0.0005 9.3964	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.237 4 0.1695 0.235 3 0.1682 0.234 2 0.1671 0.233 5 0.1663 0.234 6 0.1669 0.234 6 0.1669 0.234	6 38. 0 38. 6 38. 1 38. 3 38. 5 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865 0.51 0.0228	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120 0.3806 1.1872	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1026 -0.0963 -0.0874 -0.0673	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587 0.4354	90. DEG.F RUN NO CR CAT 0.0252 0.4044 0.0140 0.4044 0.0023 0.4026 0.0060 0.4006 0.0062 0.3999 0.0005 0.3964 0.0139 0.3916	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.2376 4 0.1695 0.234 3 0.1682 0.234 2 0.1663 0.234 6 0.1669 0.234 6 0.1669 0.234 6 0.1663 0.231 6 0.1663 0.231	8UN 6 38. 0 38. 6 38. 1 38. 3 38. 1 38. 3 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865 0.51 0.0228 -0.01 -0.0585	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120 0.3806 1.1872	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1026 -0.0963 -0.0874	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587 0.4354 0.2531	90. DEG.F RUN NO CR CAT 0.0252 0.4044 0.0140 0.4044 0.0023 0.4026 -0.0060 0.4006 -0.0062 0.3995 0.0005 0.3964 0.0139 0.3916 0.0230 0.3916	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.2376 4 0.1695 0.234 3 0.1682 0.234 2 0.1663 0.234 6 0.1669 0.234 6 0.1663 0.234 6 0.1663 0.236 7 0.1663 0.236 0 0.1663 0.236	8UN 6 38. 0 38. 1 38. 3 38. 1 38. 3 38. 3 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865 0.51 0.0228 -0.01 -0.0585 -0.52 -0.1399 -1.03 -0.2146 -1.53 -0.2848	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120 0.3806 1.1872 1.9176 2.5998	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1026 -0.0963 -0.0874 -0.0673 -0.0512 -0.0476	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587 0.4354 0.2531	90. DEG.F RUN NO CR CAT 0.0252 0.4042 0.0140 0.4044 0.0023 0.4028 0.0060 0.4006 0.0062 0.3999 0.0005 0.3966 0.0139 0.3916 0.0230 0.3916 0.0281 0.3906	POJ/PTS = 0- 0240269122 CPB CAF 2 0-1666 0-237 4 0-1695 0-234 3 0-1682 0-234 2 0-1661 0-234 5 0-1663 0-234 6 0-1663 0-234 6 0-1663 0-234 6 0-1663 0-234 7 0-1660 0-224	40. RUN 6 38. 0 38. 6 38. 1 38. 3 38. 3 38. 3 38. 3 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865 0.51 0.0228 -0.01 -0.0585 -0.52 -0.1399 -1.03 -0.2146 -1.53 -0.2848 -2.04 -0.3466	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120 0.3876 1.1872 1.9176 2.5998 3.1824	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1026 -0.0963 -0.0874 -0.0673 -0.0512 -0.0476 -0.0403	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587 0.45541 0.2041 0.1345	90. DEG.F RUN NO CR CAT 0.0252 0.4042 0.0140 0.4044 0.0023 0.4023 0.0060 0.4002 0.0062 0.3999 0.0005 0.3964 0.0139 0.3910 0.0281 0.3900 0.0281 0.3900	POJ/PTS = 0. 0240269122 CPB CAF 2 0.1666 0.237 4 0.1695 0.235 3 0.1682 0.234 2 0.1671 0.233 5 0.1663 0.234 5 0.1669 0.234 6 0.1653 0.236 0 0.1653 0.226 0 0.1660 0.226 0 0.1660 0.224	80. RUN 6 38. 0 38. 6 38. 1 38. 3 38. 3 38. 0 38. 0 38.
Q= 8.29 PS P0= 107.0 ALPHA CN 4.09 0.4663 3.07 0.3363 2.05 0.2134 1.53 0.1464 1.01 0.0865 0.51 0.0228 -0.01 -0.0585 -0.52 -0.1399 -1.03 -0.2146 -1.53 -0.2848	I RE PER CMHG PTS= CM -4.5558 -3.3438 -2.2010 -1.5761 -1.0236 -0.4120 0.3806 1.1872 1.9175 2.5998 3.1824 4.3144	IN.= .48E00 3.8665 PSI CS -0.1021 -0.0987 -0.1031 -0.1089 -0.1026 -0.0963 -0.0874 -0.0673 -0.0512 -0.0476	CY 0.7470 0.7383 0.8127 0.8876- 0.8328- 0.7635- 0.6587 0.42531 0.2041 0.1345 0.1962	90. DEG.F RUN NO CR CAT 0.0252 0.4044 0.0140 0.4044 0.0023 0.4023 0.0060 0.4002 0.0062 0.3995 0.0005 0.3916 0.0139 0.3916 0.0230 0.3916 0.0231 0.3900 0.0281 0.3900 0.0287 0.3876	POJ/PTS = 0- 0240269122 CPB CAF 2 0-1666 0-237 4 0-1695 0-234 3 0-1682 0-234 2 0-1661 0-234 5 0-1663 0-234 6 0-1663 0-234 6 0-1663 0-234 6 0-1663 0-234 7 0-1660 0-224	80. RUN 6 38. 6 38. 6 38. 1 38. 3 38. 1 38. 3 38. 3 38. 3 38. 3 38.

Ä	CDEL	946.2	CON	FIG. 2.000) н,	ACH 1.7	5	PHI =	45.	
Q	= 8.	29 PSI	RE PER	IN.= .48E0	6 TO=	90. D	EG.F	90.1/P	TS =	80.
ρ	0 ≈ 1	07.0 CM	HG PYS=	3.8665 PSI			RUN NO	02402	69123	
ALPH	A	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.0	6 0	.4094	-4.1851	-0.1938	1.4345	0.0281	0.4171	0.1714	0.2457	39.
3.0	4 0	.2768	-2.9517	-0.1860	1.3936	0.0137	0.4186	0.1743	0.2443	39.
2.0	1 0	1446	-1.7199	-0.1913	1.4840	-0.0010	0.4151	0.1689	0.2462	39.
2.4	9 0	.0713	-1.0353	-0.1929	1.5187	-0.0091	0.4097	0.1677	0.2419	39.
0.9	7 0	.0009	-0.3702	-0.1917	1.5109	0.0103	0.4102	0.1666	0.2435	39.
0.4	6 -0	.0687	0.3005	-0.1814	1.4056	-0.0072	G-4063	0.1658	0.2406	39.
		.1419		-0.1639			0.4017			
		.2209		-0.1454			0.4003			
		.3007		-0.1316			0.3970			
		.3753		-0.1199			0.3951			
		.4417		-0.1128			0.3941			
	-	.5752		-0.1076			0.3929			
-4.1	2 -0	.7001	6.3618	-0.1065	0.6049	0.0280	0.3939	0.1710	0.2229	39.
		946.2		FIG. 2.000		ACH 1.75		PHI =	_	
		. 946.2 .29 PSI		FIG. 2.000 IN.= .48E0		90. DI		PHI =	_	•
Q	= 8.	29 PSI	RE PER		6 TO=		EG.F		rs =	•
Q	= 8. 0= 1	29 PSI	RE PER	IN.= .48E0	6 TO=		EG.F	P0J/P1	rs =	RUN
Q P ALPH	= 6. 0= 1 A	29 PSI .07.0 CM	RE PER HG PTS=	IN.= .48E0	6 TO=	90. DI	EG.F RUN NO.	PØJ/P1 024026 CPB	TS = 59124 CAF	RUN
Q P ALPH 4.0	= 8. 0= 1 A 9 U	.29 PSI .07.0 CMI	RE PER HG PTS= CM -4.8237	IN.= .48E0 3.8665 PSI	6 TO= CY 0.0533	90. DI CR 0.0061	EG.F RUN NO.	PØJ/P1 024020 CPB 0-1639	TS = 59124 CAF 0-2243	RUN 40.
Q P ALPH 4.0	= 8.0 0= 1 A 9 0 8 .0	.29 PSI .07.0 CMI .5090	RE PER HG PTS= CH -4.8237 -3.6002	IN.= .48E0 3.8665 PSI CS -0.0081	6 TO= CY 0.0533 0.1066	90. DI CR 0.0061 0.0059	EG.F RUN NO. CAT 0.3882	PØJ/P1 024026 CPB 0.1639 0.1642	TS = 59124 CAF 0-2243 0-2225	RUN 40. 40.
Q P ALPH 4.0 3.0	= 8.0 0= 1 A 9 0 8 .0 6 0	.29 PSI .07.0 CMI CN 0.5090 0.3804	RE PER HG PTS= CH -4.8237 -3.6002 -2.3973	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139	6 TO= CY 0.0533 0.1066 0.1138	90. DI CR 0.0061 0.0059 0.0047	EG.F RUN NO. CAT 0.3882 0.3867	PØJ/P1 024020 CPB 0.1639 0.1642 0.1645	TS = 59124 CAF 0.2243 0.2225 0.2206	RUN 40. 40. 40.
Q P ALPH 4.0 3.0 2.0 1.5	= 8.0 0= 1 A 9 0 8 .0 6 0 4 0 3 0	29 PSI .07.0 CMI CN 0.5090 0.3804 0.2536 0.1847	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143	CY 0.0533 0.1066 0.1138 0.0972	90. DI CR 0.0061 0.0059 0.0047 0.0044	EG.F RUN NO. CAT 0.3882 0.3867 0.3851	PØJ/P1 O24020 CPB 0.1639 0.1642 0.1645 0.1626	TS = 59124 CAF 0.2243 0.2225 0.2206	RUN 40. 40. 40.
Q P ALPH 4.0 3.0 2.0	= 8.0 0= 1 A 9 0 8 .0 6 0 4 0 3 0	29 PSI .07.0 CMI CN 0.5090 0.3804 0.2536	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127	6 T0= CY 0.0533 0.1066 0.1138 0.0972 0.1187	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039	CAT 0.3882 0.3867 0.3851 0.3830	POJ/P1 O24020 CPB 0.1639 0.1642 0.1645 0.1626 0.1614	CAF 0.2243 0.2225 0.2206 0.2204 0.2216	RUN 40. 40. 40. 40.
P ALPH 4.0 3.0 2.0 1.5 1.0	= 6. 0= 1 A 9 0 8 .0 6 0 4 0 3 0 1 0	29 PSI .07.0 CMI CN 0.5090 0.3804 0.2536 0.1847	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145	CY 0.0533 0.1066 0.1138 0.0972 0.1187 0.1048 0.0939	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040	CAT 0.3882 0.3887 0.3830 0.3830 0.3795 0.3806	POJ/P1 024026 CPB 0.1639 0.1642 0.1645 0.1626 0.1614 0.1608 0.1605	CAF 0.2243 0.2225 0.2206 0.2216 0.2186 0.2201	RUN 40. 40. 40. 40. 40.
ALPH 4.9 3.0 2.0 1.5 1.0	= 8.0 0= 1 A 9 0 8 .0 6 0 4 0 3 0 1 0	29 PSI 07.0 CMI CN 0.5090 0.3804 0.2536 0.1847 0.1207 0.0600	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672 -0.0058	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145 -0.0133	CY 0.0533 0.1066 0.1138 0.0972 0.1187 0.1048 0.0939	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040	CAT 0.3882 0.3887 0.3851 0.3830 0.3830 0.3795	POJ/P1 024026 CPB 0.1639 0.1642 0.1645 0.1626 0.1614 0.1608 0.1605	CAF 0.2243 0.2225 0.2206 0.2216 0.2186 0.2201	RUN 40. 40. 40. 40. 40.
ALPH 4.93 3.00 2.00 1.55 1.00 0.55 0.00	= 8. 0= 1 A 9 0 8 .0 6 0 4 0 3 0 1 0 1 -0	29 PSI 07.0 CMI CN 0.5090 0.3804 0.2536 0.1847 0.1207 0.0600 0.0009	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672 -0.0058 0.5922	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145 -0.0133 -0.0132	CY 0.0533 0.1066 0.1138 0.0972 0.1187 0.1048 0.0939 0.0979	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040 0.0034	CAT 0.3882 0.3887 0.3830 0.3830 0.3795 0.3806	POJ/P1 024026 CPB 0.1639 0.1642 0.1645 0.1626 0.1614 0.1608 0.1605 0.1598	CAF 0.2243 0.2225 0.2206 0.2216 0.2186 0.2201 0.2206	RUN 40. 40. 40. 40. 40. 40.
4.0 3.0 2.0 1.5 1.0 0.5 0.0 -0.5 -1.0	= 8. 0= 1 A 9 0 8 .0 6 0 4 0 3 0 1 0 1 -0 2 -0 2 -0	29 PSI 07.0 CMI CN 0.5090 0.3804 0.2536 0.1847 0.1207 0.0600 0.0625 0.1191 0.1810	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672 -0.0058 0.5922 1.1231 1.7075	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145 -0.0133 -0.0132 -0.0119 -0.0110	CY 0.0533 0.1066 0.1138 9.0972 0.1187 0.1048 0.0939 0.0979 0.0826	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040 0.0034	CAT 0.3882 0.3887 0.3881 0.3830 0.3795 0.3806 0.3804	POJ/P1 O24026 CPB O.1639 O.1642 O.1645 O.1626 O.1614 O.1608 O.1605 O.1598 O.1603	CAF 0.2243 0.2225 0.2206 0.2216 0.2186 0.2201 0.2206 0.2201	RUN 40. 40. 40. 40. 40. 40. 40.
ALPH 4.0 3.0 2.0 1.5 1.0 0.5 0.0 -0.5 -1.5 -2.0	= 8.0 0= 1 A 9 0 8 .0 6 0 4 0 3 0 1 0 1 -0 2 -0 3 -0	29 PSI .07.0 CMI CN 1.5090 .3804 2.2536 1.1847 .1207 .0600 .0009 .0625 .1191 .1810 .2405	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672 -0.0058 0.59231 1.7075 2.2736	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145 -0.0133 -0.0132 -0.0119 -0.0110 -0.0121 -0.0115	CY 0.0533 0.1066 0.1138 0.0972 0.1187 0.1048 0.0939 0.0979 0.0989 0.0883	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040 0.0037 0.0035	CAT 0.3882 0.3867 0.3830 0.3830 0.3795 0.3806 0.3795 0.3794 0.3792	POJ/P1 O24026 CPB 0.1639 0.1642 0.1645 0.1626 0.1614 0.1608 0.1605 0.1598 0.1503 0.3614 0.1612	CAF 0.2243 0.2225 0.2206 0.2216 0.2216 0.2216 0.2201 0.2206 0.2192 0.2180 0.2180	RUN 40. 40. 40. 40. 40. 40. 40. 40.
ALPH 4.0 3.0 2.0 1.5 1.0 0.5 0.0 -0.5 -1.5 -1.5 -2.0 -3.0	= 8.00	29 PSI 07.0 CMI CN 0.5090 0.3804 0.2536 0.1847 0.1207 0.0600 0.0625 0.1191 0.1810	RE PER HG PTS= CM -4.8237 -3.6002 -2.3973 -1.7451 -1.1401 -0.5672 -0.0058 0.59231 1.7075 2.2736 3.4973	IN.= .48E0 3.8665 PSI CS -0.0081 -0.0139 -0.0143 -0.0127 -0.0145 -0.0133 -0.0132 -0.0119 -0.0110	CY 0.0533 0.1066 0.1138 0.0972 0.1187 0.1048 0.0939 0.0979 0.0826 0.0989 0.0883 0.0823	90. DI CR 0.0061 0.0059 0.0047 0.0044 0.0039 0.0042 0.0040 0.0035 0.0035 0.0035	CAT 0.3882 0.3867 0.3830 0.3830 0.3795 0.3806 0.3795 0.3794	POJ/P1 O24020 CPB 0.1639 0.1642 0.1645 0.1626 0.1614 0.1608 0.1605 0.1598 0.1604 0.1612 0.1612	CAF 0-2243 0-225 0-2206 0-2216 0-2216 0-2219 0-2180 0-2180 0-2180 0-2180	RUN 40. 40. 40. 40. 40. 40. 40. 40. 40.

MODEL 946.2	CONFIG.	2.000 H	ACK 1.75	PHI = 15.	•
Q= 8.29 PSI	RE PER IN.=	.48E06 TO=	90. DEG.F	POS/PTS =	10.
PO= 107.0 CM	HG PTS= 3.86	65 PSI	RUN NO	. 0240269125	
ALPHA CN	сн с	s cy	CR CAT	CPB CAF	RUN
4,08 0.4979	-4.7853 -0.0	232 0.1832	0.0067 0.3933	0.1674 0.225	9 41.
3.07 0.3673	-3.5426 -0.0		0.0046 0.3877		
2.05 0.2417	-2.3509 -0.0	262 0.2277	0.0024 0.3861	0.1655 0.220	6 41.
1.53 0.1724	-1.6933 -0.0		0.0021 0.3834		
1.01 0.1094	-1.0973 -0.0		0.0018 0.3833		
0.51 0.0469	-0.4999 -0.0		0.0023 0.3823		
-0.01 -0.0106	0.0430 -0.0		0.0027 0.3807		
-0.52 -0.0740	0.6451 -0.0		0.0030 0.3799		
-1.03 -0.1342	1.2120 -0.0		0.0039 0.3810		
-1.53 -0.1968	1.8048 -0.0		0.0039 0.3808		
-2.04 -0.2612	2.4169 -0.0		0.0050 0.3793		
-3.06 -0.3873	3.6185 -0.0		0.0050 0.3775		
-4.08 -0.5206	4.8881 -0.0	031 -0.0164	0.0056 0.3773	0.1631 0.214	2 41.
MODEL 946.2 Q= 8.29 PSI	CUNFIG. RE PER IN.=		ACH 1.75	PHI = 15.	. 20.
Q= 8.29 PSI		.48E06 TO=	90. DEG.F	PHI = 15. POJ/PTS = 0260269102	
Q= 8.29 PSI	RE PER IN.=	.48E06 TO=	90. DEG.F	POJ/PTS =	
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER IN.= HG PTS= 3.86 CH C	.48E06 TO= 65 PSI S CY	90. DEG.F RUN NO CR CAT	POJ/PTS = - 0260269102 - CPB CAF	20 .
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 G.4823	RE PER IN.= HG PTS= 3.86 CH C -4.6980 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925	90. DEG.F RUN NO CR CAT 0.0115 0.4091	POJ/PTS = . 0260269102 CPB CAF 0.1720-0.237	20. RUN 1 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER IN.= HG PTS= 3.86 CH C	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237	20. RUN 1 42. 8 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 6.4823 3.05 0.3514	RE PER IN.= HG PTS= 3.86 CH C -4.6980 -0.0 -3.4527 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839	90. DEG.F RUN NO CR CAT 0.0115 0.4091	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235	20. RUN 1 42. 8 42. 5 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.00 C4823 3.05 0.3514 2.03 0.2243	RE PER IN.= HG PTS= 3.86 CM C -4.6980 -0.0 -3.4527 -0.0 -2.2473 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 9.4013	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235	20. RUN 1 42. 8 42. 5 42.
Q= 8.29 PSI PD= 107.0 CM ALPHA CN 4.06 C4823 3.05 0.3514 2.03 0.2243 1.51 0.1596	RE PER IN.= HG PTS= 3.86 CH C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 9.4013 0.0006 0.3991	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235	20. RUN 1 42. 18 42. 15 42. 16 42. 17 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 64823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946	RE PER IN.= HG PTS= 3.86 CH C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0 -1.0165 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323 333 0.2883	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 9.4013 0.0006 0.3991	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235 0.1646 0.234 0.1635 0.234	20. RUN 1 42. 18 42. 15 42. 10 42. 15 42. 11 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 64823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282	RE PER IN.= HG PTS= 3.86 CM C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0 -1.0165 -0.0 -0.3823 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323 333 0.2883 277 0.2228	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 0.4013 0.0006 0.3991 -0. 0.3976	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235 0.1646 0.234 0.1635 0.234 0.1635 0.233	20. RUN 1
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.00 64823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282 -0.03 -0.0297	RE PER IN.= HG PTS= 3.86 CH C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0 -1.0165 -0.0 -0.3823 -0.0 0.1639 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323 333 0.2883 277 0.2228 221 0.1600	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 0.4013 0.0006 0.3991 -0. 0.3976 0.0037 0.3966	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235 0.1646 0.234 0.1635 0.234 0.1635 0.232 0.1631 0.232	20. RUN 1 42. 8 42. 5 42. 10 42. 11 42. 11 42.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.06 6.48/23 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282 -0.03 -0.0297 -0.54 -0.0957	RE PER IN.= HG PTS= 3.86 CH C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0 -1.0165 -0.0 -0.3823 -0.0 0.1639 -0.0 0.7899 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3223 333 0.2883 277 0.2228 221 0.1600 122 0.0574 089 0.0101	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 0.4013 0.0006 0.3991 -0. 0.3976 0.0037 0.3966 0.0060 0.3957 0.0083 0.3957	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235 0.1646 0.234 0.1635 0.234 0.1631 0.232 0.1631 0.231 0.1636 0.231	20. RUN 1 42. 8 42. 5 42. 6 42. 6 42. 5 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 C4823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282 -0.03 -0.0297 -0.54 -0.0957 -1.04 -0.1562 -1.55 -0.2210 -2.06 -0.2859	RE PER IN.= HG PTS= 3.86 CH C -4.6980 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.0165 -0.0 -0.3823 -0.0 0.1639 -0.0 0.7899 -0.0 1.3621 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3223 333 0.2883 277 0.2228 221 0.1600 122 0.0574 089 0.0101	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 9.4013 0.0006 0.3991 -0. 0.3976 0.0037 0.3966 0.0060 0.3957 0.0083 0.3947	POJ/PTS = . 0260269102 CPB CAF 0.1720 0.237 0.1691 0.237 0.1672 0.235 0.1663 0.235 0.1646 0.234 0.1635 0.234 0.1631 0.232 0.1631 0.231 0.1636 0.231	20. RUN 1 42. 8 42. 5 42. 6 42. 6 42. 5 42.
Q= 8.29 PSI PD= 107.0 CM ALPHA CN 4.06 6.4823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282 -0.03 -0.0297 -0.54 -0.0957 -1.04 -0.1562 -1.55 -0.2210 -2.06 -0.2859 -3.07 -0.4127	RE PER IN.= HG PTS= 3.86 CM C -4.6980 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.0165 -0.0 -0.3823 -0.0 0.1639 -0.0 0.7899 -0.0 1.3621 -0.0 1.9796 -0.0 2.5959 -0.0 3.8060 0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323 333 0.2883 277 0.2228 221 0.1600 122 0.0574 089 0.0101 030 -0.0610	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 0.4013 0.0006 0.3991 -0. 0.3976 0.0037 0.3966 0.0060 0.3957 0.0083 0.3957	POJ/PTS = . 0260269102 CPB	20. RUN 1 42. 8 42. 5 42. 10 42. 11 42. 11 42. 16 42. 16 42. 17 42. 18 42.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.06 C4823 3.05 0.3514 2.03 0.2243 1.51 0.1596 1.00 0.0946 0.49 0.0282 -0.03 -0.0297 -0.54 -0.0957 -1.04 -0.1562 -1.55 -0.2210 -2.06 -0.2859	RE PER IN.= HG PTS= 3.86 CH C -4.6930 -0.0 -3.4527 -0.0 -2.2473 -0.0 -1.6312 -0.0 -1.0165 -0.0 -0.3823 -0.0 0.1639 -0.0 0.7899 -0.0 1.3621 -0.0 1.9796 -0.0 2.5959 -0.0	.48E06 T0= 65 PSI S CY 366 0.2925 392 0.3351 430 0.3839 396 0.3530 377 0.3323 333 0.2883 277 0.2228 221 0.1600 122 0.0574 089 0.0101 030 -0.0610 019 -0.1128	90. DEG.F RUN NO CR CAT 0.0115 0.4091 0.0057 0.4070 0.0015 0.4028 -0.0003 9.4013 0.0006 0.3991 -0. 0.3976 0.0037 0.3966 0.0060 0.3957 0.0083 0.3957 0.0083 0.3951 0.0120 0.3942	POJ/PTS = . 0260269102 CPB	20. RUN 1 42. 8 42. 5 42. 10 42. 11 42. 11 42. 16 42. 16 42. 17 42.

HO	DEL 946.2	CONI	FIG. 2.00	10 M	ACH 1.75	5	bHI. =	15.	
Q=	8-29 PSI	RE PER	IN.= .48E	C6 T0=	90. DE	:G.F	P0J/P	FS = 40	٠.
20	= 107.0 CF	HG PTS=	3.8665 PS	i i		RUN NO.	. U2602	69103	
ALPHA	CN	CM	c.s	CY	CR	CAT	СРВ	CAF	RUN
4-04	0.4388	-4.3976	-0.0554	0.4288	0.0170	0.4113	0.1798	0.2316	43.
3.03			-0.0541	0.4413	0.0092	0-4057	0-1730	0.2327	43.
	0.1754		-0.0571		0.0023				43.
	0.1036		-0.0577		-0.0017	-			43.
	0.0396		-0.0544		-0.0014				43.
	-0.0215		-0.0472		-C.0012				43.
	-0.0862		-0.0438		0.0006				43.
	-0.1502		-0.0359		0-0057				43.
	-0.2189	1.8459	_		0.0099				43.
	-0.2835	2.4705	-0.0233		0.0156				43.
-		3 0260	-0.0038	-0.1043					43.
	-0.3419			-0-2762					
		4.2862							43.
-4.12	-0.6102	2.2821	0.0238	-0.4142	0-0201	0.3833	0.1024	0.2113	43.
MU	DEL 946.2	CGNI	FIG. 2.00	10 M	ACH 1.75	5	PHI =	15.	
	DEL 946.2 8.29 PSI		FIG. 2.00 IN.= .48E				PHI =) .
Q=	- · -	RE PER	IN.= .48E	:06 TO=		EG•¥		TS = 80).
Q=	8.29 PSI = 107.0 CM	RE PER	IN.= .48E	:06 TO=		EG•¥	60 1 /b	TS = 80 69104). RUN
Q= PD ALPHA	8.29 PSI = 107.0 CM	RE PER HG PTS= CM	IN.= .48E	06 TO=	90. DE	EG.F RUN NO. Cat	POJ/P 026020 CPB	TS = 80 69104 CAF	
Q= P0 ALPHA 4.00	8.29 PSI = 107.0 CM	RE PER HG PTS= CM -3.7837	IN.= .48E 3.8665 PS	CY 0.6630	90. DE	EG.F RUN NO CAT 0.4258	POJ/P 026020 CP5	TS = 80 69104 CAF 0-2395	RUN
Q= PO ALPHA 4.00 2.97	8.29 PSI = 107.0 CM CM 0.3490	RE PER HG PTS= CM -3.7837 -2.4495	IN.= .488 3.8665 PS -CS -0.0887	CY 0.6630 0.7015	90. DE	EG.F RUN NO. CAT 0.4258 0.4204	POJ/P . 026020 CPB 0.1863 0.1807	TS = 80 69104 CAF 0.2395 0.2398	RUN 44.
Q= PO ALPHA 4.00 2.97 1.95	8.29 PSI = 107.0 CM CN 0.3490 0.2096	RE PER HG PTS= CM -3.7837 -2.4495 -1.1402	IN.= .488 3.8665 PS CS -0.0887 -0.0899	CY 0.6630 0.7015 0.6959	90. DE CR 0.0272 0.0154	EG.F RUN NO. CAT 0.4258 0.4204 0.4170	POJ/P . 026020 CPB 0.1863 0.1807 0.1755	TS = 80 69104 CAF 0.2395 0.2398 0.2415	RUN 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722	RE PER GHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988	IN.= .488 3.8665 PS -CS -0.0887 -0.0899 -0.0866	CY 0.6630 0.7015 0.6959 0.7041	90. DE CR 0.0272 0.0154 0.0044	CAT 0.4258 0.4204 0.4170 0.4131	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402	RUN 44. 44.
9= P0 ALPHA 4.00 2.97 1.95 1.43 0.92	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658	RE PER GHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722	IN.= .488 3.8665 PS -CS -0.0887 -0.0899 -0.0866 -0.0867 -0.0831	CY 0.6630 0.7015 0.6959 0.7041 0.6666	90. DE CR 0.0272 0.0154 0.0044 0.0015 0.0006	CAT 0.4258 0.4204 0.4170 0.4131 0.4101	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391	RUN 44. 44. 44. 44.
Q= PO ALPHA 4.00 2.97 1.95 1.43 0.92 0.41	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307	RE PER HG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865	IN.= .488 3.8665 PS CS -0.0887 -0.0899 -0.0866 -0.0867 -0.0831 -0.0765	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008	90. D8 CR 0.0272 0.0154 0.0044 0.0015 0.0006	CAT 0.4258 0.4204 0.4170 0.4131 0.4101 0.4066	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378	RUN 44. 44. 44. 44. 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.10	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307 -0.2016	RE PER iHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 i.4665	IN.= .488 3.8665 PS CS -0.0887 -0.0899 -0.0866 -0.0867 -0.0831 -0.0765 -0.0752	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820	90. DE CR 0.0272 0.0154 0.0045 0.0015 0.0006 0.0017	CAT 0.4258 0.4254 0.4170 0.4131 0.4101 0.4066 0.4045	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688 0.1672	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378 0.2373	RUN 44. 44. 44. 44. 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.10 -0.61	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307 -0.2016 -0.2644	RE PER iHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 i.4665 2.0622	IN.= .488 3.8665 PS CS -0.0887 -0.0899 -0.0866 -0.0867 -0.0831 -0.0765 -0.0752 -0.0644	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820 0.4646	90. D8 CR 0.0272 0.0154 0.0045 0.0006 0.0017 0.0025 0.0062	CAT 0.4258 0.4254 0.4170 0.4131 0.4166 0.4045 0.4015	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688 0.1672 0.1656	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378 0.2373 0.2359	RUN 44. 44. 44. 44. 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.16 -0.61 -1.12	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307 -0.2016 -0.2644 -0.3313	RE PER iHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 1.4665 2.0622 2.6984	IN.= .488 3.8665 PS CS -0.0887 -0.0899 -0.0866 -0.0867 -0.0831 -0.0765 -c.0752 -0.0644 -0.0533	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820 0.4646 0.3417	90. D8 CR 0.0272 0.0154 0.0045 0.0006 0.0017 0.0025 0.0062 0.0105	CAT 0.4258 0.4254 0.4170 0.4131 0.4066 0.4045 0.4015	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1688 0.1672 0.1656 0.1636	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378 0.2373 0.2359 0.2355	RUN 44. 44. 44. 44. 44. 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.16 -0.61 -1.12 -1.64	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307 -0.2016 -0.2644 -0.3313 -0.3968	RE PER iHG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 1.4665 2.0622 2.6984 3.3245	IN.= .485 3.8665 PS CS -0.0887 -0.0887 -0.0866 -0.0867 -0.0831 -0.0765 -C.0752 -0.0644 -0.0533 -0.0451	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820 0.4646 0.3417 0.2394	90. D8 CR 0.0272 0.0154 0.0015 0.0006 0.0017 0.0025 0.0062 0.0105 0.0162	CAT 0.4258 0.4204 0.4170 0.4131 0.4101 0.4066 0.4045 0.4015 0.3991 0.3975	POJ/P . 02602 . CP5 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688 0.1672 0.1656 0.1636 0.1630	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378 0.2378 0.2373 0.2359 0.2355 0.2345	RUN 44. 44. 44. 44. 44. 44.
Q= P0 ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.10 -0.61 -1.12 -1.64 -2.14	8.29 PSI = 107.0 CM	RE PER THG PTS= CM -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 1.4665 2.0622 2.6984 3.3245 3.9455	IN.= .488 3.8665 PS -0.0887 -0.0899 -0.0866 -0.0867 -0.0755 -0.0752 -0.0644 -0.0533 -0.0451 -0.0320	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820 0.4646 0.3417 0.2394 0.0970	90. D8 CR 0.0272 0.0154 0.0045 0.0005 0.0017 0.0025 0.0062 0.0105 0.0162 0.0216	CAT 0.4258 0.4204 0.4170 0.4131 0.4101 0.4066 0.4045 0.4045 0.4091 0.3975 0.3964	POJ/P O26020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688 0.1672 0.1656 0.1630 0.1640	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2378 0.2373 0.2359 0.2355 0.2345 0.2324	RUN 44. 44. 44. 44. 44. 44. 44.
PO ALPHA 4.00 2.97 1.95 1.43 0.92 0.41 -0.10 -0.61 -1.12 -1.64 -2.14 -3.15	8.29 PSI = 107.0 CM CN 0.3490 0.2096 0.0722 -0.0057 -0.0658 -0.1307 -0.2016 -0.2644 -0.3313 -0.3968	RE PER CH -3.7837 -2.4495 -1.1402 -0.3988 0.1722 0.7865 1.4665 2.0622 2.6984 3.3245 3.9455 5.2252	IN.= .485 3.8665 PS CS -0.0887 -0.0887 -0.0866 -0.0867 -0.0831 -0.0765 -C.0752 -0.0644 -0.0533 -0.0451	CY 0.6630 0.7015 0.6959 0.7041 0.6666 0.6008 0.5820 0.4646 0.3417 0.2394	90. D8 CR 0.0272 0.0154 0.0045 0.0005 0.0017 0.0025 0.0162 0.0162 0.0216 0.0338	CAT 0.4258 0.4204 0.4170 0.4131 0.4101 0.4066 0.4045 0.4045 0.39975 0.3964 0.3950	POJ/P . 026020 CPB 0.1863 0.1807 0.1755 0.1729 0.1710 0.1688 0.1672 0.1656 0.1630 0.1640 0.1672	TS = 80 69104 CAF 0.2395 0.2398 0.2415 0.2402 0.2391 0.2373 0.2373 0.2355 0.2355 0.2345 0.2324 0.2279	RUN 44. 44. 44. 44. 44. 44.

PODCL 946-2	CONF	IG. 2.000	M	ACH 1.75		PHI =	30.	
G= P.29 PSI	RE PER	IN.= .48E0	5 TO=	90. DEG	.F	P03/P1	rs =	•
PO= 107.0 C	HG PTS=	3.8665 PSI		3	.GN NU	026026	59105	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.06 0.5042	-4.7707	-0.0186	0.1477	0.0067 C	.3973	0.1653	0-2320	45.
3.05 0.3751	-3.5469	-0.0201	0.1650	0.0053 0	-3937	9.1649	0.2287	7 45.
2.03 0.2483	-2.3460	-0.0190	0.1553	0.0047 0	.3907	0.1640	0.2267	45.
1.51 0.1818	-1.7197	-0.0171	0.1375	0.0046 0	-3896	C.1621	0.2276	45.
1.00 0.1206	-1-1366			0.0039 0				
0.48 0.0564	-0.5334			0.0038 0				
-0.03 -0.0032		-0.0167		0.0042 0				
-0.54 -0.0650		-0.0162		0.0038 0				
-1.04 -0.1273		-0.0202		0.0035 0				
-1.55 -0.1844		-0.0162		0.0042 0				
-2.06 -0.2466		-0.0139		0.0035 0				
-3.08 -0.3762		-0.0219		0.0035 0				
-4.10 -0.5060	4.7864	-0.0122	0.0978	0.0043-0	,3842	9491.0	0.21/4	45.
MODEL 946.2 Q= 8.29 PSI		FIG. 2.000		ACH 1.75	. . F	PH[=	30. TS =	10.
	RE PER	IN.= .49E0		90. DES			rs =	10.
Q= 8.29 PSI	RE PER	IN.= .49E0		90. DES		P0J/P1	rs =	10. RUN
Q= 8.29 PSI PO= 107.0 C! ALPHA CN	RE PER 1HG PTS= CM	IN.= .49E0 3.8665 PSI CS	6 TO=	90. DEG	UN NO.	POJ/P1 926026 CPB	TS = 59106 CAF	RUN
Q= 8.29 PSI PO= 107.0 C	RE PER	IN.= .49E0 3.8665 PSI CS -0.0308	6 TO= CY 0.2276	90. DES R CR 0.0124 0	UN NO. CAT	POJ/P1 - 926026 - CPB - 0-1658	TS = 59106 CAF 0.2318	RUN 3 46.
Q= 8.29 PSI PO= 107.0 C! ALPHA CN 4.05 0.4959	RE PER HHG PTS= CH -4.7458	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311	6 TO= CY 0.2276 0.2395	90. DEG	CAT 0.3975	POJ/P1 926026 CPB 0.1658 0.1658	TS = 59106 CAF 0.2318 0.2388	RUN 3 46. 3 46.
Q= 8.29 PSI PO= 107.0 C! ALPHA CN 4.05 0.4959 3.04 0.3646	RE PER HHG PTS= CH -4.7458 -3.5004	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336	CY 0.2276 0.2395 0.2757	90. DES R CR 0.0124 0	CAT 0.3975 0.3946 0.3924	POJ/P1 926020 CPB 0.1658 0.1658 0.1653	TS = 59106 CAF 0.2318 0.2288	RUN 3 46. 3 46.
Q= 8.29 PSI PO= 107.0 C! ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407	RE PER HHG PTS= CM -4.7458 -3.5004 -2.3330	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0333	CY 0.2276 0.2395 0.2757 0.2764	90. DES R CR 0.0124 0 0.0089 0 0.0038 0	CAT 0.3975 0.3946 0.3924 0.3900	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1637	TS = 59106 CAF 0.2318 0.2288 0.2271 0.2263	RUN 3 46. 3 46. 46.
Q= 8.29 PSI P0= 107.0 C! ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743	RE PER HHG PTS= CM -4.7458 -3.5004 -2.3330 -1.7070	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0333 -0.0300	CY 0.2276 0.2395 0.2757 0.2764 0.2498	90. DEG R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0	CAT 1.3975 1.3946 1.3924 1.3900 1.3888	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1637 0.1623	TS = 59106 CAF 0.2318 0.2288 0.2271 0.2263	RUN 46. 46. 46. 46.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137	RE PER HHG PTS= CH -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0333 -0.0300	CY 0.2276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0009 0 0.0016 0 0.0029 0	CAT 1.3975 1.3946 1.3924 1.3900 1.3888 1.3869	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1623 0.1620 0.1621	CAF 0.2318 0.2271 0.2263 0.2263 0.2263 0.2263	RUN 3 46. 3 46. 46. 46. 46. 46.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137 -0.54 -0.0787	RE PER HHG PTS= CH -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026 0.0749 0.6964	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0333 -0.0300 -0.0291 -0.0225 -0.0207	CY 0.2276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718 0.1459	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0029 0 0.0016 0 0.0029 0	CAT 1.3975 1.3946 1.3924 1.3920 1.3888 1.3869 1.3856	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1623 0.1623 0.1620 0.1621 0.1613	CAF 0.2318 0.2271 0.2263 0.2263 0.2258 0.2258	RUN 3 46. 3 46. 46. 46. 46. 46. 46.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137 -0.54 -0.0787 -1.06 -0.1421	RE PER HHG PTS= CH -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026 0.0749 0.6964 1.3002	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0333 -0.0300 -0.0291 -0.0225 -0.0207 -0.0176	CY 0.2276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718 0.1459 0.1060	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0009 0 0.0016 0 0.0029 0 0.0045 0 0.0047 0	CAT 1.3975 1.3946 1.3924 1.3900 1.3888 1.3856 1.3856 1.3856	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1627 0.1623 0.1620 0.1621 0.1613 0.3608	CAF 0.2318 0.2288 0.2271 0.2263 0.2250 0.2236	RUN 3 46. 3 46. 46. 46. 46. 5 46. 6 46.
Q= 8.29 PSI P0= 107.0 CS ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137 -0.54 -0.0787 -1.06 -0.1421 -1.56 -0.2046	RE PER 4HG PTS= CH -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026 0.0749 0.6964 1.3002 1.8962	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0300 -0.0291 -0.0225 -0.0207 -0.0176 -0.0148	CY 0.2276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718 0.1060 0.0726	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0016 0 0.0029 0 0.0045 0 0.0047 0 0.0057 0	CAT 1.3975 1.3946 1.3924 1.3900 1.3886 1.3856 1.3856 1.3845	POJ/P1 926026 CPB 0.1658 0.1658 0.1653 0.1623 0.1623 0.1621 0.1613 0.1608 0.1612	CAF 0.2318 0.2288 0.2271 0.2263 0.2256 0.2236 0.2236 0.2237	RUN 3 46. 3 46. 46. 46. 46. 46. 46. 46. 46.
Q= 8.29 PSI P0= 107.0 CS ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137 -0.54 -0.0787 -1.06 -0.1421 -1.56 -0.2046 -2.07 -0.2677	RE PER 4HG PTS= CM -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026 0.0749 0.6964 1.3002 1.8962 2.4937	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0300 -0.0291 -0.0225 -0.0207 -0.0176 -0.0148 -0.0110	CY 0.276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718 0.1459 0.1459 0.1060 0.0726 0.0405	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0009 0 0.0016 0 0.0029 0 0.0045 0 0.0047 0 0.0057 0 0.0055 0	CAT .3975 .3946 .3924 .3900 .3888 .3856 .3856 .3871 .3845	POJ/PT 926026 CPB 0.1658 0.1658 0.1653 0.1623 0.1623 0.1620 0.1621 0.1613 0.3608 0.1612 0.1623	CAF 0.2318 0.2288 0.2271 0.2263 0.2264 0.2250 0.2238 0.2231	RUN 46. 46. 46. 46. 46. 46. 46. 46. 46.
Q= 8.29 PSI P0= 107.0 CS ALPHA CN 4.05 0.4959 3.04 0.3646 2.02 0.2407 1.50 0.1743 0.99 0.1131 0.48 0.0472 -0.04 -0.0137 -0.54 -0.0787 -1.06 -0.1421 -1.56 -0.2046	RE PER 4HG PTS= CM -4.7458 -3.5004 -2.3330 -1.7070 -1.1293 -0.5026 0.0749 0.6964 1.3002 1.8962 2.4937 3.7085	IN.= .49E0 3.8665 PSI CS -0.0308 -0.0311 -0.0336 -0.0300 -0.0291 -0.0225 -0.0207 -0.0176 -0.0148 -0.0110	CY 0.276 0.2395 0.2757 0.2764 0.2498 0.2397 0.1718 0.1459 0.1060 0.0726 0.0405 0.0393	90. DES R CR 0.0124 0 0.0089 0 0.0038 0 0.0022 0 0.0016 0 0.0029 0 0.0045 0 0.0047 0 0.0057 0	CAT -3975 -3946 -3924 -3900 -3888 -3856 -3871 -3845 -3840 -3844	POJ/PT 926026 CPB 0.1658 0.1658 0.1653 0.1623 0.1620 0.1621 0.1613 0.3608 0.1612 0.1623 0.1656	CAF 0.2318 0.2288 0.2271 0.2263 0.2250 0.2236 0.2238 0.2238 0.2238 0.2238	RUN 46. 46. 46. 46. 46. 46. 46. 46. 46. 46.

MODEL 946	.2 CON	FIG. 2.060	. HA	CH 1.75	PHI =	30.	
Q= 8.29 P	SI RE PER	IN.= .48E0	6 TO=	90. DEG.F	P& J/ P	fS = 20.	
PO= 107.0	CHHG PTS	3.8635 PSI		RUN	NO. 02602	69107	
ALPHA CN	ck	cs	CY	CR CAT	г срв	CAF	RUN
4.04 0.482	2 -4.6636	-0.0455	G.3251	0.0169 0.40	005 0-1658	0-2348	47.
3.03 0.353		-0.0450	0.3427	0.0097 0.39	96 0.1674	0.2322	47.
2.01 0.228	5 -2.2738	-0.0509	0.4215	0.0012 0.39	955 0-1668	0.2287	47.
1.49 0.161	-1.6414	-0.0511	0.4378-	-0.0030 0.39	38 0.1656	0.2282	47.
0.98 0.100	3 -1.0673	-0.0500	0.4282-	-0.0040 0.39	926 0.1640	0.2287	47.
0.46 0.036	0.4550	-0.0466	0.3868-	-0.0013 0.39	0.1635	0.2273	47.
-0.05 -0.032	0.1991	-0.0385	0.2956	0.0011 0.38	887 0.1635	0.2253	47.
-0.56 -0.098	5 0.6354	-0.0251	0.1493	0.0069 G.38	393 0.1633	0.2260	47.
-1.07 -0.170	1 -5223	-0.0173	0.0624	0.0104 0.30	867 0.1628	0.2239	47.
-1.57 -0.232	1 2.1159	-0.0102	-0.0220	0.0135 0.39	347 0.1638	0.2209	47.
-2-08 -0-294	2.7130	-0.0074	-0-0539	0.0145 0.38	327 0.1639	0.2189	47.
-3.10 -0.422	3.9284	-0.0112	-0.0047	0.0128 0.38	319 G.1653	0.2166	47.
-4.12 -0.553	8 5°1625	-0.0160	0.0628	0.0107 0.38	838 0.1688	0.2150	47.
HODEL 946	2 CON	FIG. 2.000	H.	CH 1.75	PHI =	26	
			.,,	2413	F111 -	.50.	
Q= 8.29 P	SI RE PER	IN.= .48E0					
			6 TO=	90. DEG.F		TS = 40.	
		IN.= .48E0	6 TO=	90. DEG.F	PO J/ P NO. 02602	TS = 40.	`
PO= 107.0 Alpha cn	CHHG PTS=	IN.= .48E0 3.8665 PSI CS	6 T0=	90. DEG.F RUÑ CR CA	POJ/P NO. 02602 T CP8	TS = 40. 69108 CAF	
PO= 107.0 ALPHA CN 4.02 0.448	СННG PTS= СМ 6 -4.4417	IN.= .48E0 3.8665 PSI CS -0.0721	6 TO= CY 0.5039	90. DEG.F RUN CR CAT 0.0236 0.46	POJ/P NO. 02602 T CP8 093 0.1725	TS = 40. 69108 CAF 0=2368	48.
PO= 107.0 ALPHA CN 4.02 0.448 3.01 0.317	CMHG PTS= CM 6 -4.4417 5 -3.2086	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782	6 TO= CY 0.5039 0.5952	90. DEG.F RUN CR CA 0.0236 0.40	POJ/P NO. 02602 T CP8 093 0-1725 079 0-1704	TS = 40. 69108 CAF 0=2368 0-2375	48. 48.
PO= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.188	CMHG PTS= CM 6 -4.4417 5 -3.2086 4 -1.9948	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819	6 T0= CY 0.5030 0.5952 0.0648	90. DEG.F RUN CR CAT 0.0236 0.40 0.0119 0.40 0.0006 0.40	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1686	TS = 40. 69108 CAF 0.2368 0.2375 0.2346	48. 48.
PO= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.188 1.46 0.124	CMHG PTS= CM 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0831	6 T0= CY 0.5030 0.5952 0.0648 0.6895-	90. DEG.F RUN CR CA 0.0236 0.46 0.0119 0.46 0.0006 0.46 0.0061 0.46	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1686 015 0.1672	TS = 40. 69108 CAF 0.2368 0.2375 0.2346 0.2343	48. 48. 48.
PO= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057	CHHG PTS= CH 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982 0 -0.7545	IN-= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0831 -0.0859	CY 0.5039 0.5952 0.0648 0.6895- 0.7216-	90. DEG.F RUN CR CA 0.0236 0.44 0.0119 0.44 0.0006 0.44 -0.0061 0.44	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1686 015 0.1672 997 0.1659	TS = 40. 69108 CAF 0.2368 0.2375 0.2346 0.2343 0.2338	48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010	CHHG PTS= CM 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982 0 -0.7545 7 -0.1098	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0831 -0.0859 -0.0755	CY 0.5039 0.5952 0.0648 0.6895- 0.7216- 0.6150-	90. DEG.F RUN CR CA 0.0236 0.44 0.0119 0.44 0.0006 0.44 -0.0065 0.33 -0.0048 0.33	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1686 015 0.1672 997 0.1650	TS = 40. 69108 CAF 0.2368 0.2375 0.2346 0.2343 0.2338 0.2327	48. 48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010 -0.08 -0.076	CMHG PTS= CM 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982 0 -0.7545 7 -0.1098 7 0.5196	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0831 -0.0859 -0.0755 -0.0657	CY 0.5030 0.5952 0.0648 0.6895- 0.7216- 0.6150- 0.5003-	90. DEG.F RUN CR CA 0.0236 0.44 0.0119 0.44 0.0006 0.44 0.0065 0.33 -0.0048 0.33 -0.0015 0.33	POJ/P NO. 02602 CPB 093 0-1725 079 0-1704 031 0-1686 015 0-1672 997 0-1659 977 0-1650	TS = 40. 69108 CAF 0=2368 0-2375 0-2346 0-2343 0-2338 0-2327 0-2302	48. 48. 48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010 -0.08 -0.076 -0.58 -0.146	CHHG PTS= CH 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982 0 -0.7545 7 -0.1098 7 0.5196 9 1.2018	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0859 -0.0755 -0.0657 -0.0513	CY 0.5030 0.5952 0.0648 0.6895- 0.7216- 0.6150- 0.5003- 0.3327	90. DEG.F RUN CR CA 0.0236 0.41 0.0119 0.41 0.0006 0.41 -0.0065 0.33 -0.0048 0.33 -0.0015 0.33 0.0092 0.33	POJ/P NO. 02602 CP8 093 0.1725 079 0.1704 031 0.1686 015 0.1672 997 0.1659 977 0.1650 957 0.1655	TS = 40. 69108 CAF 0=2368 0-2375 0-2346 0-2343 0-2343 0-2327 0-2302 0-2290	48. 48. 48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010 -0.08 -0.076 -0.58 -0.146 -1.09 -0.219	CHHG PTS= CH 6 -4.4417 5 -3.2086 4 -1.9948 5 -0.7545 7 -0.1098 7 0.5196 9 1.2018 5 1.9061	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0859 -0.0755 -0.0657 -0.0513 -0.0366	CY 0.5030 0.5952 0.6648 0.6895- 0.7216- 0.6150- 0.5003- 0.3327 0.1598	90. DEG.F RUN CR CA 0.0236 0.41 0.0119 0.41 0.0006 0.41 -0.0065 0.31 -0.0048 0.31 -0.0015 0.31 0.0092 0.33 0.0173 0.33	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1650 097 0.1659 977 0.1650 957 0.1653 908 0.1644	TS = 40. 69108 CAF 0=2368 0-2375 0-2346 0-2343 0-2343 0-2327 0-2302 0-2290 0-2264	48. 48. 48. 48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010 -0.08 -0.076 -0.58 -0.146 -1.09 -0.219 -1.60 -0.286	CHHG PTS= CH 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3985 7 -0.1098 7 0.5196 9 1.2018 5 1.9061 6 2.5536	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0831 -0.0859 -0.0755 -0.0657 -0.0513 -0.0366 -0.0235	CY 0.5030 0.5952 0.6648 0.6895- 0.7216- 0.6150- 0.5003- 0.5003- 0.1598 0.0138	90. DEG.F RUN CR CA 0.0119 0.41 0.0006 0.41 0.0065 0.31 0.0048 0.33 0.0015 0.30 0.0017 0.30 0.0017 0.30 0.0017 0.30	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1686 015 0.1672 997 0.1659 977 0.1655 942 0.1653 908 0.1644	TS = 40. 69108 CAF 0.2368 0.2375 0.2346 0.2343 0.2338 0.2327 0.2302 0.2290 0.2264 0.2240	48. 48. 48. 48. 48. 48. 48. 48.
P0= 107.0 ALPHA CN 4.02 0.448 3.01 0.317 1.99 0.138 1.46 0.124 0.95 0.057 0.44 -0.010 -0.08 -0.076 -0.58 -0.146 -1.09 -0.219	CHHG PTS= CH 6 -4.4417 5 -3.2086 4 -1.9948 5 -1.3982 0 -0.7545 7 -0.1098 7 0.5196 9 1.2018 5 1.9061 6 2.5536 3 3.1819	IN.= .48E0 3.8665 PSI CS -0.0721 -0.0782 -0.0819 -0.0859 -0.0755 -0.0657 -0.0513 -0.0366 -0.0235 -0.0165	CY 0.5030 0.5952 0.648 0.6895- 0.7216- 0.6150- 0.5003- 0.3327 0.3327 0.0138- 0.0148	90. DEG.F RUN CR CA 0.0236 0.41 0.0119 0.41 0.0006 0.41 -0.0065 0.31 -0.0048 0.31 -0.0015 0.31 0.0092 0.33 0.0173 0.33	POJ/P NO. 02602 CPB 093 0.1725 079 0.1704 031 0.1659 977 0.1650 957 0.1655 957 0.1653 968 0.1654 693 0.1653	TS = 40. 69108 CAF 0.2368 0.2375 0.2346 0.2343 0.2338 0.2327 0.2302 0.2290 0.2264 0.2240 0.2220	48. 48. 48. 48. 48. 48. 48.

MODEL 946.2	CONF	1G. 2.000	H	ICH 1.75	PHI =	30.	
Q= 8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. DEG.F	P0J/P1	rs =	80.
PO= 107.0 C	HG PTS=	3.8665 PSI		RUN NO	. 026028	59109	
ALPHA CN	CH	cs	CY	CR CAT	CPB	CAF	RUN
3.97 0.3679	~3.8872	-0.1374	0.9817	0.0328 0.4248	0.1812	0-2436	49.
2.96 0.2337	-2.5236	-0.1392	1.0442	0.0155 0.4200	0.1766	0.2434	49.
1.94 0.0991	~1.3546	-0.1441	1.1300	0.0010 0.4166	0.1724	0-2443	49.
1.42 0.0323	-0.7301	-0.1422	1.1230-	-0.0049 0.4133	0.1707	0.2420	49.
0.90 -0.0394	-0.0454	-0.1387		-0.0057 0.4104			
0.40 -0.1088	0.6205	~0.1358		-0.0044 0.4079			
-0.13 -0.1818	1.3210	-0.1216		0.0005 A.4038			
-9.62 -9.2588	2.067-3	-0.1123		0.0080 0.4012			
-1.13 -0.3700		-0.0938		0.0179 0.3979			
-1.64 -0.3937	3.3764			0.0271 0.3960			
-2.15 -0.4649		-0.0662		0.0337 0.3960			
-3.18 -0.6011		-0.0519		0.0402 0.3941			
-4.19 -0.7316	6.5990	-0.9472	0.0724	0.0410 0.3918	0.1709	0.2209	49.
MOUFL 946.2		ig. 2.000		ACH 1.75	PHI =		
MOUFL 946.2 Q= 8.29 PSI				ACH 1.75 90. DEG.F			•
	RE PER	IN.= .48E0	6 TO=	90. DEG.F		rs =	*
Q= 8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	P03/P1	rs =	* NUR
Q= 8.29 PSI PO= 107.0 CI ALPHA CN	RE PER	IN.= .48E0 3.8665 PSI CS	6 TO=	90. DEG.F	POJ/P1 026028 CPB	rs = 59110 Caf	
Q= 8.29 PSI PO= 107.0 C	RE PER MHG PTS= CM	IN.= .48E0 3.8665 PSI CS -0.0381	6 TO= CY 0.3578	90. DEG.F RUN NE CR CAT	POJ/P1 0- 026028 CPB	TS = 59110 CAF	50•
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.06 0.5096	RE PER MHG PTS= CM -4.8216	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302	6 TO= CY 0.3578 0.255	90. DEG.F RUN NO CR CAT 0.0059 0.3972	POJ/P1 0- 026028 CPB 0-1617	TS = 59110 CAF -0.2355 0.2351	50 • 50 •
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804	RE PER HHG PTS= CM -4.8216 -3.5989	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331	6 T0= CY 0.3578 0.2:55 0.2975	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957	POJ/P1 - 026026 CPB - 0.1617 - 0.1606 - 0.1612	S = 59110 CAF 0.2355 9.2351 0.2300	50 • 50 • 50 •
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253	6 T0= CY 0.3578 0.2155 0.2975 0.2198	90. DEG.F RUN NE CR CAT 0.0059 0.3972 0.0058 0.3957 0.0057 0.3912	POJ/PI D- 026028 CPB 0-1617 0-1606 0-1612 0-1609	S = 59110 CAF 0.2355 9.2351 0.2300 0.2294	50. 50. 50.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312	6 T0= CY 0.3578 0.255 0.2975 0.2198 0.2942 0.2820	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0057 0.3912 0.0051 0.3903 0.0050 0.3879 0.0056 0.3865	POJ/PI CPB CO-1617 C-1606 C-1612 C-1609 C-1601 C-1609	CAF 0.2355 0.2351 0.2300 0.2294 0.2278	50. 50. 50. 50. 50.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312 -0.0242	6 T0= CY 0.3578 0.2755 0.2975 0.2198 0.2942 0.2820 0.2164	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0057 0.3912 0.0051 0.3903 0.0050 0.3879 0.0056 0.3865 0.0056 0.3857	PO3/P1 CPB CO-1617 O-1606 O-1612 O-1609 O-1601 O-1609 O-1609 O-1609	CAF 0.2355 0.2351 0.2300 0.2294 0.2278 0.2256	50. 50. 50. 50. 50.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024 -0.54 -0.0662	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127 0.0224 0.6283	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312 -0.0242 -0.0259	6 T0= CY 0.3578 0.2755 0.2975 0.2198 0.2942 0.2820 0.2164 0.2325	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0051 0.3903 0.0050 0.3879 0.0056 0.3865 0.0056 0.3858	PO3/P1 - 026028 - CPB - 0.1617 - 0.1606 - 0.1612 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609 - 0.1609	CAF 0.2355 0.2351 0.2300 0.2294 0.2278 0.2256 0.2248	50. 50. 50. 50. 50. 50.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024 -0.54 -0.0662 -1.05 -0.1251	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127 0.0224 0.6283 1.1787	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0325 -0.0312 -0.0242 -0.0259 -0.0176	6 T0= CY 0.3578 0.255 0.2975 0.2198 0.2942 0.2820 0.2164 0.2325 0.1509	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0051 0.3902 0.0050 0.3873 0.0056 0.3865 0.0050 0.3858 0.0050 0.3858	PO3/P1 CPB CO-1617 O-1606 O-1612 O-1609 O-1609 C-1609 O-1609 C-1609 C-1609 C-1609 C-1609 C-1609 C-1609 C-1609 C-1609 C-1609	CAF 0.2355 0.2351 0.2300 0.2294 0.2278 0.2256 0.2248 0.2257	50. 50. 50. 50. 50. 50. 50.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024 -0.54 -0.0662 -1.05 -0.1251 -1.56 -0.1883	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127 0.0224 0.6283 1.1787 1.7788	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312 -0.0242 -0.0259 -0.0176 -0.0182	6 T0= EY 0.3578 0.2:55 0.2975 0.2198 0.2942 0.2820 0.2164 0.2325 0.1509 0.1561	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0051 0.3903 0.0050 0.3856 0.0056 0.3856 0.0050 0.3858 0.0058 0.3838	POJ/PI CPB CO.1617 O.1606 O.1612 O.1609 O.1609 G.1609 G.1609 G.1609 G.1609 G.1609 G.1609 G.1609 G.1609	CAF 0.2355 0.2351 0.2300 0.2274 0.2256 0.2248 0.2257 0.2242	50. 50. 50. 50. 50. 50. 50.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024 -0.54 -0.0662 -1.05 -0.1251 -1.56 -0.1883 -2.07 -0.2523	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127 0.0224 0.6283 1.1787 1.7788 2.3819	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312 -0.0242 -0.0259 -0.0176 -0.0182 -0.0161	6 T0= EY 0.3578 0.2:55 0.2975 0.2198 0.2942 0.2820 0.2164 0.2325 0.1509 0.1561 0.1350	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0051 0.3903 0.0050 0.3857 0.0056 0.3858 0.0056 0.3858 0.0058 0.3858 0.0058 0.3858 0.0058 0.3858	POJ/PT CPB CO.1617 C.1606 C.1612 C.1609 C.1609 C.1609 C.1609 C.1609 C.1601 C.1594 C.1598 C.1595	CAF 0.2355 0.2351 0.2300 0.2294 0.2256 0.2256 0.2257 0.2255	50. 50. 50. 50. 50. 50. 50. 50.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 4.06 0.5096 3.05 0.3804 2.03 0.2490 1.51 0.1854 0.99 0.1168 0.48 0.0543 -0.03 -0.0024 -0.54 -0.0662 -1.05 -0.1251 -1.56 -0.1883	RE PER HHG PTS= CM -4.8216 -3.5989 -2.3555 -1.7528 -1.1022 -0.5127 0.0224 0.6283 1.1787 1.7788 2.3819 3.5790	IN.= .48E0 3.8665 PSI CS -0.0381 -0.0302 -0.0331 -0.0253 -0.0325 -0.0312 -0.0242 -0.0259 -0.0176 -0.0182	6 T0= CY 0.3578 0.2:55 0.2975 0.2198 0.2942 0.2820 0.2164 0.2325 0.1509 0.1561 0.1350 0.1089	90. DEG.F RUN NO CR CAT 0.0059 0.3972 0.0058 0.3957 0.0051 0.3903 0.0050 0.3856 0.0056 0.3856 0.0050 0.3858 0.0058 0.3838	POJ/PI CPB CO-1617 CO-1606 CO-1612 CO-1609 CO-1609 CO-1609 CO-1601 CO-1594 CO-1598 CO-1598 CO-1598 CO-1598 CO-1598	CAF 0.2355 0.2351 0.2300 0.2294 0.2278 0.2256 0.2248 0.2257 0.2257 0.2248	50. 50. 50. 50. 50. 50. 50. 50.

MGDEL 946.2	CONFI	G. 2.000	MA	CH 1.75	PHI =	60.	
Q= 8.29 PSI	RE PER II	N.= .48E06	10=	90. 9EG.F	F POJ/PT	'S = 10.	
PO= 107.0 C	HHG PTS= 3.	.8665 PSI		RUN	4 NO. 026036	9111	
ALPHA CN	CH	cs	£Υ	ER EA	ат срв	CAF	RUN
4.06 0.5044	-4.7966 -				4002 0.1631		51.
3.04 0.3716	-3.5393 -0				3955 0.1621		51.
2.03 0.2458	-2.3563 -				3927 0.1624		51.
1.50 0.1821	-1.7591 -0				3913 0-1626		51.
0.99 0.1243	-1.2193 -0 -0.5954 -0				3886 0.1512 3879 0.1614		51. 51.
0.48	0.0559 -				3865 0.1614		51.
-0.55 -0.0769	0.7071 -				3843 0-1607		51.
-1.05 -0.1433	1.3423 -				3828 0.1601		51.
-1.57 -0.2074	1.9436 -				3822 0.1603		51.
-2.07 -0.2694	2.5267 -				3816 0.1610		51.
-3.09 -0.3947	3.7068 -				3796 0.1527		51.
-4.11 -0.5259	4.9444 -				3809 0.1660		51.
MODEL 946.2	CONFI	G. 2.000	ММ	CH 1.75	2HI =	60.	
MODEL 946.2 Q= 8.29 PSI		G. 2.000 N.= .48E06		CH 1.75 90. DEG.F			
	RE PER IN	N.= .48E06		90. DEG.F		S = 20.	
Q= 8.29 PSI	RE PER IN	N.= .48E06		90. DEG.F	P0J/PT	S = 20.	RUN
Q= 8.29 PSI PO= 107.0 C	RE PER IN	N.= .48E06 .8665 PSI CS	T0=	90. DEG.F RUN CR CA	P0J/PT	S = 20. 9112 CAF	RUN 52.
Q= 8.29 PSI PO= 107.0 C ALPHA CN	RE PER IN MHG PTS= 3	N.= .48E06 .8665 PSI CS 0.0824	T0= CY 0.6537	90. DEG.F RUN CR CA 0.0213 0.3	POJ/PT N NO. 026026	S = 20. 9112 CAF 0.2366	
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4994	RE PER IN MHG PTS= 3. CM -4.7659 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734	T0= CY 0.6537 0.5785	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3	POJ/PT N NO. 026026 AT CPB 3994 0.1627	S = 20. 9112 CAF 0.2366 0.2346	52.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668	RE PER IN MHG PTS= 3. CM -4.7659 -(-3.5150 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646	TO= CY 0.6537 0.5785 0.5159 0.5113	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0064 0.3 0.0009 0.3	POJ/PT N NO. 026026 NT CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633	CAF 0.2366 0.2346 0.2317 0.2319	52. 52. 52. 52.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446	RE PER IN MHG PTS= 3. CM -4.7659 -(-3.5150 -(-2.3804 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018-	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0054 0.3 0.0009 0.3	POJ/PT N NO. 026026 NT CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 0.1626	CAF 0.2366 0.2346 0.2317 0.2319 0.2301	52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521	RE PER IN CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0703	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018- 0.5791-	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0054 0.3 0.0028 0.3 0.0028 0.3	POJ/PT N NO. 026026 NT CP8 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 0.1626	CAF 0.2366 0.2346 0.2317 0.2319 0.2301 0.2286	52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205	RE PER IN CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(0.1520 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0726 0.0703	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018- 0.5791- 0.4602	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0054 0.3 0.0058 0.3 0.0015 0.3 0.0036 0.3	POJ/PT N NO. 026026 NT CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 0.1626 3913 0.1627	S = 20. 9112 CAF 0.2366 0.2346 0.2317 0.2319 0.2319 0.2286 0.2276	52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521 -0.04 -0.0231 -0.55 -0.0994	RE PER IN CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(0.1520 -(0.9064 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0726 0.0703 0.0557 0.0448	TO= CY 0.6537 0.5785 0.5113 0.6018- 0.5791- 0.4602 0.3022	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0009 0.3 0.0028 0.3 0.0015 0.3 0.0036 0.3 0.0114 0.3	POJ/PT N NO. 026026 NT CPB 8994 0.1627 8958 0.1612 8944 0.1627 8952 0.1633 8927 6.1626 8913 0.1627 8910 0.1634	CAF 0.2366 0.2346 0.2347 0.2317 0.2319 0.2301 0.2286 0.2276 0.2237	52. 52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521 -0.04 -0.0231 -0.55 -0.0994 -1.05 -0.1685	RE PER IN MHG PTS= 3. CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(0.1520 -(0.9064 -(1.5720 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0703 0.0557 0.0448	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018- 0.5791- 0.4602 0.3022 0.1977	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0058 0.3 0.0028 0.3 0.0015 0.3 0.0036 0.3 0.0114 0.3 0.0168 0.3	POJ/PT N NO. 026026 NT CPB 8994 0.1627 8958 0.1612 8952 0.1633 8952 0.1634 8953 0.1627 8910 0.1634 8865 0.1628 8849 0.1629	CAF 0.2366 0.2346 0.2317 0.2319 0.2319 0.2286 0.2276 0.2237 0.2220	52. 52. 52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521 -0.04 -0.0231 -0.55 -0.0994 -1.05 -0.1685 -1.57 -0.2296	RE PER IN CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(0.1520 -(0.9064 -(1.5720 -(2.1460 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0703 0.0557 0.0448 0.0354 0.0311	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018- 0.4602 0.3022 0.1977 0.1607	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0099 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3 0.0114 0.3 0.0168 0.3 0.0151 0.3	POJ/PT N NO. 026026 NT CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 6.1626 3913 0.1627 3910 0.1634 3865 0.1628 3849 0.1629	CAF 0.2366 0.2346 0.2317 0.2319 0.2386 0.2276 0.2237 0.2220 0.2202	52. 52. 52. 52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521 -0.04 -0.0231 -0.55 -0.0994 -1.05 -0.1685 -1.57 -0.2296 -2.07 -0.2892	RE PER IN HHG PTS= 3. CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(0.1520 -(0.9064 -(1.5720 -(2.1460 -(2.7001 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0726 0.0763 0.0547 0.0448 0.0354 0.0311	TO= CY 0.6537 0.5785 0.5113 0.6018- 0.5791- 0.4602 0.3022 0.1977 0.1607 0.2308	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0054 0.3 0.0028 0.3 0.0015 0.3 0.0016 0.3 0.0168 0.3 0.0151 0.3 0.0151 0.3	POJ/PT N NO. 026026 T CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 G.1626 3910 0.1627 3910 0.1634 3865 0.1628 3849 0.1629 3828 0.1626	CAF 0.2366 0.2346 0.2317 0.2319 G.2301 0.2286 0.2276 0.2237 0.2220 0.2202 0.2190	52. 52. 52. 52. 52. 52. 52. 52. 52.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.05 0.4994 3.04 0.3668 2.02 0.2446 1.49 0.1823 0.98 0.1205 0.47 0.0521 -0.04 -0.0231 -0.55 -0.0994 -1.05 -0.1685 -1.57 -0.2296	RE PER IN CM -4.7659 -(-3.5150 -(-2.3804 -(-1.8079 -(-1.2313 -(-0.5840 -(0.1520 -(0.9064 -(1.5720 -(2.1460 -(N.= .48E06 .8665 PSI CS 0.0824 0.0734 0.0658 0.0646 0.0726 0.0703 0.0557 0.0448 0.0354 0.0311 0.0374	TO= CY 0.6537 0.5785 0.5159 0.5113 0.6018- 0.5791- 0.4602 0.3022 0.3022 0.1607 0.1607	90. DEG.F RUN CR CA 0.0213 0.3 0.0148 0.3 0.0054 0.3 0.0058 0.3 0.0015 0.3 0.0148 0.3 0.0151 0.3 0.0151 0.3 0.0152 0.3 0.0152 0.3 0.0157 0.3	POJ/PT N NO. 026026 NT CPB 3994 0.1627 3958 0.1612 3944 0.1627 3952 0.1633 3927 6.1626 3913 0.1627 3910 0.1634 3865 0.1628 3849 0.1629	CAF 0.2366 0.2346 0.2317 0.2319 0.2286 0.2276 0.2237 0.2220 0.2202 0.2190 0.2165	52. 52. 52. 52. 52. 52. 52. 52. 52.

HODEL 946.2	CONF	FIG. 2.000	H.	ac. 2.79	5	PHI =	60.	
Q= 8.29 PSI	RE PER	IN.= .48E0	5 10=	90. Di	EG.F	POJ/P	TS =	40.
PO= 107.0 C	HG PTS=	3.8665 PSI			RUN NO.	02602	69113	
ALPHA CN	См	CS	CY	CK	CAT	СРВ	CAF	RUN
4.04 0.4804	-4.6229	-0-1316	1-0175	0.0246	0.4022	0.1625	0.2397	53.
3.03 0.3549	-3.4664	-0.1140	0.8565	0.0136	0.4019	0.1624	0.2396	53.
2.01 0.2334	~2.3496	-0.1142	0.8807	0.0017	0.4028	0.1654	0.2374	53.
1.48 0.1690	-1.7558	-0.1224			0.4024			
0.97 0.1077	-1.1903				0.3998			
0.46 0.0398	_	-0.1159			0.3983			
-0.06 -0.0431		-0.1033			0.3959			
-0.56 -0.1308		-0.0901			0.3920			
-1.07 -0.2068		-0.0738			0.3895			
-1.58 -0.2797		-0.0772			0.3882			
-2.09 -0.3378		-0.0739			0.3862			
-3.10 -0.4516		-0.0776			0.3844			
-4.13 -0.5775	5.3542	-0.0776	0.5199	0.0056	0.3846	0.1690	0.2156	53.
MODEL 946.2 0= 8.29 PSI		FIG. 2.000		90. DI		PSI =	60. TS =	80.
	RE PER	IN.= .48E0			ES.F		TS =	80.
0= 8.29 PSI	RE PER	IN.= .48E0			ES.F	P0J/P	TS =	80. RUN
0= 8.29 PSI P0= 107.0 C	RE PER MHG PTS= CM	IN.= .48E0	6 TO ≃ CY	90. Di	EG.F RUN NO	POJ/P • 02602 CPB	TS = 69114 CAF	RUN
O= 8.29 PSI PO= 107.0 CA	RE PER MHG PTS= CM -4.5036	IN.= .48E00 3.8665 PSI CS	6 TO= CY 1.7182	90. Di CR 0.0243	EG.F RUN NO CAT	POJ/P • 02602 CPB 0•1658	TS = 69114 CAF 0.2498	RUN 54.
0= 8.29 PSI P0= 107.0 CALPHA CR 4.02 0.4547	RE PER MHG PTS= CM -4.5036 -3.2637	IN.= .48E00 3.8665 PSI CS -0.2283	6 TO= CY 1.7182 1.7140	90. Di CR 0.0243 0.0101	EG.F RUN NO CAT 0.4156	POJ/P . 02602 CPB 0.1658 0.1669	TS = 69114 CAF 0-2498 0-2498	RUN 54. 54.
O= 8.29 PSI PO= 107.0 CA ALPHA CR 4.02 0.4547 3.00 0.3201	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257	CY 1.7182 1.7140 1.7502	90. Di CR 0.0243 0.0101 -0.0033	EG.F RUN NO. CAT 0.4156 0.4264	POJ/P . 02602 CPB 0.1658 0.1669 0.1673	TS = 69114 CAF 0.2498 0.2495 0.2466	RUN 54. 54. 54.
O= 8.29 PSI PO= 107.0 CR ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295	IN.= .48E06 3.8665 PSI CS -0.2283 -0.2257 -0.2267	CY 1.7182 1.7140 1.7502- 1.7576	90. Di CR 0.0243 0.0101 -0.0033 -0.0098	EG.F RUN NO. CAT 0.4156 0.4264 0.4139	POJ/P . 02602 CPB 0.1658 0.1669 0.1673 0.1672	TS = 69114 CAF 0.2498 0.2495 0.2466	RUN 54. 54. 54. 54.
O= 8.29 PSI PO= 107.0 C ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219	CY 1.7182 1.7140 1.7502 1.7576 1.7213	90. 00 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121	CAT 0.4156 0.4139 0.4127	POJ/P . 02602 CPB 0.165E 0.1669 0.1673 0.1672 0.1668	TS = 69114 CAF 0.2498 0.2496 0.2466 0.2455	RUN 54. 54. 54. 54.
0= 8.29 PSI P0= 107.0 CR ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4285 -0.8106 -0.0517	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219	CY 1.7182 1.7140 1.7502 1.7576 1.7213 1.6879 1.5692	90. 00 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015	CAT 0.4156 0.4139 0.4127 0.4106 0.4071	POJ/P . 02602 CPB 0.1658 0.1669 0.1673 0.1672 0.1668 0.1661 0.1660	TS = 69114 CAF 0.2498 0.2496 0.2466 0.2455 0.2438 0.2410	RUN 54. 54. 54. 54. 54. 54. 54.
0= 8.29 PSI P0= 107.0 CS ALPHA CN 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551 0.43 -0.0231 -0.68 -0.1070 -0.59 -0.1907	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295 -0.8106 -0.0517 0.7772 1.6144	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219 -0.2186 -0.2083 -0.1840	CY 1.7182 1.7140 1.7502- 1.7576- 1.7213- 1.6879- 1.5692 1.3065	90. 00 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015	CAT 0.4156 0.4156 0.4139 0.4127 0.4106 0.4071 0.4040	POJ/P . 02602 CPB 0.1658 0.1659 0.1673 0.1672 0.1668 0.1661 0.1660 0.1642	TS = 69114 CAF 0.2498 0.2496 0.2455 0.2436 0.2438 0.2410 0.2380	RUN 54. 54. 54. 54. 54. 54. 54.
0= 8.29 PSI P0= 107.0 CS ALPHA CN 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551 0.43 -0.0231 -0.58 -0.1070 -0.59 -0.1907 -1.10 -0.2746	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295 -0.8106 -0.0517 0.7772 1.6144 2.4489	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219 -0.2186 -0.2083 -0.1840 -0.1759	CY 1.7182 1.7140 1.7502 1.7576 1.7213 1.6879 1.5692 1.3065 1.2072	90. Di CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015 0.0171 0.0301	CAT 0.4156 0.4156 0.4139 0.4127 0.4106 0.4071 0.4040 0.4006 0.3982	POJ/P . 02602 CPB 0.1658 0.1659 0.1673 0.1668 0.1661 0.1660 0.1642 0.1640	TS = 69114 CAF 0.2498 0.2495 0.2466 0.2455 0.2438 0.2438 0.2384	RUN 54. 54. 54. 54. 54. 54. 54. 54.
0= 8.29 PSI P0= 107.0 CR ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551 0.43 -0.0231 -0.28 -0.1070 -0.59 -0.1907 -1.10 -0.2746 -1.61 -0.3478	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4285 -0.8106 -0.0517 0.7772 1.6144 2.4489 3.1623	IN.= .48E06 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219 -0.2186 -0.2083 -0.1840 -0.1759 -0.1687	CY 1.7182 1.7140 1.7502 1.7576 1.7213 1.6879 1.5692 1.3065 1.2072 1.1262	90. 06 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015 0.0171 0.0301 0.0355	CAT 0.4156 0.4156 0.4164 0.4139 0.4127 0.4106 0.4071 0.4040 0.4040 0.2982 0.3973	POJ/P . 02602 CPB 0.1658 0.1659 0.1673 0.1662 0.1660 0.1642 0.1640 0.1650	TS = 69114 CAF 0.2498 0.2496 0.2466 0.2455 0.2436 0.2380 0.2380 0.2382	RUN 54. 54. 54. 54. 54. 54. 54. 554.
0= 8.29 PSI P0= 107.0 CR ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551 0.43 -0.0231 -0.08 -0.1070 -0.59 -0.1907 -1.10 -0.2746 -1.61 -0.3478 -2.11 -0.4161	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295 -0.8106 -0.0517 0.7772 1.6144 2.4489 3.1623 3.8032	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.219 -0.2186 -0.2083 -0.1840 -0.1759 -0.1687 -0.1627	CY 1.7182 1.7140 1.7502- 1.7576- 1.7213- 1.6879- 1.5692 1.3065 1.3065 1.2072 1.1262	90. 06 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015 0.0171 0.0301 0.0355 0.0362	CAT 0.4156 0.4156 0.4139 0.4127 0.4106 0.4071 0.4040 0.4040 0.2982 0.3973 0.3945	POJ/P . 02602 CPB 0.1658 0.1669 0.1673 0.1672 0.1668 0.1661 0.1660 0.1642 0.1640 0.1650 0.1654	TS = 69114 CAF 0.2498 0.2495 0.2466 0.2455 0.2438 0.2364 0.2364 0.2364	RUN 54. 54. 54. 54. 54. 54. 54. 54.
0= 8.29 PSI P0= 107.0 CR ALPHA CR 4.02 0.4547 3.00 0.3201 1.98 0.1920 1.45 0.1210 0.94 0.0551 0.43 -0.0231 -0.28 -0.1070 -0.59 -0.1907 -1.10 -0.2746 -1.61 -0.3478	RE PER MHG PTS= CM -4.5036 -3.2637 -2.0868 -1.4295 -0.8106 -0.0517 0.7772 1.6144 2.4489 3.1623 3.8032	IN.= .48E00 3.8665 PSI CS -0.2283 -0.2257 -0.2267 -0.2259 -0.2219 -0.2186 -0.2083 -0.18+0 -0.1759 -0.1687 -0.1627 -0.1617	CY 1.7182 1.7140 1.7502- 1.7576- 1.7213- 1.6879- 1.5692 1.3065 1.3065 1.3065 1.3072 1.1262 1.0691	90. 06 CR 0.0243 0.0101 -0.0033 -0.0098 -0.0121 -0.0080 C.0015 0.0017 0.0301 0.0355 0.0362 0.0312	CAT 0.4156 0.4156 0.4164 0.4139 0.4127 0.4106 0.4071 0.4040 0.4040 0.2982 0.3973	POJ/P . 02602 CPB 0.1656 0.1669 0.1673 0.1672 0.1668 0.1661 0.1660 0.1640 0.1650 0.1654 0.1654	TS = 69114 CAF 0.2498 0.2495 0.2466 0.2455 0.2438 0.2364 0.2362 0.2323 0.2262	RUN 54. 54. 54. 54. 54. 54. 54. 54. 54.

HE	DEL 946.2	CON	FIG. Z.000	H	ACH 1.75		PHI =	75.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TC=	90. DE	G.F	POJ/P	1 5 =	•
PO)= 107.0 CH	HG PTS=	3.8665 PSI		F	RUN NO.	. 02602	59115	
ALPHA	CN CN	СН	cs	CY	CR	CAT	CPB	CAF	RUN
4.08	0,5116	-4.8471	-0.0393	C.3715	0.0050	3982	0.1584	0.2398	55.
3.05	0.3805	-3.6012	-0.0338	0.3115	0.0048	3945	0.1574	0-2371	55.
2.03	0.2528	-2.3899	-0.0231	0.2078	0.0044 (3920	0.1584	0.2336	55.
1.51	0.1819	-1.7162	-0.0381		0.0037				55.
1.00	0.1215	-1-1492	-0.0329		0.0057				55.
0.48	0.0596	-0.5632	-0.0260		0.0041				55.
	-0.0038		-0.0294		0.0044				55.
	-0.0635	-	-0.0217		0.0052				55.
	-0.1285		-0.0288		0.0045				55.
	-0.1882		-0.0238		0.0051				55.
	-0-2501		-0.0277		0.0050				55.
	-0.3793		-0.0233		0.0054				55.
-4.10	-0.5151	4.8810	-0.0206	0-1776	ū-0063 (0.3761	0.1598	0.2163	55.
	DEL 946.2		FIG. 2.000		ACH 1.75			75.	_
3:	8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. DE	G.F	90J/P	TS = 1	.0.
PO)= 107.0 CH	IHG PTS=	3.8665 PSI		F	RUM NO.	02602	69116	
ALPHA	CN	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
4.08	0.5122	-4-8608	-0.0512	0.4227	0.0121	0-4010	0.1617	0-2392	56.
3.05	0.3792	-3.5004	-0.0465	0.3777	0.0096	0.3966	0.1600	0-2366	56.
2.03	3 0.2502	-2.3820	-0.0483	0.3934	0.0060	0.3938	0.1603	0-2335	56.
1.51	0.1864	-1-7874	-0.0422	0.3381	0.0045	0.3919	0.1610	0.2309	56.
1.01	0.1261	-1 -2224	-0.0465	0.3823	0.0007	0.3903	0.1606	0.2297	56.
0.48	3 0.0616	-0.6155	-0.0416	0.3322	0.0032	0.3896	0.1608	0-2296	56.
-0.03	3 -0.0087	0.0612	-9.0467	0.3830	0.0036	3894	0.1613	0.2281	56.
-0.54	-0.0781		-0.0393		0.0067				56.
	-0-1432		-0.0397		0.0072				56.
	-0-2057		-0.0359		0.0068				56.
	5 -0.2661		-0.0388		0.0059				56.
	3 -0. 3927 °		-0.0343		0.0040				56.
-4.10	-0.5283	4.9799	-0,0364	0.2805	0.0023	0.3783	0.1623	0.2159	56.

MODEL 946.2	CONFIG	. 2.00R	HA	ICH 1.75	5	PHI =	75.	
Q= 8.29 PSI	RE PER IN	.= .43E0á	T0=	90. DS	G.F	P0J/P	rs =	20.
PO= 107.0 C	MHG PTS= 3.	129 263B			RUN NO.	02502	59117	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.06 0.5096	-4.8378 -0	.0737	0.5741	0.0189	0.4020	0.1617	0.2403	57.
3.05 0.3774	-3.5914 -0	.0727	0.5685	0.0130	0.3964	0.1598	C-2366	
2.02 6.2528	-2.4297 -0	.0688	0.5323	0.0059	0.3955	0.1607	0.2349	57.
1.51 0.1923	-1.8764 -0	.0650		0.0001				
0.99 0.1303	-1.3042 -0	.0782	0.6396-	-0.9049	0.3944	0.1614	0.2330	57.
0.48 0.0355	-0.6896 -0	.0719	0.5725-	-0.0026	0.3925	0.1620	0.2305	57.
-0.03 -0.0138	0-0936 -0	.0680	0.5352	0.0026	0.3904	0.1632	0.2271	57.
-0.54 -0.0953	0.9042 -0	-0636	0.4768	0.0119	0.3883	0.1623	0.2259	57.
-1.05 -0.1664	1,5856 −0			0.0158				
-1.56 -C.2239	2.1196 -0		0.4149					
-2.07 -0.2818	2.6502 -0		0.4063					
-3.09 -0.4052	3.7986 -0		0.4342					
-4.11 -0.5356	5.0272 -0	-0572	0.4209-	-0.0007	C.3780	0.1633	0.2147	57.
HODEL 946.2				ACH 1.75		PHI =	75.	
MODEL 946.2 Q= 8.29 PSI				ACH 1.75		PHI =		40.
Q= 8.29 PSI		.= .48E06			G.F	•	rs =	40.
Q= 8.29 PSI	RE PER IN	.= .48E06			G.F	, 4/L04	rs =	40. RUN
Q= 8.29 PSI PO= 107.0 C	RE PER IN	.= .48E06 8665 PSI CS	CY	90. DE	EG.F RUN NO. CAT	POJ/P POJ/P 026020 CP8	rs = 69118 CAF	RUN
Q= 8.29 PSI PO= 107.0 C	RE PER IN MHG PTS= 3.	.= .48E06 8665 PSI CS .1247	CY 0.9438	90. DE	G.F RUN NO. CAT 0.4055	POJ/P1 026020 CP8 0-1620	(S = 59118 CAF 0.2435	RUN 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5109	RE PER IN MHG PTS= 3. CH -4.8629 -0	.= .48E06 8665 PSI CS .1247 .1185	CY 0.9438 0.8846	90. DE CR 0.0225	EG.F RUN NO. CAT 0.4055 0.4013	POJ/PT . 026020 CP8 0.1620 0.1607	CAF 0.2435	RUN 5 58. 5 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5109 3.04 0.3770	RE PER IN MHG PTS= 3. CM -4.8629 -0 -3.6203 -0	.= .48E06 8665 PSI ES .1247 .1185 .1237	CY 0.9438 0.8846 0.9497- 0.8885-	90. DE CR 0.0225 0.0114 -0.0005 -0.0080	CAT 0.4055 0.4013 0.4020 0.4009	POJ/P' . 026020 CP8 0.1620 0.1607 0.1627 0.1639	CAF 0.2435 0.2406 0.2393	RUN 58. 58. 58. 58.
Q= R.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5109 3.04 0.3770 2.02 0.2564	RE PER IN HHG PTS= 3. CH -4.8629 -0 -3.6203 -0 -2.5157 -0	.= .48E06 8665 PSI CS .1247 .1185 .1237 .1170	CY 0.9438 0.8846 0.9497- 0.8885-	90. DE CR 0.0225 0.0114 -0.0005	CAT 0.4055 0.4013 0.4020 0.4009	POJ/P' . 026020 CP8 0.1620 0.1607 0.1627 0.1639	CAF 0.2435 0.2406 0.2393	RUN 58. 58. 58. 58.
Q= R.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5109 3.04 0.3770 2.02 0.2564 1.50 0.1978	RE PER IN HHG PTS= 3. CH -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0	.= .48E06 8665 PSI CS .1247 .1185 .1237 .1170 .1196 .1238	CY 0.9438 0.8846 0.9497- 0.8885- 0.9233- 0.9643-	90. DE CR 0.0225 0.0114 -0.0005 -0.0080 -0.0116 -0.0098	CAT 0.4055 0.4013 0.4020 0.4009 0.4019 0.3995	POJ/P' . 026020 . CP8 0.1620 0.1607 0.1627 0.1639 0.1644 0.1642	CAF 0.2435 0.2435 0.2373 0.2373 0.2373	RUN 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203	RE PER IN HHG PTS= 3. CH -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0 0.1223 -0	.= .48E06 8665 PSI CS .1247 .1185 .1237 .1170 .1196 .1238 .1022	CY 0.9438 0.8846 0.9497- 0.8885- 0.9233- 0.9643- 0.7318	90. DE CR 0.0225 0.0114 -0.0005 -0.0080 -0.0116 -0.0098 0.0027	CAT 0.4055 0.4013 0.4020 0.4009 0.4019 0.3995 0.3970	POJ/P°. 026026 CP8 0.1620 0.1607 0.1627 0.1639 0.1644 0.1642 0.1653	CAF 0.2435 0.2436 0.2373 0.2371 0.2376 0.2353	RUN 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203 -0.55 -0.1165	RE PER IN HHG PTS= 3. CH -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0 0.1223 -0 1.0953 -0	.= .48E06 8665 PSI CS .1247 .1185 .1237 .1170 .1196 .1238 .1022 .1061	CY 0.9438 0.8846 0.9497- 0.8885- 0.9233- 0.9643- 0.7318 0.7599	90. DE CR 0.0225 0.0114 -0.0005 -0.0116 -0.0098 0.0027 0.0196	CAT 0.4055 0.4013 0.4020 0.4019 0.3995 0.3970 0.3942	POJ/P. 026020 CPB 0.1620 0.1607 0.1627 0.1639 0.1644 0.1653 0.1653	CAF 0.2435 0.2406 0.2373 0.2371 0.2373 0.2317	RUN 58. 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203 -0.55 -0.1165 -1.05 -0.1939	RE PER IN HHG PTS= 3. CH -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0 0.1223 -0 1.0953 -0 1.8507 -0	.= .48E06 8665 PSI C\$.1247 .1185 .1237 .1170 .1170 .1238 .1022 .1061 .1026	CY 0.9438 0.8846 0.9497- 0.8885- 0.9643- 0.7318 0.7599 0.7218	90. DE CR 0.0225 0.0114 -0.0005 -0.0080 -0.0116 -0.0098 0.0027 0.0196 0.0263	CAT 0.4055 0.4013 0.4020 0.4009 0.4019 0.3995 0.3970 0.3942 0.3908	POJ/P. 026020 CP8 0.1620 0.1607 0.1627 0.1639 0.1644 0.1642 0.1653 0.1640 0.1638	CAF 0.2435 0.2406 0.2371 0.2373 0.2373 0.2373 0.2373	RUN 58. 58. 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203 -0.55 -0.1165 -1.05 -0.1939 -1.57 -0.2558	RE PER IN MHG PTS= 3. CM -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0 0.1223 -0 1.0953 -0 1.8507 -0 2.4325 -0	.= .48E06 8665 PSI C\$.1247 .1185 .1237 .1170 .1196 .1238 .1022 .1061 .1026 .0991	CY 0.9438 0.8846 0.9497- 0.8885- 0.9643- 0.7318 0.7599 0.7218 0.6854	90. DE CR 0.0225 0.0114 -0.0005 -0.0180 -0.0196 0.0027 0.0196 0.0263 0.0248	CAT 0.4055 0.4013 0.4020 0.4009 0.4019 0.3995 0.3970 0.3942 0.3908	POJ/P. 026020 CP8 0.1620 0.1607 0.1637 0.1644 0.1642 0.1653 0.1640 0.1638 0.1639	CAF 0.2435 0.2406 0.2371 0.2373 0.2373 0.2373 0.2362 0.2270	RUN 58. 58. 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203 -0.55 -0.1165 -1.05 -0.1939 -1.57 -0.2558 -2.07 -0.3126	RE PER IN MHG PTS= 3. CM -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.9853 -0 -0.7085 -0 0.1223 -0 1.0953 -0 1.0953 -0 2.4325 -0 2.9515 -0	.= .48E06 8665 PSI CS .1247 .1185 .1237 .1170 .1196 .1238 .1022 .1061 .1026 .0991 .1008	CY 0.9438 0.8846 0.9497- 0.8885- 0.9233- 0.7318 0.75218 0.6854 0.7076	90. DE CR 0.0225 0.0114 -0.0005 -0.0080 -0.0116 -0.0098 0.0027 0.0196 0.0263 0.0248 0.0216	CAT 0.4055 0.4013 0.4020 0.4009 0.4019 0.3970 0.39742 0.3942 0.39483 0.3883	POJ/P' 026020 CP8 0.1620 0.1607 0.1627 0.1639 0.1644 0.1642 0.1653 0.1640 0.1638 0.1639 0.1639	CAF 0.2435 0.2406 0.2371 0.2376 0.2353 0.2317 0.22244 0.2245	RUN 58. 58. 58. 58. 58. 58. 58. 58.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.07 0.5107 3.04 0.3770 2.02 0.2564 1.50 0.1978 0.98 0.1338 0.47 0.0627 -0.04 -0.0203 -0.55 -0.1165 -1.05 -0.1939 -1.57 -0.2558	RE PER IN MHG PTS= 3. CM -4.8629 -0 -3.6203 -0 -2.5157 -0 -1.9853 -0 -1.3962 -0 -0.7085 -0 0.1223 -0 1.0953 -0 1.8507 -0 2.4325 -0	-= .48E06 8665 PSI CS .1247 .1185 .1237 .1170 .1196 .1238 .1022 .1061 .1026 .0991 .1008 .1033	CY 0.9438 0.8846 0.9497- 0.8885- 0.9233- 0.7318 0.7599 0.7218 0.6854 0.7076	90. DE CR 0.0225 0.0114 -0.0005 -0.0080 -0.0116 -0.0098 0.0027 0.0196 0.0263 0.0248 0.0216	CAT 0.4055 0.4055 0.4013 0.4020 0.4009 0.4019 0.3995 0.3970 0.3942 0.3983 0.3888 0.3888	POJ/P' . 026020 . CP8 0.1620 0.1607 0.1627 0.1639 0.1644 0.1642 0.1653 0.1640 0.1635 0.1645 0.1645	CAF 0.2435 0.2406 0.2371 0.2376 0.2353 0.2317 0.2244 0.2245 0.2245	RUN 58. 58. 58. 58. 58. 58. 58. 58. 58.

Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 80. PO= 107.0 CMHG PTS= 3.8665 PSI RUN NO. 0260269119 ALPHA CN CH CS CY CR CAT CPB CAF RUN 4.05 0.5048 -4.8734 -0.2305 1.7113 0.0185 0.4197 0.1664 0.2533 59. 3.04 0.3760 -3.6903 -0.2323 1 7429 0.0042 0.4156 0.1649 0.2507 59. 2.00 C.2498 -2.5360 -0.2294 1.7232-0.0042 0.4156 0.1649 0.2507 59. 1.48 0.1775 -1.8664 -0.2440 1.8759-0.0154 0.4142 0.1662 0.2480 59. 0.97 0.1088 -1.2230 -0.2360 1.8016-0.0156 0.4115 0.1663 0.2452 59. 0.46 0.0318 -0.4684 -0.2408 1.8455-0.0106 0.4076 0.1659 C.2417 590.05 -0.0564 0.4140 -0.2332 1.7623 0.0023 0.4047 0.1661 0.2386 590.56 -0.1502 1.3570 -0.2169 1.5872 0.0195 0.4015 0.1643 0.2372 591.07 -0.2331 2.1808 -0.2141 1.5528 0.0297 0.4000 0.1640 0.2361 591.59 -0.3081 2.8966 -0.2119 1.5276 0.0335 0.3988 0.1650 0.2336 592.09 -0.3683 3.4576 -0.2034 1.4445 0.0329 0.3988 0.1650 0.2336 593.11 -0.4946 4.6175 -0.2037 1.4562 G.0241 0.3928 0.1649 0.2279 594.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CDNFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
ALPHA CN CH CS CY CR CAT CP8 CAF RUN 4.05 0.5048 -4.8734 -0.2305 1.7113 0.0185 0.4197 0.1664 0.2533
4.05 0.5048
3.04 0.3760
2.00 G.2498
1.48 0.1775 -1.8664 -C.244C 1.8759-0.0154 0.4142 0.1662 0.2480 59. 0.97 0.1088 -1.2230 -0.2360 1.8016-0.0156 0.4115 0.1663 0.2452 59. 0.46 0.0318 -0.4684 -0.2408 1.8455-0.0106 0.4076 0.1659 C.2417 590.05 -0.0564 0.4140 -0.2332 1.7623 0.0023 0.4047 0.1661 0.2386 590.56 -0.1502 1.3570 -0.2169 1.5872 0.C195 0.4015 0.1643 0.2372 591.07 -0.2331 2.1808 -0.2141 1.5526 0.0297 0.4000 0.1640 0.2361 591.59 -0.3081 2.8966 -0.2119 1.5276 0.0335 0.3988 0.1650 0.2336 592.09 -0.3683 3.4576 -0.2034 1.4445 0.0329 C.3989 0.1649 0.2319 593.11 -0.4946 4.6175 -0.2037 1.4562 C.0241 0.3928 0.1649 0.2279 594.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.24 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
0.97 0.1088 -1.2230 -0.2360 1.8016-0.0156 0.4115 0.1663 0.2452 59. 0.46 0.0318 -0.4684 -0.2408 1.8455-0.0106 0.4076 0.1659 0.2417 59. -0.05 -0.0564 0.4140 -0.2332 1.7623 0.0023 0.4047 0.1661 0.2386 59. -0.56 -0.1502 1.3570 -0.2169 1.5872 0.0195 0.4015 0.1643 0.2372 59. -1.07 -0.2331 2.1808 -0.2141 1.5526 0.0297 0.4000 0.1640 0.2361 59. -1.59 -0.3081 2.8966 -0.2119 1.5276 0.0335 0.3988 0.1650 0.2336 59. -2.09 -0.3683 3.4576 -0.2034 1.4445 0.0329 0.3969 0.1649 0.2319 59. -3.11 -0.4946 4.6175 -0.2037 1.4562 0.0241 0.3928 0.1649 0.2279 59. -4.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
0.46 0.0318 -0.4684 -0.2408 1.8455-0.0106 0.4076 0.1659 C.2417 590.05 -0.0564 0.4140 -0.2332 1.7623 0.0023 0.4047 0.1661 0.2386 590.56 -0.1502 1.3570 -0.2169 1.5872 0.0195 0.4015 0.1643 0.2372 591.07 -0.2331 2.1808 -0.2141 1.5526 0.0297 0.4000 0.1640 0.2361 591.59 -0.3081 2.8966 -0.2119 1.5276 0.0335 0.3988 0.1650 0.2336 592.09 -0.3683 3.4576 -0.2034 1.4445 0.0329 C.3969 0.1649 0.2319 593.11 -0.4946 4.6175 -0.2037 1.4562 G.0241 0.3928 0.1649 0.2279 594.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
-0.05 -0.0564
-0.56 -0.1502
-1.07 -0.2331
-1.59 -0.3081
-2.09 -0.3683 3.4576 -0.2034 1.4445 0.0329 0.3969 0.1649 0.2319 593.11 -0.4946 4.6175 -0.2037 1.4562 0.0241 0.3928 0.1649 0.2279 594.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
-3.11 -0.4946
-4.14 -0.6184 5.7448 -0.2080 1.5058 0.0118 0.3903 0.1674 0.2229 59. MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
MODEL 946.2 CONFIG. 2.000 MACH 1.75 PHI = 90. Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = .
DD. 107 A CHILD DTC 2 0445 DCT
PO= 107.0 CMHG PTS= 3.8665 PSI RUN NO. 0270269102
ALPHA CN CM CS CY CR CAT CPB CAF RUN
4.08 0.5152 ~4.8867 -0.0276 0.2524 0.0032 0.3913 0.1584 0.2329 60.
3.07 0.3836 -3.6522 -0.0379 0.3595 0.0027 0.3876 0.1572 0.2304 60.
2.05 0.2533 -2.3956 -0.0300 C.2752 0.0032 0.3844 0.1575 0.2269 60.
1.53 0-1854 -1.7510 -0.0341 0.3179 0.0031 0.3829 0.1586 0.2243 60.
1.01 0.1245 -1.1742 -0.0291 0.2689 0.0036 0.3800 0.1593 0.2208 60.
0.50 0.0603 -0.5699 -0.0254 0.2313 0.0036 0.3791 0.1607 0.2184 60.
0. 0.0015 -0.0145 -0.0301 0.2777 0.0041 0.3784 0.1607 0.2177 60.
-0.52 -0.0633
-1.02 -0.1252
-1.54 -0.1897 1.7929 -0.0353 0.3345 0.0038 0.3759 0.1589 0.2171 60.
-2.04 -0.2502
-3.06 -0.3801 3.5997 -0.0301 0.2834 0.0048 0.3692 0.1557 0.2135 60.
-4.08 -0.5153 4.8853 -0.0287 0.2675 0.0060 0.3680 0.1559 0.2121 60.

THE PROPERTY OF THE PROPERTY O

MODFL 946.2	CONF	16. 2.000	H.	ICH 1.75	PHI =	90.	
Q= 8.29 PSI	RE PER	IN.= .48E0	5 TO=	90. DEG.	79\L09	'S = 10.	
PO= 107.9 CM	HG PTS=	3.8665 PSI		RUM	N NO. 027026	9103	
ALPHA CN	CM	CS	£Y.	CR CA	AT CPB	CAF	RUN
4.09 0.5188	-4.9142	-0.0481			3950 0.1633		61.
3.07 0.3861	-	-0.0512		-	3912 0.1618		61.
2.05 0.2573		-0.0485			3874 0.1609		61.
1.53 0.1921		-0.048ŏ			3879 0.1617		61.
1.01 0.1319		-0.0528			3865 0.1618		61.
0.51 0.0695		-0.0471			3836 0.1626		61.
-0.01 -0.0008		-0.0500			3833 0.1629		61.
-0.52 -0.0715		-0.0413			3815 0.1620		61.
-1.03 -0.1373 -1.54 -0.1979		-0.0435			3806 0.1612 3791 0.1608		61. 61.
-2.04 -0.2554		-0.0410 -0.0418			3770 0.1607		61.
-3.06 -0.3843					3753 0.1600		61.
-4.08 -0.5188		-0.0487			3723 0.1603		61.
MODEL 946.2	CON	=1G. 2.000	M	ACH 1.75	PHI =	90.	
MODEL 946.2 Q= 8.29 PSI		FIG. 2.000 IN.= .48E0		ACH 1.75 90. DEG.	_		
	RE PER	IN.= .48E0		90. DEG.	_	'S = 20.	
Q= 8.29 PSI	RE PER	IN.= .48E0		90. DEG.	F POJ/P1	'S = 20.	RUN
Q= 8.29 PSI PO= 107.0 CF ALPHA CN	RE PER MHG PTS= CM	IN.= .48E0	6 TO=	90. DEG. RUI	F POJ/P1 N NO. 027026 AT CPB	S = 20. 69104 CAF	RUN 62.
Q= 8.29 PSI PO= 107.0 CF	RE PER HHG PTS= CM -4.9322	IN.= .48E0 3.8665 PSI	6 TO= CY 0.5037	90. DEG.8 RUN CR CA	F POJ/P1	S = 20. 69104 CAF 0.2351	
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 4.09 0.5222	RE PER HHG PTS= CM -4.9322 -3.7217	IN.= .48E0 3.8665 PSI CS -0.0673	6 TO= CY 0.5037- 0.5377	90. DEG.8 RUN CR CA 0.0168 0.3 0.0109 0.3	F POJ/PT N NO. 027026 AT CPB 3999 0.1649	S = 20. 69104 CAF 0.2351 0.2337	62.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.5222 3.07 0.3937	RE PER HHG PTS= CM -4.9322 -3.7217 -2.5418	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704	6 TO= CY 0.5037 0.5377 0.5924	90. DEG.F RUI CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3	F POJ/PT N NO. 027026 AT CPB 3999 0.1649 3956 0.1619	S = 20. 69104 CAF 0.2351 0.2337 0.2318	62. 62.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671	RE PER SHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761	CY 0.5037- 0.5377 0.5924 0.4727-	90. DEG.F RUI CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0013 0.3	POJ/PI N NG. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610	CAF 0-2351 0-2337 0-2318 0-2297	62. 62.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062	RE PER SHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761 -0.0633 -0.0790 -0.0597	CY 0.50377 0.55377 0.5924 0.4727- 0.6301- 0.4333	90. DEG-F RUF CR CA 0.0168 0-3 0.0109 0-3 0.0039 0-3 -0.0013 0-3 -0.0057 0-3 -0.0017 0-3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1620 3913 0.1625 3900 0.1634	S = 20. 69104 CAF 0.2351 0.2337 0.2318 0.2297 0.2288 0.2266	62. 62. 62. 62. 62.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004	RE PER SHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761 -0.0633 -0.0790 -0.0597 -0.0615	CY 0.5037 0.5377 0.5924 0.4727 0.6301 0.4333 0.4568	90. DEG-18 RUF CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0013 0.3 -0.0057 0.3 -0.0017 0.3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1620 3913 0.1625 3900 0.1634 3895 0.1648	CAF 0.2351 0.2337 0.2318 0.2297 0.2288 0.2266 0.2247	62. 62. 62. 62. 62. 62.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004 -0.52 -0.0822	RE PER MHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111 0.8097	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761 -0.0633 -0.0790 -0.0597 -0.0615 -0.0686	CY 0.5037 0.5377 0.5377 0.5924 0.4727 0.6301 0.4333 0.4568 0.5258	90. DEG. F RUF CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0017 0.3 -0.0017 0.3 0.0047 0.3 0.0142 0.3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1625 3910 0.1634 3895 0.1648 3895 0.1648	CAF 0.2351 0.2351 0.2337 0.2318 0.2297 0.2288 0.2266 0.2247 0.2243	62. 62. 62. 62. 62. 62. 62.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004 -0.52 -0.0822 -1.03 -0.1497	RE PER HHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111 0.8097 1.4533	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0633 -0.0790 -0.0597 -0.0615 -0.0686 -0.0721	CY 0.5037 0.5377 0.5377 0.5924 0.4727 0.6301 0.4333 0.4568 0.5258 0.5626	90. DEG. F RUF CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0017 0.3 -0.0017 0.3 0.0047 0.3 0.0142 0.3 0.0147 0.3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3917 0.1620 3913 0.1625 3900 0.1634 3895 0.1648 3884 0.1640 3884 0.1637	CAF 0.2351 0.2351 0.2318 0.2297 0.2288 0.2266 0.2247 0.2243 0.2212	62. 62. 62. 62. 62. 62. 62.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004 -0.52 -0.0822 -1.03 -0.1497 -1.53 -0.2072	RE PER HHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111 0.8097 1.4533 1.9820	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0633 -0.0790 -0.0597 -0.0615 -0.0686 -0.0721 -0.0656	CY 0.5037 0.5377 0.5924 0.4727 0.6301 0.4333 0.4568 0.5258 0.5626 0.5024	90. DEG. F RUF CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0017 0.3 -0.0017 0.3 0.0047 0.3 0.0142 0.3 0.0147 0.3 0.0118 0.3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1629 3913 0.1625 3900 0.1634 3895 0.1648 3884 0.1640 3849 0.1637 3833 0.1630	CAF 0.2351 0.2351 0.2318 0.2297 0.2288 0.2266 0.2247 0.2243 0.2212 0.2203	62 · 62 · 62 · 62 · 62 · 62 · 62 · 62 ·
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004 -0.52 -0.0822 -1.03 -0.1497 -1.53 -0.2072 -2.04 -0.2637	RE PER 4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111 0.8097 1.4533 1.9820 2.4994	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761 -0.0633 -0.0790 -0.0597 -0.0615 -0.0686 -0.0721 -0.0656 -0.0671	CY 0.5037 0.5037 0.5037 0.5924 0.4727 0.6301 0.4333 0.4568 0.5026 0.5024 0.5136	90. DEG. RUI CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0013 0.3 -0.0057 0.3 -0.0017 0.3 0.0047 0.3 0.0142 0.3 0.0147 0.3 0.0147 0.3	POJ/PI N NG. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1629 3913 0.1625 3900 0.1634 3895 0.1648 3884 0.1640 3849 0.1637 3833 0.1630 3820 0.1626	CAF 0.2351 0.2351 0.2337 0.2318 0.2297 0.2288 0.2266 0.2247 0.2243 0.2212 0.2203 0.2194	62 · 62 · 62 · 62 · 62 · 62 · 62 · 62 ·
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.09 0.5222 3.07 0.3937 2.05 0.2671 1.52 0.2062 1.00 0.1465 0.50 0.0807 -0.01 0.0004 -0.52 -0.0822 -1.03 -0.1497 -1.53 -0.2072	RE PER HHG PTS= CM -4.9322 -3.7217 -2.5418 -1.9834 -1.4357 -0.8070 -0.0111 0.8097 1.4533 1.9820	IN.= .48E0 3.8665 PSI CS -0.0673 -0.0704 -0.0761 -0.0633 -0.0790 -0.0597 -0.0615 -0.0686 -0.0721 -0.0656 -0.0671 -0.0668	CY 0.5037- 0.5377 0.5924 0.4727- 0.6301- 0.4333- 0.4568 0.505626 0.5024 0.5136 0.5116	90. DEG. RUI CR CA 0.0168 0.3 0.0109 0.3 0.0039 0.3 -0.0057 0.3 -0.0057 0.3 -0.0047 0.3 0.0142 0.3 0.0142 0.3 0.0143 0.3 0.0145 0.3	POJ/PI N NO. 027026 AT CPB 3999 0.1649 3956 0.1619 3928 0.1610 3917 0.1629 3913 0.1625 3900 0.1634 3895 0.1648 3884 0.1640 3849 0.1637 3833 0.1630	CAF 0.2351 0.2351 0.2337 0.2318 0.2297 0.2288 0.2266 0.2247 0.2243 0.2212 0.2203 0.2194 0.2173	62 · 62 · 62 · 62 · 62 · 62 · 62 · 62 ·

	_												
	MOE	EL 946.	2	СОИ	FIG.	2.000	. H	ACH 1.7	5	PHI ≖	90.		
	Q=	8.29 PS	I RE	E PER	IN.=	-48E0	b T0=	90. D	EG.F	P0J/P	TS =	40.	
	P0=	107.0	CMHG	PTŚ=	3.86	65 PSI			RUN NO	. 02702	69105		
ALP	PHA	CN	C	CM	C	S	CY	CR	CAT	CPB	CAF		RUN
,	^^	A C222	_			202	0.0015	0.0170	0 (027	0 4444	0~220	~	63.
	.09	0.5333		.0283					0.4037				_
	.07	0.4041		8281					0.3997				63 _•
	.05	0.2876		.7645									
	53	0.2273		2179					0.3997				63.
	.01	0.1549		.6404					0.4003			-	63.
	50	0.0910		9247					0.3978				63.
-0.		0.0023		0284					0.3973				63.
		-0.0910		.9165					0.3917				63.
		-0.1655		6396					0.3902				63.
	-	-0.2275		.2137					0.3878				63.
		-0.2809		6960					0.3864				. 63.
		-0:4002		7841					0.3838				63%
-4.	OR	-0=5299	4.	9884	-0.r	100	0.1914	-0.0019	0-3806	0.1638	0.216	8	63.
	MOD	EL 946.	2	CONF	IG.	5.000	H	ACH 1.7	5	PHI =	90.		
	Q=	8.29 PS	I RE	PER	IN.=	.48E0	6 TO=	90. DI	EG.F	POJ/P	TS =	80.	
	P0=	107.0	СЯНС	PTS=	3.86	129 2 8			RUN NO.	02702	69106		•
ALP	HA	CN	C	CH	C	S	εy	CŘ	CAT	CPB	CAF		. RUN
	.09	0.5593	_6	2874	-0.2	24.2	1 7262	0.0106	0.4154	0 1475	0 247	۵	64.
	07	0.4356		1577					0.4116				64.
_	.05	0.3106		0141		-			0.4135				64.
	52	0.2409		3673					0.4123				64.
	.00	0.1730		7242					0.4098			-	64.
_	50	0.0922		9285				·-	0.4060				64.
-0.		0.0922		0302					0.4037				64.
		-0.0955		7598					0.3996			-	64.
		~0.1774		7691					0.3983				64.
		-0.2474		4319					U.3975				64.
_		-0.3085		9946					0.3959				64.
		~0.4348		1482					0.3918				64.
		-0.5597		2869					0.3911				64.
	U 7	-0-2371	3 4		UAZ	T. K. Z.	LAUZUD	U = U U U Z	UBJIUL	USIDII	HOLLE.	-	UTA

MODFL 946.2	CONF	IG. 2.45	O MA	CH 1.7	5	PHI =	•	
C= 8.29 PSI	RE PER	IN.= .48E	06 TO=	90. VI	<u>E</u> G.F	POJ/P	TS =	•
PO= 107.0 C	HG PTS=	3.8665 PS	I		RUN NO	02702	69107	
ALPHA CN	CH	cs	CY	CR	CAT	CP8	ÇAF	RUN
4.07 0.5035	-4:7632	-0.0155	0.1268	0.0057	0.3896	0.1665	0.2231	65.
3.05 0.3756	-3.5506	-0.0166	0.1318	0.0060	0.3885	0.1654	0.2231	65.
2.04 0.2488	-2 63504	-0.0112	0.0839	0.0055	0.3860	0.1645	0.2216	65.
1.51 0.1829	-1.7295	-0.0126	0.0952	0.0051	0.3863	0.1631	0.2232	65.
1.00 0.1201	-1.1353	-0.0105			0.3844			65.
0.49 0.0568		-0.0087			0.3831			65
-0.02 -0.0072		-0.0105			0.3853			65.
-0.53 -0.0594	0.5605	-			0.3818			65.
-1.04 -0.1254		-0.0084			0.3833			65.
-1.56 -C.1868		-0.0063			0.3814			65.
-2.05 -0.2416	2.2852				0.3813			65.
-3.07 -0.3709		-0.0038			0.3809			65.
-4.09 -0.5009	4.7416	-0.0024	-0.0026	0.0047	0.3819	0.1605	0.2214	.65 •
MODEL 946.2 Q= 8.29 PSI		FIĞ. 2.45 IN.≐ .48E		1CH L.79	•	PHI =	rs = 1	0.
	RE PER	IN.= .48E	06 TO=		EG.F		_	0.
124 62°8 =D	RE PER	IN.= .48E	06 TO=		EG.F	POJ/P	_	0. RUN
Q= 8.29 PSI PO= 107.0 CI ALPHA CN	RE PER MHG PTS=	IN.= .48E 3.8665 PS	06 TO=	90. DI	EG.F RÚN NO: Cat	POJ/P: • 02702: CP8	69108 CAF	RUN
Q= 8.29 FSI PO= 107.0 SI	RE PER HHG PTS= CM -4.7067	IN.= .48E 3.8665 PS CS -0.0162	06 TO= CY 0.1366	90. DI CR C. 0079	EG.F RÜN NO CAT 0.3939	POJ/P. 02702: CP8 0.1688:	69108 CAF	
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641	RE PER MHG PTS= CM -4.7067 -3.5090	IN.= .48E 3.8665 PS	CY 0.1366 0.1106	90. DI CR C.0079 0.0070	EG.F RÜN NO CAT 0.3939 0.3900	POJ/P 02702 CPB 0.1688	69108 CAF	RUN 66.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016	IN.= .48E 3.8665 PS CS -0.0162 -0.0131	CY 0.1366 0.1106 0.0738	90. DI CR 0.0079 0.0070 0.0065	EG.F RÜN NO CAT 0.3939 0.3900	POJ/P 02702 . CPB 0.1688 0.1575 0.1660	69108 CAF 0.2250 0.225 0.225	RUN 66. 66.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103	CY 0.1366 0.1106 0.0738 0.0878	90. DI CR 0.0079 0.0070 0.0065 0.0064	EG.F RÜN NO CAT 0.3939 0.3900 0.3875	POJ/P 02702 . CPB 0.1688 0.1575 0.1660 0.1647	69108 CAF 0.2250 0.2255 0.2215	RUN 66. 66. 66.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113	06 T0= CY 0.1366 0.1166 0.0738 0.0878 0.0748	90. DI CR 0.0079 0.0070 0.0065 0.0064 0.0060	CAT 0.3939 0.3900 0.3875 0.3864	POJ/P. . 02702 CPB 0.1688 0.1575 0.1660 0:1647 0.1635	69108 CAF 0.2250 0.2255 0.2215 0.2217 0.2231	RUN 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0103 -0.0068 -0.0050	CY 0.1366 0.1106 0.0738 0.0878 0.0748 0.0445 0.0263	90. DI CR 0.0079 0.0070 0.0065 0.0064 0.0069 0.0059	CAT 0.3939 0.3939 0.3875 0.3864 0.3866 0.3831 0.3833	POJ/P. . 02702 CPB 0.1688 0.1675 0.1660 0.1647 0.1635 0.1629 0.1626	69108 CAF 0.2250 0.225 0.2215 0.2217 0.2231 0.2202 0.2207	RUN 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061 0.48 0.0525 -0.03 -0.0134 -0.55 -0.0729	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659 0.6266	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0103 -0.0068 -0.0050 -0.0054	CY 0.1366 0.1106 0.0738 0.0878 0.0748 0.0445 0.0263 0.0297	90. DI CR 0.0079 0.0070 0.0065 0.0064 0.0059 0.0055 0.0060	CAT 0.3939 0.3939 0.3875 0.3866 0.3831 0.3833 0.3833	POJ/P. . 02702 CP8 0.1688 0.1575 0.1660 0.1647 0.1635 0.1629 0.1626 0.1621	69108 CAF 0.2250 0.2255 0.2215 0.2217 0.2231 0.2202 0.2207 0.2212	RUN 66. 66. 66. 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061 0.48 0.0525 -0.03 -0.0134 -0.55 -0.0729 -1.05 -0.1343	RE PER MHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659 0.6266 1.2064	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0103 -0.0068 -0.0050 -0.0054 +0.0043	CY 0.1366 0.1166 0.0738 0.0878 0.0748 0.0445 0.0263 0.0297 0.0193	90. DI CR 0.0079 0.0065 0.0064 0.0069 0.0055 0.0060 0.0053	CAT 0.3939 0.3939 0.3875 0.3866 0.3831 0.3833 0.3833	POJ/P. . 02702 CP8 0.1688 0.1575 0.1660 0.1647 0.1635 0.1629 0.1621 0.1616	69108 CAF 0.2250 0.2255 0.2215 0.2217 0.2231 0.2202 0.2207 0.2212 0.2212	RUN 66. 66. 66. 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061 0.48 0.0525 -0.03 -0.0134 -0.55 -0.0729 -1.05 -0.1343 -1.56 -0.1970	RE PER HHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659 0.6266 1.2064 1.7994	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0068 -0.0050 -0.0054 -0.0043 -0.0029	CY 0.1366 0.1106 0.0738 0.0878 0.0748 0.0463 0.0297 0.0193 0.0052	90. DI CR 0.0079 0.0070 0.0065 0.0064 0.0059 0.0053 0.0053	CAT 0.3939 0.3900 0.3875 0.3864 0.3866 0.3831 0.3833 0.3837 0.3833	POJ/P. . 02702 CP8 0.1688 0.1575 0.1660 0.1647 0.1635 0.1626 0.1621 0.1616 0.1619	69108 CAF 0.2250 0.2255 0.2215 0.2217 0.2202 0.2202 0.2202 0.2212 0.2212 0.2196	RUN 66. 66. 66. 66. 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061 0.48 0.0525 -0.03 -0.0134 -0.55 -0.0729 -1.05 -0.1343 -1.56 -0.1970 -2.07 -0.2538	RE PER HHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659 0.6266 1.2064 1.7994 2.3382	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0068 -0.0050 -0.0054 -0.0054 -0.0029 -0.0026	CY 0.1366 0.1106 0.0738 0.0878 0.0748 0.0445 0.0263 0.0297 0.0173 0.0052 0.0052	90. 00 CR C. 0079 0. 0070 0. 0065 0. 0064 0. 0059 0. 0055 0. 0065 0. 0055 0. 0055	CAT 0.3939 0.3900 0.3875 0.3864 0.3831 0.3833 0.3837 0.3815 0.3808	POJ/P. 02702 CP8 0.1688 0.1575 0.1660 0.1647 0.1635 0.1629 0.1620 0.1616 0.1619 0.1613	69108 CAF 0.2250 0.2255 0.2215 0.2217 0.2231 0.2202 0.2202 0.2212 0.2120 0.2196 0.2194	RUN 66. 66. 66. 66. 66. 66. 66. 66.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4901 3.04 0.3641 2.03 0.2367 1.50 0.1714 1.00 0.1061 0.48 0.0525 -0.03 -0.0134 -0.55 -0.0729 -1.05 -0.1343 -1.56 -0.1970	RE PER HHG PTS= CM -4.7067 -3.5090 -2.3016 -1.6835 -1.0658 -0.5592 0.0659 0.6266 1.2064 1.7994 2.3382 3.5328	IN.= .48E 3.8665 PS CS -0.0162 -0.0131 -0.0103 -0.0113 -0.0068 -0.0050 -0.0054 -0.0043 -0.0029	CY 0.1366 0.1106 0.0738 0.0878 0.0748 0.0463 0.0297 0.0193 0.0052	90. 00 CR C.0079 0.0070 0.0065 0.0064 0.0059 0.0055 0.0050 0.0055 0.0051	CAT 0.3939 0.3900 0.3875 0.3864 0.3831 0.3833 0.3837 0.383830 0.38383	POJ/P. 02702 CPB 0.1688 0.1675 0.1660 0.1647 0.1635 0.1629 0.1621 0.1619 0.1613 0.1596	CAF 0.2250 0.2255 0.2215 0.2217 0.2231 0.2202 0.2207 0.2212 0.2196 0.2194 0.2207	RUN 66. 66. 66. 66. 66. 66. 66.

MODEL 946.2	CONFIG.	2.450 M	ACH 1.75	PHI = .	
Q= 8.29 PSI	RE PER IN.	: .48EG& TO=	90. DEG.F	POJ/PTS = 20.	
PG= 107.0 CM	HG PTS= 3.80	665 PSI	RUN NO	. 0270269109	
ALPHA CN	CH (S CY	CR CAT	CPS CAF	RUN
4.04 0.4747	-4.6230 -0.6		0.0086 0.4021		67.
3.03 0.3454	-3.3949 -0.0			0.1719 0.2257	67.
2.01 0.2187	-2.1928 -0.0		0.0058 0.3932		67.
1.49 C.1501	-1.5414 -0.0		0.0057 0.3921	<u>.</u>	67.
0.97 0.0900	-0.9749 -0.0		0.0056 0.3915		57 •
0.47 0.0254	-0.3612 -0.0		0.0061 0.3883		67:
-0.05 -0.0321	0.1805 ~0.0		0.0060 0.3869		67.
-0.55 -0.0935	0.7575 -0.0		0.0062 0.3857		67.
	1.3372 -0.0	0.0160	0.0055 0.3838		67.
-1.57 -0.2176 -2.08 -0.2711	1.9288 -0.0	0.0027		0.1624 0.2195	67.
-2.08 -0.2711	2.4327 -0.0	0.0004		0.1619 0.2199	67.
	3.6318 -0.0		0.0062 0.3807		67 •
-4.12 -0.5285	4.8670 0.0	1024 -0.0441	0.0054 0.3824	0.1012 0.2211	67.
MODEL 946.2	CONFIG.	2.450 M	ACH 1.75	PHI = .	
Q= 8.29 PSI	RE PER IN.	48E06 TO=	90. DEG.F	POJ/PTS = 40.	
PO= 107.0 CM	HG PTS= 3.86	665 PSI	RUN NO	. 0270269110	
ALPHA CN	CH (s CY	CR CAT	CPB CAF	RUN
, , , , , , , , , , , , , , , , , , , ,	• • • • • • • • • • • • • • • • • • • •	•			
4.02 0.4335	-4.3584 -0.0	183 0.1556	0.0107 0:4049	0.1751 0.2298	68.
3.00 0.3042	-3.1259 -0.0		0.0090 0.4004		68.
1.99 0.1743	-1.8944 -0.0		0.0076 0.3974		68.
1.46 0.1057	-1.2445 -0.0	0.0911	0.0078 0.3963	0.1708 0.2255	68.
0.95 0.0410	-0.6327 -0.0	0.0581	0.0076 0.3937	0.1700 -0.2237	68.
0.44 -0.0172	-0.0868 -0.0		0.0078 0.3924		68.
-0.07 -0.0766	0.4727 -0.0	0.0375	0.0072 0.3911	0.1682 0.2230	68.
-0.58 -0.1361	1.0320 -0.0	0.0153	0.0071 0.3885	0.1665 0.2220	68.
-1.13 -0.2073	1.7040 -0.0	0024 -0.0027	0.0067 0.3869	0.1653 0.2216	68.
-1.60 -0.2595	2.1919 -0.0	0.0117	.0.0066 0.3860		68.
-2.11 -0.3196	2.7570 -0.0	017 -0.0098	0.0068 0.3848	0.1634 0.2214	68.
-3.13 -0.4444	3.9312 0.0	0001 -0.0286	0.0072 0.3837		68.
-4-15 -0-5705	5-1184 0-0	NOS1 _0 0745	0.0072 0.3839	0 1420 0 2211	68.

нос	EL 946.2	СОМІ	FIG. :	2.450 M	ACH 1.75	5	PHI =	•	
Ç=	8.29 PSI	RE PER	IN.=	.48E06 TO=	90. DI	EG.F	P0J/P	rs = -	80.
P0=	107.0 CM	HG PTS=	3.866	5 PSI		RUN NO	02702	69111	
ALPHA	CN	СН	c s	CY	CR	CAT	СРВ	CAF	RUN
3.97	0.3348	-3.6723	-0.02	25 0.1872	0.0148	0.4128	0.1749	0.2379	69.
2.95	0.2002	-2.3933	-0.01	86 0.1517	0.0122	D.4118	0.1752	0.2367	69.
1.93	0.0688	-1.1481	-0.013	27 0.0996	0.0103	0.4087	0.1744	0.2343	69.
1.40	0.0009	-0.5039	-0.01	0.0690	0.0093	0.4063	0.1725	0.2338	69.
0.90	~0.0683	0.1534	-0.00	87 0.0563	0.0086	0.4045	0.1714	0.2331	69.
0.39	-0.1238	0.6720	-0.00		0.0088				
-0.13	-0.1859	1.2546	-0.00	80 0.0440	0.0081	0.4013	0.1695	0.2318	69.
-0.63	-0.2467	1.8226	-0.00	37 0.0075	0:0074	0.3987	0.1678	0.2309	
-1.15	-0.3068	2.3807	-0.00	44 0.0094	0.0074	0.3962	0.1663	0.2299	69.
-1.65	-0.3670	2.9442	-0:000	08 -0.0208	0.0064	0.3942	0.1651	0.2291	69.
-2.17	-0.4238	3.4716	-0.00						
	-0.5427	4.5833							
-4.21	-0.6670	5.7381	0.00	69 -0.0928	0.0074	0.3901	0.1618	0.2283	
мос	DEL 946.2	CON	FIG. :	2.450 M	ACH 1.75	5	PHI =	15.	
	DEL 946.2 8.29 PSI	CONI RE PER			ACH 1.75		PHI =		-
Q=	-	RE PER	IN.=	.48506 TO=		EG.F		TS =	· •
Q=	8.29 PSI	RE PER	IN.=	.48506 TO=		EG.F	POJ/P	TS =	• RUN
Q= P0=	8.29 PSI = 107.0 CM	KE PER	IN.= 3.8669	.48506 TO= 5 PSI CY	90. D	EG.F RUN NO.	POJ/P • 02702 CPB	TS = 69112 CAF	
Q= PO= Alpha	8.29 PSI = 107.0 CM	RE PER HG PTS=	IN.= 3.8669 CS -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521	90. DE	EG.F RUN NO. CAT	POJ/P . 02702 CPB 0.1668	TS = 69112 CAF 0.2288	70.
Q= P0= ALPHA 4.09	8.29 PSI : 107.0 CM CN 0.5082	RE PER HG PTS= CM -4.8112	IN.= 3.8669 CS -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403	90. DE	EG.F RUN NO. CAT 10.3956 10.3907	POJ/P . 02702 CPB 0.1668 0.1659	TS = 69112 CAF 0.2288 0.2248	70. 70.
Q= PO= ALPHA 4.09 3.07	8.29 PSI = 107.0 CM CN 0.5082 0.3786	RE PER HG PTS= CM -4.8112 -3.5811	IN.= 3.8669 CS -0.017 -0.016 -0.017	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918	90. DE	EG.F RUN NO. CAT '0.3956 '0.3907 0.3884	POJ/P . 02702 . CPB 0.1668 0.1659 0.1653	TS = 69112 CAF 0.2288 0.2248 0.2231	70. 70. 70.
Q= PO= ALPHA 4.09 3.07 2.06	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669	IN.= 3.8669 CS -0.01 -0.010 -0.010 -0.010	.48 ± 06 T0 = 5 PSI CY 71 0 .1521 69 0 .1403 16 0 .0918 21 0 .0927	90. D8 CR 0.0058 0.0056 0.0061	CAT 0.3956 -0.3907 0.3884 0.3889	POJ/P . 02702 . CPB 0.1668 0.1659 0.1653 0.1644	TS = 69112 CAF 0.2288 0.2248 0.2231 0.2246	70. 70. 70. 70.
Q= PO= ALPHA 4.09 3.07 2.06 1.53	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703	IN.= 3.8669 CS -0.01 -0.010 -0.010 -0.010 -0.010	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118	90. D8 CR 0.0058 0.0056 0.0061 0.0059	CAT 0.3956 0.3907 0.3884 0.3889 0.3876	POJ/P . 02702 CPB 0.1668 0.1659 0.1653 0.1644 0.1639	TS = 69112 CAF 0.2288 0.2248 0.2231 0.2246 0.2237	70. 70. 70. 70.
Q= PO= ALPHA 4.09 3.07 2.06 1.53 1.02	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066	90. D8 CR 0.0058 0.0056 0.0051 0.0059 0.0053	CAT 0.3956 0.3997 0.3884 0.3889 0.3876	POJ/P . 02702 CP8 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640	TS = 69112 CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235	70. 70. 70. 70. 70.
Q= PO= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050	CAT 0.3956 -0.3907 0.3884 0.3876 0.3874 0.3866	POJ/P . 02702 . CPB 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640 0.1642	CAF 0.2288 0.2248 0.2248 0.2231 0.2246 0.2237 0.2235	70. 70. 70. 70. 70. 70.
Q= PO= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51 -0.	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594 -0.0025	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606 0.0204	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060 27 0.0966	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050 0.0048	CAT 0.3956 0.3957 0.3884 0.3876 0.3874 0.3866 0.3877	POJ/P . 02702 . CPB 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640 0.1642 0.1639	CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235 0.2224	70. 70. 70. 70. 70. 70. 70.
Q= P0= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51 -0.51	8.29 PSI = 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594 -0.0025 -0.0597	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606 0.0204 0.5640	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060 27 0.0966 21 0.0936	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050 0.0048	CAT 0.3956 0.3956 0.3876 0.3876 0.3876 0.3877 0.3841	POJ/P . 02702 . CPB 0.1668 0.1659 0.1653 0.1644 0.1649 0.1640 0.1642 0.1639 0.1635	CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235 0.2224 0.2238 0.2207	70. 70. 70. 70. 70. 70. 70. 70.
Q= P0= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51 -0.51 -1.02 -1.53	8.29 PSI 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594 -0.0025 -0.0597 -0.1202	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606 0.0204 0.5640 1.1364	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060 27 0.0966 21 0.0936 21 0.0936 21 0.0936 21 0.0936	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050 0.0048 0.0051 0.0049 0.0052	CAT 0.3956 0.3957 0.3884 0.3889 0.3874 0.3867 0.3874 0.3821 0.3799	POJ/P . 02702 CPB 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640 0.1642 0.1635 0.1627 0.1627	CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235 0.2224 0.2238 0.2237 0.2193 0.2179	70. 70. 70. 70. 70. 70. 70. 70. 70.
Q= P0= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51 -00.51 -1.02 -1.53 -2.04	8.29 PSI 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594 -0.0025 -0.0597 -0.1202 -0.1851	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606 0.0204 0.5640 1.1364 1.7502	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060 27 0.0966 21 0.0936 28 0.0986 58 0.1203 97 0.0666	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050 0.0048 0.0051 0.0049 0.0052 0.0049	CAT 0.3956 0.3907 0.3884 0.3889 0.3876 0.3874 0.3866 0.3871 0.3821 0.3799 0.3782	POJ/P . 02702 CPB 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640 0.1642 0.1635 0.1635 0.1627 0.1620 0.1598	TS = 69112 CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235 0.2224 0.2238 0.2217 0.2193 0.2179 0.2183	70. 70. 70. 70. 70. 70. 70. 70. 70.
Q= P0= ALPHA 4.09 3.07 2.06 1.53 1.02 0.51 -00.51 -1.53 -2.04 -3.05	8.29 PSI 107.0 CM CN 0.5082 0.3786 0.2502 0.1872 0.1206 0.0594 -0.0025 -0.0597 -0.1202 -0.1851 -0.2440	RE PER HG PTS= CM -4.8112 -3.5811 -2.3669 -1.7703 -1.1372 -0.5606 0.0204 0.5640 1.1364 1.7502 2.3097	IN.= 3.8666 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48 ± 06 T0 = 5 PSI CY 71 0.1521 69 0.1403 16 0.0918 21 0.0927 43 0.1118 36 0.1066 33 0.1060 27 0.0966 21 0.0936 28 0.0986 58 0.1203 97 0.0666	90. D8 CR 0.0058 0.0056 0.0061 0.0059 0.0053 0.0050 0.0048 0.0051 0.0049 0.0052	CAT 0.3956 0.3907 0.3884 0.3889 0.3876 0.3874 0.3866 0.3871 0.3821 0.3799 0.3782	POJ/P . 02702 CPB 0.1668 0.1659 0.1653 0.1644 0.1639 0.1640 0.1642 0.1635 0.1635 0.1627 0.1620 0.1598	TS = 69112 CAF 0.2288 0.2248 0.2231 0.2246 0.2237 0.2235 0.2224 0.2238 0.2217 0.2193 0.2179 0.2183	70. 70. 70. 70. 70. 70. 70. 70. 70.

•	IODEL	946.2	CON	FIS.	2.450	H	ich 1.7:	5	- 2Hd·	-15+	-
C	= 8.2	29 PSI	RE PER	IN.=	.48E06	* TO	90. DI	EG.F	POJ/P	TS =	10-
P	0= 10	07.0 CX	หรั PTS=	3.866	65 PSI			RUN NO.	. 02702	69113	
ALP	IA	CN	CH	C.	S	CY	CR	CÁT	CP8	CAF	RUN
4.0	7 n.	4959	-4.7611	-0.02	205	0.1647	0-0103	0.3985	0.1707	0.2278	71.
3.0		3648	-3.5150					0.3942			
2.0	-	2395	-2.3266		_			0.3919			
1.5		1721	-1.6889					C.3898			
1.0		1116	-1.1155					0.3876			
		.0482	-0.5158					0.3875			
		0106	0.0409			0.0777	0.0064	0.3859	0.1639	0.2221	71.
		0715	0.6158					0.3845			
		1324	1.1912					0.3829			
		1955	1.7862			0.0706	0.0044	0.3808	0.1626	C-2183	F1.
		2543	2.3441	-0.0	118			0.3806			
-3.0	6 -0	3786	3.5221	-0.01	112			0.3789			
-4.0	8 -0	5124	4.7900			0.0449	0.0016	0.3814	0.1613	0.2201	71.
			CON RE PER	•	, ,		90. DI		PHI =	15. rs =	20.
O)= 8.i	29 PSI	RE PER	IN.=	-48E06	T0=	90. DI	EG.F	P0 3/ P	rs =	20•
O)= 8.i	29 PSI	RE PER	IN.=	-48E06	T0=	90. DI		P0 3/ P	rs =	20.
O)= 8.2 10= 10	29 PSI	RE PER	IN.=	.48E06	T0=	90. DI	EG.F	P0 3/ P	rs =	20 . RUN
P)= 8.2 ()= 10 (A	29 PSI 07.0-CH	RE PER	IN.= 3.866	.48E06 55 P.SI	CY	90. DI	EG•F ·ŘŲN NO.	PO3/P 027020 CPB	TS = 69114 CAF	RUN
P ALPH)= 8.2 (0= 10 (A	29 PSI 07.0 CH	RE PER HG PTS= ,CH	IN.= 3.866	.48E06 55 P.SI 5	CY 0.2241	90. DI CR 0.0134	EG•F -Řýn no. Cať	POJ/P 027020 CPB 0.1741	TS = 69114 CAF 0.2288	RUN 72.
ALPH 4.0)= 8.2 0= 10 1A 16 0.0	29 PSI 07.0 CM CN 4797	RE PER HG PTS= CH -4.6663	IN.= 3.866 CS -0.02 -0.02	.48E06 55 P.S.I 5 294 248	CY 0.2241 0.1807 0.1355	90. DI CR 0.0134 0.0116 0.0099	EG.F -RUN NO. CAT 0.4029 0.4006 0.3962	POJ/P* . 027020 CPB 0.1741 0.1736 0.1723	TS = 69114 CAF 0.2288 0.2270 0.2239	RUN 72. 72.
ALPH 4.0 3.0)= 8.2 0= 10 1A 16 0.0 15 0.0	29 PSI 07.0 CH CN .4797 .3488	RE PER HG PTS= ,CH -4.6663 -3.4221	IN.= 3.866 CS -0.02 -0.02 -0.02	.48E06 55 P.SI 5 294 248 203	CY 0.2241 0.1807 0.1355	90. DI CR 0.0134 0.0116 0.0099	EG.F -ŘÚN NO. CAŤ 0.4029 0.4006	POJ/P* . 027020 CPB 0.1741 0.1736 0.1723	TS = 69114 CAF 0.2288 0.2270 0.2239	RUN 72. 72. 72.
ALPH 4.0 3.0 2.0 1.5	0= 10 1A 26 0. 35 0. 31 0.	29 PSI 07.0-CH CN .4797 .3488 ;2214	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142	IN.= 3.866 -0.02 -0.02 -0.02 -0.02	.48E06 55 P.SI 5 294 248 203 198	CY 0.2241 0.1807 0.1355 0.1324 0.1127	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074	CAT 0.4029 0.4006 0.3962 0.3948 0.3912	POJ/P* . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692	TS = 69114 CAF 0.2288 0.2270 0.2239 0.2243 0.2220	RUN 72. 72. 72. 72. 72.
ALPH 4.0 3.0 2.0	0= 10 1A 26 0. 35 0. 31 0.	29 PSI 07.0 CM .4797 .3488 .2214 .1540 .0945	RE PER HG PTS= CH -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01	.48E06 55 P.SI 294 248 203 1098 179	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0065	EG.F RUN NO. CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678	TS = 69114 CAF 0.2288 0.2270 0.2239 0.2243 0.2220	RUN 72. 72. 72. 72. 72. 72. 72.
4.0 3.0 2.0 1.5	0= 10 1A 16 0 15 0 13 0 10 0 19 0	29 PSI 07.0 CM .4797 .3488 .2214 .1540 .0945	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01	.48E06 55 P.S.I 294 248 203 198 179 175 163	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0065 0.0063	CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898 0.3883	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1666	TS = 69114 CAF 0.2288 0.2270 0.2239 0.2243 0.2220 0.2220	RUN 72. 72. 72. 72. 72. 72. 72. 72.
ALPH 4.0 3.0 2.0 1.5 1.0	= 8.6 0= 16 A	29 PSI 07.0 CM .4797 .3488 .2214 .1540 .0945 .0306 .0268	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514 0.7418	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01 -0.01	.48E06 55 P.S.I 294 248 203 198 179 175 163	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002 0.1237	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0065 0.0063 0.0054	CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898 0.3883 0.3883	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1666 0.1654	CAF CAF 0.2288 0.2270 0.2239 0.2243 0.2220 0.2217 0.2195	RUN 72. 72. 72. 72. 72. 72. 72. 72. 72.
ALPH 4.0 3.0 1.5 1.5 1.0 1.5 1.5	0= 10 0= 10 14 16 0. 15 0. 10 0. 19 0. 13 -0. 15 -0.	29 PSI 07.0 CM .4797 .3488 .2214 .1540 .0945 .0306 .0268 .0913	RE PER HG PTS= CH -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514 0.7418 1.3208	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01 -0.01	.48E06 55 P.SI 294 248 203 198 179 175 163	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002 0.1237 0.1087	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0655 0.0063 0.0054	CAT 0.4029 0.4029 0.3962 0.3948 0.3898 0.3883 0.3883 0.3848	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1666 0.1654 0.1641	CAF CAF 0.2288 0.2270 0.2239 0.2243 0.2220 0.2217 0.2195 0.2205	RUN 72. 72. 72. 72. 72. 72. 72. 72. 72. 72.
4.0 3.0 2.0 1.5 1.0 7.0 -0.5 -1.0	0= 10 0= 10 14 16 0. 15 0. 13 0. 10 0. 10 0. 13 -0. 15 -0.	29 PSI 07.0 CM CN .4797 .3488 .2214 .1540 .0945 .0306 .0268 .02127	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514 0.7418 1.3208 1.8832	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01 -0.01 -0.01	-48E06 55 PSI 294 248 203 198 179 175 163 185 171	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002 0.1237 0.1087 0.1076	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0065 0.0063 0.0054 0.0054 0.0054	CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898 0.3883 0.3848 0.3847 0.3825	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1654 0.1654 0.1654	CAF CAF 0.2288 0.2279 0.2239 0.2243 0.2220 0.2217 0.2195 0.2194	RUN 72. 72. 72. 72. 72. 72. 72. 72. 72. 72.
ALPF 4.0 3.0 1.5 1.0 0.1 -0.0 -1.5 -2.0	0= 10 1A 66 0 15 0 13 0 10 0 13 0 13 0 15 0 16 0 16 0 17 0 18 0 1	29 PSI 07.0 CM CN .4797 .3488 .2214 .1540 .0945 .0306 .0288 .0913 .1528 .2127 .2715	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514 0.7418 1.3208 1.8832 2.4405	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	-48E06 55 PSI 294 248 203 198 179 163 163 167 163 197	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002 0.1237 0.1087 0.1076	90. DI CR 0.0134 0.0116 0.0099 0.0088 0.0074 0.0065 0.0065 0.0064 0.0040 0.0038 0.0033	CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898 0.3883 0.3883 0.3847 0.3825 0.3837	POJ/P . 027020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1666 0.1654 0.1631 0.1625	CAF 0.2288 0.2270 0.2239 0.2243 0.2220 0.2217 0.2195 0.2205 0.2194	RUN 72. 72. 72. 72. 72. 72. 72. 72. 72. 72.
ALPH 4.0 3.0 1.5 1.0 0.3 -0.5 -1.0 -2.0	0= 10 1A 66 0 15 0 13 0 10 0 13 0 13 0 15 0 16 0 16 0 17 0 18 0 1	29 PSI 07.0 CM CN .4797 .3488 .2214 .1540 .0945 .0306 .0268 .0913 .0913 .2127 .2115 .3975	RE PER HG PTS= CM -4.6663 -3.4221 -2.2142 -1.5744 -1.0115 -0.4089 0.1514 0.7418 1.3208 1.8832	IN.= 3.866 CS -0.02 -0.02 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	-48E06 55 PSI 294 248 203 198 179 163 185 163 197 181	CY 0.2241 0.1807 0.1355 0.1324 0.1127 0.1109 0.1002 0.1237 0.1087 0.1076 0.1372 0.1282	90. DI CR 0.0134 6.0116 0.0099 0.0088 0.0074 0.0065 0.0063 0.0054 0.0040 0.0033 0.0013	CAT 0.4029 0.4006 0.3962 0.3948 0.3912 0.3898 0.3883 0.3848 0.3847 0.3825	POJ/P O27020 CPB 0.1741 0.1736 0.1723 0.1705 0.1692 0.1678 0.1666 0.1654 0.1641 0.1631 0.1625 0.1614	CAF 0.2288 0.2270 0.2239 0.2243 0.2220 0.2217 0.2195 0.2212 0.2194	RUN 72. 72. 72. 72. 72. 72. 72. 72. 72. 72

orn in the interestive of the contractive of the contractive weathers and the contractive of the contractive

MODEL 946.2	CONFI	IG. 2.450	HA	CH 1.75	5	PHI =	15.	
Q= 8.29 PSI	RE PER I	IN.= .48E06	s 70=	90. DE	G.F	P0J/P1	[\$. =	40.
PC= 107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	02702	59115	•
ALPHA CH	СМ	CS	CY	CR	CAT	СРЗ	CAF	RUN
4.04 0.4419	-4.4297 -	-0:0466	0.3497	0.0201	0.4070	0.1752	0.2319	73.
3.02 0.3084	-3.1554 -		0.2675	0.9157	0.4053	0.1755	0.2298	73.
2.00 0.1793	-1,9293 -	-0.0351	0.2358	0.0131	0.4003	0.1748	0.2255	
1.48 0.1084	-1.2589 -	-0.0341			0.3990			
0.98 0.0476	-0.6863 -				0.3968			
0.46 -0.0125	-0.1216 -	-0.0289			0.3933			
-0.05 -0.0769	0.4875 -				0.3919			
-0.55 -0.1408	1.0915 -				0.3905			
-1.07 -0.1968	1.6114				0.3876			
-1.58 -0.2576	2-1821 -				0.3861			
-2.08 -0.3157	2.7288	-0.0316			0.3853			
-3.11 -0.4398	3.8914	-0.0345			0.3831			
-4.13 -0.5657	5.0688 -	-0.0360	J.2736-	-0.0045	0.3850	0.1642	0.2208	73.
MODEL 946.2 C= 8.29 PSI		IG. 2.450 IN.= .48E06		NCH 1.75		PHI =	15. rs =	80.
HODEL 946.2 Q= 8.29 PSI PO= 107.0 CF	RE PER	IN.= .48E06			G.F	_	rs ≂	89.
Q= 8.29 PSI	RE PER	IN.= .48E06			G.F	P0J/P	rs ≂	89 . RUN
Q= 8.29 PSI PO= 107.0 CF ALPHA CN	RE PER : HHG PTS= : ĈM	IN.= .48E06 3.8665 PSI CS	5 TO=	90. DE	EG.F RUN NO. CAT	POJ/P ² 027020 CPB	rs = 69116 CAF	RUN
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495	RE PER : HHG PTS= : ĈH -3.7937 -	IN.= .48E06 3.8665 PSI CS ~0.0852	CY 0.6332	90. DE CR 0.0289	EG.F RUN NO	POJ/P 027020 CPB G.1775	TS = 69116 CAF 0.2376	RUN 5 74.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495 2.97 0.2103	RE PER : GH -3.7937 : -2.4686 :	IN.= .48E00 3.8665 PSI CS ~0.0852 ~0.0708	CY 0.6332 0.5001	90. DE CR 0.0289 0.0216	EG.F RUN NO. CAT 0.4151	POJ/P 027020 CPB G.1775 0.1771	TS = 59116 CAF 0.2376	RUN 74.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763	RE PER : HHG PTS= : ĈH -3.7937 -	IN.= .48E00 3.8665 PSI CS ~0.0852 ~0.0708 -0.0627	CY 0.6332 0.5001 0.4228	90. DE CR 0.0289 0.0216 0.0172	EG.F RUN NO. CAT 0.4151 0.4140	POJ/P° . 027020 . CPB . 0.1775 0.1771 0.1773	TS = 69116 CAF 0.2376 0.2369 0.2331	RUN 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083	RE PER 1 GH PTS= 1 CH -3.7937 -2.4686 -1.1936	IN.= .48E00 3.8665 PSI CS -0.0852 -0.0708 -0.0627 -0.0598	CY 0.6332 0.5001 0.4228 0.3980	90. DE CR 0.0289 0.0216 0.0172 0.0138	EG.F RUN NO. CAT 0.4151 0.4140 0.4104	POJ/P' . 027020 . CPB . 0.1775 0.1771 0.1773 0.1748	TS = 69116 CAF 0.2376 0.2369 0.2331 0.2329	RUN 74. 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763	RE PER 1 GH -3.7937 -2.4686 -1.1936 -0.5532 0.0681	CS -0.0852 -0.0627 -0.0598 -0.0584	CY 0.6332 0.5001 0.4228 0.3980 0.3857	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112	CAT 0.4151 0.4140 0.4104 0.4077	POJ/P° . 027020 CPB G.1775 0.1771 0.1773 0.1748 0.1735	CAF 0.2376 0.2369 0.2331 0.2329 0.2328	RUN 74. 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573	RE PER 1 GH -3.7937 -2.4686 -1.1936 -0.5532	CS -0.0852 -0.0627 -0.0598 -0.0584 -0.0583	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078	CAT 0.4151 0.4150 0.4160 0.4077 0.4063 0.4042 0.4013	POJ/P° . 027020 CPB G.1775 O.1771 O.1773 O.1748 O.1735 O.1720 O.1707	CAF 0.2376 0.236 0.2331 0.2329 0.2328 0.2328	RUN 74. 74. 74. 74. 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573 0.41 -0.1211	RE PER : OH -3.7937 -2.4686 -1.1936 -0.5532 0.0681 0.6653	CS -0.0852 -0.0708 -0.0627 -0.0598 -0.0584 -0.0583	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755 0.3905	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078 0.0061	CAT 0.4151 0.4150 0.4164 0.4077 0.4063 0.4042 0.4013 0.3992	POJ/P° . 027020 CPB G.1775 0.1771 0.1773 0.1748 0.1735 0.1720 0.1707 0.1692	CAF 0.2376 0.2376 0.2331 0.2329 0.2328 0.2328 0.2328	RUN 74. 74. 74. 74. 74. 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573 0.41 -0.1211 -0.17 -0.1794	RE PER 1 CH -3.7937 -2.4686 -1.1936 -0.5532 0.6653 1.2111 1.7849 2.3343	IN.= .48E06 3.8665 PSI CS -0.0852 -0.0708 -0.0627 -0.0598 -0.0584 -0.0583 -0.0563 -0.0574 -0.0575	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755 0.3905 0.3951	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078 0.0061 0.0042	CAT 0.4151 0.4150 0.4160 0.4077 0.4063 0.4042 0.4013 0.3992 0.3978	POJ/P° . 027020 CPB G.1775 0.1771 0.1773 0.1748 0.1735 0.1720 0.1707 0.1692 0.1674	CAF 0.2376 0.2376 0.2331 0.2329 0.2328 0.2328 0.2320 0.2306	RUN 74. 74. 74. 74. 74. 74. 74. 74. 74. 74.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573 0.41 -0.1211 -0.11 -0.1794 -0.62 -0.2408 +1.13 -0.2999 -1.63 -0.3586	RE PER 1 CM -3.7937 -2.4686 -1.1936 -0.5532 0.0681 0.6653 1.2111 1.7849 2.3343 2.8801	CS -0.0852 -0.0708 -0.0627 -0.0598 -0.0584 -0.0583 -0.0563 -0.0574 -0.0575 -0.0586	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755 0.3951 0.4075	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078 0.0061 0.0042 0.0025	CAT 0.4151 0.4150 0.4040 0.4077 0.4063 0.4042 0.4013 0.3992 0.3978 0.3943	POJ/P ² . 027020 . CPB G.1775 0.1771 0.1773 0.1748 0.1730 0.1720 0.1707 0.1692 0.1674 0.1660	CAF 0.2376 0.2376 0.2331 0.2329 0.2328 0.2328 0.2328	RUN 74. 74. 74. 74. 74. 74. 74. 74. 74. 74.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573 0.41 -0.1211 -0.11 -0.1211 -0.62 -0.2408 -1.13 -0.2999 -1.63 -0.3586 -2.14 -0.4152	RE PER 1 CH -3.7937 -2.4686 -1.1936 -0.5532 0.0681 0.6653 1.2111 1.7849 2.3343 2.8801 3.4087	IN.= .48E00 3.8665 PSI CS -0.0852 -0.0708 -0.0627 -0.0598 -0.0584 -0.0583 -0.0563 -0.0574 -0.0575 -0.0586 -0.0586	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755 0.3951 0.4075 0.4267	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078 0.0061 0.0042 0.0025 0.0015	CAT 0.4151 0.4140 0.4104 0.4077 0.4063 0.4042 0.4013 0.3992 0.3943 0.3921	POJ/P° 027020 CPB G.1775 0.1771 0.1773 0.1748 0.1735 0.1720 0.1707 0.1692 0.1674 0.1660 0.1645	CAF 0.2376 0.2369 0.2328 0.2328 0.2328 0.2304 0.2283 0.2276	RUN 74. 74. 74. 74. 74. 74. 74. 74. 74. 74.
Q= 8.29 PSI P0= 107.0 CP ALPHA CN 3.98 0.3495 2.97 0.2103 1.95 0.0763 1.43 0.0083 0.91 -0.0573 0.41 -0.1211 -0.11 -0.1794 -0.62 -0.2408 +1.13 -0.2999 -1.63 -0.3586	RE PER 1 CM -3.7937 -2.4686 -1.1936 -0.5532 0.0681 0.6653 1.2111 1.7849 2.3343 2.8801	CS -0.0852 -0.0708 -0.0627 -0.0598 -0.0584 -0.0583 -0.0563 -0.0575 -0.0586 -0.0586	CY 0.6332 0.5001 0.4228 0.3980 0.3857 0.3922 0.3755 0.3951 0.4075 0.4267 0.4623	90. DE CR 0.0289 0.0216 0.0172 0.0138 0.0112 0.0089 0.0078 0.0061 0.0062 0.0025 0.0015	CAT 0.4151 0.4150 0.4040 0.4077 0.4063 0.4042 0.4013 0.3992 0.3978 0.3943	POJ/P O27020 CPB G.1775 0.1771 0.1773 0.1748 0.1735 0.1720 0.1670 0.1692 0.1674 0.1660 0.1645 0.1618	CAF 0.2376 0.2369 0.2331 0.2328 0.2328 0.2306 0.2306 0.2308 0.2283 0.2276	RUN 74. 74. 74. 74. 74. 74. 74. 74. 74. 74.

•••	DEL 946.2	CONF	FIG. 2.450	M	ACH 1.75	PHI =	30.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 70=	90. DEG.F	POJ/PT	s = .	
PC	= 107.0 CM	HG PTS=	3.8665 PSI		RUN NO	. 027026	9117	
ALPHA	CN	CM	cs	CY	CR CAT	CP8	CAF	RUN
4.06	0.5077	-4.8133	-0.0205	0.1771	0.0064 0.3906	0.1655	0.2251	75.
3.06		-3.5749	-0.0202		0.0061 0.3897			75.
	0.2491		-0.0177		0.0050 0.3860			75.
	0.1797	-1.6999	-0.0187		0.0057 0.3863			75.
	0.1205	-1.1398	-0.0188	0.1511	0.0042:0.3865	0.1639	0.2226	75.
0.50	0.0592	-0.5581	-0.0193	0.1525	0.0047 0.3866	0.1641	0.2225	75.
	-C.0010	0.0094	-0.0126	0.0950	0.0056 0.3840	0.1641	0.2199	75.
	-0.0598		-0.0133		0.0050 0.3828			75.
-1.04	-0.1270	1.2027	-0.0180	0.1473	0.0043 0.3818	0.1629	0.2189	75.
-1.55	-0.1842	1.7419	-0.0177		0.0051 0.3799			75.
	-0.2464	2.3323	-0.0151		0.0055 0.3767			75.
	-0.3759		-0.0147		0.0052 0.3731			75.
	-0.5084		-0.0105		0.0041 0.3721			75.
MO								
	DEL 946.2	CONF	IG. 2.450	M	ACH 1.75	PHI =	30.	
Q=	8.29 PSI		IG. 2.450 IN.= .48E0			= IHQ TQ\LOG		
	8.29 PSI	RE PER		6 T0=	90. DEG.F	· -	S = 10.	
	8.29 PSI = 107.0 CM	RE PER	IN.= .48E0	6 T0=	90. DEG.F	POJ/PT	S = 10.	- RUN
PO ALPHA	8.29 PSI = 107.0 CM	RE PER HG PTS=	IN.= .48E0 3.8665 PSI CS	6 T0=	90. DEG.F RUN NO CR CAT	POJ/PT • 027026 CPB	S = 10. 9118 CAF	RUN
P0 ALPHA 4.06	8.29 PSI = 107.0 CM CN 0.5004	RE PER HG PTS= :CM -4.8022	IN.= .48E0 3.8665 PSI CS -0.0306	6 TO= CY 0.2304	90. DEG.F RUN NO CR CAT 0.0133 0.3969	POJ/PT • 027026 CPB 0.1686	S = 10. 9118 CAF 0.2282	RUN 76.
PO ALPHA 4.06 3.05	8.29 PSI = 107.0 CM CN 0.5004 0.3706	RE PER HG PTS= :CM -4.8022 -3.5631	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285	6 TO= CY 0.2304 0.2053	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905	POJ/PT . 027026 CPB 0.1686 0.1677	S = 10. 9118 CAF 0.2282 0.2227	RUN 76. 76.
4.06 3.05 2.03	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223	6 TO= CY 0.2304 0.2053 0.1497	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895	POJ/PT - 027026 CPB 0.1686 0.1677 0.1659	S = 10. 9118 CAF 0.2282. 0.2227 0.2235	RUN 76. 75. 76.
PO ALPHA 4.06 3.05 2.03 1.51	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400 0.1705	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276 -1.6695	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217	CY 0.2304 0.2053 0.1497 0.1457	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895 0.0079 0.3878	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223	RUN 76. 76. 76. 76.
4.06 3.05 2.03 1.51	= 107.0 CM CN 0.5004 0.3706 0.2400 0.1705 0.1089	RE PER HG PTS=	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204	CY 0.2304 0.2053 0.1497 0.1457 0.1370	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895 0.0079 0.3878 -0.0063 0.3872	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223	RUN 76. 76. 76. 76.
4.06 3.05 2.03 1.51 1.00	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400 0.1705	RE PER HG PTS= -4.8022 -3.5631 -2.3276 -1.6695 -1.0847 -0.5024	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204 -0.0209	CY 0.2304 0.2053 0.1497 0.1457 0.1370 0.1432	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895 0.0079 0.3878 0.0063 0.3872 0.0059 0.3854	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649 0.1649	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223 0.2223	RUN 76. 75. 76. 76. 76.
4.06 3.05 2.03 1.51 1.00 0.49	= 107.0 CM CN 0.5004 0.3706 0.2400 0.1705 0.1089 0.0476	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276 -1.6695 -1.0847 -0.5024 0.0832	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204	CY 0.2304 0.2053 0.1497 0.1457 0.1370 0.1432 0.1367	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3969 0.0069 0.3895 0.0079 0.3878 0.0063 0.3872 0.0059 0.3854 0.0047 0.3835	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649 0.1643 0.1637	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223 0.2223 0.2211 0.2198	RUN 76. 75. 76. 76. 76. 76.
PO ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03	= 107.0 CM CN CN 0.5004 0.3706 0.2400 0.1705 0.1089 0.0476 -0.0144	RE PER HG PTS= -4.8022 -3.5631 -2.3276 -1.6695 -1.0847 -0.5024 0.0832 0.6295	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204 -0.0209 -0.0201	6 T0= CY 0.2304 0.2053 0.1497 0.1457 0.1432 0.1367 0.1178	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895 0.0079 0.3878 0.0063 0.3872 0.0059 0.3854 0.0047 0.3835 0.0049 0.3823	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649 0.1643 0.1637 0.1631	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223 0.2223 0.2211 0.2198 0.2193	RUN 76. 76. 76. 76. 76. 76.
PO ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.54	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400 0.1705 0.1089 0.0476 6-0.0144 -0.0727 -0.1344	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276 -1.6695 -1.0847 -0.5024 0.0832 0.6295 1.2132	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204 -0.0209 -0.0201 -0.0180 -0.0204	6 T0= CY 0.2304 0.2053 0.1497 0.1457 0.1457 0.1432 0.1367 0.1178 0.1420	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3878 0.0079 0.3878 0.0059 0.3874 0.0059 0.3854 0.0047 0.3835 0.0049 0.3823 0.0030 0.3805	POJ/PT . 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649 0.1643 0.1637 0.1631 0.1623	S = 10. 9118 CAF 0.2282 0.2227 0.2235 0.2223 0.2223 0.2211 0.2198 0.2193 0.2182	RUN 76. 76. 76. 76. 76. 76. 76.
4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.54 -1.05	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400 0.1705 0.1089 0.0476 6-0.0144 -0.0727 -0.1344	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276 -1.6695 -1.0695 -0.5024 0.0832 0.6295 1.2132 1.8111	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204 -0.0209 -0.0201 -0.0180 -0.0204	CY 0.2304 0.2053 0.1497 0.1457 0.1370 0.1432 0.1367 0.1178 0.1470	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3895 0.0079 0.3878 0.0063 0.3872 0.0059 0.3854 0.0047 0.3835 0.0049 0.3825 0.0030 0.3825 0.0030 0.3825	POJ/PT - 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1649 0.1643 0.1637 0.1631 0.1623 0.1614	S = 10. 9118 CAF 0.2282. 0.2227 0.2235 0.2223 0.2221 0.2198 0.2193. 0.2182 0.2182	RUN 76. 76. 76. 76. 76. 76. 76. 76.
4.06 3.05 2.03 1.51 1.00 0.49 -0.54 -1.05 -1.56	8.29 PSI = 107.0 CM CN 0.5004 0.3706 0.2400 0.1705 0.1089 0.0476 -0.0144 -0.0727 -0.1344 -0.1975	RE PER HG PTS= CM -4.8022 -3.5631 -2.3276 -1.6695 -1.0847 -0.5024 0.0832 0.6295 1.2132 1.8111 2.3580	IN.= .48E0 3.8665 PSI CS -0.0306 -0.0285 -0.0223 -0.0217 -0.0204 -0.0209 -0.0201 -0.0180 -0.0204 -0.0203	CY 0.2304 0.2053 0.1497 0.1457 0.1370 0.1432 0.1367 0.1178 0.1470 0.1407 0.1515	90. DEG.F RUN NO CR CAT 0.0133 0.3969 0.0113 0.3905 0.0089 0.3878 0.0079 0.3878 0.0059 0.3874 0.0059 0.3854 0.0047 0.3835 0.0049 0.3823 0.0030 0.3805	POJ/PT - 027026 CPB 0.1686 0.1677 0.1659 0.1654 0.1643 0.1643 0.1637 0.1631 0.1623 0.1614 0.1610	S = 10. 9118 CAF 0.2282. 0.2227 0.2235 0.2223 0.2221 0.2198 0.2198 0.2182 0.2182 0.2180 0.2172	RUN 76. 76. 76. 76. 76. 76. 76.

MODEL 946.2	CONF	IG. 2.450	MACH 1	.75	PHI =	30.	
Q= 8.29 PS1	RE PER	IN.= .48E0	6 TO≃ 90.	DEG.F	79\L09	S = 20.	
20= 107.0 CF	HG PTS=	3.8665 PSI		RUN INO	. 027026	9119	
ALPHA CN	CH	cs	CY CF	CAT	CPB	CAF	RUN
4.05 0.4885	-4.7431	-0.0432	0.3122 0.01	92 0.4006	0.1733	0-2273	77.
3.04 0.3517	÷3.4373		0.2654 0.01				77.
2.01 0.2252	-2.2387		0.2035 0.01				77.
1.49 0.1570	-1.5906		0.2186 0.00				77.
0.99 0.0941	-0.9977		0-1882 0-00				77.
0.47 0.0328	-0.4199		0.1709 0.00				77.
-0.04 -0.0292		-0.0292	0.1905 0.00				77.
-0.55 -0.0876		-0.0308	0.2100 0.00				77.
-1.06 -0.1496		-0.0288	0.1913 0.00				77•
-1.57 -0.2098		-0.0298	0.2039 0.00				77. 77.
-2.08 -0.2739		-0.0319	0.2275-0.00				
-3.09 -0.3956 -4.11 -0.5185		-0.0330 -0.0311	0.2426-0.00				77. 77.
-4.11 -0.5165	4.1307	-0.0311	0.2312-0.00	180 0.3113	0+1011	0.2134	11.
MODEL 946.2 Q≐ 8.29 PSI		F1G. 2.450 IN.= .48EÔ		-	PHI =	30. 'S = 40.	
	RE PER	IN.= .48EÔ	6 TO= 90.	DEG.F		'S = 40•	
Q= 8.29 PSI	RE PER	IN.= .48EÔ	6 TO= 90.	DEG.F	POJ/PT	'S = 40•	RUN
Q= 8.29 PSI PO= 107.0 CP	RE PER HHG PTS=	IN.= .48EÔ 3.8665 PSI CS	6 TO= 90.	DEG.F RUN NO	POJ/PT • 027026 CPB	S = 40. 9120 CAF	
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.03 0.4605	RE PER HHG PTS= CM -4.5808	IN.= .48EÔ 3.8665 PSI CS -0.0727	6 TO= 90.	DEG.F RUN NO CAT	POJ/PT - 027026 CPB 0-1758	S = 40. 9120 CAF 0.2309	18 -
Q= 8.29 PSI PO= 107.0 CP	RE PER HHG PTS= CM -4.5808 -3.2251	IN.= .48EÔ 3.8665 PSI CS -0.0727	6 TO= 90.	DEG.F RUN NO CAT 266 0.4067	POJ/PT - 027026 CPB 0.1758 0.1751	S = 40. 9120 CAF 0.2309 0.2279	
Q= 8.29 PSI PO= 107.0 CR ALPHA CN 4.03 0.4605 3.02 0.3187	RE PER HHG PTS= CM -4.5808 -3.2251	IN.= .48EÔ 3.8665 PSI CS -0.0727 -0.0646 -0.0563	6 TO= 90. CY CF 0.5192 0.02	DEG-F RUN NO CAT 266 0-4067 199 0-4030	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743	S = 40. 9120 CAF 0.2309 0.2279 0.2263	/8 • 78 •
Q= 8.29 PST PO= 107.0 CF ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860	RE PER HHG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369	IN.= .48EÔ 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567	6 TO= 90. CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01	PDEG-F RUN NO CAT 266 0-4067 199 0-4030 146 0-4006	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1732	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270	/8. 78. 78.
Q= 8.29 PST PO= 107.0 CP ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192	RE PER 4HG PTS= CM -4.5808 -3.2251 -1.9691	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548	6 TO= 90. CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01	DEG.F RUN NO CAT 266 0.4067 199 0.4030 146 0.4006 113 0.4002	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1732 0.1719	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270 0.2239	/8. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CP ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543	RE PER HG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.01	PDEG+F RUN NO CAT 266 0-4067 199 0-4030 146 0-4006 113 0-4002 106 0-3957 076 0-3939	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1732 0.1719 0.1705	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234	/8. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CP ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543 0.45 -0.0083	RE PER HG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381 0.4297	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548 -0.0518	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.02 0.3361 0.00	PEG+F RUN NO CAT 266 0.4067 199 0.4030 146 0.4006 113 0.4002 106 0.3957 076 0.3939	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1743 0.1719 0.1705 0.1690	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234 9.2218	/8. 78. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CP ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543 0.45 -0.0083 -0.07 -0.0687	RE PER HG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381 0.4297 1.0368	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548 -0.0518 -0.0538	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.01 0.3351 0.00 0.3556 0.00	RUN NO CAT CAT CAC CAC CAC CAC CAC CAC CAC CAC	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1743 0.1719 0.1705 0.1690 0.1672	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234 9.2218 0.2225	/8. 78. 78. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CF ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543 0.45 -0.0083 -0.07 -0.0687 -0.58 -0.1332	RE PER HG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381 0.4297 1.0368 1.6136	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548 -0.0518 -0.0538 -0.0577	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.01 0.3556 0.00 0.3974 0.00	RUN NO CAT	POJ/PT . 027026 CPB 0.1758 0.1751 0.1743 0.1732 0.1719 0.1705 0.1690 0.1672 0.1659	CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234 9.2218 0.2225 0.2215	/8. 78. 78. 78. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CF ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543 0.45 -0.0083 -0.07 -0.0687 -0.58 -0.1332 -1.08 -0.1947	RE PER HG PTS= CM -4.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381 0.4297 1.0368 1.6136 2.1733	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548 -0.0518 -0.0538 -0.0577 -0.0618	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.02 0.3550 0.00 0.3974 0.00 0.4394 0.00 0.4224-0.00 0.4165-0.00	RUN NO CAT 266 0.4067 199 0.4030 146 0.4006 113 0.4002 106 0.3957 076 0.3939 064 0.3908 019 0.3874 003 0.3856 015 0.3823	POJ/PT - 027026 CPB 0.1758 0.1751 0.1743 0.1732 0.1719 0.1690 0.1672 0.1659 0.1645 0.1635	S = 40. 9120 CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234 9.2218 0.2225 0.215 0.2188	/8. 78. 78. 78. 78. 78. 78. 78.
Q= 8.29 PST PO= 107.0 CF ALPHA CN 4.03 0.4605 3.02 0.3187 1.99 0.1860 1.47 0.1192 0.95 0.0543 0.45 -0.0083 -0.07 -0.0687 -0.58 -0.1332 -1.08 -0.1947 -1.59 -0.2548	RE PER 44.5808 -3.2251 -1.9691 -1.3369 -0.7241 -0.1381 0.4297 1.0368 1.6136 2.1733 2.6673 3.8011	IN.= .48E0 3.8665 PSI CS -0.0727 -0.0646 -0.0563 -0.0567 -0.0548 -0.0518 -0.0538 -0.0577 -0.0618 -0.0591	CY CF 0.5192 0.02 0.4438 0.01 0.3681 0.01 0.3747 0.01 0.3550 0.02 0.3556 0.02 0.3974 0.02 0.4394 0.02 0.4224-0.03	RUN NO CAT C66 0.4067 199 0.4030 146 0.4006 113 0.4002 106 0.3957 076 0.3938 040 0.3856 019 0.3856 015 0.3823	POJ/PT - 027026 CPB 0.1758 0.1751 0.1743 0.1732 0.1719 0.1690 0.1672 0.1659 0.1645 0.1635 0.1624	CAF 0.2309 0.2279 0.2263 0.2270 0.2239 0.2234 9.2218 0.2225 0.2215 0.2215 0.2188 0.2184	/8. 78. 78. 78. 78. 78. 78. 78.

HCD	EL 946.2	CONI	IG. 2.450	- N	ACH 1.75	5	PHI =	30.	
Q×	8.29 PSI	RE PER	IN.≈ .48E0	6 TO=	90. Di	G.F	POJ/F	rs =	80.
- PD=	107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	. 02702	69121	
ALPHA	CN	CH	cs	CY	CR	CAT	C P B	CAF	RUN
3.98	0.3809	-4.0406	-0-1397	1.0123	0.0358	0.4175	0.1799	G-2376	79.
2.97	0.2372	-2.6674	-0.1234	0.8592	0.6770	0.4137	0.1772	0.2365	79.
1.95	0.0947	-1.3138	-0.1114	0.7512	0.0159	0.4120	0.1766	0.2354	79.
1.42	0.0275	-0.6790	-0.1084			0.4089			
0.92	-0.0362	-0.0798	-0.1037	0.6858	0.G127	0.4056	0.1734	0.2322	79.
0.40	-0.1026	0.5439	-0.1071	0.7248	0.0094	0.4033	0.1719	0.2315	79.
-0.12	~0.1643	1.1138	-0.1031			0.4016			
-0.62	-0.2248		-0.1088			0.3992			
	-0.2835		-0.1096			0:3961			
-1.65	-0.3461	2.8034				0.3951			
	-0.3962		-0.1119			0.3919			
	-0.5096	4.3020	-0.1170			0.3885			
-4.19	-0.6197	5,2906	-0.1215	0.9348	-0-0293	0.3878	0.1604	0.2274	79.
	EL 946.2		FIG. 2.450		ACH 1.75		= IH9		
	EL 946.2 8.29 PSI		FIG. 2.450 IÑ.= .48E0		4CH 1.75		PHI =		•
Q=	8.29 PSI	RE PER		6 TO=		EG.F	•	TS =	•
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=		EG.F	POJ/P	TS =	• Run
Q= PO= ALPHA	8.29 PSI 107.0 CŘ	RE PER HG PTS=	IN.= .48E0 3.8665 PSI	6 TO=	90. DI	EG.F RUN NO	POJ/P 027026 CPB	TS = 69122 CAF	• RUN 80•
Q= PO= ALPHA 4.06	8.29 PSI 107.0 CÁ	RE PER HG PTS= CM -4.8806	IN.= .48E0 3.8665 PSI CS	6 TO= CY 0.2078	90. DI CR 0.0071	EG.F RUN NO. CAT 0.3927	POJ/P 027026 CP8 0.1546	TS = 69122 CAF 0.2281	80.
Q= PO= ALPHA 4.06 3.05	8.29 PSI 107.0 CÁ CN 0.5141	RE PER HG PTS= CM -4.8806	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228	6 TO= CY 0.2078 0.1904	90. DI CR 0.0071 0.0060	EG.F RUN NO.	POJ/P . 027026 CP8 0.1546 0.1536	TS = 69122 CAF 0.2281 0.2245	80.
Q= PO= ALPHA 4.06 3.05	8.29 PSI 107.0 CÁ CN 0.5141 0.3810	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228	6 T0= CY 0.2078 0.1904 0.2176	90. DI CR 0.0071 0.0060 0.0055	EG.F RUN NO. CAT 0.3927 0.3882	POJ/P . 027020 CP8 0.1546 0.1536 0.1629	TS = 69122 CAF 0.2281 0.2245 0.2236	80. 80. 80.
Q= PO= ALPHA 4.06 3.05 2.03 1.51	8.29 PSI 107.0 CH CN 0.5141 0.3810 0.2497	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0223 -0.0254	6 T0= CY 0.2078 0.1904 0.2176 0.1558	90. DI CR 0.0071 0.0060 0.0055 0.0067	EG.F RUN NO. CAT 0.3927 0.3882 0.3865	POJ/P . 027020 CP8 0.1546 0.1536 0.1629 0.1628	TS = 69122 CAF 0.2281 0.2245 0.2236	80. 80. 80.
Q= PO= ALPHA 4.06 3.05 2.03 1.51	8.29 PSI 107.0 CR CN 0.5141 0.3810 0.2497 0.1875	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0223 -0.0254 -0.0125	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368	90. DI CR 0.0071 0.0060 0.0055 0.0057 0.0056	CAT 0.3927 0.3882 0.3865 0.3862 0.3867 0.3848	POJ/P . 027020 CP8 0.1546 0.1636 0.1629 0.1628 0.1631 0.1637	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2234 0.2236 0.2231	86. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03	8.29 PSI 107.0 CR CN 0.5141 0.3810 0.2497 0.1875 0.1244 0.0477	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604	90. DI CR 0.0071 0.0069 0.0055 0.0056 0.0056	CAT 0.3927 0.3882 0.3865 0.3862 0.3867 0.3848 0.3835	POJ/P . 027020 CP8 0.1546 0.1636 0.1629 0.1631 0.1637 0.1636	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2234 0.2236 0.2211 0.2199	80. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03 -0.54	8.29 PSI 107.0 CA CN 0.5141 0.3810 0.2497 0.1875 0.1244 0.0477 -0.	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020 0.6458	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193 -0.0206	6 T0= CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604 0.1764	90. DI CR 0.0071 0.0060 0.0055 0.0056 0.0056 0.0056	CAT 0.3927 0.3927 0.3882 0.3862 0.3867 0.3848 0.3835 0.3827	POJ/P . 027020 CP8 0.1546 0.1636 0.1629 0.1631 0.1637 0.1636 0.1631	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2234 0.2236 0.2211 0.2199 0.2195	80. 80. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03 -0.54 -1.05	8.29 PSI 107.0 CM CN 0.5141 0.3810 0.2497 0.1244 0.0477 -0. -0.0679 -0.1253	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020 0.6458 1.1870	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0223 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193 -0.0206 -0.0149	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604 0.1764 0.1198	90. DI CR 0.0071 0.0060 0.0055 0.0056 0.0056 0.0056 0.0057 0.0057	CAT 0.3927 0.3882 0.3865 0.3862 0.3868 0.3888 0.38835 0.3827	POJ/P . 027020 CP8 0.1546 0.1636 0.1629 0.1638 0.1637 0.1636 0.1631 0.1617	TS = 69122 CAF 0.2281 0.2236 0.2236 0.2234 0.2234 0.2211 0.2199 0.2195 0.2185	80. 80. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03 -0.54 -1.05 -1.56	8.29 PSI 107.0 CR CN 0.5141 0.3810 0.2497 0.1875 0.1244 0.0477 -0. -0.0679 -0.1253 -0.1906	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020 0.6458 1.1870 1.8044	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193 -0.0206 -0.0149 -0.0141	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604 0.1764 0.1198 0.1144	90. DI CR 0.0071 0.0060 0.0055 0.0067 0.0056 0.0057 0.0057	CAT 0.3927 0.3882 0.3865 0.3867 0.3848 0.3835 0.3827 0.3803 0.3781	PDJ/P . 027026 CPB 0.1646 0.1636 0.1629 0.1628 0.1631 0.1637 0.1636 0.1631 0.1617 0.1606	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2236 0.2219 0.2195 0.2195 0.2175	80. 80. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03 -0.54 -1.56 -1.56 -2.06	8.29 PSI 107.0 CH CN 0.5141 0.3810 0.2497 0.1875 0.1244 0.0477 -0.0679 -0.1253 -0.1906 -0.2507	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020 0.6458 1.1870 1.8044 2.3745	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0223 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193 -0.0206 -0.0149 -0.0141	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604 0.1764 0.1764 0.1198 0.1144 0.0999	90. DI CR 0.0071 0.0060 0.0055 0.0067 0.0056 0.0056 0.0057 0.0055 0.0055	CAT 0.3927 0.3882 0.3865 0.3867 0.3848 0.3835 0.3837 0.3781 0.3737	PDJ/P 02702 CPB 0.1546 0.1636 0.1629 0.1628 0.1631 0.1637 0.1636 0.1631 0.1617 0.1606 0.1586	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2234 0.2219 0.2195 0.2195 0.2175	80. 80. 80. 80. 80. 80. 80.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.48 -0.03 -0.54 -1.56 -2.06 -3.08	8.29 PSI 107.0 CR CN 0.5141 0.3810 0.2497 0.1875 0.1244 0.0477 -0. -0.0679 -0.1253 -0.1906	RE PER HG PTS= CM -4.8806 -3.6088 -2.3618 -1.7752 -1.1778 -0.4572 0.0020 0.6458 1.1870 1.8044 2.3745 3.5537	IN.= .48E0 3.8665 PSI CS -0.0247 -0.0228 -0.0254 -0.0175 -0.0210 -0.0285 -0.0193 -0.0206 -0.0149 -0.0141	CY 0.2078 0.1904 0.2176 0.1558 0.1696 0.2368 0.1604 0.1764 0.1198 0.1144 0.0999 0.0579	90. DI CR 0.0071 0.0060 0.0055 0.0056 0.0056 0.0057 0.0055 0.0055 0.0055	CAT 0.3927 0.3882 0.3865 0.3867 0.3848 0.3835 0.3827 0.3803 0.3781	PDJ/P 02702 CPB 0.1546 0.1636 0.1629 0.1628 0.1631 0.1637 0.1636 0.1631 0.1636 0.1558	TS = 69122 CAF 0.2281 0.2245 0.2236 0.2236 0.2211 0.2199 0.2195 0.2175 0.2175	80. 80. 30. 80. 80. 80. 80.

The state of the s

MODEL 945.2	CONF	IG. 2-450	MA	ICH 1.75	i	PHI =	45.	
G= 2.29 PSI	RE PER	IN.= .48E06	T0=	90. DE	GEF	203/21	rs =	10.
PO= 107.0 C	HG PTS=	3.8665 PSI			RUN NO.	02702	59123	
ALPHA CN	CH	CS	CY	CR	CAT	CP8	CAF	RUN
4.05 0.5078	-4.3550			0.0131				
3.04 0.3688	-3.5340			0.0143				
2.02 0.2412	-2.3225			0.0109				
1.50 0.1758	-1.7066			0.0094				
0.99 0.1141	-1.1198			0.0080				
0.48 0.0491	-0.5054			0.0075 0.0064				
-0.04 -0.0128		-0.0228 -0.0217		0.0050				
-0.55 -0.0739 -1.05 -0.1353		-0.0217		0.0042				
-1.57 -0.1964	1.8057			0.0072				
-2.07 -0.2553		-0.9200		0.0017				
-3.09 -0.3801		-0.0134		0.0003				
-4.11 -0.5111		-0.0116		0.0001				
MODEL 946.2	CONF	IG. 2.450	M	ACH 1.75	j	PHI =	45.	
MODEL 946.2 Q= 8.29 PSI		IG. 2.450 IN.= .48EG		ACH 1.75		PHI =		20.
	RE PER	IN.= .48EG	s To=	90. DE	G.F	-2-	rs =	20.
Q= 8.29 PSI	RE PER	IN.= .48EG	s To=	90. DE	G.F	POJ/P	rs =	20 . RUN
Q= 8.29 PSI PO= 107.0 CI ALPHA ÇN	RE PER. MHG FTS=	IN.= .48EGS 3.8665 PSI CS	5 TO=	90. DE	G.F RUN NO: CAT	POJ/P 027020 CPB	TS = 69124 CAF	RUN
Q= 8.29 PSI PO= 107.0 C	RE PER	IN.= .48EGS 3.8665 PSI CS -0.0407	CY 0.2352	90. DE	G.F RUN NO: CAT 0.3983	POJ/P 027020 CPB	TS = 69124 CAF 0.2273	RUN 3 82.
Q= 8.29 PSI PO= 107.0 CI ALPHA ÇN 4.05 0.4996	RE PER. MHG FTS= CM -4.8182	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424	CY 0.2352 0.2614	90. DE CR 0.0268	G.F RUN NO: CAT 0.3983 0.3953	POJ/P 027020 CPB 0.1710 0.1693	TS = 69124 CAF 0.2273	RUN 8 82.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608	RE PER. MHG FTS= CM -4.8182 -3.4981	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370	CY 0.2352 0.2614 0.2191	90. DE CR 0.0268 0.0202	CAT 0.3983 0.3953 0.3933	POJ/P 027020 CPB 0.1710 0.1693 0.1691	TS = 69124 CAF 0.2273 0.2259 0.2242	RUN 8 82 • 82 • 82 •
Q= 8.29 PSI PO= 107.0 CI ALPHA	RE PER MHG PTS= CM -4.8182 -3.4981 -2.2829	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388	CY 0.2352 0.2614 0.2191 0.2412	90. DE CR 0.0268 0.0202 0.0145	CAT 0.3983 0.3953 0.3953 0.3919	POJ/P . 027020 CPB 0.1710 0.1693 0.1691 0.1686	TS = 69124 CAF 0.2273 0.2256 0.2242 0.2232	RUN 8 82 • 82 • 82 • 82 • 82 •
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608. 2.01 0.2326 1.49 0.1632	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9911 -0.4375	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077	CAT 0.3983 0.3983 0.3953 0.3919 0.3904 0.3895	POJ/P . 027020 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672	TS = 69124 CAF 0.2273 0.2256 0.2242 0.2232 0.2222	RUN 8 82 82 82 82 82 82 82 82 82 82 82 82 82
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608. 2.01 0.2326 1.49 0.1632 0.98 0.0962	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9911	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099	CAT 0.3983 0.3983 0.3953 0.3919 0.3904 0.3895	POJ/P . 027020 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672	TS = 69124 CAF 0.2273 0.2256 0.2242 0.2232 0.2222	RUN 8 82 82 82 82 82 82 82 82 82 82 82 82 82
Q= 8.29 PSI PO= 107.0 CO ALPHA CN 4.05 0.4996 3.03 0.3608 2.01 0.2326 1.49 0.1632 0.98 0.0962 0.46 0.0371	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9211 -0.4375 0.1385	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639 0.2991	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077	CAT 0.3983 0.3983 0.3953 0.3919 0.3895 0.3895	POJ/P . 027020 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672 0.1659	TS = 69124 CAF 0.2273 0.2253 0.2242 0.2232 0.2223	RUN 8 82. 82. 82. 82. 82. 82. 82. 82. 82.
Q= 8.29 PSI PO= 107.0 CO ALPHA CN 4.05 0.4996 3.03 0.3608 2.01 0.2326 1.49 0.1632 0.98 0.0962 0.46 0.0371 -0.05 -0.0239	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9211 -0.4375 0.1385	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401 -0.0435 -0.0445	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639 0.2991 0.3099	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077 0.0060	CAT 0.3983 0.3983 0.3953 0.3919 0.3895 0.3895 0.3854	POJ/P . 02702 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672 0.1659 0.1649	TS = 69124 CAF 0.2273 0.2253 0.2242 0.2232 0.2223 0.2194 0.2196	RUN 8 82. 82. 82. 82. 82. 82. 82. 82. 82. 82.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608 2.01 0.2326 1.49 0.1632 0.98 0.0962 0.46 0.0371 -0.05 -0.0239 -0.56 -0.0866	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9911 -0.4375 0.1385 0.7238	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401 -0.0435 -0.0445 -0.0446	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639 0.2991 0.3099 0.3189	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077 C.0060 0.0038 0.0019 0.0008	CAT 0.3983 0.3953 0.3953 0.3919 0.3904 0.3895 0.3854 0.3839 0.3824 0.3795	POJ/P . 027020 CPB 0.1710 0.1693 0.1691 0.1686 0.1672 0.1672 0.1659 0.1649 0.1634 0.1619	CAF 0.2273 0.2252 0.2232 0.2232 0.2232 0.2194 0.2196 0.2176	RUN 8 82. 82. 82. 82. 82. 82. 82. 82. 82. 82.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608 2.01 0.2326 1.49 0.1632 0.98 0.0962 0.46 0.0371 -0.05 -0.0239 -0.56 -0.0239 -0.56 -0.0866 -1.07 -0.1464 -1.58 -0.2065 -2.08 -0.2659	RE PER. MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.4375 0.1385 0.7238 1.2844 1.8477	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401 -0.0435 -0.0445 -0.0446	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639 0.2991 0.3099 0.3169 0.3185 0.3113	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077 0.0060 0.0038 0.0019 0.0008	CAT 0.3983 0.3953 0.3953 0.3959 0.3895 0.3895 0.3834 0.3824 0.3785 0.3786	POJ/P 027020 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672 0.1659 0.1649 0.1619 0.1608	CAF 0.2273 0.2259 0.2242 0.2232 0.2223 0.2194 0.2196 0.2176	RUN 8 82. 82. 82. 82. 82. 83. 82. 84. 85. 86. 86. 86. 86. 86. 86. 86. 86.
Q= 8.29 PSI PO= 107.0 CI ALPHA CN 4.05 0.4996 3.03 0.3608 2.01 0.2326 1.49 0.1632 0.98 0.0962 0.46 0.0371 -0.05 -0.0239 -0.56 -0.0866 -1.07 -0.1464 -1.58 -0.2065	RE PER MHG PTS= CM -4.8182 -3.4981 -2.2829 -1.6251 -0.9911 -0.4375 0.1385 0.7238 1.2844 1.8477 2.4021	IN.= .48EGS 3.8665 PSI CS -0.0407 -0.0424 -0.0370 -0.0388 -0.0392 -0.0401 -0.0435 -0.0445 -0.0446 -0.0445	CY 0.2352 0.2614 0.2191 0.2412 0.2486 0.2639 0.2991 0.3099 0.3185 0.3113 0.3592	90. DE CR 0.0268 0.0202 0.0145 0.0113 0.0099 0.0077 C.0060 0.0038 0.0019 0.0008	CAT 0.3983 0.3953 0.3953 0.3919 0.3904 0.3895 0.3854 0.3839 0.3824 0.3757	POJ/P 02702 CPB 0.1710 0.1693 0.1691 0.1686 0.1682 0.1672 0.1659 0.1634 0.1619 0.1608 0.1594	CAF 0.2273 0.2259 0.2242 0.2232 0.2223 0.2176 0.2176 0.2176	RUN 8 82. 82. 82. 82. 82. 82. 82. 82. 82. 82.

MODEL 9	46.2 CON	FIG. 2.450	MA	CH 1.75		PHI =	45.	
Q= 6.29	PSI RE PER	IN.= .48E06	5 TO=	90. DE	.F	P0J/P1	rs = 4	0.
PO= 107	.O CMHG PTS=	3.8665 PSI		F	טא אט.	027626	9125	
ALPHA- C	Ñ CM	εs	CY	CR	CAT	CPB	CAF	RUN
4.03 0.4	786 -4.6971	-0.0805	0.5125	0.0333	0.4045	0.1756	0.2289	83.
3.02 0.3		-0.0803		0.0257 0				83.
1.99 0.19		-0.0736		0,0183 (83.
1.47 0.1		-0.0767		0.0151				83.
0.96 0.0		~0.0759		0.0120 0				83.
0.45 0.0		-0.0734		0.0089				83.
-0.07 -0.0		-0-0013		0.0072				83.
-0.58 -0.1		-0.0839		0.0047				83.
-1.08 -0.1		-0-0791		0.0002				83.
-1.60 -0.2		-0.0819		0.0003				83.
-2.10 -0.2		-0.0815		0.0045				83.
-3.12 -0.4		-0.0878		-0.0134 (83.
-4.15 -0.5	185 4.5998	-0.0887	0.6767-	·0.0278 (3.3788	0.1611	0.2177	83.
MODEL 9	46.2 COL		••				_	
		FIG. 2.450		40. DEC		= 1H9		30.
Q= 8.29		IN.= :46E0		90. DEC		PHI =		30.
Q= 8.29		IN.= .46E0		90. DEC	S.F		rs = 8	30.
Q= 8.29	PSI RE PER •O CHG .PTS=	IN.= .46E0		90. DEC	S.F	POJ/P1	rs = 8	80 . RUN
Q= 8.29 PO= 107 ALPHA C	PSI RE PER •O CHHG .PTS= N CH	: IN.= .48E00 : 3.8665 PSI : CS	5 TO=	90. DEC	S.F RUN NO.	POJ/P1 027028 CPB	TS = 8 59126 CAF	RUN
Q= 8.29 PO= 107 ALPHA C 3.99 0.4	PSI RE PER •0 CMHG .PTS= N CM 124 -4.2396	IN.= .46E00 3.8665 PSI CS -0.1675	6 TO= CY 1.1556	90. DEC F CR 0.0413 (G.F KUN NO. CAT D:4188	POJ/P1 027028 CPB 0.1817	TS = 8 59126 CAF 0.2370	
Q= 8.29 PO= 107 ALPHA C	PSI RE PER •0 CMHG .PTS= N CM 124 -4.2396 647 -2.8273	: IN.= .48E00 : 3.8665 PSI : CS	CY 1.1556 1.0735	90. DEC	G.F RUN NO. CAT D:4188 D.4148	POJ/P1 027028 CPB 0.1817 0.1769	S = 8 69126 CAF 0.2370 0.2379	RUN 84•
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1	PSI RE PER .0 CNHG .PTS= N CH 124 -4.2396 647 -2.8273 287 -1.5413	CS -0.1675 -0.1497	CY 1.1556 1.0735 0.9981	90. DEC CR 0.0413 (0.0331 (0.024+ (CAT CAT C4188 C4148 C4148	POJ/P1 027028 CPB 0.1817 0.1769 0.1752	TS = 8 59126 CAF 0.2370 0.2379 0.2351	RUN 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0	PSI RE PER .0 CSHG .PTS= N CM 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356	CS -0.1675 -0.1497 -0.1525	CY 1.1556 1.0735 0.9981 1.0235	90. DEC F CR 0.0413 (CAT CAT C:4188 C:4148 C:4148 C:4102 C:4088	POJ/P1 027028 CPB 0.1817 0.1769 0.1752 0.1739	S = 8 59126 CAF 0.2370 0.2379 0.2351 0.2349	RUN 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1	PSI RE PER .0 CSHG .PTS= N CM 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215	CS -0.1675 -0.1497	CY 1.1556 1.0735 0.9981 1.0235 1.0165	90. DEC F CR 0.0413 (0.0331 (0.024+ (0.0192 (CAT CAT C4188 0.4148 0.4162 0.4088 0.4066	POJ/PT 027028 CPB 0.1817 0.1769 0.1752 0.1739 0.1728	S = 8 59126 CAF 0.2370 0.2379 0.2351 0.2349 0.2338	RUN 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0	PSI RE PER .0 CMHG .PTS= N CM 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503	CS -0.1675 -0.1578 -0.1497 -0.1525 -0.1501	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356	90. DEC CR 0.0413 (0.0331 (0.0244 (0.0192 (9.0155 (CAT CAT C4188 0.4148 0.4102 0.4088 0.4066 0.4025	POJ/P1 027028 CP8 0.1817 0.1769 0.1752 0.1739 0.1728 0.1716	S = 8 59126 CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2309	RUN 84. 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0 0.41 -0.0	PSI RE PER .0 CNHG .PTS= N CM 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503 330 0.9046	CS -0.1675 -0.1578 -0.1497 -0.1515 -0.1501	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356 1.0336	90. DEC CR 0.0413 (0.0331 (0.0244 (0.0192 (0.0155 (0.0121 (CAT CAT C4188 C4148 C4162 C4088 C4066 C4025 C4085	POJ/P1 027028 CPB 0.1817 0.1769 0.1752 0.1739 0.1728 0.1716 0.1699	CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2309 0.2298	RUN 84. 84. 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0 0.41 -0.0 -0.11 -0.1	PSI RE PER .0 CNHG .PTS= N CM 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503 330 0.9046 021 1.5455	CS -0.1675 -0.1578 -0.1497 -0.1515 -0.1510 -0.1510	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356 1.0336 1.1462	90. DEC CR 0.0413 (0.0331 (0.0244 (0.0192 (0.0192 (0.0121 (0.0084 (CAT CAT CAT CAT CAT CATE CATE CATE CATE	POJ/P1 027028 CPB 0.1817 0.1769 0.1752 0.1739 0.1728 0.1716 0.1699 0.1683	CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2309 0.2298 0.2298	RUN 84. 84. 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0 0.41 -0.0 -0.11 -0.1 -0.62 -0.2	PSI RE PER .0 CNHG .PTS= N CH 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503 330 0.9046 021 1.5455 515 1.9929	CS -0.1675 -0.1578 -0.1497 -0.1515 -0.1501 -0.1510 -0.1502 -0.1604	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356 1.0336 1.1462 1.1137	90. DEC CR 0.0413 (0.0331 (0.0244 (0.0192 (0.0192 (0.0121 (0.0084 (0.0030 (CAT CAT C4188 C4188 C4148 C408	POJ/P1 027028 CPB 0.1817 0.1769 0.1752 0.1739 0.1718 0.1716 0.1699 0.1683 0.1668	CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2309 0.2298 0.2298 0.2298	RUN 84. 84. 84. 84. 84. 84.
Q= 8.29 PO= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0 0.41 -0.0 -0.11 -0.1 -0.62 -0.2 -1.13 -0.2	PSI RE PER .0 CNHG .PTS= N CH 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503 330 0.9046 021 1.5455 515 1.9929 113 2.5417	CS -0.1675 -0.1578 -0.1578 -0.1515 -0.1501 -0.1510 -0.1510 -0.1502 -0.1604 -0.1570	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356 1.0336 1.1462 1.1137 1.1417-	90. DEC CR 0.0413 (0.0331 (0.0192 (0.0192 (0.0192 (0.003 (0.003 (CAT CAT CAT CAT CAT CAT CAT CAT	POJ/P1 027028 CPB 0.1817 0.1769 0.1752 0.1739 0.1728 0.1716 0.1699 0.1683 0.1668	CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2298 0.2298 0.2298 0.2298	RUN 84. 84. 84. 84. 84. 84. 84.
Q= 8.29 P0= 107 ALPHA C 3.99 0.4 2.98 0.2 1.96 0.1 1.43 0.0 0.92 -0.0 0.41 -0.0 -0.11 -0.1 -0.62 -0.2 -1.13 -0.2 -1.64 -0.3	PSI RE PER .0 CNHG .PTS= N CH 124 -4.2396 647 -2.8273 287 -1.5413 538 -0.8356 114 -0.2215 731 0.3503 330 0.9040 021 1.5455 515 1.9925 113 2.5417 625 3.0092 744 4.0181	CS -0.1675 -0.1578 -0.1497 -0.1515 -0.1501 -0.1502 -0.1570 -0.1570	CY 1.1556 1.0735 0.9981 1.0235 1.0165 1.0356 1.0336 1.1462 1.1147 1.1417- 1.1457- 1.1945-	90. DEC CR 0.0413 (0.0331 (0.0192 (0.0192 (0.0121 (0.0084 (0.0030 (0.0003 (0.0003 (CAT CAT CAT CAT CAT CAT CAT CAT CAT CAT	POJ/P1 027026 CPB 0.1817 0.1769 0.1752 0.1739 0.1768 0.1699 0.1683 0.1663 0.1653 0.1642 0.1626	CAF 0.2370 0.2379 0.2351 0.2349 0.2338 0.2309 0.2298 0.2295 0.2300 0.2282 0.2277	RUN 84. 84. 84. 84. 84. 84. 84.

MODEL 946.2	CONF	IG. 2.450	M	ACH 1.75	5	PHI =	·60 .	
Q= 8.29 PSI	RE PER	IN.= .48E0	5 TO=	90. DE	G.F	POJ/P	rs ≠	•
PO= 107.0 C	MHG PTS=	3.8665 PSI			RUN NO.	02702	69127	-
ALPHA CN	CM	cs	CY	CR	CAŢ	CPB	CAF	RUN
4.06 0.5076	-4.8107	-0.0162	0.1252	0.0068	0.3947	0.1631	0.2316	85.
3.04 0.3764	-3.5622	-0.0176	0.1423	0.0058	0.3894	0.1617	0.2276	85.
2.02 0.2471	-2.3356	-0.0239		0.0054				
1.50 0.1807	-1.7093	-0.0189		0.0059				
0.98 0.1161	-1.0943	-0.0247		0.0050				
0.48 0.0617	-0.5847			0.0059				
-0.03 -0.0026		-0-0204		0.0059				
-0.54 -0.0667	0.6306	-0.0241		0.0053				
-: 76 -0.1273	1.2022			0,0055				
-1.35 -0.1906		-0.0244		0.0052				
-2 07 -0.2501		-0.0202		0.0058				
-3.09 -0.3806		-0.0251		0.0062				
-4.11 -0.5124	4.8557	-0.0261	0.2500	0.0067	0.3696	0.1553	0.2143	85.
MUDEL 946.2 Q= P.29 PSI		FIG. 2.450		ACH 1.75		PHI =	60. TS =	10.
	RE PER	IN.= .48E0			EG•F		rs =	10.
Q= P.29 PSI	RE PER	IN.= .48E0			EG•F	P0 J/ P	rs =	LO.
Q= P.29 PSI PO= 107.0 C	RE PER MHG PTS≂ CM	IN.= .48E0 3.8665 PSI CS	6 TO=	90. DE	EG.F RUN NO.	POJ/P 027020 CPB	TS = 69128 CAF	RUN
Q= P.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4988	RE PER MHG PTS= CM -4.7403	IN.= .48E0 3.8665 PSI CS -0.0297	6 TO= CY 0.1719	90. DI	RUN NO. CAT	POJ/P 027020 CPB 0.1654	TS = 69128 CAF 0.2315	RUN 86.
Q= P.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4988 3.04 0.3682	RE PER MHG PTS= CM -4.7403 -3.5036	IN.= .48E0 3.8665 PSI CS	CY 0.1719 0.1883	90. DE CR 0.0194	EG.F RUN NO. CAT 0.3970 0.3922	POJ/P . 027020 CPB 0.1654 0.1640	TS = 69128 CAF 0.2315 0.2283	RUN 86. 86.
Q= P.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4988	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299	CY 0.1719 0.1883 0.1322 0.1770	90. DE CR 0.0194 0.0158 0.0116 0.0101	CAT 0.3970 0.3922 0.3874 0.3868	POJ/P . 027026 CPB 0.1654 0.1640 0.1636 0.1636	TS = 69128 CAF 0.2315 0.2283 0.2237	RUN 86. 86. 86.
Q= P.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229	CY 0.1719 0.1883 0.1322 0.1770	90. DE CR 0.0194 0.0158 0.0116 0.0101	CAT 0.3970 0.3922 0.3874 0.3868	POJ/P . 027026 CPB 0.1654 0.1640 0.1636 0.1636	TS = 69128 CAF 0.2315 0.2283 0.2237	RUN 86. 86. 86.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.50 0.1758	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282	CY 0.1719 0.1883 0.1322 0.1770 0.1934	90. DE CR 0.0194 0.0158 0.0116	CAT 0.3970 0.3922 0.3874 0.3868 0.3869	POJ/P . 027020 CPB 0.1654 0.1636 0.1636 0.1638	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2232	RUN 86. 86. 86. 86.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.50 0.1758 0.99 0.1123	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0867 -0.4908	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282	CY 0.1719 0.1883 0.1322 0.1770 0.1934 0.1864 0.1884	90. DE CR 0.0194 0.0158 0.0116 0.00101 0.0081 0.0072 0.0060	CAT 0.3970 0.3972 0.3874 0.3868 0.3869 0.3856 0.3836	POJ/P . 02702 . CP8 0.1654 0.1636 0.1636 0.1638 0.1638 0.1638	TS = 69128 CAF 0.2315 0.2283 0.2231 0.2232 0.2231	RUN 86 • 86 • 86 • 86 • 86 •
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.50 0.1758 0.99 0.1123 0.47 0.0489 -0.04 -0.0115 -0.55 -0.0758	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0864 -0.4908 0.0742 0.6791	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282 -0.0271 -0.0270 -0.0270 -0.0315	CY 0.1719 0.1883 0.1322 0.1770 0.1864 0.1884 0.2318	90. DE CR 0.0194 0.0158 0.0101 0.0081 0.0072 0.0060 0.0045	CAT 0.3970 0.3972 0.3874 0.3869 0.3856 0.3836 0.3831	POJ/P . 02702 . CPB 0.1654 0.1636 0.1636 0.1638 0.1638 0.1630 0.1620	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2231 0.2219 0.2206	RUN 86. 86. 86. 86. 86. 86. 86.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.50 0.1758 0.99 0.1123 0.47 0.0489 -0.04 -0.0115 -0.55 -0.0758 -1.05 -0.1322	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0867 -0.4908 0.0742 0.6791 1.2091	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282 -0.0271 -0.0270 -0.0315 -0.0239	CY 0.1719 0.1883 0.1322 0.1770 0.1864 0.1884 0.2318 0.1595	90. DE CR 0.0194 0.0158 0.0101 0.0081 0.0072 0.0060 0.0045 0.0037	CAT 0.3970 0.3972 0.3874 0.3869 0.3856 0.3836 0.3831 0.3802	POJ/P . 02702 . CPB 0.1654 0.1640 0.1636 0.1638 0.1636 0.1630 0.1620 0.1603	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2231 0.2219 0.2206	RUN 86. 86. 86. 86. 86. 86. 86.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.500 0.1758 0.99 0.1123 0.47 0.0489 -0.04 -0.0115 -0.55 -0.0758 -1.05 -0.1322 -1.57 -0.1956	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0867 -0.4908 0.0742 0.6791 1.2091 1.8036	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282 -0.0271 -0.0270 -0.0315 -0.0239 -0.0228	CY 0.1719 0.1883 0.1322 0.1770 0.1934 0.1864 0.1884 0.2318 0.1595 0.1548	90. DE CR 0.0194 0.0158 0.0101 0.0011 0.0072 0.0060 0.0045 C.0037 0.0019	CAT 0.3970 0.3922 0.3874 0.3868 0.3856 0.3836 0.3831 0.3802 0.3789	POJ/P . 02702 . CPB 0.1654 0.1640 0.1636 0.1638 0.1630 0.1620 0.1603 0.1585	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2232 0.2231 0.2219 0.2206 0.2211 0.2204	RUN 86. 86. 86. 86. 86. 86. 86. 86.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.50 0.1758 0.99 0.1123 0.47 0.0489 -0.04 -0.0115 -0.55 -0.0758 -1.05 -0.1322 -1.57 -0.1956 -2.08 -0.2566	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0867 -0.4908 0.0742 0.6791 1.8036 2.3762	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282 -0.0271 -0.0270 -0.0315 -0.0239 -0.0228 -0.0223	CY 0.1719 0.1883 0.1322 0.1770 0.1934 0.1864 0.1884 0.2318 0.1595 0.1548 0.1551	90. DE CR 0.0194 0.0158 0.0116 0.00101 0.0081 0.0072 0.0060 0.0045 0.0037 0.0019 0.0004	CAT 0.3970 0.3922 0.3874 0.3868 0.3856 0.3836 0.3836 0.3832 0.3789 0.3762	POJ/P . 027026 CPB 0.1654 0.1636 0.1636 0.1636 0.1630 0.1630 0.1630 0.1630 0.1630 0.1630	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2232 0.2211 0.2206 0.2211 0.2204 0.2192	RUN 86. 86. 86. 86. 86. 86. 86. 86.
Q= 8.29 PSI P0= 107.0 CI ALPHA CN 4.05 0.4988 3.04 0.3682 2.02 0.2406 1.500 0.1758 0.99 0.1123 0.47 0.0489 -0.04 -0.0115 -0.55 -0.0758 -1.05 -0.1322 -1.57 -0.1956	RE PER MHG PTS= CM -4.7403 -3.5036 -2.2978 -1.6864 -1.0867 -0.4908 0.0742 0.6791 1.2091 1.8036 2.3762 3.5207	IN.= .48E0 3.8665 PSI CS -0.0297 -0.0299 -0.0229 -0.0270 -0.0282 -0.0271 -0.0270 -0.0315 -0.0239 -0.0228	CY 0.1719 0.1883 0.1322 0.1770 0.1934 0.1864 0.2318 0.1595 0.1548 0.1551 0.1625	90. DE CR 0.0194 0.0158 0.0101 0.0011 0.0072 0.0060 0.0045 C.0037 0.0019	CAT 0.3970 0.3922 0.3874 0.3868 0.3856 0.3856 0.3831 0.3802 0.3762 0.3762 0.3730	POJ/P . 02702 CPB 0.1654 0.1636 0.1636 0.1638 0.1636 0.1630 0.1630 0.1520 0.1520 0.1570 0.1561	TS = 69128 CAF 0.2315 0.2283 0.2237 0.2232 0.2219 0.2206 0.2211 0.2204 0.2192 0.2168	RUN 86. 86. 86. 86. 86. 86. 86. 86. 86.

MO	DEL 946.2	CON	FIG. 2.450	M.	ACH 1.75	5	PHI =	60.	
Q=	8.29 PSI	RE PER	IN.= .43E0	6 T0=	90. DE	G•F	-601/5.	ts = 2	20.
PO	= 107.0 CH	HG PTS=	3.8665 PSI			RUN NO	02702	691,29	
ALPHA	CN	CM	CŠ	CY	CR	CAT	СРВ	CAF	RUN
4.05		•	-0.0465		0.0328				87.
3.03	0.3598	-3.4436	-0.0420		0.9237				87.
2.01			-0.0451		0.0167				87.
1.49			-0.0437		0.0129				87.
	0.1018		-0.0437		0.0100				87.
0.45			-0.0422		0.0082				87.
	-0.0219		-0.0410		0.0059				87.
	-0.0814		-0.0400		0.0036				87.
	-0-1424		-0.0425		0.0015				87.
	-0-2028		-0.0402		-0.0025				87.
		2,3672			-0.0033				87.
	-0.3772		-0.0392		-0.0099				87.
-4.13	-0.5001	4-5817	-0.0356	0.2342	-0.0163	0.3763	0.1607	0.2356	87.
	DEL 946.2		FIG. 2.450		ACH 1.75		PHI =	60.	_
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	G•F	4VL03	rs = 4	0-
PÓ	= 107.0 CM	HG PTS≖	3.8665 PSI			RUN NO	. 02702	69130	
ALPHA	CN	CH	ÇS	CY	CŖ	CAT	CP8	CAF	RUN
4.04	0.4849	-4.6773	-0.0821	0.4772	0.0382	0.4066	0.1748	0.2318	88.
3.03		-3.3466	-0.0843	0.5243	0.0290	0.4012	0.1714	0.2299	88.
2.00	0.2071	-2.0532	-0.0832	0.5314	0.0210	0.3999	0.1699	0.2300	88.
1.48	0.1423	-1.4450	-0.0829	0.5319	0.0170	0.3966	0.1699	0.2267	88.
0.97	0.0776	-0.8420	-0.0841	0.5533	0.0129	0.3946	0.1700	0.2246	88.
0.44	0.0159		-0.0833	0.5484	0.0103	0.3934	0.1696	0.2238	88.
-0.06	-0.0438	0.2866	-0.0806	0.5295	0.0068	0.3934	0.1682	0.2251	88.
-0.57	-0.1062		-0.0868		0.0033				88.
-1.08	-0.1633		-0.0886		-0.0004				88.
-1.60	-0.2230	1.9440	-0.0836		-0.0036				88.
	-0.2768	2.4365	-0.0798		-0.0078				88.
	-0.3913	3.4763	-0.0809		-0.0181				88.
-4.15	-0.4986	. 4.4320	-0.0758	0.5049	-0.0361	0.3830	0.1642	0-2188	88.

MOD	EL 946.2	CONF	IG. 2.450	- M <i>i</i>	ACH 1.79	5 .	PHI =	60.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO∓	90. DI	EG.F	- POJ/ <u>P</u>	TS =	80 :
=09	107.0 CM	HG PTS=	3.8665 PSI			RUN NO	02702	59131	
ALPHA	CN	CH	CS	CY	CR.	CAT	CPB	CAF	RUN
3.98	0.4358	-4.3177	-0.1918	1.3,007	0.0438	0.4231	0.1813	0.2417	89.
3.00	0.2976	-3.010?	-0.1819	1.2183	0.0361	0.4160	0.1769	0.2391	89.
	0.1582		-0.1736			0.4098			
	0.0870		-0.1787			0-4074			
	0.0223		-0-1747			0.4053			
	-0-0364		-0.1718			0,4026			
	-0.0998		-0-1745			0.3994			
	-0.1592	1.2367				0.3997			
	-0.2136	1.7307				0.3971			
	-0-2755	2.2932	-0.1825 -0.1733	1.2971-	-0.0089	0.3973	0.1658	0.2318	89.
	-0.4369	3.138/2	-0.1696	1.1824	-0.0295	0-2946	0.1000	0.2280	89.
-4.15	-0.5460	. 4.1001	-0.1611	1.1053	-0.0480	0.3923	A. FOSÓ	0.2265	89.
,	EL 946.2		FIG. 2.450		ACH 1.75		PHI =	75.	
,			FIG. 2.450 IN.= .48E0		90. Di	EG.F	60 1 /6.	rs =	•
Ø=	8.29 PSI	RE PER		6 10=	90. Di		60 1 /6.	rs =	•
Ø=	8.29 PSI	RE PER	IN.= .48E0	6 10=	90. Di	EG.F	60 1 /6.	rs =	RUN
Q= P0=	8.29 PSI 107.0 CM	RE PER	IN.= .48E0 3.8665 PSI CS	6 10≈ CY	90. DI	EG.F RUN NO	POJ/P	rs = 69132 CAF	
Q= PO≈ ALPHA 4.06	8.29 PSI 107.0 CM	RE PER HG PTS= CM -4.7915	IN.= .48E0 3.8665 PSI CS	6 10= CY 0.0071	90. DE	EG.F RUN NO CAT	POJ/P 027020 CPB 0.1628	TS = 69132 CAF 0.2237	90.
Q= PO= ALPHA 4.06 3.05	8.29 PSI 107.0 CM CN 0.5063	RE PER HG PTS= CM -4.7915	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097	CY 0.0071 0.0729 0.1456	90. 01 CR 0.0071 0.0055 0.0047	EG.F RUN NO. CAT 0.3865 0.3810 0.3797	POJ/P . 027020 CPB 0.1628 0.1598 0.1607	CAF 0.2237 0.2212 0.2190	90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327	CY 0.0071 0.0729 0.1456 0.3018	90. 01 CR 0.0071 0.0055 0.0047 0.0054	CAT 0.3865 0.3810 0.3797 0.3776	POJ/P . 027020 CPB 0.1628 0.1598 0.1607 0.1618	TS = 69132 CAF 0.2237 0.2212 0.2190	7 90. 2 90. 3 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0211	CY 0.0071 0.0729 0.1456 0.3018 0.1850	90. Di CR 0.0071 0.0055 0.0047 0.0054 0.0060	CAT 0.3865 0.3810 0.3797 0.3776	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632	TS = 69132 CAF 0.2237 0.2212 0.2156 0.2157	7 90. 2 90. 3 90. 5 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 G.1792 0.1202 0.0586	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352 -0.5544	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0211 -0.0250	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260	90. Di CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1636	CAF 0.2237 0.2212 0.2190 0.2158 0.2157	90. 90. 90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 G.1792 0.1202 0.0586 -0.0026	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352 -0.5544 0.0243	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0211 -0.0250 -0.0257	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3749	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1636 0.1634	CAF 0.2237 0.2213 0.2190 0.2158 0.2157 0.2153	90. 90. 90. 90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.55	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202 0.0586 -0.0026 -0.0658	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352 -0.5544 0.0243 0.6229	IN.= .48E0 3.8665 PSI CS -0.0097 -0.0097 -0.0172 -0.0327 -0.0250 -0.0257 -0.0257	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342 0.3023	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048 0.0050 0.0044	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3759 0.3759	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1634 0.1634	CAF 0.2237 0.2213 0.2150 0.2153 0.2153 0.2153 0.2153	90. 90. 90. 90. 90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.55 -1.05	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202 0.0586 -0.0026 -0.0658 -0.1241	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.61352 -0.5544 0.0243 0.6229 1.1701	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0250 -0.0257 -0.0257 -0.0326 -0.0199	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342 0.3023 0.1737	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048 0.0050 0.0044	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3749 0.3726 0.3713	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1634 0.1626 0.1610	CAF 0.2237 0.2213 0.2158 0.2157 0.2158 0.2157 0.2123 0.2100	90. 2 90. 3 90. 3 90. 4 90. 5 90. 6 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.55 -1.05 -1.56	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202 0.0586 -0.0026 -0.0058 -0.1241 -0.1876	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352 -0.5544 0.0243 0.6229 1.1701	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0211 -0.0250 -0.0257 -0.0326 -0.0199 -0.0333	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342 0.3023 0.1737 0.3116	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048 0.0050 0.0044 0.0049 0.0051	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3749 0.3726 0.3713 0.3684	POJ/P . 02702 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1636 0.1634 0.1626 0.1610 0.1584	CAF 0.2237 0.2213 0.2157 0.2153 0.2157 0.2103 0.2103	90. 90. 90. 90. 90. 90. 90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.55 -1.56 -2.07	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202 0.0586 -0.0026 -0.0058 -0.1241 -0.1876	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.6915 -1.1352 -0.5544 0.0243 0.6229 1.1701	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0211 -0.0250 -0.0257 -0.0326 -0.0199 -0.0333	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342 0.3023 0.1737 0.3116 0.2805	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048 0.0050 0.0049 0.0051 0.0050	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3749 0.3726 0.3721 0.3684 0.3653	POJ/P . 027020 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1634 0.1626 0.1610 0.1584 0.1554	CAF 0.2237 0.2212 0.2158 0.2158 0.2158 0.2100 0.2100	90. 90. 90. 90. 90. 90. 90. 90. 90.
Q= P0= ALPHA 4.06 3.05 2.03 1.51 1.00 0.49 -0.03 -0.55 -1.05 -1.56 -2.07 -3.08	8.29 PSI 107.0 CM CN 0.5063 0.3782 0.2480 0.1792 0.1202 0.0586 -0.0026 -0.0658 -0.1241 -0.1876 -0.2525 -0.3796	RE PER HG PTS= CM -4.7915 -3.5769 -2.3432 -1.61352 -0.5544 0.0243 0.6229 1.1701	IN.= .48E0 3.8665 PSI CS -0.0031 -0.0097 -0.0172 -0.0327 -0.0250 -0.0257 -0.0326 -0.0199 -0.0333 -0.0303 -0.0372	CY 0.0071 0.0729 0.1456 0.3018 0.1850 0.2260 0.2342 0.3023 0.1737 0.3116 0.2805 0.3525	90. DE CR 0.0071 0.0055 0.0047 0.0054 0.0060 0.0048 0.0050 0.0049 0.0050 0.0050 0.0050	CAT 0.3865 0.3810 0.3797 0.3776 0.3789 0.3759 0.3749 0.3726 0.3713 0.3684	POJ/P . 027020 CPB 0.1628 0.1598 0.1607 0.1618 0.1632 0.1636 0.1634 0.1626 0.1554 0.1554	CAF 0.2237 0.2212 0.2190 0.2158 0.2157 0.2100 0.2100 0.2100	90. 90. 90. 90. 90. 90. 90. 90. 90. 90.

MOD	EL 946.2	COÑ	FIG. 2.450	H	ACH 1.75	PHI =	75.	
Q =	8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/Pi	S = 10.	
P0=	107.0 CM	HG PTS=	3.8665 FSI		RUN NO	. 02702 <i>6</i>	9133	
ALPHA	CN	CM	cs	ĊY	GR CAT	СРВ	CAF	RUN
4.06	0.5011	-4.7318	-0.0056	-0.0587	0.0177 0.3864	0.1631	0.2233	91.
3.05	0.3686	-3.4831	-0-0205	0.0970	0.0140 0.3825	0.1613	0.2211	91.
2.03	0.2410	-2.2818	-0.0305		0.0101 0.3785			91.
1.51	0.1738	-1.6506	-0.0357		0.0082 0.3768			91.
0.99	0.1140		-0.0300		0.0067 0.3743			91.
0:49	0.0528		-0.0307		0.0055 0.3766			91.
	-0.0113		-0.0380		0.0034 0.3737			91.
	-0•0695	0.6304	-0.0347		0.0034 0.3719			91.
	-0-1297		-0.0370		0.0010 0.3709			91.
	-0-1919		-0.0374		-0.0005 0.3685			91.
	-0.2518		-0.0397		0.0017 0.3662			91.
	-0-3749		-0.0395		-0.0035 0.3654			91.
-4-11	-0.5059	4.7243	-0.0406	0.3260-	-0.0026 0.3625	0-1568	0.2057	91.
	EL 946.2 8.29 PSI		FIG. 2.450 IN.= .48E0		ACH 1:75 90. DEG.F	PHI =	75. 'S = 20.	
0 =	8.29 PSI	RE PER	_	6 T0=	90. DEG.F		'S = 20.	
0 =	8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. DEG.F	POJ/PT	'S = 20.	RUN
0= P0= ALPHA	8.29 PSI 107.0 CMI	RE PER HG PTS=	IN.= .48E0 3.8665 PSI	6 T0=	90. DEG.F KUN NO CR CAT	POJ/PT • 027026 CPB	S = 20. 9134 CAF	RUN 92•
0= P0=	8.29 PSI 107.0 CM	RE PER HG PTS= CM	IN.= .48E0	6 TO= CY 0.0743	90. DEG.F	POJ/PT • 027026 CPB 0•1649	S = 20. 9134 CAF 0.2300	
0= P0= ALPHA 4.07 3.05	8.29 PSI 107.0 CM CN 0.4955	RE PER HG PTS= CM -4.6652 -3.4463	IN.= .48E0 3.8665 PSI CS -0.0295	6 TO= CY 0.0743 9.2377	90. DEG.F KUN NO CR CAT 0.0366 0.3949	POJ/PT • 027026 CPB 0•1649 0•1638	S = 20. 9134 CAF 0.2300 0.2285	92.
0= P0= ALPHA 4.07	8.29 PSI 107.0 CM CN 0.4955 0.3650	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435	6 To= CY 0.0743 9.2377 0.3299	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649	S = 20. 9134 CAF 0.2300 0.2285 0.2226	92. 92.
Q= PO= ALPHA 4.07 3.05 2.03 1.51	8.29 PSI 107.0 CMI CN 0.4955 0.3650 0.2352	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627	IN = .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510	CY 0.0743 0.2377 0.3299 0.2774	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1660	S = 20. 9134 CAF 0.2300 0.2285 0.2226 0.2217	92. 92. 92.
Q= PO= ALPHA 4.07 3.05 2.03 1.51	8.29 PSI 107.0 CMI CN 0.4955 0.3650 0.2352 0.1740	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.0877	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450	CY 0.0743 9.2377 0.3299 0.2774 0.3424	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1660 0.1668	S = 20. 9134 CAF 0.2300 0.2285 0.2226 0.2217 0.2193	92. 92. 92. 92.
Q= PO= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48	8.29 PSI 107.0 CM CN 0.4955 0.3650 0.2352 0.1740 0.1125	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.0877 -0.5052	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450 -0.0510	6 T0= CY 0.0743 9.2377 0.3299 0.2774 0.3424 0.3686 0.4140	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1660 0.1668 0.1668 0.1668	CAF 0.2300 0.2285 0.2226 0.2217 0.2193 0.2196 0.2182	92. 92. 92. 92. 92. 92.
PO= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48 -0.04 -0.55	8.29 PSI 107.0 CM CN 0.4955 0.3650 0.2352 0.1740 0.1125 0.0501 -0.0131 -0.0714	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.66877 -0.5052 0.0818 0.6241	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450 -0.0513 -0.0575 -0.0542	6 T0= CY 0.0743 9.2377 0.3299 0.2774 0.3424 0.3686 0.4140 0.3832	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841 0.0018 0.3830	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1660 0.1668 0.1668 0.1659 0.1649	CAF 0.2300 0.2285 0.2285 0.2217 0.2193 0.2196 0.2182 0.2181	92. 92. 92. 92. 92. 92.
0= P0= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48 -0.04 -0.55 -1.05	8.29 PSI 107.0 CM CN 0.4955 0.3650 0.2352 0.1740 0.1125 0.0501 -0.0131 -0.0714 -0.1332	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.0877 -0.5052 0.0818 0.6241 1.1978	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450 -0.0533 -0.0575 -0.0542 -0.0581	6 T0= CY 0.0743 9.2377 0.3299 0.2774 0.3424 0.3686 0.4140 0.3832 0.4224	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841 0.0018 0.3830 0.0003 0.3821	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1660 0.1668 0.1659 0.1649 0.1636	CAF 0.2300 0.2285 0.2226 0.2217 0.2193 0.2196 0.2182 0.2181 0.2184	92. 92. 92. 92. 92. 92. 92.
Q= PO= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48 -0.04 -0.55 -1.05	8.29 PSI 107.0 CMI CN 0.4955 0.3650 0.2352 0.1740 0.1125 0.0501 -0.0131 -0.0714 -0.1332 -0.1907	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.6627 -0.5052 0.0818 0.6241 1.1978 1.7325	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450 -0.0533 -0.0575 -0.0542 -0.0581 -0.0503	CY 0.0743 9.2377 0.3299 0.2774 0.3424 0.3686 0.4140 0.3832 0.4224 0.3418	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841 0.0018 0.3830 0.0003 0.3821 0.0003 0.3821	POJ/PT . 027026 CPB 0.1649 0.1638 0.1660 0.1668 0.1669 0.1649 0.1636 0.1659	CAF 0.2300 0.2285 0.2226 0.2217 0.2193 0.2196 0.2182 0.2181 0.2184 0.2167	92. 92. 92. 92. 92. 92. 92. 92.
Q= PO= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48 -0.04 -0.55 -1.56 -2.07	8.29 PSI 107.0 CMI CN 0.4955 0.3650 0.2352 0.1740 0.1125 0.0501 -0.0131 -0.0714 -0.1332 -0.1907 -0.2473	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.0877 -0.5052 0.0813 0.6241 1.1978 1.7325 2.2594	IN = .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0550 -0.0533 -0.0575 -0.0542 -0.0581 -0.0503 -0.0514	CY 0.0743 9.2377 0.3299 0.2774 0.3424 0.3686 0.4140 0.3832 0.3418- 0.3537-	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841 0.0018 0.3830 0.0003 0.3821 0.0023 0.3782	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1668 0.1668 0.1659 0.1649 0.1636 0.1615	CAF 0.2300 0.2285 0.2226 0.2217 0.2193 0.2196 0.2182 0.2181 0.2184 0.2167 0.2169	92. 92. 92. 92. 92. 92. 92. 92.
PO= ALPHA 4.07 3.05 2.03 1.51 1.00 0.48 -0.04 -0.55 -1.05 -1.05 -2.07 -3.09	8.29 PSI 107.0 CMI CN 0.4955 0.3650 0.2352 0.1740 0.1125 0.0501 -0.0131 -0.0714 -0.1332 -0.1907	RE PER HG PTS= CM -4.6652 -3.4463 -2.2353 -1.6627 -1.0877 -0.5052 0.0818 0.6241 1.1978 1.77325 2.2594 3.3636	IN.= .48E0 3.8665 PSI CS -0.0295 -0.0435 -0.0510 -0.0450 -0.0533 -0.0575 -0.0542 -0.0581 -0.0503	CY 0.0743 0.2377 0.3299 0.2774 0.3424 0.3686 0.4140 0.3832 0.4224 0.3418 0.3537 0.4084	90. DEG.F RUN NO CR CAT 0.0366 0.3949 0.0263 0.3923 0.0174 0.3875 0.0133 0.3877 0.0098 0.3861 0.0074 0.3864 0.0050 0.3841 0.0018 0.3830 0.0003 0.3821 0.0003 0.3821	POJ/PT . 027026 CPB 0.1649 0.1638 0.1649 0.1668 0.1668 0.1669 0.1649 0.1636 0.1615 0.1597 0.1590	CAF 0.2300 0.2285 0.2226 0.2217 0.2193 0.2196 0.2182 0.2181 0.2167 0.2169 0.2171	92. 92. 92. 92. 92. 92. 92. 92.

MODEL 946.2	ÇONF I	IG. 2.450	MACH 1	75	PHI =	75.	
Q= 8.29 PSI	RE PER I	IN.= .48E06	5 TO₹ 90.	DEG.F	T9\LO9	S = 40.	
PO= 107.0 CM	HG PTS= 3	3.8665 PSI	_	RUN NO	027026	9135	
ALPHA CN	CM	cs	CY CR	CAT	CPŚ	CAF	RUN
4.06 0.4907	-4.6369 -	-0.0836	0.4598 0.042	21 0.4046	0.1720	0.2326	93.
3.04 0.3577	-3.3928 -		0.5362 0.03				93.
2.02 0.2241	-2.1436 -		0.6612 0.022				93.
1.50 0.1602	-1.5515 -		0.6108 0.017				93.
0.99 0.1015	-1.0069 -		0.6357 0.012				93.
0.48 0.0354	-0.3942 -		0.7892 0.009				93.
-0.03 -0.0196	0.1138 -		0.6601 0.000				93.
-0.55 -0.0791	0.6623		0.6483 0.003				93.
-1.07 -0.1399	1.2233 -		0.6622-0.001				93.
-1.58 -0.2009	1.7852		0.7188-0.006				93. 93.
-2.08 -0.2554	2,2844		0.5841-0.019				93.
-3.10 -0.3703 -4.13 -0.4855	3.3249 - 4.3654 -		0.5539-0.034				93.
-4.13 -0.4833	4.3034	-0.0012.	0.00004-0.00	15 0.3031	0.10/4	0,2103	73•
MODEL 946.2 Q= 8.29 PSI		IG. 2.450 IN.= .48E0			PHI =	75. S = 80.	
	RE PER	IN.= .48E0		DEG.F	_	'S = 80.	
Q= 8.29 PSI	RE PER	IN.= .48E0		DEG.F RUN NO	14/504	'S = 80.	RUN
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER	IN.= .48E00 3.8665 PSI GS	6 TO= 90.	DEG.F RUN NO.	POJ/PT - 027026 CPB	S = 80. 9136 CAF	RUN 94•
Q= 8.29 PSI PO= 107.0 CF	RE PER I	IN.= .48E06 3.8665 PSI CS -0.1903	6 TO= 90.	DEG.F RUN NO. CAT 81 0.4240	POJ/PT • 027026 CPB 0•1812	S = 80. 9136 CAF 0.2428	
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.05 0.4750	RE PER 1 HHG PTS= 1 CH -4.5318	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894	6 TO= 90. CY CR 1.2371 0.04	DEG.F RUN NO. CAT B1 0.4240 B6 0.4163	POJ/PT . 027026 CPB 0.1812 0.1755	S = 80. 9136 CAF 0.2428 0.2409	94.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.05 0.4750 3.04 0.3354	RE PER 1 HG PTS= 1 CM -4.5318 -3.2234 -1.9340 -1.3160	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981	6 T0= 90. CY CR 1.2371 0.040 1.2430 0.030	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728	S = 80. 9136 CAF 0.2428 0.2409 0.2361	94 • 94 •
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976	RE PER 1 HHG PTS= 1 CM -4.5318 -3.2234 -1.9340	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342	94 • 94 •
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308	RE PER 1 HG PTS= 1 CM -4.5318 -3.2234 -1.9340 -1.3160	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021	CY CR 1.2371 0.044 1.2430 0.034 1.3372 0.024 1.3576 0.02	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342	94 • 94 • 94 •
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049 12 0.4025 67 0.4009	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 6.1702 0.1693	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316	94. 94. 94. 94. 94.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693 0.46 0.0067 -0.05 -0.0473 -0.57 -0.1079	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524 -0.1802 0.3159 0.8633	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997 -0.2015 -0.2023	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00 1.4163 0.00	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049 12 0.4025 67 0.4009 14 0.3986	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 G.1702 0.1693 0.1677	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316 0.2309	94. 94. 94. 94. 94. 94.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693 0.46 0.0067 -0.05 -0.0473 -0.57 -0.1079 -1.09 -0.1711	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524 -0.1802 0.3159 0.8633 1.4373	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997 -0.2015 -0.2023 -0.2125	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00 1.4163 0.00 1.5212-0.00	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049 12 0.4025 67 0.4009 14 0.3986 56 0.3965	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 0.1707 0.1667	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316 0.2309 0.2299	94. 94. 94. 94. 94. 94. 94.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693 0.46 0.0067 -0.05 -0.0473 -0.57 -0.1079 -1.09 -0.1711 -1.59 -0.2237	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524 -0.1802 0.3159 0.8633 1.4373 1.9091	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997 -0.2015 -0.2023 -0.2125 -0.1972	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00 1.4163 0.00 1.5212-0.00 1.3694~0.01	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4059 12 0.4025 67 0.4009 14 0.3986 56 0.3965 02 0.3973	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 0.1667 0.1667	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316 0.2309 0.2299 0.2307	94. 94. 94. 94. 94. 94. 94. 94.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693 0.46 0.0067 -0.05 -0.0473 -0.57 -0.1079 -1.09 -0.1711 -1.59 -0.2237 -2.10 -0.2786	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524 -0.1802 0.3159 0.8633 1.4373 1.9091 2.4070	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997 -0.2015 -0.2023 -0.2125 -0.1972 -0.1982	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00 1.4163 0.00 1.5212-0.00 1.3694-0.01 1.3807-0.01	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049 12 0.4025 67 0.4009 14 0.3966 56 0.3965 02 0.3973 65 0.3964	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 (0.1602 0.1667 0.1667 0.1666 0.1675	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316 0.2309 0.2299 0.2299 0.2299	94. 94. 94. 94. 94. 94. 94. 94. 94.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.05 0.4750 3.04 0.3354 2.01 0.1976 1.49 0.1308 0.98 0.0693 0.46 0.0067 -0.05 -0.0473 -0.57 -0.1079 -1.09 -0.1711 -1.59 -0.2237	RE PER 1 CM -4.5318 -3.2234 -1.9340 -1.3160 -0.7524 -0.1802 0.3159 0.8633 1.4373 1.9091	IN.= .48E06 3.8665 PSI CS -0.1903 -0.1894 -0.1969 -0.1981 -0.2021 -0.1997 -0.2015 -0.2023 -0.2125 -0.1972 -0.1982 -0.1961	CY CR 1.2371 0.04 1.2430 0.03 1.3372 0.02 1.3576 0.02 1.4009 0.01 1.3874 0.01 1.4018 0.00 1.4163 0.00 1.5212-0.00 1.3694~0.01	DEG.F RUN NO. CAT 81 0.4240 86 0.4163 85 0.4088 23 0.4058 65 0.4049 12 0.4025 67 0.4009 14 0.3966 05 0.3965 07 0.3965 07 0.3965	POJ/PT . 027026 CPB 0.1812 0.1755 0.1728 0.1717 0.1707 0.1693 0.1667 0.1666 0.1675 0.1691	S = 80. 9136 CAF 0.2428 0.2409 0.2361 0.2341 0.2342 0.2322 0.2316 0.2309 0.2299 0.2299 0.2289 0.2274	94. 94. 94. 94. 94. 94. 94. 94.

MOD	EL 946.2	CON	IG. 2.450	14	NCH 1-75	5 .	PHI =	90.	
Q=	8.29 PSI	RE FER	IN.= .48E0	5 TO=	90. DE	G.F	PÛJ/P	rs =	•
P0=	107.0 CM	HG PTS=	3.8665 PSI			RUN NO	02702	69 <u>1</u> 37	
ALPHA	CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
4.07	0.5045	-4.7668	-0.0312	0.2970	0.0029	0.3957	0.1625	C-2333	95.
3.05	0.3763	-3.5545	-0.9257	0.2384	0.0036	0-3899	0.1590	9-2309	95.
2.03	0.2489	-2.3481	-0.0235	0.2161	0.0038	0.3855	0.1597	0.2258	95.
1.51	0.1816	-1.7133	~0.0271	·0.2513	0.0042	0.3854	0.1612	0.2241	95.
	0.1210	-1.1402	-0.0285		0.0033				
	0.0583	-0.5499			0.0029				
	-0,0023		-0.0276		0.0035				
	-0.0646	0+6094	-0.0284		0.0034				
	-0-1245		-0.0280		0.0037				
	-0-1,872		-0.0327		0.0039				
	-0.2474		-0.0328		0.0044				
	-0.3742		-0.0345		0.0051				
-4.09	-0.5056	4.7762	~0 . 0383	0.3651	0.0058	0.3710	0.1564	0.2146	95.
	EL 946.2 8.29 PSI		FIG. 2.450		ACH 1.75		PHI =	90. FS ≟	10
Q=	8-29 PSI	RE PER		6 TO=		G-F	****	rs ≟	10
Q=	8-29 PSI	RE PER	IN.= .48E0	6 TO=		G-F	20J/P	rs ≟	RUN
Q= PO= Alpha	8.29 PSI 107.0 CM	RE PER HG PTS=	IN-= .48E0 3.8665 PSI	S T0=	90. DE	EG.F RUN NO	POJ/P 027020 CPB	FS = 69138 CAF	RUN
Q= PO= ALPHA 4.07	8:29 PSI 107:0 CM CN 0:4963	RE PER HG PTS= CM -4.6580	IN.= .48E06 3.8665 PSI CS -0.0284	6 TO= CY 0.1824	90. DE CR 0.0152	G.F RUN NO CAT 0.3922	POJ/P 027020 CPB 0.1609	FS = 69138 CAF 0.2312	RUN 964
Q= PO= ALPHA 4.07 3.06	8.29 PSI 107.0 CM CN 0.4963 0.3681	RE PER HG PTS= CM -4.6580 -3.4480	IN-= .48E06 3.8665 PSI CS -0.0284 -0.0340	CY 0.1824 0.2390	90. DE CR 0.0152 0.0141	G.F RUN NO. CAT 0.3922 0.3885	POJ/P 027020 CPB 0.1609 0.1571	FS = 69138 CAF 0.2312 0.2324	RUN 96.
Q= PO= ALPHA 4.07 3.06	8:29 PSI 107:0 CM CN 0:4963	RE PER HG PTS= CM -4.6580	IN.= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397	CY 0.1824 0.2390 0.3026	90. DE CR 0.0152	CAT 0.3922 0.3885 0.3856	POJ/P 027020 CPB 0.1609 0.1571 0.1596	FS = 69138 CAF 0.2312 0.2324 0.2260	RUN 96. 96.
Q= PO= ALPHA 4.07 3.06 2.03 1.51	8.29 PSI 107.0 CM CN 0.4963 0.3681 0.2424 0.1775	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621	IN-= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366	CY 0.1824 0.2390 0.3026 0.2723	90. DE CR 0.0152 0.0141 0.0099	CAT 9.3922 0.3885 0.3856 0.3854	POJ/P 027020 CPB 0.1609 0.1571 0.1596 0.1614	FS = 69138 CAF 0.2312 0.2384 0.2260	RUN 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00	8:29 PSI 107:0 CM CN 0:4963 0:3681 0:2424	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704	IN-= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388	CY 0.1824 0.2390 0.3026 0.2723 0.2976	90. DE CR 0.0152 0.0141 0.0099 0.0081	CAT 0.3922 0.3885 0.3856 0.3854	POJ/P 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1621	FS = 69138 CAF 0.2312 0.2324 0.2260 0.2240 0.2226	RUN 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50	8.29 PSI 107.0 CM CN 0.4953 0.3681 0.2424 0.1775 0.1169	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.0952 -0.5199	IN-= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388	CY 0.1824 0.2390 0.3026 0.2723 0.2976 0.2985	90. DE CR 0.0152 0.0141 0.0099 0.0081	CAT 0.3922 0.3855 0.3854 0.3854 0.3854	POJ/P . 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1621 0.1626	FS = 59138 CAF 0.2312 0.2314 0.2260 0.2240 0.2226	RUN 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50 -0.02	8.29 PSI 107.0 CM CN 0.4963 0.3681 0.2424 0.1775 0.1169 0.0553	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.0952 -0.5199 0.0342	IN-= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388 -0.0389	CY 0.1824 0.2390 0.3026 0.2723 0.2976 0.2985 0.3328	90. DE CR 0.0152 0.0141 0.0099 0.0081 0.0066 0.0051	CAT 9.3922 0.3855 0.3854 0.3854 0.3854 0.3851 0.3825	POJ/P 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1621 0.1626 0.1623	FS = 59138 CAF 0.2312 0.2312 0.2260 0.2260 0.2226 0.2205 0.2205	RUN 96. 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50 -0.02 -0.52 -1.05	8.29 PSI 107.0 CM CN 0.4963 0.3681 0.2424 0.1775 0.1169 0.0553 -0.0039 -0.0653 -0.1273	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.0952 -0.5199 0.0342 0.6092 1.1893	IN.= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388 -0.0389 -0.0424 -0.0380 -0.0408	CY 0.1824 0.2390 0.3026 0.2723 0.2976 0.2985 0.3328 0.2868 0.3152	90. DE CR 0.0152 0.0141 0.0099 0.0081 0.0066 0.0051 0.0036 0.0025 0.0007	CAT 0.3922 0.3885 0.3854 0.3854 0.3825 0.3802 0.38775	POJ/P . 027020 CPB 0.1609 0.1571 0.1576 0.1614 0.1621 0.1626 0.1623 0.1620 0.1600	FS = 59138 CAF 0.2312 0.2314 0.2260 0.2226 0.2205 0.2202 0.2182 0.2175	RUN 96. 96. 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50 -0.02 -0.52 -1.05 -1.56	8.29 PSI 107.0 CM CN 0.4953 0.3681 0.2424 0.1775 0.1169 0.0553 -0.0039 -0.0653 -0.1273 -0.1889	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.05199 0.0342 0.6092 1.1893 1.7654	IN.= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388 -0.0389 -0.0424 -0.0380 -0.0408 -0.0429	CY 0.1824 0.2390 0.3026 0.2723 0.2785 0.2985 0.3328 0.2868 0.3152 0.3364	90. DE CR 0.0152 0.0141 0.0099 0.0081 0.0051 0.0036 0.0025 0.0007	CAT 0.3922 0.3885 0.3856 0.3854 0.3854 0.3825 0.3802 0.3775 0.3781	POJ/P . 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1626 0.1623 0.1620 0.1600 0.1582	FS = 59138 CAF 0.2312 0.2324 0.2226 0.2226 0.2205 0.2182 0.2175	RUN 96. 96. 96. 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50 -0.02 -0.52 -1.05 -1.56 -2.06	8.29 PSI 107.0 CM CN 0.4953 0.3681 0.2424 0.1775 0.1169 0.0553 -0.0039 -0.0653 -0.1273 -0.1889 -0.2467	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.0952 -0.5199 0.0342 0.6092 1.1893 1.7654 2.3069	IN.= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388 -0.0424 -0.0380 -0.0408 -0.0408 -0.0429 -0.0417	CY 0.1824 0.2390 0.3026 0.2723 0.2976 0.2985 0.3328 0.3864 0.3152 0.3364 0.3229	90. DE CR 0.0152 0.0141 0.0099 0.0081 0.0066 0.0051 0.0036 0.0025 0.0007 0.	CAT 0.3922 0.3885 0.3856 0.3854 0.3854 0.3825 0.3802 0.3775 0.3781 0.3753	POJ/P 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1621 0.1620 0.1620 0.1600 0.1582 0.1562	CAF 0.2312 0.2314 0.2260 0.2226 0.2205 0.2205 0.2182 0.2175 0.2199	RUN 96. 96. 96. 96. 96. 96. 96. 96.
Q= P0= ALPHA 4.07 3.06 2.03 1.51 1.00 0.50 -0.02 -1.56 -1.56 -2.06 -3.08	8.29 PSI 107.0 CM CN 0.4953 0.3681 0.2424 0.1775 0.1169 0.0553 -0.0039 -0.0653 -0.1273 -0.1889	RE PER HG PTS= CM -4.6580 -3.4480 -2.2704 -1.6621 -1.0952 -0.5199 0.0342 0.6092 1.1893 1.7654 2.3069 3.4761	IN.= .48E06 3.8665 PSI CS -0.0284 -0.0340 -0.0397 -0.0366 -0.0388 -0.0389 -0.0424 -0.0380 -0.0408 -0.0429	CY 0.1824 0.2390 0.3026 0.2723 0.2976 0.2985 0.3328 0.2868 0.3152 0.3364 0.3229 0.3929	90. DE CR 0.0152 0.0141 0.0099 0.0081 0.0051 0.0036 0.0025 0.0007	CAT 0.3922 0.3885 0.3856 0.3854 0.3846 0.3825 0.3875 0.3775 0.3781 0.3753 0.3753	POJ/P 027020 CPB 0.1609 0.1571 0.1596 0.1614 0.1621 0.1626 0.1623 0.1600 0.1582 0.1562 0.1562	CAF 0.2312 0.2314 0.2260 0.2226 0.2205 0.2202 0.2185 0.2199 0.2186	RUN 96. 96. 96. 96. 96. 96. 96. 96. 96.

XODEL 946.2	CONFIG. 2.4	50 MACH 1.75	PHI = 90.	
Q= 8.29 PSI	RE PER IN.= .48	E06 TO= 90. DEG.F	POJ/PTS = 20.	
PO= 107.0 CM	IHG PTS= 3.8665 P	SI RUN N	0. 0270269139	
ALPHA CN	CH CS	CÝ CR CAT	CPB CAF	RUN
4.07 0.4855	-4.5090 -0.0368	0.1689 0.0361 0.394	8 0-1613 0-2335	97.
3.06 0.3616	-3.3572 -0.0527	0.3426 0.0289 0.390	7 0.1590 0.2317	97.
2.04 0.2404	-2.2357 -0.0453	0.2816 0.0179 0.388		97.
1.52 0.1749	~1.6272 -0.0599	0.4307 0.0126 0.388		97.
1.01 0.1149	-1.0710 -0.0633	0.4650 0.0085 0.387		97.
-0.02 ~0.0049	0.0415 -0.0584	0.4184 0.0047 0.384		97.
-0.53 -0.0652	0.6029 ~0.0579	0.4118 0.0020 0.383		97.
-1.05 -0.1262	1.3693 -0.0510	0.3433-0.0014 0.383		97.
-1.55 -0.1872	1.7377 -0.0590	0.4203-0.0032 0.379		97.
-2.06 -0.2447	2.2715 -0.0623	0.4495-0.0053 0.377		97.
-3.09 -0.3561	3.3938 -0.0550	0.3643-0.0125 0.376		97.
-4.10 -0.4892	4-5326 -0.0509	0.3240-0.0209 0.375	9 0-1592 0-2167	97.
MODEL 946.2 Q= 8.29 PSI	CONFIG. 2.4		PHI = 20. POJ/PTS = 40.	
PO= 107.0 CM	HG PTS= 3.8665 P	SI RUN N	0. 0270269140	
ALPHA CN	CM CS	CY CR CAT	CPB CAF	RUN
4.08 0.4869	-4.4913 -0.0859	0-5037 0-0445 0-402	3 0.1672 0.2350	98.
3.06 0.3618	-3.3365 -0.0902	0.5612 0.0331 0.396		98.
2.04 0.2393	-2.2058 -0.1076	0.6936 0.0225 0.393	9 0-1646 0-2292	98.
1.52 0.1755	-1.6167 -0.1044	0.7229 0.0164 0.393		98.
1.01 0.1166	-1.0762 -0.1039	0.7222 0.0117 0.392	3 0.1672 0.2252	98.
0.49 0.0556	-0.5146 -0.1686	0.7712 0.0085 0.391	0 0-1680 0-2230	98.
-0.03 -0.0040	0.0365 -0.1068	0.7502 0.0053 0.387	6 0.1675 0.2201	98.
-0.53 -0.0629	0.5783 -0.1161	0-8444 0-0003 0-388		98.
-1.04 -0.1233	1.1356 -0.1059	0.7397-0.0020 0.388		98.
-1.56 -0.1829	1.6844 -0.1099	0.7773-0.0058 0.386		98.
-2.06 -0.2404	2.2127 -0.1068	0.7418-0.0104 0.384		98.
-3.09 -0.3625	3.3359 -0.1028	0.6898-0.0191 0.384		98.
-4-11 -0.4864	4.4743 -0.0942	0.5896-0.0306 0.384	9 0.1679 0.2170	98.

н	ODEL	946.2		CON	FIG.	2,450	M	ACH 1-7	5	PHI =	90.		
Q	= 8.2	29 PSI	RE	PER	IN.=	.48E06	T0=	90. D	EG.F	90J/p	T\$ =	80.	
P	0= 10	07.0-CH	HG I	PTS=	3.86	65 PS1			RUN NO.	. 02702	69141		
ALPH	A	CN	CI	M	C	S	CY	CR	CAT	СРВ	CAF		RUN
4.0		4989	-4.	5784	-0.1	924	1.2601	0.0516	0.4170	0-1778	0.2392	2	99.
3.0		.3644			-0.1				0.4098				99.
2.0	_	.2365			-0.2)90			0.4057				99.
1.5		.1713			-0.2				0.4037				99•
1.0		.1116			-0.2				0.3996				99.
0.4		.0530			-0:2				0.3989				99.
	-	•0035			-0.2				0.3997				59.
-		.0621			-0.2				0.3976				99.
		.1225			-0.2				0.3968				99.
		1807			-0.2				0.3952				99.
		-2386			-0.2				0.3967				99•
	-	.3653 .4976			-0.2				0.3972				99.
-4.1	2 -0.	.4710	4.	2477	-0.2	OT t.	1.3508.	-0-0393	0.3976	0-1121	0.2223	•	99.
		946.2				000.£		ACH 1.75		PHI =	•		
		946.2 29 PSI				3.000 .48E06		NCH 1.7!		PHI =		•	
0	= 8.2		RE.	PER	IN.≃	.48E06			EG.F		rs =	•	
0	= 8.2 0= 10	29 PSI	RE.	PER PTS=	IN.≃	.48E06			EG.F	POJ/PI	rs =	•	RUN
Q P Alph	= 6.2 0= 10 A	29 PSI 07:0 CMI	RG HG I	PER PTS=	IN.≃ 3.86	.48E06	T0=	90. DE	EG.F RUN NO.	POJ/P1 . 027020 CPB	TS = 69142 CAF	•	RUN 100•
Q P Alph	= 6.2 0= 10 A 3 Q	29 PSI 07.0 CM	RE HG I CI	PER PTS= 4 3196	IN.≈ 3.860 C:	.48E06 55 PSI 5	T0= CY 0.2203	90. DE	EG.F RUN NO. CAT	POJ/P1 . 027020 CPB 0.1641	TS = 69142 CAF 0.2559		
Q P ALPH 4.0	= 6.2 0= 10 A 3 0.	29 PSI 07.0 CMI CN .6344	RE HG I CI -6.1	PER PTS= 4 3196 5990	IN.≈ 3.866 C: -0.0	.48E06 55 PSI 5 194 279	CY 0.2203 0.2994	90. D8 CR 0.0036 0.0029	EG.F RUN NO. CAT 0.4200	POJ/P1 . 027026 CPB 0.1641 0.1631	TS = 69142 CAF 0.2559 0.2575	-	100.
P ALPH 4.0 3.0 2.0	= 6.2 0= 10 A 3 0.2 2 0.1	29 PSI D7.0 CMI CN .6344 .4717	RE HG I	PER PTS= 4 3196 5990 1138	IN.= 3.866 C: -0.0: -0.0:	.48E06 55 PSI 5 194 279 311	CY 0.2203 0.2994 0.3355	90. DE CR 0.0036 0.0029 0.0026	EG.F RUN NO. CAT 0.4200 0.4205	POJ/PT . 027020 CPB 0.1641 0.1631 0.1649	TS = 69142 CAF 0.2559 0.2575	-	100.
PALPH 4.0 3.0 2.0 1.4	= 6.2 0= 10 A 3 0.2 1 0.3 9 0.8	29 PSI 07.0 CMI CN .6344 .4717 .3129	RE HG I -6.3 -4.6 -3.1 -2.6	PER PTS= 1 3196 5990 1138 2589 4891	1N.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356	CY 0.2203 0.2994 0.3355 0.3730 0.3752	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0027	EG.F RUN NO. CAT 0.4200 0.4205 0.4250 0.4254 0.4269	POJ/PT . 027020 CPB 0.1641 0.1631 0.1649 0.1668 0.1487	CAF 0.2559 0.2575 0.2600 0.2585	; - } ;	100. 100. 100. 100.
ALPH 4.0 3.0 2.0 1.4 0.9	= 5.4 0= 10 A 3 0. 2 0. 1 0. 9 0. 8 0. 8 0.	29 PSI O7.0 CM CN .6344 .4717 .3129 .2270 .1495	RE HG I -6.3 -4.6 -3.1 -2.6 -1.4	PER PTS= 4 3196 5990 1138 2589 4891 7310	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	•48E06 55 PSI 194 279 311 356 354	T0= CY 0.2203 0.2994 0.3355 0.3730 0.3752 0.3854	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0027 0.0019	CAT 0.4200 0.4205 0.4250 0.4254 0.4269 0.4270	POJ/PT . 027026 CPB 0.1641 0.1649 0.1668 0.1687 0.1697	TS = 69142 CAF 0.2559 0.2575 0.2600 0.2585 0.2582 0.2573	; - } ;	100. 100. 100. 100.
ALPH 4.0 3.0 2.0 1.4 0.9 0.4 -0.0	= 5.4 0= 10 A 3 0. 2 0. 1 0. 9 0. 8 0. 8 0. 4 -0.	29 PSI O7.0 CM 6344 4717 3129 2270 1495 0733	RE CHG II	PER PTS= 3196 5990 1138 2589 4891 7310	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356 354 363 400	T0= CY 0.2203 0.2994 0.3355 0.3730 0.3752 0.3854 0.4202	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0019 0.0016	CAT 0.4200 0.4205 0.4250 0.4254 0.4269 0.4270 0.4266	POJ/PT . 027026 CPB 0-1641 0-1631 0-1649 0-1668 0-1687 0-1697	CAF 0.2559 0.2573 0.2600 0.2585 0.2582 0.2573	; - ; ; ;	100. 100. 100. 100. 100.
P ALPH 4.0 3.0 2.0 1.4 0.9 0.4 -0.0	= 6.4 0= 10 A 3 0 2 0 1 0 9 0 8 0 8 0 8 0 4 -0	29 PSI O7.0 CM .6344 .4717 .3129 .2270 .1495 .0733 .0048	RE CHG II	PER PTS= 4 3196 5990 1138 2589 4891 7310 2464 8106	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356 354 363 400 409	T0= CY 0.2203 0.2994 0.3355 0.3752 0.3752 0.3854 0.4202 0.4311	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0019 0.0016 0.0017	CAT 0.4200 0.4200 0.4250 0.4254 0.4269 0.4270 0.4266 0.4254	POJ/PT . 027026 CPB 0.1641 0.1649 0.1668 0.1687 0.1697 0.1690	CAF 0.2559 0.2575 0.2600 0.2585 0.2582 0.2573 0.2566	- - - - - -	100. 100. 100. 100. 100. 100.
P ALPH 4.0 3.0 2.0 1.4 0.4 -0.0 -0.5 -1.0	= 6.4 0= 10 A 3 0 2 0 1 0 9 0 8 0 8 0 8 0 4 -0 5 -0	29 PSI O7.0 CM 6344 4717 3129 2270 1495 0733 0048 0816	RE -6.3 -4.6 -3.3 -2.6 -1.4 -0.5 0.6 0.8 1.6	PER PTS= 3196 5990 1138 2589 4891 7310 2464 8106 5174	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356 354 363 400 409 433	T0= CY 0.2203 0.2395 0.3750 0.3752 0.3854 0.4202 0.4311 0.4551	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0019 0.0016 0.0017 0.0011	CAT 0.4200 0.4205 0.4250 0.4254 0.4266 0.4254 0.4254	POJ/PT . 027026 CPB 0.1641 0.1631 0.1649 0.1668 0.1687 0.1700 0.1690 0.1682	CAF 0.2559 0.2575 0.2600 0.2582 0.2573 0.2566 0.2565		100. 100. 100. 100. 100. 100.
Q P ALPH 4.0 3.0 2.0 1.4 0.9 0.4 -0.0 -0.5 -1.0	= 6.4 0= 10 A 3 0. 2 0. 1 0. 9 0. 8 0. 8 0. 4 -0. 5 -0. 6 -0.	29 PSI O7.0 CM 6344 4717 3129 2270 1495 0733 0048 0816 1622	RE -6.3 -4.6 -3.1 -2.3 -1.4 -0.5 0.6 2.3	PER PTS= 3196 5990 1138 2589 4891 7310 2464 8106 5174 3554	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356 354 363 400 409 433 438	T0= CY 0.2203 0.2994 0.3355 0.3750 0.3752 0.3854 0.4202 0.4311 0.4551 0.4627	90. D8 CR 0.0036 0.0029 0.0027 0.0027 0.0019 0.0016 0.0017 0.0011	CAT 0.4200 0.4205 0.4250 0.4259 0.4266 0.4254 0.4236	POJ/PT . 027026 CPB 0.1641 0.1631 0.1649 0.1669 0.1687 0.1700 0.1690 0.1682 0.1696	CAF 0.2559 0.2575 0.2600 0.2585 0.2573 0.2566 0.2565 0.2554		100. 100. 100. 100. 100. 100. 100.
P ALPH 4.0 3.0 2.0 1.4 0.9 0.4 -0.0 -0.5 -1.5 -2.0	= 6.4 0= 10 A 3 0. 1 0. 9 0. 8 0. 4 -0. 5 -0. 6 -0. 6 -0.	29 PSI D7.0 CMI CN .6344 .4717 .3129 .2270 .1495 .0733 .0048 .0816 .1622 .2364	RE -6.3	PER PTS= 3196 5138 25891 7310 2464 8106 5174 3554 1080	IN.= 3.866 C: -0.00.02 -0.03 -0.04 -0.04 -0.04 -0.04 -0.04 -0.04	.48E06 55 PSI 194 279 311 356 354 360 400 433 438 490	CY 0.2203 0.2994 0.3355 0.3730 0.3752 0.3854 0.4202 0.4311 0.4551 0.4627 9.5096	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0019 0.0016 0.0017 0.0015 0.0010	CAT 0.4200 0.4205 0.4250 0.4254 0.4269 0.4270 0.4266 0.4236 0.4211 0.4192	POJ/PI 027026 CPB 0.1641 0.1631 0.1649 0.1668 0.1687 0.1690 0.1692 0.1696 0.1697	CAF 0.2559 0.2575 0.2600 0.2585 0.2573 0.2566 0.2565 0.2554 0.2514		100. 100. 100. 100. 100. 100. 100. 100.
P ALPH 4.0 3.0 2.0 1.4 0.9 0.4 -0.0 -0.5 -1.5 -2.0 -3.0	= 6.4 0= 10 A 3 0. 2 0. 11 0. 9 0. 8 0. 8 0. 4 -0. 4 -0. 6 -0. 6 -0. 7 -0.	29 PSI O7.0 CM 6344 4717 3129 2270 1495 0733 0048 0816 1622	RE HG II	PER PTS= 4 3196 5138 2589 47310 73464 8106 5174 3554 1084	IN.= 3.866 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E06 55 PSI 194 279 311 356 354 363 400 403 433 438 490 525	CY 0.2203 0.2994 0.3355 0.3750 0.3752 0.3854 0.4202 0.4311 0.4527 0.5090 0.5442	90. D8 CR 0.0036 0.0029 0.0026 0.0027 0.0019 0.0016 0.0017 0.0011 0.0010 0.0011	CAT 0.4200 0.4205 0.4250 0.4259 0.4266 0.4254 0.4236	POJ/PT O27026 CPB 0.1641 0.1631 0.1649 0.1668 0.1687 0.1700 0.1690 0.1696 0.1697 0.1692	CAF 0.2559 0.2575 0.2600 0.2585 0.2582 0.2573 0.2566 0.2555 0.2514		100. 100. 100. 100. 100. 100. 100.

Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 10. PO= 107.0 CMHG PTS= 3.8665 PSI RUN NO. 0270269143 ALPHA CN CM CS CY CR CAY CPB CAF RUN 4.02 0.6223 -6.2752 -0.0212 0.2404 0.0044 0.4283 0.1674 0.2609 101. 3.01 0.4608 -4.6637 -6.0223 0.2507 0.0036 0.4247 0.1659 0.2587 101. 2.0G 0.2988 -3.0445 -0.0319 0.3464 0.0022 0.4279 0.1672 0.2607 101. 1.48 0.21.75 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 101. -0.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 101. -0.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 101. -1.05 -0.1743 1.6708 -0.0433 c.4668 0.0007 0.4272 0.1697 0.2574 101. -1.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 101. -2.07 -0.3246 3.1703 -0.0490 0.5237 0.0088 0.4207 0.1699 0.2509 101. -3.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101. -4.09 -0.6499 6.4120 -0.0604 0.6345 0.0004 0.4151 0.1688 0.2463 101.
ALPHA CN CH CS CY CR CAT CPB CAF RUN 4.02 0.6223 -6.2752 -0.0212 0.2404 0.0044 0.4283 0.1674 0.2609 101. 3.01 0.4608 -4.6637 -G.0223 0.2507 0.0036 0.4247 0.1659 0.2587 101. 2.06 0.2988 -3.0445 -0.0319 0.3464 0.0022 0.4279 G.1672 0.2607 101. 1.48 0.2175 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 101. -0.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 101. -0.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 101. -1.05 -0.1743 1.6708 -0.0433 0.4668 0.0007 0.4272 0.1697 0.2574 101. -1.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 101. -2.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 101. -3.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
4.02 0.6223 -6.2752 -0.0212 0.2404 0.0044 0.4283 0.1674 0.2609 101. 3.01 0.4608 -4.6637 -C.0223 0.2507 0.0036 0.4247 0.1659 0.2587 101. 2.06 0.2988 -3.0445 -0.0319 0.3464 0.0022 0.4279 0.1672 0.2607 101. 1.48 0.2175 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 1010.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 1010.55 -0.0936 0.8670 -0.0424 0.4535 0.010 0.4283 0.1712 0.2571 1011.05 -0.1743 1.6708 -0.0433 0.4668 0.0007 0.4272 0.1697 0.2574 1011.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 1012.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 1013.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
3.01 0.4608 -4.6637 -G.0223 0.2507 0.0036 0.4247 0.1659 0.2587 101. 2.06 0.2988 -3.0445 -0.0319 0.3464 0.0022 0.4279 0.1672 0.2607 101. 1.48 0.2175 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 1010.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 1010.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 1011.05 -0.1743 1.6708 -0.0433 0.4688 0.0007 0.4272 0.1697 0.2574 1011.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 1012.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 1013.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
2.06 0.2988 -3.0445 -0.0319 0.3464 0.0022 0.4279 0.1672 0.2607 101. 1.48 0.2175 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 101. -0.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 101. -0.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 101. -1.05 -0.1743 1.6708 -0.0433 0.4688 0.0007 0.4272 0.1697 0.2574 101. -1.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 101. -2.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 101. -3.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
1.48 0.2175 -2.2336 -0.0321 0.3517 0.0022 0.4288 0.1689 0.2599 101. 0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 1010.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 1010.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 1011.05 -0.1743 1.6708 -0.0433 0.4668 0.0007 0.4272 0.1697 0.2574 1011.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 1012.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 1013.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
0.97 0.1367 -1.4274 -0.0334 0.3661 0.0014 0.4297 0.1702 0.2595 101. 0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 1010.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 1010.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 1011.05 -0.1743 1.6708 -0.0433 0.4668 0.0007 0.4272 0.1697 0.2574 1011.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 1012.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 1013.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
0.46 0.0626 -0.6879 -0.0261 0.3922 0.0020 0.4312 0.1714 0.2597 1010.05 -0.0181 0.1159 -0.0387 0.4180 0.0015 0.4301 0.1717 0.2584 1010.55 -0.0936 0.8670 -0.0424 0.4535 0.0010 0.4283 0.1712 0.2571 1011.05 -0.1743 1.6708 -0.0433 0.4668 0.0007 0.4272 0.1697 0.2574 1011.56 -0.2523 2.4486 -0.0485 0.5162 0.0011 0.4247 0.1696 0.2551 1012.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 1013.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
-0.05 -0.0181
-0.55 -0.0936
-1.05 -0.1743
-1.56 -0.2523
-2.07 -0.3246 3.1703 -0.0490 0.5237 0.0008 0.4207 0.1699 0.2509 101. -3.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
-3.08 -0.4853 4.7707 -0.0536 0.5718 0.0003 0.4166 0.1692 0.2473 101.
-4.09 -0.6499 6.4120 -0.3604 0.6345 0.0004 0.4151 0.1688 0.2463 101.
MODEL 946.2 CONFIG. 3.000 MACH 1.75 PHI = . Q= 8.29 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20.
PO= 107.0 CMHG PTS= 3.8665 PS1 RUN NO. 0270269144
ALPHA CN CM CS CY CR CAT CPB CAF RUN
4.01 0.6068 -6.1891 -0.0192 0.2221 0.0042 0.4385 0.1726 0.2659 102.
3.00 0.4441 -4.5656 -0.0228 0.2631 0.0037 0.4363 0.1715 0.2648 102.
1.99 0.2821 -2.9465 -0.0285 0.3169 0.0029 0.4348 0.1719 0.2629 102.
1.47 0.1994 -2.1224 -0.0308 0.3405 0.0024 0.4351 0.1728 0.2623 102.
0.95 0.1174 -1.3068 -0.0359 0.3903 0.0021 0.4355 0.1735 0.2620 102.
0.45 0.0394 -0.5265 -0.0383 0.4142 0.9016 0.4350 0.1740 0.2610 102.
-0.06 -0.0381
-0.57 -0.1135 0.9964 -0.0443 0.4772 0.0009 0.4327 0.1726 0.2601 102.
-1.07 -0.1910 1.7693 -0.0473 0.5063 0.0001 0.4302 0.1710 0.2591 102 ₀
-1.57 -0.2697 2.5528 -0.0489 0.5267 0.0007 0.4284 0.1710 0.2 573 102.
-2.08 -0.3457 3.3118 -0.0530 0.5687 0.0004 0.4238 0.715 0.2523 102.
-3.10 -0.5064 4.9139 -0.0611 0.6483 0.0003 0.4190 0.1710 0.2480 102.
-4.11 -0.6710 6.5494 -0.0647 0.6857 0.0006 0.4176 0.1697 0.2479 102.

HODEL 94	6.2 CQN	FIG. 3.000	НА	CH 1-75	PHI =	•	
Q= 8.29	PSI RE PER	IN.= .48E0	6 TO=	90. DEG.F	P0J/P1	rs = 40.	
PO= 107.	O CMHG PTS=	3.8665 PSI		RUN	NO. 027026	59145	
ALPHA CN	CM	cs	CÝ	CR CA	СРВ	CAF	RUN
3.98 0.56		-0.0184			486 0.1776		103,
2.97 0.39		-0.0280			485 0.1778		103.
1.96 0.23		-0.0332			472 0.1795		103.
1.44 0.15		-0.0377			455 0-1792		103.
0.93 0.06		-0.0389			437 0.1785		103.
0.42 -0.01		-0.0426			406 0.1778		103.
-0.08 -0.08 -0.59 -0.16		-0.0499 -0.0521			402 0.1772 384 0.1755		103. 103.
-0.39 -0.16 -1.10 -0.24		-0.0521 -C.0530			380 0.1732	2	103.
-1.61 -0.32		-0.0550			336 0.1715		103.
-2.11 -0.39		-0.0535 -0.0622			297 0.1724		103.
-3.12 -0.55		-0.0689			242 0.1728		103.
-4.13 -0.72		-0.0735			235 0.1728		103.
MODEL 94		FIG. 3.000		CH 1.75	PHI =	•	
MODEL 94 Q= 8.29		FIG. 3.000 IN.= .48E0		CH 1.75 90. DEG.F	-		
Q= 8.29		IN.= .48E0	6 T0≐	90. DEG.F	-	'S = 80.	
Q= 8.29	PSI RE PER O CMHG PTS=	IN.= .48E0	6 T0≐	90. DEG.F	POJ/P1	'S = 80.	RUN
Q= 8.29 PO= 107.	PSI RE PER O CMHG PTS= CH	IN.= .48E0 3.8665 PSI	6 TO≄ CY	90. DEG.F RUN CR CA	POJ/P1	S = 80. 9146 CAF	RUN 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29	PSI RE PER 0 CMHG PTS= CH 40 -5.2165	IN.= .48E0 3.8665 PSI CS	6 TO± CY 0.2291 0.3240	90. DEG.F RUN CR CA 0.0086 0.4	POJ/PT NO. 027026 T CPB 626 0.1895 9585 0.1826	S = 80. 9146 CAF 0.2732 0.2759	104 - 104 -
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500	IN.= .48E0 3.8665 PSI CS -0.0207	6 TO# CY 0.2291 0.3240 0.3863	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4	POJ/PI I NO. 027026 IT CPB 626 0.1895 585 0.1826 566 0.1808	S = 80. 9146 CAF 0.2732 0.2759 0.2757	104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362	CY 0.2291 0.3240 0.3863 0.3989-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4	POJ/PT I NO. 027026 IT CPB 1626 0.1895 1585 0.1826 1566 0.1808	S = 80. 9146 CAF 0.2732 0.2759 0.2757 0.2745	104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385	CY 0.2291 0.3240 0.3863 0.3989- 0.4224-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4	POJ/PT I NO. 027026 IT CPB 1626 0.1895 1585 0.1826 1566 0.1808 1549 0.1804	S = 80. 9146 CAF 0.2732 0.2759 0.2757 0.2745 0.2723	104. 104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440	CY 0.2291 0.3240 0.3863 0.3959- 0.4224- 0.4832-	90. DEG.F RUN CR CA 0.0086 0.4 0.0027 0.4 0.0027 0.4 0.0001 0.4 0.0001 0.4	POJ/PT I NO. 027026 IT CP8 1626 0.1895 1585 0.1826 1566 0.1808 1549 0.1816 1539 0.1816	S = 80. 9146 CAF 0.2732 0.2759 0.2757 0.2745 0.2745 0.2723 0.2718	104. 104. 104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440 -0.0476	CY 0.2291 0.3240 0.3863 0.3959- 0.4224- 0.4832- 0.5237-	90. DEG.F RUN CR CA 0.0086 0.4 0.0027 0.4 0.0027 0.4 0.0001 0.4 0.0032 0.4 0.0032 0.4	POJ/PT I NO. 027026 T CP8 1626 0.1895 1585 0.2826 1566 0.1808 1549 0.1804 1539 0.1816 1522 0.1803	CAF 0.2732 0.2759 0.2757 0.2745 0.2723 0.2718 0.2706	104. 104. 104. 104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23 -0.65 -0.28	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188 41 2.2580	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440 -0.0476 -0.0563	CY 0.2291 0.3240 0.3863 0.3989- 0.4224- 0.4832- 0.5237- 0.6109-	90. DEG.F RUN CR CA 0.0086 0.4 0.0027 0.4 0.0021 0.4 0.0001 0.4 0.0032 0.4 0.0032 0.4 0.0040 0.4	POJ/PT I NO. 027026 IT CP8 0626 0.1895 0585 0.1826 0566 0.1808 0549 0.1816 0522 0.1803 0491 0.1784	CAF 0.2732 0.2759 0.2757 0.2745 0.2745 0.2723 0.2718 0.2706 0.2705	104. 104. 104. 104. 104. 104.
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23 -0.65 -0.28 -1.16 -0.36	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188 41 2.2580 41 3.0560	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0362 -0.0385 -0.0440 -0.0476 -0.0563 -0.0597	CY 0.2291 0.3240 0.3863 0.3989- 0.4224- 0.4832- 0.5237- 0.6109- 0.6466-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4 0.0001 0.4 0.0002 0.4 0.0032 0.4 0.0032 0.4 0.0065 0.4 0.0065 0.4 0.0079 0.4	POJ/P1 I NO. 027026 IT CPB 0626 0.1895 0585 0.1826 0566 0.1808 0549 0.1804 0522 0.1803 0491 0.1784 0468 0.1762	CAF 0.2732 0.2759 0.2757 0.2745 0.2745 0.2723 0.2718 0.2706 0.2705 0.2706	104 - 104 - 104 - 104 - 104 - 104 - 104 - 104 -
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23 -0.65 -0.28 -1.16 -0.36 -1.66 -0.44	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188 41 2.2580 41 3.0560 21 3.8338	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440 -0.0476 -0.0563 -0.0597 -0.0606	CY 0.2291 0.3240 0.3863 0.3989- 0.4224- 0.5237- 0.6109- 0.6466- 0.6598-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4 0.0002 0.4 0.00032 0.4 0.0005 0.4 0.0065 0.4 0.0079 0.4 0.0079 0.4	POJ/PI NO. 027026 T CPB 626 0.1895 556 0.1808 549 0.1804 539 0.1816 522 0.1803 491 0.1784 468 0.1762	CAF 0.2732 0.2759 0.2757 0.2745 0.2745 0.2718 0.2706 0.2705 0.2706 0.2703	104- 104- 104- 104- 104- 104- 104- 104-
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23 -0.65 -0.28 -1.16 -0.36 -1.66 -0.44 -2.16 -0.52	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188 41 2.2580 41 3.0560 21 3.8338 02 4.6142	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440 -0.0476 -0.0563 -0.0597 -0.0606 -0.0653	CY 0.2291 0.3240 0.3863 0.3989- 0.4224- 0.5237- 0.6109- 0.6598- 0.7060-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4 0.0002 0.4 0.0040 0.4 0.0065 0.4 0.0079 0.4 0.0079 0.4 0.0079 0.4 0.0078 0.4	POJ/PT NO. 027026 T CPB 626 0.1895 5585 0.1826 566 0.1808 549 0.1804 539 0.1816 522 0.1803 491 0.1784 468 0.1762 437 0.1731 405 0.1702	S = 80. 9146 CAF 0.2732 0.2759 0.2757 0.2745 0.2723 0.2718 0.2705 0.2705 0.2705 0.2705	104 - 104 - 104 - 104 - 104 - 104 - 104 - 104 - 104 - 104 -
Q= 8.29 PO= 107. ALPHA CN 3.92 0.46 2.92 0.29 1.90 0.12 1.38 0.04 0.87 -0.04 0.36 -0.12 -0.14 -0.23 -0.65 -0.28 -1.16 -0.36 -1.66 -0.44	PSI RE PER 0 CMHG PTS= CM 40 -5.2165 76 -3.5500 64 -1.8389 24 -1.0018 09 -0.1703 22 0.6424 02 1.4188 41 2.2580 41 3.0560 21 3.8338 02 4.6142 83 6.1842	IN.= .48E0 3.8665 PSI CS -0.0207 -0.0300 -0.0360 -0.0362 -0.0385 -0.0440 -0.0476 -0.0563 -0.0597 -0.0606	CY 0.2291 0.3240 0.3863 0.3989- 0.4224- 0.5237- 0.6109- 0.6466- 0.6598- 0.7060- 0.7692-	90. DEG.F RUN CR CA 0.0086 0.4 0.0064 0.4 0.0027 0.4 0.0001 0.4 0.0032 0.4 0.0032 0.4 0.0079 0.4 0.0079 0.4 0.0079 0.4 0.0078 0.4 0.0078 0.4	POJ/PI NO. 027026 T CPB 626 0.1895 556 0.1808 549 0.1804 539 0.1816 522 0.1803 491 0.1784 468 0.1762	S = 80. 9146 CAF 0.2732 0.2759 0.2757 0.2745 0.2723 0.2718 0.2706 0.2705 0.2705 0.2705 0.2705 0.2705 0.2630	104- 104- 104- 104- 104- 104- 104- 104-

MÚDEL 946.2	CONI	FIG. 3.000	H/	ACH 1.7	5	PKI =	45.	
Q= 8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	601/6	rs =	•
P0= 107.0 C	MHG PYS=	3.8665 PSI			RUN NO.	. <u>0</u> 2702	69147	
ÂLPHA CN	CH	CS	CY	CR	CAT	СРВ	CAF	RUN
6-12 0-6562	-6.5284	-0.0407	0.4254	0.0034	6.4400	0.1677	0.2722	105.
3.12 0.4885	-4.8592	~0.0488	0.5076	0.0022	0.4360	0.1662	0.2698	105.
2.10 0.3297	-3.2759	-0.0466			0.4352			
1.59 0.2448	-	-0.0469			0.4335			
1:08 0:1661		-0.0477			0.4311			
0.56 0.0865		-0.0487			0.4314			
0.05 0.0094		-0.0492			0.4277			
-0.45 -0.0701		-0.0493			0.4260			
-0.95 -0.1473		-0.0508			0.4236			
-1.46 -0.2252		-0.0423			0.4210			
-1.97 -0.2983		-0.0459			0.4186			
-2.98 -0.4612		-0.0486			0.4132			
-3.99 -0.6258	5.2236	-0.0452	0.4825	0.0020	0.4203	0.1733	0.2370	105.
NODEL 946.2		FIG. 3.000		AČH 1.79		PHI =		10.
Q= 8.29 PS1	RE PER	IN.= .48E0	6 T0≃	90. DI	EG.F	P0 J/ P	rs =	10.
	RE PER	IN.= .48E0	6 T0≃		EG.F	_	rs =	10.
Q= 8.29 PS1	RE PER	IN.= .48E0	6 T0≃		EG.F	P0 J/ P	rs =	10• RUN
Q= 8.29 PSI PU= 107.0 C	RE PER MHG PTS= CM	IN.= .48E0 3.8665 PSI CS	6 TO≖	90. DI	EG.F RUN NO. CAT	POJ/P 027020	TS = 69148 CAF	RUN
Q= 8.29 PSI PU= 107.0 C ALPHA CN	RE PER MHG PTS= CM -6.4833	IN.= .48E0 3.8665 PSI CS	6 TO≃ CY 0.5718 0.5904	90. DI CR 0.0128 0.0088	EG.F RUN NO. CAT 0.4424 0.4383	POJ/P . 027020 CPB 0.1669 0.1676	TS = 59148 CAF 0.2735 0.2707	RUN 106.
Q= 8.29 PSI PU= 107.0 C ALPHA CN 4.12 0.6474	RE PER MHG PTS= CM -6.4833 -4.8176	IN.= .48E0 3.8665 PSI CS -0.0616	6 TO≃ CY 0.5718 0.5904	90. DI CR 0.0128 0.0088	EG.F RUN NO. CAT 0.4424	POJ/P . 027020 CPB 0.1669 0.1676	TS = 59148 CAF 0.2735 0.2707	RUN 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798	RE PER MMG PTS= CM -6.4833 -4.8176 -3.2379	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626	CY -0.5718 0.5904 0.5928	90. DI CR 0.0128 0.0088 0.0045	EG.F RUN NO. CAT 0.4424 0.4383	POJ/P . 027020 CPB 0.1669 0.1676 0.1672	TS = 59148 CAF 0.2735 0.2707	RUN 106. 196. 106.
Q= 8.29 PSI PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204	RE PER MMG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615	CY -0.5718 0.5904 0.5928 0.6593	90. DI CR 0.0128 0.0088 0.0045 0.0006	EG.F RUN NO. CAT 9.4424 0.4383 0.4361	POJ/P . 027020 CPB 0.1689 0.1676 0.1672 0.1677	TS = 69148 CAF 0.2735 0.2707 0.2689 0.2656	RUN 106. 196. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.8956	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0678 -0.0594 -0.0581	CY -0.5718 0.5718 0.5904 0.5928 0.6593 0.5801 0.5632	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010	CAT 0.4424 0.4383 0.4361 0.4333 0.4327 0.4316	POJ/P . 027020 CP8 0.1669 0.1676 0.1677 0.1687 0.1687	TS = 59148 CAF 0.2735 0.2707 0.2689 0.2656 0.2640 0.2609	RUN 106. 106. 106. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.8956 -0.0571	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0678 -0.0594 -0.0581 -0.0573	CY -0.5718 0.5718 0.5904 0.5928 0.6593 0.5801 0.5632 0.5545	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010 0.0014	CAT 0.4424 0.4381 0.4361 0.4327 0.4316 0.4298	POJ/P . 027020 CP8 0.1659 0.1676 0.1677 0.1687 0.1687 0.1707	TS = 59148 CAF 0.2735 0.2707 0.2689 0.2656 0.2640 0.2609	RUN 106. 106. 106. 106. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005 -0.46 -0.0756	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.9571 0.7081	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0678 -0.0594 -0.0594 -0.0581 -0.0573 -0.0490	CY 0.5718 0.5904 0.5928 0.6593 0.5801 0.5632 0.5545 0.4664	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010 0.0014	CAT 0.4424 0.4383 0.4361 0.4333 0.4316 0.4298 0.4272	POJ/P . 027020 . CP8 0.1669 0.1676 0.1677 0.1687 0.1707 0.1724 0.1730	CAF 0.2735 0.2735 0.2689 0.2656 0.2640 0.2699 0.2575	RUN 106. 106. 106. 106. 106. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005 -0.46 -0.0756 -0.96 -0.1611	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.8956 -0.9571 0.7081 1.5609	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0678 -0.0594 -0.0594 -0.0573 -0.0573 -0.0490 -0.0496	CY 0.5718 0.5904 0.5928 0.6593 0.5801 0.5632 0.5545 0.4664 0.4699	90. DI CR 0.0128 0.0088 0.0045 0.0010 0.0014 0.0019 0.0020	CAT 0.4424 0.4383 0.4361 0.4327 0.4316 0.4298 0.4272 0.4228	POJ/P . 027020 . CPB 0.1669 0.1676 0.1677 0.1677 0.1687 0.1707 0.1724 0.1730 0.1733	TS = 59148 CAF 0.2735 0.2707 0.2689 0.2656 0.2640 0.2699 0.2575 0.2542 0.2495	RUN 106. 106. 106. 106. 106. 106. 106. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005 -0.46 -0.0756 -0.96 -0.1611 -1.47 -0.2412	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6569 -0.9571 0.7081 1.5609 2.3621	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0578 -0.0594 -0.0581 -0.0573 -0.0490 -0.0496 -0.0473	CY 0.5718 0.5904 0.5928 0.6593 0.5632 0.5632 0.5645 0.4664 0.4699 0.4491	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010 0.0014 0.0019 0.0020 0.0022	CAT 0.4424 0.4383 0.4361 0.4337 0.4316 0.4272 0.4228 0.4196	POJ/P . 027020 . CP8 0.1669 0.1670 0.1672 0.1677 0.1707 0.1724 0.1730 0.1733 0.1750	TS = 59148 CAF 0.2735 0.2707 0.2689 0.2656 0.2656 0.2575 0.2542 0.2446	RUN 106. 106. 106. 106. 106. 106. 106. 106.
Q= 8.29 PSI PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005 -0.46 -0.0756 -0.96 -0.1611 -1.47 -0.2412 -1.97 0.3209	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.8956 -0.9571 0.7081 1.5609 2.3621 3.1538	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0594 -0.0594 -0.0573 -0.0573 -0.0490 -0.0496 -0.0473 -0.0509	CY -0.5718 0.5904 0.5928 0.6593 0.5632 0.5632 0.5645 0.4669 0.4699 0.4491 0.4859	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010 0.0014 0.0019 0.0020 0.0022	CAT 0.4424 0.4383 0.4361 0.4333 0.4327 0.4316 0.4278 0.4278 0.4278 0.4186	POJ/P . 027026 . CP8 0.1669 0.1676 0.1677 0.1687 0.1707 0.1724 0.1730 0.1750 0.1756	TS = 69148 CAF 0.2735 0.2707 0.2689 0.2656 0.2640 0.2575 0.2542 0.2446 0.2430	RUN 106. 106. 106. 106. 106. 106. 106. 106.
Q= 8.29 PS1 PU= 107.0 C ALPHA CN 4.12 0.6474 3.11 0.4798 2.10 0.3204 1.58 0.2360 1.06 0.1609 0.56 0.0846 0.05 0.0005 -0.46 -0.0756 -0.96 -0.1611 -1.47 -0.2412	RE PER MHG PTS= CM -6.4833 -4.8176 -3.2379 -2.3995 -1.6565 -0.8956 -0.9571 0.7081 1.5609 2.3621 3.1538 4.7211	IN.= .48E0 3.8665 PSI CS -0.0616 -0.0626 -0.0615 -0.0578 -0.0594 -0.0581 -0.0573 -0.0490 -0.0496 -0.0473	CY -0.5718 0.5904 0.5928 0.6593 0.5632 0.5632 0.5545 0.4664 0.4699 0.4491 0.4859 0.5314	90. DI CR 0.0128 0.0088 0.0045 0.0006 0.0011 0.0010 0.0014 0.0019 0.0020 0.0021 0.0021	CAT 0.4424 0.4383 0.4361 0.4337 0.4316 0.4272 0.4228 0.4196	POJ/P . 027020 CPB 0.1669 0.1676 0.1677 0.1687 0.1707 0.1724 0.1730 0.1730 0.1756 0.1756	TS = 69148 CAF 0.2735 0.2707 0.2689 0.2656 0.2640 0.2575 0.25425 0.2446 0.2430 0.2376	RUN 106. 106. 106. 106. 106. 106. 106. 106.

MO	DEL 946.2	CON	FIG. 3.000	M	ich 1.75	5	PHI =	45.	
Q=	8.29 PSI	RE PER	IN.= .48E0	5 YO=	90. DE	G.F	POJ/P	rs = 20	•
PÇ	= 107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	02702	59149	
ALPHA	CN CN	CH	cs	CY	ER	CAT	СРВ	CAF	RUN
4.11	0.6393	-6.4402	-0.0814	0.7079	0.0188	0.4414	0.1682	0-2733	107.
3.10	0.4749	-4.8224	-0.0756		0.0104				107.
2.09	0.3207		-0.0832		0.0007				107.
1.57		-2.4668	-0.0378		-0.0037				707 =
	0.1595		-0.0841		-0.0055				107.
	0.0709	; -	-0.0799		-0.0023				107.
	-0.0106		-0.0726		0.0007				107.
	-0.0965		-0.0637		0.0052				107.
	-0-1897		-0.0596		0.0075				107.
	-0.2678	2.5935	-0.0584		0.0089				107.
		3.3610			0.0090				107.
	-0.5013		-0.0615		0.0051				107.
-4.01	-0.6621	5.4933	-0.0646	0.5865	0.0005	0.4127	0-1752	0.2316	107.
MO	DEL 946.2	-	FIG. 3.000		ACH 1.75		PHI =	45.	
Q=	8.29 PSI	RE PER	IN.= .48E00	5 TO=	90. DE	EG.F	P0J/P	rs = 40	ł•
PO	= 107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	02702	69150	
ALPHA	CN CN	CH	CS	CY	CR	CAT	CP8	CAF	RUN
4.09	0.6201	-6.3514	-0.1276	1.0621	9.0182	0.4499	0.1717	0.2782	108.
3.08			-0.1338		0.0038				108.
	0.3039		-0.1382		-0.0140				108.
1.55			-0.1443		-0.0216				108.
1.04			-0.1416		-0.0223				108.
0.52	0.0498		-0.1279	1.1381	-0.0148	0.4440	0.1764	0.2677	108.
	-0.0448		-0.1159		-0.0018				108.
	-0.1369		-0.0966	0.7728	3.0097	0.4363	0.1798	0.2566	108.
-0.98	-0.2332	2.1641	-0.0803	0.5898	0.0206	0.4294	0.1801	0.2493	108.
-1.49	-0.3240	3.0828	-0.0739	0.5102	0.0273	0.4242	0.1782	0.2460	108.
-2,00	-0-4032	3-8767	-0.0706	9.4797	0.0292	0.4210	0.1760	0.2450	108.
-3.01	-0.5581	5.4002	-0.0812	0.6054	0.0207	0.4185	0.1740	0.2445	108.
-4.03	30-7141	6.9293	-0.0908	0.7242	0.0084	0.4187	0.1763	0,2424	108.

MODEL 946.2	CONI	FIG. 3:000	MA	ACH 1.75	PHI =	45.	
Ç≂ 8.29. PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	79\L09	·\$ =	80•
P0= 107.0 C	MHG PTS≖	3.8665 PSI		RUN NO	. 027026	9151	
ALPHA -CN	CM	cs	CY	CR CAT	СРВ	CAF	RUN
4.05 0.5717	-6.0966	-0.2294	1.8795	0.0090 0.4672	0.1784	0.2889	.109.
3.04 0.4107		-0.2350		0.0099 0.4674			
2.03 0.2535		-0.2408		-0.0320 0.4628			
1.51 0.1634		-0.2433		-0.0394 0.4586			
0.99 0.0716		-0.2342	-	-0.0376 0.4560			
0.48 -0.0218		-0.2180		0.0255 0.4498			
-0.03 -0.1199		-0.1944		0.0060 0.4481			
-0.52 -0.2255		-0.1708		0.0154 0.4436			
-1.02 -0.3311		-0-1491		0.0365 0.4359			
-1.54 -0.4263		-0.1378		0.0486 0.4318			
-2.03 -0.5105 -3.05 -0.6764		-0.1248		0.0545 0.4284			
-4.07 -0.8255		-0.1274 -0.1346	0.8111	0.0501 0.4251	0.1760	0.2491	109.
-4.01 -0.8233	.1.8080	-0.1-348	0.9109	0.0328 0.4219	-0.1767	0.2452	109.
MODEL 946.2		FIG. 3.000		ACH 1.75	PHI =		
MODEL 946.2 Q= 8.29 PSI		FIG. 3.000 IN.= .48E0		ACH 1.75 90. DEG.F	PHI =		•
	RE PER	IN.= .48E0		90. DES.F	-	'S =	•
Q= 8.29 PSI	RE PER	IN.= .48E0		90. DES.F	P0 J/ PT	'S =	• RUN
Q= 8.29 PSI PO= 107.0 C	RE PER MHG PTS=	IN.= .48E0	6 T0=	90. DES.F RUN NO CR CAT	POJ/PT • 027026 CPB	S = 9152 CAF	
Q= 8.29 PSI PO= 107.0 C ALPHA CN	RE PER MHG PTS= CM -6.6636	IN.= .48E0 3.8665 PSI CS	6 TO= CY 0.5253	90. DEG.F RUN NO	POJ/PT - 027026 CPB 0-1659	S =	RUN
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438	RE PER MHG PTS= CM -6.6636 -5.0330	IN.= .48E0 3.8665 PSI CS -0.0515	6 TO= CY 0.5253 0.4767	90. DES.F RUN NO CR CAT 0.0033 0.4503	POJ/PT . 027026 CPB 0.1659 0.1646	S = .9152 CAF 0.2844 0.2778	110.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464	6 T0= CY 0.5253 0.4767 0.4750	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647	S = .9152 CAF 0.2844 0.2778 0.2732	110.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362	CY 0.5253 0.4767 0.4750 0.4885 0.3764-	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647 0.1652 0.1659	S =	110. 110. 110.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4342	POJ/PT . 027026 CP8 0.1659 0.1646 0.1647 0.1652 0.1659 0.1677	S =	110. 110. 110. 110. 110.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4342 0.0025 0.4330	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647 0.1652 0.1659 0.1677	S =	110. 110. 110. 110. 110.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263 -0.34 -0.0509	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610 C.5071	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381 -0.0439	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975 0.4558	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4340 0.0025 0.4330 0.0018 0.4293	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647 0.1652 0.1659 0.1657 0.1704 0.1723	S =	110. 110. 110. 110. 110. 110.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263 -0.34 -0.0509 -0.85 -0.1298	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610 0.5071 1.2900	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381 -0.0439 -0.0329	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975 0.4558 0.3439	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4340 0.0020 0.4340 0.0025 0.4330 0.0018 0.4293 0.0020 0.4266	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647 0.1652 0.1659 0.1677 0.1704 0.1723 0.1737	S = 9152 CAF 0.2844 0.2778 0.2732 0.2765 0.2565 0.2627 0.2570 0.2529	110. 110. 110. 110. 110. 110. 110.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263 -0.34 -0.0509 -0.85 -0.1298 -1.35 -0.2091	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610 0.5071 1.2900 2.0778	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381 -0.0439 -0.0329 -0.0393	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975 0.4558 0.3439 0.4109	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4340 0.0025 0.4330 0.0018 0.4293 0.0020 0.4228	POJ/PT . 027026 CPB 0.1659 0.1646 0.1647 0.1652 0.1659 0.1657 0.1704 0.1723 0.1737	S = 9152 CAF 0.2844 0.2778 0.2732 0.2715 0.2565 0.2627 0.2570 0.2529 0.2492	110. 110. 110. 110. 110. 110. 110.
Q= 8.29 PSI PO= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263 -0.34 -0.0509 -0.85 -0.1298 -1.35 -0.2091 -1.86 -0.2856	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610 C.5071 1.2900 2.0778 2.8388	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381 -0.0439 -0.0329 -0.0393 -0.0360	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975 0.4558 0.3439 0.4109 0.3771	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4342 0.0025 0.4330 0.0018 0.4293 0.0020 0.4266 0.0024 0.4228 0.0029 0.4189	POJ/PT . 027026 CPB 0.1659 0.1646 0.1652 0.1659 0.1677 0.1704 0.1723 0.1733	CAF 0.2844 0.2778 0.2732 0.2715 0.2681 0.2565 0.2627 0.2570 0.2570 0.2492 0.2457	110. 110. 110. 110. 110. 110. 110. 110.
Q= 8.29 PSI P0= 107.0 C ALPHA CN 4.24 0.6696 3.23 0.5058 2.21 0.3438 1.70 0.2617 1.18 0.1810 0.67 0.1028 0.16 0.0263 -0.34 -0.0509 -0.85 -0.1298 -1.35 -0.2091	RE PER MHG PTS= CM -6.6636 -5.0330 -3.4190 -2.6029 -1.8002 -1.0203 -0.2610 C.5071 1.2900 2.0778 2.8388 4.4276	IN.= .48E0 3.8665 PSI CS -0.0515 -0.0464 -0.0458 -0.0472 -0.0362 -0.0407 -0.0381 -0.0439 -0.0329 -0.0393	CY 0.5253 0.4767 0.4750 0.4885 0.3764- 0.4243 0.3975 0.4558 0.3439 0.4109 0.3771 0.3656	90. DES.F RUN NO CR CAT 0.0033 0.4503 0.0024 0.4424 0.0018 0.4379 0.0008 0.4367 0.0002 0.4340 0.0020 0.4340 0.0025 0.4330 0.0018 0.4293 0.0020 0.4228	POJ/PT . 027026 CPB 0.1659 0.1646 0.1652 0.1659 0.1677 0.1704 0.1723 0.1737 0.1736 0.1733 0.1698	CAF 0.2844 0.2778 0.2732 0.2715 0.2681 0.2565 0.2627 0.2570 0.2529 0.2457 0.2453	110. 110. 110. 110. 110. 110. 110.

KOD	EL 946.2	CONF	FIG. 3.000	, W	ACH 1.75	5	PHI =	90.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	POJ/P	rs =	10.
P0=	107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	. 02702	69153	
ALPHA	CN	ÇN	cs	CY	CR	CAT	CPB	CAF	RUN
4.23	0.6709	-6.6677	-0.0622			0.4544			
3.23	0.5081	-5.0527	-0.0584			0.4472			
2.21	0.3478	-3.4637	-0.0637			0.4422			
1.69	0,2650	-2.6451	-0.0540			0.4388			
1.18	0.1896		-0.0508			0.4369			
0.68		-i .0853	-0.0599			0.4366			
0.17			-0.0606			0.4353			
	-0.0612	0.6119	-0.0497			0.4291			
-0.85	-0.1443	1.4406	-0.0465			0.4264			
-1.36	-0.2226		-0.0497			0.4233			
-1.86	-0.2960	2.9415				0.4198			
-2.87	-0.4550	4.5134	-0.0666			0.4169			
-3.88	-0.6185	6.1323	-0.0713	0.6598	-0.0023	0.4126	0.1704	0.2422	111.
	FL 946.2		FIG. 3.000		ACH 1.7		PHI. =	90.	
			FIG. 3.000 IN.= .48E0		ACH 1.75		PHI =		20.
Q=	8.29 PSI	RE PER		6 TO=		EG.F		rs =	20 . .
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=		EG.F	POJ/P	rs =	•
Q= P0=	8.29 PSI 107.0 CM	RE PER HG PTS=	IM.= .48E0	6 TO=	90. DI	EG.F RUN NO	POJ/P • 027020 CPB	TS = 69154 CAF	RUN
Q= PO= Alpha	8.29 PSI 107.0 CM CN 0.6787	RE PER HG PTS= CM -6.7326	IN.= .48E0 3.8665 PSI	CY 0.5503	90. DI CR 0.0169	EG.F RUN NO CAT	POJ/P • 027020 CPB 0-1710	TS = 6 91 54 CAF 0.2855	RUN 112.
Q= P0= Alpha 4.24	8.29 PSI 107.0 CM CN 0.6787 0.5170	RE PER HG PTS= CM -6.7326 -5.1374	IN.= .48E0 3.8665 PSI CS -0.0683	CY 0.5503 0.6155	90. DI CR 0.0169 0.0097	EG.F RUN NO CAT 0.4566	POJ/P . 027020 CPB 0.1710 0.1681	TS = 69154 CAF 0.2855 0.2808	RUN 112. 112.
Q= P0= ALFHA 4.24 3.23	8.29 PSI 107.0 CH CN 0.6787 0.5170 0.3576	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743	CY 0.5503 0.6155 0.7249	90. Di CR 0.0169 0.0097 0.0022	EG.F RUN NO CAT 0.4566 0.4489	POJ/P . 027020 CPB 0.1710 0.1681 0.1663	TS = 69154 CAF 0.2855 0.2808 0.2765	RUN 112. 112.
Q= P0= ALFHA 4.24 3.23 2.21	8.29 PSI 107.0 CH CN 0.6787 0.5170 0.3576 0.2772	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0843	CY 0.5503 0.6155 0.7249 0.6156	90. DI CR 0.0169 0.0097 0.0022 -0.0025	EG.F RUN NO. CAT 0.4566 0.4489 0.4427	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663	TS = 69154 CAF 0.2855 0.2808 0.2765 0.2744	RUN 112. 112. 112. 112.
Q= P0= ALPHA 4.24 3.23 2.21 1.69	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0843 -0.0738	CY 0.5503 0.6155 0.7249 0.6156 0.7231	90. DI CR 0.0169 0.0097 0.0022 -0.0025 -0.0067	EG.F RUN NO. CAT 0.4566 0.4489 0.4427 0.4407	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663 0.1682	TS = 69154 CAF 0.2855 0.2808 0.2765 0.2744 0.2723	RUN 112. 112. 112. 112.
Q= P0= ALPHA 4.24 3.23 2.21 1.69 1.18	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278 -1.1792	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0843 -0.0738 -0.0842	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153	90. DI CR 0.0169 0.0097 0.0022 -0.0025 -0.0067 -0.0033	CAT 0.4566 0.4489 0.4427 0.4407	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663 0.1682 0.1720	TS = 69154 CAF 0.2855 0.2808 0.2765 0.2744 0.2723 0.2656	RUN 112. 112. 112. 112. 112.
Q= P0= ALPHA 4.24 3.23 2.21 1.69 1.18 0.68 0.17	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278 -1.1792 -0.2420	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0843 -0.0738 -0.0842 -0.0739	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153	90. DI CR 0.0169 0.0097 0.0022 -0.0025 -0.0067 -0.0033 0.0010	CAT 0.4566 0.4489 0.4427 0.4404 0.4376	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663 0.1662 0.1720 0.1742	TS = 69154 CAF 0.2855 0.2806 0.2765 0.2744 0.2723 0.2656 0.2634	RUN 112. 112. 112. 112. 112. 112.
Q= P0= ALPHA 4.24 3.23 2.21 1.69 1.18 0.68 0.17 -0.34	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158 0.0241	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278 -1.1792 -0.2420 0.7337	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0848 -0.0738 -0.0842 -0.0739 -0.0781	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153 0.6555 0.6555	90. DI CR 0.0169 0.0097 0.0022 -0.0067 -0.0033 0.0010 0.0068	CAT 0.4566 0.4489 0.4427 0.4404 0.4376 0.4376	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663 0.1662 0.1720 0.1742 0.1779	CAF 0.2855 0.2855 0.2765 0.2744 0.2723 0.2656 0.2634 0.2542	RUN 112. 112. 112. 112. 112. 112. 112.
Q= P0= ALPHA 4.24 3.23 2.21 1.69 1.69 0.17 -0.34 -0.85	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158 0.0241 -0.0719	RE PER HG PTS= CM -6.732c -5.1374 -3.5690 -2.7815 -2.0278 -1.1792 -0.2420 0.7337 1.5901	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0843 -0.0738 -0.0738 -0.0743	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153 0.6555 0.6555	90. DI CR 0.0169 0.0097 0.0022 -0.0067 -0.0033 0.0010 0.0068 0.0086	CAT 0.4566 0.4489 0.4427 0.4404 0.4376 0.4376 0.4321	POJ/P O27020 CPB 0.1710 0.1681 0.1663 0.1663 0.1662 0.1720 0.1742 0.1779 0.1792	CAF 0.2855 0.2856 0.2765 0.2744 0.2723 0.2656 0.2634 0.2542	RUN 112. 112. 112. 112. 112. 112. 112.
Q= P0= ALFHA 4.24 3.23 2.21 1.69 1.18 0.68 0.17 -0.34 -0.85 -1.35	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158 0.0241 -0.0719 -0.1575	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278 -1.1792 -0.2420 0.7337 1.5901 2.3111	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0848 -0.0738 -0.0739 -0.0781 -0.0777 -0.0797	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153 0.6555 0.6759 0.7461	90. DI CR 0.0169 0.0097 0.0022 -0.0025 -0.0033 0.0010 0.0068 0.0068	CAT 0.4566 0.4489 0.4427 0.4404 0.4376 0.4376 0.4321 0.4281	POJ/P O27020 CPB 0.1710 0.1681 0.1663 0.1663 0.1682 0.1720 0.1742 0.1779 0.1792 0.1784	TS = 69154 CAF 0.2855 0.2898 0.2765 0.2744 0.2723 0.2656 0.2634 0.2542 0.2490	RUN 112. 112. 112. 112. 112. 112. 112. 112
Q= P0= ALPHA 4.24 3.23 2.21 1.69 1.18 0.68 0.17 -0.34 -0.85 -1.35 -1.86	8.29 PSI 107.0 CM CN 0.6787 0.5170 0.3576 0.2772 0.2004 0.1158 0.0241 -0.0719 -0.1575 -0.2309	RE PER HG PTS= CM -6.7326 -5.1374 -3.5690 -2.7815 -2.0278 -1.1792 -0.2420 0.7337 1.5901 2.3111 3.0405	IN.= .48E0 3.8665 PSI CS -0.0683 -0.0743 -0.0848 -0.0738 -0.0842 -0.0739 -0.0781 -0.0777 -0.0797	CY 0.5503 0.6155 0.7249 0.6156 0.7231 0.6153 0.6555 0.6555 0.6759 0.7461 0.7418	90. DI CR 0.0169 0.0097 0.0022 -0.0067 -0.0033 0.0010 0.0068 0.0066 0.0067 -0.0013	CAT 0.4566 0.4489 0.4427 0.4407 0.4404 0.4376 0.4376 0.4376 0.4321 0.4281 0.4245	POJ/P . 027020 CPB 0.1710 0.1681 0.1663 0.1663 0.1682 0.1720 0.1742 0.1779 0.1792 0.1784 0.1776	CAF 0.2855 0.2896 0.2765 0.2744 0.2723 0.2656 0.2634 0.2542 0.2490 0.2461 0.2438 0.2427	RUN 112. 112. 112. 112. 112. 112. 112. 112

MODEL 946.2	CONF	IG. 3.000	HA	CH 1.75		PHI =	90.	
Q= 8.29 PSI	RE PER	IN.= .48E06	5 TO=	90. DE	G.F	P0J/P1	rs =	40.
PO= 107.0 CM	HG PTS=	3.8665 PSI		i	RUN NO.	02702	59155	
ALPHA CN	CH	cs	CY	CR	CAT	CPS	CAF	RUN
4.24 0.6919	-6.8586	-0-1224	0.9389	0.0177	0.4597	0.1714	0.2883	113.
3.23 0.5343	-5.3200			0.0047				
2.21 0.3864	-3.8908			0.0116				
1.68 0.3109	-3.1646			0.0212				
1.18 0.2319	-2.3877	-0.1276	1.0100-	0.0236	0.4471	0.1710	0.2761	113.
0.67 0.1341	-1.3883	-0.1371	1.1042-	0.0147	0.4465	0.1739	0.2725	113.
0.16 0.0246	-0.2472	-0.1369	1.1012	0.0010	0.4433	0.1781	0.2652	113.
-0.35 -0.0916	0.9588	-0.1309	1.0410	0.0196	0-4366	0.1826	0.2540	113.
-0.83 -0.1830	1.8932	-0-1342		0.0294				
-1.35 -0.2602	2.6628	-0-1414	1.1476	0.0281	0.4288	0.1773	0.2515	113.
-1.86 -0.3337	3.3609	-0.1307	1.1212	0.0208	0.4264	0.1763	0.2501	113.
-2.88 -0.4789	4.7634	-0-1438	1.1633	0-0072	C-4199	0.1756	0.2442	113.
~3.89 -G.6369	6.3040	-0.1393	1-1146-	0.0057	9.4169	0.1770	0.2399	113.
MODEL 946.2	CONF	IG. 3.000	НА	CH 1.75		eHI =	90.	•
MODEL 946.2 C= 8.29 PSI		IG. 3.000 IN.= .48E00	-	CH 1.75		PHI =		80•
	RE PER	IN.= .48E0	-	90. DE	G.F		rs =	80•
C= 8.29 PSI	RE PER	IN.= .48E0	-	90. DE	G.F	P0J/P	rs =	80. RUN
C= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER HG PTS=	IN.= .48E00 3.8665 PSI CS	5 T0=	90. DE	G.F RUN NO. CAT	POJ/P1 027026 CPB	IS = 59156 CAF	RUN
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331	RE PER HG PTS= CM -7.2949	IN.= .48E06 3.8665 PSI CS -0.2266	CY 1.6810	90. DEG	G.F RUN NO. CAT 0.4689	POJ/P1 . 027026 . CPB	IS = 59156 CAF 0-2970	RUN 114•
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852	RE PER HG PTS= CM -7.2949 -5.8812	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377	CY 1.6810 1.8019-	90. DEC	G.F RUN NO. CAT 0.4689 0.4650	POJ/P1 027020 CPB 0.1719 0.1714	TS = 59156 CAF 0.2970 0.2936	RUN 114. 114.
Q= 8.29 PSI PO= 107.0 CM ALPHA UN 4.24 0.7331 3.23 0.5852 2.21 0.4355	RE PER HG PTS= CM -7.2949 -5.8812 -4.4461	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364	CY 1.6810 1.8019- 1.7941-	90. DEC	G.F RUN NO. CAT 0.4689 0.4650- 0.4642	POJ/P1 027020 CPB 0.1719 0.1714 0.1752	IS = 59156 CAF 0.2970 0.2936	RUN 114• 114• 114•
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533	RE PER HG PTS= CM -7.2949 -5.8812	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404	CY 1.6810 1.8019- 1.7941- 1.8338-	90. DEC	G.F RUN NO. CAT 0.4689 0.4650 0.4642	POJ/P1 027020 CPB 0.1719 0.1714 0.1752 0.1766	IS = 59156 CAF 0.2970 0.2936 0.2891 0.2859	RUN 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608	RE PER THG PTS= CM -7.2949 -5.8812 -4.4461 -3.6460	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386	CY 1.6810 1.8019- 1.7941- 1.8338- 1.8191-	90. DEI	G.F RUN NO. CAT 0.4689 0.4650 0.4642 0.4625 0.4597	POJ/PT . 027024 CPB 0.1719 0.1714 0.1752 0.1766 0.1742	IS = 59156 CAF 0.2970 0.2936 0.2891 0.2859	RUN 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430	CY 1.6810 1.8019- 1.7941- 1.8338- 1.8191- 1.8614-	90. DE(CR 0.0012 (0.0218 (0.0439 (0.0498 (0.0463 (0.04283 (G.F RUN NO. CAT 0.4689 0.4650 0.4642 0.4625 0.4597	POJ/PT . 027024 CPB 0.1719 0.1714 0.1752 0.1766 0.1742 0.1742	IS = 59156 CAF 0.2970 0.2936 0.2891 0.2859 0.2859	RUN 114. 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608 0.67 0.1491	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190 -1.5577	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430 -0.2462	CY 1.6810 1.8019- 1.7741- 1.8338- 1.8191- 1.8614- 1.8901	90. DEI	G.F RUN NO. CAT 0.4689 0.4650 0.4642 0.4625 0.4597 0.4546	POJ/PT . 027024 CPB 0.1719 0.1714 0.1752 0.1766 0.1742 0.1742 0.1809	IS = 59156 CAF 0.2970 0.2936 0.2891 0.2859 0.2855 0.2805	RUN 114. 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608 0.67 0.1491 0.16 0.0232	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190 -1.5577 -0.2326	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430 -0.2462 -0.2493	CY 1.6810 1.8019- 1.7941- 1.8338- 1.81614- 1.8901 1.9251	90. DEC	G.F RUN NO. CAT 0.4689 0.4650 0.4642 0.4625 0.4597 0.4546 0.4519	POJ/PT 027026 CPB 0.1719 0.1714 0.1752 0.1766 0.1742 0.1742 0.1809 0.1833	CAF 0.2970 0.2930 0.2891 0.2859 0.2859 0.2859 0.2859	RUN 114. 114. 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608 0.67 0.1491 0.16 0.0232 -0.33 -0.1017	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190 -1.5577 -0.2326 1.0851	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430 -0.2462 -0.2493 -0.2496	CY 1.6810 1.8019- 1.7941- 1.8338- 1.8191- 1.8614- 1.8901 1.9251	90. DE(CR 0.0012 (0.0218 (0.0439 (0.0463 (0.0463 (0.0283 (0.0011 (0.0307 (G.F RUN NO. CAT 0.4689 0.4650- 0.4642 0.4625 0.4597 0.4546 0.4519 0.4394	POJ/PT . 027026 CPB 0.1719 0.1714 0.1752 0.2766 0.1742 0.1742 0.1809 0.1833 0.1791	CAF 0.2970 0.2936 0.2891 0.2855 0.2855 0.2710 0.2598	RUN 114. 114. 114. 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608 0.67 0.1491 0.16 0.0232 -0.33 -0.1017 -0.84 -9.2120	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190 -1.5577 -0.2326 1.0851 2.2198	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430 -0.2462 -0.2493 -0.2496 -0.2485	CY 1.6810 1.8019- 1.7941- 1.8338- 1.8191- 1.8614- 1.89251 1.9285	90. DE(CR 0.0012 (0.0218 (0.0439 (0.0463 (0.0283 (0.0283 (0.0011 (0.0307 (0.0473 (G.F RUN NO. CAT 0.4689 0.4650- 0.4642 0.4625 0.4597 0.4549 0.4519 0.44314 0.4334	POJ/PT . 027026 . CPB 0.1719 0.1714 0.1752 0.1762 0.1742 0.1809 0.1833 0.1791 0.1766	CAF 0.2970 0.2936 0.2891 0.2859 0.2805 0.2805 0.2710 0.2598 0.2603 0.2607	RUN 114. 114. 114. 114. 114. 114. 114.
C= 8.29 PSI PO= 107.0 CM ALPHA CN 4.24 0.7331 3.23 0.5852 2.21 0.4355 1.68 0.3533 1.18 0.2608 0.67 0.1491 0.16 0.0232 -0.33 -0.1017 -0.84 -9.2120 -1.35 -0.3039	RE PER CM -7.2949 -5.8812 -4.4461 -3.6460 -2.7190 -1.5577 -0.2326 1.0851 2.2198 3.1401	IN.= .48E06 3.8665 PSI CS -0.2266 -0.2377 -0.2364 -0.2404 -0.2386 -0.2430 -0.2462 -0.2493 -0.2496 -0.2495 -0.2491	CY 1.6810 1.8019- 1.7941- 1.8338- 1.8191- 1.8614- 1.8901 1.9251 1.9251 1.9166 1.9221 1.9373	90. DE(CR 0.0012 (0.0218 (0.0439 (0.0463 (0.0283 (0.011 (0.0307 (0.0473 (0.0502 (G.F RUN NO. CAT 0.4689 0.4650 0.4642 0.4625 0.4597 0.4546 0.4519 0.4313 0.4373 0.4373	POJ/P7 027026 CPB 0.1719 0.1714 0.1752 0.2766 0.1742 0.1809 0.1833 0.1736 0.1755 0.1754	CAF 0.2970 0.2936 0.2859 0.2855 0.2710 0.2598 0.2607 0.2507	RUN 114. 114. 114. 114. 114. 114. 114. 114

MOD	EL 946.2	CONI	FIG. 3.450	M	ACH 1.79	£	PHI =	•	
Q=	8.29 PSI	RE PER	IN.= .48E0	5 - TO=	90. D	EG.F	POJ/P	TS ≃	•
P0=	107.0 CM	HG PTS=	3.8665 PS1			RUN NO	02802	69102	
ALPHA	CN	CH	CS	CY	CR	CAT	СРВ	CAF	RUN
4.10	0-6423	-6.3914	-0.0432	0.4380	0.0016	0.4296	0.1697	0.2599	115.
3.09	0-4821	~4.7962	-0.0397	0.4085	0.0016	0.4287	0.1707	0.2580	115.
2.08	0-3199		-0.0377			0.4284			
1.55	0.2340	-2.3301	-0:0425			0.4282			
1.06	0-1610	-1.6031	-C.0398			0.4282			
	0.0796		-0.0400			0.4286			
0.03	0.0067		-0.0339			0.4279			
	-0.0721		-0.0412			0.4274			
	-0-1476	_	-0.0392			0.4262			
	-0.2270		-0.0395			0.4264			
	-0.3012		-0.0407			0.4245			
	-0.4634		-0.0400			0.4230			
~4.02	-0-6268	6-2374	-0.0365	0.3853	-0.0015	0.4214	0.16//	0.2537	115.
	EL 946.2 8.29 PSI		FIG. 3.450		ACH 1.7:		PHI =	• TS =	10.
Q=	8-29 PSI	RE PER				EG.F		rs =	10.
Q=	8-29 PSI	RE PER	IN.= .48E0			EG.F	P0 J/ P	rs =	10. RUN
Q= PO= Alpha	8.29 PSI 107.0 CM	RE PER HG .PTS= CM	IN.= .48E00 3.8665 PSI CS	S T0=	90. U	EG.F RUN NO: CAT	POJ/P 028020 CPB	TS = 69103 CAF	RUN
Q= P0=	8.29 PSI 107.0 CM	RE PER HG .PTS= CM -6.3645	IN.= .48E00 3.8665 PSI CS -0.0418	CY 0.4321	90. 00 CR 0.0035	EG.F RUN NO CAT G.4366	POJ/P 028020 CPB 0.1730	TS = 69103 CAF 0.2636	RUN 116.
Q= PO= ALPHA 4.08	8.29 PS1 107.0 CM CN 0.6314	RE PER HG .PTS= CM -6.3645 -4.7711	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387	CY 0.4321 0.4020	90. 00 CR 0.0035 0.0030	EG.F RUN NO: CAT	POJ/P 028020 CP8 0.1730 0.1738	TS = 69103 CAF 0.2636 0.2618	RUN 116.
Q= PO= ALPHA 4.08 3.08	8.29 PSI 107.0 CM CN 0.6314 0.4718	RE PER HG .PTS= CM -6.3645 -4.7711	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387 -0.0406	CY 0.4321 0.4020 0.4220	90. 08 CR 0.0035 0.0030 0.0027	EG.F RUN NO. CAT 0.4366 0.4356	POJ/P 02802 CPB 0.1730 0.1738 0.1748	TS = 69103 CAF 0.2636 0.2618 0.2605	RUN 116. 116.
Q= PO= ALPHA 4.08 3.08 2.06	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383	CY 0.4321 0.4020 0.4220 0.4022	90. 08 CR 0.0035 0.0030 0.0027 0.0024	EG.F RUN NO. CAT 0.4366 0.4356 0.4353	POJ/P 02802 CPB 0.1730 0.1738 0.1748 0.1744	TS = 69103 CAF 0.2636 0.2618 0.2605	RUN 116. 116. 116.
Q= PO= ALPHA 4.08 3.08 2.06 1.55	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383	CY 0.4321 0.4020 0.4220 0.4022 0.3911	90. 0 CR 0.0035 0.0030 0.0027 0.0024 0.0022	EG.F RUN NO. CAT 0.4366 0.4356 0.4353 0.4343.	POJ/P 028020 CPB 0.1730 0.1738 0.1748 0.1744 0.1737	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2599 0.2588	RUN 116. 116. 116. 116.
Q= PO= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387 -C.0406 -0.0383 -0.0371	CY 0.4321 0.4020 0.4220 0.4022 0.3911 0.4108	90. 09 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019	CAT 0.4366 0.4356 0.4353 0.4343	POJ/P 02802 CPB 0.1730 0.1738 0.1748 0.1744 0.1737 0.1733	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2599 0.2588 0.2601	RUN 116. 116. 116. 116.
Q= PO= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53 0.02 -0.48	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495 0.0714 -0.0035 -0.0803	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829 -0.0366 0.7290	IN.= .48E00 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383 -0.0371 -0.0394 -0.0375 -0.0374	CY 0.4321 0.4020 0.4220 0.4022 0.3911 0.4108 0.3903 0.3927	90. 09 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019 0.0017 0.0017	CAT 0.4366 0.4356 0.4353 0.4343 0.4343 0.4325 0.4333 0.4314 0.4302	POJ/P 028020 CP8 0.1730 0.1738 0.1748 0.1744 0.1737 0.1733 0.1727	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2599 0.2588 0.2601 0.2587	RUN 116. 116. 116. 116. 116. 116.
Q= PO= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53 0.02 -0.48 -1.00	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495 0.0714 -0.0035 -0.0803 -0.1584	RE PER -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829 -0.0366 0.7290 1.5063	IN.= .48E06 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383 -0.0371 -0.0394 -0.0375 -0.0374	CY 0.4321 0.4020 0.4020 0.4022 0.4021 0.4108 0.3903 0.3927 0.4033	90. 09 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019 0.0017 0.0017	CAT 0.4366 0.4356 0.4353 0.43432 0.4325 0.4333 0.4314 0.4302 0.4284	POJ/P . 028020 . CPB 0.1730 0.1738 0.1748 0.1744 0.1737 0.1733 0.1727 0.1717	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2599 0.2588 0.2601 0.2587	RUN 116. 116. 116. 116. 116. 116. 116. 116
Q= PO= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53 0.02 -0.48 -1.00 -1.50	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495 0.0714 -0.0035 -0.0803 -0.1584 -0.2379	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829 -0.0366 0.7290 1.5063 2.2963	IN.= .48E06 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383 -0.0371 -0.0394 -0.0375 -0.0374 -0.0387	CY 0.4321 0.4020 0.4220 0.4022 0.4022 0.4033 0.3903 0.3927 0.4033 0.3788	90. 09 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019 0.0017 0.0012 C.0006	CAT 0.4366 0.4356 0.4353 0.4343 0.4325 0.4323 0.4314 0.4302 0.4284 0.4299	POJ/P . 02802 . CPB 0.1730 0.1738 0.1748 0.1744 0.1747 0.1737 0.1737 0.1717 0.1711	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2589 0.2588 0.2601 0.2587 0.2585	RUN 116. 116. 116. 116. 116. 116. 116. 116
Q= P0= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53 0.02 -0.48 -1.00 -1.50 -2.01	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495 0.0714 -0.0035 -0.0803 -0.1584 -0.2379 -0.3160	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829 -0.0366 0.7290 1.5063 2.2963 3.0752	IN.= .48E06 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383 -0.0371 -0.0394 -0.0375 -0.0374 -0.0387 -0.0366	CY 0.4321 0.4020 0.4220 0.4022 0.3911 0.4108 0.3903 0.3903 0.3903 0.3788 0.3895	90. 00 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019 0.0017 0.0012 C.0006 0.0006	CAT 0.4366 0.4356 0.4353 0.4343 0.4325 0.4333 0.4314 0.4302 0.4284 0.4299 0.4274	POJ/P CP8 0.1730 0.1738 0.1748 0.1744 0.1737 0.1737 0.1717 0.1717 0.1711 0.1710 0.1705	TS = 69103 CAF 0.2636 0.2618 0.2695 0.2589 0.2588 0.2691 0.2585 0.2589 0.2589	RUN 116. 116. 116. 116. 116. 116. 116. 116
Q= PO= ALPHA 4.08 3.08 2.06 1.55 1.03 0.53 0.02 -0.48 -1.00 -1.50 -2.01 -3.02	8.29 PSI 107.0 CM CN 0.6314 0.4718 0.3117 0.2290 0.1495 0.0714 -0.0035 -0.0803 -0.1584 -0.2379	RE PER HG .PTS= CM -6.3645 -4.7711 -3.1742 -2.3532 -1.5616 -0.7829 -0.0366 0.7290 1.5063 2.2963 3.0752 4.6705	IN.= .48E06 3.8665 PSI CS -0.0418 -0.0387 -0.0406 -0.0383 -0.0371 -0.0394 -0.0375 -0.0374 -0.0387	CY 0.4321 0.4020 0.4220 0.4022 0.3911 0.4108 0.3903 0.3927 0.4033 0.3788 0.3895 0.3872	90. 00 CR 0.0035 0.0030 0.0027 0.0024 0.0022 0.0019 0.0017 0.0017 0.0017 0.0016 0.0006	CAT 0.4366 0.4356 0.4353 0.4343 0.4325 0.4323 0.4314 0.4302 0.4284 0.4299	POJ/P 02802 CPB 0.1730 0.1738 0.1748 0.1744 0.1737 0.1733 0.1727 0.1717 0.1717 0.1717 0.1715 0.1705	TS = 69103 CAF 0.2636 0.2618 0.2605 0.2589 0.2587 0.2587 0.2589 0.2589 0.2589	RUN 116. 116. 116. 116. 116. 116. 116. 11

THE TENED OF THE PERSON OF THE

MOD	EL 946.2	CON	FIG. 3.450	H	ACH 1.75	PHI =	•	
Q=	8.29 251	RE PER	IN.= .48E0	6 T0=	90. DEG:F	POJ/PTS	= 20.	
P0=	107.0 CM	HG PTS=	3.8065 PSI		RUN NO	. 0280269	104	
ALPHA	CN	CM	cs	CY	ER CAT	CPB	ÇAF	RUN
4.07	0.6186		-0.0437		0.0046 0.4462			117.
3.07	0.4577		-0.0381		0.0037 0.4445			117.
2.05	0.2962		-0.0399		0.0032 0.4436			117.
1.53	0.2090		-0.0412	_	0.0029 0.4427			117.
1.03	0.1354		-0.0375		0.0029 0.4421			117.
0.51	0.0566		-0.0395		0.0027 0.4389			117.
	-0.0176	-	-0.0390		0.0024 0.4377			117.
	-0.0990		-0.0357		0.0016 0.4346			117.
	-0.1777		-0.0408		0.0019 0.4335			117.
	-0.2539		-0.0385		0.0017 0.42%6			117.
	-0.3282		-0.0359		0.0017 0.4290			117.
	-0.4883		-0.0398		0.0012 0.4268			117.
-4.04	-0.6512	6.3278	-0.0367	0.3895	0.0006 0.4259	0-1692 0	-2567	117.
	8.29 PSI		FIG. 3.450 IN.= .48E0		ACH 1.75	= IH9 2 7 9\L09	- 40-	
			FIG. 3.450 IN.= .48E0		ACH 1.75 90. DEG.F	PHI = 279\LO9	_	
Q=	8.29 PSI	RE PER		6 TO=	90. DEG.F	_	= 40•	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS - 0280269	= 40•	RUN
Q= PO= Alpha	8.29 PSI	RE PER HG PTS=	IN.= .48E0	6 TØ=	90. DEG.F RUN NO	POJ/PTS - 0280269 - CPB	= 40. 105 Caf	RUN 118.
Q= PO= Alpha	8.29 PSI 107.0 CM	RE PER HG PTS= CM -6.0466	IN.= .48E0 3.8665 PSI CS	6 TO= CY 0.4745	90. DEG.F RUN NO CR CAT	POJ/PTS - 0280269 - CPB - 0.1806 0	= 40. 105 CAF .2705	
Q= P0= Alpha 4.04	8.29 PSI 107.0 CM CN 0.5767	RE PER HG PTS= CM -6.0466 -4.4224	IN.= .48E0 3.8665 PSI CS -0.0459	6 TØ= CY 0.4745 0.4429	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474	POJ/PTS - 0280269 - CPB - 0.1806 0 - 0.1807 0	= 40. 105 CAF .2705 .2668	118.
Q= PO= ALPHA 4.04 3.04 2.02	8.29 PSI 107.0 CM CN 0.5767 0.4139	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428	6 T0= CY 0.4745 0.4429 0.4041	90. DEG.F RUN NO CR CAT 0.0073 0.4511	POJ/PTS - 0280269 CPB 0.1806 0 0.1807 0 0.1825 0	= 40. 105 CAF .2705 .2668 .2654	118.
Q= PO= ALPHA 4.04 3.04 2.02 1.51	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386	6 T0= CY 0.4745 0.4429 0.4041 0.4694	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0	= 40. 105 CAF .2705 .2668 .2654 .2639	118. 118. 118.
Q= PO= ALPHA 4.04 3.04 2.02 1.51	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408	6 T0= CY 0.4745 0.4429 0.4041 0.4694 0.4218	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1821 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644	118. 118. 118.
Q= PO= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466	6 T0= CY 0.4745 0.4429 0.4041 0.4694 0.4218 0.4382	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0044 0.4465	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1821 0 0.1812 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634	118. 118. 118. 118.
Q= P0= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48 -0.02	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432	CY 0.4745 0.4429 0.4041 0.4694 0.421.8 0.4382 0.44077	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0044 0.4465 0.0045 0.4446	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1821 0 0.1812 0 0.1793 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2634	118. 118. 118. 118. 118.
Q= P0= ALPHA 4.04 3.04 2.02 1.51 0.48 -0.02 -0.52	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082 -0.0674	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647 1.1465	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432 -0.0391	CY 0.4745 0.4429 0.4041 0.4694 0.421.8 0.4382 0.4077 0.4093	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0044 0.4465 0.0045 0.4446 0.0039 0.4407	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1821 0 0.1812 0 0.1793 0 0.1775 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2634 .2615	118. 118. 118. 118. 118. 118.
Q= PO= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48 -0.02 -0.52 -1.03	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082 -0.0674 -0.1461	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647 1.1465	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432 -0.0391 -0.0393	CY 0.4745 0.4429 0.4041 0.4694 0.4218 0.4382 0.4077 0.4093 0.4023	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4465 0.0045 0.4446 0.0039 0.4407 0.0037 0.4382	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1823 0 0.1812 0 0.1812 0 0.1793 0 0.1775 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2634 .2615 .2608 .2595	118. 118. 118. 118. 118. 118.
Q= PO= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48 -0.02 -0.52 -1.03 -1.54	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082 -0.0674 -0.1461 -0.2230	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647 1.1465 1.9104 2.6775	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432 -0.0391 -0.0393 -0.0388	CY 0.4745 0.4429 0.4041 0.4694 0.4218 0.4382 0.4077 0.4093 0.4023 0.4100	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0044 0.4465 0.0045 0.4446 0.0039 0.4407 0.0037 0.4382 0.0032 0.4357	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1823 0 0.1812 0 0.1793 0 0.1775 0 0.1762 0 0.1751 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2615 .2608 .2595	118. 118. 118. 118. 118. 118. 118.
Q= P0= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48 -0.02 -0.52 -1.03 -1.54 -2.04 -3.06	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082 -0.0674 -0.1461 -0.1461 -0.2230 -0.3005 -0.3734 -0.5317	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647 1.1465 1.9104 2.6775 3.4019	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432 -0.0391 -0.0393 -0.0388 -0.0393	CY 0.4745 0.4429 0.4041 0.4694 0.4218 0.4382 0.4077 0.4093 0.4023 0.4100 0.3983	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0045 0.4446 0.0039 0.4407 0.0037 0.4382 0.0032 0.4357 0.0032 0.4346	POJ/PTS . 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1821 0 0.1812 0 0.1793 0 0.1775 0 0.1775 0 0.1751 0 0.1750 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2615 .2608 .2595	118. 118. 118. 118. 118. 118. 118. 118.
Q= P0= ALPHA 4.04 3.04 2.02 1.51 0.99 0.48 -0.02 -0.52 -1.03 -1.54 -2.04 -3.06	8.29 PSI 107.0 CM CN 0.5767 0.4139 0.2517 0.1690 0.0837 0.0082 -0.0674 -0.1461 -0.2230 -0.3005 -0.3734	RE PER HG PTS= CM -6.0466 -4.4224 -2.8071 -1.9843 -1.1357 -0.3861 0.3647 1.1465 1.9165 1.9175 3.4019 4.9710	IN.= .48E0 3.8665 PSI CS -0.0459 -0.0428 -0.0386 -0.0466 -0.0408 -0.0432 -0.0393 -0.0388 -0.0393 -0.0381	CY 0.4745 0.4429 0.4041 0.4694 0.4218 0.4407 0.4093 0.4023 0.4100 0.3983 0.4027	90. DEG.F RUN NO CR CAT 0.0073 0.4511 0.0053 0.4474 0.0044 0.4479 0.0042 0.4462 0.0044 0.4465 0.0045 0.4446 0.0039 0.4407 0.0037 0.4382 0.0032 0.4387 0.0032 0.4346 0.0027 0.4340	POJ/PTS - 0280269 CPB 0.1806 0 0.1807 0 0.1825 0 0.1823 0 0.1812 0 0.1812 0 0.1775 0 0.1762 0 0.1762 0 0.1762 0	= 40. 105 CAF .2705 .2668 .2654 .2639 .2644 .2634 .2615 .2608 .2595	118. 118. 118. 118. 118. 118. 118. 118.

MO	DEL 946.Z	CON	FIG. 3.450	H	ACH 1.79	5	PHI =	•	-
Q=	8.23 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	EG.F	POJ/P	TS = 60)•
PO:	= 107.0 CM	HG PTS=	3.8665 PSI			RUN HO	02802	69106	
ALPHA	CN	CH	cs	CY	CR	CAT	CP8	CAF	RUN
3.99	0.4871	-5.4670	-0.0507		0.0126				119.
2.98	0.3203	-3.8064	-0.0469	9.4741	0.0101	9.4561	0.1835	0.2725	119.
1.97	0.1548		-0.0413		0.0069				119.
1.45			-0.0404		0.0063				119.
	-0.0107		-0.0368		0.0060				119.
	-0.0882		-0.0398		0.0055				119.
	-0.1650		-0.0385		0.0059				119.
	0.2465		-0.0387		0.0030				119.
	-0.3201		-0.0357		0.0030				119.
	-0.3963		-0.0369		0.0028				119.
		4.0142			0.0029				119.
	-0.6229		-0.0388		0.0019				119.
-4.13	-0.7793	7.0820	-0.0349	0.3636	0.0017	0.4349	0.1697	0.2651	119.
MOI	DEL 946.2	CONI	FIG 3.450	М	ACH 175	5	PHI =	45.	
Q=	8.29 PSI	RE PER	IN.= .48E0	5 TQ=	90. DE	G.F	POJ/P	rs =	•
PO=	= 107.0 CH	HG PTS=	3.8665 PSI			RUN NO	02802	69107	
ALPHA	CFI	CH	CS	.CY	CR	CAT	CPB	CAF	RUN
4.20	0.6653	-6.6253	-0.0425	0.4198	0.0036	0.4423	0.1659	0.2764	120.
3.19			-0.0431		0.0027				120.
2.18	0.3394	-3.3801	-0.0399	0.3948	0.0022	0.4340	0.1689	0.2651	120.
166	0.2562	-2.5523	-0.0401	0.3956	0.0015	0.4370	0.1705	0.2664	120.
1.14	0.1773	-1.7663	-0.0390	0.3840	0.0008	0.4366	0.1715	0.2650	120.
0.64	0.0966	-0.9600	-0.0397	0.3925	0.0007	0.4355	0.1722	0.2633	120.
0.13	0.0205	-0.2036		0.3556	0.0008	0.4330	0.1725	0.2604	120,
~0.38	-0.0582	0.5784	-0.0349	0.3462	0.0004	0.4305	0.1724	0-2581	120.
	-0.1338	1.5331			0.0007				120.
	-0.2177	2.1672	-0.0364		0.0002		_	-	120.
-1.88	-0.2885	2.8711	-0.0312		0.0005				120.
	-0.4524	4.4997	-0.0330		0.0008				120 .
-3.02	-0.6168	6.1390	-0.0270	0.2704	0.0011	0.4088	0.1637	0.2451	120.

UUDEL	946-2	CONFIG	. 3.450	HA	CH 1.75	i	PHI =	45.	
Q= 8.	29 PSI R	E PER IN	.= .48E06	10=	99. DE	G.F	POJ/P1	rs =	10.
20= 1	07.0 CHHG	PTS= 3.	129 2 368			RUN NO.	028026	59108	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.19 0	-4591 -6	.6064 ~0	-0524	Q.4485	0.0156	0.4459	888 £ 0	0-2763	121.
		.9373 -0		0.4169					
2.17 0		.3517 -0		0.4225					
1.65 0		.4962 -0		0.4089					
1.14 0		.7075 -0		0.4157					
0.62 0		-9218 -0		0.3778					
0.12 0		-1628 -0		0.3680	0.0016	0.4317	0.1724	0.2594	121.
-0.39 -0		.6168 -0	.0435	0.3860	0.	0.4301	0.1715	0.2585	121.
-0.89 -0	.1448 1	.3847 -0	.0441	0.3949-	0.0012	0.4270	0.1702	0-2568	121.
-1.40 -0	.2245 2	.1727 -9	.0393	G.3516-	0.0013	0.4238	0.1686	0.2553	121.
-1.90 -0	.2973 2	.8976 -0	-0415	0.3732-	0.0042	0.4208	0.1680	0.2528	. 121.
	.4546 . 4	.4549 -0	.0397	0.3597-	0.0056	0.4159	0.1672	0.2487	121.
-3.93 -0		-0939 -0		0.3506-	0.0030	0.4125	0.1666	0.2459	121.
RUDEI									
110000	946.2	CONFIG	. 3.450	AM	CH 1.75	•	PHI =	45.	
			• 3•450 •= •48E06						20•
Q= 8.		E PER IN	-= -48E06		90. DE		P0J/P1	rs =	20•
Q= 8.	29 PSI R 07.0 CMHG	E PER IN	-= -48E06		90. DE	G•F	P0J/P1	rs =	20• RUN
Q= 8. PG= 1 ALPHA	29 PSI R 07.0 CMHG	E PER IN PTS= 3. CM	•= •48E06 8665 PSI ·CS	T0=	90. DE	G.F RUN NO. CAT	POJ/P1 028026 CP8	FS = 59109 CAF	RUN
Q= 8. PO= 1 ALPHA 4.18 0	29 PSI R 07.0 CMHG CN .6470 -6	E PER IN PTS= 3. CM .5295 -0	•= •48E06 8665 PSI •CS	T0= CY 0.5064	90. DE CR 0.0299	G.F RUN NO. CAT 0.4522	POJ/P1 028020 CPB	FS = 69109 CAF 0.2766	RUN 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0	29 PSI R 07.0 CMHG CN -6470 -6	E PER IN PTS= 3. CM .5295 -0 .8755 -0	•= •48E06 8665 PSI •CS •0656	CY C•5064 0•4692	90. DE CR 0.0299 0.0218	G.F RUN NO. CAT 0.4522 0.4506	POJ/P1 028026 CPB 0.1756 0.1770	TS = 59109 CAF 0.2766 0.2736	RUN 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0	•= •48E06 8665 PSI ·CS •0656 •0606	CY 0.5064 0.4692 0.4793	90. DE CR 0.0299 0.0218 0.0143	CAT 0.4522 0.4506	POJ/P1 . 028026 . CPB 0.1756 0.1770 0.1778	TS = 59109 CAF 0.2766 0.2736 0.2680	RUN 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0	.= .48E06 8665 PSI CS .0656 .0606 .0601	CY C.5064 0.4692 0.4793 0.4366	90. DE CR 0.0299 0.0218 0.0143 0.0099	CAT 0.4522 0.4506 0.4458 0.446	POJ/P1 . 028026 . CPB 0.1756 0.1770 0.1778 0.1788	FS = 59109 CAF 0.2766 0.2736 0.2680 0.2659	RUN 122. 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0	•= •48E06 8665 PSI CS •0656 •0606 •0601 •0554 •0522	CY 0.5064 0.4692 0.4793 0.4366 0.4078	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069	CAT 0.4522 0.4506 0.4458 0.4446	POJ/PT 028026 CPB 0.1756 0.1778 0.1778 0.1788	TS = 59109 CAF 0.2766 0.2736 0.2680 0.2659 0.2657	RUN 122. 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1 -0730 -0	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0	-= .48E06 8665 PSI CS .0656 .0606 .0601 .0554 .0522	CY 0.5064 0.4692 0.4793 0.4366 0.4078 0.4432	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069	CAT 0.4522 0.4506 0.4458 0.4446	POJ/PT 028026 CPB 0.1756 0.1776 0.1778 0.1788 0.1784 0.1776	TS = 59109 CAF 0.2766 0.2736 0.2680 0.2659 0.2657 0.2630	RUN 122. 122. 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0 0.61 0 0.11 -0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1 -0730 -0 -0003 -0	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0 .1027 -0	-= .48E06 8665 PSI CS .0656 .0606 .0554 .0552 .0552	CY 0.5064 0.4692 0.4793 0.4366 0.4078 0.4432 0.4430	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069 0.0036	CAT 0.4522 0.4528 0.4458 0.4446 0.4446 0.4466	POJ/PT . 028026 CPB 0.1756 0.1770 0.1778 0.1784 0.1776 0.1765	CAF 0.2766 0.2736 0.2680 0.2659 0.2657 0.2630	RUN 122. 122. 122. 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0 0.61 0 0.11 -0 -0.40 -0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1 -0730 -0 -0003 -0 -0789 0	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0 .1027 -0 .6742 -0	.= .48E06 8665 PSI CS .0656 .0606 .0601 .0554 .0552 .0552 .0559	CY 0.5064 0.4692 0.4793 0.4366 0.4078 0.4432	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069 0.0036 0.0024	CAT 0.4522 0.4506 0.4458 0.4442 0.4406 0.4368 0.4337	POJ/P1 . 028026 . CPB 0.1756 0.1770 0.1778 0.1788 0.1784 0.1776 0.1765 0.1753	CAF 0.2766 0.2736 0.2680 0.2659 0.2657 0.2630 0.2632	RUN 122. 122. 122. 122. 122. 122. 122.
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0 0.61 0 0.11 -0 -0.40 -0 -0.90 -0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1 -0730 -0 -0789 0 -1583 1	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0 .1027 -0	-= .48E06 8665 PSI CS .0656 .0606 .0601 .0554 .0522 .0552 .0559 .0559	CY 0.5064 0.4692 0.4793 0.4366 0.4078 0.4432 0.4430 0.4565-	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069 0.0036 0.0024	CAT 0.4522 0.4506 0.4458 0.4442 0.4406 0.4368 0.4337 0.4307	POJ/P1 . 028026 . CPB 0.1756 0.1778 0.1778 0.1788 0.1784 0.1776 0.1765 0.1753	CAF 0.2766 0.2736 0.2659 0.2657 0.2630 0.2632 0.2584	RUN 122. 122. 122. 122. 122. 122. 122. 122
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0 0.61 0 0.11 -0 -0.40 -0 -0.90 -0 -1.40 -0	29 PSI R 07.0 CMHG CN -6470 -6 -4806 -4 -3171 -3 -2363 -2 -1580 -1 -0730 -0 -0003 -0 -0789 0 -1583 1 -2324 2	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0 .1027 -0 .4595 -0 .4595 -0 .1915 -0	-= .48E06 8665 PSI CS .0656 .0606 .0601 .0554 .0522 .0552 .0559 .0559	CY 0.5064 0.4692 0.4793 0.4366 0.4432 0.4430 0.4565- 0.4661-	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0036 0.0024 0.0015 0.0030	CAT 0.4522 0.4506 0.4558 0.4442 0.4446 0.4368 0.4337 0.4307	POJ/P1 . 028026 . CP8 0.1756 0.1778 0.1788 0.1784 0.1776 0.1753 0.1734 0.1707	CAF 0.2766 0.2736 0.2659 0.2659 0.2630 0.2602 0.2584 0.2573	RUN 122. 122. 122. 122. 122. 122. 122. 122
Q= 8. PO= 1 ALPHA 4.18 0 3.18 0 2.16 0 1.64 0 1.13 0 0.61 0 0.11 -0 -0.40 -0 -0.90 -0	29 PSI R 07.0 CMHG CN .6470 -6 .4806 -4 .3171 -3 .2363 -2 .1580 -1 .0730 -0 .0003 -0 .0789 0 .1583 1 .2324 2	E PER IN PTS= 3. CM .5295 -0 .8755 -0 .2503 -0 .4507 -0 .6731 -0 .8309 -0 .1027 -0 .6742 -0 .4595 -0	-= .48E06 8665 PSI CS .0656 .0606 .0601 .0554 .0522 .0569 .0559 .0551 .0551	CY 0.5064 0.4692 0.4793 0.4366 0.4078 0.4432 0.4430 0.4565- 0.4661- 0.4570-	90. DE CR 0.0299 0.0218 0.0143 0.0099 0.0069 0.0024 0.0024 0.0051 0.0030	CAT 0.4522 0.4506 0.4458 0.4446 0.4442 0.4406 0.4368 0.4337 0.4262 0.4232	POJ/PI 028026 CPB 0.1756 0.1778 0.1788 0.1784 0.1776 0.1765 0.1753 0.1734 0.1707 0.1686	CAF 0.2766 0.2736 0.2659 0.2657 0.2630 0.2584	RUN 122. 122. 122. 122. 122. 122. 122. 122

ЖC	DEL 946.2	CON	FIG. 3.450	H	ACH 1.75	5	PHI =	45.	
Q=	8.29 PSI	RE PER	IN.= -48E0	6 10=	90. D	EG.F	POJ/P	rs =	40.
99	= 107.0 0	MRG PTS=	3.8665 PSI			RUN NO.	02802	69110	
ALPHA	CN.	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.17	0.6308	-6.4589	-0.0955	0.6714	0.0439	U-4609	0.1816	0.2793	123.
3.16			-0.0901		0.0323				
2.14	0.2891	-3.0707	-0.0878	0.6302	0.0210	0.4518	0.1816	0.2703	123.
1.62	0.2017	-2,2055	-0.0903	0.6616	0.0154	0.4502	0.1815	0.2688	123.
	0.1216	-1.4129	-0.0863	0.6280	0.0115	0.4471	0.1812	0.2659	123.
0.60	0.0435	-0.6438	-0.0868		0.0071				
_	-0.0320		-0.0863		0.0033				
	-0.1064		-0.0850		0.0001				
	-0.1828		-0.0872		-0.0040				
	-0.2575		-0.0902		-0.0084				
	-0.3292		-0.0897		-C. 0130				
	-0.4777		-0.0912		-0.0237				
-3.96	-0.6234	5.8813	-0.0892	0.7065	-0.0342	0.4244	0.1716	0.2528	123.
мс	DEL 946.2	: CON	FIG. 3.450	Ħ,	ACH 1-75	5	PHI =	45.	
Q=	8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. DE	G.F	POJ/P	rs =	80.
٥٩	= 107.0 0	MHG PTS=	3.8665 PSI			RUN NO.	02802	69111	
ALPHA	CN.	CM	CS	CY	CR	CAT	СРВ	CAF	RUN
4.13	0.5691	-6.0533	-0.1705	1.1773	0.0590	0.4736	0.1869	0.2867	7 124.
3.12			-0.1641		0.0462				
	0.2174		-0.1605		0.0304				
	0.1302	-1.7032	-0.1542	1.0608	0.0227	0.4587	0.1831	0.2756	
1.08	0.0489	-0.9023	-0.1554	1.0839	0.0165	0.4570	0.1826	0.2744	124.
0.57	-0-0319	-0.1098	-0.1605		0.0098				
	-0.1037		-0.1582		0.0049				124.
-0.46	-0.1788	1.3237	-0.1590	1.1432	-0.0015	0.4475	0.1793	0.2682	2 124.
-0.97	-0.2545	2.0600	-0.1629	1.1936	-0.0093	0.4453	0.1777	0.2676	
-1.48	-0.3270	2.7619	-0.1626	1.1995	-0.0163	0.4409	0.2760		
-1.98									
	-0.3930		-0.1623		-0-0234				
-3.00	-0.3930 -0.5315	4.7284	-0.1623 -0.1655 -0.1597	1.2508	-0.0234 -0.0426 -0.0675	0.4321	0.1712	0.2609	124.

MOD	EL 946.2	CONI	FIG. 3.450	Mi	ACH 1.75	.PHI =	90.	~ ~
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TØ=	90. DEG.F	P0J/P	₹S =-	•
P0=	107.0 CM	HG PTS=	3.8665 PSI		RUN N	02802	69112	
ALPHA	CN	CM	CS	CY	CR CAT	CP8	CAF	RUN
4.20	0.6621	-6.5876	-0.0338	0.3722	0.0033 0.4513	0.1702	0.2813	125.
3.19	0.4990		-0.0422		0.0027 0.445			125.
2.17	0.3377		-0:0345		0.0014 0.439			125.
1.65	0.2541		-0.0333		0.0012 0.438			125.
1.15	0.1773		-0.0306		0.0017 0.436			125.
0.64	0.0974		-0.0307		0.0010 0.434			125.
	0.0209		-0.0326	0.3089		0.1733		125.
	-0.0584	0.5805			0.0008 0.4304			.125 •
	-0.1373		-0.0196		0.0007 0.425			125.
	-0.2156		-0.0228		0.0005 0.420			125.
	-0.2917		-0.0156		0.0013 0.417			125.
	-0.4528 -0.6169		-0.0216 -0.0099		0.0013 0.4124			125.
-3.92	-0.0109	0 • 1 33 (-0.0099	0.0803	0.0022 0.408	0.1033	U.2449	125.
_	EL 946.2		FIG. 3.450		ACH 1.75	PHI =		10.
_	EL 946.2 8.29 PSI		FIG. 3.450 IN.= .48E0		ACH 1.75 90. DEG.F	PHI =		10.
Q=	8.29 PSI	RE PER		6 TQ=	90. DEG.F		rs = 1	10.
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TQ=	90. DEG.F	P0 J/ P1	rs = 1	LO.
Q= P0=	8.29 PSI 107.0 CM	RE PER HG PTS=	IN.= .48E0	6 T0=	90. DEG.F	POJ/P1	SS = 1 59113 CAF	
Q= PO= ALPHA	8.29 PSI 107.0 CMI	RE PER HG PTS= CM -6.5048 -4.9039	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343	6 T0= CY 0.2380	90. DEG.F RUN NO CR CAT	POJ/P1 0- 028026 CP8 3- 0-1722	SS = 1 S9113 CAF 0.2811	RUN
Q= PO= ALPHA 4.19 3.19 2.18	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346	RE PER HG PTS= CM -6.5048 -4.9039	IN.= .48E0 3.8665 PSI CS -0.0342	6 T0= CY 0.2380 0.2409 0.3168	90. DEG.F RUN NO CR CAT 0.0128 0.453; 0.0111 0.4460; 0.0079 0.441;	POJ/P1 0. 028026 CPB 0.1722 0.1687 2.0.1695	SS = 1 59113 CAF 0.2811 0.2781 0.2717	RUN 126.
Q= PO= ALPHA 4.19 3.19	8.29 PSI 107.0 CMI CN 0.6563 0.4949	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343	6 T0= CY 0.2380 0.2409 0.3168	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4466	POJ/P1 0. 028026 CPB 0.1722 0.1687 2.0.1695	SS = 1 59113 CAF 0.2811 0.2781 0.2717	RUN 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65 1.15	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474	6 T0= CY 0.2380 0.2409 0.3168 0.2849 0.3780	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4460 0.0079 0.4412 0.0057 0.4380 0.0036 0.4350	POJ/P7 CPB 3 0.1722 3 0.1687 2 0.1695 6 0.1710	SS = 1 S9113 CAF 0.2811 0.2781 0.2717 0.2676 0.2641	RUN 126. 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396	6 T0= CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2998	90. DEG.F RUN NO CR CAT 0.0128 0.4533 0.0111 0.4466 0.0079 0.4412 0.0057 0.4386 0.0036 0.4356 0.0026 0.434	POJ/PT CPB 3 0.1722 3 0.1695 5 0.1710 6 0.1715 7 0.1724	SS = 1 59113 CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619	RUN 126. 126. 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2998 0.3270	90. DEG.F RUN NO CR CAT 0.0128 0.4533 0.0111 0.4466 0.0079 0.4412 0.0057 0.4386 0.0036 0.4356 0.0026 0.4314 0.0010 0.4314	POJ/PT CPB 3 0.1722 3 0.1687 2 0.1695 5 0.1710 5 0.1715 7 0.1724 9 0.1728	SS = 1 59113 CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619 0.2590	RUN 126. 126. 126. 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178 -0.0612	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819 0.6005	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422 -0.0396	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2998 0.3270 0.2986	90. DEG.F RUN NO CR CAT 0.0128 0.4533 0.0111 0.4466 0.0079 0.4412 0.0057 0.4356 0.0036 0.4356 0.0026 0.4314 0.0010 0.4314	POJ/P7 CPB 3 0.1722 3 0.1695 6 0.1710 6 0.1715 7 0.1724 9 0.1728 0 0.1715	CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619 0.2590 0.2565	RUN 126. 126. 126. 126. 126. 126.
Q= P0= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13 -0.39 -0.88	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178 -0.0612 -0.1384	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819 0.6005 1.3647	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422 -0.0396 -0.0383	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2988 0.3270 0.2986- 0.2851-	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4461: 0.0079 0.441: 0.0057 0.438: 0.0036 0.435: 0.0026 0.436: 0.0010 0.431: -0.0008 0.428: -0.0020 0.4248	POJ/PT CPB 3 0.1722 8 0.1687 2 0.1695 6 0.1710 6 0.1715 3 0.1724 9 0.1728 0.1725 0.1692	SS = 1 59113 CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619 0.2590 0.2565	RUN 126. 126. 126. 126. 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13 -0.39 -0.88 -1.40	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178 -0.0612 -0.1384 -0.2174	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819 0.6005 1.3647 2.1448	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422 -0.0396 -0.0483 -0.0461	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2998 0.3270 0.2986- 0.2851- 0.3650-	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4460 0.0079 0.441: 0.0057 0.4380 0.0036 0.4350 0.0026 0.4310 0.0010 0.4310 0.0010 0.4310 0.0008 0.4280 0.0020 0.4240 0.0036 0.4210	POJ/PT CPB 3 0.1722 8 0.1687 2 0.1695 6 0.1710 6 0.1715 7 0.1724 9 0.1728 0.1692 0.1658	CAF 0.2811 0.2781 0.2781 0.2717 0.2676 0.2641 0.2619 0.2565 0.2556	RUN 126. 126. 126. 126. 126. 126. 126. 126.
Q= P0= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13 -0.39 -0.88 -1.40 -1.90	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178 -0.0612 -0.1384 -0.2174 -0.2925	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819 0.6005 1.3647 2.1448 2.8892	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422 -0.0396 -0.0480	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2986 0.2986- 0.2851- 0.3650- 0.3808-	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4460 0.0079 0.441: 0.0057 0.4380 0.0036 0.4350 0.0026 0.4310 0.0010 0.4314 0.0010 0.4210 0.0008 0.4280 0.0008 0.4281 0.0008 0.4211	POJ/P7 CPB 3 0.1722 8 0.1687 2 0.1695 5 0.1710 5 0.1724 9 0.1728 3 0.1724 0.1692 1 0.1658 6 0.1641	CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619 0.2550 0.2556 0.2553 0.2552	RUN 126. 126. 126. 126. 126. 126. 126. 126.
Q= PO= ALPHA 4.19 3.19 2.18 1.65 1.15 0.65 0.13 -0.39 -0.88 -1.40 -1.90 -2.91	8.29 PSI 107.0 CMI CN 0.6563 0.4949 0.3346 0.2493 0.1736 0.0953 0.0178 -0.0612 -0.1384 -0.2174	RE PER HG PTS= CM -6.5048 -4.9039 -3.3150 -2.4741 -1.7230 -0.9490 -0.1819 0.6005 1.3647 2.1448 2.8892 4.4647	IN.= .48E0 3.8665 PSI CS -0.0342 -0.0343 -0.0415 -0.0383 -0.0474 -0.0396 -0.0422 -0.0396 -0.0480	CY 0.2380 0.2409 0.3168 0.2849 0.3780 0.2998 0.3270 0.2851- 0.3650- 0.3808- 0.3577-	90. DEG.F RUN NO CR CAT 0.0128 0.453: 0.0111 0.4460 0.0079 0.441: 0.0057 0.4380 0.0036 0.4350 0.0026 0.4310 0.0010 0.4310 0.0010 0.4310 0.0008 0.4280 0.0020 0.4240 0.0036 0.4210	POJ/P? CPB 3 0.1722 3 0.1687 2 0.1695 5 0.1710 5 0.1724 9 0.1725 3 0.1692 1 0.1658 6 0.1641 3 0.1628	CAF 0.2811 0.2781 0.2717 0.2676 0.2641 0.2619 0.2556 0.2553 0.2552 0.2495	RUN 126. 126. 126. 126. 126. 126. 126. 126.

KOD	EL 946.2	CON	FIG. 3.450	М	ACH 1.75	5	PHI =	90-	
Q=	8.29 PSI	RE PEP.	IN.= .48E0	6 TC=	90. DE	EG.F	POJFP	TŞ ≃	20.
P0=	107.0 CM	HG PTS=	3.8665 PSI			RUN NO.	02802	59 <u>11</u> 4	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.20	0.6508	~6.4141	-0.0438	0.2395	0.0309	0.4554	0.1745	0.2809	127.
3.19	0.4884	-4.8108	-0.0432	0.2392	0.0257	0.4482	0.1699	0.2783	
2.18	0.3301	-3.2560	-0.0537	0.3528	0.0170	0.4420	0.1708	0.2712	127.
	0.2501	-2.4711	-0.0595		0.0114				
	0.1715		-0.0622		0.0075				
	0:0936		-0.0603		0.0036				
0.13	0.0132		-0.0526		0.0009				
	-0.0601		-0.0674		-0.0024				
	-0.1377		-0.0687		-0.0056				
	-0.2146		-0.0648		-0.0089				
	-0.2887		-0.0595		-0.0121				
	-0.4443		-0.0596		-0.0186				
-3.93	-0.6072	5.9653	-0.0558	0.3809-	-0.0235	0.4111	0.1655	0.2456	127.
	EL 946.2 8.29 PSI		FIG. 3.450 IN.= .48E0		ACH 1.79		PHI =		40.
Q=	8-29 PSI	RE PER		6 TO=		G.F		rs =	40.
Q= P0≃	8.29 PSI 107.0 CM	RE PER	IN.= .48E0	6 TO=	90. DE	EG.F RUN NO.	POJ/P	rs = 69115	,
Q=	8-29 PSI	RE PER	IN.= .48E0	6 TO=		G.F	P0J/P	rs =	40• • RUN
Q= PO≃ ALPHA	8.29 PSI 107.0 CM	RE PER HG PTS=	IN.= .48E0 3.8665 PSI	6 TO=	90. DE	EG.F RUN NO. CAT	POJ/P	TS = 69115 CAF	· RUN
Q= PO≃ ALPHA 4.21	8.29 PSI 107.0 CM CN 0.6366	RE PER HG PTS= CH -6.2197	IN.= .48E0 3.8665 PSI CS -0.0819	6 TO= . CY 0.4405	90. DE CR 0.0579	EG.F RUN NO. CAT 0.4592	POJ/P 02802 CP8 0.1753	TS = 69115 CAF 0.2839	• RUN
Q= PO= ALPHA 4.21 3.20	8.29 PSI 107.0 CM CN 0.6366 0.4812	RE PER HG PTS= CM -6.2197 -4.7058	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910	6 TO= . CY 0.4405 0.5525	90. DE CR 0.0579 0.0421	EG.F RUN NO. CAT 0.4592 0.4509	POJ/P° . 028020 CP8 0.1753 0.1702	TS = 69115 CAF 0.2839 0.2867	- RUN 128 - 128 -
Q= P0= ALPHA 4.21 3.20 2.18	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976	6 TO= . CY 0.4405 0.5525 0.6320	90. DE CR 0.0579 0.0421 0.0268	CAT 0.4592 0.4509 0.4481	POJ/P . 028020 CP8 0.1753 0.1702 0.1728	TS = 69115 CAF 0.2839 0.2867 0.2752	RUN 128 • 128 • 128 •
Q= PO= ALPHA 4.21 3.20 2.18 1.66	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890 -2.4102	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029	6 T0= . CY 0.4405 0.5525 0.6320 0.6921	90. DE CR 0.0579 0.0421 0.0268 0.0192	CAT 0.4592 0.4509 0.4481 0.4450	POJ/P . 028020 CP8 0.1753 0.1702 0.1728 0.1742	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2707	RUN 128. 128. 128. 128.
Q= PO= ALPHA 4.21 3.20 2.18 1.66 1.14	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258	RE PER HG PTS= CH -6.2197 -4.7058 -3.1890 -2.4102 -1.6543	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976	6 TO= CY 0.4405 0.5525 0.6320 0.6921 0.7219	90. DE CR 0.0579 0.0421 0.0268 0.0192 0.0124	CAT 0.4592 0.4509 0.4481 0.4450	POJ/P . 028020 CP8 0.1753 0.1702 0.1726 0.1742 0.1771	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2707	RUN 128. 128. 128. 128.
Q= PO= ALPHA 4.21 3.20 2.18 1.66 1.14	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461 0.1685	RE PER HG PTS= CH -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055	6 T0= CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418	90. D8 CR 0.0579 0.0421 0.0268 0.0192 0.0124 0.0077	CAT 0.4592 0.4599 0.4481 0.4450 0.4446	POJ/P . 02802 CP8 0.1753 0.1702 0.1726 0.1742 0.1771 0.1787	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2752 0.2675	RUN 128. 128. 128. 128. 128.
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927	RE PER HG PTS= CH -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122 -0.1658	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055 -0.1074	CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722	90. DE CR 0.0579 0.0421 0.0268 0.0192 0.0124	CAT 0.4592 0.4599 0.4481 0.4446 0.4429 0.4396	POJ/P . 02802 CP8 0.1753 0.1702 0.1726 0.1742 0.1771 0.1787	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2757 0.2675 0.2642 0.2609	RUN 128. 128. 128. 128. 128. 128.
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11 -0.37	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927 0.0165	RE PER HG PTS= CH -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122 -0.1658 0.5435	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1029 -0.1074 -0.1003	6 T0= CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722 0.6707-	90. D8 CR 0.0579 0.0421 0.0268 0.0192 0.0124 0.0077	CAT 0.4592 0.4599 0.4481 0.4450 0.4446 0.4429 0.4396 0.4372	POJ/P . 02802 . CP8 0.1753 0.1702 0.1742 0.1742 0.1771 0.1787 0.1788 0.1779	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2767 0.2675 0.2642 0.2592	RUN 128. 128. 128. 128. 128. 128. 128.
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11 -0.37 -0.88	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927 0.0165 -0.0562	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122 -0.1658 0.5435 1.2848	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055 -0.1074 -0.1003 -0.1002	CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722 0.6707- 0.6685-	90. DE CR 0.0579 0.0421 0.0268 0.0192 0.0124 0.0077 0.0025	CAT 0.4592 0.4599 0.4450 0.4446 0.4446 0.4446 0.4429 0.4396 0.4372 0.4354	POJ/P . 02802 . CP8 0.1753 0.1702 0.1726 0.1742 0.1771 0.1787 0.1788 0.1779 0.1755	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2675 0.2642 0.2699 0.2592	RUN 128. 128. 128. 128. 128. 128. 128. 128.
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11 -0.37 -0.88 -1.40	8.29 PSI 107.0 CMI CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927 0.0165 -0.0562 -0.1320	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890 -2.4102 -1.658 -0.9122 -0.1658 0.5435 1.2848 2.0271	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055 -0.1074 -0.1003 -0.1002 -0.1002	CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722 0.6707- 0.6685-	90. DE CR 0.0579 0.0421 0.0192 0.0194 0.0077 0.0025 0.0025	CAT 0.4592 0.4509 0.4450 0.4456 0.4446 0.4429 0.4396 0.4372 0.4354 0.4324	POJ/P . 02802 . CP8 0.1753 0.1702 0.1726 0.1742 0.1747 0.1787 0.1788 0.1779 0.1755 0.1725	TS = 69115 CAF 0.2839 0.2867 0.2757 0.2675 0.2642 0.2609 0.2599	RUN 128. 128. 128. 128. 128. 128. 128. 128.
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11 -0.37 -0.88 -1.40 -1.90 -2.92	8.29 PSI 107.0 CMI CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927 0.0165 -0.0562 -0.1320 -0.2082 -0.2810 -0.4353	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122 -0.1658 0.5435 1.28435 1.28435 1.2871 2.7373 4-2396	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055 -0.1074 -0.1003 -0.1002 -0.1002 -0.1002 -0.1002 -0.0963 -0.0886	CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722 0.6707- 0.6685- 0.6854- 0.6180- 0.5273-	90. DE CR 0.0579 0.0421 0.0268 0.0192 0.0124 0.0077 0.0025 0.0025 0.0086 0.0139 0.0203	CAT 0.4592 0.4509 0.4481 0.4450 0.4446 0.4429 0.4396 0.4372 0.4372 0.4324 0.4273 0.4197	POJ/P . 02802 . CP8 0.1753 0.1702 0.1726 0.1742 0.1771 0.1787 0.1788 0.1775 0.1725 0.1725 0.1702	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2707 0.2675 0.2642 0.2509 0.2599 0.2591 0.2538	RUN 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 -
Q= P0= ALPHA 4.21 3.20 2.18 1.66 1.14 0.63 0.11 -0.37 -0.88 -1.40 -1.90 -2.92	8.29 PSI 107.0 CM CN 0.6366 0.4812 0.3258 0.2461 0.1685 0.0927 0.0165 -0.0562 -0.1320 -0.2082 -0.2810	RE PER HG PTS= CM -6.2197 -4.7058 -3.1890 -2.4102 -1.6543 -0.9122 -0.1658 0.5435 1.28435 1.28435 1.2871 2.7373 4-2396	IN.= .48E0 3.8665 PSI CS -0.0819 -0.0910 -0.0976 -0.1029 -0.1055 -0.1074 -0.1003 -0.1002 -0.1002 -0.1002 -0.1002 -0.1002 -0.1002 -0.1002	CY 0.4405 0.5525 0.6320 0.6921 0.7219 0.7418 0.6722 0.6707- 0.6685- 0.6854- 0.6180- 0.5273-	90. DE CR 0.0579 0.0421 0.0268 0.0192 0.0124 0.0077 0.0025 -0.0086 -0.0139 -0.0203	CAT 0.4592 0.4509 0.4481 0.4450 0.4446 0.4429 0.4396 0.4372 0.4372 0.4324 0.4273 0.4197	POJ/P . 02802 . CP8 0.1753 0.1702 0.1726 0.1742 0.1771 0.1787 0.1788 0.1775 0.1725 0.1725 0.1702	TS = 69115 CAF 0.2839 0.2867 0.2752 0.2707 0.2675 0.2642 0.2509 0.2599 0.2591 0.2538	RUN 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 - 128 -

GGH	EL 946.2	COM	FIG. 3.450	H	ICH 1.7:	ž	PHI =	90.	
Q≃	8.29 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	P0J/P	rs =	80.
₽0=	107.0 CH	HG PTS=	3.8665 PSI			RUN NO.	. 02802	69116	
ALPHA	CN	CM	cs	CY	CR	CAT	CP8	EAF	RUN
4.22	0.6345	-6.1440	-0.1652	0.9355	0.0814	0.4700	0.1834	0.2866	129.
3-21	0.4763	-4.6095	-0.1841	1.1507	0.0612	0.4632	0.1784	0.2848	129.
2.18	0.3201	-3.0997	-0.1920	1.2518	0.0399	0.4577	0.1776	0-2801	129.
1.66	0.2404		-0.1954			0.4547			
	0.1649		-0.2065			0.4531			
	0.0915		-0.2025			0.4520			
	C.0180		-0.2070			0.4497			
	-0.0536		-0.2024			0.4473			
	-0.1271		-0.2005			0.4456			
_	-0.2020		-0.1972			0.4432			
	-0.2737		-0.1842			0-4413			
	-0.4278		-0.1754			0.4379			
~3.95	-0.5867	5.6465	-0.1628	0.9585-	-0.0792	0.4342	0.1783	0.2560	129.
	FL 946.2 8.29 PSI	CONF RE PER	FIG0000 IN.= .48E0		ACH 1.7:		PHI =	• TS =	•
Q=	8.29 PSI	RE PER		6 TO=		EG.F	-	TS =	•
Q=	8.29 PSI	RE PER	IN.= .48E0	6 TO=		EG.F	POJ/P	TS =	• RUN
Q= PO= ALPHA	8.29 PSI 107.0 CM	RE PER HG PTS=	IN.= .48E0 3.8665 PSE	6 TO=	90. DI	EG.F RUN NO CAT	POJ/P	TS = 69117 CAF	
Q= PO= ALPHA 4.09	8.29 PSI 107.0 CM	RE PER HG PTS= CM -1.1656	IN.= .48E0 3.8665 PSE CS ~2.0044	6 TO= CY 0.0111-	90. DI CR -0.0012	EG.F RUN NO CAT 0.3131	POJ/P' - 028020 - CPB - 0-1672	TS = 69117 CAF C-1459	130.
Q= PO= ALPHA 4.09 3.06	8.29 PSI 107.0 CM CN 0.1978 G.1472	RE PER HG PTS= CM -1.1656 -0.8631	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080	6 TO= CY 0.0111- 0.0429-	90. DI CR -0.0012-	EG.F RUN NO CAT 0.3131 0.3057	POJ/P • 028020 CPB 0•1672 0•1620	TS = 69117 CAF 0-1459 0-1437	130.
Q= PO= ALPHA 4.09 3.06 2.03	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554	IN.= .48E0 3.8665 PSI CS -9.0044 -0.0080 -0.0063	6 TO= CY 0.0111- 0.0429- 0.0231-	90. D CR -0.0012- -0.0012 -0.0007	EG.F RUN NO. CAT 0.3131 0.3057 0.3016	POJ/P • 028020 CPB 0•1672 0•1620 0•1613	TS = 69117 CAF 0-1459 0-1437 0-1402	130. 130.
Q= PO= ALPHA 4.09 3.06 2.03 1.50	8.29 PSI 107.0 CM CN 0.1978 G.1472	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080	CY 0.0111- 0.0429- 0.0231- 0.9251-	90. D	EG.F RUN NO CAT 0.3131 0.3057	POJ/P 028020 CPB 0.1672 0.1620 0.1613 0.1626	TS = 69117 CAF 0-1459 0-1437 0-1402 0-1377	130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959 0.0693	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069	CY 0.0111- 0.0429- 0.0231- 0.0251- 0.0460-	90. Di CR -0.00120.00120.0007 -0.0001	CAT 0.3131 0.3057 0.3016 0.3003	POJ/P . 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632	TS = 69117 CAF 0-1459 0-1437 0-1402 0-1377	130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0100	CY 0.0111- 0.0429- 0.0231- 0.0251- 0.0460- 0.0536-	90. DI CR -0.00120.0007 -0.0001 -0.0015 -0.0013	CAT 0.3131 0.3057 0.3016 0.3003 0.3002	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.2645	TS = 69117 CAF 0-1459 0-1437 0-1402 0-1377 0-1369 0-1364	130. 130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46 -0.66	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465 0.0199	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077 0.0426	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0100 -0.0105	CY 0.0111- 0.0429- 0.0231- 0.0251- 0.0460- 0.0536- 0.0325-	90. DI CR -0.00120.0017 -0.0015 -0.0013 -0.0004	CAT 0.3131 0.3057 0.3016 0.3003 0.3002 0.3008	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.1645 0.1654	TS = 69117 CAF 0-1459 0-1437 0-1402 0-1377 0-1369 0-1364 0-1364	130. 130. 130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46 -0.06 -0.57	8.29 PSI 167.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465 0.0199 -0.0054	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077 0.0426 0.1255	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0105 -0.0083	CY 0.0111- 0.0429- 0.0231- 0.0251- 0.0460- 0.0536- 0.0325- 0.0495-	90. DO CR -0.00120.0007 -0.00130.00130.0004 -0.0007	CAT 0.3131 0.3057 0.3016 0.3003 0.3002 0.3008 0.2994	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.2645 0.1654 0.1658	TS = 69117 CAF 0-1459 0-1437 0-1369 0-1364 0-1341	130. 130. 130. 130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46 -0.66 -0.57	8.29 PSI 167.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465 0.0199 -0.0054 -0.0235	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077 0.0426 0.1255 0.2769	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0100 -0.0105 -0.0083 -0.0104	CY 0.0111- 0.0429- 0.0231- 0.9251- 0.9250- 0.0536- 0.0325- 0.0495- 0.0234-	90. DECR -0.0012-0.0007 -0.0001 -0.0013-0.0004 -0.0007 -0.0002	CAT 0.3131 0.3057 0.3016 0.3003 0.3002 0.3008 0.2994 0.2999	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.1645 0.1654 0.1658 0.1658	TS = 69117 CAF 0-1459 0-1437 0-1364 0-1364 0-1340 0-1328	130. 130. 130. 130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46 -0.66 -0.57 -1.07	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465 0.0199 -0.0054 -0.0235 -0.0489	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077 0.0426 0.1255 0.2769 0.4273	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0100 -0.0105 -0.0083 -0.0104 -0.0018	CY 0.0111- 0.0429- 0.0231- 0.0450- 0.0536- 0.0325- 0.0495- 0.0234- 0.0470	90. DECR -0.0012-0.0017-0.00013-0.0004-0.0007-0.0002-0.0004-0.0004-0.0004-0.0004	CAT 0.3131 0.3057 0.3016 0.3003 0.3002 0.3008 0.2994 0.2999 0.2998	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.1645 0.1654 0.1658 C.1670 0.1674	TS = 69117 CAF 0-1459 0-1437 0-1364 0-1364 0-1341 0-1328 0-1317	130. 130. 130. 130. 130. 130. 130. 130.
Q= P0= ALPHA 4.09 3.06 2.03 1.50 0.99 0.46 -0.06 -0.57 -1.60 -2.11	8.29 PSI 107.0 CM CN 0.1978 0.1472 0.0959 0.0693 0.0465 0.0199 -0.0054 -0.0235 -0.0489 -0.0742	RE PER HG PTS= CM -1.1656 -0.8631 -0.5554 -0.3990 -0.2711 -0.1077 0.0425 0.1255 0.2769 0.4273 0.5278	IN.= .48E0 3.8665 PSE CS ~9.0044 -0.0080 -0.0063 -0.0069 -0.0105 -0.0105 -0.0083 -0.0104 -0.0018 -0.0108	CY 0.0111- 0.0429- 0.0231- 0.0460- 0.0536- 0.0495- 0.0495- 0.0470 0.0550-	90. Di CR -0.0012-0.0012-0.0001 -0.0013-0.0004 -0.0004 -0.0002	CAT 0.3131 0.3057 0.3016 0.3003 0.3002 0.3008 0.2994 0.2999 0.2998 0.2998	POJ/P - 028020 CPB 0.1672 0.1620 0.1613 0.1626 0.1632 0.1654 0.1658 0.1654 0.1658 0.1674 0.1680	TS = 69117 CAF 0.1459 0.1437 0.1369 0.1364 0.1341 0.1328 0.1317 0.1308	130. 130. 130. 130. 130. 130. 130. 130.

HODE	L 946.2	CÖNF	FIG000	AM OC	CH 1.75	5	PHI =	•	
Q= 8	-29 PSI	RE PER	IN.= .488	06 TO=	90. DE	EG.F	POJ7P	T S =	10.
P0=	107.0 CH	HG PTS=	3.8665 PS	5 1		RUN NO	02802	69118	
ALPHA	CN	CH	cs:	CY	CR	CAT	CPB	CAF	RUN
4.09	0-1831	-1-0805	-0.0055	0.0309-	0.0013	0.3213	0.1709	0.1505	131.
	0.1305	-0.7591		0.0347-	0.0008	0.3133	0.1654	0.1478	
2.03	0.0787	-0.4463	-0.0086	0:0537-					
1.50	0.0520	-0.2861	-0.0084	0,0466-					
0.97	0.0286	-0.1520	-0.0084	0.0432-	0.0006				
	0.0001		-0.0079	0.0345-			0.1660		
-0.06 -			-0.0039	0.0409					
-0.58 -			-0.0077	0.0283-					
-1-10 -			-0.0030	-0.0137					
-1.63 -			-0.0099	0.0451					
-2.13 -			-0-0067	0.0176-					
-3.16 -			-0.0051	-0.0020			0.1731		
-4.20 -	0.2155	3.2743	-0.0043	-0.0012	0.0005	0.3143	0.1758	0.1385	131.
	î 945.2		FIG000		CH 1.75		PHI =	• rs =	20.
Q= 8	.29 PSI	RE PER		06 TO=		EG.F		TS =	20.
Q= 8	.29 PSI	RE PER	in.= ≠48(06 TO=		EG.F	POJ/P	TS =	20 . RUN
Q= 8 PO= Alpha	.29 PSI 107.0 CMI	RE PEK HG PTS=	IN.= €489 3,8665 PS	606 TO=	90. DE	EG.F RUN NO. CAT	POJ/P 028020 CPB	TS = 69119 CAF	RUN
Q= 8 PO= ALPHA 4.05	.29 PSI 107.0 CHI CN 0.1584	RE PEK HG PTS= CH -0.9138	in.= :489 3,8665 P3 CS -0:0018	06 TO= 51 CY -0.0197	90. DE CR 0.0008	EG.F RUN NO. CAT 0.3258	POJ/P 028020 CPB 0.1763	TS = 69119 CAF 0.1495	RUN 132.
Q= 8 PO= ALPHA 4.05 3.02	.29 PSI 107.0 CMI CN 0.1584 0.1072	RE PER HG PTS= CH -0.9138 -0.6012	in.= :489 3,8665 P3 CS -0:0018	606 TO=	90. DE CR 0.0008 0.0016	EG.F RUN NO. CAT 0.3258	POJ/P 028020 CPB 0.1763 0.1729	TS = 69119 CAF 0.1495	RUN 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99	.29 PSI 107.0 CMI CN 0.1584 0.1072 0.0566	RE PER HG PTS= CH -0.9138 -0.6012 -0.2933	IN.= 2485 3,8665 PS CS -0.0018 -0.0051	CY -0.0197:	90. DE CR 0.0008 0.0076	EG.F RUN NO. CAT 0.3258 0.3170 0.3122	POJ/P* . 028020 . CPB 0.1763 0.1729 0.1673	TS = 69119 CAF 0.1495 0.1450 0.1448	RUN 132• 132• 132•
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49	.29 PSI 107.0 CMI CN 0.1584 0.1072	RE PER HG PTS= CM -0.9138 -0.6012 -0.2933 -0.1149	IN.= :485 3.8665 PS CS -0:0018 -0:0051 -0:0042	CY -0.0197: 0.0089- 0.0027-	90. DE CR 0.0008 0.0076 0. 4	EG.F RUN NO. CAT 0.3258 0.3170 0.3122	POJ/P* . 028020 . CPB 0.1763 0.1729 0.1673 0.1673	TS = 69119 CAF 0.1495 0.1550 0.1448 0.1435	RUN 132. 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49 0.96	.29 PSI 107.0 CHI CN 0.1584 0.1072 0.0566 0.0281	RE PER HG PYS= CM -0.9138 -0.6012 -0.2933 -0.1149 0.0120	IN.= :489 3.8665 PS CS -0:0018 -0:0051 -0:0042 -0:0047	CY -0.0197: 0.0089- 0.0027- 0.0085-	90. DE CR 0.0008 0.0076 0.0002 0.0002	CAT 0.3258 0.3170 0.3122 0.3108 0.3094	POJ/P 028020 CPB 0.1763 0.1720 0.1673 0.1673 0.1682	TS = 69119 CAF 0.1495 0.1550 0.1448 0.1435	RUN 132. 132. 132. 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49 0.96	.29 PSI 107.0 CHI CN 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193	RE PER HG PTS= CM -0.9138 -0.6012 -0.2933 -0.1149 0.0120 0.1620	IN.= :485 3.8665 P3 CS -0.0018 -0.0051 -0.0042 -0.0047	CY -0.0197: 0.0089- 0.0027- 0.0065- 0.0168 0.0197- 0.0370	90. DE CR 0.0008 0.0076 0.0002 0.0001 0.0010 0.0006	CAT 0.3258 0.3122 0.3122 0.3108 0.3094 0.3066 0.3052	POJ/P 028020 CPB 0.1763 0.1673 0.1673 0.1682 0.1686	TS = 69119 CAF 0.1495 0.1448 0.1448 0.1435 0.1412 0.1381 0.1367	RUN 132. 132. 132. 132. 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49 0.96 0.44	.29 PSI 107.0 CMI CN 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193 0.0445	RE PER HG PTS= CH -0.6012 -0.2933 -0.1149 0.0120 0.1620 0.3157	IN.= :485 3.8665 P3 CS -0.0018 -0.0051 -0.0042 -0.0047 -0.0060 -0.0067	CY -0.0197 - 0.0089 - 0.0065 - 0.0168 0.0197 - 0.0370 0.0208 -	90. DE CR 0.0008 0.006 0.0002 0.0001 0.0010 0.0006	CAT 0.3258 0.3120 0.3122 0.3108 0.3094 0.3066 0.3052 0.3059	POJ/P . 028020 CPB 0.1763 0.1729 0.1673 0.1673 0.1686 0.1686 0.1686	TS = 69119 CAF 0.1495 0.1448 0.1448 0.1435 0.1367 0.1370	RUN 132. 132. 132. 132. 132. 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49 0.96 0.44 -0.07 -0.58 -1.11	0.1584 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193 0.0445 0.0731	RE PER HG PTS= CM -0.9138 -0.6012 -0.2933 -0.1149 0.0120 0.1620 0.3157 0.5021	IN.= = +35 3.8665 P3 CS -0.0018 -0.0051 -0.0042 -0.0067 -0.0067 -0.0080 -0.0064 -0.0021	CY -0.0197: 0.0089- 0.0085- 0.0168 0.0197- 0.0370 0.02080.0200	90. DE CR 0.0008 0.006 0.0001 0.0001 0.0006 0.0006 0.0014	CAT 0.3258 0.3120 0.3122 0.3128 0.3094 0.3052 0.3059 0.3059	POJ/P . 028020 CPB 0.1763 0.1729 0.1673 0.1673 0.1686 0.1686 0.1686 0.1688	TS = 69119 CAF 0.1495 0.1450 0.1448 0.1435 0.1367 0.1370 0.1370	RUN 132. 132. 132. 132. 132. 132. 132. 132.
Q= 8 P0= ALPHA 4.05 3.02 1.99 1.49 0.96 0.44 -0.07 -0.58 -1.11 -1.62	.29 PSI 107.0 CMI CN 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193 0.0445 0.0731 0.0906 0.1159	RE PER HG PYS= CH -0.9138 -0.6012 -0.2933 -0.1149 0.0120 0.1620 0.3157 0.5021 0.5719 0.7252	CS -0.0018 -0.0051 -0.0047 -0.0060 -0.0067 -0.0064 -0.0064 -0.0069	CY -0.0197 0.0089- 0.0027- 0.0065- 0.0168 0.0197- 0.0370 0.02080.0200 0.0160	90. DE CR 0.0008 0.006 0.0001 0.0001 0.0010 0.0006 0.0014 0.0017	CAT 0.3258 0.3170 0.3122 0.3108 0.3094 0.3052 0.3059 0.3059 0.3043 0.3043	POJ/P . 028020 . CPB 0.1763 0.1729 0.1673 0.1673 0.1686 0.1686 0.1688 0.1698 0.1707	TS = 69119 CAF 0.1495 0.1450 0.1448 0.1435 0.1381 0.1367 0.1370 0.1375	RUN 132. 132. 132. 132. 132. 132. 132. 132.
Q= 8 PO= ALPHA 4.05 3.02 1.99 1.49 0.96 0.44 -0.07 -0.58 -1.11 -1.62 -2.14	.29 PSI 107.0 CMI CN 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193 0.0445 0.0731 0.0906 0.1159 0.1406	RE PER HG PYS= CH -0.9138 -0.6012 -0.2933 -0.1149 0.0120 0.1620 0.3157 0.5021 0.5719 0.7252 0.8705	CS -0.0018 -0.0051 -0.0047 -0.0060 -0.0060 -0.0064 -0.0064 -0.0069 -0.0069	CY -0.0197: 0.0089- 0.0027- 0.0065- 0.0168 0.0197- 0.0370 0.02080.0200 0.0160, -0.0228	90. DE CR 0.0008 0.006 0.0002 0.0001 0.0006 0.0014 0.0017 0.0002	CAT 0.3258 0.3170 0.3122 0.3108 0.3094 0.3066 0.3052 0.3059 0.3043 0.3043 0.3043	POJ/P O28020 CPB 0.1763 0.1720 0.1673 0.1682 0.1686 0.1686 0.1688 0.1707 0.1722	TS = 69119 CAF 0.1495 0.1448 0.1435 0.1412 0.1367 0.1370 0.1370 0.1370 0.1370	RUN 132. 132. 132. 132. 132. 132. 132. 132.
Q= 8 P0= ALPHA 4.05 3.02 1.99 1.49 0.96 0.44 -0.07 -0.58 -1.11 -1.62	.29 PSI 107.0 CMI CN 0.1584 0.1072 0.0566 0.0281 0.0054 0.0193 0.0445 0.0731 0.0906 0.1159 0.1406	RE PER HG PYS= CH -0.9138 -0.6012 -0.2933 -0.1149 0.0120 0.1620 0.3157 0.5021 0.5719 0.7252 0.8705 1.1666	CS -0.0018 -0.0051 -0.0047 -0.0060 -0.0067 -0.0064 -0.0064 -0.0069	CY -0.0197 0.0089- 0.0027- 0.0065- 0.0168 0.0197- 0.0370 0.02080.0200 0.0160	90. DE CR 0.0008 0.0076 0.0002 0.0001 0.0006 0.0016 0.0017 0.0002 0.0002	CAT 0.3258 0.3170 0.3122 0.3108 0.3094 0.3066 0.3052 0.3059 0.3043 0.3043 0.3043	POJ/P O28020 CPB 0.1763 0.1729 0.1673 0.1673 0.1686 0.1686 0.1688 0.1707 0.1722 0.1728	TS = 69119 CAF 0.1495 0.1448 0.1435 0.1412 0.1381 0.1367 0.1376 0.1376 0.1376	RUN 132. 132. 132. 132. 132. 132. 132. 132.

MODEL 946.2	CONF	IG000	OG MA	ACH 1.75	5	PHI =	•	
Q= P.29 P\$1	RE PER	IN.= .486	06 TO=	90. DE	G.F	POJ/P	īs =	40.
PU= 107.0 CM	HG PTS=	3.8665 PS	1		RUN NO.	02802	69120	
ALPHA CN	CH	CS	CY	CR	CAT	СРВ	CAF	RUN
4.05 0-1153	-0.6157			-0.0005				
3.00 0.0569	-0.2373	-0.0096	0.0509	0.0003	0.3266	0.1738	0.1528	133.
1.96 0.0037	0.0938	-0.0055	0.0123-	-0.0010	0:3198	0.1689	0.1509	133.
1.45 -0.0248	0.2766	-0.0071	0.0265-	-0.0007	0.3158	0.1681	0.1477	133.
0.95 -0.0481	0.4138	-0.0092	0.0433-	-0.0004	0.3136	0-1684	0.1452	
0.41 -0.0780		-0.0090		-0.0002				
-0.10 -0.1027		-0.0044		0.0003				
-0.63 -0.1273		-0.0067		0.0005				
-1.14 -0.1545		-0.0062		0.0008				
-1.66 -0.1766		~0.0054		0.0003				
-2.18 -0.2026		-0.9050		0.0016				
-3.22 -0.2533		-0.0020	-0.0350					
-4.23 -0.3046	1.9677	-0.0016	-0.0318	0.0026	0.3170	0.1756	0.1414	133.
MODEL 946.2 Q= 8.29 PSI	CONF RE PER	FIG000		ACH 1.75		PHI =	• TS =	80.
	RE PER	IN.= .48E	:06 TO=		G.F	60 1\ b.	_	80.
Q= 8.29 PSI	RE PER	IN.= .48E	:06 TO=		G.F		_	80.
Q= 8.29 PSI	RE PER	IN.= .48E	:06 TO=		G.F	60 1\ b.	_	80 . RUN
Q= 8.29 PSI PO= 107.0 CM	RE PER HG PTS=	IN.= .48E	606 TO=	90 . Di	EG.F RUN NO.	POJ/P	69121 CAF	RÚN
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER HG PTS= CM 0.0891	IN.= .48E 3.8665 PS	E06 T0= SI CY 0.0947	90. D&	G.F RUN NO. CAT 0.3392	POJ/P 028020 CPB 0.1803	69121 CAF 0.1590	RÚN 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477	RE PER HG PTS= CM 0.0891 0.5167	IN.= .48E 3.8665 PS CS -0.0140 -0.0086	CY 0.0947 0.0407	90. Da	CAT 0.3392 0.3325	POJ/P D28020 CPB 0.1803 0.1735	69121 CAF 0.1590	RUN 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061	RE PER HG PTS= CM 0.0891 0.5167 0.9050	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034	CY 0.0947 0.0407 -0.0101	90. 08 CR 0.0002 0.0006 0.0010	CAT 0.3392 0.3325 0.3244	POJ/P . 028020 CPB 0.1803 0.1735 0.1686	69121 CAF 0.1590 0.1590 0.1558	RÚN 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033	CY 0.0947 0.0407 -0.0101 -0.0093	90. D8 CR 0.0002 0.0006 0.0010 0.0012	CAT 0.3392 0.3325 0.3244 0.3237	POJ/P . 028020 CPB 0.1803 0.1735 0.1686 0.1683	CAF 0.1590 0.1590 0.1558 0.1558	RÚN 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772 0.87 -0.1684	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060	90. D8 CR 0.0002 0.0006 0.0010 0.0012 0.0009	CAT 0.3392 0.3325 0.3244 0.3237 0.3205	POJ/P . 02802 CPB 0.1803 0.1735 0.1686 0.1683 0.1679	CAF 0.1590 0.1590 0.1558 0.1554 0.1526	RUN 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.172 0.87 -0.1684 0.36 -0.1937	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158	90. D8 CR 0.0002 0.0006 0.0010 0.0012 0.0009 0.0017	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197	POJ/P . 02802 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1682	69121 CAF 0.1590 0.1598 0.1558 0.1554 0.1526	RUN 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.172 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067 -0.0044	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088	90. D8 CR 0.0002 0.0006 0.0010 0.0012 0.0009 0.0017 0.0020	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197 0.3177	POJ/P . 02802 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1682 0.1687	CAF 0.1590 0.1590 0.1558 0.1558 0.1526 0.1515	RUN 134. 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.172 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599	IN.= .488 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067 -0.0044 -0.0036	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135	90. D8 CR 0.0002 0.0006 0.0010 0.0012 0.0009 0.0017 0.0020 0.0022	CAT 0.3392 0.3324 0.3237 0.3205 0.3197 0.3177 0.3170	POJ/P . 92802:	CAF 0.1590 0.1590 0.1558 0.1558 0.1526 0.1518 0.1489 0.1473	RUN 134. 134. 134. 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.172 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514 -1.17 -0.2741	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599 1.9981	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067 -0.0044 -0.0036 -0.0032	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135 -0.0184	90. D8 CR 0.0002 0.0006 0.0012 0.0009 0.0017 0.0020 0.0022 0.0024	CAT 0.3392 0.3325 0.3244 0.3237 0.3177 0.3177 0.3161	POJ/P . 92802:	CAF 0.1590 0.1590 0.1558 0.1558 0.1558 0.1516 0.1489 0.1473 0.1449	RUN 134. 134. 134. 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514 -1.17 -0.2741 -1.69 -0.3027	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599 1.9981 2.1790	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067 -0.0044 -0.0036 -0.0032 -0.0053	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135 -0.0184 -0.0065	90. D8 CR 0.0002 0.0006 0.0012 0.0017 0.0020 0.0022 0.0024 0.0027	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197 0.3177 0.3170 0.3161 0.3168	POJ/P . 92802 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1687 0.1697 0.1712	CAF 0.1590 0.1590 0.1558 0.1558 0.1526 0.1518 0.1449 0.1449	RUN 134. 134. 134. 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514 -1.17 -0.2741 -1.69 -0.3027 -2.22 -0.3300	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599 1.9981 2.1790 2.3465	IN.= .488 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0067 -0.0044 -0.0036 -0.0032 -0.0053 -0.0053 -0.0019	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135 -0.0184 -0.0065 -0.0307	90. D8 CR 0.0002 0.0006 0.0012 0.0009 0.0017 0.0020 0.0024 0.0027 0.0012	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197 0.3177 0.3161 0.3168 0.3175	POJ/P . 02802 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1682 0.1687 0.1697 0.1712 0.1727 0.1728	CAF 0.1590 0.1590 0.1558 0.1554 0.1526 0.1518 0.1449 0.1444 0.1444	RUN 134. 134. 134. 134. 134. 134. 134. 134.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514 -1.17 -0.2741 -1.69 -0.3027 -2.22 -0.3300 -3.26 -0.3800	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599 1.9981 2.1790 2.3465 2.6454	IN.= .48E 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0053 -0.0067 -0.0044 -0.0036 -0.0032 -0.0053 -0.0019 -0.0027	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135 -0.0184 -0.0065 -0.0307 -0.0284	90. D8 CR 0.0002 0.0006 0.0012 0.0009 0.0017 0.0020 0.0024 0.0027 0.0029	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197 0.3170 0.3161 0.3168 0.3175 0.3194	POJ/P . 028020 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1682 0.1687 0.1712 0.1727 0.1728 0.1725	CAF 0.1590 0.1590 0.1558 0.1554 0.1526 0.1489 0.1444 0.1447 0.1468	RUN 134. 134. 134. 134. 134. 134. 134. 134
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 3.98 0.0146 2.95 -0.0477 1.90 -0.1061 1.41 -0.1772 0.87 -0.1684 0.36 -0.1937 -0.16 -0.2209 -0.67 -0.2514 -1.17 -0.2741 -1.69 -0.3027 -2.22 -0.3300	RE PER HG PTS= CM 0.0891 0.5167 0.9050 1.1168 1.3257 1.4832 1.6540 1.8599 1.9981 2.1790 2.3465 2.6454	IN.= .488 3.8665 PS CS -0.0140 -0.0086 -0.0034 -0.0033 -0.0067 -0.0044 -0.0036 -0.0032 -0.0053 -0.0053 -0.0019	CY 0.0947 0.0407 -0.0101 -0.0093 0.0060 0.0158 -0.0088 -0.0135 -0.0184 -0.0065 -0.0307	90. D8 CR 0.0002 0.0006 0.0012 0.0009 0.0017 0.0020 0.0024 0.0027 0.0029	CAT 0.3392 0.3325 0.3244 0.3237 0.3205 0.3197 0.3170 0.3161 0.3168 0.3175 0.3194	POJ/P . 028020 CPB 0.1803 0.1735 0.1686 0.1683 0.1679 0.1682 0.1687 0.1712 0.1727 0.1728 0.1725	CAF 0.1590 0.1590 0.1558 0.1554 0.1526 0.1489 0.1444 0.1447 0.1468	RUN 134. 134. 134. 134. 134. 134. 134. 134

MOD	EL 946.2	CON	IG0000	н	ACH 1.75	5	PHI =	15.	
Ç=	8.29 PSI	RE PER	IN.= .48E0	6 T0=	90. D	EG.F	P0J/P	TS =	•
PO=	107.0 CM	HG PTS≃	3.8665 PSI			RUN NO.	02802	69122	
ALPHA	CN	CH	ĊS	CY	CR	CAT	CP8	CAF	RUN
4.09	0.1984	-1.1690	-0.0143	0.0838-	-0.0020	0.3184	0.1664	0.1520	135.
3.07	0.1469	-0.8585	-0.9122	0.0650	-0.0017	0.3135	0.1631	0.1504	135.
2.04	0.0968		-0.0100			0.3112			
1.51	0.0699	-0.4042				0.3100			
	0.0449	-0.2549				0.3131			
0.48	0.0204		-0.0074			0.3096			
	-0.0047		-0.0112			0.3097			
-	-0.0258		-3.0097			0.3094			
-	-0.0468	, .	-0.0088	-		0.3099			
	-0.0709		-0.0088			0.3111			
	-0.0940	–	-0.0100			0.3109			
	-0.1423		-0.0100			0.3127			
-4-10	-0.1949	1.1278	-0.0062	0.0237	0.0028	0.3192	0.1091	0.1495	135.
	PEL 946.2	CONF			ACH 1.75		PHI =	15.	10
Q=	8-29 PSI	RE PER	IN.= .48E0		ACH 1.75	EG.F	POJ/P	rs =	10.
Q=	8-29 PSI	RE PER				EG.F	_	rs =	10.
Q=	8.29 PSI = 107.0 CM	RE PER	IN.= .48E0			EG.F	POJ/P	rs =	10. RUN
Q= PO= ALPHA 4.08	8.29 PSI : 107.0 CM CN 0.1787	RE PER HG PTS= CM ~1.0416	IN.= .48E00 3.8665 PSI CS -0.0178	CY 0.1099-	90. DE CR -0.0024	EG.F RUN NO. CAT 0.3201	POJ/P1 028020 CPB 0•1696	FS = 69123 CAF 0.1505	RUN 136.
Q= P0= ALPHA 4.08 3.06	8.29 PSI : 107.0 CM CN 0.1787 0.1285	RE PER HG PTS= CM ~1.0416 -0.7393	IN.= .48E00 3.8665 PSI CS -0.0178 -0.0176	CY 0.1099- 0.1076-	90. DE CR -0.0024 -0.0022	EG.F RUN NO. CAT 0.3201 0.3144	POJ/P	FS = 69123 CAF 0.1505 0.1488	RUN 136. 136.
Q= PO= ALPHA 4.08 3.06 2.03	8.29 PSI = 107.0 CM CN 0.1787 0.1285 0.0784	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401	IN.= .48E00 3.8665 PSI CS -0.0178 -0.0176 -0.0155	CY 0.1099- 0.1076- 0.0886-	90. DECR-0.0024-0.0022-0.0019	EG.F RUN NO. CAT 0.3201 0.3144 0.3095	POJ/P3 028020 CPB 0.1696 0.1657 0.1643	FS = 69123 CAF 0.1505 0.1488 0.1452	RUN 136. 136.
Q= PO= ALPHA 4.08 3.06 2.03 1.49	8.29 PSI = 107.0 CM CN 0.1787 0.1285 0.0784 0.0502	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2681	IN.= .48E00 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132	CY 0.1099- 0.1076- 0.0886- 0.0691-	90. DECR-0.0024-0.0022-0.0019-0.0004	CAT 0.3201 0.3144 0.3095 0.3115	POJ/P3 028020 CPB 0.1696 0.1657 0.1643 0.1646	FS = 69123 CAF 0.1505 0.1488 0.1452 0.1469	RUN 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.98	8-29 PSI = 107.0 CM CN 0-1787 0-1285 0-0784 0-0502 0-0279	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2681 -0.1441	IN.= .48E08 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593-	90. DECR.	CAT 0.3201 0.3144 0.3095 0.3115 0.3093	POJ/P3 028020 CPB 0.1696 0.1657 0.1643 0.1646 0.1655	TS = 69123 CAF 0.1505 0.1488 0.1452 0.1469 0.1438	RUN 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.98 0.46	8.29 PSI = 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009	IN.= .48E08 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644	90. DE	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092	POJ/P ³ . 028020 . CPB 0.1696 0.1657 0.1643 0.1646 0.1655 0.1668	TS = 69123 CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423	RUN 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.98 0.46 -0.06	8.29 PSI : 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285	IN.= .48E08 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132 -0.0113	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644	90. DECR. CR0.0024 -0.0019 -0.0004 -0.0003 0.0004 0.0002	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097	POJ/P3 . 028020 CPB 0.1696 0.1657 0.1643 0.1646 0.1655 0.1668 0.1677	TS = 69123 CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423 C.1420	RUN 136. 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.46 -0.66	8-29 PSI = 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192 -0.0415	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285 0.2509	IN.= .48E06 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132 -0.0113 -0.0105	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644 0.0521	90. DE CR -0.0024 -0.0022 -0.0019 -0.0004 -0.0003 0.0004 0.0002	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097 0.3081	POJ/P3 . 028020 CPB 0.1696 0.1657 0.1668 0.1677 0.1683	CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423 0.1423 0.1429	RUN 136. 136. 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.46 -0.57 -1.08	8-29 PSI = 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192 -0.0415 -0.0661	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285 0.2509 0.3982	IN.= .48E06 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0132 -0.0132 -0.0113 -0.0105 -0.0110	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644 0.0521 0.0427	90. DE CR -0.0024 -0.0022 -0.0019 -0.0004 -0.0003 0.0004 0.0002 0.0006	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097 0.3081 0.3107	POJ/P3 O29020 CPB 0.1696 0.1657 0.1648 0.1677 0.1688 0.1677	CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423 0.1429 0.1398 0.1416	RUN 136. 136. 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.46 -0.57 -1.08 -1.60	8-29 PSI 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192 -0.0415 -0.0661 -0.0945	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285 0.2509 0.3982 0.5786	IN.= .48E06 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132 -0.0113 -0.0105 -0.0110	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0694- 0.0521 0.0427 0.0507	90. DE CR -0.0024 -0.0029 -0.0019 -0.0003 0.0004 0.0002 0.0006 0.0005 0.0003	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097 0.3081 0.3107 0.3113	POJ/P3 O29020 CPB 0.1696 0.1657 0.1643 0.1645 0.1668 0.1677 0.1683 0.1691 0.1691	CAF 0.1505 0.1488 0.1452 0.1463 0.1423 0.1429 0.1398 0.1416 0.1422	RUN 136. 136. 136. 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.98 0.46 -0.05 7-1.08 -1.60 -2.11	8.29 PSI E 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192 -0.0415 -0.0661 -0.0945 -0.1144	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285 0.2509 0.3982 0.5786 0.6776	IN.= .48E00 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132 -0.0113 -0.0105 -0.0105 -0.0100	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644 0.0521 0.0427 0.0507 0.0440	90. DE CR -0.0024 -0.0022 -0.0019 -0.0004 -0.0003 0.0004 0.0002 0.0005 0.0003 0.0013	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097 0.3081 0.3113 0.3113	POJ/P3 CPB 0.1696 0.1657 0.1643 0.1646 0.1655 0.1668 0.1677 0.1681 0.1691 0.1696	TS = 69123 CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423 C.1420 0.1398 0.1416 0.1422 0.1421	RUN 136. 136. 136. 136. 136. 136. 136. 136.
Q= P0= ALPHA 4.08 3.06 2.03 1.49 0.98 0.46 -0.57 -1.08 -1.60 -2.11 -3.15	8-29 PSI 107.0 CM CN 0.1787 0.1285 0.0784 0.0502 0.0279 0.0034 -0.0192 -0.0415 -0.0661 -0.0945	RE PER HG PTS= CM -1.0416 -0.7393 -0.4401 -0.2631 -0.1441 0.0009 0.1285 0.2509 0.3982 0.5786 0.6776 0.9449	IN.= .48E06 3.8665 PSI CS -0.0178 -0.0176 -0.0155 -0.0132 -0.0124 -0.0132 -0.0113 -0.0105 -0.0110	CY 0.1099- 0.1076- 0.0886- 0.0691- 0.0593- 0.0644 0.0521 0.0427 0.0487 0.0487	90. D8 CR -0.0024 -0.0022 -0.0019 -0.0004 -0.0003 0.0004 0.0005 0.0005 0.0003	CAT 0.3201 0.3144 0.3095 0.3115 0.3093 0.3092 0.3097 0.3081 0.3107 0.3113	POJ/P3 O28020 CPB 0.1696 0.1657 0.1643 0.1646 0.1655 0.1668 0.1677 0.1683 0.1691 0.1692 0.1699	TS = 59123 CAF 0.1505 0.1488 0.1452 0.1469 0.1438 0.1423 C.1420 0.1398 0.1416 0.1422 0.1421 0.1443	RUN 136. 136. 136. 136. 136. 136. 136. 136.

The most of the second of the

GOM	EL 946.2	ואמס	F1G0C00	MACH 1	.75	PHI =	15.	
Q=	8.29 PSI	KE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/P1	rs = 20.	
20=	107.0 CM	HG PTS=	3.8665 PSI		RUN NO	. 028026	9124	
ALPHA	CN	CM	cs	CY CR	CAT	CPB	CAF	RUN
4.07	0.1598	-0.9132	-0.0314	0.2207-0.00	13 0.3265	0.1747	0.1518	137.
	0.1078	-0.5958	-0.0273	0.1853-0.00				137.
2.02			-0.0216	0-1342-0-00				137.
	0.0282		-0.0203	0.1220 0.		0.1678		137.
	0.0005		-0.0221	0.1356-0.00				137.
	-0.0216		-0.0197	0.1168-0.00				137.
	-0.6432		-0.0161	0.0858 0.00				137.
	-0.0701 -0.0901		-0.0161 -0.0186	0.0851 0.00				137. 137.
	-0.0901 -0.1182	0.7556		0.0912-0.00				137.
	-0.1395		-0.0164	0.0923 0.00				137.
	-0.1884		-0.0165	0.0923 0.00				137.
	-0.2407		-0.0142	0.0784 0.00				137.
MOD	EL 946.2	CON	FIG0000	MACH 1	.75	PHI =	15.	
Q =	8.29 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/P1	rs = 40.	
P0≖	107.0 CM	HG PTS=	3.8665 PSI		RUN NO	. 028026	9125	
ALPHA	CN	CM	CS	CY CR	CAT	CPB	CAF	RUN
4.05	0 1202							138.
	0.1202	-0.6547	-0.0547	0.4047-0.	0.3321	0.1765	0.1556	.130 .
	0.0528		-0.0547 -0.0436	0.4047-0. 0.3062 0.009				
		-0.2819			01 0.3271	0.1722	0.1549	138.
1.99	0.0628	-0.2819 0.0570	-0.0436	0.3062 0.00	01 0.3271 03 0.3228	0.1722 0.1687	0.1549 0.1541	138.
1.99 1.46	0.0528 0.0090	-0.2819 0.0570 0.2578	-0.0436 -0.0404	0.3062 0.00	01 0.3271 03 0.3228 01 0.3167	0.1722 0.1687 0.1680	0.1549 0.1541 0.1487	138. 138.
1.99 1.46 0.94	0.0628 0.0090 -0.0216	-0.2819 0.0570 0.2578 0.4175	-0.0436 -0.0404 -0.0366	0.3062 0.000 0.2784-0.000 0.2386 0.000 0.2374-0.000 0.2192 0.000	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165	0.1722 0.1687 0.1680 0.1682 0.1685	0.1549 0.1541 0.1487 0.1484 0.1480	138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10	0.0628 0.0090 -0.0216 -0.0472 -0.0753 -0.1004	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487	-0.0436 -0.0404 -0.0366 -0.0359 -0.0336 -0.0372	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165 04 0.3144	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691	0.1549 0.1541 0.1487 0.1484 0.1480 0.1453	138. 138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10 -0.60	0.0628 0.0090 -0.0216 -0.0472 -0.0753 -0.1004 -0.1236	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487 0.8774	-0.0436 -0.0404 -0.0366 -0.0359 -0.0336 -0.0372 -0.0332	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00 0.2189 0.00	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165 04 0.3144 19 0.3156	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691 0.1700	0.1549 0.1541 0.1487 0.1484 0.1480 0.1453 0.1455	138. 138. 138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10 -0.60 -1.12	0.0528 0.0090 -0.0216 -0.0472 -0.0753 -0.1004 -0.1236 -0.1522	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487 0.8774 1.0648	-0.0436 -0.0404 -0.0366 -0.0359 -0.0336 -0.0372 -0.0332	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00 0.2189 0.00 0.2279 0.00	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165 04 0.3144 19 0.3156	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691 0.1700 0.1714	0.1549 0.1541 0.1487 0.1484 0.1480 0.1453 0.1455 0.1420	138. 138. 138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10 -0.60 -1.12 -1.65	0.0528 0.0090 -0.0216 -0.0472 -0.0753 -0.1004 -0.1236 -0.1522 -0.1758	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487 0.8774 1.0648 1.1975	-0.0436 -0.0404 -0.0366 -0.0359 -0.0372 -0.0332 -0.0341 -0.0332	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00 0.2189 0.00 0.2279 0.00 0.2221 0.00	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165 04 0.3144 19 0.3156 05 0.3135 18 0.3127	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691 0.1700 0.1714 0.1717	0.1549 0.1541 0.1487 0.1484 0.1453 0.1453 0.1455 0.1420 0.1410	138. 138. 138. 138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10 -0.60 -1.12 -1.65 -2.15	0.0628 0.0090 -0.0216 -0.0472 -0.0753 -0.1004 -0.1236 -0.1522 -0.1758 -0.1975	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487 0.8774 1.0648 1.1975 1.3188	-0.0436 -0.0404 -0.0366 -0.0359 -0.0372 -0.0332 -0.0341 -0.0332 -0.0322	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00 0.2189 0.00 0.2279 0.00 0.2221 0.00 0.2142 0.00	0.3271 0.3228 0.3167 0.3166 0.3166 0.3166 0.3146 0.3156 0.3156 0.3135 0.3135 0.3135	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691 0.1700 0.1714 0.1717 0.1720	0.1549 0.1541 0.1487 0.1484 0.1480 0.1453 0.1455 0.1420 0.1410	138. 138. 138. 138. 138. 138. 138. 138.
1.99 1.46 0.94 0.43 -0.10 -0.60 -1.12 -1.65 -2.15	0.0528 0.0090 -0.0216 -0.0472 -0.0753 -0.1004 -0.1236 -0.1522 -0.1758	-0.2819 0.0570 0.2578 0.4175 0.5967 0.7487 0.8774 1.0648 1.1975 1.3188 1.6374	-0.0436 -0.0404 -0.0366 -0.0359 -0.0372 -0.0332 -0.0341 -0.0332	0.3062 0.00 0.2784-0.00 0.2386 0.00 0.2374-0.00 0.2192 0.00 0.2499 0.00 0.2189 0.00 0.2279 0.00 0.2221 0.00	01 0.3271 03 0.3228 01 0.3167 02 0.3166 02 0.3165 04 0.3156 05 0.3135 18 0.3127 19 0.3145 21 0.3183	0.1722 0.1687 0.1680 0.1682 0.1685 0.1691 0.1700 0.1714 0.1717 0.1720 0.1719	0.1549 0.1541 0.1487 0.1484 0.1480 0.1453 0.1455 0.1455 0.1420 0.1410 0.1424 0.1464	138. 138. 138. 138. 138. 138. 138.

	MODE	L 946.2	CONI	FIG000	0 M	ACH 1.75	5	PHI =	15.	
	Q= 8	-29 PSI	RE PER	IN.= .48E	06 TO=	90. DE	EG.F	P0J/P	TS =	80.
	P0=	107.0 SM	HG PTS=	3.8665 PS	I		RUN NO	02802	69126	
ALP	HA	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
3.	99	0.0247	0.0082	-0.0922	0.6983	0.0007	0.3422	0.1768	0.1654	139.
		0.0349		-0.0826		0.0014				
		0.0957		-0.0714		0.0017				
	_	0.1281		-0.0682		0.0018				
		0.1611		-0.0654		0.0018				
		0.1884		-0.0659		0.0019				
		0.2167		-0.0629		0.0020				
		0.2434		-0.0632		0.0021				
		0.2700		-0.0661		0.0022				
		0.2981		-0.0638		0.0023				
		0.3221		-0.0642		0.0024				
		0.3721 0.4252		-0.0627 -0.0624		0.0023				
-4.	21 -	0.4252	2.9051	-0.0024	0.4230	0.0022	0.3311	0.1150	0.1302	139.
		L 946.2	CONI			ACH 1.75		PHI =		
	Q= 8	.29 PSI	RE PER	IN.= .48E	06 10=	90. DE	EG•F	601\b.	rs =	•
	PC=	107.0 CM	HG PTS=	3.8665 PS	I		RUN NO	02802	69127	
ALP	HA	CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.	01	0.1902	-1.1043	-0.0064	0.0011-	-0.0034	0.3001	0.1693	0.1308	140.
2.		0.1410		-0.0059		-0.0029				140.
.1.	95	0.0908	-0.5206	-0.0051		-0.0024				140.
ı.	42	0.0636	-0.3570	-0.0057	0.0048-	-0.0030	0.2956	0.1641	0.1315	140.
0.	90	0.0394	-0.2188	-0.0050	-0.0004-	-0.0025	0.2934	0.1649	0.1284	140.
0.	39	0.0157	-0.0823	-0.0012	-0.0352-	-0.0016	0.2963	0.1655	0.1308	140.
-0.	13	0.0003	-0.0261		-0.0467-	-0.0030	0.2939	0.1664	0.1275	140.
		0.0257		-0.0012	-0.0355					140.
		0.0564		-0.0075	0.0281-	-0.0034				140.
		0.0780		-0.0020	-0.0213			0.1682		140.
	_	0.0994		-0.0009	-0.0267-					140.
		0.1483		0.0002	-0.0344					140.
-4.	25 -	0.2015	1.1715	0.0020	-0.0491	0.0007	0.3101	0.1702	0.1399	140.

MODEL 946.2	CONF	IG0000	MACH 1	.75	PHI =	30.	
Q= 9.29 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/PT	s = 10) .
PO= 107.0 CM	HG PTS=	3.8665 PSI		RUN NO.	028026	9128	
ALPHA CN	СН	cs	CY CR	CAT	СРВ	CAF	RUN
4.00 0.1795	-1.0573	-0.0285	0.1901-0.003				141.
2.98 0.1257	-0.7231		0.1300-0.003				141.
1.94 0.0749	-0.4209		0.1031-0.002				141.
1.41 0.0445	-0.2250		0.1062-0.003				141.
0.90 0.0221	-0.1018		0.0585-0.003				141.
0.38 -0.0008		-0:0137	0.0597-0.002				141. 141.
-0.14 -0.0267 -0.65 -0.0488		-0.0177 -0.0126	0.0589 0.000				141.
-1.17 -0.0722	0.4406		0.0442-0.001				141.
-1.68 -0.0942		-0.0111	0.0500-0.000				141.
-2.21 -0.1205	0.7203		0.0735-0.000				141.
-3.23 -0.1650	0.9610		0.0163 0.000				141.
-4.26 -0.2178		-0.0055	0.0139 0.001				141.
MUDEL 946.2	CONF		MACH 1.		PHI =	30.	n
MUDEL 946.2 Q= 8.29 PSI		IG0000 IN.= .48E0			PHI =		D.
	RE PER	1N.= .48E0		DEG.F		'S = 20	0.
Q= 8.29 PSI	RE PER	1N.= .48E0		DEG.F	P0 J/ PT	'S = 20	D. RUN
Q= 8.29 PSI PO= 107.0 CF	RE PER	1N.= .48E0 3.8665 PSI CS	6 TO= 90.	DEG.F RUN NO.	P0J/PT . 028026 . CPB	S = 20 9129 CAF	
Q= 8.29 PSI PO= 107.0 CF ALPHA CN	RE PER 4HG PTS=	1N.= .48E00 3.8665 PSI CS -0.0449	6 FO= 90. CY CR 0.3273-0.003 0.2315-0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110	POJ/PT C28026 CPB 0-1732 0-1701	S = 20 9129 CAF 0.1419 0.1409	RUN [*] 142• 142•
Q= 8.29 PSI PO= 107.0 CF ALPHA CN 3.99 0.1654	RE PER HHG PTS= CM -0.9745	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347	6 F0= 90. CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079	POJ/PT . 028026 . CPB 0.1732 0.1701 0.1686	S = 20 9129 CAF 0.1419 0.1409 0.1393	RUN [*] 142. 142. 142.
Q= 8.29 PSI PU= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280	RE PER AHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064	POJ/PT C28026 CPB 0-1732 0-1701 0-1686 0-1682	CAF 0.1419 0.1409 0.1393 0.1382	RUN ⁻ 142. 142. 142. 142.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066	RE PER AHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315	6 T0= 90. CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-9.006	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064 04 0.3067	POJ/PT . 028026 . CP8 0.1732 0.1701 0.1686 0.1682 0.1686	CAF 0.1419 0.1409 0.1393 0.1382 0.1381	RUN [*] 142. 142. 142. 142. 142.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066 0.36 -0.0179	RE PER HHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328	6 T0= 90. CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-9.006 0.2152-0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064 04 0.3067 13 0.3051	POJ/PT . 028026 . CP8 0.1732 0.1701 0.1686 0.1682 0.1686 0.1691	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360	RUN [*] 142. 142. 142. 142. 142.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066 0.36 -0.0179 -0.15 -0.0434	RE PER HHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482 0.3013	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328 -0.0271	6 T0= 90. CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-0.000 0.2152-0.003 0.1643 0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064 04 0.3067 13 0.3051 20 0.3048	POJ/PT 028026 CPB 0.1732 0.1701 0.1686 0.1682 0.1686 0.1691 0.1692	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355	RUN 142. 142. 142. 142. 142. 142.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066. 0.36 -0.0179 -0.15 -0.0434 -0.66 -0.0746	RE PER HHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482 0.3013 0.5125	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328 -0.0271 -0.0326	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-0.003 0.2152-0.003 0.1643 0.003 0.2207-0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064 04 0.3067 13 0.3051 20 0.3048 09 0.3054	POJ/PT 028026 CPB 0.1732 0.1701 0.1686 0.1682 0.1686 0.1691 0.1692 0.1691	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355 0.1362	RUN 142. 142. 142. 142. 142. 142. 142.
Q= 8.29 PSI P0= 107.0 CF ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066. 0.36 -0.0179 -0.15 -0.0434 -0.66 -0.0746 -1.18 -0.0950	RE PER HHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482 0.3013 0.5125 0.6122	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328 -0.0271 -0.0326 -0.0292	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-0.000 0.2152-0.003 0.1643 0.003 0.2207-0.000 0.1932-0.	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3067 13 0.3051 20 0.3048 09 0.3054 0.3057	POJ/PT 028026 CPB 0.1732 0.1701 0.1686 0.1682 0.1686 0.1691 0.1692 0.1691 0.1697	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355 0.1362 0.1360	RUN 142. 142. 142. 142. 142. 142. 142. 142.
Q= 8.29 PSI PU= 107.0 CN ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066 0.36 -0.0179 -0.15 -0.0434 -0.66 -0.0746 -1.18 -0.0950 -1.70 -0.1134	RE PER HHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.012 0.1482 0.3013 0.5125 0.6122 0.6950	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328 -0.0271 -0.0326 -0.0292 -0.0268	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-9.000 0.2152-0.003 0.1643 0.003 0.2207-0.000 0.1932-0. 0.1672-0.	DEG.F RUN NO. CAT 19 0.3151 20 0.3110 27 0.3079 27 0.3064 04 0.3051 20 0.3051 20 0.3054 0.3057 0.3073	POJ/PT 028026 CPB 0.1732 0.1701 0.1686 0.1682 0.1691 0.1692 0.1691 0.1697 0.1704	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355 0.1362 0.1360 0.1370	RUN 142. 142. 142. 142. 142. 142. 142. 142
\$\psi = 8.29 PSI\$ PO = 107.0 C8 ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066 0.36 -0.0179 -0.15 -0.0434 -0.66 -0.0746 -1.18 -0.0950 -1.70 -0.1134 -2.21 -0.1379	RE PER 4HG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482 0.3013 0.5125 0.6122 0.6950 0.8406	IN.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0318 -0.0328 -0.0271 -0.0326 -0.0292 -0.0268 -0.0255	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-0.003 0.1643 0.003 0.2207-0.003 0.1932-0. 0.1672-0. 0.1593 0.003	DEG.F RUN NO. CAT 19 0.3151 20 0.3150 27 0.3079 27 0.3064 04 0.3067 13 0.3051 20 0.3048 0.3057 0.3073 02 0.3090	POJ/PT C28026 CPB 0.1732 0.1701 0.1686 0.1682 0.1686 0.1691 0.1692 0.1697 0.1704	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355 0.1360 0.1370 0.1381	RUN 142. 142. 142. 142. 142. 142. 142. 142. 142. 142.
Q= 8.29 PSI PU= 107.0 CN ALPHA CN 3.99 0.1654 2.97 0.1141 1.93 0.0576 1.40 0.0280 0.89 0.0066 0.36 -0.0179 -0.15 -0.0434 -0.66 -0.0746 -1.18 -0.0950 -1.70 -0.1134	RE PER AHG PTS= CM -0.9745 -0.6667 -0.3035 -0.1178 -0.0012 0.1482 0.3013 0.5125 0.6122 0.6950 0.8406 1.1363	1N.= .48E00 3.8665 PSI CS -0.0449 -0.0347 -0.0336 -0.0302 -0.0315 -0.0328 -0.0271 -0.0326 -0.0292 -0.0268	CY CR 0.3273-0.003 0.2315-0.003 0.2206-0.003 0.1917-0.003 0.2044-9.000 0.2152-0.003 0.1643 0.003 0.2207-0.000 0.1932-0. 0.1672-0.	DEG.F RUN NO. CAT 19 0.3151 20 0.3150 27 0.3079 27 0.3064 04 0.3067 13 0.3051 20 0.3048 09 0.3054 0.3057 0.3073 02 0.3090 08 0.3119	POJ/PT C28026 CPB 0-1732 0-1701 0-1686 0-1682 0-1686 0-1691 0-1692 0-1697 0-1704 0-1710	CAF 0.1419 0.1409 0.1393 0.1382 0.1381 0.1360 0.1355 0.1360 0.1370 0.1381 0.1404	RUN 142. 142. 142. 142. 142. 142. 142. 142

H	ODE	L 94	6.2		(CONF	-1G	,	-01	000	•	,	4AC	Н	1.7	5		P	HL	=		30.		
Q	= 8	-29	PSI	RE	: F	PER	IN.	,=	. 4!	BE06	•	TO:	=	90	. D	EG.F	:	P	1.0	/P	rs :	3	40.	
P	D=	107	0 CM	HG	PI	rs=	3.8	66	5 (SI						RUN	NO	. 0	28	026	592	30		
ALPH	A	CI	4	C	;H			c s			C	•		С	R	CA	T		C.P	8	C,	ÁF		RUN
3.9	7	0.13	339	-0.	77	750	-0.	08	41		0.6	386)-a	. 0	014	0.3	221	ø.	17	6),	٥.	1459	•	143.
2,9	4.	0.0	734	-0.	.37	724	-0.	06	87		0.4	899	5-0	. 0	010	0.3	186	0-	117	25	0.	146	ļ	143.
1.9	1	0.0	185	-0.	02	229	-0.	06	38		0.4	438	3-0	. 0	012	0.3	154	0.	86	93	0.	146	ι	143.
1.3	8 -	0.0	155	-			-0.									0.3								143.
0.8			-				-0.									0.3								143.
0.3							-0.									0.3								143.
-0.1							-0.									0.3								143.
-0.69							-0.									0.3								143.
-1.2							-0.		_							0.3								143.
-1.7							-0.									0.3								143.
-2.2							-0									0.3								143.
-3.2	_	-		_			-0									0.3								143.
-4.3	0 -	0.29	936	1.	.8	559	-0.	05	99		0.4	482	2 0	,, 0	020	0.3	206	0.	17	50	0.	1456	5	143.
			46•2 PSI	RE			IG.			000 BEQ6	,				1.79	5 EG.F	:		LO:		TS :	30• =	80.	
P	0=	107	.0 CM	HG	PΊ	rs≃	3.8	166	5 6	SI						RUN	NO	• 0	28	026	591	31		•
ALPH	A	CI	1	C	M			C S			CY	•		С	R	CA	T		C₽	В	C.	AF		RUN
3.9	3 (0.0	572	-0.	.26	569	-0.	15	23		1.1	563	3-0	• 0	800	0.3	316	0.	17	55	0.	1561	ı	144.
2.9	0 -	0.0	121	0.	2	319	-0.	13	35							0.3								144.
1.8	7 -	0.0	778	0.	.69	900	-0.	12	07							0.3								144.
1.34	4 -	0.1	112	0.	91	190	-0.	11	96							0.3								144.
0.8	2 -	0.14	116	1.	.12	21-1	-0.	11	84		0.8	3516	5 0	. 0	001	0.3	190	0.	16	97	0.	1503	3	144.
0.3	1 -	0.17	727				-0.	-			0.8	1456	5-Q	.0	003	0.3	201	0.	16	95	0.	1507	7	144.
-0.2	2 -	0.19	994	1.	50	200	-0.	12	01			3785										1490		144.
-0.7	3 -	0.22	224				-0.				0.8	3566	5-0	- 0	006	0.3	177	0.	17	02	0.	1474	\	144.
-1.2				1.	80	090	-0.	11	97							0.3								144.
-1.7	8 -	0.27	787	1.	98	328	-0.	12	18							0.3								144.
-2.2							-0.									0.3								144.
-3.3	2 -	0.34	497	2.	39	902	-0.	12	21		0.9	227	7 0	. 0	012	0.3	233	0.	17	09	0.	1524	į.	144.
-4.3	5 -	0.40	367	2.	.74	124	-0.	11	90		0.8	3998	3 0	- 0	019	0.3	283	0.	17	48	0.	1534	;	144.

AND THE PROPERTY OF THE PROPER

MODEL 946.2	CONI	FIG000	O MACI	H 1.75	PH1 =	45.	
Q= 8.29 PSI	RE PER	IN.= .48E	06 TO=	90. GEG.F	POJ/PT	'\$ [,] =	•
PO= 107.0 CF	HG PTS=	3.8665 PS	I	RUN NO.	028026	9133	
ALPHA CN	CH	cs	CY	CR CAT	CPB	CAF	RUŃ
4.19 0.2007		-0.0058		.0008 0.3151			145.
3.17 0.1487		-0.0079		.0005 0.3122			145.
2.14 0.0971		-0.0086		.0007 0.3107			145.
1.60 0.0727		-0:0049		.0006 0.3103			145.
1.09 0.0482		-0.0056		.0002 0.3091			145.
0.56 0.0247		-0.0046		.0023 0.3094			145.
0.05 0.0036		-0.0068		.0016 0.3102			145. 145.
-0.47 -0.0195		-0.0070 -0.0048		.0020 0.3111 .0024 0.3126			145.
-0.98 -0.0433	,	-0-0048		.0023 0.3136			145.
-1.50 -0.0704 -2.01 -0.0915		-0.0043		.0032 0.3143			145.
-3.04 -0.1420		-0.0053		.0035 0.3188			145.
-4.07 -0.1915		-0.0035		.0057 0.3259			145.
MODEL 946.2		FIG000		H 1.75	PHI =		
MODEL 946.2 Q= 8.29 PSI		FIG000 IN.= .48E		H 1.75 90. DEG.F	= IH9) .
	RE PER	IN.= .48E	06 TO=	90. DEG.F		S = 10) .
Q= 8.29 PSI	RE PER	IN.= .48E	06 TO=	90. DEG.F	POJ/PT	S = 10	P.UN
Q= 8.29 PSI PO= 107.0 CR	RE PER 4HG PTS= CM	IN.= .48E 3.8665 PS CS	06 TO= 1	90. DEG.F RUN NO.	POJ/PT 028026 CPB	S = 10 9134 CAF	
Q= 8.29 PSI PO= 107.0 CR ALPHA CN 4.18 0.1887	RE PER 4HG PTS= CM -1.1024	IN.= .48E	06 TO= 1 I CY 0.2169-0	90. DEG.F RUN NO. CR CAT	POJ/PT 028026 CPB 0-1765	S = 10 9134 CAF 0.1384	RUN
Q= 8.29 PSI PO= 107.0 CR	RE PER 4HG PTS= CM -1.1024 -0.7742	IN.= .48E 3.8665 PS CS -0.0309	06 TO= I CY 0.2169-0 0.1903 0	90. DEG.F RUN ND. CR CAT .0007.0.3150	POJ/PT - 028026 - CPB - 0-1765 - 0-1723	S = 10 9134 CAF 0.1384 0.1384	RUN 146.
Q= 8.29 PSI PO= 107.0 CR ALPHA CN 4.18 0.1887 3.16 0.1358	RE PER 4HG PTS= CM -1.1024 -0.7742 -0.4925	IN.= .48E 3.8665 PS CS -0.0309 -0.0285	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0	90. DEG.F RUN ND. CR CAT .0007. 0.3150 .0001. 0.3106	POJ/PT . 028026 CPB 0.1765 0.1723 0.1685	S = 10 9134 CAF 0.1384 0.1384 0.1417	RUN 146. 146. 146.
Q= 8.29 PSI PO= 107.0 C8 ALPHA CN 4.18 0.1887 3.16 0.1358 2.13 0.0872	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0	90. DEG.F RUN ND. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102	POJ/PT . 028026 CPB 0.1765 0.1723 0.1685 0.1672	S = 10 9134 CAF 0.1384 0.1384 0.1417 0.1432	RUN 146 • 146 •
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.18 0.1887 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0	90. DEG.F RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3108	POJ/PT 028026 CP8 0.1765 0.1723 0.1685 0.1672 0.1673 0.1677	CAF 0.1384 0.1384 0.1417 0.1432 0.1420 0.1430	RUN 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1887 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0	90. DEG.F RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3108 .0005 0.3111	POJ/PT . 028026 CP8 0.1765 0.1723 0.1685 0.1672 0.1673 0.1677 0.1683	S = 10 9134 CAF 0.1384 0.1384 0.1417 0.1432 0.1420 0.1430 0.1428	RUN 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1887 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143 0.04 -0.0149 -0.47 -0.0425	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149 0.2913	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192 -0.0223	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0 0.1418 0	90. DEG.F RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3108 .0005 0.3111 .6012 0.3127	POJ/PT . 028026 CP8 0.1765 0.1723 0.1685 0.1672 0.1673 0.1677 0.1683 0.1690	S = 10 9134 CAF 0.1384 0.1384 0.1417 0.1432 0.1420 0.1430 0.1428 0.1437	RUN 146. 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1887 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143 0.04 -0.0149 -0.47 -0.0425 -0.99 -0.0651	RE PER MHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149 0.2913 0.4151	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192 -0.0223 -0.0255	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0 0.1418 0	90. DEG.F RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3094 .0012 0.3108 .0005 0.3111 .6012 0.3127	POJ/PT . 028026 . CPB 0.1765 0.1723 0.1685 0.1672 0.1673 0.1677 0.1683 0.1690 0.1688	S = 10 9134 CAF 0.1384 0.1384 0.1417 0.1420 0.1420 0.1420 0.1428 0.1427	RUN 146. 146. 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1857 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143 0.04 -0.0149 -0.47 -0.0425 -0.99 -0.0651 -1.50 -0.0866	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149 0.2913 0.4151 0.5255	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192 -0.0223 -0.0195 -0.0185	06 T0= I CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0 0.1418 0 0.1148 0 0.1060 0	RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3108 .0005 0.3111 .6012 0.3127 .0016 0.3115	POJ/PT . 028026 . CPB 0.1765 0.1723 0.1685 0.1672 0.1673 0.1677 0.1683 0.1690 0.1688	S = 10 9134 CAF 0.1384 0.1384 0.1417 0.1432 0.1432 0.1430 0.1428 0.1437 0.1427 0.1431	RUN 146. 146. 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1857 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143 0.04 -0.0149 -0.47 -0.0425 -0.99 -0.0651 -1.50 -0.0866 -2.01 -0.1056	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149 0.2913 0.4151 0.5255 0.6205	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192 -0.0223 -0.0195 -0.0185 -0.0147	CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0 0.1418 0 0.148 0 0.1060 0 0.0691 0	90. DEG.F RUN ND. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3128 .0005 0.3111 .0012 0.3127 .0016 0.3115 .0023 0.3124 .0019 0.3138	POJ/PT 028026 CPB 0.1765 0.1723 0.1685 0.1672 0.1677 0.1687 0.1688 0.1690 0.1688 0.1693 0.1698	S = 10 9134 CAF 0.1384 0.1417 0.1432 0.1420 0.1430 0.1428 0.1427 0.1431 0.1440	RUN 146. 146. 146. 146. 146. 146. 146. 146.
Q= 8.29 PSI PO= 107.0 CN ALPHA CN 4.18 0.1857 3.16 0.1358 2.13 0.0872 1.60 0.0594 1.08 0.0342 0.56 0.0143 0.04 -0.0149 -0.47 -0.0425 -0.99 -0.0651 -1.50 -0.0866	RE PER HHG PTS= CM -1.1024 -0.7742 -0.4925 -0.3227 -0.1741 -0.0766 0.1149 0.2913 0.4151 0.5255 0.6205 0.9217	IN.= .48E 3.8665 PS CS -0.0309 -0.0285 -0.0222 -0.0206 -0.0198 -0.0149 -0.0192 -0.0223 -0.0195 -0.0185	CY 0.2169-0 0.1903 0 0.1310 0 0.1164 0 0.1092-0 0.0656 0 0.1114 0 0.1418 0 0.1418 0 0.1060 0 0.0691 0	RUN NO. CR CAT .0007 0.3150 .0001 0.3106 .0003 0.3102 .0001 0.3105 .0003 0.3094 .0012 0.3108 .0005 0.3111 .6012 0.3127 .0016 0.3115	POJ/PT 028026 CPB 0.1765 0.1723 0.1685 0.1677 0.1683 0.1690 0.1688 0.1693 0.1698 0.1698	S = 10 9134 CAF 0.1384 0.1417 0.1432 0.1420 0.1428 0.1428 0.1427 0.1431 0.1440 0.1488	RUN 146. 146. 146. 146. 146. 146. 146.

HO	DEL 946.2	CON	FIG0000	M	ACH 1.7	5	PHI =	45.	
Q=	8-29 PSI	RE PER	IN.= .48E0	6 T0=	90. 0	EG•F	POJ/P	TS = 2	0.
P0:	= 107.0 CM	HG PTS=	3,8665 PSI			RUN NO	02802	69135	
ALPHA	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.18	0.1743	-0.9999	-0.0638	0.4920	0.0001	0.3190	0.1778	0.1412	147.
3.15	0.1258	-0.7174	-0.0457	0.3109	0.0009	0.3150	0.1738	0.1412	147.
2.12	0.0730	-0.3942	-0.0417	0.2741	0.0011	0.3146	0.1701	0.1445	147.
1.59	0.0417	-0.1936	-0.0385	0.2482	0.0003	0.3109	0.1695	0.1414	147.
1.07	0.0199		-0.0364			0.3103			147.
	-0.0050		-0.0339			0.3118			147.
	-0.0299		-0.0334			0.3114			147.
	-0.0502		-0.0263			0.3121			147.
	-0.0795		-0.0351			0.3145			147.
	-0.1045		-0.0371					0.1457	147.
	-0.1292		-0.0339			0.3156			147.
	-0.1772		-0.0346			0.3200			147.
-4.09	-0.2302	1,4014	-0.0386	0.2742	0.0036	0.3273	0.1734	0.1539	147.
	0EL 946.2 8.29 PSI		FIG0000 IN.= .48E0		ACH 1.75		PHI =	45. 50 - 41	0.
4-	0427 F31	אב דבת	1114- 44050	0 19-	70. 0	20.1	, OU/ F	13	J•
P0=	= 107.0 CM	HG PTS=	3.8665 PSI			RUN NO	02802	69136	
ALPHA									
	CN	CM	cs	CY	CR	CÁT	СРВ	CAF	RUN
4.16	CN 0.1610		CS -0.0930	_		CAT 0.3243			RUN 148.
		-0.9596		0.6766	0.0012		0.1773	0.1470	148.
3.14	0.1610	-0.9596 -0.5195	-0.0930	0.6766 0.6548	0.0012 0.0013	0.3243	0.1773 0.1727	0.1470 0.1490	
3.14	0.1610 0.0971 0.0344	-0.9596 -0.5195 -0.1038	-0.0930 -0.0908	0.6766 0.6548 0.5773	0.0012 0.0013 0.0020	0.3243 0.3226	0.1773 0.1737 0.1710	0.1470 0.1490 0.1480	148. 148.
3.14 2.10 1.57	0.1610 0.0971 0.0344	-0.9596 -0.5195 -0.1038 0.0680	-0.0930 -0.0908 -0.0826	0.6766 0.6548 0.5773 0.5352	0.0012 0.0013 0.0020 0.0017	0.3243 0.3226 0.3190	0.1773 0.1737 0.1710 0.1705	0.1470 0.1490 0.1480 0.1466	148. 148. 148.
3.14 2.10 1.57 1.06	0.1610 0.0971 0.0344 0.0067	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483	148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02	0.1610 0.0971 0.0344 0.0067 -0.0226 -0.0436 -0.0724	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3171	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473	148. 148. 148. 148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02	0.1610 0.0971 0.0344 0.0067 -0.0226 -0.0436 -0.0724 -0.0957	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549 0.6796	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803 -0.0785	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767 0.5600	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006 0.0024	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3171 0.3173	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698 0.1705	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473 0.1469	148. 148. 148. 148. 148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02 -0.50 -1.01	0.1610 0.0971 0.0344 0.0067 -0.0216 -0.0436 -0.0724 -0.0957 -0.1220	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549 0.6796 0.8399	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803 -0.0785 -0.0775	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767 0.5600 0.5540	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006 0.0024 0.0023	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3171 0.3173 0.3175	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698 0.1705 0.1710	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473 0.1469 0.1466	148. 148. 148. 148. 148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02 -0.50 -1.01 -1.52	0.1610 0.0971 0.0344 0.0067 -0.0226 -0.0436 -0.0724 -0.0957 -0.1220 -0.1453	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549 0.6796 0.8399 0.9702	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803 -0.0785 -0.0775 -0.0803	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767 0.5600 0.5540 0.5841	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006 0.0024 0.0023 0.0024	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3171 0.3175 0.3175	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698 0.1705 0.1710	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473 0.1469 0.1468	148. 148. 148. 148. 148. 148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02 -0.50 -1.01 -1.52 -2.04	0.1610 0.0971 0.0344 0.0067 -0.0226 -0.0436 -0.0724 -0.0957 -0.1220 -0.1453 -0.1732	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549 0.6796 0.8399 0.9702 1.1473	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803 -0.0785 -0.0775 -0.0803 -0.0812	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767 0.5560 0.5540 0.5841 0.6005	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006 0.0024 0.0023 0.0024 0.0027	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3173 0.3175 0.3198 0.3207	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698 0.1705 0.1710 0.1710	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473 0.1469 0.1466 0.1488 0.1490	148. 148. 148. 148. 148. 148. 148. 148.
3.14 2.10 1.57 1.06 0.53 0.02 -0.50 -1.01 -1.52 -2.04 -3.08	0.1610 0.0971 0.0344 0.0067 -0.0226 -0.0436 -0.0724 -0.0957 -0.1220 -0.1453	-0.9596 -0.5195 -0.1038 0.0680 0.2496 0.3649 0.5549 0.6796 0.8399 0.9702 1.1473 1.4142	-0.0930 -0.0908 -0.0826 -0.0774 -0.0798 -0.0739 -0.0803 -0.0785 -0.0775 -0.0803	0.6766 0.6548 0.5773 0.5352 0.5644 0.5102 0.5767 0.55600 0.5540 0.6005 0.5841 0.6005	0.0012 0.0013 0.0020 0.0017 0.0010 0.0011 0.0006 0.0024 0.0023 0.0024 0.0027	0.3243 0.3226 0.3190 0.3171 0.3173 0.3181 0.3171 0.3175 0.3175	0.1773 0.1727 0.1710 0.1705 0.1697 0.1698 0.1698 0.1705 0.1710 0.1717 0.1717	0.1470 0.1490 0.1480 0.1466 0.1476 0.1483 0.1473 0.1469 0.1468 0.1488 0.1490 0.1515	148. 148. 148. 148. 148. 148. 148. 148.

нар	EL 946.2	CONI	F1G0000	Ma	ACH 1.75	PHI =	45.	
C=	8.29 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	4,rod	rs =	80.
PG=	107.0 CM	HG PTS=	3.8665 PSI		אן אטא	02892	69137	
AL PHA	CN	CM	CS	CY	CR CAT	CP8	CAF	RUN
4.13	0.0995	-0.5412	-0.1874	1.3917	0.0014 0.3366	0.1785	0.1581	149.
3.10	0.0298	-0.0426	-0.1741		0.0017 0:3320			
	-0.0376		-0.1613		0.0017 0.3295			
	-0.0735		-0.1672		0.0024 0.3294			
	-0.0998		-0.1597		0.0024 0.3260			_
	-0.1328		-0.1657		0.0022 0.3244			
	-0-1602		-0.1662		0.0025 0.3266			
	-0.1925		~0.1730		0.0023 0.3257			
	-0.2149		-0.1729		0.0016 0.3272			
-	-0.2353		-0.1658		0.0028 0.3280			
	-0.2586		-0.1658		0.0038 0.3302			
	-0.3128 -0.3654		-0.1601		0.0037 0.3326			
-4.15	-0.0004	2.4309	-0.1001	1.2109	0.0047 0.3391	0.1152	0.1034	149.
	EL 946.2		FIG0000		ACH 1.75	PHI =		
	EL 946.2 8.29 PSI		FIG0000 IN.= .48E0		ACH 1.75 90. DEG.F	PHI =		•
Q=	8.29 PSI	RE PER		6 10=	90. DEG.F		rs =	•
Q=	8.29 PSI	RE PER	IN.= ,48E0	6 10=	90. DEG.F	P0J/P	rs =	• RUN
Q= PO= Alpha	8.29 PSI 107.0 CM	RE PER HG PTS=	IN.= ,48E0	6 10= CY	90. DEG.F	POJ/P1 - 028026 CPB	TS = 69138 CAF	
Q= PO= Alpha	8.29 PSI 107.0 CM CN	RE PER HG PTS= CM -1.1471	1N.= ,48E0 3.8665 PSI	6 TO= CY 0.0622	90. DEG.F RUN NO CR CAT	POJ/P1 - 028026 - CPB - 0.1764	TS = 69138 CAF Q.1412	150.
Q= PO= ALPHA 4.11	8.29 PSI 107.0 CM CN 0.1962	RE PER HG PTS= CH -1.1471 -0.8402	IN.= ,48E0 3.8665 PSI CS -0.0128	6 TO= CY 0.0622 0.1196	90. DEG.F RUN NO CR CAT 0.0005 0.3116	POJ/P1 - 028026 - CPB - 0.1704 - 0.1694	TS = 69138 CAF Q.1412 0.1368	150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52	8.29 PSI 107.0 CM CN 0.1962 0.1452 0.0957 0.0671	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141	6 T0= CY 0.0622 0.1196 0.0794 0.0870	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3080	POJ/Pi - 028026 CPB 0-1704 0-1694 0-1669	TS = 69138 CAF Q.1412 0.1368 0.1399 0.1411	150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52	8.29 PSI 107.0 CM CN 0.1962 0.1452 0.0957	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103	6 T0= CY 0.0622 0.1196 0.0794 0.0870 0.0483	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3080 0.0007 0.3086	POJ/Pi - 028026 CPB 0.1704 0.1694 0.1669 0.1669	TS = 69138 CAF Q.1412 0.1368 0.1399 0.1411 0.1414	150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 Q.48	8.29 PSI 107.0 CM CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.0483 0.1203-	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3086 0.0007 0.3086	POJ/Pi - 028024 CPB - 0.1704 - 0.1694 - 0.1669 - 0.1672 - 0.1674	TS = 69138 CAF Q.1412 0.1369 0.1399 0.1411 0.1414 0.1439	150. 150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 0.48 -0.03	8.29 PSI 107.0 CM CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204 0.0137	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.0483 0.1203- 0.0973	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3080 0.0007 0.3080 0.0007 0.3113	POJ/Pi - 028024 CP8 0.1704 0.1694 0.1669 0.1669 0.1672 0.1674 0.1677	TS = 69138 CAF Q.1412 0.1369 0.1411 0.1414 0.1439	150. 150. 150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 0.48 -0.03 -0.56	8.29 PSI 107.0 CMI CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016 -0.0252	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204 0.0137 0.1436	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145 -0.0131	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.9870 0.0973 0.0973 0.0810	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3086 0.0007 0.3088 0.0007 0.3113 0.0015 0.3112 0.0013 0.3098	POJ/Pi - 028020 CP8 0.1704 0.1694 0.1669 0.1672 0.1674 0.1677	TS = 69138 CAF Q.1412 0.1368 0.1399 0.1411 0.1414 0.1439 0.1435	150. 150. 150. 150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 0.48 -0.03 -0.56 -1.06	8.29 PSI 107.0 CMI CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016 -0.0252 -0.0484	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204 0.0137 0.1436 0.2743	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145 -0.0131 -0.0126	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.1203- 0.0973 0.0810 0.0789	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3080 0.0007 0.3080 0.0005 0.3112 0.0015 0.3112 0.0013 0.3098 0.0021 0.3124	POJ/Pi - 028024 CP8 0.1704 0.1694 0.1669 0.1672 0.1674 0.1677 0.1681 0.1683	TS = 69138 CAF Q.1412 0.1368 0.1398 0.1411 0.1414 0.1439 0.1435 0.1417	150. 150. 150. 150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 0.48 -0.03 -0.56 -1.06 -1.58	8.29 PSI 107.0 CMI CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016 -0.0252 -0.0484 -0.0713	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.1204 0.0137 0.1436 0.2743 0.4052	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145 -0.0131 -0.0126 -0.0130	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.0483 0.1203- 0.0973 0.0810 0.0789 0.0824	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3086 0.0007 0.3112 0.0015 0.3112 0.0013 0.3098 0.0021 0.3124 0.0019 0.3143	POJ/Pi - 028024 CPB - 0.1704 0.1694 0.1669 0.1672 0.1674 0.1681 0.1683 0.1691	CAF CAF Q.1412 Q.1412 Q.1368 Q.1414 Q.1414 Q.1439 Q.1417 Q.1440 Q.1453	150. 150. 150. 150. 150. 150. 150.
Q= PO= ALPHA 4.11 3.08 2.05 1.52 1.00 Q.48 -0.03 -0.56 -1.58 -2.09	8.29 PSI 107.0 CM CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016 -0.0252 -0.0484 -0.0713 -0.0938	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204 0.0137 0.1436 0.2743 0.4052 0.5290	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145 -0.0131 -0.0126 -0.0130 -0.0091	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.0483 0.1203- 0.0973 0.0810 0.0789 0.0824 0.0474	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3086 -0.0004 0.3113 0.0015 0.3112 0.0013 0.3098 0.0021 0.3124 0.0019 0.3143 0.0030 0.3168	POJ/Pi - 028026 CP8 0.1704 0.1608 0.1669 0.1672 0.1677 0.1681 0.1683 0.1691	TS = 69138 CAF 0.1412 0.1368 0.1399 0.1411 0.1414 0.1439 0.1435 0.1417	150. 150. 150. 150. 150. 150. 150. 150.
Q= P0= ALPHA 4.11 3.08 2.05 1.52 1.00 0.48 -0.03 -0.56 -1.06 -1.58 -2.09 -3.13	8.29 PSI 107.0 CMI CN 0.1962 0.1452 0.0957 0.0671 0.0474 0.0215 -0.0016 -0.0252 -0.0484 -0.0713	RE PER HG PTS= CM -1.1471 -0.8402 -0.5523 -0.3769 -0.2790 -0.1204 0.0137 0.1436 0.2743 0.4052 0.5290 0.7969	IN.= ,48E0 3.8665 PSI CS -0.0128 -0.0181 -0.0139 -0.0141 -0.0103 -0.0173 -0.0145 -0.0131 -0.0126 -0.0130	6 T0= CY 0.0622 0.1196 0.0794 0.9870 0.0483 0.1203- 0.0973 0.0810 0.0789 0.0824 0.0474 0.0252	90. DEG.F RUN NO CR CAT 0.0005 0.3116 0.0005 0.3062 0.0004 0.3067 0.0007 0.3086 0.0007 0.3112 0.0015 0.3112 0.0013 0.3098 0.0021 0.3124 0.0019 0.3143	POJ/Pi - 028026 CP8 0.1704 0.1694 0.1669 0.1672 0.1677 0.1681 0.1683 0.1691 0.1691	TS = 69138 CAF 0.1412 0.1368 0.1399 0.1411 0.1414 0.1439 0.1445 0.1447 0.1440	150. 150. 150. 150. 150. 150. 150. 150.

H	ODEL	946.2	•	CONF	IG.	*0300	Mi	ACH 1.7	5	PHI =	60.		
Q	= 8.2	9 PSI	RE	PER	IN.=	e48E06	5 10=	90. D	EG.F	POJ/P	TS =	10.	
P	0= 10	7.0 CMH	IG P	TS=	3.86	55 PSI			RUN NO.	. 02802	69139		
ALPH	A i	CN	CH		C	s	EY.	CR	CAT	CP3	CAF	RU	N
4.1	1 0-	1949	-1 -1	586	-0.04	416	0.2983	0-0004	0.3147	0.1773	0-1379	5 151	
3.0					-0.0				0.3091				
2.0					-0.0			_	0.3103			-	
1.5					-0.0		0.2289	-		0.1697			
1.0	0 0.	0340	-0.1	748	-0.03	368	0.2614-	-0-	0.3117	0.1695	0.1422	2 151	•
0.4		0139	-0.0	759	-0.02	260	0.1586	0.0011	0.3093	0.1692	0.140		
-0.0	4 ~0.	0085	0.0	509	-0.0	282	0.1817	0.0020	0.3100	0.1695	0.1403	3 151	
-0.5	6 -0-	0354	0.2	168	-0.0	272	0.1724	0.0014	0.3139	0.1697	0.1442	2 151	•
-1.0	7 -0.	0596	0.3	538	-0.0	268	0.1736	0.0019	0.3132	0.1695	0.1437	7 151	•
-1.5	9 -0.	0854	0.5	041	-0.0	271	0.1788	0.0016	0.3145	0.1694	0.145	151	•
~2.1	0 -0.	1044	0.5	97.8	-9.03	222	0.1338	0.0022	0.3156	0.1700	0.1456	5 151	•
-3.1	3 -0.	1582	0.9	272	-0.0	268			0.3216				
-4.1	6 -0.	22,37	1.2	547	-0.0	286	0.2048	0.0041	0.3303	0.1746	0.1557	7 151	•
н	ODEL	946.2	(CONF	IG.	.0000	H.	ACH 1.75	5	PHI =	60.		
	ODEL '					-0000 -48E06		ACH 1.79		PHI =		20.	
Q	= 8.2		RE	PER	IN.=	-48E06			EG.F		rs =	20.	
Q	= 8.2° 0= 10°	9 PSI	RE	PER TS=	IN.=	•48E06			EG.F	P0J/P1	rs =	20+ RU	N
Q P ALPH	= 8.2° 0= 10° A	9 PSI 7.0 CMH CN	RE I	PER TS=	IN.= 3.866	•48E06	CY	90. DE	EG.F RUN NO. CAT	POJ/P1 028020 CP8	TS = 59140 CAF	RU	
Q P ALPH	= 8.2° 0= 10° A °	9 PSI 7.0 CMH CN 1951	RE (PER TS=	IN.=	.48E06 55 PSI 6	CY 0.5116	90. DE	EG.F RUN NO	POJ/P1 028020 CP9 0.1808	TS = 59140 CAF 0.1338	RU B 152	•
P ALPH 4.1	= 8.2° 0= 10° A ° 0 ° 0.	9 PSI 7.0 CMH CN 1951 1316	RE (PER TS= 841 615	IN.= 3.866 C:	•48E06 55 PSI 6 690 621	CY 0.5116 0.4478	90. DE CR 0.0013 0.0011	EG.F RUN NO. CAT 0.3146	POJ/P1 - 028026 - CP9 - 0.1808 - C.1758	TS = 59140 CAF 0.1338	RU B 152 5 152	•
P ALPH 4.1 3.0	= 8.2° 0= 10° A	9 PSI 7.0 CMH CN 1951 1316 0773	RE (PER TS= 841 615 317	IN.= 3.866 C: -0.06	•48E06	CY 0.5116 0.4478 0.3464	90. DECR 0.0013 0.0011 0.0010	EG.F RUN NO. CAT 0.3146 0.3123	POJ/PT - 028026 - CPS - 0.1808 - 0.1758 - 0.1721	CAF 0.1338 0.1365 0.1405	RU 8 152 5 152 5 152	•
P ALPH 4-1 3-0 2-0	= 8.2° 0= 10° A	9 PSI 7.0 CMH CN 1951 1316 0773 0528	RE (PER TS= 841 615 317 882	IN.= 3.866 C: -0.06 -0.06	•48E06	CY 0.5116 0.4478 0.3464 0.3365	90. DECR 0.0013 0.0011 0.0010 0.0010	EG.F RUN NO. CAT 0.3146 0.3123 0.3126	POJ/PT 028026 CPS 0.1808 C.1758 0.1721 0.1714	TS = 59140 CAF 0.1336 0.1365 0.1405 0.1399	RU B 152 5 152 5 152 0 152	•
P ALPH 4.1 3.0 2.0 1.5	= 8.2° 0= 10° A	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234	RE (PER TS= 841 615 317 882 954 539	IN.= 3.866 -0.06 -0.06 -0.06 -0.06 -0.06	.48E06 55 PSI 590 521 515 502 519	CY 0.5116 0.4478 0.3365 0.4586	90. DE CR 0.0013 0.0011 0.0010 0.0010	CAT 0.3146 0.3123 0.3126 0.3112	POJ/PT . 028026 CPS 0.1808 C.1758 0.1721 0.1714 0.1710	TS = 59140 CAF 0.1336 0.1365 0.1405 0.1406	RUI B 152 B 152 B 152 B 152 B 152 B 152	•
P ALPH 4.1 3.0 2.0 1.5 0.9	= 8.2° 0= 10° A	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019	RE (PER TS= 841 615 317 882 954 539	IN.= 3.866 -0.06 -0.06 -0.06 -0.06 -0.06	.48E06 55 PSI 590 521 515 502 519	CY 0.5116 0.4478 0.3365 0.4586 0.4069	90. D8 CR 0.0013 0.0011 0.0010 0.0010 0.0010	CAT 0.3146 0.3123 0.3126 0.3112 0.3121	POJ/PT . 028026 CPS 0.1808 C.1758 0.1721 0.1714 0.1710 0.1709	TS = 59140 CAF 0-1336 0-1365 0-1405 0-1396 0-1397	RUI 3 152 5 152 5 152 0 152 0 152 0 152	•
ALPH 4.1 3.0 2.0 1.5 0.9 0.4	= 8.2' 0= 10' A 0.0.7' 7' 0.0.4' 1' 0.0.1' 9' 0.0.1'	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019 0179	RE 11 CM -1.1: -0.70 -0.4: -0.2: -0.0: 0.1: 0.2:	PER TS= 841 615 317 882 954 539 124 961	IN.= 3.866 -0.06 -0.09 -0.09 -0.09 -0.09 -0.09	.48E06 55 PSI 590 521 515 502 519 565 650 672	CY 0.5116 0.4478 0.3464 0.3365 0.4069 0.2946 0.3216	90. D8 CR 0.0013 0.0010 0.0010 0.0010 0.0007 0.0033 0.0024	CAT 0.3146 0.3123 0.3126 0.3112 0.3099 0.3122 0.3116	POJ/PT . 028026 CPS 0.1808 C.1758 0.1721 0.1714 0.1710 0.1709 0.1707	CAF 0-1336 0-1365 0-1405 0-1405 0-1416 0-1396	RUI 3 152 5 152 5 152 0 152 0 152 0 152 152 152	
ALPH 4.1 3.0 2.0 1.5 0.4 -0.0 -0.5 -1.0	= 8.2' 0= 10' A	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019 0179 0469 0733	RE	PER TS= 841 615 317 882 954 539 124 961 550	IN.= 3.866 C: -0.06 -0.09 -0.09 -0.09 -0.09 -0.09 -0.09	.48E06 55 PSI 590 521 515 502 519 565 572 479	CY 0.5116 0.4478 0.3464 0.3365 0.4069 0.2946 0.3216 0.3292	90. D8 CR 0.0013 0.0010 0.0010 0.0010 0.0007 0.0033 0.0024 0.0023	CAT 0.3146 0.3123 0.3126 0.3112 0.3099 0.3122 0.3116 0.3142	POJ/PT . 028026 CPS 0.1808 C.1758 0.1721 0.1714 0.1719 0.1707 0.1707 0.1705 0.1707	CAF 0.1336 0.1365 0.1405 0.1416 0.1415 0.1415	RUI 3 152 5 152 5 152 6 152 0 152 0 152 1 152 1 152	
ALPH 4.1 3.0 2.0 1.5 0.4 -0.0 -0.5 -1.0	= 8.2' 0= 10' A 0 0.0' 7 0.0' 4 0.0' 1 0.0' 8 -0.0' 6 -0.0'	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019 0179 0469 0733 1011	RE i	PER TS= 841 615 317 882 954 539 124 961 550 290	IN.= 3.866 C: -0.06 -0.09 -0.09 -0.09 -0.09 -0.09 -0.09 -0.09	.48E06 55 PSI 590 521 515 502 519 565 572 579 553	CY 0.5116 0.4478 0.3464 0.3365 0.4069 0.2946 0.3216 0.3292 0.4075	90. D8 CR 0.0013 0.0011 0.0010 0.0010 0.0017 0.0033 0.0024 0.0023 0.0026	CAT 0.3146 0.3123 0.3126 0.3112 0.3099 0.3122 0.3116 0.3142 0.3142	POJ/PT . 028026 . CPS 0.1808 C.1758 0.1721 0.1714 0.1710 0.1707 0.1705 0.1707 0.1705	CAF 0.1338 0.1365 0.1405 0.1410 0.1411 0.1435 0.1462	RUI 3 152 5 152 5 152 6 152 0 152 0 152 1 152 1 152 1 152 1 152	
ALPH 4.1 3.0 2.0 1.5 0.9 0.4 -0.0 -1.5 -1.5 -2.1	= 8.2' 0= 10 A 0 0.7 7 0.4 4 0.1 1 0.1 9 0.3 6 -0.1 6 -0.1 8 -0.1 9 0.0 0 0 0 0.0 0 0 0 0.0 0 0 0 0.0 0	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019 0179 0469 0733 1011	RE 6 CM -1.1: -0.7: -0.4: -0.2: -0.0: 0.0: 0.1: 0.2: 0.6: 0.6:	PER TS= 841 615 317 882 954 539 124 961 550 228	IN.= 3.866 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06 -0.06	.48E06 55 PSI 590 521 515 502 519 565 672 679 553	CY 0.5116 0.4478 0.3464 0.3365 0.4586 0.4069 0.2946 0.3216 0.3292 0.4075 0.3288	90. D8 CR 0.0013 0.0011 0.0010 0.0010 0.0007 0.0033 0.0024 0.0023 0.0026 0.0035	CAT 0.3146 0.3123 0.3126 0.3112 0.3099 0.3122 0.3116 0.3142 0.3177 0.3167	POJ/PT - 028026 - CPS - 0.1808 - 0.1758 - 0.1714 - 0.1710 - 0.1707 - 0.1707 - 0.1707 - 0.1714 - 0.1715	CAF 0.1338 0.1365 0.1405 0.1416 0.1415 0.1445 0.1445	RUI 3 152 5 152 5 152 0 152 0 152 0 152 1 152 1 152 1 152 1 152 1 152	
P ALPH 4.1 3.0 2.0 1.5 0.9 0.4 -0.0 -0.5 -1.5 -2.1	= 8.2' 0= 10' A	9 PSI 7.0 CMH CN 1951 1316 0773 0528 0234 0019 0179 0469 0733 1011 1206	RE (GP) CM -1.1: -0.7(-0.4(-0.2(-0.4(-0.2(-0.4(-0.4(-0.4(-0.4(-0.4(-0.4(-0.4(-0.4	PER TS= 841 615 317 882 954 951 950 2228 417	IN.= 3.866 C: -0.06 -0.09 -0.09 -0.09 -0.09 -0.09 -0.09 -0.09	.48E06 55 PSI 590 521 515 502 519 565 470 553 471 509	CY 0.5116 0.4478 0.3464 0.3365 0.4586 0.4069 0.2946 0.3216 0.3219 0.4075 0.3288 0.3698	90. D8 CR 0.0013 0.0011 0.0010 0.0019 0.0007 0.0033 0.0024 0.0023 0.0026 0.0035	CAT 0.3146 0.3123 0.3126 0.3112 0.3099 0.3122 0.3116 0.3142 0.3142	POJ/PT O28026 CPS 0.1808 C.1758 0.1721 0.1714 0.1710 0.1707 0.1707 0.1707 0.1707 0.1714 0.1715	CAF 0.1336 0.1365 0.1405 0.1416 0.1415 0.1415 0.1445 0.1462	RUI 3 152 5 152 5 152 6 152 6 152 6 152 6 152 1 152 1 152 1 152 1 152	

THE THE SECTION OF THE PROPERTY OF THE PROPERT

HODFL 946.2	CONF	IG0000	×	ICH 1.75	PHI =	60.	
Q= 8.29 PSI	RE PER	la:= .48E06	5 TO=	90. CEG.F	POJ/PT	S = 40.	
PO= 107.0 CM	HG PTS= :	3.3665 PSI		RUN NO	028026	9141	
ALPHA CH	CH	cs	CY	CR CAT	CP8	CAF	RUN
4.09 0.1774	-1.0654	-0.1213	0.9017	0,0017 0.3210	0-1826	0-1384	153.
3.06 G.1134	-0.6379 -	-0.1119		0.0018 0.3186			153.
2.04 0.0586	-0.2971 -			0.0020 0.3168			153.
1.50 0.0271	-0.0895	-0.1647		0.0019 0.3159			153.
0.98 -0.0040	0.1144 -	-0.1065		0.0012 0.3162			153.
0.46 -0.0210	0.1810			0.0010 0.3152			153.
-0.06 -0.0462	0.3282 -	-0.0958		0.0021 0.3159			153.
-0.57 -0.0797	0.5577 -			0.0020 0.3194			153.
-1.09 -0.1009	0.6603 -	-0.0968		0.0037 0.3192			153.
-1.61 -0.1225	0.7727	-0.0957		0.0040 0.3205			153.
-2.12 -0.1479	g.9245 ·			0.0029 0.3230			153.
-3.15 -0.2002	1.2345			0.0045 0.3270			153.
-4.18 -C.2520	1.5392	-0.1004	0.7605	0.0053 0.3317	0.1730	0.1586	153.
MODEL 946.2		IG0000		ACH 1.75	PHI ≠		
MODEL 946.2 G= 8.27 PSI		IG0000 IN.= .48E06		90. DEG.F	PHI ≈		
	RE PER	IN.= .48E06		90. DEG.F		rs = 80.	
Q= 8.27 PSI	RE PER	IN.= .48E06		90. DEG.F	POJ/PT	rs = 80.	RUN
Q= 8.27 PSI PD= 107.0 CM	RE PER	1N.= .48E06 3.8665 PSI CS	5 TO=	90. DEG.F RUN NO	POJ/PT • 028026 CP8	TS = 80. 59142 CAF	RUN 154•
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER : IHG PTS= :	1N.= .48E06 3.8665 PSI CS -0.2228	CY 1.6398	90. DEG.F RUN NO CR CAT	POJ/PT . 028026 CP8 C.1861	TS = 80. 59142 CAF 0.1491	
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 5.07 0.1441	RE PER : ING PTS= : CM -0.8587	1N.= .48E06 3.8665 PSI CS -0.2228 -0.2089	CY 1.6398 1.5196	90. DEG.F RUN NO CR CAT 0.0023 0.3351	POJ/PT . 028026 CP8 C.1861 0.1802	TS = 80. 59142 CAF 0.1491 0.1511	154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750	RE PER : ING PTS= : CM -0.85870.3823 -	IN.= .48E06 3.8665 PSI CS -0.2228 -0.2089 -0.2042	CY 1.6398 1.5196 1.4852	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3313	POJ/PT . 028026 CP8 0.1861 0.1802 0.1758	S = 80. 59142 CAF 0.1491 0.1511 0.1505	154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047	RE PER : THG PTS= : CM -0.85870.3823 - 0.1114 -	IN.= .48E06 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967	CY 1.6398 1.5196 1.4852 1.4206	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3313 0.0023 0.3263	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745	S = 80. 59142 CAF 0.1491 0.1511 0.1505 0.1509	154. 154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255	RE PER : CM -0.8587 -0.3823 0.1114 0.2985	IN.= .48E06 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063	CY 1.6398 1.5196 1.4852 1.4206 1.5250	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3313 0.0023 0.3263 0.0031 0.3254	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1739	S = 80. 59142 CAF 0.1491 0.1511 0.1505 0.1509 0.1510	154. 154. 154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611	RE PER : CM -0.8587 -0.3823 0.1114 0.2985 0.5501	IN.= .48 E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5084	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3313 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1739 0.1732	S = 80. 59142 CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1509	154. 154. 154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0849	RE PER : CM -0.8587 -0.3823 0.1114 0.2985 0.5501 0.6845	IN.= .48 E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5084 1.5465	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3313 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249 0.0029 0.3241	POJ/PT . 028026 CP8 0.1861 0.1802 0.1758 0.1745 0.1739 0.1732 0.1719	S = 80. 59142 CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1509 0.1529	154. 154. 154. 154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0349 -0.08 -0.1136	RE PER : CM -0.8587 -0.3823 0.1114 0.2985 0.5501 0.6845 0.8618	IN.= .48 E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070 -0.2047	CY 1.6398 1.5196 1.4852 1.4206 1.5084 1.5084 1.5465 1.5270	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249 0.0029 0.3241 0.0026 0.3248	POJ/PT . 028026 CP8 0.1861 0.1802 0.1758 0.1745 0.1749 0.1732 0.1719 0.1713	S = 80. 69142 CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1509 0.1529 0.1542	154. 154. 154. 154. 154. 154.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0349 -0.08 -0.1136 -0.61 -0.1346	RE PER : CM -0.8587 -0.3823 0.1114 0.2985 0.5501 0.6845 0.8618 0.9635	IN.= .48 E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070 -0.2047 -0.2072	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5250 1.5578 1.5578	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3251 0.0023 0.3254 0.0027 0.3254 0.0029 0.3241 0.0026 0.3248 0.0029 0.3254 0.0026 0.3258 0.0031 0.3268 0.0036 0.3301	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1749 0.1732 0.1719 0.1713 0.1710	S = 80. 69142 CAF 0.1491 0.1511 0.1505 0.1509 0.1509 0.1529 0.1529 0.1542 0.1558 0.1586	154. 154. 154. 154. 154. 154. 154.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0349 -0.08 -0.1136 -0.61 -0.1346 -1.12 -0.1657	RE PER : CM -0.8587 -0.3823 0.1114 0.2985 0.5501 0.6845 0.8618 0.9435 1.1641	IN.= .48 E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070 -0.2047 -0.2072	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5084 1.5465 1.5270 1.5578 1.5644 1.5260	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249 0.0029 0.3241 0.0026 0.3248 0.0029 0.3254 0.0029 0.3254 0.0031 0.3268 0.0036 0.3301 0.0035 0.3327	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1739 0.1732 0.1719 0.1713 0.1714 0.1721	S = 80. 69142 CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1529 0.1529 0.1542 0.1558 0.1586 0.1606	154. 154. 154. 154. 154. 154. 154.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0349 -0.08 -0.1136 -0.61 -0.1346 -1.12 -0.1657 -1.63 -0.1909 -2.17 -0.2159 -3.18 -0.2680	RE PER CM -0.8587 -0.3823 0.1114 0.2985 0.5501 0.6845 0.9635 1.1641 1.3053 1.4422 1.7526	IN.= .48E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070 -0.2047 -0.2072 -0.2070 -0.2070 -0.2070	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5084 1.5465 1.5570 1.5570 1.5544 1.5260 1.5114	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249 0.0029 0.3241 0.0026 0.3248 0.0029 0.3254 0.0031 0.3268 0.0031 0.3268 0.0031 0.3268 0.0036 0.3301 0.0035 0.3327 0.0038 0.3345	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1739 0.1732 0.1719 0.1713 0.1714 0.1721 0.1735	CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1529 0.1542 0.1586 0.1606 0.1610	154. 154. 154. 154. 154. 154. 154. 154.
Q= 8.27 PSI PO= 107.0 CM ALPHA CN 4.07 0.1441 3.04 0.0750 2.00 0.0047 1.47 -0.0255 0.95 -0.0611 0.44 -0.0349 -0.08 -0.1136 -0.61 -0.1346 -1.12 -0.1657 -1.63 -0.1909 -2.17 -0.2159	RE PER : CM -0.85870.3823 - 0.1114 - 0.2985 - 0.6845 - 0.8618 - 0.9635 - 1.1641 - 1.3053 - 1.4422 -	IN.= .48E08 3.8665 PSI CS -0.2228 -0.2089 -0.2042 -0.1967 -0.2063 -0.2039 -0.2070 -0.2047 -0.2072 -0.2070 -0.2070 -0.2070	CY 1.6398 1.5196 1.4852 1.4206 1.5250 1.5084 1.5465 1.5570 1.5570 1.5544 1.5260 1.5114	90. DEG.F RUN NO CR CAT 0.0023 0.3351 0.0023 0.3263 0.0031 0.3254 0.0027 0.3249 0.0029 0.3241 0.0026 0.3248 0.0029 0.3254 0.0029 0.3254 0.0031 0.3268 0.0036 0.3301 0.0035 0.3327	POJ/PT . 028026 CP8 C.1861 0.1802 0.1758 0.1745 0.1739 0.1732 0.1719 0.1713 0.1714 0.1721 0.1735	CAF 0.1491 0.1511 0.1505 0.1509 0.1510 0.1529 0.1542 0.1586 0.1606 0.1610	154. 154. 154. 154. 154. 154. 154. 154.

MODEL 946.2	CONF	IĜ0000	MAC	H 1.75		PHI =	75.	
Q= 8-29 PSI	RE PER	IN.= .48E0	6 10=	90. DE	G.F	POJ/P	rs =	•
PO= 107.0 C	HHG PTS=	3.8665 PSI		i	RUN NO.	02802	59143	
ALPHA CN	CF	CS	CY	CR	CAT	CPB	CAF	RUN
4.10 0.1933	-1-1207	-0.0294	0.1427-0	.0007	0.3097	0.1699	0.1398	155.
3.07 0.1449	-0.8405	-0.0147	0.0869-0	-0006	0.3088	0.1670	0.1418	155.
2.05 0.0920	-0.5212		0.1041-0					155.
1.51 0.0674	-0.3793		0.1303-0					155.
0.99 0.0453	-0.2605		0.0397-0					155 .
0.47 0.0226	-0.1335		0.0571-0					155.
-0.05 -0.0027	0.0190		0.1082-0					155.
-0.56 -0.0230		-0.0098	0.0491-0					155.
-1.07 -0.0472	0.2610		0:0578 0					155.
-1.60 -0.0763	0.4454		0.1317 0					155.
-2.09 -0.0968	G.5534		0.0880 0					155.
-3.13 -0.1442	0.8735		0.0524 0					155.
-4.16 -0.1962	1.1340	-0.0022 -	-0.0185 U	-0036	0.3261	0.1698	0.1563	155.
MUDEL 946.2	CONF RE PER			H 1.75		PHI =	75.	10
0= P.29 PSI	RE PER	IN.= .48E0		90. DE(G.F	P0J/P1	rs = 1	10.
0= P.29 PSI PU= 107.0 C	RE PER	IN.= .48E00	5 TO=	90• DE(G.F RUN NO.		rs = 1	
0= P.29 PSI	RE PER	IN.= .48E0		90. DE(G.F	P0J/P1	rs = 1	10• RUN
0= P.29 PSI PU= 107.0 CN ALPHA CN 4.10 0.1968	RE PER	IN.= .48E06 3.8665 PSI CS	5 TO=	90. DE(Cr	G.F RUN NO. CAT	POJ/P1 028026 CPB	TS = 1 59144 CAF	
0= P.29 PSI PU= 107.0 CN ALPHA CN 4.10 0.1968 3.07 0.1395	RE PER MHG PTS= :	IN.= .48E06 3.8665 PSI CS -0.0424	5 TO=	90. DE(F CR .0006 (G.F RUN NO. CAT 0.3100	POJ/P1 028026 CPB 0.1727	TS = 1 59144 CAF 0.1373	RUN
O= F.29 PSI PU= 107.0 CN ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335	5 TO= CY 0.3062-0	90. DEC GR .0008 (G.F RUN NO. CAT 0.3100 0.3079	POJ/P1 028026 CPB 0.1727 0.1709	CAF 0-1373 0-1370	RUN 156.
O= F.29 PSI PU= 107.0 CR ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645	RE PER MHG PTS= CM -1.1638 -0.8003	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0	90. DE(CR .000b (.0011 (.0002 (G.F RUN NO. CAT 0.3100 0.3079 0.3096 0.3085	POJ/P1 028026 CPB 0.1727 0.1709 0.1700 0.1696	CAF 0.1373 0.1370 0.1396 0.1388	RUN 156. 156.
O= F.29 PSI PU= 107.0 CR ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0530	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.7218-0	90. DE6	G.F RUN NO. CAT 0.3100 0.3079 0.3096 0.3085	POJ/P1 028026 CPB 0.1727 0.1709 0.1706 0.1696 0.1695	CAF 0.1373 0.1370 0.1396 0.1388 0.1401	RUN 156. 156.
0= F.29 PSI PU= 107.0 CR ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0530 -0.0264	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.7218-0 0.1589 0	90. DE6	G.F RUN NO. CAT 0.3100 0.3079 0.3096 0.3085 0.3095 0.3117	POJ/P1 028026 CPB 0.1727 0.1709 0.1706 0.1696 0.1695 0.1698	CAF 0.1373 0.1370 0.1396 0.1388 0.1401 0.1419	RUN 156. 156. 156. 156.
0= F.29 PSI PU= 107.0 CR ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.7218-0 0.1589 0 0.1812-0	PQ. DEG	G.F RUN NO. CAT 0.3100 0.3079 0.3096 0.3085 0.3095 0.3117 0.3107	POJ/P1 028026 CPB 0.1727 0.1709 0.1700 0.1696 0.1695 0.1698	CAF 0.1373 0.1370 0.1376 0.1388 0.1401 0.1419 0.1412	RUN 156. 156. 156. 156. 156.
0= P.29 PSI PU= 107.0 CM ALPHA CN 4.10 0.1968 3.07 0.1395 2.64 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089 -0.56 -0.0358	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602 0.2283	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289 -0.0364	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.7218-0 0.1589 0 0.1812-0 0.2646-0	OOO3 (0.0003 (G.F RUN NO. CAT 0.3100 0.3079 0.3095 0.3095 0.3117 G.3107 C.3124	POJ/P1 028026 CPB 0.1727 0.1709 0.1700 0.1696 0.1695 0.1698 0.1695	CAF 0.1373 0.1370 0.1396 0.1388 0.1419 0.1419 0.1412	RUN 156. 156. 156. 156. 156.
0= P.29 PSI PU= 107.0 CM ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089 -0.56 -0.0358 -1.09 -0.0583	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602 0.2283 0.3459	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289 -0.0364 -0.0296	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.1589 0.1812-0 0.2646-0 0.1958-0	CR - 0008 (- 0011 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0003 (- 0006 (- 0003 (- 0006 (G.F RUN NO. CAT 0.3100 0.3079 0.3096 0.3095 0.3117 0.3107 0.3124 0.3153	POJ/P1 028026 CPB 0.1727 0.1709 0.1696 0.1695 0.1698 0.1695 0.1694 0.1687	CAF 0.1373 0.1373 0.1376 0.1388 0.1401 0.1419 0.1412 0.1430 0.1466	RUN 156. 156. 156. 156. 156. 156.
0= P.29 PSI PU= 107.0 CM ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089 -0.56 -0.0358 -1.09 -0.0583 -1.59 -0.0840	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602 0.2283 0.3459 0.5012	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289 -0.0364 -0.0296 -0.0308	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.1589 0.1589 0.1589 0.1589-0 0.1958-0 0.2646-0 0.1958-0	90. DE6 CR .0008 (CAT 0.3100 0.3079 0.3096 0.3095 0.3117 0.3124 0.3153	POJ/PI 028026 CPB 0.1727 0.1709 0.1706 0.1696 0.1695 0.1698 0.1694 0.1687 0.1684	CAF 0.1373 0.1370 0.1396 0.1388 0.1401 0.1419 0.1412 0.1430 0.1466 0.1459	RUN 156. 156. 156. 156. 156. 156. 156.
0= F-29 PSI PU= 107.0 CR ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089 -0.56 -0.0358 -1.09 -0.0583 -1.59 -0.0840 -2.10 -0.1091	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602 0.2283 0.3459 0.5012 0.6513	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289 -0.0364 -0.0296 -0.0308 -0.0355	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.7218-0 0.1589-0 0.1812-0 0.2646-0 0.2100 0.2100 0.2605-0	CR .0008 (.0011 (.0002 (.0003	CAT 0.3100 0.3079 0.3096 0.3085 0.3095 0.3117 0.3124 0.3124 0.3143	POJ/PI 028020 CPB 0.1727 0.1709 0.1696 0.1695 0.1695 0.1695 0.1694 0.1687 0.1684 0.1682	CAF 0.1373 0.1370 0.1376 0.1388 0.1401 0.1419 0.1412 0.1430 0.1466 0.1459 0.1474	RUN 156. 156. 156. 156. 156. 156. 156.
0= P.29 PSI PU= 107.0 CM ALPHA CN 4.10 0.1968 3.07 0.1395 2.04 0.0909 1.51 0.0645 0.99 0.0392 0.48 0.0171 -0.04 -0.0089 -0.56 -0.0358 -1.09 -0.0583 -1.59 -0.0840	RE PER MHG PTS= CM -1.1638 -0.8003 -0.5218 -0.3646 -0.2158 -0.0940 0.0602 0.2283 0.3459 0.5012	IN.= .48E06 3.8665 PSI CS -0.0424 -0.0426 -0.0335 -0.0291 -0.0330 -0.0264 -0.0289 -0.0364 -0.0296 -0.0308 -0.0355 -0.0302	CY 0.3062-0 0.3093-0 0.2214-0 0.1829-0 0.1589 0.1589 0.1589 0.1589-0 0.1958-0 0.2646-0 0.1958-0	CR -0008 (-0011 (-0003	CAT 0.3100 0.3079 0.3096 0.3095 0.3117 0.3124 0.3124 0.3153 0.3143	POJ/PI 028020 CPB 0.1727 0.1709 0.1696 0.1695 0.1698 0.1694 0.1687 0.1684 0.1682 0.1692	CAF 0.1373 0.1370 0.1396 0.1388 0.1401 0.1419 0.1412 0.1430 0.1466 0.1459 0.1474	RUN 156. 156. 156. 156. 156. 156. 156.

MODEL 946.2	CONI	FIG0000	НАСН	1.75	PHI =	75.	
Q= 8.79 PSI	RE PER	IN.= .49E0	6 TO= 9	O. DEG.F	POJ/P1	rs = 2	0.
PO= 107.0 CF	HS PTS=	3.8665 PSI		KUN NO	028028	9145	
ALPHA CN	CH	cs	CY	CR CAT	СРВ	CAF	RUN
4.10 0.2000	-1.1996	-0.0733	0.5488-0.	0003 0.3132	0.1752	0.1380	157.
3.07 0.1401		-0.0627		0003 0.3115			157.
2.03 0.0876		-C.U533	0.3564-0.	0009 0.3112	0.1717	0.1395	157.
1.51 0.0595		-0.0576	0.4022 0.	0007 0.3123			157.
1.00 0.0349		-0.0552	0.3822-0.		0.1709		157.
0.48 0.0083		-0.0588		0001 0.3082			157.
-0.05 -0.0201		-2.0619		0003 0.3125			157.
-0.56 -0.0412		~0.0528		0002 0.3147			157.
-1.08 -0.0657		-0.0483	0.3232 0.		0.1704		157.
-1.59 -0.0916 -2.11 -0.1167		-0.0568		0001 0.3187			157.
-3.14 -0.1661		-0.0547		0006 0.3189			157.
-4.17 -0.2213		-0.0555 -0.0629		0013 0.3222			157.
-4.17 -0.2213	1.3303	-0.0029	0.4859 0.	0023 0.3310	0.1724	0-1280	157.
MODEL 946.2 Q= 8.29 PSI		FIG0000 IN.= .48E0		1.75 0. DEG.F	PHI =	75.	0.
Q= 8.29 PSI	RE PER	IN.= .48E0	6 TO= 9	1.75 O. DEG.F	PHI =		0•
	RE PER	IN.= .48E0	6 TO= 9	O. DEG.F		rs = 4	0•
Q= 8.29 PSI	RE PER	IN.= .48E0	6 TO= 9	O. DEG.F	POJ/PT	rs = 4	0• RUN
Q= 8.29 PSI PO= 107.0 CM	RE PER SHG PTS≃ CM	IN.= .48E0	6 TO= 9	O. DEG.F RUN NO.	POJ/PT - 028026 CPB	S = 46 69146 CAF	RUN
Q= 8.29 PSI PO= 107.0 CM ALPHA CN	RE PER SHG PTS= CM -1.1703	IN.= .48E0 3.8665 PST	6 TO= 9 CY 0.8843 C.	O. DEG.F RUN NO	POJ/PT - 028026 - CPB - 0-1799	S = 46 69146 CAF 0.1388	
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950	RE PER SHG PTS= CM -1.1703 -0.7615	IN.= .48E0 3.8665 PS3 CS -0.1206	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0003 0.3148	POJ/PT - 028026 - CPB - 0.1799 - 0.1762 - 0.1737	S = 4 69146 CAF 0.1388 0.1401 0.1412	RUN 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163	POJ/PT - 028026 - CPB - 0.1799 - 0.1762 - 0.1737	S = 4 69146 CAF 0.1388 0.1401 0.1412	RUN 158. 158.
Q= 8.29 PST PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833 -0.2269	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0003 0.3148	POJ/PT - 028026 CPB 0.1799 0.1762 0.1737 0.1725	S = 4 69146 CAF 0-1388 0-1401 0-1412 0-1433	RUN 158• 158• 158•
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1113	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 C.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3763 0003 0.3148 0002 0.3158 0002 0.3158 0004 9.3165	POJ/PT . 028026 CPB 0.1799 0.1762 0.1737 0.1725 0.1716 0.1712	CAF 0.1388 0.1401 0.1412 0.1433 0.1432 0.1453	RUN 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058 -0.05 -0.0314	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1113 -0.1117 -0.1152 -0.1130	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 0. 0.8287 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0003 0.3148 0002 0.3158 0002 0.3148 0004 9.3165 0006 0.3167	POJ/PT . 028026 CPB 0.1799 0.1762 0.1737 0.1725 0.1716 0.1712 0.1707	CAF 0.1388 0.1401 0.1412 0.1433 0.1432 0.1453 0.1460	RUN 158. 158. 158. 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058 -0.05 -0.0314 -0.58 -0.0545	RE PER CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370 0.3609	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1117 -0.1152 -0.1130 -0.11G1	CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 C. 0.8287 0. 0.8038-0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3763 0003 0.3148 0002 0.3158 0002 0.3158 0004 9.3165 0006 0.3167 0001 0.3197	POJ/PT - 028026 - CPB - 0.1799 - 0.1762 - 0.1737 - 0.1725 - 0.1716 - 0.1712 - 0.1707 - 0.1709	CAF 0.1388 0.1401 0.1412 0.1433 0.1432 0.1453 0.1460 0.1488	RUN 158. 158. 158. 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0658 -0.05 -0.0314 -0.58 -0.0545 -1.08 -0.0762	RE PER CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370 0.3609 0.4760	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1117 -0.1152 -0.1130 -0.11C1 -0.1089	6 T0= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8518 0. 0.8287 0. 0.8038-0. 0.7950 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0002 0.3158 0002 0.3158 0002 0.3165 0004 9.3165 0006 0.3167 0001 0.3197	POJ/PS - 028026 CPB 0.1799 0.1762 0.1737 0.1725 0.1716 0.1712 0.1707 0.1709 0.1709	CAF CAF C.1388 0.1401 0.1412 0.1433 0.1432 0.1453 0.1460 0.1488 0.1487	RUN 158. 158. 158. 158. 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058 -0.05 -0.0314 -0.58 -0.0545 -1.08 -0.0762 -1.60 -0.1023	RE PER CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370 0.3609 0.4760 0.6237	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1117 -0.1152 -0.1130 -0.11C1 -0.1089 -0.1032	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 0. 0.8287 0. 0.8287 0. 0.6038-U. 0.7950 0. 0.7405 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0002 0.3158 0002 0.3158 0004 9.3165 0006 0.3167 0001 0.3197 0018 0.3193 0013 0.3215	POJ/PS . 028026 CPB 0.1799 0.1762 0.1737 0.1725 0.1716 0.1712 0.1707 0.1709 0.1709 0.1709	CAF C.1388 0.1401 0.1412 0.1433 0.1453 0.1453 0.1460 0.1488 0.1487 0.1506	RUN 158. 158. 158. 158. 158. 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058 -0.05 -0.0314 -0.58 -0.0545 -1.08 -0.0762 -1.60 -0.1023 -2.13 -0.1311	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370 0.3602 0.4760 0.6237 0.8022	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1117 -0.1152 -0.1130 -0.1161 -0.1089 -0.1032 -0.1090	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 C. 0.8287 0. 0.6038-0. 0.7950 0. 0.7405 0. 0.8003 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0002 0.3158 0002 0.3165 0004 9.3165 0006 0.3167 0018 0.3197 0018 0.3215 0014 0.3260	POJ/PS - 028026 - CPB - 0.1799 - 0.1762 - 0.1737 - 0.1725 - 0.1716 - 0.1717 - 0.1707 - 0.1709 - 0.1709 - 0.1714	S = 409146 CAF 0.1388 0.1401 0.1412 0.1433 0.1432 0.1453 0.1468 0.1487 0.1506 0.1545	RUN 158. 158. 158. 158. 158. 158. 158. 158.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.09 0.1950 3.07 0.1376 2.03 0.0734 1.51 0.0470 0.97 0.0186 0.46 -0.0058 -0.05 -0.0314 -0.58 -0.0545 -1.08 -0.0762 -1.60 -0.1023	RE PER SHG PTS= CM -1.1703 -0.7615 -0.3833 -0.2269 -0.0515 0.0898 0.2370 0.3609 0.4760 0.6237 0.8022 1.1126	IN.= .48E0 3.8665 PS3 CS -0.1206 -0.1140 -0.1130 -0.1117 -0.1152 -0.1130 -0.11C1 -0.1089 -0.1032	6 TO= 9 CY 0.8843 C. 0.8255-0. 0.8191 0. 0.8051-0. 0.8113 0. 0.8518 0. 0.8287 0. 0.6038-0. 0.7405 0. 0.7405 0. 0.8003 0. 0.8408 0.	O. DEG.F RUN NO. CR CAT 0001 0.3187 0005 0.3163 0002 0.3158 0002 0.3158 0004 9.3165 0006 0.3167 0001 0.3197 0018 0.3193 0013 0.3215	POJ/PS - 028026 - CPB - 0.1799 - 0.1762 - 0.1737 - 0.1725 - 0.1716 - 0.1717 - 0.1707 - 0.1709 - 0.1709 - 0.1714 - 0.1713	S = 409146 CAF 0.1388 0.1401 0.1412 0.1433 0.1432 0.1453 0.1460 0.1487 0.1506 0.1545 0.1593	RUN 158. 158. 158. 158. 158. 158. 158. 158.

MODEL 946.2	CON	IG0000	· H/	ICH 1.75		PHI =	75.	
Q= 8.29 PS1	RE PER	IN.= .48E0	5 TO=	90. DEG.	F	POJ/P1	rs =	80.
PO= 107.0 (MHG PTS=	3.8665 PSI		RL	JN NO.	028026	9147	
ALPHA CN	CH	CS	CY	CR C	CAT	893	CAF	RUN
4.08 0.1852	-1.1258	-0.2282	1.6641	0.0007 0.	3301	0.1852	0.1449	159.
3.06 0.1156	-0.6439	-0.2252	1.6389	0.0008 0.	.3265	0.1835	0.1430	159.
2.02 0.0529	-0.2362	-0.2185		0.0013 0.				
1.48 0.0214	-0.0328	-0.2181		0.0007 0.				
0.98 -0.0081		-0.2202		0.0017 0.				
0.45 -0.0340		-0.2130		0.0010 0.				
-0.06 -0.0612		-0.2261		0.0011 0.				
-0.59 -0.0881		-0.2262		0.0009 0				
-1.09 - 0.1130		-0.2282		0.0011 0.				
-1.63 -0.1395		-0.2325	1.7624			0.1709		
-2.13 -0.1635		-0.2233		0.0016 0.				
-3.18 -0.2245		-0.2272		0.0018 0.				
-4.20 -0.2810	1.7780	-0.2134	1.580:	0.0032 0.	3403	0.1744	0.1659	159.
MODEL 946.2		FIG0000		ACH 1.75	£	PHI =	90. rc =	
MODEL 946.2 Q= 8.29 PS1		FIG0000 IN.= .48E0		ACH 1.75 90, DEG.	. F	PHI =		•
	RE PER	IN.= .48E0		90. DEG.			rs =	•
Q= 8.29 PS1	RE PER	IN.= .48E0		90. DEG.		P0J/P1	rs =	• RUN
Q= 8.29 PS1 PO= 107.0 (RE PER CMHG PTS=	IN.= .48E0	6 TO=	90. DEG.	UN NO. Cat	POJ/P1 028028 CPB	rs = 69148 CAF	RUN
Q= 8.29 PS1 PO= 107.0 (ALPHA CN	RE PER CMHG PTS= CM -1.1498	IN.= .48E0 3.8665 PSI CS	6 TO= CY 0.0815	90. DEG. RU CR (UN NO. Cat .3076	POJ/P1 028023 CPB 0.1697	FS = 59148 CAF 0.1379	RUN 160•
Q= 8.29 PS1 PO= 107.0 (ALPHA CN 4.12 0.1971	RE PER CMHG PTS= CM -1.1498 -0.8296	IN.= .48E0 3.8665 PSI CS -0.0140	6 TO= CY 0.0815- 0.1636-	90. DEG. RU CR (0-0.0015 0.	UN NO. CAT .3076 .3069	POJ/P1 028023 CPB 0.1697 0.1656	TS = 59148 CAF 0.1379 0.1413	RUN 160.
Q= 8.29 PS1 P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220	CY 0.0815- 0.1636- 0.1331-	90. DEG. RU CR (0-0.0015 0.	UN NO. CAT .3076 .3069 .3075	POJ/P1 028023 CPB 0.1697 0.1656 0.1657	FS = 69148 CAF 0.1379 0.1413 0.1418	RUN 160. 160.
Q= 8.29 PSI PO= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190	CY 0.0815- 0.1636- 0.1331- 0.1485-	90. DEG. RU CR C -0.0015 0. -0.0019 0.	UN NO. 3076 3069 3075 3082	POJ/P1 028023 CPB 0.1697 0.1656 0.1657 0.1674	FS = 59148 CAF 0.1379 0.1413 0.1418 0.1407	RUN 160. 160. 160. 160.
Q= 8.29 PSI PO= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317-	90. DEG. RU CR (0.0015 0. -0.0019 0. -0.0018 0. -0.0017 0. -0.0015 0.	UN NO. 3076 3069 3075 3082 3066	POJ/P1 028029 CPB 0.1697 0.1656 0.1657 0.1674 0.1681	TS = 59148 CAF 0.1379 0.1413 0.1418 0.1407 0.1386	RUN 160. 160. 160. 160.
Q= 8.29 PSI P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0133 -0.0183 -0.0156	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042-	90. DEG. RU CR (0.0015 00.0019 00.0018 00.0015 00.0019 0.	.3076 .3076 .3069 .3075 .3082 .3066 .3080	POJ/P1 028024 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1681	FS = 69148 CAF 0.1379 0.1413 0.1418 0.1400 0.1442	RUN 160. 160. 160. 160. 160.
Q= 8.29 PSI P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007 -0.53 -0.0242	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043 0.1384	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0133 -0.0183 -0.0156 -0.0101	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042- 0.0527-	90. DEG. RU CR (0.0015 0. -0.0019 0. -0.0017 0. -0.0019 0. -0.0019 0. -0.0019 0.	3076 3076 3069 3075 3082 3066 3080 3120	POJ/P1 028024 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1677 0.1680	CAF 0.1379 0.1418 0.1407 0.1400 0.1442 0.1431	RUN 160. 160. 160. 160. 160. 160.
Q= 8.29 PSI P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007 -0.53 -0.0242 -1.05 -0.0474	CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043 0.1384 0.2673	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0133 -0.0183 -0.0156 -0.0101 -0.0196	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042- 0.0527- 0.1545-	90. DEG. RU CR (0.0015 00.0019 00.0017 00.0019 00.0019 00.0009 0.	3076 3076 3069 3075 3082 3082 3080 3120 3111	POJ/P1 028024 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1681 0.1677 0.1680 0.1677	FS = 59148 CAF 0.1379 0.1418 0.1407 0.1400 0.1442 0.1431 0.1449	RUN 160. 160. 160. 160. 160. 160.
Q= 8.29 PSI P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007 -0.53 -0.0242 -1.05 -0.0474 -1.57 -0.0714	RE PER CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043 0.1384 0.2673 0.4043	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0133 -0.0183 -0.0183 -0.0156 -0.0101 -0.0196 -0.0233	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042- 0.0527- 0.1545- 0.1905-	90. DEG. RU CR (1) -0.0015 0. -0.0019 0. -0.0017 0. -0.0019 0. -0.0009 0. -0.0009 0. -0.0009 0.	.3076 .3076 .3069 .3075 .3082 .3086 .3086 .3120 .3111 .3126	POJ/P1 028024 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1681 0.1677 0.1680 0.1677	FS = 59148 CAF 0.1379 0.1413 0.1418 0.1407 0.1402 0.1442 0.1431 0.1449 0.1484	RUN 160. 160. 160. 160. 160. 160. 160. 160.
Q= 8.29 PSI PO= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007 -0.53 -0.0242 -1.05 -0.0474 -1.57 -0.0714 -2.09 -0.0946	CMHG PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043 0.1384 0.2673 0.4043 0.5385	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0183 -0.0156 -0.0101 -0.0196 -0.0233 -0.0108	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042- 0.1545- 0.1905- 0.0639	90. DEG. RU CR C -0.0015 00.0018 00.0015 00.0019 00.0009 00.0009 00.0009 00.0005 0.	.3076 .3076 .3069 .3075 .3082 .3086 .3120 .3111 .3126 .3160	POJ/P1 028026 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1681 0.1677 0.1676 0.1677	S = 59148 CAF 0.1379 0.1413 0.1418 0.1407 0.1386 0.1400 0.1442 0.1443 0.1449 0.1484 0.1500	RUN 160. 160. 160. 160. 160. 160. 160. 160.
Q= 8.29 PSI P0= 107.0 (ALPHA CN 4.12 0.1971 3.09 0.1443 2.05 0.0936 1.51 0.0679 1.01 0.0465 0.49 0.0218 -0.02 -0.0007 -0.53 -0.0242 -1.05 -0.0474 -1.57 -0.0714	CM PTS= CM -1.1498 -0.8296 -0.5316 -0.3835 -0.2668 -0.1220 0.0043 0.1384 0.2673 0.4043 0.5385 0.8097	IN.= .48E0 3.8665 PSI CS -0.0140 -0.0220 -0.0190 -0.0201 -0.0133 -0.0183 -0.0183 -0.0156 -0.0101 -0.0196 -0.0233	CY 0.0815- 0.1636- 0.1331- 0.1485- 0.0810- 0.1317- 0.1042- 0.0527- 0.1545- 0.1905- 0.0639 0.0934	90. DEG. RU CR (1) -0.0015 0. -0.0019 0. -0.0017 0. -0.0019 0. -0.0009 0. -0.0009 0. -0.0009 0.	.3076 .3076 .3069 .3075 .3082 .3086 .3080 .3120 .3111 .3126 .3160 .3177	POJ/P1 028026 CPB 0.1697 0.1656 0.1657 0.1674 0.1681 0.1677 0.1687 0.1676 0.1677	S = 69148 CAF 0.1379 0.1413 0.1418 0.1407 0.1386 0.1400 0.1442 0.1449 0.1449 0.1484 0.1500 0.1544	RUN 160. 160. 160. 160. 160. 160. 160. 160.

MODEL 946.2	CONI	FIG0000	MAC	1 1.75	PHI =	90.	
Q= 8.29 PSI	RE PER	IN.= .48)	6 TO= 9	O. DEG.F	POJ/P1	S = 10.	
PO= 107.0 C	HG PTS=	3.8665 PSI		RUN	NO. 028026	9149	
ALPHA CN	CH	cs	CY	CR CAT	CPB	CAF	RUN
4.11 0.2005	-1.1791	-0.0513	0.4027-0	0014 0.30	95 0.1709	0.1386	161.
3.09 0.1463	-0.8449	~0.0380	0.2637-0	.0012 0.30	78 0.1700	0.1377	161.
2.05 0.0956	-0.5482	-0.0337	0.2213-0	.0013 0.30	89 0-1698	0.1391	161.
1-52 0.0695	-0.3962	-0.0354	0.2398-0	.0015 0.31	10 0.1702	0.1408	161.
1.01 0.0442		-0.0333			02 0.1702		161.
0.49 0.0210	-0.1157	-0.0422			10 0.1702		161.
-0.01 -0.0026		-0.0335			34 0-1699		161.
-0.54 -0.0286		-0.0294			33 0.1696		161.
-1.05 -0.0515		-0.0343			34 0.1691		161.
-1.57 -0.0779		-0.0374			60 0.1686		161.
-2.09 -0.1025	-	-0.0339			86 0.1683		161.
-3.12 -0.1525		-0.0401			33 0.1697		161.
-4.16 -0.2060	1.2191	-0.0358	0.2671 0	.0013 0.32	84 0.1733	0.1551	161.
MODEL 946.2 Q= 8.29 PSI		FIG0000 IN.= .48E0		1 1.75 90. DEG.F	PHI = POJ/P1	90. 'S = 20.	
	RE PEP	IN-= .48E0	6 TO= 9	90. DEG.F		'S = 20.	
Q= 8.29 PSI	RE PEP	IN-= .48E0	6 TO= 9	90. DEG.F	POJ/P1	'S = 20.	RUN
Q= 8.29 PSI PO= 107.0 CP	RE PEP 4HG PTS= CM	IN.= .48E0 3.8665 PSI CS	6 TO= 9	PO. DEG.F RUN CR CAT	POJ/P1 NO. 028026 CPB	'S = 20. 69150 CAF	
Q= 8.29 PSI PO= 107.0 CF	RE PEP HHG PTS= CM -1.2362	IN.= .48E0 3.8665 PSI CS -0.0778	6 TO= 9 CY 0.5921-0	00. DEG.F RUN CR CAT	POJ/P1 NO. 028026 CPB 40 0.1737	S = 20. 69150 CAF 0.1403	162.
Q= 8.29 PSI PO= 107.0 CP ALPHA CN 4.11 0.2073	RE PEP HHG PTS= CM -1.2362 -0.8664	IN.= .48E0 3.8665 PSI CS	6 TO= 9 CY 0.5921-0.0.4703-0.	RUN CR CAT .0006 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719	S = 20. 59150 CAF 0.1403 0.1397	162. 162.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493	RE PEP 4HG PTS= CM -1.2362 -0.8664 -0.5612	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651	6 TO= 9 CY 0.5921-0. 0.4703-0. 0.4105-0.	RUN CR CAT .0006 0.31 .0005 0.31	POJ/P1 NO. 028026 CPB 40 0.1737	S = 20. 69150 CAF 0.1403 0.1397 0.1410	162. 162. 162.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588	6 TO= 9 CY 0.5921-0.0.4703-0.0.4105-0.0.3748-0.0	RUN CR CAT .0006 0.31 .0005 0.31 .0006 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716	S = 20. 69150 CAF 0.1403 0.1397 0.1410 0.1406	162. 162.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553	6 T0= 9 CY 0.5921-0.0.4703-0.0.4105-0.0.3748-0.0.3627-0.0	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719	S = 20. 69150 CAF 0.1403 0.1397 0.1410 0.1406 0.1389	162. 162. 162. 162.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538	CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.3627-0. 0.4541-0.	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31 .0005 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 C.1715	S = 20. 69150 CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402	162. 162. 162. 162.
Q= 8.29 PSI PO= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440 0.50 0.9194	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991 0.0329 0.1778	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538 -0.0627 -0.0534 -0.0590	CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.3627-0. 0.4541-0. 0.3627-0. 0.4236-0.	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31 .0007 0.31 .0007 0.31 .0007 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 C.1715 12 0.1710 17 0.1706 44 0.1705	CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402 0.1411 0.1439	162. 162. 162. 162. 162.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440 0.50 0.0194 -0.04 -0.045 -0.56 -0.0295 -1.06 -0.0538	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991 0.0329 0.1778 0.3185	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538 -0.0627 -0.0534 -0.0590 -0.0588	CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.3627-0. 0.4541-0. 0.3627-0. 0.4236-0. 0.4214-0.	RUN CR CAT .0006 0.31 .0006 0.31 .0005 0.31 .0007 0.31 .0007 0.31 .0007 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 C.1715 12 0.1710 17 0.1706 44 0.1705 77 0.1708	CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402 0.1411 0.1439 0.1469	162. 162. 162. 162. 162. 162. 162. 162.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440 0.50 0.9194 -0.04 -9.0045 -0.56 -0.0295 -1.06 -0.0538 -1.59 -0.0803	RE PEP HHG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991 0.0329 0.1778 0.3185 0.4755	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538 -0.0627 -0.0534 -0.0590 -0.0588 -0.0638	6 T0= 9 CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.4541-0. 0.3627-0. 0.4236-0. 0.4214-0. 0.4719 0.	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31 .0007 0.31 .0007 0.31 .0007 0.31 .0002 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 0.1715 12 0.1710 17 0.1706 44 0.1705 77 0.1708 05 0.1710	CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402 0.1411 0.1439 0.1469 0.1495	162. 162. 162. 162. 162. 162. 162. 162.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440 0.50 0.0194 -0.04 -0.0045 -0.56 -0.0295 -1.06 -0.0538 -1.59 -0.0803 -2.09 -0.1042	RE PEP HG PTS= CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991 0.0329 0.1778 0.3185 0.4755 0.6152	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538 -0.0627 -0.0534 -0.0590 -0.0588 -0.0638 -0.0638	CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.3627-0. 0.4541-0. 0.4214-0. 0.4719 0. 0.4505-0.	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31 .0007 0.31 .0017 0.31 .0017 0.31 .0000 0.31	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 C.1715 12 0.1710 17 0.1706 44 0.1705 77 0.1708 05 0.1710 24 0.1699	CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402 0.1411 0.1439 0.1469 0.1495 0.1525	162. 162. 162. 162. 162. 162. 162. 162.
Q= 8.29 PSI P0= 107.0 CM ALPHA CN 4.11 0.2073 3.09 0.1493 2.06 0.0976 1.52 0.0693 0.99 0.0440 0.50 0.9194 -0.04 -9.0045 -0.56 -0.0295 -1.06 -0.0538 -1.59 -0.0803	RE PEP CM -1.2362 -0.8664 -0.5612 -0.3921 -0.2452 -0.0991 0.0329 0.1778 0.3185 0.4755 0.6152 0.9219	IN.= .48E0 3.8665 PSI CS -0.0778 -0.0651 -0.0588 -0.0553 -0.0538 -0.0627 -0.0534 -0.0590 -0.0588 -0.0638	CY 0.5921-0. 0.4703-0. 0.4105-0. 0.3748-0. 0.3627-0. 0.4541-0. 0.4236-0. 0.4214-0. 0.4719 0. 0.4505-0. 0.3965 0.	RUN CR CAT .0006 0.31 .0005 0.31 .0005 0.31 .0007 0.31 .0007 0.31 .0007 0.31 .0000 0.31 .0000 0.31 .0000 0.32	POJ/P1 NO. 028026 CPB 40 0.1737 15 0.1719 26 0.1716 25 0.1719 05 0.1715 12 0.1710 17 0.1706 44 0.1705 77 0.1708 05 0.1710	CAF 0.1403 0.1397 0.1410 0.1406 0.1389 0.1402 0.1411 0.1439 0.1469 0.1495 0.1525 0.1553	162. 162. 162. 162. 162. 162. 162. 162.

MO	DEL 946.	2 CON	FIG0000	H	ACH 1.75	PHI =	90.	
G=	8.29 PS	I RE PER	IN.= .48E0	6 T0=	90. DEG.F	P0J/P1	rs = 40	•
PO	= 197.0	CMHG PTS=	3.8665 PSI		RUN	NO. 028026	59151	
ALPHA	CN	CM	cs	CY	CR CA	т срв	CAF	สบท
4.12	0.2155	-1.2965	-0.1209	0.8887	0.0010 0.3	207 0.1791	0-1416	163.
3.09	0.1556		-0.1265		0.0007 0.3			163.
2.05	0.1000	-0.5726	-0.1136	0.8231	0.0015 0.3			163.
1.52	0.0718	-0.4055	-0.1284	0.9726-		164 0.1733		163.
_	0.0464		-0.1152		0.0007 0.3			163.
0.48			-0.1195		-0.0001 C.3			163.
	-0.001		-0.1076		0.0015 0.3			163.
	-0.027		-0.1132		-0.0008 0.3			163.
	-0.0519		-0.1123		0.0010 0.3			163.
	-0.0782		-0.1199		0.0004 0.3			163.
	-0-1046		-0.1106		0.0008 0.3			163.
	-0.158		-0.1214		0.0009 0.3			163.
-4.16	-0.215	5 1.2898	-0.1144	0.8494	0.0027 0.3	349 0.2133	0.1011	163.
	DEL 946.		FIG0000 IN.= .48E0		ACH 1.75 90. DEG.F	PHI =	•	•
Q=	8.29 P	SI RE PER		6 TO=	90. DEG.F	_	rs = 80	•
Q=	8.29 P	SI RE PER	IN.= .48E0	6 TO=	90. DEG.F	P0J/P1	rs = 80	
Q= P0	8.29 PS	SI RE PER CMHG PTS=	IN.= .48E0 3.8665 PSI	6 TO=	90. DEG.F	POJ/P1 NO. 028026 T CPB	FS = 80 59152 CAF	• RUN 164•
Q= PO ALPHA	8.29 PS = 107.0 CN	SI RE PER CMHG .PTS= CM 3 -1.4105	IN.= .48E0 3.8665 PSI CS	6 TO= CY 1.7178	90. DEG.F RUN CR CA	POJ/P1 NO. 028026 T CPB 308 0.1819	FS = 80 59152 CAF 0.1489	RUN
Q= P0 ALPHA 4•12	8.29 PS = 107.0 CN 2 0.229 0 0.164	SI RE PER CMHG PTS= CM 3 -1.4105 9 -0.9846	IN.= .48E0 3.8665 PSI CS -0.2340	6 TO= CY 1.7178 1.7069	90. DEG.F RUN CR CA 0.0015 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811	rs = 80 59152 CAF 0.1489 0.1487	RUN 164.
Q= PO ALPHA 4-12 3-10	E 8.29 PS E 107.0 CN CN CN CN CN CN CN CN CN CN	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317	CY 1.7178 1.7069 1.7463 1.7602	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0012 0.3	POJ/PI NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784	TS = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458	RUN 164. 164. 164.
Q= PO ALPHA 4.12 3.10 2.06	8.29 P: 1= 107.0 CN 2: 0.229: 0: 0.164: 0: 0.103: 0: 0.074:	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352	CY 1.7178 1.7069 1.7463 1.7602 1.7813	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0012 0.3 0.0012 0.3	POJ/PT NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763	TS = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1493	RUN 164. 164. 164. 164.
Q= PO ALPHA 4-12 3-10 2-06 1-52 1-00 0-50	8.29 PS = 107.0 CN 2 0.229 0 0.164 0 0.103 2 0.074 0 0.046 0 0.021	CMHG .PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.2469 9 -0.1091	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763 261 0.1742	TS = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1493 0.1519	RUN 164. 164. 164. 164.
Q= P0 ALPHA 4.12 3.10 2.06 1.52 1.50 0.50 -0.03	8.29 PS = 107.0 CN 2. 0.229 0.164 0.0103 1. 0.074 0.0046 0.021 30.004	CMHG .PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.2469 9 -0.1091 6 0.0407	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0012 0.3 0.0015 0.3 0.0016 0.3 0.0019 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763 261 0.1742 275 0.1724	S = 80 S9152 CAF 0.1489 0.1487 0.1438 0.1458 0.1493 0.1519 0.1552	RUN 164. 164. 164. 164. 164.
Q= PO ALPHA 4.12 3.10 2.06 1.52 1.50 0.50 -0.03	8.29 PS = 107.0 CN CN 2 0.229 0.164 0.074 0.046 0.021 3 -0.004 5 -0.004	CMHG .PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.2469 9 -0.1091 6 0.0407 0 0.1739	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389 -0.2413	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864 1.8049	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0012 0.3 0.0015 0.3 0.0016 0.3 0.0019 0.3 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1763 261 0.1742 275 0.1724 283 0.1715	S = 80 S9152 CAF 0.1489 0.1487 0.1438 0.1493 0.1519 0.1552 0.1568	RUN 164. 164. 164. 164. 164. 164.
Q= P0 ALPHA 4.12 3.10 2.06 1.52 1.00 -0.03 -0.55 -1.08	8.29 PS = 107.0 CN 2 0.229 0 0.164 0 0.103 0 0.074 0 0.046 0 0.021 3 -0.004 6 -0.029 3 -0.055	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.2456 9 -0.1091 0.0407 0.1739 0.3265	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389 -0.2413 -0.2404	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864 1.8049 1.8085	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3 0.0016 0.3 0.0019 0.3 0.0011 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1763 261 0.1742 275 0.1724 283 0.1715 315 0.1710	TS = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1519 0.1519 0.1552 0.1568 0.1605	RUN 164. 164. 164. 164. 164. 164. 164.
Q= P0 ALPHA 4.12 3.10 2.06 1.52 1.00 -0.03 -0.55 -1.08 -1.59	8.29 PS 1= 107.0 CN	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.24156 9 -0.1091 6 0.0407 0 0.1739 8 0.3265 2 0.4874	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389 -0.2413 -0.2404 -0.2342	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864 1.8049 1.8085 1.7583	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3 0.0016 0.3 0.0019 0.3 0.0011 0.3 0.0029 0.3	POJ/P1 NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763 261 0.1742 275 0.1724 283 0.1715 315 0.1710 339 0.1714	S = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1493 0.1519 0.1552 0.1568 0.1605 0.1626	RUN 164. 164. 164. 164. 164. 164. 164.
Q= P0 ALPHA 4.12 3.10 2.06 1.52 1.00 0.50 -0.03 -0.56 -1.59 -2.11	8.29 PS 1= 107.0 CN 1 0.229 0 0.164 0 0.103 1 0.074 0 0.021 3 -0.004 0 -0.029 3 -0.055 0 -0.083 -0.111	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.24156 9 -0.1091 6 0.0407 0 0.1739 8 0.3265 2 0.4874 6 0.6616	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389 -0.2413 -0.2404 -0.2342 -0.2420	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864 1.8049 1.8085 1.7583 1.8131	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3 0.0019 0.3 0.0019 0.3 0.0011 0.3 0.0029 0.3 0.0032 0.3	POJ/PT NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763 261 0.1742 275 0.1724 283 0.1715 315 0.1710 339 0.1714 376 0.1724	TS = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1493 0.1519 0.1552 0.1568 0.1605 0.1626 0.1652	RUN 164. 164. 164. 164. 164. 164. 164. 164.
9= P0 ALPHA 4.12 3.10 2.06 1.52 1.00 0.50 -0.03 -1.08 -1.08 -2.11 -3.13	8.29 PS 1= 107.0 CN	CMHG PTS= CM 3 -1.4105 9 -0.9846 7 -0.5926 4 -0.4156 5 -0.2469 9 -0.1091 6 0.0407 0 0.1739 8 0.3265 2 0.4874 6 0.6616 7 1.0367	IN.= .48E0 3.8665 PSI CS -0.2340 -0.2317 -0.2352 -0.2363 -0.2388 -0.2385 -0.2389 -0.2413 -0.2404 -0.2342	CY 1.7178 1.7069 1.7463 1.7602 1.7813 1.7895 1.7864 1.8049 1.8085 1.7583 1.8131	90. DEG.F RUN CR CA 0.0015 0.3 0.0023 0.3 0.0015 0.3 0.0015 0.3 0.0016 0.3 0.0016 0.3 0.0019 0.3 0.0011 0.3 0.0029 0.3	POJ/PT NO. 028026 T CPB 308 0.1819 297 0.1811 249 0.1811 242 0.1784 256 0.1763 261 0.1742 275 0.1724 283 0.1715 339 0.1714 376 0.1724 417 0.1740	S = 80 59152 CAF 0.1489 0.1487 0.1438 0.1458 0.1458 0.1519 0.1552 0.1568 0.1605 0.1626 0.1652 0.1677	RUN 164. 164. 164. 164. 164. 164. 164.

HODEL 946.2	CON	FIG00	AM 00	CH 2.0	0	PHI =	•	
C= 8.13 PSI	RE PER	IN.= .48	E06 TO=	90. Di	EG.F	P0J/P	TS =	•
PO= 118.0 C	HG PTS=	2.9018 P	12		RUN NO	. 00503	69102	
ALPHÀ CN	CK	cs	CY	CR	CAT	СРВ	CAF	RUN
4.05 0.2023	-1.1962	0.0006	-0.0462-	0.0038	0.3023	0.1487	0.1536	165.
3.03 0.1507	-0.8881	0.0009	-0.0448-	0.0027	0.3001	0.1432	0.1569	165.
2.00 0.1005	-0.5943	-0.0017	-0.0203-	0.0021	0.2966	0.1417	0.1549	165.
1.46 0.0706	-0.4137	-0.0040	0.0022-	0.0015	0.2954	0.1434	051520	165.
0.94 0.0454	-0.2680		-0.0247-	0.0022	0.2947	0.1458	0.1488	165.
0.43 0.0176	-0.0902		-0.0217-					
-0.09 -0.0082		0.0003	-0.0359-					
-0.60 -0.0280		-0.0014	-0.0215-					
-1.12 -0.0525		-0.0016	-0.0215-					
-1.64 -0.0737		-0.0011	-0.0239			0.1501		
-2.15 -0.0962		0.0001	-0.0342-					
-3.19 -0.1451	0.8125		-0.0329-					
-4.21 -0.1988	1.1343	0.	-0.0273	0.0004	0.3013	0.1510	0.1504	165.
MODEL 946.2	CONF			CH 2.00		PHI =	• rc –	10
Q= 8.13 PSI	RE PER	IN.= .488	:06 TO=	CH 2.00	EG.F	POJ/P	rs =	10.
	RE PER	IN.= .488	:06 TO=		EG.F		rs =	10.
Q= 8.13 PSI	RE PER	IN.= .488	:06 TO=		EG.F	POJ/P	rs =	10. RUN
Q= 8.13 PSI PO= 118.0 CA	RE PER	IN.= .488 2.9018 FS	=06 TO=	90. DE	EG&F RUN NO. Cat	POJ/P	rs = 69103 Caf	RUN
Q= 8.13 PSI PO= 118.0 CF ALPHA CN	RE PER HHG PTS=	IN.= .48E 2.9018 FS CS -0.0005	E06 T0=	90. DE	EG&F RUN NO CAT 0.3128	POJ/P 005036 CP8	rs = 69103 Caf 0.1574	RUN 166.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687	RE PER HHG PTS= CM -1.0316	IN.= .488 2.9018 FS CS -0.0005 -0.0035	CY -0+0181-	90. DE CR 0.0015 0.0012	EG.F RUN NO. CAT 0.3128 0.3038	POJ/P 005036 CPB 0.1554 0.1499	TS = 69103 CAF 0.1574	RUN 166•
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408	RE PER HHG PTS= CM -1.0316 -0.7201	IN.= .488 2.9018 FS CS -0.0005 -0.0035 -0.0029	CY -0.0181- 0.0065-	90. DE	EG.F RUN NO. CAT 0.3128 0.3038 0.2989	POJ/P . 005036 CPB 0.1554 0.1499 0.1454	TS = 69103 CAF 0.1574 0.1538 0.1535	RUN 166• 166•
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124	RE PER THG PTS = CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026	CY -0.0181- 0.00650.0020- 0.00800.0043	90. DE CR 0.0015 0.0012 0.0001 0.0001	CAT 0.3128 0.3038 0.2989 0.2976 0.2949	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1479	TS = 69103 CAF 0.1574 0.1538 0.1535 0.1519	RUN 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088	RE PER HG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039	CY -0.0181- 0.00650.0020- 0.0080-	90. DE CR 0.0015 0.0012 0.0001 0.0001	CAT 0.3128 0.3038 0.2989 0.2976 0.2949	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1479	TS = 69103 CAF 0.1574 0.1538 0.1535 0.1519	RUN 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339	RE PER HG PTS = CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017	CY -0.0181- 0.00650.0020- 0.00800.0043 0.00420.0115	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0.	CAT 0.3128 0.3038 0.2989 0.2976 0.2949 0.2933 0.2925	POJ/P . 005036 CPB 0.1554 0.1459 0.1457 0.1479 0.1493 0.1501	TS = 69103 CAF 0.1574 0.1538 0.1539 0.1469 0.1440 0.1424	RUN 166. 166. 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339 -0.62 -0.0538	RE PER HG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226 0.3162	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017 -0.0023	CY -0.0181- 0.00650.0020- 0.00800.0043 0.00420.01150.0097	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0.	CAT 0.3128 0.3038 0.2989 0.2974 0.2933 0.2925 0.2923	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1479 0.1493 0.1501 0.1503	CAF CAF C.1574 C.1538 C.1539 C.1469 C.1469 C.1424 C.1424	RUN 166. 166. 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339 -0.62 -0.0538 -1.14 -0.0816	RE PER HG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226 0.3162 0.4924	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017 -0.0023 -0.0025	CY -0.0181- 0.00650.0020- 0.00800.0043 0.00420.01150.0097 -0.0116	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0.	CAT 0.3128 0.3038 0.2989 0.2976 0.2933 0.2925 0.2923	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1479 0.1493 0.1501 0.1503 0.1509	CAF CAF C.1574 C.1538 C.1539 C.1469 C.1460 C.1424 C.1421 C.1428	RUN 166. 166. 166. 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339 -0.62 -0.0538 -1.14 -0.0816 -1.66 -0.1054	RE PER THG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226 0.3162 0.4924 0.6224	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017 -0.0023 -0.0025 -0.0016	CY -0.0181- 0.00650.00200.0043 0.00420.0115 -0.0097 -0.0116	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0. 0.0003	CAT 0.3128 0.3038 0.2989 0.2976 0.2933 0.2925 0.2923 0.2923	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1493 0.1501 0.1503 0.1509 0.1518	CAF C.1574 C.1574 C.1538 C.1519 C.1469 C.1424 C.1421 C.1428 C.1428	RUN 166. 166. 166. 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339 -0.62 -0.0538 -1.14 -0.0816 -1.66 -0.1054 -2.16 -0.1272	RE PER HHG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226 0.3162 0.4924 0.6224 0.7467	IN.= .488 2.9018 FS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017 -0.0023 -0.0025 -0.0016 -0.0027	CY -0.0181- 0.00650.0020- 0.00800.0043 0.00420.0115 -0.0097 -0.0116 -0.0164	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0. 0.0003 0.0003 0.0003	CAT 0.3128 0.3038 0.2989 0.2976 0.2949 0.2933 0.2925 0.2923 0.2923 0.2943	POJ/P . 005036 . CPB 0.1554 0.1499 0.1454 0.1457 0.1479 0.1493 0.1501 0.1503 0.1508 0.1518	TS = 69103 CAF 0.1574 0.1538 0.1539 0.1469 0.1424 0.1424 0.1428 0.1428	RUN 166. 166. 166. 166. 166. 166. 166.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.03 0.1738 3.01 0.1223 1.98 0.0687 1.45 0.0408 0.93 0.0124 0.41 -0.0088 -0.10 -0.0339 -0.62 -0.0538 -1.14 -0.0816 -1.66 -0.1054	RE PER HG PTS= CM -1.0316 -0.7201 -0.3918 -0.2256 -0.0417 0.0708 0.2226 0.3162 0.4924 0.6224 0.7467 1.0335	IN.= .488 2.9018 PS CS -0.0005 -0.0035 -0.0029 -0.0037 -0.0026 -0.0039 -0.0017 -0.0023 -0.0025 -0.0016	CY -0.0181- 0.00650.00200.0043 0.00420.0115 -0.0097 -0.0116	90. DE CR 0.0015 0.0012 0.0001 0.0001 0.0002 0. 0. 0.0003 0.0003 0.0008	CAT 0.3128 0.3038 0.2989 0.2976 0.2949 0.2933 0.2925 0.2923 0.2927 0.2947 0.2947	POJ/P . 005036 CPB 0.1554 0.1499 0.1454 0.1457 0.1479 0.1479 0.1501 0.1503 0.1503 0.1518 0.1530 0.1538	CAF 0.1574 0.1538 0.1535 0.1519 0.1469 0.1424 0.1424 0.1421 0.1428 0.1425	RUN 166. 166. 166. 166. 166. 166. 166. 16

HODEL	946.2	CONFIG.	.0000	MACH 2.00) P	HI =	•
Q= 8.13	3 PSI RE	PER IN.=	-48E06 1	10= 90. DE	G _e f P	OJ/PTS =	20•
PO= 11	8.0 CMHG P	TS= 2.90	18 PSI		RUN NO. 0	05036910	4
ALPHA (CN CH	С	S CY	CR	CAT	СРВ СА	F RUN
4.03 0.3	1643 -0.9	759 -0.0	019 -0.00	26-0.0014	0.3175 0.	1576 0.1	599 167.
3.00 0.1	1114 -0.6	489 -0.0	024 -0.00	002-0-0009	0.3125 0.	1519 0.1	606 167.
		260 -0.0		79-0.0012			
		337 -0.0		76-0.0009			
_		226 -0.0		32-0.0007			
0.41 -0.6		236 -0.0		59 0.0005			
-0.11 -0.0	-	737 -0.0		66-0.0001			
-0.62 -0.0		039 -0.0		27 0.0001			
-1.15 -0.0		360 -0.0		76 0.0007			
-1.66 -0.1		042 -0.0	-	26 0.0009			
-2.17 -0.1		387 -0.0		18 0.0006			
-3.20 -0.1		415 -0.0		64 0.0005			
-4.23 -0.2	2475 1-4	893 -0.0	033 -0.00	95 0.0016	0.3068 0.	1560 0.1	508 167.
MODEL 9		CONFIG. PER IN.=	.0000 .48E06	MACH 2.00		HI = OJ/PTS =	•
Q= 8.13		PER IN.=	.48E06 T	MACH 2.00		OJ/PTS =	40.
Q= 8.13 PO= 118	3 PSI RE	PER IN.= TS= 2.90	.48E06 T	MACH 2.00	G.F P	OJ/PTS =	40 .
Q= 8.13 PO= 118	3 PSI RE 8.0 CMHG P	PER IN.= TS= 2.90	.48E06 T	MACH 2.00	G.F P	03/PTS =	40 .
Q= 8.13 PO= 118	3 PSI RE B.O CMHG P CN CM	PER IN.= TS= 2.90	•48E06 T 18 PSI S CY	MACH 2.00	G.F P RUN NO. O	0J/PTS = 05036910 CPB CA	40. 5 F RUN
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 0633 -0.3	PER IN.= YS= 2.90 C 921 -0.0 215 -0.0	•48E06 T 18 PSI S CY 056 0.03	MACH 2.00 TO= 90. DE	G.F P RUN NO. 0 CAT 0.3224 0.	0J/PTS = 05036910 CPB CA 1593 0-1	40. 5 F RUN 631 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 0633 -0.3	PER IN.= YS= 2.90 C 921 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04	MACH 2.00 TO= 90. DE CR 114-0.0004 165-0.0005	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0.	0J/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1	40. 5 F RUN 631 168. 646 168. 628 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 3633 -0.3 0091 0.0 0194 0.1	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02	MACH 2.00 TO= 90. DE CR 114-0.0004 65-0.0005 03 0.0003 71 0.0009	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1 1488 0.1	40. 5 F RUN 631 168. 646 168. 628 168. 585 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.90 -0.0	3 PSI RE B.O CMHG P CN CM 1202 -0.6 3633 -0.3 0091 0.0 0194 0.1 0524 0.4	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 283 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02	MACH 2.00 O= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1 1488 0.1 1494 0.1	40. 5 F RUN 631 168. 646 168. 628 168. 585 168. 585 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.90 -0.0 0.38 -0.0	3 PSI RE B.O CMHG P CN CM 1202 -0.6 3633 -0.3 30091 0.0 0194 0.1 0524 0.4 0709 0.5	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 283 -0.0 120 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 053 0.02	MACH 2.00 O= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002	CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0. 0.3036 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1 1488 0.1 1494 0.1 1504 0.1	40. 5 F RUN 631 168. 646 168. 628 168. 585 168. 585 168. 551 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.90 -0.0 0.38 -0.0 -0.14 -0.1	3 PSI RE B.0 CMHG P CN CM 1202 -0.6 3633 -0.3 3091 0.0 0194 0.1 0524 0.4 0709 0.5 1061 0.7	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 283 -0.0 120 -0.0 621 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 053 0.02	MACH 2.00 O= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002 17-0.0001 97-0.0002	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0. 0.3036 0. 0.3031 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1 1488 0.1 1494 0.1 1504 0.1 1508 0.1	40. 5 F RUN 631 168. 646 168. 585 168. 585 168. 551 168. 532 168. 532 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.94 0.0 0.42 -0.0 0.38 -0.0 -0.14 -0.1 -0.65 -0.1	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 3633 -0.3 0091 0.0 0194 0.1 0524 0.4 0709 0.5 1061 0.7 1272 0.8	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 283 -0.0 120 -0.0 621 -0.0 704 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 058 0.02 059 0.02	MACH 2.00 O= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002 17-0.0001 97-0.0002 128 0.0012	CAT 0.3224 0. 0.3182 0. 0.3182 0. 0.3073 0. 0.3045 0. 0.3036 0. 0.3031 0. 0.3029 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1536 0.1 1492 0.1 1488 0.1 1494 0.1 1504 0.1 1508 0.1 1524 0.1	40. 5 F RUN 631 168. 646 168. 585 168. 585 168. 551 168. 532 168. 532 168. 532 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.38 -0.0 -0.14 -0.1 -0.65 -0.1 -1.16 -0.1	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 30633 -0.3 0091 0.0 0194 0.1 0524 0.4 0709 0.5 1061 0.7 1272 0.8 1498 0.9	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 283 -0.6 120 -0.0 621 -0.0 704 -0.0 957 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 058 0.02 058 0.02 059 0.02	MACH 2.00 O= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002 17-0.0001 97-0.0002 28 0.0012 34 0.0009	CAT 0.3224 0. 0.3182 0. 0.3182 0. 0.3073 0. 0.3073 0. 0.3073 0. 0.3075 0. 0.3075 0. 0.3075 0. 0.3075 0. 0.3075 0. 0.3075 0. 0.3075 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1596 0.1 1492 0.1 1488 0.1 1504 0.1 1508 0.1 1524 0.1 1538 0.1	40. F RUN 631 168. 646 168. 585 168. 585 168. 551 168. 532 168. 532 168. 532 168. 632 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.38 -0.0 -0.14 -0.1 -0.65 -0.1 -1.68 -0.1	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 3633 -0.3 3091 0.0 3194 0.1 37524 0.4 3709 0.5 1061 0.7 1272 0.8 1498 0.9 1802 1.1	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 120 +0.0 621 -0.0 704 -0.0 957 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 058 0.02 058 0.02 058 0.02 058 0.02	MACH 2.00 TO= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 17-0.0001 97-0.0002 28 0.0012 34 0.0009 37 0.0006	CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0. 0.3036 0. 0.3031 0. 0.3029 0. 0.3020 0. 0.3028 0.	OJ/PTS = 05036910 CPB CA 1593 0.1 1596 0.1 1498 0.1 1494 0.1 1504 0.1 1508 0.1 1524 0.1 1538 0.1 1542 0.1	40. F RUN 631 168. 646 168. 628 168. 585 168. 585 168. 551 168. 552 168. 552 168. 6523 168. 6523 168. 6524 168.
Q= 8.13 PO= 118 ALPHA (0.12.98 0.00 1.94 0.00 1.42 -0.00 0.38 -0.00 -0.14 -0.11 -0.65 -0.12 -1.66 -0.12 -1.68 -0.12 -2.20 -0.22	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 3633 -0.3 3091 0.0 0194 0.1 0524 0.4 0709 0.5 1061 0.7 1272 0.8 1498 0.9 1802 1.1	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 283 -0.6 120 -0.0 621 -0.0 957 -0.0 970 -0.0 024 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 058 0.02 056 0.01 033 -0.00 014 -0.02 067 0.02	MACH 2.00 TO= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 59 0.0002 17-0.0001 97-0.0001 97-0.0001 97-0.0006 03 0.0009	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0. 0.3036 0. 0.3031 0. 0.3029 0. 0.3029 0. 0.3028 0. 0.3026 0.	OJ/PTS = 05036910 CPB	40. F RUN 631 168. 646 168. 628 168. 551 168. 551 168. 532 168. 532 168. 623 168. 648 168. 485 168. 487 168.
Q= 8.13 PO= 118 ALPHA (4.00 0.1 2.98 0.0 1.94 0.0 1.42 -0.0 0.38 -0.0 -0.14 -0.1 -0.65 -0.1 -1.68 -0.1	3 PSI RE 8.0 CMHG P CN CM 1202 -0.6 3633 -0.3 3091 0.0 3194 0.1 3524 0.4 3709 0.5 1061 0.7 1272 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8 1498 0.8	PER IN.= TS= 2.90 C 921 -0.0 215 -0.0 172 -0.0 937 -0.0 120 +0.0 621 -0.0 704 -0.0 957 -0.0	.48E06 T 18 PSI S CY 056 0.03 062 0.03 070 0.04 058 0.02 058 0.02 058 0.02 059 0.01 033 -0.00 014 -0.02 067 0.02 067 0.02 067 0.02	MACH 2.00 TO= 90. DE CR 14-0.0004 65-0.0005 03 0.0003 71 0.0009 17-0.0001 97-0.0002 28 0.0012 34 0.0009 37 0.0006	G.F P RUN NO. 0 CAT 0.3224 0. 0.3182 0. 0.3120 0. 0.3073 0. 0.3045 0. 0.3036 0. 0.3031 0. 0.3029 0. 0.3020 0. 0.3020 0. 0.3020 0. 0.3026 0. 0.3026 0.	OJ/PTS = 05036910 CPB CA 1593 0-1 1536 0-1 1492 0-1 1488 0-1 1504 0-1 1508 0-1 1524 0-1 1524 0-1 1542 0-1 1542 0-1	40. F RUN 631 168. 646 168. 628 168. 551 168. 552 168. 523 168. 523 168. 6482 168. 485 168. 479 168.

HODEL 9	46.2 CON	FIG0000) HA	CH 2.00	PHI =	•	
Q= 8.13	PSI RE PER	IN.= .48E0)6 TU=	90. DEG.F	P0J/P1	rs =	80.
PO= 118	.O CMHG PTS=	2.9018 PSI	ī	RUN	NO. 00 5 036	9106	
ALPHA C	н сн	cs	CY	CR CAT	CPB	CAF	RUN
3.94 0.0	201 -0.0138	-0.0087		0.0006 0.32			169.
2.92 -0.0		-0.0103		0.0001 0.32			169.
1.89 -0.0		-0.0063		0.0006 C.31			169.
1.36 -0.1		-0.0079		0.0006 0.31			169.
0.84 -0.1		-0.0071		0.0005 0.31			169.
0.32 -0.1		-0.0034		0.0004 0.30			169.
-0.19 -0.2		-0.0034		0.0010 0.30			169.
-0.71 -0.2		-0.0047		0.0012 0.30			169.
-1.22 -0.2		-0.0010		0.0014 0.30			169.
-1.75 -0.3		-0.0027		0.0014 0.30			169.
-2.25 -0.3		-0.0012		0.0019 0.30			169.
-3.28 -0.3		-0.0042		0.0025 0.30			169.
-4.32 -0.4	337 2.0773	-C.0041	-0.0004	0.0016 0.31	30 0.1552	0.15/8	169.
MODEL 9 Q≈ 8.13		FIG0000		CH 2.00	PH ! =	15. (S =	•
Q= 8.13		IN.= .48E)6 TO=	90. DEG.F	-	î\$ =	•
Q= 8.13	PSI RE PER .O CMHG PTS=	IN.= .48E)6 TO=	90. DEG.F	POJ/P1	î\$ =	• RUN
Q= 8.13 PO= 118 ALPHA C	PSI RE PER .O CMHG PTS= N CM	IN.= .48E0 2.9018 PSI	20 00= 1 1 2	90. DEG.F RUN CR CAT	POJ/P1 NO. 005038 CP8	is = 59107 Caf	-
Q= 8.13 P0= 118	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026	IN.= .48E0	06 T0= I EY -0•0004-	90. DEG.F RUN CR CAT	POJ/P1 NO. 005038 CPB	fS = 59107 CAF 2.1529	170.
Q= 8.13 PO= 118 ALPHA C 4.10 0.2	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811	IN.= .48EC 2.9018 PSI CS -0.0029	CY -0.0004-	90. DEG.F RUN CR CAT	POJ/P1 NO. 005038 CPB 07 0.1478 49 0.1436	FS = 59107 CAF 9.1529 0.1513	-
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953	IN.= .48E0 2.9018 PSI CS -0.0029 -0.0001	CY -0.00040.03400.0031-	90. DEG.F RUN CR CAT 0.0009 0.30 0.0007 0.29	POJ/P1 NO. 005038 CPB 07 0.1478 49 0.1436 46 041426	75 = 59107 CAF 2.1529 0.1513 0.1522	170. 170. 170.
Q= 8.13 PO= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031	IN.= .48E0 2.9018 PSI CS -0.0029 -0.0001 -0.0028	CY -0.00040.03400.0031-	90. DEG.F RUN CR CAT 0.0009 0.30 0.0007 0.29	POJ/PI NO. 005038 CPB 07 0.1478 49 0.1436 46 011426 22 0.1442	S = 59107 CAF 0.1529 0.1513 0.1522 0.1480	170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0	PSI RE PER .0 CMHG PTS= N CH 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 47,9 -0.2796	IN.= .48E0 2.9018 PSI CS -0.0029 -0.0001 -0.0028 -0.0032	EY -0.00040.03400.00140.0002- 0.0118	90. DEG.F RUN CR CAT 0.0009 0.309 0.0007 0.29 0.0003 0.29 0.0003 0.29 0.0002 0.29 0.0002 0.29	POJ/P1 NO. 0G5038 CPB 07 0.1478 49 0.1436 46 041426 22 0.1442 06 0.1454	CAF 0.1529 0.1513 0.1522 0.1480 0.1452 0.1436	170. 170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 1.00 0.0 0.48 0.0 -0.04 -0.0	PSI RE PER .0 CMHG PTS= N CH 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 479 -0.2796 258 -0.1633 013 0.0078	IN.= .48E0 2.9018 PSI CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033	EY -0.00040.03400.00140.0002- 0.0118 -0.0018	90. DEG.F RUN CR CAT 0.0009 0.309 0.0007 0.29 0.0003 0.29 0.0003 0.29 0.0002 0.29 0.0001 0.29	POJ/P1 NO. 0G5038 CPB 07 0.1478 49 0.1436 46 041426 02 0.1442 06 0.1454 05 0.1469 17 0.1479	CAF 0.1529 0.1513 0.1522 0.1430 0.1438	170. 170. 170. 170. 170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 1.00 0.0 0.48 0.0 -0.04 -0.0 -0.55 -0.0	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 479 -0.2796 258 -0.1633 013 0.0078 255 0.1464	IN.= .48E0 2.9018 PS1 CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033 -0.0045 -0.0030 -0.0043	EY -0.00040.03400.00310.00140.0002- 0.0118 -0.0018	90. DEG.F RUN CR CAT 0.0009 0.30 0.0007 0.29 0.0007 0.29 0.0003 0.29 0.0002 0.29 0.0002 0.29 0.0005 0.29 0.0005 0.29	POJ/P1 NO. 0G5038 CPB 07 0.1478 49 0.1436 46 041426 22 0.1442 06 0.1454 05 0.1469 17 0.1479 09 0.1487	CAF 0.1529 0.1513 0.1522 0.1430 0.1438 0.1438	170. 170. 170. 170. 170. 170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 1.00 0.0 0.48 0.0 -0.48 0.0 -0.55 -0.0 -1.08 -0.0	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 47,9 -0.2796 258 -0.1633 013 0.0078 255 0.1464 552 0.3377	IN.= .48E0 2.9018 PS1 CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033 -0.0045 -0.0030 -0.0043	EY -0.00040.03400.00310.00140.0018- 0.0018 0.0079 0.0218-	90. DEG.F RUN CR CAT 0.0009 0.30 0.0007 0.29 0.0007 0.29 0.0003 0.29 0.0002 0.29 0.0001 0.29 0.0005 0.29 0.0005 0.29	POJ/P1 NO. 0G5038 CPB 07 0.1478 49 0.1436 46 0.1442 22 0.1442 05 0.1469 17 0.1479 09 0.1487	CAF 0.1529 0.1513 0.1522 0.1430 0.1452 0.1438 0.1428 0.1428	170. 170. 170. 170. 170. 170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 0.48 0.0 0.48 0.0 -0.55 -0.0 -1.08 -0.0 -1.59 -0.0	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 479 -0.2796 258 -0.1633 013 0.0078 255 0.1464 552 0.3377 744 0.4250	IN.= .48E0 2.9018 PS1 CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033 -0.0045 -0.0030 -0.0043 -0.0060 -0.0057	CY -0.00040.03400.00310.00140.0002- 0.0118 -0.0018 0.0079 0.0218- 0.0179	90. DEG.F RUN CR CAT 0.0009 0.300 0.0007 0.29 0.0003 0.29 0.0002 0.29 0.0005 0.29 0.0005 0.29 0.0005 0.29 0.0008 0.29	POJ/P1 NO. 0G5038 CPB 07 0.1478 49 0.1436 46 0.1442 06 0.1442 05 0.1469 17 0.1479 09 0.1487 09 0.1491 28 0.1492	CAF 0.1529 0.1513 0.1522 0.1430 0.1452 0.1436 0.1438 0.1422 0.1418	170. 170. 170. 170. 170. 170. 170. 170.
Q= 8.13 PO= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 1.00 0.0 0.48 0.0 -0.48 0.0 -0.55 -0.0 -1.08 -0.0 -1.59 -0.0 -2.10 -0.0	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 47,9 -0.2796 258 -0.1633 013 0.0078 255 0.1464 552 0.3377 744 0.4250 922 0.5067	IN.= .48E0 2.9018 PSI CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033 -0.0045 -0.0030 -0.0043 -0.0060 -0.0057 -0.0050	CY -0.00040.03400.00140.0002- 0.0118 -0.0018 0.0079 0.0218- 0.0179 0.0110	90. DEG.F RUN CR CAT 0.0009 0.30 0.0007 0.29 0.0003 0.29 0.0002 0.29 0.0001 0.29 0.0005 0.29 0.0002 0.29 0.0002 0.29 0.0005 0.29 0.0008 0.29 0.0008 0.29	POJ/PI NO. 005038 CPB 07 0.1478 49 0.1436 46 041426 22 0.1442 06 0.1454 05 0.1469 17 0.1479 09 0.1481 28 0.1491	CAF 0.1529 0.1513 0.1522 0.1430 0.1452 0.1438 0.1428 0.1428 0.1436 0.1440	170. 170. 170. 170. 170. 170. 170. 170.
Q= 8.13 P0= 118 ALPHA C 4.10 0.2 3.08 0.1 2.05 0.1 1.51 0.0 0.48 0.0 0.48 0.0 -0.55 -0.0 -1.08 -0.0 -1.59 -0.0	PSI RE PER .0 CMHG PTS= N CM 037 -1.2026 509 -0.8811 011 -0.5953 704 -0.4031 47,9 -0.2796 258 -0.1633 013 0.0078 255 0.1464 552 0.3377 744 0.4250 922 0.5967 432 0.8043	IN.= .48E0 2.9018 PS1 CS -0.0029 -0.0001 -0.0028 -0.0032 -0.0033 -0.0045 -0.0030 -0.0043 -0.0060 -0.0057	EY -0.00040.03400.00140.0002- 0.0118 -0.0018 -0.0079 0.0218- 0.0179 0.0110 0.0216	90. DEG.F RUN CR CAT 0.0009 0.300 0.0007 0.29 0.0003 0.29 0.0002 0.29 0.0005 0.29 0.0005 0.29 0.0005 0.29 0.0008 0.29	POJ/PI NO. 005038 CPB 07 0.1478 49 0.1436 46 0.1442 02 0.1442 05 0.1469 17 0.1469 17 0.1487 128 0.1491 28 0.1491 50 0.1487	CAF 0.1529 0.1513 0.1522 0.1430 0.1452 0.1438 0.1428 0.1428 0.1440	170. 170. 170. 170. 170. 170. 170. 170.

MC	DEL	946.2		CONF	IG.	.0000	M	ACH 2.8	0	PHI =	15.	
Q=	8.13	B PSI	RE	PER	IN.=	.48E06	5 TO=	90. D	EG.F	P0J/P	TS =	10.
PC	= 110	8.0 CM	HG P	7\$=	2.90	18 PSI			RUN NO	. 00503	69108	
ALPHA	. (CN	CM	,	C:	S	CY	CR	CAT	CPB	CAF	RUN
÷.08	0.1	1838	-1.0	885	-0.0	224	0.1578	-0.0011	0.2973	0.1531	0-1442	2 171.
3.09	0.1	1304	-0.7	611	-0.0	171	0.1101-	-0.0010	0.2922	0.1494	0.1428	B 171.
2.02	0.0	2807	-0.4	717	-0.0	150	0.0909	-0.0007	0.2878	0.1472	0.1407	7 171.
1.49	0.0	0504	-0.2	804	-0.0	149	0.0875	-0.0012	9.2893	0.1479	0.1414	4 171.
0.98	0.0	225	-0.1	058	-0.0	150			0.2865			
0.49	0.0	0007	0.0	056	-0.0	127			0.2877			
-0.0					-0.0				0.2861			
-0.58					-0.0				0.2874			
-1.10		-			-0.0				0.2872			
-1.61					-0.0				0.2877			
~2.12					-0.0				0.2902			
-3.16					-0.0				0.2927			
-4.18	-0.7	2201	1.2	2882	-0.0	124	0.0716	0-0022	0.2987	0.1553	0+1434	4 171.
	_	946.2 3 PSI				.0000		4CH 2.0		PHI =	15 TS =	20.
Q=	8.13	_	RE	PER	IN.=	•48E06			EG.F		rs =	20.
Q=	: 8.13)= 118	B PSI	RE	PER	IN.=	.49E06			EG.F	POJ/P	rs =	20 . RUN
Q= PC ALPHA	: 8.13)= 118	B PSI B • O CMI	RE HG P	PER TS=	IN.= 2.90	•49E06	6 T0=	90. DI	EG.F RUN NO.	POJ/P1 005030 CPB	TS = 59109 CAF	RUN
Q= P0	: 8-13)= 118 . (0-1	B PSI	RE HG P CM -1.0	PER PTS=	IN.= 2.90	•49E06	CY 0.2486-	90. DI CR -0.0012	EG.F RUN NO	POJ/P1 . 005030 CPB 0.1560	TS = 59109 CAF 0-1526	RUN 5 172•
Q= PC ALPHA 4.06	8-13 = 118 (0-1 - 0-1	B PSI B.O CHI CN L699	RE HG P CM -1.0 -0.6	PER TS= 1 0180 6693	IN.= 2.90: C: -0.0:	.49E06	CY 0.2486- 0.1782-	90. DI CR -0.0012	EG.F RUN NO CAT 0.3086	POJ/P1 . 005030 CPB 0.1560 0.1529	FS = 59109 CAF 0.1526	RUN 5 172. 7 172.
Q= PC ALPHA 4.06 3.04 2.00	8-13 = 118 (0-1 - 0-1	3 PSI B.O CMI CN L699 L145 D603	RE CM -1.0 -0.6 -0.3	PER TS= 1 180 180 6693 1343	IN.= 2.902 C: -0.02 -0.03	.49E06	CY 0.2486- 0.1782- 0.1485- 0.1326-	90. DI CR -0.0012 -0.0013 -0.0014 -0.0013	CAT 0.3086 0.3028 0.2964 0.2964	POJ/P7 . 005030 CPB 0.1560 0.1529 0.1500 0.1499	TS = 59109 CAF 0.1526 0.1499 0.1464	RUN 5 172. 6 172. 6 172.
Q= PC ALPHA 4.06 3.04 2.00	8.13 9= 118 0 0.1 0 0.1 0 0.0 0 0.0 0 0.0	3 PSI B.O CMI CN L699 L145 D603	RE CM -1.0 -0.6 -0.3 -0.1	PER TS= 1 180 180 1843 1593	IN.= 2.90: C: -0.0: -0.0: -0.0:	.49E06	CY 0.2486- 0.1782- 0.1485- 0.1326-	90. DI CR -0.0012 -0.0013 -0.0014 -0.0013	EG.F RUN NO. CAT 0.3086 0.3028 0.2964	POJ/P7 . 005030 CPB 0.1560 0.1529 0.1500 0.1499	TS = 59109 CAF 0.1526 0.1499 0.1464	RUN 5 172. 6 172. 6 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.97	8-13 9= 118 0	3 PSI 3.0 CMI CN 1699 1145 7603 7317 70031 7178	RE CM -1.0 -0.6 -0.3 -0.1	PER TS= 1 180 180 1343 1343 1264	IN.= 2.90: C: -0.0: -0.0: -0.0: -0.0:	.49E06	CY 0.2486- 0.1782- 0.1485- 0.1394- 0.1394-	90. DI CR -0.0012 -0.0013 -0.0014 -0.0013 -0.0009 0.0007	CAT 0.3086 0.3028 0.2964 0.2964 0.2956 0.2934	POJ/P1 . 005030 CP8 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515	TS = 59109 CAF 0.1526 0.1499 0.1464 0.1465 0.1445	RUN 5 172. 6 172. 6 172. 5 172. 6 172. 8 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.97	8-13 9= 118 0	3 PSI 3.0 CMI CN 1699 1145 7603 7317 70031 7178	RE CM -1.0 -0.6 -0.3 -0.1 0.0 0.1	PER TS= 1 180 180 1843 1593 1264 1359	IN.= 2.903 C3 -0.03 -0.03 -0.04 -0.04	•49E06	CY 0.2486- 0.1485- 0.1485- 0.1326- 0.1394- 0.1199	90. DI CR -0.0012 -0.0013 -0.0014 -0.0013 -0.0009 -0.0007 -0.0010	CAT 0.3086 0.3028 0.2964 0.2964 0.2956 0.2934 0.2917	POJ/P1 . 005030 CPB 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1511	TS = 59109 CAF 0.1526 0.1496 0.1464 0.1465 0.1445 0.1416	RUN 5 172. 6 172. 6 172. 6 172. 6 172. 7 172. 8 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.44 -0.07	8 - 13 9 = 118 0 0 - 1 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0	3 PSI 3.0 CMI CN 1699 1145 10603 10317 10031 10178 10382 10651	RE CM -1.0 -0.6 -0.3 -0.1 0.0 0.1	PER TS= 1 180 693 343 593 264 359 395	IN.= 2.90 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.49E06	CY 0.2486- 0.1782- 0.1485- 0.1326- 0.1394- 0.1199 0.0984- 0.1135	90. DI CR -0.0012 -0.0013 -0.0019 -0.0009 -0.0007 -0.0010 0.0006	CAT 0.3086 0.3028 0.2964 0.2956 0.2956 0.2934 0.2917 0.2931	POJ/P1 . 005030 CPB 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1511 0.1514	CAF 0.1526 0.1496 0.1464 0.1465 0.1416 0.1416	RUN 5 172. 6 172. 6 172. 6 172. 7 172. 8 172. 8 172. 8 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.44 -0.07 -0.59	8.13 9= 118 0	3 PSI 3.0 CMI CN 1699 1145 0603 0317 0031 0178 0382 0651 0897	RE -1.0 -0.6 -0.3 -0.1 0.0 0.1	PER TS= 1180 1693 1343 1593 1264 1359 1395 1037	IN.= 2.90 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.49E06	CY 0.2486- 0.1782- 0.1485- 0.1326- 0.1399 0.0984- 0.1135 0.1144	90. DI CR -0.0012 -0.0013 -0.0019 -0.0009 -0.0007	CAT 0.3086 0.3028 0.2964 0.2964 0.2956 0.2934 0.2917 0.2931 0.2922	POJ/P1 . 005030 CPB 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1511 0.1514	CAF 0.1526 0.1496 0.1464 0.1465 0.1416 0.1416	RUN 5 172. 6 172. 6 172. 6 172. 7 172. 8 172. 8 172. 9 172. 9 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.97 -0.59 -1.10 -1.63	8.13 9= 118 0	B PSI B 0 CMI CN 1699 1145 20603 20317 2031 20178 20382 20651 20897	RE -1.0 -0.6 -0.3 -0.1 0.0 0.1 0.2	PER TS= 1 180 6693 1343 593 1264 359 395 037 1468 219	IN.= 2.90 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.49E06	CY 0.2486- 0.1782- 0.1326- 0.1394- 0.1199 0.0984- 0.1135 0.1144	90. DI CR -0.0012 -0.0013 -0.0009 0.0007 -0.0010 0.0007	CAT 0.3086 0.3028 0.2964 0.2966 0.2956 0.2931 0.2931 0.2922 0.2956	POJ/P1 . 005030 CP8 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1511 0.1514 0.1516	CAF 0.1526 0.1496 0.1466 0.1446 0.1446 0.1446 0.1446 0.1446 0.1436	RUN 5 172. 6 172. 6 172. 7 172. 8 172. 8 172. 7 172. 8 172.
Q= PC ALPHA 4.06 3.04 2.00 1.48 0.97 0.44 -0.07 -1.16 3-2.13	8.13 9 0.13 9 0.13	3 PSI 3.0 CMI 1699 1145 10603 1317 10031 10178 10897 1174 1372	RE -1.0 -0.6 -0.3 -0.1 0.0 0.1 0.2	PER TS= 1 180 6693 1343 593 1264 359 395 037 6468 219	IN.= 2.90 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.49E06 18 PSI 336 264 232 215 198 172 189 189 201 173	CY 0.2486- 0.1782- 0.1485- 0.1326- 0.1394- 0.1199 0.0984- 0.1135 0.1144 0.1242 0.1037	90. Di CR -0.0012 -0.0013 -0.0014 -0.0007 -0.0010 0.0006 0.0007	CAT 0.3086 0.3028 0.2964 0.2956 0.2956 0.2931 0.2931 0.2931 0.2956 0.2956	POJ/PT . 005036 CPB 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1514 0.1516 0.1520 0.1522	CAF 0.1526 0.1499 0.1464 0.1465 0.1416 0.1416 0.1416 0.1416 0.1416 0.1436	RUN 5 172. 6 172. 6 172. 7 172. 8 172. 7 172. 7 172. 8 172.
Q= PO ALPHA 4.06 3.04 2.00 1.48 0.97 -0.59 -1.10 -1.63	8.13 9 0.13 9 0.13	3 PSI 3.0 CMI 1699 1145 10603 1317 10031 10178 1082 10897 1174 1372 1886	RE HG P CM -1.0 -0.6 -0.3 -0.1 0.0 0.1 0.2 0.4 0.5 0.7	PER TS= 1180 1693 1343 1593 1264 1395 1468 1218 1218	IN.= 2.90 C: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.49E06 18 PSI 336 264 232 215 198 172 189 201 173 194	CY 0.2486- 0.1782- 0.1485- 0.1326- 0.1394- 0.1199 0.0984- 0.1135 0.1144 0.1242 0.1037	90. Di CR -0.0012 -0.0013 -0.0019 -0.0007 -0.0010 0.0006 0.0007 0.0011 0.0012 0.0015	CAT 0.3086 0.3028 0.2964 0.2966 0.2956 0.2931 0.2931 0.2922 0.2956	POJ/PT . 005036 CPB 0.1560 0.1529 0.1500 0.1499 0.1507 0.1515 0.1514 0.1514 0.1520 0.1522 0.1525	CAF 0.1526 0.1499 0.1466 0.1449 0.1416 0.1416 0.1416 0.1416 0.1431	RUN 5 172. 6 172. 6 172. 7 172. 7 172. 7 172. 8 172. 9 172. 9 172.

MODEL 946.2	CONF	IG0000	MA	ACH 2.0	ט	PH1 =	15.	
Q= 8.13 PSI	RE PER	IN.= .48E0	6 10=	90. DI	EG.F	POJ/P	rs =	40.
PO= 118.0 CF	HG PTS=	2.9018 PSI			RUN NO	. 00503	59110	
ALPHA CN	СМ	CS	CY	CR	CAT	CP8	CAF	RUN
4.04 0.1306	-0.7737	-0.0569	0,4358	C. 0001	0.3157	0.1567	0,1591	173.
3.02 0.0717	-0.3852	-0.0466	0.3391	0.0002	0.3092	0.1542	0.1550	
1.98 0.0138	-0.0123	-0.0400	0.2784	0.0001	0.3035	0.1509	0.1526	173.
1.44 -0.0168	0.1868	-0.0359			0.3028			
0.94 -0.0423	0.3439	-0.0373			U.2999			173.
0.41 -0.0708	0.5260	-0.0379			0.2992			
-0.09 -0.0963		-0.0349			0.2990			173.
-0.61 -0.1291		-0.0374			0,2997			
-1.13 -0.1466		-0.0329			0.2994			
-1.64 -0.1745		-0.0334			0.2993			
-2.16 -0.1946		-0.0348			0.3004			
-3.19 -0.2475		-0.0361			0.3023			
-4.22 -0.3027	1.9111	-0.0371	0.2668	0.0029	0.3084	0.1567	0.1518	173.
MODEL 946.2 Q= 8.13 PSI		FIG0000 IN.= .45E0		ACH 2.0		PHI =	15. TS =	80.
	RE PER	IN.= .45E0	6 TO=	ACH 2.0	EG.F		TS =	80•
Q= 8.13 PS1	RE PER	IN.= .45E0	6 TO=		EG.F	POJ/P	TS =	80• RUN
Q= 8.13 PSI P9= 118.0 CM ALPHA CN	RE PER IHG PTS=	1N.= .45E0 2.9018 PSI CS	6 TO=	90. D	EG.F RUN NO.	POJ/P . 005030 CPE	TS = 69111 CAF	RUN
Q= 8.13 PSI P9= 118.0 CN ALPHA CN 3.98 0.0369	RE PER HHG PTS= CM -0.1492	1N.= .45E0 2.9018 PSI CS -0.1004	6 TO≈ CY 0.7916	90. D	EG.F RUN NO. CAT 0.3187	POJ/P . 005036 CPE 0.1547	TS = 69111 CAF 0.1640	RUN 174.
Q= 8.13 PSI PQ= 118.0 CN ALPHA CN 3.98 0.0369 2.96 -0.0278	RE PER HHG PTS= CM -0.1492 0.3061	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794	6 TO= CY 0.7916 0.5883	90. Di	EG.F RUN NO. CAT 0.3187 0.3134	POJ/P . 005036 CPE 0.1547 0.1506	TS = 69111 CAF 0.1640 0.1628	RUN 174. 174.
Q= 8.13 PSI P9= 118.0 CN ALPHA CN 3.98 0.0369	RE PER HHG PTS= CM -U.1492 U.3061 U.7346	1N.= .45E0 2.9018 PSI CS -0.1004	6 T0= CY 0.7916 0.5883 0.5052	90. D	EG.F RUN NO. CAT 0.3187	POJ/P . 00503/ CPE 0.1547 0.1506 C.1490	TS = 69111 CAF 0.1640 0.1628 0.2593	RUN 174. 174. 174.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241	RE PER HHG PTS= CM -0.1492 0.3061 0.7346 0.9646	IN.= .48E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680	CY 0.7916 0.5883 0.5052 0.4805	90. D CR 0.0013 0.0012 0.0013 C.0014	EG.F RUN NO. CAT 0.3187 0.3134 0.3083	POJ/P . 005036 CPE 0.1547 0.1506 C.1490 0.1484	TS = 69111 CAF 0.1640 0.1628 0.1579	RUN 174. 174. 174. 174.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904	RE PER HHG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708	CY 0.7916 0.5883 0.5052 0.4805 0.4507	90. D CR 0.0013 0.0012 0.0013 C.0014 0.0020	CAT 0.3187 0.3134 0.3083 0.3063	POJ/P . 005030 CPE 0.1547 0.1506 C.1490 0.1484 0.1491	TS = 69111 CAF 0.1640 0.1628 0.1593 0.1579 0.1557	RUN 174. 174. 174. 174.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559	IN.= .48E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4542	90. D CR 0.0013 0.0012 6.0013 C.0014 0.0020 0.0024	CAT 0.3187 0.3134 0.3083 0.3063 0.3048	POJ/P . 00503 . CPE 0.1547 0.1506 0.1490 0.1484 0.1491 0.1500	TS = 69111 CAF 0.1640 0.1628 0.1593 0.1577 0.1557	RUN 174. 174. 174. 174. 174.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558 0.36 -0.1831	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559 1.5487	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647 -0.0647	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4542 0.4366	90. D CR 0.0013 0.0012 0.0013 C.0014 0.0020 0.0024 0.0025	CAT 0.3187 0.3134 0.3083 0.3063 0.3048 0.3047	POJ/P . 00503 . CPE 0.1547 0.1506 0.1490 0.1491 0.1500 0.1503	TS = 69111 CAF 0.1640 0.1628 0.1593 0.1577 0.1557 0.1547	RUN 174. 174. 174. 174. 174. 174.
Q= 8.13 PSI P9= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558 0.36 -0.1831 -0.16 -0.2124	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559 1.5487 1.7266	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647 -0.0647	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4542 0.4366 0.4388	90. D CR 0.0013 0.0012 0.0014 0.0020 0.0024 0.0025 0.0026	CAT 0.3187 0.3187 0.3083 0.3083 0.3063 0.3048 0.3047 0.3046	POJ/P . 00503 . CPE 0.1547 0.1506 0.1490 0.1491 0.1500 0.1503 0.1512	TS = 69111 CAF 0.1640 0.1628 0.1579 0.1577 0.1547 0.1543 0.1519	RUN 174. 174. 174. 174. 174. 174. 174.
Q= 8.13 PS1 PQ= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558 0.36 -0.1831 -0.16 -0.2124 -0.67 -0.2404	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559 1.5487 1.7266 1.8828	IN.= .45E0 2.9018 PSE CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647 -0.0626 -0.0624	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4542 0.4366 0.4388 0.4526 0.4349	90. D CR 0.0013 0.0012 0.0013 C.0014 0.0020 0.0024 0.0025 0.0026 0.0027	CAT 0.3187 0.3187 0.3083 0.3063 0.3064 0.3047 0.3046 0.3031 0.3030 0.3029	POJ/P . 00503 . CPE 0.1547 0.1506 0.1490 0.1494 0.1500 0.1503 0.1512 0.1524 0.1523	TS = 69111 CAF 0.1640 0.1628 0.1579 0.1557 0.1547 0.1543 0.1519 0.1506	RUN 174. 174. 174. 174. 174. 174. 174. 174.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558 0.36 -0.1831 -0.16 -0.2124 -0.67 -0.2404 -1.19 -0.2660 -1.71 -0.2933 -2.22 -0.3209	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559 1.5487 1.7266 1.8828 2.0534 2.2249	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647 -0.0626 -0.0624 -0.0637 -0.0614 -0.0629	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4546 0.4388 0.4526 0.4349 0.4521	90. Di CR 0.0013 0.0012 0.0013 C.0014 0.0020 0.0024 0.0025 0.0026 0.0027 0.0028 0.0029	CAT 0.3187 0.3184 0.3083 0.3063 0.3048 0.3047 0.3046 0.3031 0.3030 0.3029 0.3049	POJ/P . 00503 CPE 0.1547 0.1506 C.1490 0.1484 0.1491 0.1503 C.1512 0.1512 0.1523 0.1515	TS = 69111 CAF 0.1640 0.1628 0.2593 0.1579 0.1557 0.1547 0.1543 0.1510 0.1506 0.1534	RUN 174. 174. 174. 174. 174. 174. 174. 174.
Q= 8.13 PS1 PQ= 118.0 CM ALPHA CN 3.98 0.0369 2.96 -0.0278 1.93 -0.0904 1.40 -0.1241 0.88 -0.1558 0.36 -0.1831 -0.16 -0.2124 -0.67 -0.2404 -1.19 -0.2660 -1.71 -0.2933	RE PER HG PTS= CM -0.1492 0.3061 0.7346 0.9646 1.1848 1.3559 1.5487 1.7266 1.8828 2.0534 2.2249 2.5163	IN.= .45E0 2.9018 PSI CS -0.1004 -0.0794 -0.0708 -0.0680 -0.0647 -0.0626 -0.0624 -0.0637 -0.0614 -0.0629	CY 0.7916 0.5883 0.5052 0.4805 0.4507 0.4542 0.4388 0.4526 0.4389 0.4526 0.4349	90. D CR 0.0013 0.0012 0.0013 C.0014 0.0020 0.0024 0.0025 0.0027 0.0028 0.0029 0.0031	CAT 0.3187 0.3187 0.3083 0.3063 0.3064 0.3047 0.3046 0.3031 0.3030 0.3029	POJ/P . 00503 CPE 0.1547 0.1506 0.1490 0.1484 0.1491 0.1503 0.1512 0.1523 0.1515 0.1525	TS = 69111 CAF 0.1640 0.1628 0.1579 0.1557 0.1547 0.1543 0.1519 0.1506 0.1506 0.1534 0.1545	RUN 174. 174. 174. 174. 174. 174. 174. 174.

HO	DEL 946.2	CON	IG00	00 M	NCH 2.09	0	PHI =	30.	
Q=	8-13 PSI	RE PER	IN.= .48	=07 TO=	90. DI	EG.F	POJ/P	rs =	•
P04	4 118.0 CF	HG PTS=	2.9018 P	SI		RUN NO.	00503	59112	
ALPHA	CN	СМ	cs	CY	CR	CAT	CP8	CAF	KUN:
4.14	0.2073	-1.2301	-0.0099	0.0547-	-0.0002	0.2972	0.1512	0.1460	175.
3.12	0.1544	-0.9105	-0.0089			0.2933			
2.09	0.1035	-0.6144	-0.0074	0.0344-	-0.0009	0.2907	0.1469	0.1438	175.
1.56	0.0767	-0.4589	-0.0083	0.0426	0.0005	0.2906	0.1469	0.1437	175.
1.04	0.0513	-0.3075	-0.0051	0.0119	0.0002	0.2903	0.1474	0.1429	175.
0.53	0.0289	-0.1853	-0.0069	0.0301	0.0008	0.2921	0.1482	0.1439	
0.	0.0047	-0.0456				0.2905			
-0.51	-0.0161	0.0608	-0.0047			0.2908			
	-0.0435		-0.0072			0.2927			
-1.55	-0.0993	0.6884	0.0478	-0.5242					
	-0.0882		-0.0057			0.2941			
	-0.1391		-0.0043			0.2977			
-4.12	-0.1946	1.1118	-0.0030	0.0004	0.0041	0.3034	0.1525	0.1509	175.
	DEL 946.2	CONF			ACH 2.0		PHI =	30.	
	DEL 946.2 8.13 PSI		FIG00		ACH 2.08		PHI =		10.
Ç=		RE PER	IN.= .48	E06 T0=		EG.F		rs =	10.
Ç=	8.13 PSI = 118.0 CF	RE PER	IN.= .48	E06 T0=		EG.F	P0 J/ P	rs =	10. . RUN
Ç= P0:	8.13 PSI = 118.0 CF CN	RE PER HHG PTS=	IN.= .48	E06 T0= SI CY	90. DI	EG.F :UN NO	POJ/P	TS = 69113 CAF	RUN
G= PO: ALPHA	8.13 PSI = 118.0 CF CN	RE PER HHG PT.S= CH -1.1374	IN.= .48 2.9018 P	E06 TO= SI CY 0.1944-	90. DI CR -0.0003	EG.F :UN NO CAT	POJ/P 005030 CPB 0.1532	TS = 69113 CAF 0.1445	RUN 176.
Q= PO: ALPHA 4,13	8.13 PSI = 118.0 CN CN 0.1910 0.1403	RE PER HHG PTS= CH -1.1374 -0.8380	IN.= .48 2.9018 P CS -0.0275	E06 TO= SI CY 0.1944- 0.1577-	90. Di CR -0.0003	EG.F :UN NO CAT 0.2977	POJ/P · 005030 CPB 0.1532 0.1507	TS = 69113 CAF 0.1445 0.1430	RUN 176. 176.
G= PO: ALPHA 4.13 3.11	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873	RE PER HHG PTS= CH -1.1374 -0.8380 -0.5151	IN.= .48 2.9018 P CS -0.0275 -0.0237	E06 T0= SI CY 0.1944- 0.1577- 0.1223	90. DECR-0.0003-0.0004	EG.F :UN NO CAT 0.2977 0.2937	POJ/P . 005036 CPB 0.1532 0.1507 0.1486	TS = 69113 CAF 0.1445 0.1430 0.1439	RUN 176. 176. 176.
G= PO: ALPHA 4.13 3.11 2.07	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570	RE PER HHG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198	E06 T0= SI CY 0.1944- 0.1577- 0.1223 0.1126 0.1138	90. DE	CAT 0.2977 0.2937 0.2925 0.2923 0.2915	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1428	RUN 176. 176. 176. 176. 176.
G= PO: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570 0.0311 0.0012	RE PER HG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209	E06 T0= SI CY 0.1944- 0.1577- 0.1223 0.1126 0.1138 0.1382	90. DE	CAT 0.2977 0.2937 0.2925 0.2923 0.2915 0.2926	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1428	RUN 176. 176. 176. 176. 176.
G= P0: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 0.	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570 0.0311 0.0012 -0.0136	RE PER HG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209 -0.0158	E06 T0= SI CY 0.1944- 0.1577- 0.1223 0.1126 0.1138 0.1382 0.0897	90. DE	CAT 0.2977 0.2937 0.2937 0.2925 0.2923 0.2915 0.2926 0.2921	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499 0.1508	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1428 0.1427	RUN 176. 176. 176. 176. 176. 176. 176.
G= P0: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 00.52	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570 0.0311 0.0012 -0.0136 -0.0384	RE PER HG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795 0.2223	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209 -0.0158 -0.0148	CY 0.1944- 0.1577- 0.1223 0.1126 0.1382 0.0897 0.0828	90. Di CR -0.0003 -0.0004 0.0004 0.0006 0.0006 0.0009	CAT 0.2977 0.2937 0.2925 0.2925 0.2921 0.2921 0.2932	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499 0.1508 0.1511	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1421 0.1427	RUN 176. 176. 176. 176. 176. 176. 176. 176.
Q= P0: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 0. -0.52 -1.03	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570 0.0311 0.0012 -0.0136 -0.0384 -0.0638	RE PER THG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795 0.2223 0.3747	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209 -0.0158 -0.0148 -0.0154	CY 0.1944- 0.1577- 0.1223 0.1126 0.1382 0.0897 0.0828 0.0888	90. Di CR -0.0003 -0.0004 0.0004 0.0006 0.0006 0.0009 0.0017 0.0023	CAT 0.2977 0.2937 0.2925 0.2925 0.2921 0.2926 0.2932 0.2936	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499 0.1508 0.1511 0.1501	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1421 0.1423	RUN 176. 176. 176. 176. 176. 176. 176. 176.
Q= P0: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 0. -0.52 -1.03 -1.55	8.13 PSI = 118.0 CP	RE PER THG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795 0.2223 0.3747 0.5473	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209 -0.0158 -0.0148 -0.0154 -0.0198	CY 0.1944- 0.1577- 0.1223 0.1126 0.1138 0.1382 0.0897 0.0828 0.0888 0.1317	90. Di CR -0.0003 -0.0004 0.0007 0.0006 0.0006 0.0009 0.0017 0.0023 0.0023	CAT 0.2977 0.2937 0.2925 0.2925 0.2926 0.2921 0.2932 0.2936 0.2962	POJ/P . 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1489 0.1508 0.1511 0.1501 0.1496	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1421 0.1423 0.1466	RUN 176. 176. 176. 176. 176. 176. 176. 176.
G= PO: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 0. -0.52 -1.03 -1.55 -2.06	8.13 PSI = 118.0 CM CN 0.1910 0.1403 0.0873 0.0570 0.0311 0.0012 -0.0136 -0.0384 -0.0638 -0.0916 -0.1086	RE PER 4HG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795 0.2223 0.3747 0.5473 0.6206	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0166 -0.0209 -0.0158 -0.0148 -0.0154 -0.0198 -0.0163	CY 0.1944- 0.1577- 0.1223 0.1126 0.1382 0.0897 0.0828 0.0888 0.1317 0.1035	90. Di CR -0.0003 -0.0004 0.0006 0.0006 0.0009 0.0017 0.0023 0.0023	CAT 0.2977 0.2937 0.2925 0.2925 0.2921 0.2921 0.2932 0.2936 0.2962 0.2964	POJ/P 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499 0.1508 0.1511 0.1496 0.1495	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1428 0.1427 0.1413 0.1425 0.1466	RUN 176. 176. 176. 176. 176. 176. 176. 176
G= P0: ALPHA 4.13 3.11 2.07 1.55 1.02 0.51 0. -0.52 -1.03 -1.55 -2.06 -3.10	8.13 PSI = 118.0 CP	RE PER 4HG PTS= CH -1.1374 -0.8380 -0.5151 -0.3237 -0.1710 0.0264 0.0795 0.2223 0.3747 0.5473 0.6206 0.9161	IN.= .48 2.9018 P CS -0.0275 -0.0237 -0.0198 -0.0190 -0.0186 -0.0209 -0.0158 -0.0148 -0.0154 -0.0198	CY 0.1944- 0.1577- 0.1223 0.1126 0.1382 0.0897 0.0828 0.0888 0.1317 0.1035 0.0837	90. Di CR -0.0003 -0.0004 0.0006 0.0006 0.0009 0.0017 0.0023 0.0023 0.0029 0.0031	CAT 0.2977 0.2937 0.2925 0.2925 0.2926 0.2921 0.2932 0.2936 0.2962	POJ/P 005030 CPB 0.1532 0.1507 0.1486 0.1483 0.1486 0.1499 0.1508 0.1511 0.1496 0.1495 0.1498	TS = 69113 CAF 0.1445 0.1439 0.1441 0.1428 0.1427 0.1413 0.1421 0.1426 0.1466	RUN 176. 176. 176. 176. 176. 176. 176. 176

MODEL 946.2	CONF	160000	MA	CH 2.00	PHI =	39.	
Q= 8.13 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	2Tq\LOq	× 20.	
PO= 118.0 C	MHG PTS=	2.9018 PSI		RUN NO	. 0050369	114	
ALPHA CN	Сh	CS	CY	CR CAT	CPB	CAF	RUN
4.12 0.1778	-1.0702	-0.0477	0.3526-	0.0003 U.3037	0.1545 0	.1493	177.
3.10 0.1226	-0.7229	-0.0390	0.2708-	0.0004 0.2989	0.1523 0	-1466	177.
2.07 0.0696	-0.4016			0.0005 0.2977			177.
1.54 0.0400	-0.2156			0.0012 0.2954			177.
1.02 0.0141	-0.0559			0.0012 0.2951			177.
0.50 -0.0088		-0.0294		0.0008 0.2955			177.
-0.02 -0.0328		-0.0271		0.0005 0.2945			177.
-0.54 -0.0585		-0.0261		0.0007 0.2970			177.
-1.05 -0.0852		-0.0258		0.0013 0.2954			1776
-1.57 -0.1089		-0.0266		0.0021 0.2965			177.
-2.09 -0.1347		-0.0265		0.G021 0.2959 0.0026 0.2998			177. 177.
-3.11 -0.1831 -4.14 -0.2353		-0.0279 -0.0281		0.0034 0.3068			į77.
-4.14 -0.2333	1 34043	-0.0281	0.1330	0.0034 0.3000	U-1352 U	1-1310	111.
MODEL 946.2 Q= 8.13 PSI		:1G0000 1N.= .48E0		CH 2.00 90. DEG.F	PHI = POJ/PTS	30 . 5 = 40.	
- · · · · · · · · · · · · · · · · · · ·	RE PER	IN.= .48E0	6 TO=	90. DEG.F		= 40.	
Q= 8.13 PS1	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS . 0050369	= 40.	RUN
Q= R.13 PS1 PO= 118.0 C ALPHA CN	RE PER MHG PTS= CM	IN.= .48E0 2.9018 PST CS	6 TO=	90. DEG.F RUN NO. CR CAT	P03/PTS • 0050369 CPB	= 40. 2115 CAF	RUN 178.
Q= A.13 PS1 PO= 118.0 C	RE PER	IN.= .48E0 2.9018 PSI CS -0.0853	6 TO= CY 0.6460 (90. DEG.F	POJ/PTS - 0050369 - CPB - 0.1558 0	= 40. P115 CAF -1503	
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481	RE PER MHG PTS= CM -0.9030	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734	6 TO= CY 0.6460 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062	POJ/PTS - 0050369 - CPB - 0.1558 0 - 0.1537 0	= 40. PLIS CAF (-1503	178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734	CY 0.6460 (0.5336 (0.4224 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 0.0003 0.3036	POJ/PTS - 0050369 CPB 0.1558 0 0.1537 0 0.1511 0	= 40. P115 CAF (.1503 (.1497	178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616	CY 0.6460 (0.5336 (0.4224 (0.3792 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0	= 40. 2115 CAF (-1503) 1-1497 1-1495	178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567	CY 0.6460 (0.5336 (0.4224 (0.3792 (0.3834 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006 0.0020 0.3011	POJ/PTS . 0050369 CP8 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1509 0	= 40. 2115 CAF 3.1503 3.1497 3.1495 3.1504 3.1472	178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566	CY 0.6460 (0.5336 (0.4224 (0.3792 (0.3834 (0.4016 (0.3937 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006 0.0020 0.3011 0.0002 0.2981 0.0013 0.2986 0.0010 0.2983	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1511 0 0.1514 0	2115 CAF (.1503 (.1497 (.1495 (.1504 (.1472 (.1475 (.1469)	178. 178. 178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297 0.45 -0.0640	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990 0.6165	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566 -0.0578	CY 0.6460 (0.5336 (0.4224 (0.3792 (0.3834 (0.4016 (0.3937 (0.4067 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006 0.0020 0.3011 0.0002 0.2981 0.0013 0.2986 0.0010 0.2983 0.0015 0.2995	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1512 0 0.1514 0 0.1514 0	2115 CAF (.1503 (.1497 (.1495 (.1504 (.1472 (.1475 (.1469 (.1472	178. 178. 178. 178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297 0.45 -0.0640 -0.04 -0.0858 -0.56 -0.1139 -1.07 -0.1369	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990 0.6165 0.7922	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566 -0.0578 -0.0567	CY 0.6460 (0.5336 (0.4224 (0.3834 (0.3837 (0.4016 (0.3937 (0.4067 (0.4045 (90. DEG.F RUN NO CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006 0.0020 0.3011 0.0002 0.2981 0.0013 0.2986 0.0010 0.2983 0.0015 0.2995	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1514 0 0.1514 0 0.1522 0	= 40. CAF (.1503) (.1497) (.1495) (.1504) (.1472) (.1475) (.1469) (.1472) (.1524)	178. 178. 178. 178. 178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297 0.45 -0.0640 -0.04 -0.0858 -0.56 -0.1139	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990 0.6165 0.7922 0.9191 1.1358	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566 -0.0578 -0.0567 -0.0579 -0.0579 -0.0579	CY 0.6460 (0.5336 (0.4224 (0.3792 (0.3834 (0.4016 (0.3937 (0.4067 (0.4045 (0.40324 (90. DEG.F RUN NO CR CAT 0.0002 0.3062 9.0003 0.3036 0.0020 0.3011 0.0002 0.2981 0.0013 0.2988 0.0013 0.2988 0.0015 0.2995 0.0015 0.3046 0.0015 0.2990	POJ/PTS - 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1514 0 0.1514 0 0.1522 0 0.1522 0 0.1521 0	CAF (.1503 (.1497 (.1495 (.1472 (.1475 (.1469 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472 (.1472	178. 178. 178. 178. 178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297 0.45 -0.0640 -0.04 -0.0858 -0.56 -0.1139 -1.07 -0.1369	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990 0.6165 0.7922 0.9191 1.1358 1.2002	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566 -0.0579 -0.0579 -0.0579 -0.0598 -0.0561	CY 0.6460 (0.5336 (0.4224 (0.3792 (0.3834 (0.4016 (0.3937 (0.4045 (0.4324 (0.3983 (0.43983 (90. DEG.F RUN NO. CR CAT 0.0002 0.3062 9.0003 0.3036 0.0007 0.3006 0.0020 0.3011 0.0002 0.2981 0.0013 0.2983 0.0015 0.2983 0.0015 0.2995 0.0015 0.3046 0.0015 0.2990 0.0023 0.3006	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1512 0 0.1512 0 0.1522 0 0.1522 0 0.1521 0 0.1521 0	CAF (.1503 .1497 .1495 .1495 .1475 .1475 .1469 .1472 .1475 .1469	178. 178. 178. 178. 178. 178. 178. 178.
Q= R.13 PS1 PO= 118.0 C ALPHA CN 4.10 0.1481 3.08 0.0849 2.04 0.0286 1.52 -0.0047 1.00 -0.0297 0.45 -0.0640 -0.04 -0.0858 -0.56 -0.1139 -1.07 -0.1369 -1.58 -0.1689	RE PER MHG PTS= CM -0.9030 -0.4745 -0.1156 0.1080 0.2565 0.4990 0.6165 0.7922 0.9191 1.1358 1.2002 1.4798	IN.= .48E0 2.9018 PSI CS -0.0853 -0.0734 -0.0616 -0.0567 -0.0566 -0.0578 -0.0567 -0.0579 -0.0579 -0.0579	CY 0.6460 0.5336 0.4224 0.3792 0.3834 0.4016 0.3937 0.4065 0.4324 0.3983 0.4266	90. DEG.F RUN NO CR CAT 0.0002 0.3062 9.0003 0.3036 0.0020 0.3011 0.0002 0.2981 0.0013 0.2988 0.0013 0.2988 0.0015 0.2995 0.0015 0.3046 0.0015 0.2990	POJ/PTS . 0050369 CPB 0.1558 0 0.1537 0 0.1511 0 0.1507 0 0.1512 0 0.1512 0 0.1522 0 0.1521 0 0.1521 0 0.1521 0 0.1521 0 0.1521 0	CAF (-1503 -1497 -1495 -1495 -1475 -1469 -1472 -1469 -1472 -1469 -1487 -1520	178. 178. 178. 178. 178. 178. 178. 178.

MODEL 946.2	CONFIG0000	MACH 2.00	PHI = 30.
Q= 8.13 PSI	RE PER IN.= .48E0	5 TO= 90. DEG.F	POJ/PTS = 80.
P0= 118.0 CMHG	PTS= 2.9018 PSI	RUN NO	. 0050369116
ALPHA CN	CM CS	CY CR CAT	CPB CAF RUN
	0.4331 -0.1618	1.2497 0.0018 0.3127	
	0.1081 -0.1324	0.9644 0.0013 0.3103	
	0.5590 ~0.1259	0.9104 0.0025 0.3090	
	0.8274 -0.1200	0.8551 0.0015 0.3061	· · · - · · · - · · · · · · · · · ·
•	1.0672 -0.1196	0.8569 0.0017 0.3044	
· · · · · · · · · · · · · · · · · · ·	1.2888 -0.1197	0.8673 0.0022 0.3043	
	1.3961 -0.1148	0.6221 0.0021 0.3039	
	1.6202 -0.1177	0.8607 0.0018 0.3037	
	1.7750 -0.1164	0.8514 0.GO17 D.3034	
	1.9020 -0.1128	0.8195 0.0034 0.3039	
	2.0310 -0.1149	0.8490 0.0025 0.3049	
	2.3536 -0.1142	0.8467 0.0036 0.3065	
-4.21 -0.4027	2.6771 -0.1115	0.8252 0.0047 0.3122	0.1553 0.1569 179.
MODEL 946.2	CONFIG0000	MACH 2.00	PHI = 45.
Q= 8.13 PSI	KE PEK 1N.= .40EU	10= 90. DEG.F	POJ/PTS = .
PO= 118.0 CMHG	PTS= 2.9018 PS1	RUN NO.	. 0050369117
ALPHA CŇ	CM CS	CY CR CAT	ĆPB CAF RUN
4.07 0.2003 -	1.1739 -0.0106	0.0421 0.0001 0.2923	0.1518 0.1405 180.
	0.8405 -0.0103	0.0480 0.0006 0.2900	
2.02 0.0976 -	0.5702 -0.0089	0.0374 C.0008 Q.2884	0.1479 0.1405 180.
1.48 0.0715 -	0.4194 -0.0095	0.0411 0.0018 0.2874	
0.96 0.0404 -	0.2130 -0.0136	0.0871 0.0005 0.2891	
	0.1025 -0.0135	0.0874-6.0003 0.2893	
	0.0147 -0.0076	0.0382 0.0010 0.2893	
	0.1311 -0.0055	0.0142 0.0009 0.2916	
	0.3014 -0.0061	0.0256 0.0018 0.2924	
	0.4146 -0.0083	0.0465 0.0026 0.2933	
	0.5547 -0.0041	0.0119 0.0030 0.2948	
-3.17 -0.1472	C.8385 -0.0016 -	0.0081 0.0029 0.2979	0.1496 0.1483 180.
-4.19 -0.2008	1.1581 0.0004 -	0.0233 0.0046 0.3038	0.1522 0.1516 180.

กบเ	DEL 946.2	CON	fig0000	M	ACH 2.00	5HI =	45.	
0 =	8.13 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	P0J/P	TS = 1	.0.
P0:	= 118.0 CM	HG PTS=	2.9018 PSI		RUN NI	0. 00503	69118	
ALPHA	CN	СН	cs	CY	CR CAT	СРВ	CAF	RUN
4.06	0.1936	-1.1612	-0.0362	0.2430	0.0001 0.293	0.1574	0.1362	181.
3.04			-0.0295		0.0002 0.2913			181.
2.01	0.0834	-0.4814	-0.0253	0.1506	0.0001 0.288	0.1497	0.1384	181.
	0.0548	-0.3077	-0.0207	0.1098	0.0005 0.289	7 0.1483	0.1414	181.
	0.0257	-0.1210	-0.0249	0.1563	-0.0003 0.2914	0.1483	0.1431	181.
0.44	0.0014	0.0250	-0.0234	0.1453	-0.0005 0.2908	0.1492	0.1416	181.
-0.07	-0.0193	0.1316	-0.0228	0.1425	0.0005 0.2930	0.1496	0.1434	181.
-0.60	~0.0494	0.3263	-0.0259	0.1801	0.0009 0.292	7 0.1499	0.1428	181.
-1.11	-0.0658	0.3853	~0.0154	0.0787	0.0022 0.2939	0.1495	0-1444	181.
-1.62	-0.0913		-0.0175		0.0024 0.296			181.
-2.14	-0.1138	0.6609	-0.0141		0.0028 0.2943			181.
	-0-1664		-0.0158		0.0033 0.3009			16%.
-4.20	-0.2192	1.2884	-0.0146	0.0908	0.0041 0.306	2 0-1540	0.1522	181.
MOI	DEL 946.2	CON	FIG0000	H	ACH 2.00	PHI =	45.	
					AGH 2.00 90. DEG.F			20•
Q=	8.13 PS:	RE PER		6 TO=	90. DEG.F		rs = 2	20•
Q=	8.13 PS:	RE PER	IN.= .48E0	6 TO=	90. DEG.F RUN NO	POJ/P1	rs = 2	20 • RUN
Q= PO: Alpha	8.13 PS: = 118.0 CM CN	RE PER HG PYS=	IN.= .48E0 2.9018 PSI CS	6 TO=	90. DEG.F RUN NO CR CAT	POJ/P1	TS = 2 69119 CAF	RUN
Q= PO: ALPHA 4.06	8.13 PS: = 118.0 CM CN 9.17.91	RE PER HG PYS= CM ~1.0652	IN.= .48E00 2.9018 PSI CS -0.0644	6 TO= CY 0.4715	90. DEG.F RUN NO CR CAT 0.0006 0.2993	POJ/P1 3- 005036 CP8	TS = 2 69119 CAF 0-1426	RUN 182•
Q= PO: ALPHA 4.06 3.03	8.13 PS: = 118.0 CM CN 0.17.91 0.1221	RE PER HG PYS= CM =1.0652 =0.7047	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544	6 TO= CY 0.4715 0.3787-	90. DEG.F RUN NO CR CAT 0.0006 0.2993	POJ/P1 0- 005036 CP8 1- 0-1564 2- 0-1535	TS = 2 69119 CAF 0-1426 0-1437	RUN 182. 182.
Q= PO: ALPHA 4.06 3.03 2.00	8.13 PS: = 118.0 CM CM 9.1791 0.1221 0.0685	RE PER HG PYS= CM =1.0652 -0.7047 -0.3805	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440	CY 0.4715 0.3787- 0.2841	90. DEG.F RUN NO CR CAT 0.0006 0.2993 -0.0002 0.2973 0.0003 0.2940	POJ/PI 0- 005036 CPB 1 0-1564 2 0-1535 0 0-1509	TS = 2 69119 CAF 0.1426 0.1437 0.1431	RUN 182. 182. 182.
Q= PO: ALPHA 4.06 3.03 2.00 1.47	8.13 PS: = 118.0 CM CN 9.17.91 0.1221 0.0685 0.0425	RE PER HG PYS= CM =1.0652 -0.7047 -0.3805 -0.2288	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409	CY 0.4715 0.3787- 0.2841 0.2562	90. DEG.F RUN NO CR SAT 0.0006 0.299; -0.0002 0.297; 0.0003 0.294(0.0004 0.292)	POJ/PI 0. 005036 CPB 1 0.1564 2 0.1535 0.1509 3 0.1499	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429	RUN 182. 182.
Q= PO= ALPHA 4.06 3.03 2.00 1.47 0.95	8.13 PS: = 118.0 CM CN 0.1751 0.1221 0.0685 0.0425 0.0171	RE PER HG PYS= CM -1.0652 -0.7047 -0.3805 -0.2288 -0.0772	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384	CY 0.4715 0.3787- 0.2841 0.2562 0.2405-	90. DEG.F RUN NO CR CAT 0.0006 0.2993 -0.0002 0.2973 0.0003 0.2940	POJ/PI 0- 005036 CPB 1 0-1564 2 0-1535 0-1509 3 0-1499 0-1500	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429 0.1450	RUN 182. 182. 182.
Q= PO= ALPHA 4.06 3.03 2.00 1.47 0.95 0,43	8.13 PS: = 118.0 CM CN 0.17.71 0.1221 0.0685 0.0425 0.0171 -0.0109	RE PER HG PYS= CM \$1.0652 \$0.7047 -0.3805 -0.2288 -0.0772 0.0990	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384 -0.0389	CY 0.4715 0.3787- 0.2841 0.2562 0.2405- 0.2489	90. DEG.F RUN NO CR CAT 0.0006 0.2997 0.0002 0.2977 0.0003 0.2940 0.0004 0.2920 0.0001 0.2950 0.0009 0.2939	POJ/PI 0- 005036 CPB 1 0-1564 2 0-1535 0 0-1509 3 0-1499 0 0-1500 0 0-1504	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429 0.1450 0.1434	RUN 182. 182. 182. 182. 182.
Q= PO= ALPHA 4.06 3.03 2.00 1.47 0.95 0.43 -0.09	8.13 PS: = 118.0 CM CN 0.17.91 0.12.21 0.0685 0.0425 0.0171 -0.0109 -0.0339	RE PER HG PYS= CM -1.0652 -0.7047 -0.3805 -0.2288 -0.0772 0.0990 0.2259	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384 -0.0389 -0.0350	CY 0.4715 0.3787- 0.2841 0.2562 0.2405- 0.2489 0.2175	90. DEG.F RUN NO CR EAT 0.0006 0.2997 0.0002 0.2977 0.0003 0.2940 0.0004 0.2920 -0.0001 0.2950	POJ/Pi 0- 005036 CPB 1 0-1564 2 0-1535 0 0-1509 3 0-1499 0 0-1504 0 0-1499	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429 0.1450 0.1434	RUN 182. 182. 182. 182. 182.
Q= PO: ALPHA 4.06 3.03 2.00 1.47 0.95 0.43 -0.09 -0.60	8.13 PS: = 118.0 CM CN 0.17.91 0.1221 0.0685 0.0425 0.0171 -0.0109 -0.0339 -0.0599	RE PER HG PYS= CM -1.0652 -0.7047 -0.3805 -0.2288 -0.0772 0.0990 0.2259 0.3828	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384 -0.0389	CY 0.4715 0.3787- 0.2841 0.2562 0.2405- 0.2489 0.2175 0.2270	90. DEG.F RUN NO CR CAT 0.0006 0.2993 -0.0002 0.2940 0.0004 0.2920 0.0004 0.2930 0.0009 0.2930 0.0007 0.2940 0.0005 0.2955	POJ/PI 0-005036 CPB 0-1564 2-0-1535 0-1509 0-1500 0-1500 0-1504 0-1499 0-1502	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429 0.1450 0.1434 0.1441	RUN 182. 182. 182. 182. 182.
Q= P0: ALPHA 4.06 3.03 2.00 1.47 0.95 0.43 -0.09 -0.60 -1.12	8.13 PS: = 118.0 CM CN 0.17.91 0.12.21 0.0685 0.0425 0.0171 -0.0109 -0.0339	RE PER HG PYS= CM -1.0652 -0.7047 -0.3805 -0.2288 -0.0772 0.0990 0.2259 0.3828 0.5301	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384 -0.0389 -0.0350 -0.0357	CY 0.4715 0.3787- 0.2841 0.2562 0.2405- 0.2489 0.2175 0.2270 0.2340	90. DEG.F RUN NO CR CAT 0.0006 0.2991 0.0003 0.2940 0.0004 0.2920 0.0001 0.2950 0.0009 0.2939 0.0007 0.2940	POJ/Pi CPB CPB 0.1564 2 0.1535 0 0.1509 3 0.1499 0 0.1500 0 0.1504 0 0.1499 5 0.1497	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1429 0.1450 0.1434 0.1454 0.1454	RUN 182. 182. 182. 182. 182. 182.
Q= P0: ALPHA 4.06 3.03 2.00 1.47 0.95 0.43 -0.09 -0.60 -1.12 -1.63	8.13 PS: = 118.0 CM CN 0.1791 0.1221 0.0685 0.0425 0.0171 -0.0109 -0.0339 -0.0599 -0.0853 -0.1082	RE PER HG PYS= CM -1.0652 -0.7047 -0.3805 -0.2288 -0.0990 0.2259 0.3828 0.5301 0.6557	IN.= .48E00 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0389 -0.0389 -0.0357 -0.0360	CY 0.4715 0.3787- 0.2841 0.2562 0.2495- 0.2489 0.2175 0.2270 0.2340 0.2283	90. DEG.F RUN NO CR CAT 0.0006 0.2993 -0.0002 0.2940 0.0004 0.2926 0.0009 0.2930 0.0007 0.2940 0.0005 0.2955 0.0012 0.2965	POJ/Pi CPB 0.1564 2 0.1535 0.1509 3 0.1509 0.1500 0.1504 0.1499 0.1502 5 0.1497 0.1501	TS = 2 59119 CAF 0.1426 0.1437 0.1431 0.1450 0.1434 0.1444 0.1454 0.1468 0.1472	RUN 182. 182. 182. 182. 182. 182. 182.
Q= PO: ALPHA 4.06 3.03 2.00 1.47 0.95 0.43 -0.09 -0.60 -1.12 -1.63 -2.15	8.13 PS: = 118.0 CM CN 0.17.91 0.12.21 0.0685 0.0425 0.0171 -0.0109 -0.0339 -0.0599 -0.0853	RE PER HG PYS= CM =1.0652 =0.7047 -0.3805 -0.2288 -0.0772 0.0990 0.2259 0.3828 0.5301 0.6557 0.8300	IN.= .48E06 2.9018 PSI CS -0.0644 -0.0544 -0.0440 -0.0409 -0.0384 -0.0389 -0.0357 -0.0360 -0.0350	CY 0.4715 0.3787- 0.2841 0.2562 0.2405- 0.2489 0.2175 0.2270 0.2340 0.2283 0.2334	90. DEG.F RUN NO CR CAT 0.0006 0.2997 0.0003 0.2940 0.0004 0.2920 0.0009 0.2930 0.0007 0.2940 0.0005 0.2950 0.0012 0.2950 0.0012 0.2950	POJ/Pi CP8 CP8 0.1564 2 0.1535 0.1509 3 0.1499 0.1500 0.1504 0.1502 5 0.1497 3 0.1501 0.1493	TS = 2 69119 CAF 0.1426 0.1437 0.1431 0.1450 0.1434 0.1454 0.1454 0.1454 0.1472	RUN 182. 182. 182. 182. 182. 182. 182. 182.

HO	DEL 946.2	CON	FIG0000	M	ACH 2.00	PHI =	45.	
Q=	8.13 PSI	RE PER	.IN.= .48E0	6 TO=	90. DEG.F	POJ/P	TS = 4	40 -
P0:	= 118.0 CM	HG PTS=	2.9018 PSI		RUN	NO. 00503	69120	
ALPHA	CN	CM	cs	CY	CR CAT	CPB	CAF	ŔUN
4.04	0.1603	-0.9791	-0.1084	0.8058	0.0011 0.30	55 0.1531	0.1524	183.
3.01	0.0958	-0.5418	-0.0967	0.6929	0.0012 0.39	09 0.1520	0.1489	183.
1.98	0.0375	-0.1672	-0.0845	0.5830	0.0018 0.29	97 0.1506	0.1491	183.
1.45			-0.0828		0.0016 0.29			183.
	-0.0217		-0.0806		0.0008 0.29			183.
	-0.0481		-0.0781		0.0006 0.29			183.
	-0.0751		-0.0796		0.0004 0.29			183.
	-0.1022		-0.0792		0.0017 0.30			183.
	-0.1244		-0.0770		0.0024 0.30			183.
	-0.1496		-0.0793		0.0028 0.30			183.
	-0.1787		-0.0788		0.0034 0.30			183.
			-0.07?7		0.0034 0.30			183.
-4.23	-0.2789	1.7284	-0.0787	0.5808	0.0045 0.30	98 0.1549	0.1549	183.
MOI	DEL 946•2	CONI	FIG0000	н	ACH 2.00	РНІ =	45.	
	DEL 946.2 8.13 PSI		FIG0000 IN.= .48E0		ACH 2.00 90. DEG.F	PHI =		B 0•
Q=	8.13 PSI	RE PER		6 TO=	90. DEG.F		TS = 8	BO•
Q=	8.13 PSI = 118.0 CM	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/P NO. 00503	TS = 8	BO• RUN
Q= PO: Alpha	8.13 PSI = 118.0 CM	RE PER HG PTS=	IN.= .48E0 2.9018 PSI CS	6 T0=	90. DEG.F	P0J/P NO. 00503 CPB	TS = 8 69121 CAF	RUN
Q= P0: ALPHA 4.00	8.13 PSI = 118.0 CM CN	RE PER HG PTS= CM -0.6612	IN.= .48E0 2.9018 PSI	6 TO= CY 1.4888	90. DEG.F RUN CR CAT	POJ/P NO. 00503 CPB 19 0.1521	TS = 8 69121 CAF 0.1598	
Q= P0: ALPHA 4.00 2.98	8.13 PSI = 118.0 CM CN 0.1060	RE PER HG PTS= CM -0.6612 -0.1350	IN.= .48E0 2.9018 PSI CS -0:1989	6 TO= CY 1.4888 1.2904	90. DEG.F RUN CR CAT 0.0023 0.31	POJ/P NO. DO503 CPB 19 0.1521 64 0.1493	TS = 6 69121 CAF 0.1598 0.1571	RUN 184.
Q= P0: ALPHA 4.00 2.98 1.94	8.13 PSI = 118.0 CM CN 0.1060 0.0331	RE PER HG PTS= CM -0.6612 -0.1350 0.3977	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780	6 TO= CY 1.4888 1.2904 1.2266	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30	POJ/P NO. DO503 CPB 19 0.1521 64 0.1493 46 0.1469	TS = { 69121 CAF 0.1598 0.1571 0.1577	RUN 184. 184.
Q= PO: ALPHA 4.00 2.98 1.94 1.41	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780 -0.1704	CY 1.4888 1.2904 1.2266 1.2411	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30	POJ/P NO. DO503 CPB 19 0.1521 64 0.1493 46 0.1469 36 0.1466	TS = { 69121 CAF 0.1598 0.1571 0.1577 0.1570	RUN 184. 184. 184.
Q= P0: ALPHA 4.00 2.98 1.94 1.41 0.90	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780 -0.1704 -0.1715	CY 1.4888 1.2904 1.2266 1.2411 1.2351	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0029 0.30	POJ/P NO. 00503 CPB 19 0.1521 64 0.1493 46 0.1469 36 0.1466 31 0.1494	TS = { 69121 CAF 0.1598 0.1571 0.1577 0.1570 0.1538	RUN 184. 184. 184.
Q= PO: ALPHA 4.00 2.98 1.94 1.41 0.90 0.38	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1096	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780 -0.1704 -0.1715 -0.2699 -0.1645 -0.1638	CY 1.4888 1.2904 1.2266 1.2411 1.2351 1.1872 1.1884	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0025 0.30 0.0025 0.30 0.0026 0.30 0.0026 0.30 0.0027 0.30	POJ/P NO. 00503 CPB 19 9.1521 64 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1492	TS = { 69121 CAF 0.1598 0.1571 0.1577 0.1577 0.1578 0.1538 0.1535	RUN 184. 184. 184. 184.
Q= PO: ALPHA 4.00 2.98 1.94 1.41 0.90 0.38 -0.15	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1096 -0.1341	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967 1.3259	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780 -0.1704 -0.1715 -0.1699 -0.1645 -0.1638 -0.1594	CY 1.4888 1.2904 1.2266 1.2411 1.12351 1.1872 1.1884 1.1516	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0025 0.30 0.0026 0.30 0.0026 0.30 0.0027 0.30 0.0027 0.30	POJ/P NO. 00503 CPB 19 9.1521 64 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1492 28 0.1497	TS = { 69121 CAF 0.1598 0.1571 0.1577 0.1577 0.1578 0.1538 0.1538 0.1538	RUN 184. 184. 184. 184.
Q= P0: ALPHA 4.00 2.98 1.94 1.41 0.38 -0.15 -0.66 -1.18	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1096 -0.1341 -0.1624 -0.1860 -0.2156	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967 1.3259 1.5150	IN.= .48E0 2.9018 PSI CS -0:1989 -0:1780 -0:1704 -0:1715 -0:2699 -0:1645 -0:1638 -0:1594 -0:1630	CY 1.4888 1.2904 1.2266 1.2411 1.2351 1.1872 1.1884 1.1516 1.1926	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0025 0.30 0.0020 0.30 0.0026 0.30 0.0026 0.30 0.0027 0.30 0.0019 0.30 0.0020 0.30	POJ/P NO. 00503 CPB 19 9.1521 64 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1497 52 0.1497	TS = { 69121 CAF 0.1598 0.1571 0.1577 0.1570 0.1538 0.1538 0.1535 0.1528 0.1531	RUN 184. 184. 184. 184. 184. 184. 184.
Q= P0: ALPHA 4.00 2.98 1.94 1.41 0.90 0.38 -0.15 -0.66 -1.18 -1.69	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1341 -0.1624 -0.1860 -0.2156 -0.2416	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967 1.3259 1.5150 1.6672	IN.= .48E0 2.9018 PSI CS -0.1989 -0.1780 -0.1704 -0.1715 -0.1699 -0.1645 -0.1638 -0.1594 -0.1630 -0.1636	CY 1.4888 1.2904 1.2266 1.2411 1.2351 1.1872 1.1884 1.1516 1.1926	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0025 0.30 0.0020 0.30 0.0027 0.30 0.0019 0.30 0.0020 0.30 0.0020 0.30	POJ/P NO. DO503 CPB 19 0.1521 64 0.1493 46 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1492 28 0.1497 52 0.1497 34 0.1505	TS = 6 69121 CAF 0.1598 0.1571 0.1577 0.1570 0.1538 0.1538 0.1535 0.1535 0.1528	RUN 184. 184. 184. 184. 184. 184. 184.
Q= P0: ALPHA 4.00 2.98 1.94 1.41 0.90 0.38 -0.15 -0.66 -1.18 -1.69 -2.20	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1341 -0.1624 -0.1860 -0.2156 -0.2416 -0.2669	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967 1.3259 1.5150 1.6672 1.8196	IN.= .48E0 2.9018 PSI CS -0:1989 -0.1780 -0.1704 -0.1715 -0.2699 -0.1645 -0.1638 -0.1630 -0.1630 -0.1636	CY 1.4888 1.2904 1.2266 1.2411 1.2351 1.1872 1.1884 1.1516 1.1926 1.2062 1.2117	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0025 0.30 0.0020 0.30 0.0027 0.30 0.0027 0.30 0.0020 0.30 0.0020 0.30 0.0020 0.30	POJ/P NO. DO503 CPB 19 9.1521 64 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1492 28 0.1497 52 0.1497 34 0.1505 77 0.1512	TS = 6 69121 CAF 0.1598 0.1571 0.1577 0.1570 0.1538 0.1535 0.1528 0.1535 0.1528	RUN 184. 184. 184. 184. 184. 184. 184. 184.
Q= P0: ALPHA 4.00 2.98 1.94 1.41 0.90 0.38 -0.15 -0.66 -1.18 -1.69 -2.20 -3.24	8.13 PSI = 118.0 CM CN 0.1060 0.0331 -0.0404 -0.0766 -0.1341 -0.1624 -0.1860 -0.2156 -0.2416	RE PER HG PTS= CM -0.6612 -0.1350 0.3977 0.6511 0.8750 1.0203 1.1967 1.3259 1.5259 1.6672 1.8196 2.1510	IN.= .48E0 2.9018 PSI CS -0.1989 -0.1780 -0.1704 -0.1715 -0.1699 -0.1645 -0.1638 -0.1594 -0.1630 -0.1636	CY 1.4888 1.2904 1.2266 1.2411 1.2351 1.1872 1.1884 1.1516 1.1926 1.2062 1.2117 1.2408	90. DEG.F RUN CR CAT 0.0023 0.31 0.0025 0.30 0.0028 0.30 0.0025 0.30 0.0020 0.30 0.0027 0.30 0.0019 0.30 0.0020 0.30 0.0020 0.30	POJ/P NO. DO503 CPB 19 0.1521 64 0.1469 36 0.1466 31 0.1494 32 0.1497 20 0.1492 28 0.1497 34 0.1505 77 0.1512 83 0.1511	TS = 6 69121 CAF 0.1598 0.1571 0.1577 0.1570 0.1538 0.1535 0.1528 0.1555 0.1528 0.1565 0.1572	RUN 184. 184. 184. 184. 184. 184. 184.

MODEL 946.2	CONFIG.	.0000 M	ACH 2.00	PHI = 60.	
Q= 8.13 PSI	RE PER IN.=	.48E96 TO=	90. DEG.F	POJ/PTS =	•
PG= 118.0 CF	HG PTS= 2.90	18 PSI	RUN ÑO	. 0050369122	
ALPHA CN	CM C	S CY	CR CAT	CPB CAF	RUN
4.09 0.2011	-1.1755 -0.0	133 0.0763	0.0014 0.2947	0.1510 0.1437	185.
3.07 0.1483	-0.8624 -0.0		0.0013 0.2897		
2.04 0.0594	-0.5827 -0.0		0.0013 0.2902		
1.50 0.0695	-0.3953 -0.0		0.0007 0.2910		
0.99 0.0441	-0.2443 -0.0		0.0001 0.2910		
0.47 0.0195	-0.1908 -0.0	,	0.0010 0.2944		
-0.05 0.0028	-0.0364 -0.0		0.0016 0.2926		
-0.56 -0.0295	0.1843 -0.0		0.0018 0.2976		
-1.08 -0.0479	0.2625 -0.0		0.0033 0.2953		
-1.60 -0.0732	0.4130 -0.0		0.0033 0.2980		
-2.11 -0.0942 -3.14 -0.1458	0.5237 -0.0 0.8295 -0.0		0.0042 0.2971 0.0042 0.3018		
-4.17 -0.1456	1.1425 -0.0		0.0042 0.3018		
-4-11 -0-1480	1.1423 -0.0	1044 0.0208	0.0055 0.5078	0.1252 0.1323	102*
MODEL 946.2	CÓNFIG.		ACH 2.00	PHI = 60.	10.
MODEL 946.2 Q= 8.13 PSI			ACH 2.00 90. DEG.F		10.
Q= 8.13 PSI		48E06 TO=	90. DEG.F		10.
Q= 8.13 PSI	RE PER IN.=	48E06 TO=	90. DEG.F	POJ/PTS =	10. RUN
Q= 8.13 PSI PO= 118.0 CF	RE PER IN.=	48E06 TO= D18 PSI CY	90. DEG.F RUN NO	POJ/PTS = 0050369123 CPB CAL	RUN
Q= 8.13 PSI PO= 118.0 CF ALPHA CN	RE PER IN.= KNG PTS= 2.90 CM C	• .48E06 T0= 018 PSI CS CY 0362 0.2371	90. DEG.F RUN NO. CR CAT	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338	RUN 3 185.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.09 0.2004	RE PER IN.= KMG PTS= 2.90 CM C -1-2031 -0.0	: .48E06 T0= 018 PSI CS CY 0362 0.2371 0340 0.2205	90. DEG.F RUN NO. CR CAT 0.0014 0.2924	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364	RUN 3 186.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.09 0.2004 3.06 0.1429	RE PER IN.= KMG PTS= 2.90 CM C -1-2031 -0.0 -0.8418 -0.0	48E06 T0= 018 PSI CS CY 0362 0.2371 0340 0.2205 0330 0.2196	90. DEG.F RUN NO. CR CAT 0.0014 0.2924 0.0010 0.2909	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399	RUN 3 186. 4 186. 7 186.
Q= 8.13 PSI PO= 118.0 CH ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876	RE PER IN.= RNG PTS= 2.90 CM C -1-2031 -0.0 -0.8418 -0.0 -0.4997 -0.0	48E06 T0= 018 PSI CS CY 0362 0.2371 0340 0.2205 0330 0.2196 0338 0.2329	90. DEG.F RUN NO. CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1418	RUN 3 186. 4 186. 5 186. 6 186.
Q= 8.13 PSI PO= 118.0 CF ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 G.0568 0.98 0.0355 0.47 0.0103	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.3036 -0.0 -0.1969 -0.0 -0.0445 -0.0	340 0.2205 3362 0.2371 3340 0.2205 3330 0.2196 3338 0.2329 3262 0.1587 0.1741	90. DEG.F RUN NO CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2918	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1425	RUN 3 186. 4 186. 5 186. 6 186. 6 186.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 G.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.1969 -0.0 -0.0445 -0.0 0.0626 -0.0	3.48E06 T0= 118 PSI 12.5 CY 13.62 0.2371 13.40 0.2205 13.30 0.2196 13.38 0.2329 12.62 0.1587 12.71 0.1741 12.12 0.1168	90. DEG.F RUN NO CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2918 0.0017 0.2936	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1425 0.1494 0.1443	RUN 3 186. 4 186. 5 186. 6 186. 6 186. 7 186.
Q= 8.13 PSI P0= 118.0 CP ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 0.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107 -0.57 -0.0412	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.1969 -0.0 -0.0445 -0.0 0.0626 -0.0 0.2625 -0.0	2.48E06 T0= 2.18 PSI 2.5 CY 2.362 0.2371 2.340 0.2205 2.330 0.2196 2.338 0.2329 2.262 0.1587 2.271 0.1741 2.212 0.1168 2.275 0.1870	90. DEG.F RUN NO CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2918 0.0017 0.2936 0.0019 0.2950	POJ/PTS = . 0050369123 CPB CAI 0.1586 0.1338 0.1545 0.1369 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1425 0.1494 0.1443 0.1496 0.1454	RUN 3 186. 4 186. 5 186. 6 186. 6 186. 6 186.
Q= 8.13 PSI P0= 118.0 CP ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 0.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107 -0.57 -0.0412 -1.09 -0.0672	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.1969 -0.0 -0.0445 -0.0 0.0626 -0.0 0.2625 -0.0 0.4163 -0.0	2.48E06 T0= 2.18 PSI 2.5 CY 2.362 0.2371 2.340 0.2205 2.330 0.2196 2.338 0.2329 2.262 0.1587 2.271 0.1741 2.212 0.1168 2.275 0.1870 2.294 0.2112	90. DEG.F RUN NO CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2918 0.0017 0.2936 0.0019 0.2950 0.0028 0.2957	POJ/PTS = . 0050369123 CPB CAI 0.1586 0.1338 0.1545 0.1369 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1425 0.1494 0.1445 0.1496 0.1454 0.1495 0.1465	RUN 3 186. 186. 186. 186. 186. 186. 186.
Q= 8.13 PSI P0= 118.0 CP ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 G.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107 -0.57 -0.0412 -1.09 -0.0672 -1.60 -0.0872	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.1969 -0.0 -0.0445 -0.0 0.0626 -0.0 0.2625 -0.0 0.4163 -0.0 0.5118 -0.0	362 0.2371 3340 0.2205 3330 0.2196 338 0.2329 3262 0.1587 3271 0.1741 3212 0.1168 3275 0.1870 3294 0.2112	90. DEG.F RUN NO. CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2926 0.0014 0.2936 0.0017 0.2936 0.0019 0.2957 0.0028 0.2957	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1438 0.1492 0.1434 0.1492 0.1434 0.1494 0.1445 0.1496 0.1454 0.1495 0.1493 0.1493 0.1475	RUN 3 185. 186. 186. 186. 186. 186. 186. 186.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 G.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107 -0.57 -0.0412 -1.09 -0.0672 -1.60 -0.0872 -2.11 -0.1130	RE PER IN.= RNG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.3036 -0.0 -0.1969 -0.0 0.0626 -0.0 0.2625 -0.0 0.4163 -0.0 0.5118 -0.0 0.6473 -0.0	362 0.2371 340 0.2205 338 0.2329 3262 0.1587 3271 0.1741 3212 0.1168 3275 0.1870 3294 0.2112 3203 0.1207	90. DEG.F RUN NO. CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2926 0.0014 0.2936 0.0019 0.2936 0.0019 0.2957 0.0028 0.2968 0.0034 0.2995	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1452 0.1496 0.1454 0.1496 0.1454 0.1493 0.1475 0.1494 0.1503	RUN 3 186. 186. 186. 186. 186. 186. 186. 186.
Q= 8.13 PSI P0= 118.0 CP ALPHA CN 4.09 0.2004 3.06 0.1429 2.03 0.0876 1.50 G.0568 0.98 0.0355 0.47 0.0103 -0.05 -0.0107 -0.57 -0.0412 -1.09 -0.0672 -1.60 -0.0872	RE PER IN.= KMG PTS= 2.90 CM C -1.2031 -0.0 -0.8418 -0.0 -0.4997 -0.0 -0.1969 -0.0 -0.0445 -0.0 0.0626 -0.0 0.2625 -0.0 0.4163 -0.0 0.5118 -0.0	3.48E06 T0= 118 PSI 23.62 0.2371 23.40 0.2205 23.30 0.2196 23.38 0.2329 22.62 0.1587 22.11 0.1168 22.15 0.1870 22.10 0.1207 22.10 0.1207 22.10 0.1489 22.16 0.1445	90. DEG.F RUN NO. CR CAT 0.0014 0.2924 0.0010 0.2909 0.0012 0.2914 0.0005 0.2914 0.0014 0.2926 0.0014 0.2926 0.0014 0.2936 0.0017 0.2936 0.0019 0.2957 0.0028 0.2957	POJ/PTS = . 0050369123 CPB CAL 0.1586 0.1338 0.1545 0.1364 0.1515 0.1399 0.1498 0.1418 0.1492 0.1434 0.1493 0.1425 0.1495 0.1454 0.1495 0.1456 0.1493 0.1475 0.1494 0.1501 0.1506 0.1506	RUN 186. 186. 186. 186. 186. 186. 186. 186

MDDEL 946.2	CON	iG0000	M	ICH 2.00	PHI =	50.
Q= 8.13 PSI	RE PER	IN.= .48E0	=CT 8	90. DEG.F	POJ/PTS =	= 20.
PO= 118.0 C	HHG PTS=	2.9018 PSI		RUN N	0. 00503691	24
ALPHA CN	CM	£S	CY	CR CAT	CPB C	AF RUN
4.09 0.1961		-0.0655		0.0010 0.298		
3.06 0.1358		-0.0617		0.0003 0.295		
2.03 0.0758 1.49 0.0517		-0.0543 -0.0474		0.0005 0.293		
0.98 0.0227		-0.0531		·C.0003 0.294		
0.45 -0.0014		-0.0462		0.0010 0.294		
-0.06 -0.0257		-0.0438		0.9013 0.294		
-0.57 -0.0533		-0.0486		9.0015 0.295		
-1.09 -0.0752	0.4600	-0.0399	0.2523	0.0021 0.297	9 0.1503 0.	1476 287.
-1.61 -0.1022	0.6251	-0.0459	0.3175	G.0032 0.300	0 0.1504 0.	1496 187.
-2.12 -0.1223	0.7283	~0.0420	0.2859	0.0025 0.301	B 0.1501 0.	1517 187.
-3.15 -0.1751		-0.0417		0.0040 0.305		
-4.18 -0.2303	1.3755	-0.0439	0.3180	0.0045 0.313	3 0-1528 0-1	1605 187.
MODEL 946.2		IG0000		ACH 2.00		50.
Q= 8.13 PSI	RE PER	IN.= .48E0	6 TO=	ACH 2.00	PHI = 0	
	RE PER	IN.= .48E0	6 TO=	90. DEG.F		= 40.
Q= 8.13 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS =	= 40.
Q= 8.13 PSI PO= 118.0 CI	RE PER HHG PTS=	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS = 0. 005036912 CPB C	= 40. 25 AF RUN
Q= 8.13 PSI PO= 118.0 CI ALPHA CN 4.07 0.1798 3.05 0.1175	RE PER MHG PTS= CM -1.0943 -0.6814	IN.= .48E0 2.9018 PSI CS -0.1243 -0.1118	6 TO= CY 7.9211 0.8049	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299	POJ/PTS = 0.05036912 CPB CPB CPB CPB CPB CPB CPB CPB CPB CPB	= 40. 25 AF RUN 1439 188. 1454 188.
Q= 8.13 PSI PO= 118.0 CI ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564	RE PER 9HG PTS= CM -1.0943 -0.6814 -0.2839	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008	6 TO= CY 7.9211 0.8049 0.7045	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298	POJ/PTS = 0. 005036912 CPB C: 1 0.1592 0.1545 0.1545 0.1525 0.	= 40. 25 AF RUN 1439 188. 1454 188.
Q= 8.13 PSI P0= 118.0 CP ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973	CY 7.9211 0.4049 0.7045 0.6742	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298	POJ/PTS = CPB C 1 0.1592 0.1 9 0.1545 0.1 3 0.1525 0.1 7 0.1515 0.1	= 4C. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188.
Q= 8.13 PSI P0= 118.0 CI ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973 -0.0991	CY 7,9211 0.4049 0.7045 0.6742 0.6999	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298 0.0016 0.298	POJ/PTS = CPB C 1 0.1592 0.1 9 0.1545 0.1 3 0.1525 C.1 7 0.1515 0.1 0 0.1507 0.1	= 4C. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1473 188.
Q= 8.13 PSI P0= 118.0 CI ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309	RE PER 9HG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973 -0.0991 -0.0999	CY 7.9211 0.4049 0.7045 0.6742 0.6999 0.7133	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298 0.0016 0.298 0.0010 0.298	PCJ/PTS = CP8	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1472 188.
Q= 8.13 PSI P0= 118.0 CR ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -9.0578	RE PER 9HG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602 0.4265	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013	CY 7-9211 0-8049 0-7045 0-6742 0-6999 0-7133 0-7337	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298 0.0016 0.298 0.0010 0.298 0.0018 0.300	POJ/PTS = CPB	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1473 188. 1481 188.
Q= 8.13 PSI P0= 118.0 CR ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -0.0578 -0.59 -0.0807	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602 0.4265 0.5481	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013 -0.0951	CY 7.9211 0.8049 0.7045 0.6742 0.6742 0.6743 0.7337 0.6763	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.298 0.0017 0.298 0.0019 0.298 0.0016 0.298 0.0010 0.298 0.0018 0.300 0.0024 0.302	PCJ/PTS = C-10.005036912 CPB C-10.1592 0.1595 0.1595 0.1595 0.1505 0.1505 0.1508 0.15	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1473 188. 1481 188. 1499 188.
Q= 8.13 PSI P0= 118.0 CR ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -9.0578 -0.59 -0.0807 -1.10 -0.1045	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602 0.4265 0.5481 0.6817	IN.= .4860 2.9018 PSI CS -0.1243 -0.1118 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013 -0.0951 -0.0968	CY 7.9211 0.4049 0.7045 0.6742 0.6742 0.7133 0.7337 0.6763 0.6991	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298 0.0016 0.298 0.0018 0.300 0.0024 0.302 0.0026 0.301	POJ/PTS = C-10.1592 0.1595 0.1595 0.1515 0.1507 0.1505 0.1508 0.1	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1472 188. 1472 188. 1473 188. 1471 188. 1481 188. 1499 188.
Q= 8.13 PSI P0= 118.0 CR ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -9.0578 -0.59 -0.0807 -1.10 -0.1045 -1.62 -0.1320	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0757 0.2602 0.4265 0.5481 0.6817 0.8471	IN.= .4860 2-9018 PSI CS -0.1243 -0.1318 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013 -0.0951 -0.0968 -0.0964	CY 7.9211 0.4049 0.7045 0.6742 0.6742 0.7133 0.7337 0.6763 0.6991 0.7020	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.298 0.0017 0.298 0.0016 0.298 0.0016 0.298 0.0018 0.300 0.0024 0.302 0.0026 0.301 0.0029 0.303	POJ/PTS = 0.005036912 CPB C: 0.1592 0.0 0.1545 0.0 0.1525 0.0 7 0.1515 0.0 0.1507 0.0 0.1500 0.0 0.1500 0.0 0.1500 0.0 0.1500 0.0 0.1500 0.0 0.1500 0.0 0.1500 0.0	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1472 188. 1473 188. 1471 188. 1481 188. 1499 188. 1517 188. 1515 188.
Q= 8.13 PSI P0= 118.0 CR ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -9.0578 -0.59 -0.0807 -1.10 -0.1045	RE PER MHG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602 0.4265 0.5481 0.6817 0.8471 0.9690	IN.= .4860 2.9018 PSI CS -0.1243 -0.1318 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013 -0.0951 -0.0968 -0.0964 -0.0926	CY 7.9211 0.8049 0.7045 0.6742 0.6999 0.7133 0.7337 0.6763 0.6991 0.7020 0.6668	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.299 0.0017 0.298 0.0019 0.298 0.0016 0.298 0.0010 0.298 0.0018 0.300 0.0024 0.302 0.0026 0.301 0.0029 0.303 0.0040 0.307	POJ/PTS = CPB C CPB C 1 0.1592 0.1545 0.1505 0.1505 0.1505 0.1500 0.1	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1472 188. 1473 188. 1471 188. 1481 188. 1499 188. 1517 188. 1515 188. 1535 188.
Q= 8.13 PSI P0= 118.0 CI ALPHA CN 4.07 0.1798 3.05 0.1175 2.01 0.0564 1.48 0.0261 0.96 -0.0015 0.44 -0.0309 -0.07 -9.0578 -0.59 -0.0807 -1.10 -0.1045 -1.62 -0.1320 -2.13 -0.1546	RE PER HG PTS= CM -1.0943 -0.6814 -0.2839 -0.0958 0.0757 0.2602 0.4265 0.5481 0.6817 0.8471 0.9690 1.2635	IN.= .4860 2-9018 PSI CS -0.1243 -0.1318 -0.1008 -0.0973 -0.0991 -0.0999 -0.1013 -0.0951 -0.0968 -0.0964	CY 7.9211 0.8049 0.7045 0.6742 0.6999 0.7133 0.7337 0.6763 0.7020 0.6668 0.6572	90. DEG.F RUN N CR CAT 0.0020 0.303 0.0016 0.298 0.0017 0.298 0.0016 0.298 0.0016 0.298 0.0018 0.300 0.0024 0.302 0.0026 0.301 0.0029 0.303	POJ/PTS = CPB C CPB C 1 0.1592 0.1 9 0.1545 0.1 3 0.1525 0.1 7 0.1515 0.1 0 0.1507 0.1 7 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1 1 0.1508 0.1	= 40. 25 AF RUN 1439 188. 1454 188. 1463 188. 1472 188. 1473 188. 1473 188. 1473 188. 1517 188. 1517 188. 1515 188. 1515 188.

HODE	L 946.2	CONF	FIG0000	, MA	/CH. 5 • 00	0	PHI =	60.		
Ç≈ A	.13 PSI	RE PER	1N.= .48E0	6 10=	90. 08	EG.F	903/6	TS =	80-	
PU=	118.0 CM	HG PTS=	2.9018 PSI			RUN NO.	. 00503	69126		
ALPHA	CN	CH	cs	CY	CR	CÂT	CP8	CAF		RUN
4.05	0.1488	-0.9376	-0.2300	1.6970	0.0024	0.3082	0.1567	0.1515	;	189.
	0.0736	-0.3944	-0.2149		0.0024					189.
1.98	2900.6	0.9634	-0.2000	1.4238	0.0022	0.3043	0.1496	0.1547	f	189.
1.45 -	-0-0253		-0.1962		0.0032					1,89.
	0.0505		-0.1990		0.0031					189.
0.42 -	-0.0855	0.6610	-0.1924	1.3769	0.0030	0.3045	0.1498	0.1548	1	189.
-0.10 -			-0.1971		0.0027					189.
-0.63 -			-0.2015		0.0031					189.
-1.13 -			~0.2005		0.0028					189.
-1.65 -			-0.2041		0.0030					189.
-2.16 -			-0.1963		9.0036					189.
-3.20 -		1.8299			0.0047					189.
-4.23 -	-0.3369	2.1838	-0.1917	1.4220	0.0051	0.3158	0.1543	0-1615	5	189.
	L 946.2		FIG0000		NCH 2.00		PHI =	75 .		
	EL 946.2 3.13 PSI		FIG0000 IN.= .48E0		90. DE		PHI =	_	*	
Q= 8	3-13 PSI	RE PER		6 TO=		EG.F	_	TS =	w	
Q= 8	3-13 PSI	RE PER	IN.= .48E0	6 TO=		EG.F	POJ/P	TS =	u	RUN
Q= 8 PO= ALPHA	3.13 PSI 118.0 CM	RE PER HG PYS=	IN.= .48E0	6 10=	90. DE	EG.F RUN NO. Cat	POJ/P	TS = 69127 CAF		
Q= 8 PO= ALPHA 4-21	3.13 PSI 118.0 CMI	RE PER HG PYS= CH -1+1884	IN.= .48E0 2.9018 PSI CS	6 TO= CY 0.1176	90. DE	EG.F RUN NO. CAT 0.2951	POJ/P 005030 CPB	TS = 69127 CAF 0.1459		RUN 190.
Q= 8 PO= ALPHA 4-21 3-18	3.13 PSI 118.0 CM CN 0.2053	RE PER HG PYS= CM -1-1884 -0-8651	IN.= .48E0 2.9018 PSI CS -0.0149	6 TO= CY 0.1176- 0.0706-	90. DE CR -0.0007	EG.F RUN NO. CAT 0.2951 0.2915	POJ/P ² . 005036 CPB 0.1492 0.1473	TS = 69127 CAF 0.1459 0.1442	!	190.
Q= 8 PO= ALPHA 4-21 3-18 2-14	3.13 PSI 118.0 CM CN 0.2053 0.1517	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108	6 TO= CY 0.1176- 0.0706- 0.1112-	90. DE CR -0.0007	EG.F RUN NO. CAT 0.2951 0.2915 0.2930	POJ/P ² - 005030 - CPB - 0.1492 - 0.1473 - 0.1460	TS = 69127 CAF 0.1459 0.1442 0.1470	1	190. 190.
Q= 8 PO= ALPHA 4-21 3-18 2-14	0.2053 0.1517 0.0997	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613 -0.4105	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154	CY 0.1176- 0.0706- 0.1112- 0.0891-	90. DE CR -0.0007 -0.0004 -0-0009	CAT 0.2951 0.2915 0.2930 0.2926	POJ/P . 005030 CPB 0.1492 0.1473 0.1460 0.1464	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462		190. 190.
Q= 8 PO= ALPHA 4-21 3-18 2-14 1-62 1-10	0.2053 0.1517 0.0997 0.0737	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613 -0.4105 -0.2786	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132	CY 0.1176 0.0706 0.1112 0.0891 0.1208	90. DE CR -0.0007 -0.0004 -0.0009 -0.0010	CAT 0.2951 0.2915 0.2930 0.2930 0.2930	POJ/P . 005030 CPB 0.1492 0.1473 0.1460 0.1464 0.1461	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462		190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58	0.2053 0.1517 0.0997 0.0737	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1599	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702	70. DE CR -0.0007 -0.0004 -0.0009 -0.0010	CAT 0.2951 0.2955 0.2930 0.2926 0.2930 0.2946	POJ/P . 005030 CPB 0.1492 0.1473 0.1464 0.1464 0.1461 0.1456	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462 0.1469		190. 190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58	0.2053 0.1517 0.0997 0.0737 0.0500 0.0278 9.0051	RE PER HG PYS= CH -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1599 -0.0369 0.1262	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164 -0.0111 -0.0063 -0.0149	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702 0.0169 0.1047	O. DE CR -0.0007 -0.0004 -0.0010 -0.0002 -0.0006 0.0008	CAT 0.2951 0.2951 0.2935 0.2936 0.2936 0.2936 0.2935	POJ/P . 005030 CPB 0.1492 0.1473 0.1464 0.1464 0.1464 0.1454 0.1454 0.1454	TS = 69127 CAF 0.1459 0.1442 0.1462 0.1469 0.1469 0.1481 0.1514		190. 190. 190. 190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58 0.06 -0.45 -0.97	0.2053 0.1517 0.0997 0.0737 0.0500 0.0278 9.0051 0.0216	RE PER HG PYS= CH -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1599 -0.0369 0.1262 0.2385	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164 -0.0111 -0.0063 -0.0149 -0.0083	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702 0.0169 0.1047 0.0343	O. DE CR -0.0007 -0.0004 -0.0010 -0.0002 -0.0006 0.0008 0.0003	CAT 0.2951 0.2951 0.2915 0.2936 0.2936 0.2936 0.2936 0.2937	POJ/P . 005030 CPB 0.1492 0.1473 0.1464 0.1464 0.1454 0.1454 0.1454 0.1455	TS = 69127 CAF 0.1459 0.1442 0.1462 0.1469 0.1469 0.1481 0.1514		190. 190. 190. 190. 190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58 0.06 -0.45 -0.97 1.48	0.2053 0.1517 0.0997 0.0737 0.0500 0.0278 9.0051 0.0216 0.0435	RE PER HG PYS= CH -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1599 -0.0369 0.1262 0.2385 0.4008	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164 -0.0111 -0.0063 -0.0149 -0.0083 -0.0142	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702 0.0169 0.1047 0.0343 0.0932	O. DE CR -0.0007 -0.0004 -0.0010 -0.0006 0.0008 0.0008 0.0003 0.0014	CAT 0.2951 0.2915 0.2930 0.2930 0.2946 0.2935 0.2967 0.2975	POJ/P . 005036 CPB 0.1492 0.1473 0.1460 0.1464 0.1454 0.1454 0.1452 0.1457 0.1461	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462 0.1490 0.1481 0.1514 0.1519 0.1526		190. 190. 190. 190. 190. 190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58 0.06 -0.45 -0.97 -1.48 -2.00	0.2053 0.1517 0.0997 0.0737 0.0500 0.0278 9.0051 0.0216 0.0216	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1599 -0.0369 0.1262 0.2385 0.4008 0.5416	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164 -0.0111 -0.0063 -0.0149 -0.0083 -0.0142 -0.0166	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702 0.0169 0.1047 0.0343 0.0932 0.1172	O. DE CR -0.0007 -0.0004 -0.0002 -0.0006 0.0008 0.0003 0.0014 0.0013	CAT 0.2951 0.2915 0.2930 0.2926 0.2930 0.2946 0.2935 0.2947 0.2987	POJ/P . 005036 CPB 0.1492 0.1473 0.1460 0.1461 0.1454 0.1454 0.1457 0.1461 0.1464	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462 0.1469 0.1481 0.1514 0.1516		190. 190. 190. 190. 190. 190. 190. 190.
Q= 8 PO= ALPHA 4.21 3.18 2.14 1.62 1.10 0.58 0.06 -0.45 -0.97 1.48	0.2053 0.1517 0.0997 0.0737 0.0500 0.0278 9.0051 0.0216 0.0216 0.0435 0.0702	RE PER HG PYS= CM -1.1884 -0.8651 -0.5613 -0.4105 -0.2786 -0.1569 0.1262 0.2385 0.4008 0.5416 0.8352	IN.= .48E0 2.9018 PSI CS -0.0149 -0.0108 -0.0154 -0.0132 -0.0164 -0.0111 -0.0063 -0.0149 -0.0083 -0.0142	CY 0.1176 0.0706 0.1112 0.0891 0.1208 0.0702 0.0169 0.1047 0.0343 0.0932 0.1172 0.1399	O. DE CR -0.0007 -0.0004 -0.0010 -0.0006 0.0008 0.0008 0.0003 0.0014	CAT 0.2951 0.2915 0.2930 0.2930 0.2946 0.2935 0.2967 0.2987 0.2987 0.3025	POJ/P . 005030 CPB 0.1492 0.1473 0.1460 0.1461 0.1454 0.1452 0.1452 0.1461 0.1464 0.1464 0.1464	TS = 69127 CAF 0.1459 0.1442 0.1470 0.1462 0.1469 0.1519 0.1516 0.1526 0.1559		190. 190. 190. 190. 190. 190. 190. 190.

1101	DEL 946.2	CON	IG0900	MAC	H 2.00	PHI =	75.	
Q=	8.13 PSI	RE PER	IN.= .48E0	6 T0=	90. DEG.F	2T9\LC9	= 10.	
6 0:	= 118,0 CM	HG PTS=	2.9018 PSI		RUN NO	. 0050369	128	
ALPHA	CN	CH	cs	CY	CR CAT	СРВ	CAF	RUN
4.20	0.2082	-1.2300	-0.0325	0.2279-0	0.0002 0.2940	0.1526 0	-1414	191.
3.18	0.1516		-0.0352	0.2500-0	0.0002 0.2933	0.1515 0	.1418	191.
2-15	0.0976	-0.5560	-0.0310	0-2048-0	0.0004 0.2938	0.1496 0	.1442	191.
1.61	0.0702	-0.3934	-0.0312		0.0012 0.2929			191.
1.10			-0.0346		0.0007. 0.2946			191.
0.57			~0.0278		0.0005 0.2955			191.
	-0.0051		-0.0349		0.0003 0.2966			191.
	-0.0308		-0.0329		0.0004 0.2997			191.
	-0.0552		-0.0331		0.0015 0.3007			191.
	-0.0807		-0.0345		0.0017 0.2997			191.
	-0.1060		-0.0366		0.0015 0.3028			.191.
	-0.1548		-0.0352		0.0019 0.3061			191.
-4.06	-0.2120	1.2563	-0.0398	0.2790	0.0034 0.3144	0.1550 0	-1634	191.
но	DEL 946.2	CONI	FIG0000	MAC	CH 2.00	PHI =	75.	
_			•				•	
Q=	8.13 PSI		IN.= .48E0		90. DEG.F		•	
	•	RE PEX	•	6 T0=	90. DEG.F		20.	·
	= 118.0 CM	RE PEX	IN.= .48E0	6 T0=	90. DEG.F	POJ/PTS	20.	. RUN-
PO:	≃ 118.0 CM	RE PER HG PTS= CM	IN.= .48E0 2.9018 PSI CS	6 T0=	90. DEG.F RUN NO CR CAT	POJ/PTS • 0050369 • CPB	= 20. 0129 CAF	` RUN-
PO: ALPHA 4-20	= 118.0 CM CN- 0.2092	RE PEX HG PTS= CM -1.2494	IN.= .48E0 2.9018 PSI CS -0.0695	6 T0= CY 0.5275-0	90. DEG.F RUN NO CR CAT 0.0003 0.2988	POJ/PTS . 0050369 . CPB 0.1549 0	S = 20. 2129 CAF 2.1439	
PO: ALPHA 4.20 3.18	= 118.0 CM CN- 0.2092 0.1498	RE PEX HG PTS= CM -1.2494 -0.8735	IN.= .48E0 2.9018 PSI CS	6 T0= CY 0.5275-0	90. DEG.F RUN NO CR CAT	POJ/PTS . 0050369 . CPB 0.1549 0 0.1526 0	E 20. 0129 CAF 0.1439	RUN-
PO: ALPHA 4-20	2 118.0 CM CN: 0.2092 0.1498 0.0945	RE PEX HG PTS= CM -1.2494 -0.8735 -0.5366	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633	CY 0.5275-0 0.4608-0 0.3769-0	90. DEG.F RUN NO CR CAT 0.0003 0.2988 0.0008 0.2959	POJ/PTS - 0050369 - CPB - 0.1549 0 - 0.1526 0 - 0.1501 0	CAF 0.1439 0.1432 0.1468	RUN- 192. 192.
PO: ALPHA 4.20 3.18 2.15	2 118.0 CM CN- 0.2092 0.1498 0.0945 0.0651	RE PEX HG PTS= CM -1.2494 -0.2735 -0.5366 -0.3549	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546	CY 0.5275-0 0.4608-0 0.3769-0 0.4305-0	90. DEG.F RUN NO CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969	POJ/PTS . 0050369 . CPB 0.1549 0 0.1526 0 0.1501 0 0.1499 0	CAF 0.1439 0.1432 0.1468	RUN- 192. 192.
PO- ALPHA 4-20 3-18 2-15 1-62	CN 0.2092 0.1498 0.0945 0.0651 0.0372	RE PEX HG PTS= CM -1.2494 -0.2735 -0.5366 -0.3549 -0.1832	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605	CY 0.5275-0 0.4608-0 0.3769-0 0.4305-0 0.4924-0	90. DEG.F RUN NG CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940	POJ/PTS - 0050369 - CPB - 0.1549 0 - 0.1526 0 - 0.1501 0 - 0.1499 0 - 0.1493 0	CAF 0.1439 0.1432 0.1468 0.1441	RUN- 192. 192. 192.
PO: ALPHA 4-20 3-18 2-15 1-62 1-10 0-58	CN 0.2092 0.1498 0.0945 0.0651 0.0372	RE PEX HG PTS= CM -1.2494 -0.2735 -0.5366 -0.3549 -0.1832 -0.0476	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668	CY 0.5275-0 0.4608-0 0.3769-0 0.4305-0 0.4924-0 0.4067-0	90. DEG.F RUN NG CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979	POJ/PTS . 0050369 . CPB 0.1549 0 0.1501 0 0.1499 0 0.1493 0 0.1498 0	CAF 0.1439 0.1432 0.1468 0.1441 0.1486	RUN- 192. 192. 192. 192.
PO: ALPHA 4.20 3.18 2.15 1.62 1.10 0.58 0.06	CN- 0.2092 0.1498 0.0945 0.0951 0.0372 0.0129	RE PEX HG PTS= CM -1.2494 -0.8735 -0.5366 -0.3549 -0.1832 -0.0476 0.1064	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668 -0.0582	CY 0.5275-0 0.4608-0 0.3769-0 0.4305-0 0.4924-0 0.4067-0	90. DEG.F RUN NG CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979 0.0009 0.2974 0.0008 0.2985	POJ/PTS . 0050369 . CPB 0.1549 0 0.1526 0 0.1501 0 0.1499 0 0.1493 0 0.1494 0	CAF 0.1439 0.1432 0.1468 0.1441 0.1486 0.1488	RUN- 192. 192. 192. 192. 192.
PO: ALPHA 4.20 3.18 2.15 1.62 1.10 0.58 0.06	2 118.0 CM CN- 0.2092 0.1498 0.0945 0.0651 0.0372 0.0129 -0.0129	RE PEX HG PTS= CM -1.2494 -0.8735 -0.5366 -0.3549 -0.1832 -0.0476 0.1064 0.2533	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668 -0.0582 -0.0636	CY 0.5275-0 0.4608-0 0.4305-0 0.4305-0 0.4924-0 0.4632-0 0.4351-0	90. DEG.F RUN NG CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979 0.0009 0.2974 0.0008 0.2985	POJ/PTS . 0050369 . CPB 0.1549 0 0.1526 0 0.1501 0 0.1499 0 0.1493 0 0.1494 0 0.1494 0	CAF 0.1439 0.1432 0.1468 0.1441 0.1486 0.1488 0.1510	RUN- 192. 192. 192. 192. 192. 192.
PO: ALPHA 4.20 3.18 2.15 1.62 1.10 0.58 0.06 -0.46 -0.97	2 118.0 CM CN 0.2092 0.1498 0.0945 0.0651 0.0372 0.0129 -0.0129 -0.0385	RE PEX HG PTS= CM -1.2494 -0.2735 -0.5366 -0.3549 -0.1832 -0.0476 0.1064 0.2533 0.3870	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668 -0.0582 -0.0636 -0.0608	CY 0.5275-0 0.4608-0 0.4305-0 0.4924-0 0.4632-0 0.4632-0 0.4072 0.4351-0 0.4072	90. DEG.F RUN NO CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979 0.0009 0.2974 0.0008 0.2985 0.0008 0.2985 0.0008 0.3038	POJ/PTS - 0050369 CPB 0.1549 0 0.1526 0 0.1501 0 0.1499 0 0.1493 0 0.1474 0 0.1476 0 0.1479 0	CAF 0.1439 0.1432 0.1468 0.1486 0.1488 0.1510 0.1559 0.1562	RUN- 192. 192. 192. 192. 192. 192. 192.
PO: ALPHA 4.20 3.18 2.15 1.62 1.10 0.58 0.06 -0.46 -0.97 -1.49	2 118.0 CM CN 0.2092 0.1498 0.0945 0.0651 0.0372 0.0129 -0.0129 -0.0385 -0.0626	RE PEX HG PTS= CM -1.2494 -0.2735 -0.5366 -0.3549 -0.1832 -0.0476 0.1064 0.2533 0.3870 0.5166	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668 -0.0582 -0.0636 -0.0608 -0.0584	CY 0.5275-0 0.4608-0 0.4724-0 0.4632-0 0.4072 0.3683 0.3853	90. DEG.F RUN NG CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979 0.0009 0.2974 0.0008 0.2985 0.0008 0.2985 0.0008 0.3038	POJ/PTS - 0050369 CPB 0.1549 0 0.1526 0 0.1501 0 0.1499 0 0.1493 0 0.1474 0 0.1474 0 0.1476 0 0.1478 0 0.1478 0	CAF 0.1439 0.1432 0.1468 0.1441 0.1486 0.1510 0.1521 0.1559 0.1562	RUN- 192. 192. 192. 192. 192. 192. 192. 192.
PO: ALPHA 4.20 3.18 2.15 1.62 1.10 0.58 0.046 -0.46 -0.97 -1.49 -2.01 -3.04	2 118.0 CM CN 0.2092 0.1498 0.0945 0.0051 0.0372 0.0129 -0.0129 -0.0385 -0.0626 -0.0864	RE PEX CH -1.2494 -0.2735 -0.5366 -0.3549 -0.1832 -0.0476 0.1064 0.2533 0.3870 0.5166 0.6850 0.9897	IN.= .48E0 2.9018 PSI CS -0.0695 -0.0633 -0.0546 -0.0605 -0.0668 -0.0582 -0.0636 -0.0608 -0.0584 -0.0547	CY 0.5275-(0.4608-(0.3769-(0.4305-(0.4924-(0.4067-(0.4632-(0.4351-(0.40583 (0.4327	90. DEG.F RUN NO CR CAT 0.0003 0.2988 0.0008 0.2959 0.0006 0.2969 0.0016 0.2940 0.0020 0.2979 0.0009 0.2974 0.0008 0.2985 0.0008 0.2985 0.0008 0.3038	POJ/PTS - 0050369 - CPB - 0.1549 0 - 0.1526 0 0.1501 0 0.1499 0 0.1493 0 0.1494 0 0.1474 0 0.1474 0 0.1476 0 0.1478 0 0.1482 0 0.1487 0	CAF 0.1439 0.1432 0.1468 0.1441 0.1486 0.1510 0.1521 0.1559 0.1562 0.1569 0.1612	RUN- 192. 192. 192. 192. 192. 192. 192. 192.

MODEL 946.2	CONF	FIG0000	H	ACH 2.00	PHI =	75.	
C= 8.13 PSI	RE PER	IN.= .48E0	5 TO=	90. DEG.F	79\L09	s = 40.	
PO= 118.0 C	HG PTS=	2.9018 PSI		RUN N	005036	9130	
ALPHA CN	СН	cs	CY	CR CAT	СРВ	CAF	RUN
4.20 0.2120		-0.1198		0.0005 0.3039			193.
3.17 0.1458	-0.8587	-0.1167		0.0001 0.3016			193.
2.14 0.0849		-0.1107		0.0007 0.3000			193.
1.60 0.0535		-0.1146		0.0002 0.3018			193.
1.09 0.0274		-0.1070		-0.0008 0.3008			193.
0.57 -0.0004		-0.1126		-0.0012 0.3017			193.
0.05 -0.0255		-0.1099		0.0010 0.3013			193.
-0.46 -0.0504		-0.1046		0.0006 0.3042			193.
-0.93 -0.0778		-0.1185		0.0007 0.3069			193.
-1.50 -0.1054		-0.1151		0.0011 0.306			193.
-2.01 -0.1290		-0.1122		0.0016 0.310			193.
	1.1245			0.0019 0.314			193.
-4.08 -0.2414	1.4752	-0.1144	0.9243	0.0028 0.3177	0.1499	0.1678	193.
MODEL 946.2	CONF			ACH 2.00	PHI =	75.	
MODEL 946.2 G= 8.13 PSI		FIG0000 IN.= .48E0		ACH 2.00 90. DEG.F	PHI = POJ/PT:		
	RE PER	IN.= .48E0		90. DEG.F		.08 = 2	
C= 8.13 PSI	RE PER	IN.= .48E0		90. DEG.F	POJ/PT:	.08 = 2	RUN
G= 8.13 PSI PO= 118.0 C	RE PER HHG PTS=	IN.= .48E0	5 TO=	90. DEG.F	POJ/PT: 0. 0050369 CPB	S = 80. 9131 CAF	RUN 194•
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288	RE PER HHG PTS= CM -1.2841	IN.= .48E00 2,9018 PSI CS	CY 1.7148 1.7070	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080	POJ/PT: 0. 0050369 CPB 0.1616 (S = 80. 9131 CAF 0.1487 0.1502	194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928	IN.= .48E00 2.9018 PSI CS -0.2338 -0.2327 -0.2255	CY 1.7148 1.7070 1.6409	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063	POJ/PT: 0. 0050369 CPB 0.1616 (0) 0.1578 (0) 0.1536 (0)	S = 80. 9131 CAF 0.1487 0.1502 0.1527	194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699	IN.= .48E00 2.9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274	CY 1.7148 1.7070 1.6409 1.6637	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063 0.0008 0.3066	POJ/PT: CPB CPB CONTROL CPB CONTROL CONTRO	S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553	194. 194. 194.
G= 8.13 PSI PO= 118.0 CM ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144	IN.= .48E00 2,9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243	CY 1.7148 1.7070 1.6409 1.6637 1.6345	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3060 0.0008 0.3060 C 0010 0.3041	POJ/PT: 0. 0050369 CPB 0.1616 (0.1578 (0.1536 (0.1513 (0.1494 (S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1547	194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766	IN.= .48E00 2,9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243 -0.2197	CY 1.7148 1.7970 1.6409 1.6637 1.6345 1.5901	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3060 0.0008 0.3060 C 0010 0.3041 0.0011 0.3036	POJ/PT: 0. 0050369 CPB 0.1616 6 0.1578 6 0.1536 6 0.1513 6 0.1494 6 0.1482 6	S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1547 0.1555	194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306 0.04 -0.0573	RE PER HHG PTS= CH -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333	IN.= .48E00 2,9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.6521	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3060 0.0008 0.3060 C 0010 0.3041 0.0011 0.3036 0.0015 0.3066	POJ/PT: 0. 0050369 CPB 0. 1616 (0. 1578 (0. 1536 (0. 1513 (0. 1494 (0. 1482 (0. 1470 (S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1547 0.1555 0.1598	194. 194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306 0.04 -0.0573 -0.48 -0.0896	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333 0.6403	IN.= .48E00 2,9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256 -0.2314	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.6521 1.7130-	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063 0.0008 0.3066 0.0010 0.3041 0.0011 0.3036 0.0015 0.3066 -0.0004 0.3059	POJ/PT: 0. 0050369 CPB 0.1616 (0.1578 (0.1536 (0.1536 (0.1494 (0.1492 (0.1471 (0.1471 (0.1471 (S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1553 0.1555 0.1555 0.1558	194. 194. 194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.00306 0.04 -0.0573 -0.48 -0.0896 -1.00 -0.1145	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333 0.6403 0.7777	IN.= .48E00 2,9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256 -0.2314 -0.2329	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.6521 1.7130- 1.7260	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3086 0.0017 0.3066 0.0008 0.3066 0.0015 0.3066 -0.0004 0.3059 0.0018 0.3117	POJ/PT: 0. 0050369 CPB 0. 1616 (0. 1578 (0. 1536 (0. 1513 (0. 1492 (0. 1482 (0. 1471 (0. 1474 (S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1555 0.1555 0.1598 0.1588	194. 194. 194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306 0.04 -0.0573 -0.48 -0.0896 -1.00 -0.1145 -1.52 -0.1428	RE PER HHG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333 0.6403 0.7777 0.9456	IN.= .48E00 2,9018 PSI CS -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256 -0.2314 -0.2329 -0.2322	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.6521 1.7130- 1.7260 1.7207	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063 0.0008 0.3066 0.0010 0.3041 0.0011 0.3036 0.0015 0.3066 0.0015 0.3066 0.0016 0.3056 0.0018 0.3113	POJ/PT: 0. 005036 CPB 0.1616 (0.1578 (0.1536 (0.1536 (0.1494 (0.1494 (0.1470 (0.1471 (0.1474 (0.1473 (0.147	S = 80. 9131 CAF 0.1487 0.1502 0.1553 0.1553 0.1555 0.1598 0.1598 0.1643 0.1643	194. 194. 194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306 0.04 -0.0573 -0.48 -0.0896 -1.00 -0.1145 -1.52 -0.1428 -2.03 -0.1683	RE PER HG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333 0.6403 0.7777 0.9456 1.0932	IN.= .48E00 2.9018 PSI CS -0.233E -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256 -0.2314 -0.2329 -0.2322 -0.2267	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.6521 1.7130 1.7260 1.7207	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063 0.0008 0.3066 0.0010 0.3041 0.0011 0.3036 0.0004 0.3055 0.0004 0.3055 0.0018 0.3113 0.0013 0.3164	POJ/PT: 0. 0050369 CPB 0. 1616 6 0. 1578 6 0. 1536 6 0. 1513 6 0. 1494 6 0. 1494 6 0. 1471 6 0. 1471 6 0. 1473 6 0. 1473 6 0. 1473 6 0. 1473 6 0. 1473 6	S = 80. 9131 CAF 0.1487 0.1502 0.1527 0.1553 0.1547 0.1555 0.1588 0.1588 0.1643 0.1679 0.1657	194. 194. 194. 194. 194. 194. 194. 194.
G= 8.13 PSI PO= 118.0 CP ALPHA CN 4.19 0.2028 3.16 0.1288 2.12 0.0601 1.59 0.0262 1.08 -0.0033 0.55 -0.0306 0.04 -0.0573 -0.48 -0.0896 -1.00 -0.1145 -1.52 -0.1428	RE PER HG PTS= CM -1.2841 -0.7614 -0.2928 -0.0699 0.1144 0.2766 0.4333 0.6403 0.7777 0.9456 1.0932 1.4586	IN.= .48E00 2,9018 PSI CS -0.2327 -0.2255 -0.2274 -0.2243 -0.2197 -0.2256 -0.2314 -0.2329 -0.2322	CY 1.7148 1.7070 1.6409 1.6637 1.6345 1.5901 1.7130 1.7260 1.7207 1.6632 1.6368	90. DEG.F RUN NO CR CAT 0.0014 0.3103 0.0012 0.3080 0.0017 0.3063 0.0008 0.3066 0.0010 0.3041 0.0011 0.3036 0.0015 0.3066 0.0015 0.3066 0.0016 0.3056 0.0018 0.3113	POJ/PT: 0. 0050369 CPB 0.1616 6 0.1578 6 0.1536 6 0.1513 6 0.1494 6 0.1494 6 0.1471 6 0.1471 6 0.1473 6 0.1473 6 0.1473 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6 0.1474 6	S = 80. 9131 CAF 0.1487 0.1527 0.1527 0.1553 0.1547 0.1555 0.1588 0.1588 0.1643 0.1677	194. 194. 194. 194. 194. 194. 194.

	6.2 CON	FIG0000) HAI	CH 2.00)	PHI =	90.	
Q= 8.13	PSI RE PER	IN.= .48E0	6 T0=	90. DE	G.F	POJ/P1	rs =	•
PO= 118.	O CHHG PTS=	2.9018 PSI			RUN NO.	005036	59136	
ALPHA CN	CH.	cs	CY	CR	CAT	СРВ	CAF	RUN
4.12 0.20	00 -1.1580	-0.0191	0.1471-	0.0004	0.2892	0.1510	0.1382	199.
3.10 0.14	90 -0.8588	-0.0141	0.0966-	0.0008	0.2855	0.1478	0.1378	199.
2.07 0.09	76 -0.5563	-0.0150	0.1042-					199.
1.55 0.07		-0.0207	0.1633			0:1493		199.
1.03 0.04		-0.0165	0.1207					199.
0.51 0.02			-0.0018			0.1486		199.
-0.02 -0.00		-0.0201	0.1585-					199.
-0.54 -0.02		-0.0145	0.1032			-		199.
-1.05 -0.04		-0.0269	0.2273-					199.
-1.56 -0.07		-0.0095	0.0510					199.
-2.07 -0.09		-0.0172	0.1332					199.
-3.10 -0.14		-0.0108	0.0667					199.
-4.14 -0.19	90 1.1513	-0.0178	0.1346	00026	0.3050	0.1522	0.1528	199.
MODEL 94	6.2 CON	FIG. 20000	МА	CH 2,00)	PHI =	90.	
Q= 8.13	PSI RE PER	IN.= .48E0	6 TO=	90. DE	G.F	POJ/P1	rs = 1	0.
Q= 8.13 PC= 118.	-	IN.= .48E0				POJ/P1	_	0.
-	O CMHG PTS=						_	
PC= 118. ALPHA CN	O CMHG PTS=	2.9018 PSI	СУ	CR	RUN NO.	005036 CPB	59135 CAF	
PG= 118. ALPHA CN 4.13 0.20	0 CMHG PTS= cm 41 -1.1945	2.9018 PSI CS -0.0447	CY 0.3346-1	CR 0.0002	RUN NO. CAT 0.2868	005036 CPB 0.1520	0.1349	RUN
PG= 118. ALPHA CN 4.13 0.20 3.10 0.15	0 CMHG PTS= CM 41 -1.1945	2.9018 PSI CS -0.0447 -0.0410	СУ	CR 0.0002 0.0006	RUN NO. CAT 0.2868 0.2859	CPB 0.1520 0.1520	0.1349 0.1340	RUN 198.
PG= 118. ALPHA CN 4.13 0.20	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492	2.9018 PSI CS -0.0447	CY 0.3346-0 0.2984-0	CR 0.0002 0.0006 0.0007	RUN NO. CAT 0.2868 0.2859 0.2856	CPB 0.1520 0.1520 0.1516	0.1349 0.1340 0.1340	RUN 198. 198.
PG= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829	2.9018 PSI CS -0.0447 -0.0410 -0.0313	CY 0.3346-1 0.2984-0 0.2014-1	CR 0.0002 0.0006 0.0007 0.0001	RUN NO. CAT 0.2868 0.2859 0.2856 0.2865	CPB 0.1520 0.1520 0.1516 0.1514	0.1349 0.1340 0.1340 0.1352	RUN 198. 198. 198.
PG= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.2425	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404	CY 0.3346-1 0.2984-0 0.2014-0	CR 0.0002 0.0006 0.0007 0.9001 0.0004	RUN NO. CAT 0.2868 0.2859 0.2856 0.2865 0.2873	005036 CPB 0.1520 0.1520 0.1516 0.1514 0.1508	0.1349 0.1340 0.1340 0.1352 0.1365	RUN 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.2425 02 -0.1056	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481	CY 0.3346-1 0.2984-1 0.2014-1 0.2936 (CR 0.0002 0.0006 0.0007 0.0001 0.0004 0.0001	RUN NO. CAT 0.2868 0.2859 0.2856 0.2865 0.2873 0.2877	005036 CPB 0.1520 0.1520 0.1516 0.1514 0.1508 0.1503	0.1349 0.1340 0.1340 0.1352 0.1365 0.1375	RUN 198. 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04 0.51 0.02	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.2425 02 -0.1056 46 0.0362	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481 -0.0373	CY 0.3346-1 0.2984-0 0.2014-0 0.2936-0 0.3743-0 0.2621 0.2222-0 0.2663-0	CR 0.0002 0.0006 0.0007 0.0001 0.0004 0.0001 0.0003	CAT 0.2868 0.2859 0.2856 0.2865 0.2873 0.2877 0.2883 0.2890	CPB 0.1520 0.1520 0.1516 0.1514 0.1508 0.1503 0.1501 0.1499	CAF 0.1349 0.1340 0.1340 0.1352 0.1365 0.1375 0.1382 0.1391	RUN 198. 198. 198. 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04 0.51 0.02 -0.02 -0.00 -0.53 -0.02 -1.05 -0.05	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.2425 02 -0.1656 46 0.0362 90 0.1770 45 0.3255	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481 -0.0373 -0.0373 -0.0375 -0.0373	CY 0.3346-1 0.2984-0 0.2014-0 0.2736-0 0.3743-0 0.2621 0.2222-0 0.2663-0 0.7677	CR 0.0002 0.0006 0.0007 0.0001 0.0004 0.0003 0.0003	CAT 0.2868 0.2859 0.2856 0.2873 0.2877 0.2883 0.2890 0.2890	CPB 0.1520 0.1520 0.1516 0.1514 0.1508 0.1503 0.1501 0.1499 0.1499	0.1349 0.1340 0.1340 0.1340 0.1352 0.1365 0.1375 0.1382 0.1391 0.1397	RUN 198. 198. 198. 198. 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04 0.51 0.02 -0.02 -0.00 -0.53 -0.02 -1.05 -0.05 -1.57 -0.08	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.2425 02 -0.1056 46 0.0362 90 0.1770 45 0.3255 04 0.4773	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481 -0.0373 -0.0375 -0.0375 -0.0378	CY 0.3346-1 0.2984-0 0.2014-1 0.2936-1 0.3743-1 0.2621-1 0.2222-1 0.2663-1 0.7677-1 0.2713-1	CR 0.0002 0.0006 0.0007 0.0004 0.0003 0.0003 0.0003	CAT 0.2868 0.2859 0.2856 0.2857 0.2873 0.2873 0.2883 0.2890 0.2890	CPB 0.1520 0.1520 0.1516 0.1514 0.1503 0.1501 0.1499 0.1493 0.1485	CAF 0.1349 0.1340 0.1340 0.1352 0.1365 0.1375 0.1382 0.1391 0.1397 0.1432	RUN 198. 198. 198. 198. 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04 0.51 0.02 -0.02 -0.00 -0.53 -0.02 -1.05 -0.05 -1.57 -0.08 -2.07 -0.10	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3255 02 -0.1056 46 0.0355 90 0.1770 45 0.3255 04 0.4773 44 0.6197	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481 -0.0373 -0.0373 -0.0375 -0.0373	CY 0.3346-1 0.2984-0 0.2014-1 0.2936 (0.3743-1 0.2621 (0.2621 (0.2663-1 0.2663-1 0.2713 (0.2691 (CR 0.0002 0.0006 0.0007 0.0001 0.0003 0.0003 0.0007	CAT 0.2868 0.2859 0.2856 0.2853 0.2877 0.2883 0.2890 0.2890 0.2890	CPB 0.1520 0.1520 0.1516 0.1514 0.1508 0.1503 0.1501 0.1499 0.1493 0.1485 0.1489	0.1349 0.1349 0.1340 0.1340 0.1352 0.1365 0.1375 0.1382 0.1391 0.1397 0.1432 0.1455	RUN 198. 198. 198. 198. 198. 198. 198. 198.
PC= 118. ALPHA CN 4.13 0.20 3.10 0.15 2.07 0.09 1.53 0.06 1.01 0.04 0.51 0.02 -0.02 -0.00 -0.53 -0.02 -1.05 -0.05 -1.57 -0.08	0 CMHG PTS= CM 41 -1.1945 02 -0.8682 67 -0.5492 86 -0.3829 42 -0.1656 00 -1770 45 0.3255 04 0.4773 44 0.6197	2.9018 PSI CS -0.0447 -0.0410 -0.0313 -0.0404 -0.0481 -0.0373 -0.0375 -0.0375 -0.0378	CY 0.3346-0 0.2984-0 0.2014-0 0.2733-0 0.3743-0 0.2621-0 0.2222-0 0.2663-0 0.7677-0 0.2713-0	CR 0.0002 0.0006 0.0007 0.0004 0.0001 0.0003 0.0003 0.0007 0.0011 0.0016	CAT 0.2868 0.2859 0.2856 0.2865 0.2877 0.2883 0.2890 0.2890 0.2917 0.2944 0.2997	CPB 0.1520 0.1520 0.1516 0.1514 0.1508 0.1503 0.1501 0.1499 0.1493 0.1485 0.1489 0.1506	0.1349 0.1349 0.1340 0.1352 0.1352 0.1365 0.1375 0.1382 0.1391 0.1397 0.1432 0.1455 0.1491	RUN 198. 198. 198. 198. 198. 198. 198.

TOWN THE PROPERTY OF THE PROPE

MODEL 946.2	CONFIG	0000 HA	CH 2.CO	PHI = 90	l -
Q= 8.13 PSI	RE PER IN. = .	48E06 T0≂	90. DEG.F	P0J/PTS =	20.
PO= 118.0 CH	HG PTS= 2.9018	PSI .	RUN NO.	. 0050369134	•
ALPHA CN	CM ES	CY	CR CAT	CPB CAF	RUN
	1 2524 0 040	3 0 E014	n.0006 D.2893	0 1542 0 12	51 197.
4.13 0.2107 3.10 0.1540	-1.2524 -0.0683 -0.8994 -0.0646		0.0010 0.2863		
2.07 0.0983	-0.5605 -0.0649		0.0003 0.2862		
1.54 0.0710	-0.4000 -0.062		0.0005 0.2875		
1.01 0.0440	-0.2394 -0.052		0.0001 0.2894		
0.51 0.0203	-0.1038 -0.060		0.0901 0.2881		
-0.01 -0.0041	0.0342 -0.060	1 0.4221-	0.0006 0.2928	0.1504 0.14	24 197.
-0.53 -0.0299	0.1849 -0.051		0.0004 0.2926	0.1510 0.14	
-1.05 -0.0554	0.3316 -0.058	4 0.4063-	0.0007 0.2941		
-1.57 -0.0809	9.4792 -0.060			0:1505 0.14	
-2.07 -0.1060	0.6306 -0.058		0.0001 0.2974		
-3.12 -0.1603	0.9547 -0.066		0.0008 0.3002		
-4.14 -0.2171	1.3058 -0.067	2 0.4961	0.0020 0.3062	0.1535 0.15	197.
MODEL 946.2			CH 2.00	PHI = 90	-
MODEL 946.2 Q= 8.13 PSI				PHI = 90	-
Q= 8.13 PSI		48E06 TO=	90. DEG.F		40.
Q= 8.13 PSI	RE PER IN.= .	48E06 TO=	90. DEG.F	POJ/PTS =	40 .
Q= 8.13 PSI PO= 118.0 CM ALPHA CN	RE PER IN.= . HG PTS= 2.9018 CM CS	48E06 TO=	90. DEG.F RUN NO CR CAT	POJ/PTS = - 0050369133 - CPB CAR	40. 3 = RUN
Q= 8.13 PSI PO= 118.0 CH ALPHA CN 4.13 C.2207	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126	48E06 TO= PSI CY 2 0.9342	90. DEG.F	POJ/PTS = . 0050369133 CPB CAE 0.1575 0.13	40. 3 = RUN 329 196.
Q= 8.13 PSI PO= 118.0 CH ALPHA CN 4.13 C.2207 3.11 0.1585	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117	48E06 TO= PSI CY 2 0.9342 3 0.8407	90. DEG.F RUN NO CR CAT 0.0001 0.2904	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13	40. 3 = RUN 329 196. 331 196.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204-	90. DEG.F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13	40. RUN 329 196. 331 196. 348 196.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 2 0.8031	90- DES-F RUN NO CR CAT 0-0001 0-2904 0-0002 0-2893 0-0006 0-2900 0-0007 0-2918	POJ/PTS = . 0050369133 CPB CA6 0.1575 0-13 0.1562 0-13 0.1552 0-13 0.1541 0-13 0.1530 0-13	40. RUN 329 196. 331 196. 348 196. 365 196. 388 196.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 2 0.8031 6 0.8506	90. DES.F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2905 0.0007 0.2918 0.0011 0.2925	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1541 0.13 0.1530 0.13 0.1520 0.14	40. RUN 329 196. 331 196. 348 196. 365 196. 388 196.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471	RE PER IN.= . SHG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 12 0.8031 16 0.8506 10 0.9152	90. DES.F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2905 0.0007 0.2918 0.0011 0.2925 0.0003 0.2946	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1541 0.13 0.1530 0.13 0.1520 0.14 0.1512 0.1512	40. 329 196. 331 196. 348 196. 365 196. 368 196. 40.
Q= 8.13 PS1 P0= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471 0.50 0.0213	RE PER IN.= . THG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113 -0.1144 -0.117 0.0222 -0.124 0.1320 -0.117	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 2 0.8031 6 0.8506 0 0.9152 1 0.8523-	90. DES.F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2905 0.0011 0.2925 0.0003 0.2946 0.0005 0.2951	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1541 0.13 0.1530 0.14 0.1512 0.14 0.1512 0.15	40. 329 196. 331 196. 348 196. 365 196. 368 196. 405 196. 434 196.
Q= 8.13 PS1 P0= 118.0 CF ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471 0.50 0.0213 -0.01 -0.0028 -0.54 -0.0301 -1.05 -0.0564	RE PER IN.= . THG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113 -0.1144 -0.117 0.0222 -0.124 0.1320 -0.117 0.3361 -0.124	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 2 0.8031 6 0.8506 0 0.9152 1 0.8523- 3 0.9195-	90. DES.F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2918 0.0011 0.2925 0.0003 0.2946 0.0005 0.2951 0.0010 0.2973	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1530 0.13 0.1520 0.14 0.1512 0.15 0.1515 0.14 0.1515 0.15	40. RUN 329 196. 331 196. 348 196. 388 196. 388 196. 405 196. 435 196. 463 196.
Q= 8.13 PS1 P0= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471 0.50 0.0213 -0.01 -0.0028 -0.54 -0.0301 -1.05 -0.0564 -1.57 -0.0826	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113 -0.1144 -0.117 0.0222 -0.124 0.1320 -0.117 0.3361 -0.124 0.4902 -0.118	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 2 0.8031 6 0.8506 0 0.9152 1 0.8523- 0 0.8596	90- DEG-F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2918 0.0011 0.2925 0.0003 0.2946 0.0005 0.2951 0.0010 0.2973 0.0008 0.2985	POJ/PTS = . 0050369133 CP8 CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1541 0.13 0.1520 0.14 0.1512 0.14 0.1515 0.14 0.1515 0.14 0.1517 0.150	40. RUN 329 196. 331 196. 348 196. 365 196. 388 196. 405 196. 4063 196. 4078 196.
Q= 8.13 PSI PO= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471 0.50 0.0213 -0.01 -0.0028 -0.54 -0.0301 -1.05 -0.0564 -1.57 -0.0826 -2.08 -0.1088	RE PER IN.= . THG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113 -0.1144 -0.117 0.0222 -0.124 0.1320 -0.117 0.3361 -0.124 0.4902 -0.118 0.6488 -0.120	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 6 0.8506 0 0.9152 1 0.8523- 1 0.8596 1 0.8596	90- DEG-F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2918 0.0011 0.2925 0.0003 0.2946 0.0005 0.2951 0.0010 0.2951 0.0010 0.2973 0.0008 0.2985 0.0012 0.3025	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1541 0.13 0.1530 0.13 0.1510 0.14 0.1510 0.15 0.1507 0.15 0.1508 0.15	40. RUN 329 196. 331 196. 348 196. 365 196. 388 196. 435 196. 435 196. 436 196. 437 196.
Q= 8.13 PS1 P0= 118.0 CM ALPHA CN 4.13 C.2207 3.11 0.1585 2.07 0.1032 1.51 0.0733 1.02 0.0471 0.50 0.0213 -0.01 -0.0028 -0.54 -0.0301 -1.05 -0.0564 -1.57 -0.0826	RE PER IN.= . HG PTS= 2.9018 CM CS -1.3410 -0.126 -0.9352 -0.117 -0.6003 -0.124 -0.4197 -0.116 -0.2642 -0.113 -0.1144 -0.117 0.0222 -0.124 0.1320 -0.117 0.3361 -0.124 0.4902 -0.118	48E06 T0= PSI CY 2 0.9342 3 0.8407 9 0.9204- 0 0.8316 6 0.8506 0 0.9152 1 0.8523- 1 0.8596 1 0.8596 1 0.8596 1 0.8596	90- DEG-F RUN NO CR CAT 0.0001 0.2904 0.0002 0.2893 0.0006 0.2900 0.0007 0.2918 0.0011 0.2925 0.0003 0.2946 0.0005 0.2951 0.0010 0.2973 0.0008 0.2985	POJ/PTS = . 0050369133 CPB CA6 0.1575 0.13 0.1562 0.13 0.1552 0.13 0.1552 0.13 0.1510 0.14 0.1510 0.14 0.1507 0.15 0.1516 0.13	40. RUN 329 196. 331 196. 348 196. 365 196. 388 196. 405 196. 434 196. 435 196. 436 196. 437 196. 547 196.

HOD	EL 946•2	CONI	FIG0000	H	ACH 2.00	0	PHI =	90.	
Q=	8.13 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	POJ/P	rs =	80.
P0=	118-9 CH	HG PTS=	2.9018 PSI			RUN NO	00503	69132	
ÂLPHA	CN	CH	cs	YS	CR	CAT	CPB	CAF	RUN
4.14 3.11	0.2396 0.1715	-1.5141 -1.0500				0.3002			
2.07	0.1086	-0.6449				0.2981			
1.54	0.0763	-0.4400	-0,2340	1.7110	0.0016	0.2973	0.1568	0.1405	195.
1.02	0.0475	-0-2627	~0.2332			0.2986			
0.49	0.0195	-0.0953	-0.2323			0.2985			
	-0.0057		-0.2433			0.3007			
_	-0.0330		-0.2438	_		0.3055			
	-0.0611		~0.2403			0.3047			
	-0.0899		-0.2308	_	_	0.2385			_
	-0.1197 -0.1826		-0.2400 -0.2378			0.3132	_		
	-0.1320 -0.2498		-0.2336			0.3156			
HOD	EL 946.2	CON	=1G0000	H	ACH 3.00	ß	PHI =	•	
_									
Q =	6.37 PSI	RE PER	IN.= .43E0	6 T0=	90. DI	EG.F	POJ/P	rs =	•
•			IN.= .43E00	6 TO=	90. DI		POJ/P	_	•
•			_	6 T0=	90. DI		. •	_	• RUN
P.O=	193.0 CM	HG PTS=	1.0109 PSf	CY	CR	RUN NO	. 00603	69105 CAF	
PO=	193.0 CM	HG PTS= CH -7.1281	1.0109 PSf	CY	CR -0.0022	RUN NO.	. 006036 CP8 0.1272	69105 CAF 0.1345	200.
PO= ALPHA 10.26	193.0 CMI CN 0.9447	CH -7.1281 -5.9024	1.0109 PS1 CS -0.0229	CY 0.1676- 0.1757- 0.1480-	CR -0.0022 -0.0011 -0.0015	CAT 0.2618 0.2562 0.2524	. 00603 CPS 0.1272 0.1262 0.1230	69105 CAF 0.1345 0.1301 0.1294	200 • 200 • 200 •
PO= ALPHA 10.26 9.24 8.20 7.16	193.0 CHI CN 0.9447 0.7958 0.6470 0.5194	HG PTS= CH -7.1281 -5.9024 -4.6654 -3.6279	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160	CY 0.1676- 0.1757- 0.1480- 0.1181-	CR -0.0022 -0.0011 -0.0015	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454	. 00603 CPS 0.1272 0.1262 0.1230 0.1188	CAF 0.1345 0.1301 0.1294 0.1265	200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12	193.0 CHI CN 0.9447 0.7958 0.6470 0.5194 0.4121	HG PTS= CH -7.1281 -5.9024 -4.6654 -3.6279 -2.7945	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942-	CR -0.0022 -0.0011 -0.0015 -0.	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143	69105 CAF 0.1345 0.1301 0.1294 0.1265 0.1255	200. 200. 200. 230. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09	193.0 CM CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228	HG PTS= CM -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752-	CR -0.0022 -0.0011 -0.0015 -0.	RUN NO. CAT 0.2618 0.2562 0.2554 0.2454 0.2397 0.2346	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095	69105 CAF 0.1345 0.1301 0.1294 0.1265 0.1255	200. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453	HG PTS= CM -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106 -0.0091	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002	RUN NO. CAT 0.2618 0.2562 0.25524 0.2454 0.2397 0.2346 0.2308	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 6.1053	CAF 0.1345 0.1301 0.1294 0.1265 0.1250 0.1251 0.1255	200. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779	HG PTS= CM -7.1281 -5.9024 -4.6654 -3.66279 -2.7945 -2.1362 -1.5883 -1.1389	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2308 0.2287	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1053 0.1023	CAF 0.1345 0.1301 0.1294 0.1265 0.1255 0.1255 0.1264	200. 200. 200. 230. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157	HG PTS= CH -7.1281 -5.9024 -4.6654 -3.6654 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081 -0.0063	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0529- 0.0458-	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002 -0.0012	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2308 0.2287 0.2272	. 00603 CPS 0.1272 0.1262 0.1230 0.1143 0.1095 0.1053 0.1023 0.1009	CAF 0.1345 0.1301 0.1294 0.1255 0.1255 0.1250 0.1250 0.1250	200. 200. 200. 230. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769	CH -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369	1.0109 PS1 CS -0.0229 -0.0221 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081 -0.0063 -0.0058	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0539- 0.0458- 0.0429-	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.003 0.0002 -0.0012 -0.0007	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2308 0.2287 0.2272 0.2280	. 00603 CPS 0.1272 0.1262 0.1230 0.1183 0.1095 0.1053 0.1023 0.1009 0.1009	CAF 0.1345 0.1301 0.1294 0.1265 0.1255 0.1255 0.1264 0.1263 0.1271	200. 200. 200. 230. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534	CH -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4670 -0.3355	1.0109 PS1 CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081 -0.0063 -0.0058 -0.0058	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0539- 0.0458- 0.0429- 0.0436-	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.003 0.0002 -0.0012 -0.0007 -0.0004 -0.0002	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2308 0.2287 0.2272 0.2280 0.2275	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1093 0.1009 0.1009 0.1009	CAF 0.1345 0.1301 0.1294 0.1265 0.1255 0.1255 0.1264 0.1263 0.1271 0.1265	200. 200. 200. 230. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769	-7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1369 -1.1389 -0.7369 -0.4670 -0.3355 -9.1817	1.0109 PS1 CS -0.0229 -0.0221 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081 -0.0063 -0.0058	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0529- 0.0458- 0.0429- 0.0436- 0.0352	CR -0.0022 -0.0011 -0.0015 -0.0026 -0.0002 -0.0012 -0.0007 -0.0004 -0.0002 0.0019	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2308 0.2287 0.2272 0.2280	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1053 0.1003 0.1009 0.1009 0.1010 0.1012	CAF 0.1345 0.1301 0.1294 0.1265 0.1255 0.1255 0.1264 0.1263 0.1271 0.1265 0.1249	200. 200. 230. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45 -0.07	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534 0.0275	-7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4670 -0.3355 -0.1817 0.1010	1.0109 PSf CS -0.0229 -0.0221 -0.0160 -0.0130 -0.0106 -0.0091 -0.0081 -0.0063 -0.0058 -0.0058 -0.0058	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0529- 0.0458- 0.0429- 0.0436- 0.0352 0.0294	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0002 -0.0012 -0.0007 -0.0004 -0.0002	RUN NO. CAT 0.2618 0.2562 0.2524 0.2454 0.2397 0.2346 0.2287 0.2272 0.2280 0.2275 0.2262	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1003 0.1003 0.1009 0.1010 0.1012 0.1012	CAF 0.1345 0.1301 0.1294 0.1265 0.1251 0.1255 0.1264 0.1263 0.1271 0.1265 0.1249	200. 200. 230. 200. 200. 200. 200. 200.
P.O= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45 -0.07 -0.58	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534 0.0275 -0.0122	-7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4675 -0.4675 -0.1817 0.1010 0.1626	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0106 -0.0091 -0.0063 -0.0058 -0.0058 -0.0058 -0.0059	CY 0.1676- 0.1757- 0.1480- 0.1481- 0.0942- 0.0752- 0.0640 0.0529- 0.0458- 0.0429- 0.0436- 0.0352 0.0294 0.0309 0.0238	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002 -0.0012 -0.0007 -0.0004 -0.0002 0.0019 0.0003	RUN NO. CAT 0.2618 0.2562 0.2554 0.2397 0.2346 0.2308 0.2287 0.2270 0.2262 0.2262 0.2262 0.2268	. 00603 CPS 0.1272 0.1262 0.1230 0.1143 0.1095 0.1023 0.1009 0.1010 0.1010 0.1012 0.1016 0.1023 0.1038	CAF 0.1345 0.1301 0.1294 0.1255 0.1255 0.1256 0.1264 0.1263 0.1271 0.1264 0.1263 0.1273 0.1259	200. 200. 200. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45 -0.07 -0.58 -1.10 -1.61	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534 0.0275 -0.0122 -0.0279 -0.0582 -0.0851	HG PTS= CM -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4670 -0.3357 0.1010 0.1626 0.3571 0.5213	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0061 -0.0063 -0.0058 -0.0058 -0.0058 -0.0059 -0.0050 -0.0041 -0.0032 -0.0033	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0529- 0.0436- 0.0436- 0.0352 0.0352 0.0294 0.0309 0.0238 0.0257	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002 -0.0012 -0.0007 -0.0004 -0.0002 0.0019 0.0003 0.0024 0.0008 0.0015	RUN NO. CAT 0.2618 0.2562 0.2524 0.2397 0.2346 0.2308 0.2287 0.2272 0.2262 0.2270 0.2262 0.2268 0.2268	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1023 0.1009 0.1010 0.1012 0.1016 0.1023 0.1038 0.1047	CAF 0.1345 0.1301 0.1294 0.1255 0.1255 0.1251 0.1264 0.1263 0.1271 0.1259 0.1249 0.1230 0.1217	200. 200. 200. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45 -0.07 -0.58 -1.10 -1.61 -2.11	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534 0.0275 -0.0122 -0.0279 -0.0582 -0.0851 -0.1128	HG PTS= CM -7.1281 -5.9024 -4.6627 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4670 -0.3355 -0.1817 0.1010 0.1626 0.3571 0.5213 0.6970	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0063 -0.0063 -0.0058 -0.0058 -0.0058 -0.0059 -0.0050 -0.0050 -0.0050	CY 0.1676- 0.1757- 0.1480- 0.0942- 0.0752- 0.0640 0.0939- 0.0436- 0.0352 0.0294 0.0309 0.0238 0.0257 0.0113	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0003 0.0002 -0.0012 -0.0004 -0.0002 0.0019 0.0003 0.0003 0.0003 0.0003	RUN NO. CAT 0.2618 0.2562 0.2524 0.2397 0.2346 0.2308 0.2287 0.2272 0.2260 0.2275 0.2262 0.2268 0.2263 0.2263 0.2285	. 00603 CPS 0.1272 0.1262 0.1230 0.1188 0.1143 0.1095 0.1023 0.1009 0.1010 0.1010 0.1012 0.1016 0.1023 0.1038 0.1047 0.1048	CAF 0.1345 0.1301 0.1294 0.1255 0.1255 0.1264 0.1263 0.1271 0.1259 0.1259 0.1264 0.1271 0.1259 0.1249 0.1230 0.1217	200. 200. 200. 200. 200. 200. 200. 200.
PO= ALPHA 10.26 9.24 8.20 7.16 6.12 5.09 4.06 3.03 2.00 1.46 0.96 0.45 -0.07 -0.58 -1.10 -1.61 -2.11 -3.14	193.0 CMI CN 0.9447 0.7958 0.6470 0.5194 0.4121 0.3228 0.2453 0.1779 0.1157 0.0769 0.0534 0.0275 -0.0122 -0.0279 -0.0582 -0.0851	HG PTS= CM -7.1281 -5.9024 -4.6654 -3.6279 -2.7945 -2.1362 -1.5883 -1.1389 -0.7369 -0.4670 -0.3357 0.1010 0.1626 0.3571 0.5213	1.0109 PSf CS -0.0229 -0.0221 -0.0194 -0.0160 -0.0130 -0.0063 -0.0063 -0.0058 -0.0058 -0.0058 -0.0058 -0.0059 -0.0050 -0.0041 -0.0032 -0.0033 -0.0015 0.0026	CY 0.1676- 0.1757- 0.1480- 0.1181- 0.0942- 0.0752- 0.0640 0.0529- 0.0436- 0.0436- 0.0352 0.0352 0.0294 0.0309 0.0238 0.0257	CR -0.0022 -0.0011 -0.0015 -00.0026 -0.0002 -0.0012 -0.0007 -0.0004 -0.0002 0.0019 0.0003 0.0003 0.0015 0.0013	RUN NO. CAT 0.2618 0.2562 0.2524 0.2524 0.2397 0.2346 0.2308 0.2287 0.2272 0.2260 0.2275 0.2262 0.2262 0.2268 0.2263 0.2263 0.2285 0.2313	. 00603 CPS 0.1272 0.1262 0.1230 0.1035 0.1053 0.1009 0.1009 0.1010 0.1012 0.1012 0.1012 0.1013 0.1023 0.1023 0.1047 0.1048 0.1046	CAF 0.1345 0.1301 0.1294 0.1255 0.1251 0.1255 0.1264 0.1263 0.1271 0.1269 0.1249 0.1237 0.1237 0.1267	200. 200. 200. 200. 200. 200. 200. 200. 200. 200. 200. 200. 200. 200.

MODFL 946.2	CONFIG	0000 MACH 3-00	= 1H9	•
Q= 6.37 PSI	RE PER IN	48E96 TO# 90. DI	EG.F POJ/P	rs = 10.
PO= 193.0 CM	HG PTS= 1.0109	PSI	RUN ND. 006036	99406
ALPHA CN	CH CS	CY CR	CAT CPB	CAF RUN
10.26 0.9166	-6.8840 -0.028	2 0.2302-0.0028	0-2644 0-1296	0.1388 201.
9.23 0.7718	-5.6963 -0.021	8 0.1703-0.0022	0.2613 0.1247	0.1366 201.
8.19 0.6280	-4.5097 -0.014		0.2547 0.1220	
7-15 0.5038	-3.5089 -0.009		0.2512 0.1186	
6.12 0.3991	-2.7038 -0.006		0.2455-0.1141	
5.08 0.3172	-2.0678 -0.005		0.2411 0.1099	
4.05 0.2355	-1.5297 -0.003			
3.02 0.1691	-1.6907 -0.001		0.2352 0.1042	
1.99 0.1060	-0.6773 0.	-0.0116 0.0004		
1.47 0.0723	-0.4574 0.001			
0.96 0.0472	-0.3119 0.002			
0.44 0.6186	-0.1306 0.002			
-0.08 -0.0133	0.0859 0.003			
-0.58 -0.0368	0.2193 0.004			
-1.10 -0.0619	0.3630 0.005			
-1.62 -0.0922 -2.12 -0.1207	0.5597 0.006			
-3.14 -0.1787				
-4.17 -0.2443	1.5467 0.010			
-4.17 -0.2443	1.5401 0.010	7 -0.0891 0.0015	0.2334 0.1055	0.2297 201.
MODEL 946.2 Q= 6.37 PSI	CONFIG RE PER IN.= .	0000 M/SH 3.00		• fs =
PO= 193.0 CF	HG PTS= 1.0109	PSI	KUN NO. 00603	59107
ALPHA CN	CH CS	CY CR	CAT CP8	CAF RUN
10.25 5.8924	-6.4813 -0.019	1 0-1487-0-0048	0.2686 0.1253	0.1433 202.
9.22 0.7453	-5.4723 -0.017		0.2613 0.1245	
8.19 0.6073	-4.3426 -0.011		0.2589 0.1225	
7.15 0.4873	-3.3878 -0.007		0.2518 0.1191	
6.11 0.3844	-2.5991 -0.004		0.2461 0.1146	
5.08 0.3000	-1.9885 -0.002			
4.05 0.2225	~1.4441 -0.001			
3.02 0.1552	-0.9940 -0.000			
2.00 0.0956	-0.6127 0.001			
1.46 0.0560	-0.3330 0.002			
0.97 0.0359	-0.2343 0.004			
0.44 0.0099	-0.0812 0.004			
-0.07 -0.0279	0.1988 0.004			
-0.59 -0.0582	0.3974 0.005			
-1.11 -0.0732	0.4390 0.006			
-1.63 -0.1068 -2.12 -0.1303	0.6650 0.007			
	0.8059 0.008			
3-150-1908 -4-18 -0-2547		4 -0.1117 0.0018	0.2321.0.1045.	0-1275202

HODEL 946.2	CONFIG.	.0000 MACH 3e0	0 PHE = .	
Q= 6.37 PSI	RZ PER IN.=	.48E06 YO= 90. 0	EG.F POJ/PTS =	46.
PO= 193.0 CF	IHG PTS= 1.010	129 FSI	RUN NO. 0069367108	
ALPHA CN	CH CS	CY CR	CAT CPB CAF	RUN
10.24 0.8539	-6.3649 -0.01	67 0 1157-D 0070	0.2656 0.1252 0.1404	203.
9.22 0.7101	-5.183E -0.01		0-2616 0-1244 C-1373	
8.17 0.5755	-4.0942 ~0.00		0.2601 0.1227 0.1374	
7.14 0.4598	-3.1850 -0.00		9.7529 0.1191 0.1339	
6.10 0.3610	-2.4394 -0.00		0.2498 0.1146 0.1351	
5.07 0.2759	-1.8236 -0.00		0.2437 0.1109 0.1328	
4.04 0.2009	-1.3008 -0.00		. 0.2408 G.1078 O.1330	
3.01 0.1353	-0.8643 0.00		0.2376 0.1051 0.1325	
1.99 0.0740	-0.4677 0.00		0.2361 0.1030 0.1331	
1.45 0.0369	-0.2094 0.00		0.2351 0.1024 0.1328	
0.94 0.0134	-0.0781 0.00		0.2355 0.1025 0.1330	
0.42 -0.0168	0.1230 0.00		0.2360 0.1028 0.1331	
-0.09 -0.0351	0.2036 0.00	81 -0.0843 0.0020	0.2345 0.1034 0.1311	203.
-0.60 -0.0671	0.4173 0.00	89 -0.0923 0.0008	0.2350 0.1037 0.1313	203.
-1.11 -0.0990	0.6319 0.00		0.2329 0.1047 0.1282	
-1.63 -0.1318	0.3558 0.00	48 -0.0979 0.0012	0.2335 0.1055 0.1280	203.
-2.14 -0.1519	0.9603 0.01		0.2337 0.1049 0.1288	
-3.15 -0.2107	1.3352 0.01		0.2321 0.1039 0.1281	
-4.18 -0.2746	1.7562 0.01	46 -0.1309 0.0020	0.2350 0.1048 0.1302	203.
MODEL 946.2 Q= 6.37 PS1	CONFIG.	.0000 MACH 3.0	_	00.
Q= 6.37 PS1		.48E06 TO= 90. D	_	00.
Q= 6.37 PS1	RE PER IN.=	.48E06 TO= 90. D 9 PSI	EG.F POJ/PTS = 1	00 . RUN
Q= 6.37 PS1 PU= 193.0 CM ALPHA CN	RE PER IN.= HG PTS= 1.010 CH CS	.48E06 TO= 90. D 9 PSI CY CR	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF	RUN
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482	RUN 204.
Q= 6.37 PS1 PU= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425	RUN 204 • 204 •
Q= 6.37 PS1 PU= 193.0 CF ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5623 -0.01 -3.5062 -0.01	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0925 01 0.0561-0.0021	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428	RUN 204. 204. 204.
Q= 6.37 PSI PU= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -9.01 -4.5623 -0.01 -3.5062 -0.01 -2.6604 -0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.0333-0.0017	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393	RUN 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3366 6.07 0.2938	RE PER IN.= "HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0925 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1393 0.2538 0.1143 0.1395	RUN 204. 204. 204. 204. 204.
Q= 6.37 PSI PU= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.033-0.0017 50 0.0186-0.0012 43 0.0166-0.007	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398	RUN 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PU= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0661-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0002 22 -0.0421-0.0006	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1393 0.2538 0.1143 0.1395	RUN 204. 204. 204. 204. 204. 204.
Q= 6.37 PSI PU= 193.0 CF ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0925 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0002 24 -0.00633 -0.0002	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2544 0.1085 0.1376	RUN 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0007 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1398 0.2511 0.1113 0.1398 0.2511 0.1113 0.1398 0.2415 0.1057 0.1376	RUN 204. 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 -0.0438 0.00	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0925 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0012 24 -0.0627 0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2464 0.1085 0.137 0.2415 0.1057 0.1358 0.2399 0.1033 0.1368	RUN 204. 204. 204. 204. 204. 204. 204. 204.
0= 6.37 PSI PU= 193.0 CP ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 -0.4478 0.00 -0.1356 0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.033-0.0017 50 0.0186-0.0012 43 0.0166-0.0012 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1398 0.2511 0.1113 0.1398 0.2511 0.1113 0.1398 0.2516 0.1085 0.1377 0.2415 0.1085 0.1377 0.2415 0.1085 0.1366 0.2399 0.1038 0.1368	RUN 204. 204. 204. 204. 204. 204. 204. 204.
0= 6.37 PSI P0= 193.0 CP ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730 -0.12 -0.1135	RE PER IN.= HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 -0.4478 0.00 0.1356 0.00 0.3782 0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0007 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002 88 -0.0953-0.0025 78 -0.0865 G.0014	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2511 0.1113 0.1398 0.2464 0.1085 0.1377 0.2415 0.1057 0.1358 0.2399 0.1033 0.1366 0.2395 0.1028 0.1368 0.2395 0.1024 0.1368	RUN 204. 204. 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730	RE PER IN.= "HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.5062 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.9741 -0.00 -1.9741 0.00 -0.4947 0.00 0.3782 0.00 0.3782 0.00 0.4954 0.00	.48E06 TO= 90. D 9 PSI CY CR 31 0.0947-0.0029 10 0.0561-0.0021 70 0.0333-0.0017 50 0.0166-0.0012 43 0.0166-0.0007 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0859 0.0002 80 -0.0953-0.0015 78 -0.0865 0.0014 87 -0.0918-0.0010	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2464 0.1085 0.1370 0.2415 0.1057 0.1358 0.2399 0.1033 0.1366 0.2395 0.1028 0.1368 0.2378 0.1022 0.1355	RUN 204. 204. 204. 204. 204. 204. 204. 204.
0= 6.37 PSI P0= 193.0 CP ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730 -0.12 -0.1135	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -2.6604 -0.00 -1.4088 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 0.1356 0.00 0.3782 0.00 0.43782 0.00 0.47971 0.00	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0012 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002 88 -0.0953-0.0015 78 -0.0865 0.0014 87 -0.0918-0.0010 00 -0.1030 0.0019	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2464 0.1085 0.137° 0.2415 0.1057 0.1358 0.2399 0.1034 0.1358 0.2395 0.1028 0.1368 0.2395 0.1028 0.1368 0.2396 0.1024 0.1368 0.2378 0.1024 0.1368 0.2378 0.1022 0.1355	RUN 204. 204. 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3366 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730 -0.12 -0.1345 -0.62 -0.1343 -1.14 -0.1603 -1.65 -0.1897	RE PER IN.= "HG PTS= 1.010 CH CS -5.7066 -0.01 -4.5523 -0.01 -3.55062 -0.00 -1.9741 -0.00 -1.9741 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.20 -0.4478 0.00 0.1356 0.00 0.3782 0.00 0.3782 0.00 0.4954 0.00 0.4954 0.00 0.7971 0.00 0.4954 0.01 1.0598 0.01	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0325 01 0.0561-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0002 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002 80 -0.0883 0.0002 81 -0.0953-0.0015 82 -0.0865 0.0014 83 -0.0953-0.0015 94 -0.0918-0.0010 95 -0.0018-0.0010 96 -0.0018-0.0010 97 -0.0018-0.0010 98 -0.0018-0.0010	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2511 0.1113 0.1398 0.2511 0.1085 0.1370 0.2415 0.1057 0.1358 0.2399 0.1033 0.1366 0.2395 0.1028 0.1368 0.2392 0.1024 0.1368 0.2392 0.1024 0.1368 0.2393 0.1022 0.1355 0.2394 0.1024 0.1370 0.2353 0.1027 0.1326 0.2353 0.1027 0.1355 0.2345 0.1027 0.1355	RUN 204. 204. 204. 204. 204. 204. 204. 204.
Q= 6.37 PSI PU= 193.0 CP ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3966 6.07 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730 -0.12 -0.1135 -0.62 -0.1343 -1.14 -0.1603 -1.14 -0.1603 -1.65 -0.1897 -2.16 -0.2166	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 -0.4478 0.00 0.1356 0.00 0.1356 0.00 0.3782 0.00 0.3782 0.00 0.4954 0.00 0.7971 0.00 0.9013 0.01 1.0598 0.01 1.2473 0.01	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0661-0.0021 70 0.0333-0.0017 50 0.0186-0.0012 43 0.0166-0.0006 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002 80 -0.0953-0.0015 78 -0.0953-0.0016 87 -0.0953-0.0013 88 -0.0953-0.0013 90 -0.1024 0.0010 100 -0.1024 0.0021 17 -0.1149 0.0004	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 9.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2464 0.1085 0.1377 0.2415 0.1057 0.1358 0.2399 0.1024 0.1368 0.2399 0.1024 0.1368 0.2392 0.1024 0.1368 0.2392 0.1024 0.1368 0.2393 0.1027 0.1368 0.2394 0.1024 0.1368 0.2395 0.1028 0.1369 0.2353 0.1027 0.1368 0.2357 0.1042 0.1355 0.2357 0.1042 0.1315	RUN 204. 204. 204. 204. 204. 204. 204. 204.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.21 0.7680 9.19 0.6284 8.15 0.4964 7.11 0.3366 6.07 0.2938 5.04 0.2137 4.01 0.1395 2.98 0.0731 1.95 0.0118 1.43 -0.0168 0.92 -0.0513 0.40 -0.0730 -0.12 -0.1345 -0.62 -0.1343 -1.14 -0.1603 -1.65 -0.1897	RE PER IN.= HG PTS= 1.010 CM CS -5.7066 -0.01 -4.5523 -0.01 -2.6604 -0.00 -1.9741 -0.00 -1.4088 -0.00 -0.8944 0.00 -0.4478 0.00 -0.4478 0.00 0.1356 0.00 0.1356 0.00 0.3782 0.00 0.3782 0.00 0.4954 0.00 0.7971 0.00 0.9013 0.01 1.0598 0.01 1.2473 0.01	.48E06 TO= 90. 0 9 PSI CY CR 31 0.0947-0.0029 10 0.0662-0.0025 01 0.0561-0.0021 70 0.033-0.0017 50 0.0186-0.0012 43 0.0166-0.0012 22 -0.0421-0.0006 35 -0.0533 0.0002 48 -0.0627 0.0007 80 -0.0883 0.0002 88 -0.0953-0.0015 78 -0.0865 0.0014 87 -0.0918-0.0010 00 -0.1030 0.0019 00 -0.1024 0.0021 32 -0.1279 0.0023 17 -0.1149 0.0004 48- -0.1374 0.0020	EG.F POJ/PTS = 1 RUN NO. 0060369109 CAT CPB CAF 0.2725 0.1243 0.1482 0.2658 0.1233 0.1425 0.2643 0.1215 0.1428 0.2571 0.1178 0.1393 0.2538 0.1143 0.1395 0.2511 0.1113 0.1398 0.2511 0.1113 0.1398 0.2511 0.1085 0.1370 0.2415 0.1057 0.1358 0.2399 0.1033 0.1366 0.2395 0.1028 0.1368 0.2392 0.1024 0.1368 0.2392 0.1024 0.1368 0.2393 0.1022 0.1355 0.2394 0.1024 0.1370 0.2353 0.1027 0.1326 0.2353 0.1027 0.1355 0.2345 0.1027 0.1355	RUN 204. 204. 204. 204. 204. 204. 204. 204.

			-					
MODEL 946	-2 CONF	IG0000) HAC	CH 3.00)	PHI =	15.	
Q= 6.37 P	SI RE PER	IN.= .48EC)6 TO≈	90. DE	G.F	POJ/P1	rs =	•
PO= 193.0	CMHG PTS≓	1.0109 PS1	•		RIIN: NO.	006036	0110	
			•					
ALPHA CN	CH.	CS	CY	CR	CAT	CPB	CAF	. RUN
4.07 0.238		-0.0040	0.0206-0	0.0009	0.2369	0.1030	C-1339	205.
3.05 0.175	0 -1.1081	-0.0037	0.0177-0	0.0015	0.2352	0.1018	2.1335	205.
2.03 0.113	2 -0.7082	-0.0033	0.0123-0	1000.0	0.2336	0-1011	0.1325	205.
1.49 0.079	9 -0.4949	-0.0025	0.0040-0					
0.97 0.053	2 -0.3328	-0.0029	0.0077	D. C009	0.2338	0.1013	0.1326	205.
0.47 0.025	0 -0.1550	-0.0047	9.0237					
-0.05 -0.002	6 0.0164	-0.0049	0.0243 (0.0011	0.2338	0.1020	0.1317	205.
-0.56 -0.029	6 0.1852	-0.0078	0.0459	0.0013	0.2376	0.1029	0.1347	205.
-1.08 -0.057	6 0.3546	-0.0038	0.0129	0.0013	0.2366	0.1044	0.130L	
-1.59 -0.087	1 0.5431.	-0.0039	.0.0139	0.0022	0.2368	0.1049	0.1319	
-2.09 -0.110	5 0.6809	-0.0036	0.0108	0.0016	C-2370	0.1049	0.1321	205.
-3.11 -0.174	3 1.1000	-0.0023	0.0003 (
-4.14 -0.239	2 1.5309	-0.0033	0.0081					
HODEL 946	•2 CONF	ig0000	AM C	CH 3.00	D	PHI =	15.	
Q= 6.37.P	SI RE PER	IN.= .48E0	06 TO=	90. Di	EG.F	P0J/P1	rs ≖	10.
PO=- 193.0	CMHG PTS=	1.0109 PS	Ţ.		RUN NO.	006036	59111	
ALPHA CN	CH	cs	GY	CR	CAT	CPB	CAF	RUN
4.07 0.228	1 -1.4710	-0.0026	-0.0010-0	0.0016	0.2427	0.1044	0.1382	206.
3.05 0.166	8 -1.0677	-0.0007	-0.0174-0	0.0010	0.2400	0.1034	0.1366	206.
2.02 0.104	0 -0.6564	0.0003	-0.0273-0	8000.0	0-2375	0-1028	0.1347	
1.50 0.072	9 -0.4599	-0.0003	-0.0199-	0.0004	0.2389	0.1024	0.1366	
0.99 0.048	3 -0.3097	0.0012	-0.03\$3 (1000.0	0.2392	0.1020	0.1371	206.
0.46 0.017	0 -0.1124	0.0011	-0.0355-					
-0.05 -0.010	8 0.0642	0.0013	-0.0360-1			0.1021		
-0.57 -0.038	6 0.2370	0.0015	-0.0364	0.0001				
-1.08 -0.067	3 0.4173	0.0020	-0.0424					
-1.59 -0.096		0.0021	-0.0440					
-2.10 -0.119	4 0.7369	0.0024	-0.0441					
-3.12 -0.181	0 1.1362	0.0052	-0.0661	0.0013	0.2443	0.1048	0.1396	
-4.14 -0.249	1 1.5952	0.0063	-0:0684	0.0026	0.2437	0.1062	0.1375	206.

MO	DEL 946.2	CGN	FIG60	ро м	ACH 3.00		PHI =	15.	
Q=	6.37 PSI	RE PER	IN.= .48	E06 T0=	90. DE	G.F	P0J/ P	rs =	20.
- PO:	= 193.0 CM	HG PTS=	1.0109 P	SI	1	RUN NO.	00603	69112	
ALPHA	CN	СМ	CS	CY	CR	CAT	СРВ	CAF	RUN
4-06	0.2167	~1.3944	-0.0067	0.G286	-0.0015	0.2459	0.1053	0-1406	207.
3,04			-0.0049		-0.0017				
2.02	0.0961	-0.6113	-0.0039	0.0035	-0.0011	0.2397	0.1030	0-1367	207.
1.50	0.0634	-0.4010	-0.0020	-0.0131	-0.0010	0.2412	0.1023	0.1369	207.
0.97			-0.0020		-0.0005				207.
0.47			-0.0011		-0.0008				207.
	-0.0200		-0.0014		-0.0007				
	-0.0458		-0.0049		0.0013				207.
	-0.0776	0.4877			0.0003				207.
	-0.1073	0.6757			0.0011				
	-0.1318	0.8245			0.0005				207.
	-0.1922	1.2151			0.0006				207.
-4.15	-0.2570	1.6424	0.0054	-0.0653	0.0015	0.2458	0.1055	0.1403	207.
моя	DEL 946.2	CON	FIG000	00 M	ACH 3.00		PHI =	15.	
(,	6.37 PSI	RE PER	IN.= .481	E06 TG=	90. DE	G•Ê	P0J/P1	rs =	40•
Р0:	= 193.0 CM	HG PTS=	1.0109 P	12	1	RUN NO.	00603	59113	
ALPHA	CN	CM.	cs	CY	CR	CAT	СРВ	CAF	RŲN
4.05	0.1991	-1-2871	-0.0146	0.0900-	-0.0013	0.2469	0.1058	0-1411	208.
3.03			-0.0112		-0.0034				208.
2.01		-0.4770	-0.0083		-0.0013				208.
1.47	0.0423	-0.2597	-0.0066		-0.0001				208.
0.97	0.0151	-0.0876	-0.0053		-0.0004				208.
:0.46	-0.0112	0.0757	-0.0042	-0.0083	0-0004	0.2403	0.1030	0.1373	208.
-0.06	-0.0387	0.2497	-0.0049		-0.0002				208.
	-0-0695	0.4496	-0.0097	0.0364	0.0004	0.2404	0.1039	0.1365	208.
-1.09	-0.0957	0.6053	-0.0028	-0.0199	0.0008	0.2415	0-1045	0.1370	208.
-	-0.1266		-0.0039		0.0005				208.
	-0.1503		-0.0026		0.0006				208.
	-0.2123		-0.0009		0.0023				208.
-4.15	-0.2768	1.7805	0.0025	-0.0514	0.0013	0.2441	0.1049	0.1392	208.

HOD	EL 946.2	CON	FIG. +000	00 HA	CH 3.0	0	PHY =	15.	
Q=	6.37 PSI	RE PER	IN.= .488	06 TO=	90. Di	EG.F	POJ/P	TS =	100.
PO=	193.0 0	MHG PTS=	1.0109 PS	XT.		RUN 'NO.	. 00603	69114	
	.,,,,,,		200207						
ALPHA	CN	CM	CS	ÇY	CR	CAT	CPB	CAF	RUN
4.02	0.1368	-0.8682	-0.0356	0.2486-	-G. UO19	0.2527	0.1068	0-145	9 209.
3.01	0.0763	-0.4657	-0.0299	0.1938-	0.0022	0.2473	0.1052	0.142	
1.98	0.0161	-0.0698	-0.0255			0.2437			
1.45	-0.0159	-0.0698 0.1414 0.3405	-0.0230	0.1284-	0.0023	0.2424	0.1025	0-140	0 209.
0.93	-0.0463	0.3405	-0.0230	0.1290-	0.0022	0.2447	0.1020	0.142	7 209.
0.42	-0.0736	0.5119	-0.0212	0.1121-	0.0021	0.2415	0.1021	0.139	4 209.
-0.09	-0.1017	0.6930	-0.0197	0.0999-	0.0002	0.2410	0.1025	0.138	5 209.
-0.60	-0.1328	0.8989	-0.0236	0.1355	0.0003	0.2406	0.1031	0.137	6 209.
-1.11	-0.1579	1.0486	-0.0203	0.1078		0.2409			
-1.63	-0.1890		-0.0209	0:1131	0.0002	0.2397	0-1034	0.136	3 209.
-2.13	-0.2142	1.4068	-0.0200	0.1071	0.0014	0.2399	0.1027	0.137	
	-0.2735		-0.0190			0.2399			
	-0.3372	2.2038	-0.0183	0.0948	0.0025	0.2453	0.1037	0.141	6 209.
-4-18			-0.0183 FIG000		0.0025 ICH 3.0		0.1037 PHI =		6 2U9.
-4-18 MOD	-0.3372	CON)O MA	ICH 3.00	υ		30.	
-4.18 · MOD: Q= ·	-0.3372 EL 946.2 6.37 PSI	CON	FIG000	00 MA E06 TO=	ICH 3.00	D EG• f	PHI =	30. TS =	
-4.18 · MOD:	-0.3372 EL 946.2 6.37 PSI	CON	FIGCOC	00 MA E06 TO=	ICH 3.00	D EG• f	PHI =	30. TS =	
-4.18 MOD: Q=	-0.3372 EL 946.2 6.37 PSI 193.0 C	CON RE PER MHG PTS=	FIG000 IN.= .48E 1.0109 PS	00 MA E06 TO= SI CY 0.0153-	90. D	O EG.F RUN NO CAT 0.2112	PHI = POJ/P 007036 CP8	30. TS = 69102 CAF 0.107	• RUN 9 210•
-4.18 MODE Q= PO= ALPHA 3.94	-0.3372 EL 946.2 6.37 PSI 193.0 C	CON RE PER MHG PTS= CM -1.5024	FIG000 IN.= .48E 1.0109 PS CS	00 MA E06 TO= SI CY 0.0153- 0.0085-	CR -0.0033	0 EG.F RUN NO. CAT 0.2112 0.2082	PHI = POJ/P 007036 CP8 0.1033	30. TS = 69102 CAF 0.107 0.106	• RUN 9 210. 4 210.
MOD: Q= P0= ALPHA 3.94 2.92	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332	CON RE PER MHG PTS= CM -1.5024 -1.0794	FIG000 IN.= .48E 1.0109 PS CS -0.0061	00 MA E06 TO= SI CY 0.0153-	CR -0.0033	0 EG.F RUN NO. CAT 0.2112 0.2082	PHI = POJ/P 007036 CP8 0.1033	30. TS = 69102 CAF 0.107 0.106	• RUN 9 210. 4 210.
-4.18 MOD Q= PO= ALPHA 3.94 2.92 1.90	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697	CONI RE PER MHG PTS= CM -1.5024 -1.0794 -0.6924	FIG000 IN.= .48E 1.0109 PS CS -0.0061 -0.0048	00 MA E06 TO= SI CY 0.0153- 0.0085-	CR -0.0033	0 EG.F RUN NO. CAT 0.2112 0.2082 0.2071	PHI = POJ/P 007036 CPB 0.1033 0.1018 0.1009	30. TS = 69102 CAF 0.107 0.106	• RUN 9 210. 4 210. 2 210.
-4.18 MODE Q= PO= ALPHA 3.94 2.92 1.90 1.36	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092	CONI RE PER MHG PTS= CM -1.5024 -1.0794 -0.6924 -0.4205	FIG000 IN.= .48E 1.0109 PS CS -0.0061 -0.0048 -0.0032	00 MA 06 TO= SI CY 0.0153- 0.0085- -0.0034-	CR -0.0033 -0.0034 -0.0021 -0.0025	0 EG.F RUN NO. CAT 0.2112 0.2082 0.2071 0.2077	PHI = POJ/P 007036 CPB 0.1033 0.1018 0.1009 0.1009	30. TS = 69102 CAF 0.107 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210.
-4.18 MOD: Q= PO= ALPHA 3.94 2.92 1.90 1.36 0.85	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702	CONI RE PER CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354	FIG000 IN.= .48E 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079	00 MA 506 TO= SI CY 0.0153- 0.0085- -0.0034- 0.0442- -0.0242- -0.0001-	CR -0.0033 -0.0034 -0.0021 -0.0025 -0.0018	0 EG.F RUN NO. CAT 0.2112 0.2082 0.2071 0.2077 0.2069 0.2072	PHI = POJ/P . 007036 CPB . 0.1033 0.1018 0.1009 0.1009 0.1009 0.1012	30. TS = 69102 CAF 0.107 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210. 0 210. 0 210.
-4.18 MOD Q= PO= ALPHA 3.94 2.92 1.90 1.36 0.85 0.34	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702 0.0509	CON RE PER MHG PTS= CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354 -0.1434 0.0576	FIG000 IN.= .488 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0008	00 MA 00 TO= SI CY 0.0153- 0.0085- -0.0034- 0.0442- -0.0242-	CR -0.0033 -0.0034 -0.0021 -0.0025 -0.0018	0 EG.F RUN NO. CAT 0.2112 0.2082 0.2071 0.2077 0.2069 0.2072	PHI = POJ/P . 007036 CPB . 0.1033 0.1018 0.1009 0.1009 0.1009 0.1012	30. TS = 69102 CAF 0.107 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210. 0 210. 0 210.
-4.18 MOD Q= PO= ALPHA 3.94 2.92 1.90 1.36 0.85 0.34 -0.18	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702 0.0509 0.0213	CON RE PER MHG PTS= CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354 -0.1434 0.0576	FIG000 IN.= .488 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0008	00 MA 506 TO= SI CY 0.0153- 0.0085- -0.0034- 0.0442- -0.0242- -0.0001-	CR -0.0033 -0.0034 -0.0025 -0.0018 -0.0015 -0.0008	CAT 0.2112 0.2082 0.2071 0.2077 0.2069 0.2072 0.2084	PHI = POJ/P . 007036 CPB . 0.1033 0.1018 0.1009 0.1009 0.1009 0.1012 0.1016	30. TS = 69102 CAF 0.106 0.106 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210. 0 210. 0 210. 8 210.
-4.18 MOD Q= P0= ALPHA 3.94 2.92 1.90 1.36 0.85 0.34 -0.18 -0.68	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702 0.0509 0.0213 -0.0095	CON RE PER MHG PTS= CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354 -0.1434 0.0576	FIG000 IN.= .488 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0008	00 MA E06 T0= SI CY 0.0153- 0.00850.0034- 0.04420.0001- 0.0007-	CR -0.0033 -0.0034 -0.0025 -0.0018 -0.0018 -0.0018	CAT 0.2112 0.2082 0.2071 0.2079 0.2079 0.2072 0.2084 0.2087	PHI = POJ/P . 007036 CPB . 0.1033 0.1018 0.1009 0.1009 0.1009 0.1012 0.1016 0.1022	30. TS = 69102 CAF 0.107 0.106 0.106 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210. 0 210. 0 210. 8 210. 5 210.
-4.18 MOD Q= P0= ALPHA 3.94 2.92 1.90 1.36 0.85 0.34 -0.68 -0.68 -1.20	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702 0.0509 0.0213 -0.0095 -0.0429	CONI RE PER CM -1.5024 -1.0794 -0.6924 -0.4305 -0.3354 -0.1434 0.0576 0.2924 0.4100	FIG000 IN.= .488 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0008	00 MA E06 TO= SI CY 0.0153- 0.00850.0034- 0.04420.0201- 0.0007- 0.0304-	CR -0.0033 -0.0034 -0.0025 -0.0015 -0.008 -0.0013 -0.005	CAT 0.2112 0.2082 0.2071 0.2077 0.2069 0.2072 0.2084 0.2087 0.2084	PHI = POJ/P . 007036 CP8 . 0.1033 0.1018 0.1009 0.1009 0.1012 0.1016 0.1022 0.1033	30. TS = 69102 CAF 0.106 0.106 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 2 210. 9 210. 0 210. 8 210. 5 210.
-4.18 MOD Q= PO= ALPHA 3.94 2.92 1.90 1.36 0.85 0.34 -0.18 -0.68 -1.20 -1.71	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0702 0.0509 0.0213 -0.0429 -0.0655	CONI RE PER CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354 -0.1434 0.0576 0.2924 0.4100 0.5509 0.7122	FIG600 IN.= .486 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0029 -0.0029 -0.0052 -0.0058 0.0011 0.0016	00 MA E06 TO= SI CY 0.0153- 0.00850.0034- 0.04420.001- 0.0007- 0.03040.03070.0323-	CR -0.0033 -0.0034 -0.0025 -0.0018 -0.0005 -0.0008 -0.0008	CAT 0.2112 0.2082 0.2071 0.2069 0.2072 0.2084 0.2088 0.2099 0.2101	PHI = POJ/P . 007036 CP8 . 0.1033 0.1018 0.1009 0.1009 0.1012 0.1016 0.1016 0.1016 0.1016 0.1040 0.1041	30. TS = 69102 CAF 0.106 0.106 0.106 0.106 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 9 210. 0 210. 0 210. 5 210. 5 210. 9 210.
-4.18 MOD Q= PO= ALPHA 3.94 2.92 1.90 1.36 0.85 0.318 -0.68 -1.20 -1.71 -2.21	-0.3372 EL 946.2 6.37 PSI 193.0 C CN 0.2332 0.1697 0.1092 0.0509 0.0213 -0.0095 -0.0429 -0.0655 -0.0906	CONI RE PER CM -1.5024 -1.0794 -0.6924 -0.4205 -0.3354 -0.1434 0.0576 0.2924 0.4100 0.5509 0.7122	FIG600 IN.= .48E 1.0109 PS CS -0.0061 -0.0048 -0.0032 -0.0079 -0.0008 -0.0029 -0.0029 -0.0052 -0.0058 0.0011	00 MA E06 TO= SI CY 0.0153- 0.00850.0034- 0.04420.001- 0.0007- 0.03040.03070.0323-	CR -0.0033 -0.0034 -0.0025 -0.0018 -0.0005 -0.0008 -0.0008	CAT 0.2112 0.2082 0.2071 0.2069 0.2072 0.2084 0.2088 0.2099 0.2101	PHI = POJ/P . 007036 CP8 . 0.1033 0.1018 0.1009 0.1009 0.1012 0.1016 0.1016 0.1016 0.1016 0.1040 0.1041	30. TS = 69102 CAF 0.106 0.106 0.106 0.106 0.106 0.106 0.106 0.106	RUN 9 210. 4 210. 9 210. 0 210. 0 210. 5 210. 5 210. 9 210.

MO	DEL 946.2	CON	FIG000	AK O	сн 3•о́с	j.	PHI =	30.	
Q=	6.37 PSI	RE PĘR	IN.= .48E	06 T0=	90. DÉ	G.F	POJ/P	TS =	10-
P0=	= 193.0 CM	HG PTS=	1.0109 PS	I		RUN NO	. 00703	69103	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
3.94	0.2270	-1.4863	-0.0113	0.0523-					
2.92	0.1633		-0.0095	0.0438-					
1.89			-0.0064	0.0170-					
1:36		-0.4262	-0.0090	0.0449-					
0.86	0.0431	-0.2998	-0.0032	-0.0104-					
0.33	0.0137	-0.1130	-0.0057	0.0125-					
-0.18	-0.0113	0.0367	-0.0020	-0.0152-	0,0011	0-2218	0.1018	0-1200	211.
-0.69	-0.0405	0.2245	-0.0049	0.0099-	0.0098	0-2230	0.1031	0.1200	211.
-1.20	-0.0747	0.4608	-0.0042	0.0132-	0.0005	0-2251	0.1040	0.1211	211.
-1.72	-0.0972	0.5751	-0.	-0.0276-	0.0002	0.2244	0.1046	0.1198	211.
-2.23	-0.1221	0.7221	0.0001	-0.0267	G. 0006	0-2246	0.1041	0-1204	211.
-3.25	-0.1831	1.1160	0.0040	-0.0541	0.0011	0.2286	0.1041	0.1244	211.
-4.27	-0.2487	1.5545	0.0089	-0.0879	0.0016	0.2317	0.1059	0.1258	
	DEL 946•2		FIG000		CH 3.00		PHI =		
Q=	6.37 PSI	RE PER	IH.= .48E	06 TO=	90. DE	G.F	P0J/P7	rs =	20.
P0=	= 193.0 CM	HG PTS=	1.0109 PS	I		RUN NO.	. 00703	69104	
ALPHA	CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
3.93	0.2213	-1.4693	-0.0205	0.1241-	0-0027	6.2342	0.1049	0.1234	212.
2.91	0.1576		-0.0187	0.1103-					
1.89	_		-0.0144	0.0756-					
1.36	0.0658		-0.0116	0.0496-					
0.85			-0.0107	0.0423					
0.33	0.0042	• • • • • • • • • • • • • • • • • • • •	-0.0134	0.0723-					
	-G-0255		-0.0119	0.0661-					
	-0.0458		-0.0081	0.0277					
	-0,0728		-0.0096	0.0412	0.0008	0.2325	0.1041	0.1284	212.
	-0.1033		-0.0069	0.0218					
	-0.1267		-0.0060	0.0181					
	-0.1887		-0.0021	-0.0102					
	-0.2544		0.0013				0.1055		

MODEL 946.2	CONFIG.	. 0000 .	MACH 3.00	PHI =	30.	-
Q= 6.37 PSI	RE PER IN.	= .48E06	TO= 90. DE	G.F POJ/	PTS = 4,0.	
PO= 193.0 CM	IHG PTS= 1.0	109 PSI		RUN NO. 00703	69105	
ALPHA CN	CH	CS CY	Y CR	CAT CPB	CAF	RUN
3.92 0.2069	-1.3914 -0.	.0386 0.2	2709-0.0021	0.2398 0.105	0.1347	213.
2.90 0.1446	-0.9745 -0.	0308 0-1	1979-0-0012	0.2392 0.1030	0.1354	213.
1.88 0.0817	-0.5604 -0.	.0254 0.1	1503-0-0006	0:2371 0:1020	0.1345	213.
1.35 0.0462	-0.3186 -0.	.0260 0	1581-0.0003	0.2376 0.102	0.1355	213.
0.84 0.0197	-0.1608 -0.			0.2378 0.102		213.
0.32 -0.0147	0.0841 -0.		1456-0.0001	0.2381 0.1029		213.
-0.19 -0.0325	0.1588 -0.			0.2381 0.103		213.
-0.71 -0.0626	0.3503 -0.			D.2384 0.103		213.
-1.22 -0:0900	0.5194 -0.			0.2403 0.1030		213.
-1.73 -0.1242	0.7586 -0.			0.2390 0.1034		213.
-2.24 -0.1456	0.8708 -0.			0.2390 0.103		213.
-3.26 -0.2047	1.2461 -0.			0.2404 0.1034		213.
-4.29 -0.2723	1.6989 -0.	.0074 0.0	0269 G:0022	U.2454 0.1054	0.1400 2	213.
MODEL 946.2 Q= 6.37 PSI		48E06	MACH 3.00		= 30. PTS = 100.	
Q= 6.37 PSI		48E06	TG= 90. DE		PTS = 100.	
Q= 6.37 PSI	RE PER IN:	48E06	Ţ0= 90. DE	G.F POJ/	PTS = 100.	RUN
Q= 6.37 PSI PO= 193.0 CP	RE PER ING MHG PTS= 1.0	-= .48E06 D109 PSI CS CY	TO= 90. DE	G.F POJ/S Run no. 0070 Cat CPB	PTS = 100. 869106 CAF	
Q= 6.37 PSI P0= 193.0 CP	RE PER IN:	.= .48E06 D109 PST CS CY	TG= 90. DE Y CR 5771-0.0012	G.F POJ/6	PTS = 100. 869106 CAF 2 0-1394	214.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 3.90 0.1586	RE PER IN: MHG PTS= 1.0 CM -1.0852 -0.	48E06 D109 PSI CS CY .0788- 0.5	TG= 90. DE Y CR 5771-0.0012 4607-0.0014	G.F POJ/6 RUN NO. DO70: CAT CPB D.2446 0.105: 0.2423 0.1046	PTS = 100. 869106 CAF 2 0.1394 2	
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919	RE PER ING HHG PTS= 1.0 CM -1.0852 -0. -0.6237 -0.	48E06 0109 PSI CS CY .0788- 0.5 .0672 0.4	TG= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009	G.F POJ/6 RUN NO. 0070 CAT CPB 0-2446 0-105	PTS = 100. 669106 CAF 2 0.1394 3 0.1383 2 0.1379	214.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291	RE PER INC CM -1.0852 -0. -0.6237 -0. -0.2038 -0.	48E06 0109 PSI CS CY .0788- 0.5 .0672 0.4 .0587 0.5	TG= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010	G.F POJ/6 RUN NO. 00703 CAT CPB 0.2446 0.1053 0.2423 0.1041 0.2401 0.102	PTS = 100. 369106 CAF 2 0.1394 3 0.1383 1 0.1379 3 0.1398	214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016	RE PER INC CM -1.0852 -0. -0.6237 -0. -0.2038 -0. -0.0038 -0.	.= .48E06 0109 PSI .CS CY .0788 0.5 .0672 0.4 .0587 0.3 .0555 0.3 .0529 0.3	T0= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0011	G.F POJ/6 RUN NO. 00703 CAT CPB 0.2446 0.105 0.2423 0.104 0.2401 0.102 0.2412 0.101 0.2414 0.101	PTS = 100. 369106 CAF 2 0.1394 3 0.1398 3 0.1398 3 0.1398	214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340	RE PER INC CM -1.0852 -0. -0.6237 -0. -0.2038 -0. 0.2160 -0.	48E06 0109 PSI CS CY .0788 0.5 .0672 0.4 .0587 0.5 .0529 0.3 .0496 0.3	T0= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0011 3157 0.0010	G.F POJ/6 RUN NO. 00703 CAT CPB 0.2446 0.105 0.2423 0.104 0.2401 0.102 0.2412 0.101 0.2414 0.1019 0.2416 0.1019	PTS = 100. 369106 CAF 2 0.1394 3 0.1383 0.1379 3 0.1398 3 0.1398 3 0.1398 2 0.1389	214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340 0.30 -0.0618	RE PER ING CM -1.0852 -00.6237 -00.2038 -00.0038 -0. 0.2160 -0. 0.3891 -0. 0.5799 -0. 0.7609 -0.	48E060109 PSI0788-	TO= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0011 3157 0.0010	CAT CPB 0-2446 0-105 0-2423 0-102 0-2412 0-101 0-2414 0-101 0-2416 0-101 0-2416 0-101 0-2410 0-102 0-2404 0-102	PTS = 100. 369106 CAF 2 0.1394 3 0.1383 1 0.1379 3 0.1398 3 0.1398 2 0.1389 3 0.1378	214. 214. 214. 214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340 0.30 -0.0618 -0.22 -0.0913 -0.73 -0.1199 -1.24 -0.1490	RE PER ING CM -1.0852 -00.6237 -00.2038 -00.0038 -0. 0.2160 -0. 0.3891 -0. 0.5799 -0. 0.7609 -0. 0.9448 -0.	48E060109 PSI0788-	TO= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0010 3079 0.0010 3083 0.0013	CAT CPB 0-2446 0-105 0-2423 0-104 0-2401 0-101 0-2412 0-101 0-2414 0-101 0-2416 0-101 0-2410 0-102 0-2404 0-102 0-2407 0-1034	CAF CAF CAF CAF CO.1394 CO.1383 CO.1379 CO.1398 CO.1398 CO.1398 CO.1398 CO.1378 CO.1378	214. 214. 214. 214. 214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340 0.30 -0.0618 -0.22 -0.0913 -0.73 -0.1199 -1.24 -0.1490 -1.76 -0.1786	RE PER IN. CM -1.0852 -00.6237 -00.2038 -00.0038 -0. 0.2160 -0. 0.3891 -0. 0.5799 -0. 0.7609 -0. 0.9448 -0. 1.1328 -0.	48E06 0109 PSI CS CY 0788 0.5 0672 0.4 0587 0.5 0555 0.3 0529 0.3 0590 0.3 0590 0.3	TG= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0010 3079 0.0010 3083 0.0013 3022 0.0012	CAT CPB 0-2446 0-105 0-2423 0-104 0-2401 0-102 0-2412 0-101 0-2414 0-101 0-2410 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102	CAF CAF CAF CO.1394 CO.1383 CO.1379 CO.1379 CO.1398 CO.1398 CO.1378 CO.1378 CO.1378 CO.1378 CO.1378	214. 214. 214. 214. 214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340 0.30 -0.0618 -0.22 -0.0913 -0.73 -0.1199 -1.24 -0.1490 -1.76 -0.1786 -2.27 -0.2069	RE PER IN. CM -1.0852 -00.6237 -00.2038 -00.0038 -0. 0.2160 -0. 0.3891 -0. 0.5799 -0. 0.7609 -0. 0.9448 -0. 1.1328 -0. 1.3090 -0.	48E06 0109 PSI CS CY 0788 0.5 0672 0.4 0587 0.5 0555 0.3 0529 0.3 0501 0.3 05489 0.3 0485 0.3	TG= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0010 3079 0.0010 3083 0.0013 3022 0.0012 2977 0.0015	G.F POJ/6 RUN NO. 00703 CAT CPB 0.2446 0.105 0.2423 0.1041 0.2402 0.1013 0.2414 0.1013 0.2416 0.1013 0.2410 0.102 0.2404 0.102 0.2404 0.102 0.2404 0.102 0.2404 0.102 0.2403 0.102	CAF CAF CAF CO.1394 CO.1383 CO.1379 CO.1398 CO.1398 CO.1398 CO.1378 CO.1378	214. 214. 214. 214. 214. 214. 214. 214.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 3.90 0.1586 2.88 0.0919 1.86 0.0291 1.33 -0.0016 0.82 -0.0340 0.30 -0.0618 -0.22 -0.0913 -0.73 -0.1199 -1.24 -0.1490 -1.76 -0.1786	RE PER IN. CM -1.0852 -00.6237 -00.2038 -00.0038 -0. 0.2160 -0. 0.3891 -0. 0.5799 -0. 0.7609 -0. 0.9448 -0. 1.1328 -0.	48E06 0109 PSI CS CY 0788 0.5 0672 0.4 0587 0.5 0529 0.3 0496 0.3 0485 0.3 0485 0.3	TG= 90. DE Y CR 5771-0.0012 4607-0.0014 3808-0.0009 3561-0.0010 3334-0.0007 3078 0.0010 3079 0.0010 3083 0.0013 3022 0.0012 2977 0.0015 2853 0.0017	CAT CPB 0-2446 0-105 0-2423 0-104 0-2401 0-102 0-2412 0-101 0-2414 0-101 0-2410 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102 0-2404 0-102	CAF CAF CAF CO.1394 CO.1383 CO.1379 CO.1398 CO.1398 CO.1398 CO.1378 CO.1378 CO.1378 CO.1378 CO.1378 CO.1378	214. 214. 214. 214. 214. 214. 214. 214.

MOI	DEL 946.2	СОМ	FIG00	00 MACH 3.0	0 P	H1 = 45.	
Q=	6.37 PSI	RE PER	IN.= .48	E06 TO= 90. D	EG.F P	01/PTS =	•
PO:	= 193.0 CK	HG PTS=	1.0109 P	SI	RUN NO. 0	070369107	
ALPHA	CN	CM	ES	CY GR	CAT	CPB CAF	RUN
10.14	0.9462		-0.0128	0.0777-0.0042			
9.12	0.7952		-0.0117	0.0672-0.0046			
8.08	0.6451	-4.6587		0.0308-0.0043			
7.04	0.5178		-0.0060	0.0156-0.0041			
6.00 4.97	0.4077 0.3175	-2-1034	0.0019	-0.0192-0.0039 -0.0407-0.0034			
3.94	0.2395	-1.5533	0.0020	-0.0471-0.0032			
2.91	0.1702	-1.0861	0.0021	-0.0454-0.0022			
1.88	0.1117	-0.7199	0.0045	-0.0672-4.0023			
1.35	0.6740	-0.4609	0.0010	-0.0290-0.0029	0.2107 0.	1012 0-1095	
-0.83	0.0446	-0.2735	0.0011	-0.0261-0.0035	0.2108 0.	1013 0.1095	215.
0.32	0.0208	-0.1415	0.0041	-0.0567-0.0014			
	-0.0136		-0.0002	-0.0129-0.0013			
	-0.0419		-0.0010	0.0004-0.0004			
	-0.0662	0.4084	0.0036	-0.0457 0.0006			
	-0.0909 -0.1203	0.5480	0.0064 0.0102	-0.0704 0. -0.1013 0.0009		1034 0.1118	
	-0.1797	1.1177	0.0102	-0.1184 0.0005			
	-0.2467	1.5655	0.0160	-0.1440 0.0011			
мог	DEL 946.2	CONF	IG001	00 HACH 3-00	O PI	HI = 45.	
	DEL 946.2 6.37 PSI		FIG000				10.
Q=		RE PER	IN.= .480	E06 TG= 90. 0		DJ/PTS =	10.
Q=	6.37 PSI	RE PER	IN.= .480	E06 TG= 90. 0	EG.F P	DJ/PTS =	10. RUN
Q= PU-	6.37 PSI = 193.0 CM	RE PER'	IN.= .488 1.0109 PS	E06 TO= 90. 0! SI	EG.F PERUN NO. OF	DJ/PTS = DT0369108 CPB CAF	RUN
Q= PU- ALPHA	6.37 PSI = 193.0 CM	RE PER HG PTS= CM	IN.= .480 1.0109 P: CS -0.0247	E06 T0= 90. 08 SI CY CR 0.1945-0.0055 0.1762-0.0055	EG.F PF RUN NO. 00 CAT (0.2451 0. 0.2380 0.	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126	RUN 216. 216.
Q= PU- ALPHA 10.14 9.11 8:07	6.37 PSI = 193.0 CM CN 0.9181 0.7707 0.6256	RE PER' HG PTS= CM -6.9108 -5.6924 -4.4862	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201	CY CR 0.1945-0.0055 0.1762-0.0051	EG.F PF RUN NO. 00 CAT 0.2451 0. 0.2380 0. 0.2326 0.	DJ/PTS = D70369108 CPB CAF 1264 0-1187 1254 0-1126 1227 0-1049	RUN 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8:07 7.03	6.37 PSI = 193.0 CM CN 0.9181 0.7707 0.6256 0.5043	RE PER' HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045	EG.F PF RUN NO. 00 CAT 0.2451 0. 0.2380 0. 0.2326 0. 0.2296 0.	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1049 1196 0.1100	RUN 216. 216. 216.
Q= PU-1 ALPHA 10.14 9.11 8.07 7.03 6.00	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3963	RE PER HG PTS= CH -6.9108 -5.6924 -4.6482 -3.5281 -2.6928	IN-= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0098	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050	CAT (0.2451 0.0.2380 0.10.2326 0.0.2326 0.0.2246	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100	RUN 216. 216. 216. 216.
Q= PU-1 ALPHA 10.14 9.11 8.07 7.03 6.00 4.96	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3963 0.3069	RE PER' HG PTS= CM -0.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343	IN.= .480 1.0109 P: CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0038 -2.0047	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041	EG.F PI RUN NO. 01 CAT 0.2451 0. 0.2380 0. 0.2326 0. 0.2296 0. 0.2240 0. 0.2208 0.	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100 1161 0.1079 1125 0.1083	RUN 216. 216. 216. 216. 216.
Q= PU-1 ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3069 0.2293	RE PER HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0088 -3.0047 -0.0037	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0051	EG.F P RUN NO. 01 CAT 0. 0.2451 0. 0.2380 0. 0.2296 0. 0.2240 0. 0.2240 0. 0.2240 0.	0J/PTS = 070369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100 1161 0.1079	RUN 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93 2.90	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5063 0.3963 0.3069 0.2293 0.1607	RE PER' HG PTS= CM -6.9108 -5.6924 -4.4842 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0088 -2.0047 -0.0037 -0.0037	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0358-0.0033	EG.F P RUN NO. 0 CAT 0.2451 0.0.2380 0.0.2326 0.0.2296 0.0.2240 0.0.2240 0.0.2176 0.0.2176 0.0.2176 0.0.2169 0.0.2169 0.0.2169 0.0.2169 0.0.2169 0.0.2169	DJ/PTS = DT0369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100 1161 0.1079 1125 0.1083 1080 0.1096	RUN 216. 216. 216. 216. 216. 216. 216.
Q= PU-1 ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3069 0.2293	RE PER HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0088 -2.0047 -0.0037 -0.0037	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0051	EG.F P RUN NO. 0 CAT 0 0.2451 0. 0.2380 0. 0.2326 0. 0.2296 0. 0.2240 0. 0.2240 0. 0.2169 0. 0.2169 0.	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100 1161 0.1079 1125 0.1083 1080 0.1096 1041 0.1128	RUN 216. 216. 216. 216. 216. 216. 216.
Q= PU-1 ALPHA 10.14 9.11 7.03 6.00 4.96 3.93 2.90 1.87	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6266 0.5043 0.3069 0.2293 0.1607 0.1014	RE PER HG PTS= CH -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.6504	IN.= .486 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0098 -0.0047 -0.0037 -0.0009 -0.	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0358-0.0033 -0.0418-0.0030 -0.0418-0.0040	EG.F P RUN NO. 01 CAT 0.2451 0. 0.2380 0. 0.2396 0. 0.2296 0. 0.2296 0. 0.2276 0. 0.2176 0. 0.2169 0. 0.2153 0. 0.2173 0. 0.2165 0.	DJ/PTS = D70369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1109 1125 0.1083 1080 0.1096 1041 0.1128 1025 0.1127 1023 0.1150	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93 2.90 1.87 1.35 0.83	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3069 0.2293 0.1607 0.1014 0.0660 0.0352 0.0114	RE PER' HG PTS= CH -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.6504 -0.4181 -0.2159	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0098 -2.0047 -0.0037 -0.0009 -0. C.0001 -0.0019 0.0011	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0418-0.0030 -0.0418-0.0040 -0.0183-0.0023	EG.F P RUN NO. 0 CAT 0.2451 0.0.2380 0.0.2326 0.0.2240 0.0.2240 0.0.22176 0.0.2169 0.0.2169 0.0.2163 0.0.2163 0.0.2163 0.0.2163 0.0.2163 0.0.2173 0.0.2163 0.0.2173 0.0.2163 0.0.2173 0.0.2163 0.0.2173	DJ/PTS = DT0369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1099 1080 0.1099 1041 0.1128 1025 0.1127 1023 0.1150 1021 0.1144	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8:07 7.03 6.00 4.96 3.93 2.90 1.87 1.35 0.83 0.83 -0.20	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6266 0.5043 0.3963 0.3969 0.2293 0.1607 0.1014 0.0660 0.0352 0.0114 -0.0233	RE PER HG PTS= CH -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.6504 -0.4181 -0.2159 -0.9818 0.1610	IN.= .488 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0038 -2.0047 -0.0037 -0.0009 -0. C.0001 -0.0019 -0.0019 -0.0029	CY CR 0.1945-0.0055 0.1762-0.0055 0.1762-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0358-0.0033 -0.0418-0.0030 -0.0183-0.0040 -0.0183-0.0023 -0.0484-0.0018	EG.F PI RUN NO. 00 CAT 0.2451 0. 0.2380 0. 0.2326 0. 0.2296 0. 0.2260 0. 0.2169 0. 0.2169 0. 0.2173 0. 0.2173 0. 0.2165 0. 0.2173 0.	0J/PTS = 070369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1049 1196 0.1100 1161 0.1079 125 0.1083 1080 0.1096 1041 0.1128 1025 0.1127 1023 0.1150 1021 0.1153 1020 0.1172	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93 2.90 1.87 1.35 0.83 0.32 -0.20	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3063 0.3069 0.2293 0.1607 0.1014 0.0660 0.0352 0.0114 -0.0233 -0.0444	RE PER HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.6504 -0.4181 -0.2159 -0.0818 0.6664	IN.= .486 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0098 -0.0047 -0.0009 -0.0001 -0.0019 -0.0019 -0.0019 -0.0019 -0.0019 -0.0019	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0418-0.0030 -0.0418-0.0030 -0.0418-0.0040 -0.0183-0.0023 -0.0488-0.0018	CAT 0.2451 0.0.2326 0.0.2296 0.0.2240 0.0.2153 0.0.2153 0.0.2173 0.0.2165 0.0.2173 0	0J/PTS = 070369108 CPB	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93 2.90 1.87 1.35 0.32 -0.20 -0.70	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5063 0.3963 0.3069 0.2293 0.1607 0.1014 0.0650 0.0352 0.0114 -0.0233 -0.0444 -0.0761	RE PER' HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.4504 -0.4181 -0.2159 -0.0818 0.1610 0.2684 0.4763	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0038 -2.0047 -0.0037 -0.0009 -0. C.0001 -0.0019 0.0011 -0.0029 0.0034 0.0012	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0358-0.0033 -0.0418-0.0040 -0.0183-0.0023 -0.0484-0.0018 -0.00361-0.0020 -0.0651-0.0010 -0.0415-0.0010	EG.F P RUN NO. 01 CAT 0.2451 0. 0.2380 0. 0.2326 0. 0.2296 0. 0.2240 0. 0.2260 0. 0.2173 0.	DJ/PTS = DT0369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1100 1161 0.1079 1125 0.1083 1080 0.1096 1080 0.1198 1023 0.1150 1021 0.1153 1020 0.1174 1019 0.1153 1029 0.1173	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.00 4.96 3.93 2.90 1.87 1.35 0.83 -0.20 -0.70 -1.74	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5043 0.3069 0.2293 0.1607 0.1014 0.0660 0.0352 0.0114 -0.0233 -0.0444 -0.0761 -0.1048	RE PER HG PTS= CH -6.9108 -5.6924 -4.4528 -2.6928 -2.0343 -1.4877 -1.0268 -0.6504 -0.4181 -0.2159 -0.9818 0.1610 0.2684 0.4763 0.4763 0.6565	IN.= .488 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0037 -0.0037 -0.0001 -0.0019 -0.0011 -0.0029 -0.0034 -0.0032 -0.0007	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0418-0.0030 -0.0418-0.0040 -0.0183-0.0023 -0.0484-0.0018 -0.0036-0.0020 -0.0651-0.0010 -0.0415-0.0009	CAT 0.2451 0.0.2380 0.0.2326 0.0.2240 0.0.2240 0.0.2173 0	DJ/PTS = DT0369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1090 1101 0.1128 1025 0.1127 1023 0.1150 1021 0.1144 1019 0.1153 1020 0.1172 1029 0.1143 1034 0.1122	RUN 216. 216. 216. 216. 216. 216. 216. 216.
Q= PU- ALPHA 10.14 9.11 8.07 7.03 6.06 4.96 3.93 2.90 1.87 0.83 0.32 -0.20 -0.70 -1.22 -1.74 -2.24	6.37 PSI 193.0 CM CN 0.9181 0.7707 0.6256 0.5063 0.3963 0.3069 0.2293 0.1607 0.1014 0.0650 0.0352 0.0114 -0.0233 -0.0444 -0.0761	RE PER' HG PTS= CM -6.9108 -5.6924 -4.4862 -3.5281 -2.6928 -2.0343 -1.4877 -1.0268 -0.4504 -0.4181 -0.2159 -0.0818 0.1610 0.2684 0.4763	IN.= .480 1.0109 PS CS -0.0247 -0.0234 -0.0201 -0.0131 -0.0038 -2.0047 -0.0037 -0.0009 -0. C.0001 -0.0019 0.0011 -0.0029 0.0034 0.0012	CY CR 0.1945-0.0055 0.1762-0.0055 0.1410-0.0051 0.0765-0.0045 0.0304-0.0050 -0.0067-0.0041 -0.0120-0.0032 -0.0358-0.0033 -0.0418-0.0040 -0.0183-0.0023 -0.0484-0.0018 -0.00361-0.0020 -0.0651-0.0010 -0.0415-0.0010	CAT 0.2451 0.0.2380 0.0.2296 0.0.2296 0.0.2176 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2173 0.0.2193 0.0.2173 0.0.2193 0.0.2088 0	0J/PTS = 070369108 CPB CAF 1264 0.1187 1254 0.1126 1227 0.1099 1196 0.1000 1161 0.1079 1125 0.1128 1025 0.1127 1023 0.1150 1021 0.1144 1019 0.1153 1020 0.1172 1029 0.1172 1029 0.1143 1034 0.1122	RUN 216. 216. 216. 216. 216. 216. 216. 216.

MODEL 946.2	CONFIG0000	MACH 3-00	PHI = 45.	
Q= 6.37 PSI	RE PER IN48EC	6 10= 90. DEG.F	POJ/PTS = 20.	
PU= 193.0 CM	HG PTS= 1.0109 PSI	RUN NO	. C970369109	
				RUN
ALPHA CN	CM CS	CY CR CAY	CPB CAF	KUR
10.14 0.9092	-6.8436 -0.0314	0.2569-2.0055 0.2411		217. 217.
9.11 0.7605 8.07 0.8225	-5.6188 -0.0325 -4.4938 -0.0346	0.2639-0.0059 0.2376 0.2781-0.0061-0.2333		217.
7.03 0.5037	-3.5568 -0.0280	-0.2706-0.0044 0.2294		217.
5.99 0.3984	-2.7446 -0.0216	0.1415-0.0048 0.2246	0:1167 0:1079	217.
4.96 0.3087	-2.0824 -0.0173	0.0991-0.0040 0.2223		217.
3.93 0.2307	-1.5310 -0.0161	0.0856-0.0060 0.2200		217.
7.90 0.1649 1.87 0.1016	-1.0949 -0.0125 -0.6788 -0.0124	0:0504-0:0061 0:2184 0:0504-0:0043 0:2168		217. 217.
1.87 0.1016 1.35 0.0717	-0.4938 -0.0094	0.0206-0.0041 0.2186		217.
0.83 0.0424	-0.3062 -0.0093	0.0221-0.0043 0.2186		217.
0.31 .0.0110	-0.0973 -0.0107	0.0387-0.0038 0.2196	0.1024 0.1172	217.
-0.20 -0.0200	0.1077 -0.0148	0.0798-0.0025 0.2197		217.
-0.71 -0.0448	0.2496 -0.0108	0.0415-0.0042 0.2205		217.
-1.21 -0.0676	0.3806 -0.0088	0.0228-0.0010 0.2212 0.0311-0.0008 0.2222		217.
-1.74 -0.0959 -2.25 -0.1250	0.5512 -0.0095 0.73490.0085	0.0228-0.0003 0.2249		217.
-2.27 -0.1842	1:1134 -0.0042	-0.0134-0.0003 0.2275		217.
-4.29 -0.2501	1.5518 -0.0053	-0.0025-0.0004 0.2303		217.
MDDEL 946.2 Q≃ 6.37 PSI	CONFIG0000		PHI = 45.	
MODEL 946.2 Q= 6.37 PSI PO= 193.0 CP	RE PER IN.= .48E0	06 10= 90. DEG.F		
Q= 6.37 PSI	RE PER IN.= .48E0	06 10= 90. DEG.F	POJ/PTS = 40.	RUN
Q= 6.37 PSI PO= 193.0 CP ALPHA CN	RE PER IN.= .48EC HG PTS= 1.0109 PSI CM CS	06 TO= 90. DEG.F RUN NO CY CR CAT	POJ/PTS = 40. D. 0070369110 CPB CAF	
Q= 6.37 PSI PO= 193.0 CP	RE PER IN.= .48E0	06 10= 90. DEG.F I RUN NO	POJ/PTS = 40. 1. 0070369110 CPB CAF 2. 0.1262 0.1306	RUN 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119	RE PER IN.= .48E0 HG PTS= 1.0109 PS1 CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2548 0.5580-0.0055 0.2483	POJ/PTS = 40. 1. 0070369110 CPB CAF 2 0.1262 0.1306 0 0.1256 0.1293 7 0.1232 0.1255	218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955	RE PER IN.= .48EG HG PTS= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.25487 0.5580-0.0055 0.2483	POJ/PTS = 40. 1. 0070369110 CPB CAF 2. 0.1262 0.1306 0.1256 0.1293 0.1232 0.1255 0.1203 0.1245	218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 9.4955 5.99 0.3923	RE PER IN.= .48E0 CH CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2463 0.4760-0.0056 0.2463 0.3808-0.0049 0.2417	POJ/PTS = 40. 1. 0070369110 CPB CAF 0.1262 0.1306 0.1256 0.1293 0.1232 0.1255 0.1203 0.1245 0.1109 0.1248	218. 218. 218. 213. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027	RE PER IN.= .48EG SHG P7S= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429	06 TO= 90. DEG.F RUN NG CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2463 0.4760-0.0056 0.2445 0.3608-0.0049 0.2417 0.3027-0.0048 0.2376	POJ/PTS = 40. 1. 0070369110 CPB CAF 7 0.1262 0.1306 9 0.1256 0.1293 7 0.1232 0.1255 9 0.1130 0.1248 9 0.1130 0.1246	218. 218. 218. 213. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 9.4955 5.99 0.3923	RE PER IN.= .48E0 CH CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2463 0.4760-0.0056 0.2463 0.3808-0.0049 0.2417	POJ/PTS = 40. 1. 0070369110 CPB CAF 2. 0.1262 0.1293 3. 0.1232 0.1293 3. 0.1232 0.1245 9. 0.1109 0.1248 9. 0.1130 0.1246 9. 0.1080 0.1263	218. 218. 218. 213. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 9.2244	RE PER IN.= .48EG RHG PTS= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2449 0.4760-0.0056 0.2417 0.3027-0.0048 0.2376 0.2605-0.0043 0.2376	POJ/PTS = 40. 1. 0070369110 CPB CAF 2 0.1262 0.1306 0 0.1256 0.1293 0 0.1232 0.1255 0 0.1203 0.1245 0 0.1130 0.1246 0 0.1080 0.1263 0 0.1047 0.1287	218. 218. 218. 213. 218. 213. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0931	RE PER IN.= .48EG RHG PTS= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.66424 -0.0285 -0.4066 -0.0275	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2449 0.4760-0.0056 0.2417 0.3027-0.0048 0.2377 0.2605-0.0043 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2317	POJ/PTS = 40. 1. 0070369110 CP8 CAF 7 0.1267 0.1306 9 0.1256 0.1293 9 0.1232 0.1255 0 0.1203 0.1245 0 0.1199 0.1248 0 0.1190 0.1263 0 0.1047 0.1287 0 0.1030 0.1287	218. 218. 218. 213. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233	RE PER IN.= .48EG HG PTS= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0579 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327	06 TO= 90. DEG.F RUN NG CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0065 0.2549 0.5580-0.0055 0.2449 0.4760-0.0056 0.2449 0.3027-0.0048 0.2376 0.2605-0.0043 0.2346 0.1986-0.0037 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2316 0.2099-0.0031 0.2336	POJ/PTS = 40. 1. 0070369110 CPB CAF 2. 0.1262 0.1306 0.1256 0.1293 0.1232 0.1255 0.1203 0.1245 0.1149 0.1248 0.1130 9.1246 0.1080 0.1263 0.1047 0.1287 0.1030 0.1287 0.1032 0.1288 0.1023 0.1315	218. 218. 218. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 9.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037	RE PER IN.= .48EG CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0597 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327 -0.0001 -0.0303	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2569 0.5580-0.0055 0.2463 0.4760-0.0056 0.2463 0.3027-0.0048 0.2376 0.2605-0.0043 0.2343 0.1986-0.0037 0.2353 0.1613-0.0041 0.2317 0.1486-0.0037 0.2318 0.2049-0.0031 0.2338 0.1817-0.0036 0.2338	POJ/PTS = 40. 1. 0070369110 CPB CAF 7 0.1262 0.1306 10.1256 0.1293 10.1232 0.1255 10.1203 0.1245 10.1130 0.1246 10.1130 0.1246 10.1030 0.1263 10.1047 0.1287 10.1030 0.1287 10.1032 0.1315 10.1028 0.1315	218. 218. 218. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037 -0.20 -0.0326	RE PER IN.= .48EG CH CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0507 -2.0806 -0.0429 -1.5221 -0.0304 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327 -0.0001 -0.0303 0.1870 -0.0317	06 TO= 90- DEG.F RUN NG CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2549 0.5580-0.0055 0.2649 0.4760-0.0056 0.2449 0.3027-0.0048 0.2376 0.2605-0.0043 0.2336 0.1613-0.0041 0.2311 0.1486-0.0025 0.2316 0.2049-0.0031 0.2338 0.1817-0.0036 0.2338 0.19172-0.0036 0.2338	POJ/PTS = 40. 1. 0070369110 CP8 CAF 7 0.1267 0.1306 9 0.1256 0.1293 9 0.1232 0.1255 9 0.1203 0.1245 9 0.1190 0.1246 9 0.1190 0.1246 9 0.1080 0.1263 9 0.1047 0.1287 9 0.1022 0.1288 9 0.1023 0.1315 9 0.1028 0.1310 9 0.1028 0.1310	218. 218. 218. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 9.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037	RE PER IN.= .48EG CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0597 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327 -0.0001 -0.0303	06 TO= 90. DEG.F RUN NG CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2569 0.4760-0.0055 0.2469 0.3027-0.0048 0.2376 0.2605-0.0043 0.2376 0.2605-0.0043 0.2376 0.1986-0.0037 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2310 0.2049-0.0037 0.2335 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338	POJ/PTS = 40. 1. 0070369110 CPB CAF 2 0.1262 0.1306 0.1256 0.1293 0.1232 0.1255 0.1203 0.1245 0.1109 0.1248 0.1109 0.1248 0.1100 0.1263 0.1047 0.1287 0.1030 0.1287 0.1030 0.1287 0.1030 0.1287 0.1030 0.1287 0.1030 0.1315 0.1023 0.1315 0.1024 0.1316 0.1035 0.1317	218. 218. 218. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037 -0.20 -0.0326 -0.72 -0.0568 -1.23 -0.0839 -1.74 -0.1157	RE PER IN.= .48EG CH CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327 0.0001 -0.0303 0.1870 -0.0317 0.3208 -0.0259 0.4884 -0.0255 0.6945 -0.0277	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2569 0.5580-0.0055 0.2443 0.4760-0.0056 0.2443 0.3808-0.0049 0.2417 0.3027-0.0048 0.2376 0.2605-0.0043 0.2343 0.1986-0.0037 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2310 0.2049-0.0031 0.2338 0.1972-0.0026 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2336 0.1972-0.0040 0.2366 0.1392-0.0040 0.2366 0.1392-0.0020 0.2364	POJ/PTS = 40. 1. 0070369110 CPB CAF 7 0.1262 0.1306 9 0.1256 0.1293 9 0.1232 0.1255 9 0.1203 0.1245 9 0.1130 0.1246 0 0.1080 0.1263 9 0.1077 0.1287 9 0.1023 0.1287 9 0.1023 0.1315 9 0.1024 0.1322 9 0.1035 0.1319 9 0.1030 0.1319	218. 218. 218. 218. 218. 218. 218. 218.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037 -0.20 -0.037 -0.20 -0.0326 -0.72 -0.0839 -1.74 -0.1157 -2.25 -0.1385	RE PER IN.= .48EG RHG PTS= 1.0109 PSI CM CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4626 -0.0275 -0.1658 -0.0327 0.0001 -0.0303 0.1870 -0.0317 0.3208 -0.0259 0.4884 -0.0255 0.6945 -0.0277 0.8217 -0.0245	06 TO= 90. DEG.F RUN NG CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2547 0.5580-0.0055 0.2469 0.4760-0.0056 0.2449 0.3027-0.0048 0.2376 0.2605-0.0043 0.2343 0.1986-0.0037 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2318 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0036 0.2388 0.1972-0.0020 0.2344	POJ/PTS = 40. 1. 0070369110 CP8 CAF 1. 0.1262 0.1306 0.1256 0.1293 1. 0.1232 0.1255 0.1203 0.1245 0.1130 0.1246 1. 0.1080 0.1263 1. 0.1047 0.1287 1. 0.1020 0.1287 1. 0.1023 0.1315 1. 0.1023 0.1315 1. 0.1035 0.1317 1. 0.1035 0.1317 1. 0.1030 0.1317	218. 218. 213. 218. 218. 218. 218. 218. 218. 218. 218
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 10.13 0.8793 9.10 0.7422 8.06 0.6119 7.02 0.4955 5.99 0.3923 4.95 0.3027 3.92 0.2244 2.89 0.1544 1.87 0.0931 1.34 0.0580 0.83 0.0233 0.31 -0.0037 -0.20 -0.0326 -0.72 -0.0568 -1.23 -0.0839 -1.74 -0.1157	RE PER IN.= .48EG CH CS -6.5998 -0.0693 -5.4897 -0.0698 -4.4476 -0.0675 -3.5340 -0.0598 -2.7418 -0.0507 -2.0806 -0.0429 -1.5221 -0.0390 -1.0450 -0.0324 -0.6424 -0.0285 -0.4066 -0.0275 -0.1658 -0.0327 0.0001 -0.0303 0.1870 -0.0317 0.3208 -0.0259 0.4884 -0.0255 0.6945 -0.0277	06 TO= 90. DEG.F RUN NO CY CR CAT 0.5851-0.0065 0.2567 0.5886-0.0064 0.2569 0.5580-0.0055 0.2443 0.4760-0.0056 0.2443 0.3808-0.0049 0.2417 0.3027-0.0048 0.2376 0.2605-0.0043 0.2343 0.1986-0.0037 0.2335 0.1613-0.0041 0.2317 0.1486-0.0025 0.2310 0.2049-0.0031 0.2338 0.1972-0.0026 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2338 0.1972-0.0036 0.2336 0.1972-0.0040 0.2366 0.1392-0.0040 0.2366 0.1392-0.0020 0.2364	POJ/PTS = 40. 1. 0070369110 CPB CAF 2. 0.1262 0.1306 0.1256 0.1293 0.1232 0.1255 0.1203 0.1245 0.1149 0.1248 0.01130 0.1246 0.1080 0.1263 0.1047 0.1287 0.1022 0.1287 0.1022 0.1288 0.1023 0.1315 0.1028 0.1310 0.1028 0.1310 0.1035 0.1319 0.1035 0.1319 0.1035 0.1319 0.1030 0.1317 0.1030 0.1317 0.1030 0.1317 0.1030 0.1317 0.1030 0.1317	218. 218. 218. 218. 218. 218. 218. 218.

MODEL 946.2	CONFIG.	•0000 M	NEN 3.00	PHI = 49	5.
•			•		-
Q= 6.37 PSI	RE PER IN.	•48E06 TO=	90. DEG.F	POJ/PTS =	100.
PO= 193.0 Ci	HHG PTS= 1.010	9 PSI	RUN NO	. 007036911	l
ALPHA CN	CM- CS	CY	CR CAT	CPB CAI	RUN
10-11 0.8162	-6.1137 -0.15		-0.0065 0.2642		
9.08 0.6892	-5.1111 -0.15		-0.0063 0.2606		
8.04 0.5678	-4.159R -0.14		-0.0054 0.2550		
7.00 0.4525	-3.27.06 -0.12		-0.0059 0.2510		
5.97 0.3545	-2.5177 -0.11		0.0044 0.2477		
4.93 0.2644	-1.8460 -0.09		-0.0039 0.2434		
3.90 0.1829	-1.2517 -0.08		0.0027 0.2417		
2.87 0.1115	-0.7543 -0.07		0.0017 0.2381		
1.85 0.0445	-0.2902 -0.07		-0.0026 0.2371		
1.32 0.0056	-0.0220 -0.07		-0.0018 0.2365 -0.0027 0.2365		
0.80 -0.0216 0.29 -0.0578	0.1447 -0.96 0.4029 -0.07		0.0021 0.2383		
-0.24 -0.0769	0.4866 -0.06		-0.0012 0.2356		
-0.74 -0.1104	0.7185 -0.06		0.0008 0.2375		
-1.25 -0.1426	0.9360 -0.07		0.0003 0.2376		
-1.76 -0.1656	1.0591 -0.06		0.0013 0.2375		
-2.27 -0.1899	1.2003 -0.06		0.0013 0.2391		
-3.29 -0.2484	1.5661 -0.06		0.0035 0.2417		
-4-32 -0.3139	1.9982 -0.05		0.0015 0.2436		
,					
•		•			•
NODEL 946.2	CONFIG.	.0000 MA	ICH 3.00	PHI = 60)•
Q= 6.37 PSI	RE PER IN.=	.48E06 10=	90. DEG.F	POJ/PTS =	•
PO= 193.0 C	HG PTS= 1.010	9 PSI	RUN NO	. 0070369112	2
ALPHA CN	CM CS	CY	CR CAT	CPB CÂF	RUN
4.13 0.2417	-1.5479 -0.00	44 0-0129-	0.0021 0.2261	0-1046 0-12	215 220.
3.11 0.1776	-1.1199 -0.00		0.0021 0.2220		
2.08 0.1163	-0.7264 -0300		0.0016 0.2232		
1.55 0.0842	-0.5224 -0.00		0.0013 0.2231		
1.05 0.0582	-0.3664 -0.00		0.0004 0.2228		
0.53 0.0281	-0.1711 -0.00		0.0015 0.2270		
0.01 -0.0042	0.0453 -0.01	09 0.0844-	0.0004 0.2251	0.1019 0.12	220 •
-0.50 -0.0241	0.1411 0.00	15 -0.0377	0.0012 0.2245	0.1022 0.12	223 220.
-1.01 -0.0530	0.3209 -0.00		0.0005 0.2279		
-1.52 -0.0832	0.5158 -0.00		0.0009 0.2285		
-2.03 -0.1073	0.6575 0.00		0.0002 0.2281		
-3.06 -0.1686	1.0537 0.00		0.0014 0.2319		
-4.08 -0.2351	1.5018 0.00	44 -0.0512	0.0002 0.2348	0.1039 0.13	308 220.

MODEL 946.2	CONF	1G000Ô	AH	CH 3.00		FHI =	60.	
Q= 6.37 PSÎ	RE PER	IN-= .48E0	5 10=	90. DE	G.F	PCJ/P1	rs * .	10.
PO= 193.0 C	AHG PTS=	1.0109 PSI		1	RUN NO.	007036	9113	
ALPHA N	CH	CS	CY	CR	CAT	CPB	CAF	RÚN
4.13 0.2353	-1.5110	-0.0128	0.0630-	ข. 0028 <i>(</i>	0-2310	0.1055	0.1255	221.
3.11 0.1697	-1.0704	-0.0096	0.0344~	0-0024	0.2234	0.1038	0.1196	221,5
2.08 0.1092	-0.6815	-0.0093	0.0350-					221.
1.55 0.0763	-0.4693	-0.0082	0.0234-					222.
1.04 0.0499	-0.3110		.0.0015-					221.
0.52 0.0215	-0:1308		0.0173-					221.
0.01 -0.0035	0.0131		-0.0249					221.
-0.51 -0.0395	0.2684			0.0011				221.
-1.02 -0.0633	0.3975		0.0280					
-1.53 -0.0910	0.5630		0.0363-					
-2.03 -0.1154	0.7237		0.0015-					
-3.06 -0.1764	1.1042		-0.0111					221.
-4.08 -0.2413	1.5335	0.0018	-0.0518	0.0010	0.2713	ń•1021	U-1316	221.
MODEL 946.2 Q= 6.37 PSI	CONF RE PER	IG0000 IN.= .48E0		CH 3.00		PHI =	60. rs =	20•
	RE PER	IN.= .48E0		90. DE	G.F		rs = :	20.
Q= 6.37 PSI	RE PER	IN.= .48E0		90. DE	G.F	POJ/P	rs = :	20 . RUN
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN	RE PER HHG PTS=	IN.= .48E0 1.0109 PSI CS	6 TO=	90. DE	G.F RUN NO. CAT	POJ/P1 007036 CP8	TS = : 59114 CAF	RUN
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 4.12 0.2326	RE PER HHG PTS= CM -1.5044	IN.= .48E0 1.0109 PSI CS -0.0232	6 TO= CY -0.1358-	90. DE	G.F RUN NO. CAT D.2333	P0J/P1 007036 CPB 0-1057	TS =	RUN 222.
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678	RE PER KHG PTS= CM -1.5044 -1.0694	IN.= .48E00 1.0109 PSI CS -0.0232 -0.0196	6 TO= CY 0.1358- 0.1014-	90. DE CR	G.F RUN NO. CAT D.2333 0.2318	POJ/P1 . 007036 CP8 0.1057 0.1041	S = 59114 CAF 0.1276	RUN 222. 222.
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 4.12 0.2326	RE PER HHG PTS= CM -1.5044	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167	CY 0.1358- 0.1014- 0.0763-	90. DE CR 0.0030 0.0026	G.F RUN NO. CAT 0.2333 0.2318 0.2286	POJ/P1 . 007036 CP8 0.1057 0.1041 0.1026	CAF 0.1276 0.1277 0.1260	RUN 222. 222. 222. 222.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -0.0191	CY 0.1358- 0.1014- 0.0763- 0.1002-	90. DE CR 0.0030 0.0026 0.0030	G.F RUN NO. CAT 0.2333 0.2318 0.2286 0.2293	POJ/P1 . 007036 CP8 0.1057 0.1041 0.1026 0.1020	S9114 CAF 0.1276 0.1277 0.1260 0.1273	RUN 222. 222. 222. 222.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703 -0.4492	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0191	CY 0.1358- 0.1014- 0.0763- 0.1027- 0.1027-	90. DE CR 0.0030 0.0026 0.0030 0.0007 0.0018	G.F RUN NO. CAT 0.2333 0.2318 0.2286 0.2293 0.2291 0.2314	POJ/P1 . 007036 CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1024	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1272	RUN 222. 222. 222. 222. 222. 222.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0191	CY 0.1358- 0.1014- 0.0763- 0.1027- 0.1167- 0.1212-	90. DE CR 0.0030 0.0030 0.0030 0.0007 0.0018 0.0018	G.F RUN NO. CAT 0.2333 0.2318 0.2293 0.2293 0.2291 0.2314 0.2303	POJ/P1 . 007036 . CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1024 0.1030	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1272	RUN 222. 222. 222. 222. 222. 222. 222.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436 0.52 0.0144	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771 0.1042 0.2608	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0200 -0.0204 -0.0150	CY 0.1358- 0.1014- 0.0763- 0.102- 0.1027- 0.1167- 0.1212- 0.0699-	90. DE CR 0.0030 0.0026 0.0030 0.0007 0.0018 0.0018	G.F RUN NO. CAT 0.2333 0.2318 0.2293 0.2293 0.2291 0.2314 0.2303 0.2325	POJ/P1 . 007036 . CP8 0.1057 0.1041 0.1026 0.1029 0.1019 0.1024 0.1030 0.1034	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1273 0.1273	RUN 222. 222. 222. 222. 222. 222. 222. 22
Q= 6.37 PSI P0= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436 0.52 0.0144 0.01 -0.0141	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771 0.1042 0.2608 0.4084	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0200 -0.0204 -0.0150 -0.0124	CY 0.1358- 0.1014- 0.0763- 0.1027- 0.1167- 0.1212- 0.0699- 0.0455-	90. DE CR 0.0030 0.0026 0.0030 0.0018 0.0018 0.0018 0.0018	G.F RUN NO. CAT 0.2333 0.2318 0.2293 0.2293 0.2291 0.2314 0.2303 0.2325 0.2322	POJ/P1 . 007036 . CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1024 0.1030 0.1034	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1273 0.1291 0.1289	RUN 222. 222. 222. 222. 222. 222. 222. 22
Q= 6.37 PSI P0= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436 0.52 0.0144 0.01 -0.0141 -0.51 -0.0407 -1.01 -0.0658 -1.53 -0.0958	RE PER HHG PTS= CH -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771 0.1042 0.2608 0.4084 0.5975	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0200 -0.0204 -0.0150 -0.0124 -0.0109	CY 0.1358- 0.1014- 0.0763- 0.1027- 0.1167- 0.1212- 0.0699- 0.0455- 0.0325-	90. DE CR 0.0030 0.0026 0.0030 0.0018 0.0018 0.0018 0.0018 0.0005	G.F RUN NO. CAT 0.2333 0.2318 0.2293 0.2293 0.2293 0.2314 0.2303 0.2325 0.2325	POJ/P1 . 007036 . CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1024 0.1030 0.1034 0.1033	CAF 0.1276 0.1276 0.1277 0.1260 0.1273 0.1273 0.1290 0.1273 0.1291 0.1289	RUN 222. 222. 222. 222. 222. 222. 222. 22
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436 0.52 0.0144 0.01 -0.0141 -0.51 -0.0407 -1.01 -0.0658 -1.53 -0.0958 -2.04 -0.1257	RE PER HHG PTS= CM -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771 0.1042 0.2608 0.4084 0.5975 0.7875	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -6.0191 -0.0200 -0.0204 -0.0150 -0.0124 -0.0109 -0.0183	CY 0.1358- 0.1014- 0.0763- 0.1002- 0.1027- 0.1167- 0.1212- 0.0699- 0.0455- 0.0325- 0.1049-	90. DE CR 0.0030 0.0026 0.0030 0.0007 0.0018 0.0018 0.0018 0.0018 0.0018	G.F RUN NO. CAT 0.2333 0.2318 0.2293 0.2291 0.2314 0.2303 0.2325 0.2354 0.2354	POJ/P1 . 007036 . CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1034 0.1033 0.1025 0.1025	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1291 0.1291 0.1289 0.1328	RUN 222. 222. 222. 222. 222. 222. 222. 22
Q= 6.37 PSI P0= 193.0 CI ALPHA CN 4.12 0.2326 3.11 0.1678 2.08 0.1062 1.56 0.0728 1.04 0.6436 0.52 0.0144 0.01 -0.0141 -0.51 -0.0407 -1.01 -0.0658 -1.53 -0.0958	RE PER CM -1.5044 -1.0694 -0.6703 -0.4492 -0.2646 -0.0771 0.1042 0.2608 0.4084 0.5975 0.7875 1.1351	IN.= .48E0 1.0109 PSI CS -0.0232 -0.0196 -0.0167 -0.0191 -0.0200 -0.0204 -0.0150 -0.0124 -0.0109 -0.0183 -0.0109	CY 0.1358- 0.1014- 0.0763- 0.1002- 0.1027- 0.1167- 0.1212- 0.0699- 0.0455- 0.0325- 0.1049-	90. DE CR 0.0030 0.0026 0.0030 0.0007 0.0018 0.0018 0.0006 0.0005 0.0005 0.0005	G.F RUN NO. CAT 0.2333 0.2318 0.2286 0.2293 0.2291 0.2314 0.2303 0.2325 0.2325 0.2354 0.2353 0.2389	POJ/PT . 007036 CP8 0.1057 0.1041 0.1026 0.1020 0.1019 0.1024 0.1030 0.1034 0.1035 0.1025 0.1031	CAF 0.1276 0.1277 0.1260 0.1273 0.1272 0.1273 0.1273 0.1291 0.1289 0.1329 0.1328	RUN 222. 222. 222. 222. 222. 222. 222. 22

MODE	L 946.2	CON	FIG0000	НА	CH 3.00	0	PHI =	60.	
Q= 6	-37 PSI	RE PER	IN.= .48E0	6 TO=	90° ÓI	EG.F	POJ/P	rs ≃	40•
P0=	193.0 CM	IG PTS=	1.0109 PSI			RUR NO	. 007036	59115	
ALPHA	CN	C#	£S	CY	CR	CAT	CPB	CAF	สบห
4.12	0.2262	-1.4738	-0.0414	0.2592-	0.0025	0.2343	0.1062	0.1281	223.
3-10	0.1603	-1.0250	-0.0362	0~2115-	0.0025	0.2301	0.1046	0.1255	223.
2.08	0-0986	-0.6222	-0.0343	0.1947-	0.0024	0.2330	0.1030	0.1300	223.
1.55	0.0607	-0.3609	-0.0390	0.2428-	0.0017	0.2295	0.1021	0.1274	223.
1.04	0.0366	-0.2224	-G.0321	0.1785-	0.0009	0.2325	0.1021	0.1304	223.
	0.0040	-0.0049		0.2022-					
	0.0555		-0.0308	0.1706-					
~0 _• 51 -			-0.0291	0.1528					
-1.03 -			-0.0355	0.2204-					
~1.53 -			-0.0297	0.1636					
-2.04 -			-0.0282	0.1496					
-3.07 -			-0.0272	0.1496					
-4.09 -	0.2583	1.6511	-0.0223	0.1110	0.	0.2444	0.1043	0-1401	223•
	L 946.2	CONF			CH 3.00		PHI =	60. S = 1	00.
Q= 6	.37 PSI	RE PER	IN.= .48E0		CH 3.00			60. rs = 1	00.
Q= 6	.37 PSI	RE PER			•	EG.₽		rs = 1	00.
Q= 6	.37 PSI	RE PER	IN.= .48E0		•	EG.₽	POJ/PI	rs = 1	00 . RUN
Q= 6 .PO= ALPHA	.37 PSI 193.0 CM	RE PER	IN.= .48E00 1.0109 PSI CS.	5 TO=	90. DE	EG.F RUN NO. CAT	POJ/P1 007036 CP8	rs = 1 59116 CAF	RUN
Q= 6 .PO= ALPHA	.37 PSI 193.0 CMH CN 0.2052	RE PER IG PTS= CM -1.3620	IN.= .48E00 1.0109 PSI CS.	5 T0=	90. DE CR 0.0023	EG.F RUN NO. CAT 0.2365	POJ/P1 007036 CP8	TS = 1 59116 CAF 0.1297	RUN 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09	.37 PSI 193.0 CMH CN 0.2052	RE PER IG PTS= CM -1.3620	IN.= .48E00 1.0109 PSI CS. -0.1038 -0.0942	5 TO= CY .0.7100-	90. DE CR 0.0023 0.0016	EG.F RUN NO. CAT 0.2365 0.2339	POJ/P1 . 007036 . CP8 0.1068 0.1050	TS = 1 59116 CAF 0.1297 0.1289	RUN 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09 2.06	.37 PSI 193.0 CMH CN 0.2052 0.1350	RE PER IG PTS= CH -1.3620 -0.3578	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966	CY -0.7100- 0.6205-	90. DE CR 0.0023 0.0016 0.0016	EG.F RUN NO. CAT 0.2365 G.2339 0.2325	POJ/P7 . 007036 CP8 0.1068 0.1050 0.1025	S = 1 S9116 CAF 0.1297 0.1289 0.1300	RUN 224 • 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09 2.06 1.54 1.03 -	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002	RE PER CM -1.3620 -0.3678 -0.3851 -0.1776 0.0514	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954	CY 0.7100- 0.6205- 0.6525- 0.5963- 0.6454-	90. DE CR 0.0023 0.0016 0.0016 0.0013 0.0017	CAT 0.2365 0.2339 0.2325 0.2322	POJ/P7 . 007036 CP8 0.1068 0.1050 0.1025 0.1016 0.1017	CAF 0.1297 0.1289 0.1300 0.1308	RUN 224 • 224 • 224 • 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.50 -	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251	RE PER CM -1.3620 -0.3578 -0.3851 -0.1776 0.0514 0.1917	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860	CY 0.7100- 0.6205- 0.6525- 0.5963- 0.6454- 0.5549-	90. DE CR 0.0023 0.0016 0.0016 0.0013 0.0017 0.0012	CAT 0.2365 0.2339 0.2325 0.2322 0.2355 0.2359	POJ/P7 . 007036 . CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022	CAF 0.1297 0.1289 0.1300 0.1306 0.1338 0.1238	RUN 224 • 224 • 224 • 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.50 -	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578	RE PER CH -1.3620 -0.3578 -0.3851 -0.1776 0.0514 0.1917 0.4148	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928	CY 0.7100- 0.6525- 0.5963- 0.6454- 0.5549- 0.6268-	90. DE CR 0.0023 0.0016 0.0016 0.0013 0.0017 0.0012	CAT 0.2365 0.2339 0.2325 0.2355 0.2359 0.2375	POJ/P7 . 007036 CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024	CAF O.1297 O.1297 O.1300 O.1306 O.1338 O.1338 O.1338	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 •
Q= 6 PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.50 - -0	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578 0.0848	RE PER CM -1.3620 -0.3578 -0.3851 -0.1776 0.0514 0.1917 0.4148 0.5735	IN.= .48E06 1.0109 PSI CS0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928 -0.0871	CY 0.7100- 0.6205- 0.6525- 0.5963- 0.6454- 0.5549- 0.6268- 0.5714-	90. DE CR 0.0023 0.0016 0.0016 0.0017 0.0012 0.0012	CAT 0.2365 0.2339 0.2325 0.2355 0.2359 0.2375 0.2375	POJ/P7 . 007036 . CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024 0.1024	CAF 0.1297 0.1297 0.1300 0.1308 0.1338 0.1351 0.1347	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 •
Q= 6 PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.50 - -0 -0.52 - -1.04 -	.37 PSI 193.0 CMF CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578 0.0848 0.1132	RE PER CM -1.3620 -0.3578 -0.3851 -0.175 0.0514 0.1917 0.4148 0.5735 0.7492	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928 -0.0871 -0.0866	CY 0.7100- 0.6205- 0.6525- 0.5963- 0.6454- 0.6268- 0.5714- 0.5694-	90. DE CR 0.0023 0.0016 0.0013 0.0017 0.0012 0.0012 0.0014 0.0019	CAT 0.2365 0.2339 0.2325 0.2355 0.2359 0.2375 0.2372 0.2372	POJ/P7 . 007036 . CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024 0.1024 0.1029	CAF 0.1297 0.1297 0.1300 0.1308 0.1338 0.1351 0.13147	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 •
Q= 6 PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.500.521.041.54 -	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578 0.0848 0.1132 0.1395	RE PER CM -1.3620 -0.3578 -0.3851 -0.1776 0.0514 0.1917 0.4148 0.5735 0.7492 0.9066	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928 -0.0871 -0.0866 -0.0833	CY 0.7100- 0.6205- 0.6525- 0.5549- 0.6268- 0.5714- 0.5694- 0.5394	90. DE CR 0.0023 0.0016 0.0015 0.0017 0.0012 0.0012 0.0014 0.0019 0.0004	CAT 0.2365 0.2339 0.2325 0.2322 0.2355 0.2355 0.2372 0.2373 0.2373 0.2365	POJ/P7 . 007036 CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024 0.1029 0.1030	CAF 0.1297 0.1297 0.1300 0.1306 0.1338 0.1338 0.13347 0.1314 0.1335	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 •
Q= 6 .PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.500.521.041.542.06 -	.37 PSI 193.0 CMF CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578 0.0848 0.1132 0.1395 0.1692	RE PER CM -1.3620 -0.0578 -0.3851 -0.1775 0.0514 0.1917 0.4148 0.5735 0.7492 0.9066 1.0910	IN.= .48E06 1.0109 PSI CS0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928 -0.0871 -0.0866 -0.0833 -0.0839	CY 0.7100- 0.6205- 0.6525- 0.5963- 0.6454- 0.5549- 0.6268- 0.5714- 0.5394 0.5394	90. DE CR 0.0023 0.0016 0.0015 0.0017 0.0012 0.0012 0.0019 0.0019 0.0004 0.0008	CAT 0.2365 0.2339 0.2325 0.2325 0.2355 0.2375 0.2375 0.2373 0.2363 0.2389	POJ/P7 O07036 CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024 0.1024 0.1029 0.1030 0.1029	CAF 0.1297 0.1289 0.1300 0.1306 0.1338 0.1331 0.1347 0.1347 0.1345 0.1360	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 •
Q= 6 PO= ALPHA 4.11 3.09 2.06 1.54 1.03 - 0.500.521.041.54 -	.37 PSI 193.0 CMH CN 0.2052 0.1350 0.0656 0.0332 0.0002 0.0251 0.0578 0.0848 0.1132 0.1395 0.1692 0.2268	RE PER CM -1.3620 -0.3578 -0.3851 -0.1776 0.0514 0.1917 0.4148 0.5735 0.7492 0.9066 1.0910 1.4553	IN.= .48E0 1.0109 PSI CS. -0.1038 -0.0942 -0.0966 -0.0909 -0.0954 -0.0860 -0.0928 -0.0871 -0.0866 -0.0833	CY 0.7100- 0.6205- 0.6525- 0.5549- 0.6268- 0.5714- 0.5694- 0.5394	90. DE CR 0.0023 0.0016 0.0015 0.0017 0.0012 0.0012 0.0019 0.0004 0.0008 0.0008	CAT 0.2365 0.2339 0.2325 0.2325 0.2355 0.2359 0.2375 0.2372 0.2373 0.2363 0.2389 0.2426	POJ/P7 007036 CP8 0.1068 0.1050 0.1025 0.1016 0.1017 0.1022 0.1024 0.1024 0.1029 0.1030 0.1029 0.1038	CAF 0.1297 0.1289 0.1300 0.1308 0.1338 0.1351 0.13147 0.13147 0.1315 0.1360 0.1388	RUN 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 • 224 •

МО	DEL 946.2	CON	FIG000	AM OC	CH 3.00	0	PHI =	75.	
0=	6.37 PSI	RE PER	IN.= .48	=01 60	90. DI	EG.F	POJ/P	rs =	•
PO	= 193.0 CM	HG PTS=	1.0109 P	SI		RUN NO	. 00703	69117	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
5.11	0.3143	-2.0571	-0.0045	0.0160-	0.0012	0.2225	0.1076	0.114	9 22Š.
4.09	0.2419	-1.5516	-0.0020	-0.0077-	0.0008	0.2202	0.1051	0.115	
3.07	0.1739	-1.0955	-0.0023	-0.0017	0.0001	0.2189	0.1021	0.116	8 225.
2.03	0.1133	-0.7069	-0.0001	-0.0231-	0.0001	0.2186	0.1017	0.116	8 [:] 225•
1.51	0.0823	-0.5100	-0.0059	0.0385-	0.0002	0.2198	.0.1016	0.118	2 225.
1.00	0.0536	-0.3298	-0.0069	0.0493-	0.0003	0.2227	0.1017	0.121	225.
0.47	0.0252	-0.1552	-0.0028	0.0094			0.1019		
-0.07	1.0003	-0.0011	0.0006	-0.0199	0.0018	0.2231	0-1021	0.121	0 225.
-0.55	J.0291	0.1774	U.0030	-0.0425	0.0010	0.2224	0.1022	0.120	3 225.
-1.06	-0.0591	0.3717	-0.0065	0.0542	0.0002	0.2255	0.1023	0.123	2 225.
-1.57	-0.0852	0.5243	-0.0012	0.0037	0.0016	0.2283	0.1021	0.126	1 225.
-2.08	-0.1140	0.7062	0.0012	-0.0216	0.0023	0.2276	0.1021	0.125	5 225.
-3.10	-0.1714	1.0737	0.0061	-0.0640	0.0024	0.2288	0.1025	0.126	3 225.
-4.13	-0.2351	1.4925	0.0090	-0.0864	0.0030	0.2335	0.1044	0.129	L 225.
	DEL 946.2	CONF			CH 3.00		PHI =	75.	
Q=	6.37 PSI	RE PER	IN.= .481	06 T0=	90+ DE	EG.F	POJ/P1	rs =	10.
PO	= 193.0 CM	HG PTS=	1.0109 PS	SI		RUN NO	. 007036	69118	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.08	0.2328	-1.4860	-0.0113	0.0478-	0.0011	0.2208	0.1047	0.116	L 226.
3.06			-0.0094	0.0340-					
2.04			-0.0070	0.0146-					
1.51	0.0777	-0.4812	-0:0023	-0.0316-	0.0009	0.2235	0.1021	0.121	
0.99		-0.2756		0.0582-					
0.49			0.0002	-0.0502-					
-	-0.0069		-0:0015	-0.0310					
	-0.0365		-0.0093	0.0502~					
	-0.0666		-0.0135	0.0932					
_	-0.0914		-0.0051	0.0083					
	-0.1198		-0.0099	0.0428					
	-0.1798		-0.0043				0.1025		
				0.000,	0.0010	042720			

MO	DEL 946.2	CON	FIGOOAÓ	MA	CH 3.00		PHI =	75.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 T0=	90. DEG	•F	P0J/P	rs =	20.
P 0:	= 193.0 CH	HG PTS≃	1.0109 PSI		R	UN NO.	00703	69119	
ALPHA	CN	CM	CS	CY	CR.	CAT	CP8	CAF	RUN
4.08	0.2330	-1.4964	~0.0203	0.1067-	0.0018 0	.2273	0.1051	0.1223	227.
3.06	0.1695	-1.0749	-0.0201	0.1067-	0.0016 0.	-2269	0.1038	0.1231	227.
2.04	0.1073	-0.6703	-0.0166	0.0741-	0.0014 0.	.2256	0.1027	0.1229	227.
1.51	0.0717	-0.4317	~0.0255		0.0013 0.				
1.00		-0.2727	-0.0210		0.0006 0				
0,48	0.0199	-0.1247	-0.0133		0.0005 0				
	-0.0039		-0.0150		0.0001 0.				
	-0.0384		-0.0169		0.0007 0.				
	-0.0654		-0.0185		0.0007 0.				
	-0.0948		-0.0202		0.0016 0				
	-0.1251		-0.0217		0.0009 0.				
	-0.1817		-0.0101		0.0015 0.				
-4.13	-0.2465	1.5731	-0.0060	-0.0055	0.0020 0.	.2397	0.1045	0.1352	227.
	•								
	DEL 946.2 6.37 PSI	CONF	IG0000		CH 3.00	.F	PHI =	75. [S =	40.
Q=	6.37 PSI	RE PER			90. DEG.			rs =	40.
Q=	6.37 PSI	RE PER	IN.= .48E0		90. DEG.		POJ/P1	rs =	40 . RUN
Q= P0:	6.37 PSI = 193.0 CM	RE PER	IN.= .48E0 1.0109 PSI CS	6 TO=	90. DEG.	UN NO. CAT	POJ/P1 -007036 CPB	S = 59120 CAF	RUN
Q= PO: ALPHA	6.37 PSI = 193.0 CM	RE PER HG PTS=	IN.= .48E0 1.0109 PSI CS -0.0416	6 TO= CY 0.2536-	90. DEG.	UN NO. CAT .2301	POJ/P1 007036 CPB 0-1057	(S = 59120 CAF 0.1244	RUN 228+
Q= P0: ALPHA 4.08	6.37 PSI = 193.0 CM CN 0.2324	RE PER HG PTS= CH -1.5027	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388	6 TO= CY 0.2536- 0.2310-	90. DEG. RI CR (UN NO. CAT .2301 .2287	POJ/P1 007036 CPB 0-1057 0-1043	S = 59120 CAF 0.1244	RUN 228 • 228 •
Q= P0: ALPHA 4.08 3.06	6.37 PSI = 193.0 CM CN 0.2324 0.1658	RE PER HG PTS= CH -1.5027 -1.0507	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360	CY 0.2536- 0.2310- 0.2097- 0.1767-	90. DEG. RI CR (0.0012 0.0015 0.0015 0.0013 0.0013 0.0010	UN NO. CAT .2301 .2287 .2273 .2285	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022	S = 59120 CAF 0.1244 0.1243 0.1242 0.1263	RUN 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328	CY 0.2536- 0.2310- 0.2097- 0.1767-	90- DEG. RI CR (0-0012 0. 0-0015 0. 0-0013 0.	UN NO. CAT .2301 .2287 .2273 .2285	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022	S = 59120 CAF 0.1244 0.1243 0.1242 0.1263	RUN 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04 1.51	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2961- 0.2716-	90. DEG. RI CR (0.0012 0.0015 0.00013 0.00010 0.00012 0.00012 0.00009 0.00009 0.00009 0.00009	UN NO. 2301 2287 2273 2285 2324 2309	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022 0-1023 0-1029	CAF 0.1244 0.1243 0.1243 0.1243 0.1242 0.1263 0.1301	RUN 228 • 228 • 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.99 0.48 -0.04	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.0391 0.0099 -0.0169	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2961- 0.2716- 0.2451-	90. DEG. RI CR (0.0012 0.0015 0.00013 0.00010 0.00012 0.00012 0.00009 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.000002 0.000002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.00002 0.000002 0.00002 0.000002 0.000002 0.00000000	UN NO. 2301 2287 2273 2285 2324 2309 2294	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022 0-1023 0-1029 0-1034	CAF 0.1244 0.1243 0.1243 0.1243 0.1263 0.1301 0.1279	RUN 228 • 228 • 228 • 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.48 -0.04 -0.56	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.0391 0.0099 -0.0169 -0.0463	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223 0.3058	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389 -0.0390	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2716- 0.2716- 0.2451- 0.2480-	90. DEG. RI CR (0.0012 0.0015 0.0013 0.0010 0.0010 0.0012 0.0009 0.00002 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.00003 0.000003 0.000003 0.00000000	2301 .2301 .2287 .2273 .2285 .2324 .2309 .2294	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022 0-1023 0-1029 0-1034 0-1033	CAF 0.1244 0.1243 0.1243 0.1243 0.1263 0.1269 0.1279	RUN 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.99 0.48 -0.04 -0.56 -1.06	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.0391 0.0099 -0.0169 -0.0463 -0.0715	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223 0.3058 0.4526	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389 -0.0390 -0.0339	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2716- 0.2716- 0.2451- 0.2480- 0.1967	90. DEG. RI CR (0.0012 0. 0.0015 0. 0.0013 0. 0.0010 0. 0.0010 0. 0.0012 0. 0.0002 0. 0.0003 0. 0.0004 0.	UN NO. 2301 2287 2287 2285 2324 2309 2294 2331	POJ/P1 007036 CPB 0-1057 0-1043 0-1031 0-1022 0-1023 0-1029 0-1034 0-1033 0-1028	CAF 0.1244 0.1243 0.1242 0.1263 0.1279 0.1279 0.1299	RUN 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 •
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.48 -0.48 -0.56 -1.06	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.00391 0.0099 -0.0169 -0.0463 -0.0715 -0.1036	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223 0.3058 0.4526 0.6596	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389 -0.0390 -0.0339 -0.0367	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2716- 0.2451- 0.2451- 0.2480- 0.1967 0.2281	90. DEG. RI CR (0.0012 0. 0.0015 0. 0.0013 0. 0.0010 0. 0.0012 0. 0.0009 0. 0.0009 0. 0.0009 0. 0.0009 0. 0.0009 0.	2301 2287 2287 2283 2285 2324 2309 2394 2331 2324	POJ/P1 007036 CPB 0-1057 0-1043 0-1032 0-1023 0-1029 0-1034 0-1033 0-1028 0-1020	CAF 0.1244 0.1243 0.1242 0.1263 0.1279 0.1279 0.1299 0.1296	RUN 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 - 228 -
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.99 0.48 -0.04 -0.56 -1.06 -1.59 -2.08	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.0391 0.0099 -0.0169 -0.0463 -0.0715 -0.1036 -0.1279	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223 0.3058 0.4526 0.6596 0.8076	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389 -0.0390 -0.0339 -0.0339	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2961- 0.2451- 0.2451- 0.2480- 0.1967 0.2281 0.1983	90- DEG. RI CR 0.0012 0. 0.0015 0. 0.0013 0. 0.0010 0. 0.0012 0. 0.0009 0. 0.0009 0. 0.0009 0. 0.0007 0. 0.0007 0.	.2301 .2287 .2287 .2283 .2284 .2309 .2394 .2331 .2324 .2336 .2364	POJ/P1 007036 CPB 0-1057 0-1043 0-1022 0-1023 0-1029 0-1034 0-1034 0-1038 0-1020 0-1022	CAF 0.1244 0.1243 0.1242 0.1263 0.1301 0.1279 0.1299 0.1296 0.1316	RUN 228 -
Q= P0: ALPHA 4.08 3.06 2.04 1.51 0.99 0.48 -0.04 -0.56 -1.05 -1.06 -1.59 -2.08 -3.11	6.37 PSI = 193.0 CM CN 0.2324 0.1658 0.1030 0.0711 0.0391 0.0099 -0.0169 -0.0463 -0.0715 -0.1036 -0.1279	RE PER HG PTS= CH -1.5027 -1.0507 -0.6410 -0.4371 -0.2249 -0.0384 0.1223 0.3058 0.4526 0.6596 0.8076	IN.= .48E0 1.0109 PSI CS -0.0416 -0.0388 -0.0360 -0.0328 -0.0443 -0.0418 -0.0389 -0.0390 -0.0339 -0.0339	CY 0.2536- 0.2310- 0.2097- 0.1767- 0.2961- 0.2451- 0.2480- 0.1987 0.1983 0.1523	90. DEG. RI CR (0.0012 0. 0.0015 0. 0.0013 0. 0.0010 0. 0.0012 0. 0.0009 0. 0.0009 0. 0.0009 0. 0.0009 0. 0.0009 0.	.2301 .2287 .2287 .2285 .2324 .2399 .2331 .2324 .2336 .2364 .2376	POJ/P1 007036 CPB 0-1057 0-1043 0-1022 0-1023 0-1029 0-1034 0-1033 0-1020 0-1020 0-1022 0-1032	CAF 0.1244 0.1243 0.1242 0.1263 0.1301 0.1279 0.1299 0.1299 0.1316 0.1316 0.1342	RUN 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 • 228 •

MODEL 946.2	CON	FIG0000	HACH 3	.00	PHI =	75.	
Q= 6.37 PS1	RE PER	IN.= .48E)6 TO= 90.	DEG.F	9\L09	TS = 10	00.
90= 193.0 CI	HIG PTS=	1.0109 PS	i	RUN NO	. 20703	69121	
ALPHA CN	СН	CS	CY CR	CAT	ÇP8	CAF	RUN
4.07 0.2248 3.06 0.1551		-0.1046 -0.1010	0.6979-0.00				229•
2.02 0.0890	-0.5483		0.6667-0.00		· · ·		229.
1.50 0.0537		-0.1020	0-6484-0-00				229.
0.99 0.0252		-0.0970	0.6854-0.00 0.6357 0.		0.1024		229÷ 229•
0.47 -0.0064		~0.1000	0.6692-0.00				229.
-0.05 -0.0332		-0.0936	0.6080 0.00				229.
-0.56 -0.0510		-0.0914	0.5867 0.00				229.
-1.07 -0.0933	-	-0.1056	0.7308 0.		0.1028		
-1.58 -0.1190		-0.0934	0.6090 0.00				229.
-2.10 -0.1509		-0.1007	0.6868 0.00				229.
-3.11 -0.2092		-0.0886	0.5707 C.00				229.
-4.14 -0.2752		-0.0851	0.5414 0.00	-			229.
MODEL 946.2	CONF	IG00Ó	MACH 3	•00	PHI =	90.	
Q= 6.37 PSI	RE PER	IN = .48E0	6 T9= 90.	DEG.F	601/6 3	rs =	•
Q= 6.37 PSI PO= 193.0 CP		-			POJ/P	_	•
		-		RUN NO	•	_	ĸ'nn
20= 193.0 C	HG PTS=	1.0109 PSI		RUN NO Ç a t	• 007036 CPB	59122 CAF	
20≈ 193.0 CP Alpha cn	HG PTS=	1.0109 PSI CS -0.0183	CY CR	RUN NO ÇAT 01 0.2504	• 007036 CPB 0•1274	59122 CAF 0-1230	ŖŪN
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537	HG PTS= CM -7.2278	1.0109 PSI CS -0.0183 -0.0192	CY CR 0.1374-0.ŏ0	RUN NO CAT 01 0.2504 06 0.2473	• 007036 CPB 0•1274	0-1230 0-1206	RUN 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250	HG PTS= CH -7.2278 -5.9801	1.0109 PSI CS -0.0183 -0.0192 -0.0169	CY CR 0.1374-0.00 0.1458-0.00	RUN NO ÇAT 01 0.2504 06 0.2473 0.2450	. 007036 CPB 0.1274 0.1267 0.1241	0.1230 0.1206 0.1209	RUN 230 • 230 •
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159	HG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359	. 007036 EPB 0.1274 0.1267 0.1241 0.1201 0.1155	0.1230 0.1230 0.1206 0.1209 0.1211 0.1204	RUN 230 • 230 • 230 • 230 •
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242	HG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248	1.0109 PSI CS =0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0687 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1105	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1204	RUN 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476	HG PTS= CH -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0086	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0687 0.00 0.0535 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309 04 0.2296	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1105 0.1060	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1204 0.1236	RUN 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793	HG PTS= CH -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0086 -0.0083	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0687 0.00 0.0535 0.00 0.0536-0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309 04 0.2296 01 0.2275	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1105 0.1060 0.1032	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1204 0.1236 0.1243	RUN 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174	HG PTS= CH -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297	1.0109 PSI CS =0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0086 -0.0083 -0.0055	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00 0.0687 0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309 04 0.2296 01 0.2275 07 0.2281	. 007036 CPB 0.1274 0.1267 0.1241 0.1255 0.1105 0.1060 0.1032 0.1023	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1204 0.1236 0.1243 0.1258	RUN 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859	HG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00 0.0687 0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00 0.0288 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2451 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2289	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1105 0.1060 0.1032 0.1023 0.1018	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563	THE PTS = CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0086 -0.0083 -0.0055 -0.0070 -0.0052	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00 0.0687 0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00 0.0288 0.00 0.0455 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2452 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2305	. 007036 CPB 0.1274 0.1267 0.1241 0.1155 0.105 0.1060 0.1032 0.1023 0.1018 0.1019	CAF 0.1230 0.1206 0.1209 9.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0120 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00 0.0535-0.00 0.0536-0.00 0.0288 0.00 0.0288 0.00 0.0288 0.00 0.0288 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2383	. 007036 CPB 0.1274 0.1267 0.1241 0.1255 0.1105 0.1060 0.1023 0.1018 0.1019 0.1021	0.1230 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1291	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864 -0.0160	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0120 -0.0120 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058 -0.0039	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 6.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00 0.0455 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2289 10 0.2305 13 0.2313	. 007036 CPB 0.1274 0.1267 0.1241 0.1255 0.1105 0.1060 0.1022 0.1023 0.1018 0.1019 0.1021 0.1021	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1291	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022 -0.49 -0.0260	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864 -0.0160 0.1592	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058 -0.0039 -0.0054	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0.00 0.1001 6.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00 0.0288 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00 0.0344 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2281 0 0.2305 13 0.2313 11 0.2311	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1105 0.1060 0.1032 0.1013 0.1019 0.1021 0.1021	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1290 0.1290	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022 -0.49 -0.0260 -1.00 -0.0556	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864 -0.0160 0.1592 0.3448	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058 -0.0039 -0.0054 -0.0027	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0288 0.00 0.0455 0.00 0.0272 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00 0.0344 0.00 0.0387 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2281 10 0.2313 11 0.2313 11 0.2319 19 0.2335	. 007036 CPB 0.1274 0.1267 0.1267 0.1261 0.105 0.1060 0.1032 0.1018 0.1019 0.1021 0.1021 0.1021	CAF 0.1230 0.1206 0.1209 9.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1291 0.1291 0.1298 0.1313	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022 -0.49 -0.0260 -1.00 -0.0556 -1.51 -0.0833	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3428 -0.0160 0.1592 0.3448 0.5128	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058 -0.0039 -0.0054 -0.0051	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0258 0.00 0.0252 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00 0.0344 0.00 0.0350 0.00 0.0350 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309 04 0.2296 01 0.2275 07 0.2281 05 0.2383 11 0.2313 13 0.2313 19 0.2335 18 0.2352	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1060 0.1032 0.1018 0.1019 0.1021 0.1021 0.1021 0.1022 0.1022	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1271 0.1290 0.1290 0.1313 0.1333	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022 -0.49 -0.0260 -1.00 -0.0556 -1.51 -0.0833 -2.03 -0.1116	THG PTS= CM -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864 -0.0160 0.1592 0.3448 0.5128 0.6893	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0083 -0.0055 -0.0070 -0.0052 -0.0058 -0.0039 -0.0054 -0.0027 -0.0051 -0.0049	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0258 0.00 0.0258 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00 0.0350 0.00 0.0344 0.00 0.0330 0.00 0.0330 0.00 0.0330 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 09 0.2309 04 0.2296 01 0.2275 07 0.2281 05 0.2383 11 0.2313 11 0.2313 11 0.2313 11 0.2315 19 0.2335 18 0.2352 20 0.2342	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.1155 0.1060 0.1032 0.1023 0.1018 0.1019 0.1021 0.1021 0.1022 0.1022 0.1022	CAF 0.1230 0.1206 0.1209 0.1211 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1291 0.1290 0.1313 0.1333 0.1333	RUN 230. 230. 230. 230. 230. 230. 230. 230.
PO= 193.0 CM ALPHA CN 10.36 0.9580 9.34 0.8067 8.29 0.6537 7.25 0.5250 6.22 0.4159 5.18 0.3242 4.15 0.2476 3.12 0.1793 2.09 0.1174 1.56 0.0859 1.05 0.0563 0.54 0.0300 0.02 0.0022 -0.49 -0.0260 -1.00 -0.0556 -1.51 -0.0833	THE PTS = CH -7.2278 -5.9801 -4.7071 -3.6564 -2.8063 -2.1248 -1.5873 -1.1291 -0.7297 -0.5309 -0.3423 -0.1864 -0.0160 0.1592 0.3448 0.5128 0.6893 1.1018	1.0109 PSI CS -0.0183 -0.0192 -0.0169 -0.0142 -0.0120 -0.0104 -0.0083 -0.0055 -0.0055 -0.0052 -0.0058 -0.0054 -0.0027 -0.0049 -0.0020	CY CR 0.1374-0.00 0.1458-0.00 0.1238-0. 0.1001 G.00 0.0839-0.00 0.0535 0.00 0.0536-0.00 0.0258 0.00 0.0252 0.00 0.0272 0.00 0.0350 0.00 0.0175 0.00 0.0344 0.00 0.0350 0.00 0.0350 0.00	RUN NO CAT 01 0.2504 06 0.2473 0.2450 09 0.2412 03 0.2359 04 0.2296 01 0.2275 07 0.2281 05 0.2383 11 0.2313 11 0.2313 11 0.2313 11 0.2335 18 0.2352 20 0.2342 24 0.2330	. 007036 CPB 0.1274 0.1267 0.1241 0.1201 0.105 0.1060 0.1022 0.1023 0.1018 0.1019 0.1021 0.1021 0.1021 0.1022 0.1019 0.1019	CAF 0.1230 0.1206 0.1204 0.1204 0.1204 0.1236 0.1243 0.1258 0.1271 0.1286 0.1291 0.1290 0.1333 0.1323 0.1323	RUN 230. 230. 230. 230. 230. 230. 230. 230.

MDDFL 946.2	CONFIG	0000	HACH 3-0	O PHI:	90.	
Q= 6.37 PSI	RE PER IN	4-= -48E06	T0= 90. D	EG.F 90J/	PTS = 10.	
PO= 193.0 CH	HG PTS= 1.	.0109 PSI		RUN NO. 0070	369123	
-ALPHA CN	ĊН	εs	CY CR	CAT CP8	CAF	RUN
10.37 0.9539	-7°1931 -0		0.2643-0.0008			231.
9:33 0:8035	-5.9574 -0		0.7214-0.0010			231.
8.29 0.6491	-4.6651 -0		0.1803-4.0003			231.
7.26 0.5214	-3.6216 -0		0.1329-0.0002 0.1112-0.0003			231.
6.22 0.4105 5.18 0.3197	-2.7562 -0 -2.0849 -0		0.1225-0.0006			231.
4.15 0.2441	-1.5576 -0		0.1100-C.0003			231.
3:12 0-1734	-1-0799 -0		0.0868-0.0004			231.
2.10 0.1120	-0,6847 -0		0.0962-0.0008			231.
1.57 0.0773	-0.4624 -0		0.0712 0.0001			231.
1.05 0.0468	-0.2646 -0	0.0182	0.1235-0,0005	0.2344 0.101	3 0-1326	231.
0.53 0.0214	-0.1168 -0		0.1424-0.0010			231.
0.02 -0.0059	0.0505 -0		0.0048 0.0004			231.
-0.49 -0.0346	0.2310 -0		0.0723 0.0006			231.
-1.00 -0.0628	0.4053 -0		0.0708 0.0012			231.
-1.52 -0.0905	0.5723 -0		0.0188 0.0010			231.
-2.02 -0.1201	0.7640 -0		0.0638 0.0008			231.
-3.05 -0.1796	1.1470 -0		0.0234 0.0009			231.
-4.07 -0.2429	1-5639 -0	0.0055	0.0191 0.0020	0.2477 0.165	0.1420	231.
MODEL 946.2	CGNFIG		MACH 3.0			
Q= 6.37 PS!	RE PER IN	4.= .4RE06		EG.F POJ/	PTS = 20+	
*******	RE PER IN	N.= .48E06 .0109 PSI	10= 90. D	EG.F POJ/	PTS = 20. 369124	
Q= 6.37 PS!	RE PER IN	4.= .48E06 .0109 PSI CS	T0= 90. D	EG.F POJ/	PTS = 20. 869124 CAF	RUN
Q= 6.37 PS: PO= 193.0 CM	RE PER IN	4.= .48E06 .0109 PSI CS 0.0493	TO= 90. D CY CR 0.3593-0.0007	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125	PTS = 20. 369124 CAF 9 0.1277	232.
Q= 6.37 PS! PO= 193.0 CM	RE PER IN HG PTS= 1. C⊭	.0109 PSI CS 0.0493	TO= 90. D CY CR 0.3593-0.0007 0.2845-9.0012	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125	PTS = 20. 369124 CAF 9 0.1277 4 0.1266	232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530	RE PER IN CM -7.2466 -0 -5.9815 -0 -4.6976 -0	CS 0.0493 0.0418 0.0353	CY CR 0.3593-0.0007 0.2845-9.0012 0.2199-0.0013	EG.F POJ/6 RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123	PTS = 20. 369124 CAF 9 0.1277 6 0.1266 2 0.1246	232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0	.0109 PSI CS D.0493 D.0418 D.0353 D.0326	TO= 90. D CY CR 0.3593-0.0007 0.2845-9.0012 0.2199-0.0013 0.1997-0.0016	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248	232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0	CS 0.0493 0.0418 0.0353 0.0326 0.0312	CY CR 0.3593-0.0007 0.2845-9.0012 0.2199-0.0013 0.1997-0.0016 0.1934-0.0002	EG.F POJ/6 RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262	232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8064 8.29 0.6530 7.26 0.5530 6.22 0.4130 5.18 0.3213	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0	CS 0.0493 0.0493 0.0418 0.0353 0.0326 0.0326 0.0304	CY CR 0.3593-0.0007 0.2845-9.0012 0.2199-0.0013 0.1994-0.0002 0.1934-0.0002	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252	232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438	RE PER IN CH	N.= .48E06 .0109 PSI CS 0.0493 0.0418 0.0353 0.0326 0.0312 0.0304 0.0294	CY CR 0.3593-0.0007 0.2845-9.0012 0.199-0.0013 0.1997-0.0016 0.1934-0.0002 0.1899-0.0008	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2333 0.106	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267	232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0	CS 0.0493 0.0493 0.0418 0.0353 0.0326 0.0312 0.0304 0.0294	CY CR 0.3593-0.0007 0.2845-9.0012 0.199-0.0013 0.1994-0.0002 0.1899-0.0008 0.1885 0.0001 0.1633-0.0011	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.104	PTS = 20. 369124 CAF 9 0.1277 6 0.1266 2 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.6944 -0	CS 0.0493 0.0418 0.0326 0.0312 0.0304 0.0266 0.0263	TO= 90. D CY	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.106 0.2334 0.102	PTS = 20. 369124 CAF 9 0.1277 6 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1277 0 0.1279 9 0.1305	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802	RE PER IN CH	N.= .48E06 .0109 PSI CS 0.0493 0.0418 0.0353 0.0326 0.0312 0.0304 0.0294 0.0294 0.0263 0.0338	TO= 90. D CY	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2448 0.123 0.2448 0.120 0.2442 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 2 0.1312	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.4824 -0 -0.3141 -0	CS 0.0493 0.0493 0.0418 0.0353 0.0326 0.0312 0.0304 0.0264 0.0266 0.0263 0.0338 0.0225	TO= 90. D CY	EG.F POJ/R RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.110 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102 0.2334 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1267 0 0.1267 0 0.1279 9 0.1305 2 0.1310	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8066 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.55 0.0225	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.4824 -0 -0.4824 -0 -0.4824 -0	CS 0.0493 0.0418 0.0326 0.0326 0.0312 0.0312 0.0304 0.0266 0.0263 0.0338 0.0338 0.0328	TO= 90. D CY CR 0.3593-0.0007 0.2845-0.0012 0.2199-0.0016 0.1934-0.0002 0.1899-0.0008 0.1885 0.0001 0.1637 0.0011 0.1637 0.002413-0.0017 0.1303 0.0004 0.1918-0.0002	EG.F POJ/ RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2448 0.123 0.2448 0.120 0.2442 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102	PTS = 20. 369124 CAF 9 0.1277 6 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 2 0.1310 9 0.1346	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.55 0.0225 0.02 -0.0058	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.5531 -0 -0.6944 -0 -0.4824 -0 -0.3141 -0 -0.1216 -0 -0.0499 -0	CS 0.0493 0.0418 0.0326 0.0312 0.0304 0.0266 0.0263 0.0338 0.0225 0.0284 0.0282	TO= 90. D CY CR 0.3593-0.0007 0.2845-0.0012 0.2199-0.0016 0.1934-0.0002 0.1899-0.0008 0.1885 0.0001 0.1637 0.0011 0.1637 0.002413-0.0017 0.1303 0.0004 0.1918-0.0002	EG.F POJ/RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.106 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2337 0.102 0.2374 0.102 0.2374 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 2 0.1310 9 0.1346 3 0.1341	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8066 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.55 0.0225	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.4824 -0 -0.4824 -0 -0.4824 -0	N.= .48E06 .0109 PSI CS 0.0493 0.0418 0.0353 0.0326 0.0312 0.0304 0.0294 0.0263 0.0318 0.0255 0.0388 0.0225	TO= 90. D CY	EG.F POJ/RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.106 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2337 0.102 0.2374 0.102 0.2374 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 2 0.1312 1 0.1310 9 0.1346 3 0.1341 2 0.1330	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.02 -0.0058 -0.49 -0.0344	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.4824 -0 -0.3141 -0 0.01216 -0 0.02282 -0	CS 0.0493 0.0493 0.0418 0.0326 0.0326 0.0326 0.0264 0.0263 0.0338 0.0328 0.0328 0.0284 0.0282 0.0282	CY CR 0.3593-0.0007 0.2845-9.0012 0.199-0.0016 0.1934-0.0002 0.1899-0.0011 0.1633-0.0011 0.1637 0. 0.2413-0.0017 0.1918-0.0012 0.1918-0.0010 0.1918-0.0010 0.1918-0.0010	EG.F POJ/R RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.111 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102 0.2374 0.103 0.2374 0.103 0.2374 0.103	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1248 0 0.1252 1 0.1252 5 0.1267 0 0.1269 9 0.1305 2 0.1310 9 0.1346 3 0.1341 2 0.1330 5 0.1343	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.36 0.8066 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.55 0.0225 0.02 -0.0058 -0.49 -0.0344 -1.00 -0.0635	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -1.0928 -0 -0.4824 -0 -0.4824 -0 -0.3141 -0 0.0499 -0 0.2282 -0 0.4126 -0	N.= .48E06 .0109 PSI CS 0.0493 0.0418 0.0326 0.0326 0.0312 0.0304 0.0294 0.0263 0.0338 0.0225 0.0225 0.0282 0.0229 0.0183 0.0198	TO= 90. D CY	EG.F POJ/R RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2374 0.103 0.2374 0.103 0.2369 0.103 0.2369 0.103 0.2367 0.102 0.2377 0.102 0.2377 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1246 0 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1312 1 0.1310 9 0.1346 3 0.1346 3 0.1346 3 0.1343 4 0.1353 0 0.1356	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.55 0.0225 0.02 -0.0058 -0.49 -0.0344 -1.00 -0.0635 -1.51 -0.0899 -2.02 -0.1190 -3.05 -0.1809	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -3.6326 -0 -2.7754 -0 -2.0959 -0 -1.5531 -0 -0.4824 -0 -0.3141 -0 -0.1216 -0 0.0499 -0 0.2282 -0 0.4126 -0 0.5697 -0 0.5697 -0 0.5697 -0 1.587 -0	CS 0.0493 0.0493 0.0493 0.0353 0.0326 0.0312 0.0304 0.0266 0.0263 0.0338 0.0225 0.0382 0.0382 0.0383 0.0193 0.0193 0.0193 0.0193	CY CR 0.3593-0.0007 0.2845-9.0012 0.1997-0.0013 0.1997-0.0016 0.1934-0.0002 0.1899-0.0011 0.1633-0.0011 0.1637 0. 0.2413-0.0017 0.1303 0.0004 0.1918-0.0002 0.1916-0.0011 0.1415 0.0003 0.1066 0.0005 0.0966 0.0011 0.1151 0.0006	EG.F POJ/R RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2363 0.110 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2374 0.102 0.2374 0.103 0.2362 0.103 0.2369 0.102 0.2376 0.102 0.2376 0.102 0.2376 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 0 0.1346 3 0.1341 2 0.1330 6 0.1343 4 0.1353 0 0.1356 9 0.1404	232. 232. 232. 232. 232. 232. 232. 232.
Q= 6.37 PS: PO= 193.0 CM ALPHA CN 10.36 0.9595 9.34 0.8064 8.29 0.6530 7.26 0.5230 6.22 0.4130 5.18 0.3213 4.15 0.2438 3.12 0.1750 2.10 0.1131 1.57 0.0802 1.05 0.0525 0.02 0.025 0.02 0.025 0.02 0.025 0.02 0.025 0.02 0.0344 -1.00 -0.0635 -1.51 -0.0899 -2.02 -0.1190	RE PER IN CH -7.2466 -0 -5.9815 -0 -4.6976 -0 -2.7754 -0 -2.7754 -0 -1.5531 -0 -1.5531 -0 -0.6944 -0 -0.4824 -0 -0.4126 -0 0.5697 -0 0.4282 -0 0.4126 -0 0.57582 -0	CS 0.0493 0.0493 0.0493 0.0353 0.0326 0.0312 0.0304 0.0266 0.0263 0.0338 0.0225 0.0382 0.0382 0.0383 0.0193 0.0193 0.0193 0.0193	CY CR 0.3593-0.0007 0.2845-9.0012 0.1997-0.0013 0.1997-0.0016 0.1934-0.0002 0.1899-0.0011 0.1633-0.0011 0.1637 0. 0.2413-0.0017 0.1303 0.0004 0.1918-0.0002 0.1916-0.0011 0.1415 0.0003 0.1066 0.0005 0.0966 0.0011 0.1151 0.0006	EG.F POJ/R RUN NO. 0070 CAT CP8 0.2535 0.125 0.2520 0.125 0.2476 0.123 0.2448 0.120 0.2422 0.116 0.2332 0.106 0.2319 0.104 0.2334 0.102 0.2334 0.102 0.2334 0.102 0.2374 0.103 0.2374 0.103 0.2369 0.103 0.2369 0.103 0.2367 0.102 0.2377 0.102 0.2377 0.102	PTS = 20. 369124 CAF 9 0.1277 4 0.1266 2 0.1248 0 0.1262 1 0.1252 5 0.1267 0 0.1279 9 0.1305 0 0.1346 3 0.1341 2 0.1330 6 0.1343 4 0.1353 0 0.1356 9 0.1404	232. 232. 232. 232. 232. 232. 232. 232.

HODEL 946.2	CONFIG. :0	000 MACH 3.00	PHI = 90.	
Q= 6.37 PSI	RE PER IN. = .4	8E06 TO* 90. DEG.F	POJ/PTS = 400	
PO= 193.0 CM	HG PTS= 1.0109	PSI RUN N	a. 0970369125	
ALPHA CN	CM CS	CÝ CR CAT	CPB CAF	RUN
ALPRA CY		3. 3.	CPB CAF	
10.36 0.9627	-7.2724 -0.0717 -5.9954 -0.0634			233.
8.29 0.6552	-4.7091 -0.0560	-		233.
7.26 0.5247	-3.6411 -0.0525			233.
6.22" 0.4157	-2.7960 -0.0528			233.
5.18 0.3235	-2.1123 -0.0512			233.
4.15 0.2451	-1.5615 -0.0485 -1.0970 -0.0482			233.
3.12 0.1758 2.09 0.1121	-0.6814 -0.0437			233.
1.57 0.0788	-0.4684 -0.0528			233.
1.05 0.0515	-0.30320:0458			233.
0.54 0.0224	-0.1196 -0.0414			233.
3.02 -0.0058	0.0526 -0.0523			233.
-0.49 -0.0354	0.2392 -0.0360			233.
-1.00 -0.0631 -1.52 -0.0936	0.4103 -0.0426			233.
-2.02 -0.1218	0.7793 -0.0372			233.
-3.05 -0.1828	3.1788 -0.0369			233.
-4.08 -0.2488	1.6189 -0.0324			233.
MODEL 946.2		0000 MACH 3.00	PHI = 90.	
Q= 6.37 PS1	RE PER IN.= .4	8E06 T9= 90. DEG.F	POJ/PTS = 100.	
Q= 6.37 PSI PO= 193.0 CM	RE PER IN.= .4	8806 TO= 90., DEG.F PSI RUN N	POJ/PTS = 100.	
Q= 6.37 PS1	RE PER IN.= .4	8E06 T9= 90. DEG.F	POJ/PTS = 100.	RUN
Q= 6.37 PSI PO= 193.0 CM	RE PER IN.= .4	88E06 T9= 90. DEG.F PSI RUN N CY CR CAT	POJ/PTS = 100. 0. 0070369126 CPB CAF	RUN 234•
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.136	8806 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287	234. 234.
Q= 6.37 PS1 PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241	PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252 0.8341-0.0005 0.250	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 0.1283	234. 234. 234.
Q= 6.37 PSI PU= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125 8.30 0.6638 7.26 0.5337	RE PER IN.= .4 HG PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1361 -4.7721 -0.1241 -3.7181 -0.1180	PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267	234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1186 -2.8781 -0.1157	PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 7 0.7680-0.0002 0.243	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1226 C.1283 1 0.1203 0.1267 5 C.1161 0.1275	234. 234. 234. 234. 234.
Q= 6.37 PS1 PD= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316	RE PER IN.= .4 HG PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1361 -4.7721 -0.1241 -3.7181 -0.1180	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.243 7 0.7680-0.0002 0.243 0.7374-0.0005 0.243	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 C.1161 0.1275 1 0.1112 0.1289	234. 234. 234. 234.
Q= 6.37 PS1 PD= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.136) -4.7721 -0.1241 -3.7181 -0.1186 -2.8761 -0.1157	RED6 T9= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0002 0.243 0.7374-0.0005 0.240 0.7532 0.0004 0.235	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1226 G.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282	234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1185 -2.8761 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1075	PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 7 0.7680-0.0002 0.243 6 0.7374-0.0005 0.240 0.7532 0.0004 0.233 6 0.7347-0.0001 0.233	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 C.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PD= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763	RE PER IN.= .4 HG PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1180 -2.8781 -0.1157 -2.1851 -0.1157 -1.6128 -0.122 -1.1179 -0.1095 -0.6931 -0.1073 -0.4486 -0.1073	RED6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0005 0.240 0.7532 0.0004 0.235 0.7347-0.0001 0.233 0.7175-0.0001 0.233 0.7175-0.0001 0.233	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 60.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 C.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486	RE PER IN.= .4 HG PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1187 -2.8761 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1073 -0.2773 -0.1071	RED6 T9= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0002 0.243 0.7347-0.0005 0.240 0.7532 0.0004 0.235 0.7175-0.0009 0.233 0.7175-0.0009 0.233 0.7175-0.0009 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1031 0.1302	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486 0.54 0.0194	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1185 -2.8781 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1077 -0.4486 -0.1073 -0.2773 -0.1071	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0005 0.240 0.7532 0.0004 0.235 0.7347-0.0001 0.233 0.7175-0.0009 0.233 0.7190-0.0002 0.231 0.7225 0.0062 0.233 0.72890 0.0004 0.235	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1203 0.1267 5 0.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1031 0.1282 9 0.1031 0.1282	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486	RE PER IN.= .4 HG PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1187 -2.8761 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1073 -0.2773 -0.1071	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 7 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 7 0.7680-0.0002 0.243 6 0.734-0.0005 0.240 2 0.7532 0.0004 0.235 6 0.7347-0.0001 0.233 6 0.7175-0.0009 0.233 7 0.7890 0.0004 0.235 0.7225 0.0062 0.233 0.7890 0.0004 0.235 0.7890 0.0004 0.235 0.7890 0.0004 0.235	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1203 0.1267 5 0.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1031 0.1282 9 0.1031 0.1282	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486 0.54 0.0194 0.03 -0.0079 -0.49 -0.375 -1.01 -0.0666	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1157 -2.1851 -0.1157 -2.1851 -0.1122 -1.1179 -0.1095 -0.6931 -0.1077 -0.4486 -0.1077 -0.2773 -0.1071 -0.0937 -0.1137 0.2/16 -0.1006 0.2571 -0.1151 0.4375 -0.1099	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0005 0.243 0.7374-0.0005 0.243 0.7374-0.0001 0.233 0.715-0.0004 0.235 0.7175-0.0009 0.231 0.7125 0.0062 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233 0.7890 0.0004 0.235 0.6521 0.0003 0.235 0.8669 0. 0.236	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 9 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1031 0.1502 9 0.1029 0.1330 6 0.1026 0.1329 6 0.1024 0.1355	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486 0.54 0.0194 0.03 -0.0079 -0.49 -0.2375 -1.01 -0.0666 -1.52 -0.0958	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1185 -2.8781 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1073 -0.2773 -0.1073 -0.2773 -0.1073 -0.2773 -0.1073 0.2/16 -0.1000 0.2571 -0.1153 0.4375 -0.1090 0.6190 -0.1028	REO6 T9= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0005 0.240 0.7532 0.0004 0.235 0.734-0.0001 0.233 0.7175-0.0009 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233 0.7890 0.0004 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6631 0.0003 0.235 0.7468 0.0003 0.236 0.7468 0.0003 0.236	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1226 C.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1091 0.1502 9 0.1029 0.1330 6 0.1026 0.1329 6 0.1026 0.1329 6 0.1026 0.1355 1 0.1029 0.1341	234. 234. 234. 234. 234. 234. 234. 234.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8125 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486 0.54 0.0194 0.03 -0.0079 -0.49 -0.2375 -1.01 -0.0666 -1.52 -0.0958 -2.03 -0.1248	RE PER IN.= .4 HC PTS= 1.0109 CM CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1187 -2.1851 -0.1157 -2.1851 -0.1157 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1072 -0.2773 -0.1071 -0.0937 -0.1137 0.0716 -0.1000 0.2571 -0.1151 0.4375 -0.1090 0.6100 -0.1028 0.8072 -0.1053	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0002 0.243 0.7374-0.0001 0.235 0.7374-0.0001 0.233 0.7175-0.0009 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233 0.7890 0.0004 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6521 0.0003 0.235 0.6531 0.0003 0.235 0.6531 0.0003 0.235	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 0.1226 G.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1031 0.1502 9 0.1026 0.1329 6 0.1026 0.1329 6 0.1026 0.1355 1 0.1029 0.1341 0 0.1031 0.1339	234 ·
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 10.36 0.9648 9.34 0.8126 8.30 0.6638 7.26 0.5337 6.22 0.4251 5.19 0.3316 4.16 0.2508 3.12 0.1784 2.09 0.1137 1.57 0.0763 1.05 0.0486 0.54 0.0194 0.03 -0.0079 -0.49 -0.2375 -1.01 -0.0666 -1.52 -0.0958	RE PER IN.= .4 HG PTS= 1.0109 CH CS -7.2734 -0.1518 -6.0135 -0.1367 -4.7721 -0.1241 -3.7181 -0.1185 -2.8781 -0.1157 -2.1851 -0.1115 -1.6128 -0.1122 -1.1179 -0.1095 -0.6931 -0.1073 -0.2773 -0.1073 -0.2773 -0.1073 -0.2773 -0.1073 0.2/16 -0.1000 0.2571 -0.1153 0.4375 -0.1090 0.6190 -0.1028	REO6 TO= 90. DEG.F PSI RUN N CY CR CAT 1.1180-0.0012 0.256 0.9589-0.0016 0.252 0.8341-0.0005 0.250 0.7797-0.0008 0.247 0.7680-0.0002 0.243 0.7347-0.0001 0.235 0.7175-0.0009 0.233 0.7175-0.0009 0.233 0.7175-0.0009 0.233 0.7175-0.0009 0.233 0.7190-0. 0.231 0.7225 0.0062 0.233 0.7890 0.004 0.235 0.6521 0.0003 0.235 0.66837 0.0009 0.236 0.7468 0.0003 0.235 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236 0.7689 0. 0.236	POJ/PTS = 100. 0. 0070369126 CPB CAF 8 0.1244 0.1324 6 0.1239 0.1287 9 9.1226 C.1283 1 0.1203 0.1267 5 G.1161 0.1275 1 0.1112 0.1289 3 0.1071 0.1282 9 0.1044 0.1295 6 0.1032 0.1304 7 0.1034 0.1282 3 0.1034 0.1282 3 0.1034 0.1389 6 0.1026 0.1329 6 0.1026 0.1355 1 0.1026 0.1339 6 0.1031 0.1339 6 0.1031 0.1339	234. 234. 234. 234. 234. 234. 234. 234.

MO	DEL 946.2	CON	FIG001	00 HACH 4.0	10 .	2HI =	•	
Q=	4.56 PSI	RE PER	IN.= .481	E06 10= 90. C	EG.F	POJ/PT	rs =	•
PO	≥ 321.0 C	MHG PTS=	.4068 PS	S I	RUN NO	. 007036	9128	
ALPHA	EN	CM	CS	CY CR	CAT	CPB	CAF	ŔUN
4.05			-0.0065	0.0218-0.0027				235.
3.04			-0.0054	0.0127-0.0012				235.
2.02			-0.0056	0.0131-0.0007				235.
1.49			-0.0053	0.0121-0.0015				235.
0.99			-0.0038	-0.0013-0.0002				235.
0.47			-0.0055	0.0138-0.0010				235.
	0.0029		-0.0034	-0.0085 0.0013				235.
	-0.0272		-0.0039	0.0012-0.0003				235.
	-0-0705		-0.C037	-0.0002-0.0030				235.
	-0.0876	,	-0.0040	0.0030 0.0005				235.
	-0.1154		-0.0052	0.0128-0.0924				235.
	-0.1805		0.0004	-0.0317 0.0006				235.
-4.09	-0-2504	1.6763	0.0022	-0.0463-0.0016	0.1897	0.0663	0.1234	235.
	DEL 946.2		FIG000 :No≈ .488		•	≈ 1H9 Tq\1.09	•	
	OEL 946.2 4.56 PSI		FIG000 IN.= .48E		•	PHI ≈ POJ/PT	• S = 10	•
Q=	4.56 PSI	RE PER		:06 TO= 90. D	EG.F	_		•
Q=	4.56 PSI	RE PER	IN.= .48E	:06 TO= 90. D	EG.F	P0J/PT		• RUN
Q= P0=	4.56 PSI = 321.0 CI CN	RE PER MHG PTS= CM	IN.= .48E .4068 PS	E06 T0= 90. D SI CY CR	EG.F RUN NO.	POJ/PT • Di0036 CPB	9102 CAF	RUN
Q= PO: Alpha	4.56 PSI = 321.0 CI CN 0.2529	RE PER MHG PTS= CM -1.7271	IN.= .488 .4068 PS CS -0.0088	CY CR 0.0513-0.0031	EG.F RUN NO CAT 0.1587	POJ/PT • Di0036 CPB 0•0665	9102 CAF 0.0922	RUN 236.
Q= P0= Alpha 4.04	4.56 PSI = 321.0 C/ CN 0.2529 0.1867	RE PER MHG PTS= CM -1.7271 -1.2645	IN.= .48E .4068 PS	CY CR 0.0513-0.0031 0.0688-0.0015	EG.F RUN NO CAT 0.1587 0.1565	POJ/PT • Di0036 CPB 0.0665 0.0666	9102 CAF 0.0922 0.0899	RUN 236. 236.
Q= P0= ALPHA 4.04 3.04 2.02	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240	RE PER MHG PTS= CM -1.7271 -1.2645 -0.8478	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0.	EG.F RUN NO. CAT 0.1587 0.1565 0.1568	POJ/PT Di0036 CPB 0.0665 0.0666 0.0661	9102 CAF 0.0922 0.0899 0.0906	RUN 236. 236. 236.
Q= PO= ALPHA 4.04 3.04 2.02 1.49	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772	RE PER MHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0.0992-0.0008	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561	POJ/PT Di0036 CPB 0.0665 0.0666 0.0661 0.0657	9102 CAF 0.0922 0.0899 0.0906 0.0904	RUN 236. 236. 236. 236.
Q= PO= ALPHA 4.04 3.04 2.02 1.49 0.98	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636	RE PER MHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893 -0.4621	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0139	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0.0992-0.0008 0.0892-0.0008	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535	POJ/PT Di0036 CPB 0.0665 0.0666 0.0661 0.0657 0.0655	9102 CAF 0.0922 0.0899 0.0906 0.0904 0.0880	RUN 236. 236. 236. 236.
Q= P0= ALPHA 4.04 3.04 2.02 1.49 0.98 0.46	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636	RE PER MHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893 -0.4621 -0.0836	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0.0992-0.0008 0.0892-0.0005 0.0877-0.0008	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1528	POJ/PT Di0036 CPB 0.0665 0.0666 0.0657 0.0655 0.0655	9102 CAF 0.0922 0.0899 0.0906 0.0904 0.0880 0.0875	RUN 236. 236. 236. 236. 236.
Q= P0= ALPHA 4.C4 3.04 2.02 1.49 0.98 0.46 -0.04	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156	RE PER MHG PTS= CM -1.727i -1.2645 -0.8478 -0.4893 -0.4621 -0.0836 0.0066	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0139 -0.0137	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0. 0.0992-0.0008 0.0897-0.0008 0.0842-9.0006	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1528 0.1513	POJ/PT Di0036 CPB 0.0665 0.0666 0.0661 0.0657 0.0655 0.0652 0.0652	9102 CAF 0.0922 0.0899 0.0906 0.0906 0.0980 0.0875 0.0861	RUN 236. 236. 236. 236. 236. 236.
Q= P0= ALPHA 4.04 3.04 2.02 1.49 0.98 0.46 -0.04 -0.54	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156 -0.0027	RE PER MHG PTS= CM -1.727i -1.2645 -0.8478 -0.4893 -0.4621 -0.0836 0.0066 0.1776	IN.= .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0139 -0.0137	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0.0992-0.0008 0.0892-0.0005 0.0877-0.0008	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1528 0.1513 0.1528	POJ/PT Di0036 CPB 0.0665 0.0666 0.0661 0.0657 0.0655 0.0652 0.0652 0.0651	9102 CAF 0.0922 0.0899 0.0906 0.0906 0.0980 0.0875 0.0861 0.0874	RUN 236. 236. 236. 236. 236. 236. 236.
Q= P0= ALPHA 4.04 3.04 2.02 1.49 0.98 0.46 -0.04 -0.54 -1.05	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156 -0.0027 -0.0305	RE PER MHG PTS= CM -1.7271 -1.2645 -0.4893 -0.4893 -0.4893 -0.4893 0.0066 0.1776 0.3307	IN.= .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0137 -0.0136 -0.0147	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0. 0.0992-0.0008 0.0877-0.0008 0.0842-0.0006 0.0931-0.0003 0.1050 0.	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1528 0.1513 0.1526 0.1538	POJ/PT Di0036 CPB 0.0665 0.0666 0.0657 0.0655 0.0652 0.0652 0.0651 0.0652	9102 CAF 0.0922 0.0899 0.0906 0.0980 0.0875 0.0861 0.0874 0.0885	RUN 236. 236. 236. 236. 236. 236. 236. 236.
Q= P0= ALPHA 4.04 3.04 2.02 1.49 0.98 9.46 -0.04 -0.54 -1.05 -1.56	4.56 PSI = 321.0 CN CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156 -0.0027 -0.0305 -0.0560	RE PER MHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893 -0.46921 -0.0836 0.0066 0.1776 0.3307 0.6118	IN.= .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0137 -0.0136 -0.9147 -0.0164	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0. 0.0992-0.0008 0.0877-0.0008 0.0842-9.0006 0.0931-0.0003	EG.F RUN NO CAT 0.1587 0.1568 0.1561 0.1535 0.1528 0.1513 0.1528 0.1513	POJ/PT Di0036 CPB 0.0665 0.0661 0.0657 0.0655 0.0652 0.0652 0.0652 0.0652	9102 CAF 0.0922 0.0899 0.0906 0.0880 0.0875 0.0861 0.0874 0.0885 0.0863	RUN 236. 236. 236. 236. 236. 236. 236. 236.
Q= PO= ALPHA 4.04 3.04 2.02 1.49 0.98 0.46 -0.04 -0.54 -1.05 -1.56 -2.06	4.56 PSI = 321.0 CN CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156 -0.0027 -0.0305 -0.0560 -0.0944	RE PER HHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893 -0.4621 -0.0836 0.1076 0.1776 0.3307 0.6118 0.7186	IN.= .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0137 -0.0136 -0.9147 -0.0164 -0.0168	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0. 0.0992-0.0008 0.0877-0.0008 0.0842-0.0006 0.0931-0.0003 0.1050 0. 0.1110 0.0002	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1513 0.1513 0.1516	POJ/PT Di0036 CPB 0.0665 0.0666 0.0657 0.0655 0.0652 0.0652 0.0652 0.0651 0.0652 0.0654 0.0655	9102 CAF 0.0922 0.0899 0.0906 0.0880 0.0875 0.0861 0.0874 0.0885 0.0863 0.0885	RUN 236. 236. 236. 236. 236. 236. 236. 236.
Q= PO= ALPHA 4.04 3.04 2.02 1.49 0.98 0.46 -0.04 -0.54 -1.05 -1.56 -2.06 -3.08	4.56 PSI = 321.0 CI CN 0.2529 0.1867 0.1240 0.0772 0.0636 0.0156 -0.0027 -0.0305 -0.0305 -0.0944 -0.1151	RE PER HHG PTS= CM -1.7271 -1.2645 -0.8478 -0.4893 -0.4621 -0.0836 0.1066 0.1776 0.3307 0.6118 0.7186 1.1700	IN = .488 .4068 PS CS -0.0088 -0.0110 -0.0131 -0.0148 -0.0139 -0.0137 -0.0136 -0.9147 -0.0164 -0.0168 -0.0193	CY CR 0.0513-0.0031 0.0688-0.0015 0.0840 0. 0.0992-0.0008 0.0877-0.0008 0.0842-0.0006 0.0931-0.0003 0.1050 0. 0.1110 0.0002	EG.F RUN NO CAT 0.1587 0.1565 0.1568 0.1561 0.1535 0.1513 0.1526 0.1538 0.1516	POJ/PT Di0036 CPB 0.0665 0.0666 0.0657 0.0655 0.0652 0.0652 0.0652 0.0654 0.0655 0.0656	9102 EAF 0-0922 0-0899 0-0906 0-0880 0-0875 0-0861 0-0885 0-0885 0-0885 0-0873	RUN 236. 236. 236. 236. 236. 236. 236. 236.

MODEL 946.2	CONF	IG0000	HACH 4.0	00	PHI =	•
Q= 4.56 PSI	RE PER	IN.= .48E0	6 70= 90. 0	EG•F	POJ/PTS =	20.
PO= 321.0 C	HG PTS=	.4068 PSI		RUN NO.	0100369103	!
ALPHA CN	CH	CS	CY ČR	CAT	CPB CAF	RUN
4.04 0.2407	-1.6555		0.1506-0.0018			
3.03 0.1781	-1.2295		0.1427-0.0908			
2.01 0.1129		-0.0186	0.1352-0.0009			
1.49 0.0839		-0.0170	0.1210-0.0001			
0.97 0.0489 0.47 0.0188	-0.3600 -0.1553		0.0761-0.0002			
-D.04 -0.0279		-0.0114	0.0761-0.000			
-0.55 -0.0332		-0.0136	0.0948 0.000			
-1.06 -0.0764		-0.0134	0.0932-0.0001			
-1.57 -0.0936		-0.0100	0.0635 0.000			
-2.06 -0.1225		-0.0124	0.0880 0.0004			
-3.08 -0.1864		-0.0113	0.0806 0.0009			
-4.10 -0.2575	1.7003	-0.0038	0.0210 0.0017	r, 0.1757 (0.0659 0.10	98 237.
MODEL 946.2 D= 4.56 PSI		FIG00 <i>0</i> 0			PHI = POJ/PTS =	•
Q= 4.56 PSI	RE PER	IN-= -48E0	06 TO= 90. I	DEG.F	POJ/PTS =	40,
	RE PER	IN-= -48E0	06 TO= 90. I	DEG.F	_	40,
Q= 4.56 PSI	RE PER	IN-= -48E0	06 TO= 90. I	DEG.F	POJ/PTS =	40 ,
Q= 4.56 PSI PO= 321.0 CI ALPHA CN	RE PER MHG PTS=	.4068 PSI	06 TO= 90, I	DEG.F RUN NO. EAT	POJ/PTS = 0100369104 CPB CAR	40 , i. : RUN.
Q= 4.56 PSI PO= 321.0 CI	RE PER MHG PTS= CM -1.5481	.4068 PSI	06 TO= 90. I CY CR 0.1283-0.0000 0.1041 0.000	DEG.F RUN NO. CAT 2 0.1857 (3 0.1835 (POJ/PTS = 0100369104 CPB CAE 0.0674 0.11 0.0672 0.11	40, i. = RUN. 183 238. 162 238.
Q= 4.56 PSI PO= 321.0 CI ALPHA CN 4.63. 0.2250	RE PER MHG PTS= CM -1.5481 -1.0966	.4068 PSI CS -0.0183	06 T0= 90. I CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0000	CAT 2 0.1857 (3 0.1835 (2 0.1824 (POJ/PTS = 0100369104 CPB CAE 0.0674 0.11 0.0672 0.11 0.0666 0.11	40, i. RUN. 163 238. 162 238. 158 238.
Q= 4.56 PSI PO= 321.0 CI ALPHA CN 4.03. 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634	RE PER MHG PTS= CM -1.5481 -1.0966 -0.6871	.4068 PSI CS -0.0183 -0.0153	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0000 0.0882 0.0010	CAT 2 0.1857 (3 0.1835 (2 0.1824 (0 0.1815 (POJ/PTS = 0100369104 CPB CAE 0.0674 0.11 0.0666 0.11 0.0666 0.11	40, 6. RUN. 163 238. 162 238. 158 238.
Q= 4.56 PSI PO= 321.0 CI ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356	RE PER MHG PTS= CM -1.5481 -1.0966 -0.6871 -0.4480 -0.2691	.4068 PSI CS -0.0183 -0.0153 -0.0130 -C.0133 -0.0125	CY CR 0.1283-0.000; 0.1041 0.000; 0.0861 0.000; 0.0882 0.001; 0.0820 0.000	CAT 2 0.1857 (3 0.1835 (2 0.1824 (0 0.1815 (7 0.1804 (POJ/PTS = 0100369104 CPB CAB 0.0674 0.11 0.0672 0.11 0.0666 0.11 0.0661 0.11 0.0652 0.11	40, RUN. 163 238. 162 238. 158 238. 154 238. 146 238.
Q= 4.56 PSI P0= 321.0 CI ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126	RE PER MHG PTS= CK -1.5481 -1.0966 -0.6871 -0.4480 -0.2691 -0.1338	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -C.0133 -0.0125 -0.0111	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0010 0.0882 0.0010 0.0820 0.0000 0.0710 0.001	CAT 2 0.1857 (3 0.1835 (2 0.1824 (0 0.1815 (7 0.1804 (4 0.1790 (POJ/PTS = 0100369104 CPB CAB 0.0674 0.11 0.0672 0.11 0.0666 0.11 0.0661 0.11 0.0652 0.11 0.0657 0.11	40, RUN. 183 238. 162 238. 158 238. 154 238. 146 238. 134 238.
Q= 4.56 PSI P0= 321.0 CI ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280	RE PER MHG PTS= CM -1.5481 -1.0966 -0.6871 -0.4480 -0.2691 -0.1338 -0.2872	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -C.0133 -0.0125 -0.0111	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0000 0.0882 0.0010 0.0820 0.0000 0.0710 0.0010 0.0768 0.0010	CAT 2 0-1857 (8 0-1857 (8 0-1854 (0 0-1815 (0 0-1815 (0 0-1816 (0 0-1786 (0 0-1786 (POJ/PTS = 0100369104 CPB CAR 0.0674 0.11 0.0672 0.11 0.0666 0.11 0.0661 0.11 0.0657 0.12 0.0656 0.11	40, RUN. 163 238. 162 238. 158 238. 154 238. 146 238. 134 238. 130 238.
Q= 4.56 PSI P0= 321.0 CI ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280 -0.53 0.0542	RE PER MHG PTS= CK -1.5481 -1.0966 -0.6871 -0.4480 -0.2691 -0.1338 -0.2872 -0.5525	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -C.0133 -0.0125 -0.0111 -0.0117	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0001 0.0882 0.0010 0.0820 0.0001 0.0710 0.001 0.0768 0.0010 0.0768 0.0001	CAT 2 0.1857 (8 0.1835 (2 0.1824 (0 0.1815 (7 0.1804 (4 0.1790 (0 0.1786 (1 0.1730 (POJ/PTS = 0100369104 CPB CAR 0.0674 0.11 0.0666 0.11 0.0661 0.11 0.0650 0.11 0.0657 0.11 0.0654 0.16	40, RUN. 183 238. 162 238. 158 238. 154 238. 146 238. 134 238. 130 238. 176 238.
Q= 4.56 PSI P0= 321.0 CF ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280 -0.53 0.0542 -1.06 -0.0909	RE PER MHG PTS= CK -1.5481 -1.0966 -0.6871 -0.4480 -0.2691 -0.1338 -0.2872 -0.5525 0.6009	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -C.0133 -0.0125 -0.0111 -0.0117 -0.0111	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0001 0.0882 0.0010 0.0820 0.0001 0.0768 0.0010 0.0768 0.0010 0.07557 0.0010	CAT 2 0.1857 (8 0.1857 (9 0.1854 (1 0.1815 (1 0.1804 (1 0.1790 (1 0.1790 (1 0.1795 (1 0.17	POJ/PTS = 0100369104 CPB CAR 0.0674 0.11 0.0666 0.12 0.0661 0.12 0.0657 0.12 0.0656 0.12 0.0654 0.16 0.0655 0.12	40, 6. RUN. 163 238. 162 238. 158 238. 154 238. 134 238. 134 238. 130 228. 176 238. 141 238.
Q= 4.56 PSI P0= 321.0 CF ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280 -0.53 0.0542 -1.06 -0.0909 -1.57 -0.1200	RE PER MHG PTS= CK -1.5481 -1.0966 -0.6871 -0.4680 -0.2691 -0.1338 -0.2872 -0.5525 0.6009 0.7877	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -0.0133 -0.0125 -0.0111 -0.0117 -0.0111	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0001 0.0882 0.0010 0.0820 0.0001 0.0710 0.001 0.0768 0.0010 0.07557 0.0010 0.0483 0.0010	CAT 2 0.1857 (3 0.1857 (3 0.1835 (4 0.1815 (4 0.1790 (4 0.1790 (5 0.186 (6 0.1795 (6 0.1795 (6 0.184	POJ/PTS = 0100369104 CPB CA8 0.0674 0.11 0.0666 0.12 0.0650 0.12 0.0657 0.12 0.0654 0.16 0.0655 0.12 0.0655 0.12	40, RUN. 83 238. 862 238. 858 238. 854 238. 846 238. 846 238. 830 238. 841 238. 841 238.
Q= 4.56 PSI PO= 321.0 CI ALPHA CN 4.03. 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280 -0.53 0.0542 -1.06 -0.0909 -1.57 -0.1200 -2.07 -0.1358	RE PER MHG PTS= CK -1.5481 -1.0966 -0.6871 -0.4680 -0.2691 -0.1338 -0.2872 -0.5525 0.6009 0.7877 0.8477	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -0.0133 -0.0125 -0.0111 -0.0117 -0.0111 -0.0092 -0.0083 -0.0095	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0000 0.0882 0.0010 0.0820 0.0000 0.0710 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.0768 0.0010 0.00681 0.0003	CAT 2 0.1857 (3 0.1857 (3 0.1835 (2 0.1824 (0 0.1815 (0 0.1804 (0 0.1786 (1 0.1786 (1 0.1786 (1 0.1785 (2 0.1845 (1 0.1769 (POJ/PTS = 0100369104 CPB CAR 0.0674 0.11 0.0666 0.11 0.0650 0.11 0.0654 0.16 0.0655 0.11 0.0655 0.11 0.0655 0.11	40, RUN. 83 238. 862 238. 858 238. 854 238. 846 238. 834 238. 830 238. 830 238. 841 238. 841 238. 841 238.
Q= 4.56 PSI P0= 321.0 CF ALPHA CN 4.03 0.2250 3.03 0.1599 2.01 0.0984 1.49 0.0634 0.98 0.0356 0.47 0.0126 -0.03 0.0280 -0.53 0.0542 -1.06 -0.0909 -1.57 -0.1200	RE PER MHG PTS= CM -1.5481 -1.0966 -0.6871 -0.4480 -0.2691 -0.1338 -0.2872 -0.5525 0.6009 0.7877 0.8477 1.2746	IN-= .48E0 .4068 PSI CS -0.0183 -0.0153 -0.0130 -0.0133 -0.0125 -0.0111 -0.0117 -0.0111	CY CR 0.1283-0.0000 0.1041 0.0000 0.0861 0.0001 0.0882 0.0010 0.0820 0.0001 0.0710 0.001 0.0768 0.0010 0.07557 0.0010 0.0483 0.0010	CAT 2 0.1857 (3 0.1857 (3 0.1835 (4 0.1804 (4 0.1790 (5 0.1795 (6 0.1796 (6 0.1797 (7 0.1845 (6 0.1769 (7 0.1771 (7 0.17	POJ/PTS = 0100369104 CPB CAE 0.0674 0.11 0.0666 0.11 0.0652 0.11 0.0654 0.16 0.0654 0.16 0.0655 0.11 0.0655 0.11 0.0655 0.11 0.0655 0.11	40, RUN. 163 238. 162 238. 158 238. 154 238. 134 238. 130 238. 131 238. 141 238. 141 238. 141 238. 141 238.

MO	DDEL 946.2	CON	FIG0000	н	ACH 4.0	0	PHI =	•	
Q:	= 4.56 PSI	RE PEŔ	IN.= .48E0	6 TC=	90. 0	EG.F	901/6	TS = 10	G.
P	D= 321.0 CH	HG PTS=	.4068 PSI			RUN NO	01003	69105	
ALPH	A CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.0	2 0.1768	-1.1886	-0:0154		-0.0005				239.
3.0		-0.7521	-0.0143		-0.0016				239.
1.99	0.0514	-0.3396	-0.0152	0.0994	-0.0001	0.1869	0.0666	0.1203	239.
1.48	0.0128	-0.0668	-0.0110		0.0001				239.
0.97	7 -0.0029	0.0254	-0.0124	0.0783	0.0003	0.1880	0.0660	0.1220	239.
0.40	5 -0.0344	0.2134	-0.0094	0.0530	0.0011	0.1858	0.0658	0.1200	239.
-0.09	0.0049	-0.1538	-0.0110	0.0660	0.CO07	0.1847	0.0657	0ä1191	239•
-0.56	5 -0.1089	0.7598	-0.0090	0.0512	0.0005	0.1850	0.0654	0.1197	239.
-1.07	7 -0.1308	0.8712	-0.0094		0.0013				239.
-1.59	-0.1539	1.0000	-0.0079	0.0452	0.0015	0.1838	0.0653	0.1185	239.
-2.09	-0.1829	1.1884	-0.0064	0.0332	0.0012	0.1826	0.0650	0.1176	239.
-3.10	0.2432	1.5962	-0.0042	9.0160	0.0017	0.1815	0.0647	0.1168	239.
-4.11	-0.3131	2.0857	0.0009 -	-0.0209	0.0020	0.1843	0.0651	0.1192	239.
ME	DEL 946.2	CONI	FIG0000	M	ACH 4.01	D	PHI =	15.	
Q=	= 4.56 PST	RE PER	IN.= .48E0	6 T0=	90. DI	EG.F	POJ/P	TS =	•
P)= 321.0 CM	HG PTS=	.4068 PSI			RUN NO.	. 01003	69106	
ALPH	CN CN	CH	CŚ	CY	CR	CAT	CPB	CAF	RUN
4.24	0.2135	-1.3803	-0.0199	0.1363	0.0003	0.1791	0.0665	0.1126	240.
3.24		_	~0.0060		0.0003				240.
2.22			-0.0064		0.000°				240.
1.70			-0.0054		0.0006				240.
1.19			-0.0061		0.0007				240.
0.69	-		-0.0067		0 0008				240.
0.17			-0.0065		0-0003				240.
	-0.0173		-0.0072		0.0004				240.
	-0.0477		-0.0057		0.0005				240.
	-0.0779		-0.0048		0.0001				240.
	-0.1090		-0.0054		0.0002				240.
	-0.1762		-0.0060		0.0009				240.
	-0-2447		-0.0064		0.0005				240.

MODE	L 946.2	CONF	IG00	00 M	NEH 4.00	PHI =	15.	
Q= 4	-56 PSI	RE PER	IN.= .48	E06 70=	90. DEG.F	P01/P1	(S _j =	10.
P0=	321.0 CMH	IG PTS=	-4068 P	SI	RUN N	C. 010036	9107	
ALPHA	CN	ĈĦ	cs	CY	CR CAT	CPB	CAF	RUN
4.25	0.2574	-1.7448	-0.0122	0.0784	0.0023 0.175	2 0.0667	0.1085	241.
	0.1909	-1.2824	-0.0107		0.0025 0.174			
	0.1282	-0.8574	-0.0096		0.0021 0.172			
	0.0960	-0.6482			0.0017 0.170			
1.19	-	-0.4314			0.0023 0.173			
0.68		-0.2499			0.0024 0.171			
C.17			-0.0103		0.0025 0.170			
-0,34 -			-0.0110		0.0042 0.169			
-0:84 -			-0.0092		0.0032 0.171			
-1.35 -			-0.0099		0.0049 0.170			
-1.87 -			-0.0101		0.0050 0.170			
-2.88 -			-0.0102		0.0046 0.174			
-3.90 -	0.2433	1.0438	~0.0078	0.0408	0.0053 0.173	2 0.0008	0-1508	241.
	L 946.2		FIG00		ACH 4.00 90. DEG.F	PHI =	15., rs = ,	
Q= 4		RE PER	IN.= .48	IE06 TO=	96. DEG.F		rs = .	
Q= 4	.56 PSI	RE PER	IN.= .48	IE06 TO=	96. DEG.F	bol\b.	rs = .	
Q= 4 PO= ALPHA	.56 PSI 321.0 CMH	RE PER IG PTS=	IN.= .48	E06 T0= PSI CY	90. DEG.F RUÑ N CR CAT	PØJ/P 0. 010036 CPB	TS = , 59108- CAF	20• RUN
Q= 4 PO= ALPHA 4.25	.56 PSI 321.0 CMH CN 0.2504	RE PER IG PTS= CM -1.7018	IN.= .48 .4068 F CS -0.0145	E06 T0= SI CY 0.0962	96. DEG.F RUÑ N CR CAT 0.0003 0.178	POJ/P	TS =	20. RUN 242.
Q= 4 PO= ALPHA 4.25 3.24	.56 PSI 321.0 CMH CN 0.2504 0.1855	RE PER HG PTS= CM -1.7018 -1.2518	IN.= .48	CY 0.0962 0.0895	90. DEG.F RUÑ N CR CAT	POJ/P 0. 010036 CPB 0 0.0669 6 0.0668	TS =	20. RUN 242. 242.
Q= 4 PO= ALPHA 4.25 3.24 2.22	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225	RE PER IG PTS= CH -1.7018 -1.2518 -0.8268	IN.= .48 .4068 F CS -0.0145	0.0962 0.095 0.0725	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175	POJ/P 0. 010036 CPB 0 0.0669 6 0.0668 7 0.0664	CAF 0.1111 0.1388 0.1093	20. RUN 242. 242. 242.
Q= 4 PO= ALPHA 4.25 3.24 2.22	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122	0.0962 0.0962 0.095 0.0725 0.0890	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175	POJ/P 0. 010036 CPB 0 0.0669 6 0.0668 7 0.0664 4 0.0660	S = 59108 CAF 0.1111 0.1388 0.1093 0.1093	20. RUN 242. 242. 242. 242.
Q= 4 PO= ALPHA 4.25 3.24 2.22 1.69	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0140	CY 0.0962 0.0895 0.0725 0.0890 0.0953	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 -0.0003 0.172	POJ/P 0. 010036 CPB 0 0.0669 6 0.0668 7 0.0664 4 0.0660 3 0.0658	CAF 0.1111 0.1388 0.1093 0.1064 0.1066	20. RUN 242. 242. 242. 242. 242.
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0140 -0.0147	CY 0.0962 0.0725 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0003 0.172 0.0009 0.177 0.0010 0.173	POJ/P 0. 010036 CPB 0.0669 6.0664 4.0660 3.0658 3.0655 0.0656	CAF CAF 0.1111 0.1064 0.1064 0.1166 0.1116	RUN 242. 242. 242. 242. 242. 242. 242.
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0140 -0.0147 -0.0138	CY 0.0962 0.0725 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 -0.0003 0.172 0.0003 0.172	POJ/P 0. 010036 CPB 0.0669 6.0664 4.0660 3.0658 3.0655 0.0656	CAF CAF 0.1111 0.1064 0.1064 0.1166 0.1116	RUN 242. 242. 242. 242. 242. 242. 242. 242
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68 0.17	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012 0.0273	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242 0.15781	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0147 -0.0138 -0.0114 -0.0121	CY 0.0962 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655 0.0733	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0009 0.177 0.0010 0.173 0.0006 0.171 0.0023 0.173	POJ/P 0. 010036 CPB 0.0669 6.0.0668 7.0.0656 0.0656 3.0.0656 5.0.0656 0.0656 0.0656	CAF CAF 0.1111 0.1083 0.1064 0.1066 0.1166 0.1079	RUN 242. 242. 242. 242. 242. 242. 242. 242
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68 0.17 -0.34 -0.85 -1.36	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012 0.0273 0.0595 0.0861	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242 0.15781	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0147 -0.0138 -0.0114 -0.0121	CY 0.0962 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655 0.0733 0.0802 0.0672	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0009 0.177 0.0010 0.173 0.0006 0.171 0.0023 0.173 0.0024 0.173	POJ/P 0. 010036 CPB 0. 0.0669 6 0.0668 7 0.0664 4 0.0660 3 0.0656 5 0.0656 6 0.0656 3 0.0656	CAF CAF 0.1111 0.1088 0.1093 0.1064 0.1166 0.1079 0.1055 0.1079	RUN 242. 242. 242. 242. 242. 242. 242. 242
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68 0.17 -0.34 -	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012 0.0273 0.0595 0.0861	RE PER IG PTS= CH -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242 0.1578 0.3781 0.5413 0.7400	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0147 -0.0138 -0.0118 -0.0122	CY 0.0962 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655 0.0733 0.0802 0.0672 0.0726	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0003 0.172 0.0009 0.177 0.0010 0.173 0.0006 0.171 0.0023 0.173 0.0024 0.173 0.0009 0.173	POJ/P 0. 010036 CPB 0.0669 6.0.0668 7.0.0660 3.0.0658 3.0.0656 0.0656 6.0.0656 3.0.0657	CAF 0.1111 0.1988 0.1093 0.1064 0.1066 0.1179 0.1055 0.1078 0.1078	RUN 242. 242. 242. 242. 242. 242. 242. 242
Q= 4 PO= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68 0.17 -0.85 - -1.87 - -2.87 -	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012 0.0273 0.0595 0.0861 0.1160 0.1774	RE PER IG PTS= CM -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242 0.1578 0.3781 0.5413 0.7400 1.1514	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0147 -0.0138 -0.0114 -0.0121 -0.0130 -0.0118 -0.0122 -0.0114	CY 0.0962 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655 0.0733 0.0802 0.0672 0.0726	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0009 0.177 0.0010 0.173 0.0006 0.171 0.0004 0.173 0.0004 0.173 0.0006 0.173	POJ/P 0. 010036 CPB 0.0669 6.0668 7.0.0664 4.0.0660 3.0.0658 3.0.0656 0.0656 0.0656 3.0.0657 5.0.0658	CAF 0.1111 0.1388 0.1093 0.1064 0.1066 0.1166 0.1079 0.1055 0.1077	RUN 242- 242- 242- 242- 242- 242- 242- 242
Q= 4 P0= ALPHA 4.25 3.24 2.22 1.69 1.19 0.68 0.17 -0.34 -0.85 -1.36 -1.87	.56 PSI 321.0 CMH CN 0.2504 0.1855 0.1225 0.0869 0.0583 0.0281 0.0012 0.0273 0.0595 0.0861 0.1160 0.1774	RE PER IG PTS= CH -1.7018 -1.2518 -0.8268 -0.5883 -0.3993 -0.2005 -0.0242 0.1578 0.3781 0.5413 0.7400	IN.= .48 .4068 P CS -0.0145 -0.0140 -0.0122 -0.0147 -0.0138 -0.0114 -0.0121 -0.0130 -0.0118 -0.0122 -0.0114	CY 0.0962 0.0895 0.0725 0.0890 0.0953 0.0881 0.0655 0.0733 0.0802 0.0672 0.0726	90. DEG.F RUN N CR CAT 0.0003 0.178 0.0005 0.175 0.0001 0.175 0.0003 0.172 0.0003 0.172 0.0009 0.177 0.0010 0.173 0.0006 0.171 0.0023 0.173 0.0024 0.173 0.0009 0.173	POJ/P 0. 010036 CPB 0.0669 6.0668 7.0.0664 4.0.0660 3.0.0658 3.0.0656 0.0656 0.0656 3.0.0657 5.0.0658	CAF 0.1111 0.1388 0.1093 0.1064 0.1066 0.1166 0.1079 0.1055 0.1077	RUN 242- 242- 242- 242- 242- 242- 242- 242

H	ODE	L 946.2	2	CON	FIG.	•00,00	н	ACH 4.0	0	PHI =	25.	
Q	= 4	.56 PS1	RE	PER	[N.=	.4820	5 YO=	90. D	EG.F	P0J/P	TS ≐	40.
Р	0= :	321.0 0	MHG	PTS=	-406	129 88			RUN NO	. 01003	69109	
ALPH	A	CN	c	Ħ	C:	5	CY	CR	CAT	C98	CAF	RUN
4.2	4 1	0.2348	-1.	5947	-0.01	169	0.1106	0.0019	0.1860	0-0670	0.119	L 243.
		0.1672			-0.01		0.0989	0.0016	0.1813	0.0671	0.1142	2 243.
2.2		0.1056			-0.0				0.1789			
1.6		0.0621			-0.0				0.1793			
-		0.0457	_		-0.0	-	0.0839	0.0020	0.1778	0.0659	0.111	243.
0.5		0.0202			-0.0		0.0678	0.0041	0.1790	0.0658	0.113	2 243.
		0.0166	Ō.	1081	-0.0	144	0.0852	0.0026	0.1766	0.0657	0.1109	243.
-0.3	5 -	0.0421	0.	2597	-0.0	130	0.0718	0.0027	0.1790	0.0657	0.113	3 243.
		0.0745			-0.0		0.0732	0.0018	0.1790	0.0657	0.113	3 243.
-1.3	7 -	0.1045			-0.0		0.1111	0.0019	0.1779	0.0657	0.112	2 243.
		0.1271			-0.0	_	0.0685	0.0046	.0.1801	0.0657	0.1144	4 243.
		0.1923	-		-0.0				0.1790			
-3.9	0 -	0.2624	ī.	7522	-0.01	105			0.1804			
н	ODE	L 946.2	:	CONF	FIG.	.0000	H	ACH 4.0	0	PHI =	15.	-
		L 946.2				-0000		ACH 4.0			15. TS = 1	100.
q	= 4		R.E	PER	IN.=				EG.F		TS = 1	100.
q	= 4 0= :	.56 PSI	R.E	PER PTS=	IN.=	•48E06			EG.F	POJ/P	TS = 1	LOO. RUN
Q P	= 4. 0= :	.56 PSI 321.0 C	RE ∰HG Ć	PER PTS=	ÎN.=.	•48E06 58 P.SI	5 TO=	90. D	EG.F RUN NO	POJ/P 01003 CPB	TS = 1 69110 CAF	RUN
Q P AL?H	= 4: 0= : A	.56 PSI 321.0 C	RE ∰HG Ć	PER PTS= M 2398	ÎN.=- -406 CS	•48E06 58 P.SI 5	čY 0.2094	90. D	EG.F RUN NO CAT	POJ/P 01003 CPB 0-0673	TS = 1 69110 CAF 0.1220	RUN) 244•
P ALPH 4-2	= 4. 0= : A 3 ()	.56 PSI 321.0 C CN 0.1872	RE MHG C -1.	PER PTS= M 2398 2421	ÎN.=. .406 CS	•48E06 58 P.SI 5 298 504	ČY 0.2094 0.2154	90. D	EG.F RUN NO CAT	POJ/P 01003 CP8 0.0673 0.0675	TS = 1 69110 CAF 0.1220 0.1255	RUN 0 244. 5 244.
4.2 4.2	= 4. 0= : A 3 (3)	.56 PSI 321.0 C CN 0.1872 0.1874	RE MHG C -1. -1.	PER PTS= M 2398 2421 7979	.406 CS -0.02	•48E06 58 P.S.I 50 298 504 272	CY 0.2094 0.2154 0.1836	90. D CR 0.0017 0.0018	EG.F RUN NO CAT 0.1893- 0.1930	POJ/P 01003 CPB 0.0673 0.0675 0.0674	TS = 1 69110 CAF 0.1220 0.1251	RUN 244. 5 244. L 244.
4.2 4.2 4.2 3.2	= 4. 0= : A 3 () 2 ()	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228	RE MHG C -1. -1. -0.	PER PTS= M 2398 2421 7979 3880	.400 CS -0.02 -0.03	•48E06 58 P.SI 5 298 504 272 264	CY 0.2094 0.2154 0.1836 0.1714	90. D CR 0.0017 0.0018 0.0018	EG.F RUN NO. CAT 0.1893- 0.1930 0.1906	POJ/P . 01003 CPB 0.0673 0.0675 0.0674 0.0668	TS = 1 69110 CAF 0.1220 0.1255 0.1231	RUN 244. 5 244. L 244.
9 P ALVH 4.2 4.2 3.2 2.2	= 4. 0= : A 3 (3. 2 (0. 9)	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614	RE HHG C -1. -0. -0.	PER PTS= M 2398 2421 7979 3880 2248	1N.=- .406 C3 -0.02 -0.03 -0.02	• 48 E 06 58 P.SI 50 298 504 272 264 227	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603	90. D. CR 0.0017-0.9011 0.6018 0.0010 0.0016	CAT 0.1893 0.1930 0.1930 0.1906 0.1882 0.1882 0.1885	POJ/P . 01003 . CP8 0.0673 0.0675 0.0674 0.0668 0.0663 0.0661	TS = 1 69110 CAF 0.1226 0.1255 0.1214 0.1214	RUN 244. 5 244. L 244. 6 244. 9 244.
9 P ALVH 4.2 4.2 3.2 2.2 1.6	= 4 0= : A 3 (3 2 (0 9 (6	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340	RE C-1. -1. -0. -0.	PER PTS= M 2398 2421 7979 3880 2248 0339	IN-=	• 48 E 06 58 P.S.I. 50 298 504 272 264 227 252	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384	90. D CR 0.0017 0.0018 0.0018 0.0010 0.0016 0.0011	CAT 0.1893 0.1930 0.1906 0.1882 0.1882 0.1859 0.1870	POJ/P . 01003 . CP8 0.0673 0.0675 0.0674 0.0668 0.0663 0.0661 0.0659	TS = 1 69110 CAF 0.1220 0.1255 0.1214 0.3245 0.1198	RUN 244. 5 244. 6 244. 6 244. 8 244.
4.2 4.2 4.2 3.2 2.2 1.6 1.1	= 4 0= : A 3 (3 2 (0 6 -(6	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013	RE #HG C -1. -0. -0. 0. 0.	PER PTS= M 2398 2421 7979 3880 2248 0339 1879	1N -= .406 C5 -0.02 -0.02 -0.02 -0.02 -0.02	.48E06 58 P.SI 504 272 264 277 232	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384 0.1476	90. D. CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0018	CAT 0.1893 0.1930 0.1906 0.1882 0.1882 0.1859 0.1870 0.1871	POJ/P 01003 CP8 0.0673 0.0675 0.0668 0.0663 0.0661 0.0659 0.0657	TS = 1 69110 CAF 0.1220 0.1255 0.1214 0.3214 0.3198 0.1211	RUN 244. 244. 244. 244. 244. 244. 244. 244
4.2 4.2 3.2 2.2 1.6 1.1 0.6	= 4 0= : A 3 (3 2 (0 6 -1 6 -1 5 -1	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013 0.0270	RE 5HG -1. -0. -0. 0.	PER PTS= M 2398 2421 7979 3880 2248 0339 1879 4122	IN -= .406 C5 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02	.48E06 58 P.SI 504 272 264 277 252 231	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384 0.1476	90. D. CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0018	CAT 0.1893 0.1930 0.1906 0.1882 0.1882 0.1859 0.1870	POJ/P 01003 CP8 0.0673 0.0675 0.0668 0.0663 0.0661 0.0659 0.0657	TS = 1 69110 CAF 0.1220 0.1255 0.1214 0.3214 0.3198 0.1211	RUN 244. 244. 244. 244. 244. 244. 244. 244
4.2 4.2 3.2 2.2 1.6 0.1 -0.3	= 4 0= : A 3 (1 3 (1 6 -1 5 -1 5 -1	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013 0.0270 0.0591	RE 644G -1. -0. -0. 0. 0.	PER PTS= 398 2421 7979 3880 2248 0339 1879 4122 6835	IN.=406 CS -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02	.48E06 58 P.SI 504 272 264 277 252 231 241	CY 0.2094 0.2154 0.1339 0.1603 0.1384 0.1476 0.1606	90. D CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0018 0.0024 0.0024	CAT 0.1893 0.1930 0.1906 0.1882 0.1882 0.1859 0.1870 0.1871	POJ/P 01003 CP8 0.0673 0.0674 0.0668 0.0663 0.0661 0.0659 0.0657	TS = 1 69110 CAF 0.1220 0.1231 0.1214 0.1214 0.1213 0.1213	RUN 244. 244. 244. 244. 244. 244. 244. 244
4.2 4.2 3.2 2.2 1.6 0.1 -0.3	= 4 0= : A 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013 0.0270 0.0591 0.0962	RE -1. -0. -0. 0. 0.	PER PTS= 2398 2421 7979 3880 339 1879 4122 6835 8781	IN.=406 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02	.48E06 58 P.SI 504 272 264 227 231 241 251 267	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384 0.1476 0.1779	90. D CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0018 0.0024 0.0024	EG.F RUN NO. CAT 0.1893 0.1930 0.1906 0.1882 0.1859 0.1859 0.1871 0.1871 0.1876 0.1860 0.1837	POJ/P 01003 CP8 0.0673 0.0675 0.0674 0.0668 0.0663 0.0657 0.0655 0.0655	TS = 1 69110 CAF 0.1226 0.1237 0.1214 0.1215 0.1215 0.1215 0.1215 0.1205 0.1182	RUN 244. 5 244. 6 244. 6 244. 8 244. 8 244. 8 244. 8 244.
4.24.23.22.1.66.1.10.60.11-0.38-0.88-1.3	= 4 0= : A 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013 0.0270 0.0591 0.0962 0.1257	RE COMMG	PER PTS= 2398 2421 7979 3880 0339 1879 4122 6835 8781 0908	IN.= -406 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02 -0.02	.48E08 58 P.SI 504 272 264 27 232 231 241 251 267 294	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384 0.1476 0.1604 0.1779 0.1997	90. D CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0024 0.0024 0.0024 0.0026 0.0026	CAT 0.1893 0.1930 0.1906 0.1882 0.1859 0.1871 0.1871 0.1860 0.1837 0.1845	POJ/P 01003 CPB 0.0673 0.0675 0.0674 0.0668 0.0663 0.0661 0.0659 0.0655 0.0655 0.0654 0.0653	TS = 10 CAF 0.1220 0.1231 0.1214 0.1215 0.1215 0.1215 0.1215 0.1205 0.1185 0.1195	RUN 244. 244. 244. 244. 244. 244. 244. 244. 244. 244. 244. 244.
4.24.23.22.1.66.1.10.66.10.38.1.33.1.33.1.33	= 4 0= : A 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	.56 PSI 321.0 C CN 0.1872 0.1874 0.1228 0.0614 0.0340 0.0013 0.0270 0.0591 0.0962 0.1257	RE -1. -0. -0. -0. 0. 0.	PER PTS= M 2398 2421 7979 3880 2248 0339 1879 4122 68781 0908 1404	IN-=	.48E06 58 P.SI 504 272 264 227 232 231 241 251 267 294 225	CY 0.2094 0.2154 0.1836 0.1714 0.1339 0.1603 0.1384 0.1476 0.1604 0.1779 0.1997	90. D CR 0.0017 0.0018 0.0010 0.0016 0.0011 0.0024 0.0024 0.0024 0.0026 0.0026	EG.F RUN NO. CAT 0.1893 0.1930 0.1906 0.1882 0.1859 0.1859 0.1871 0.1871 0.1876 0.1860 0.1837	POJ/P 01003 CPB 0.0673 0.0675 0.0674 0.0668 0.0663 0.0661 0.0659 0.0655 0.0655 0.0654 0.0653	TS = 10 CAF 0.1220 0.1231 0.1214 0.1215 0.1215 0.1215 0.1215 0.1205 0.1185 0.1195	RUN 244. 244. 244. 244. 244. 244. 244. 244. 244. 244. 244. 244.

MODEL 946.2	CON	FIG. 200	DO MAC	H 4.00	PHĮ =	30.	
Q= 4.56 PSI	RE PER	IN.= .48!	E06 TO≖	90. DEG.F	POJ/PT	S =	•
PO= 321.0 C	MHG PTS=	.4068 P	sı	RUN NO	. 010036	9111	
ALPHA CN	CH	CS	·CY	CR CAT	CPB	CAF	RUN
4-15 0-2617	-1.7730	0.0075	~0 •0599~0	0.0018-0.1787	0.0666	0.1120	245.
3.15 0.1936	-1.2953			0.0014 0.1747			245.
2-13 0-1278	-0.8446			,0016 0,1733			245.
1.61 0.0965	-0.6423			0.0016 0.1722			245.
1.10 0.0653	-0.4375			.0004 0.1709			245.
0.58 0.0354	-0.2391			.0017 0-1720			245.
0.08 0.0045	-0.0314			.0007 0.1731			245.
-0.43 -0.0223	0.1385	0.0055		.0028 D.1729			245.
-0.94 -0.0566	0.3801			.0008 0.1716			245.
-1:45 -0:0902	0.6130	-		0.0004 0-1716			245.
-1.95 -0.1104	0.7159			.0004 0.1736			245.
-2.96 -0.1691	1.0972			.0011 0.1745			245.
-3.98 -0.2463	1:6560	0.0033	-0.0736 0	.0009 0.1782	0.0667	0.1115	245.
MODEL 946.2 Q≈ 4.56 PSI		FIG09(IN.≅ .488	-	H 4.00 90: DEG.F	PHI =	30. 'S = 1	0.
	RE PER		:06 TO=	90: DEG.F		s = 1	0.
Q= 4.56 PSI	RE PER	IN.≅ .486	:06 TO=	90: DEG.F	79\L09	s = 1	O. RUN
0= 4.56 PSI P0= 321.0 C	RE PER MHG PTS=	IN.= .488	ĆĀ 21 509 £0≠	90: DEG.F RUN NO. CR CAT	POJ/PT - 010036 CPB	S = 1 9112 C45	ŔÚŊ
Q≈ 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567	RE PER MHG PTS= CM -1-7490	1N.≅ .486 .4068 PS CS 0.0041	06 T0± 51 ÇY -0.0912 0	90: DEG.F RUN NO. CR CAT	POJ/PT - 010036 CP8 -0.0669	S = 1 9112 C45 G.1061	RÚN 246 •
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869	RE PER MHG PTS=	IN.≅ .488 .4068 PS	06 T0± 51 ÇY -0.0912 0 -0.1168-0	90: DEG.F RUN NO. CR CAT 0.0004 0.1730	POJ/PT • 010036 CP8 • 0.0669	S = 1 9112 C4F G-1061 0-1045	RÚN 246 - 246 -
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869	RE PER MHG PTS= CM -1.7490 -1.2546	1N.= .486 .4068 PS CS 0.0041 0.0069	CY -0.0912 0 -0.1168-0 -0.1181 0	90: DEG.F RUN NO CR CAT 0:004 0:1730 0:003 0:1714 0:001 0:1676	POJ/PT - 010036 - CP8 - 0.0669 - 0.0569 - 0.0664	S = 1 9112 C45 G-1061 0-1045 9-1012	RÚN 246 • 246 • 246 •
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343	1N.= .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.0003 0.1714 0.0005 0.1700	POJ/PT . 010036 CP8 0.0669 0.0469 0.0664 0.0658	S = 1 9112 C4F G-1061 0-1045 9-1012 0-1042	RUN 246 • 246 • 246 • 246 •
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110	IN. ≈ .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1246-0	90: DEG.F RUN NO CR CAT 0:004 0:1730 0:003 0:1714 0:001 0:1676	POJ/PT . 010036 CP8 0.0669 0.0569 0.0664 0.0658 0.0657	S = 1 9112 C4F G-1061 0-1045 9-1012 0-1042 0-1042	RUN 246 • 246 • 246 • 246 • 246 •
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155	IN. ≈ .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.003 0.1714 0.0001 0.1676 0.0005 0.1700 0.0004 0.1709	POJ/PT . 010036 CP8 0.0669 0.0569 0.0664 0.0658 0.0657 0.0655	S = 1 9112 CAF G.1061 0.1045 0.1012 0.1042 0.1042	RÚN 246. 246. 246. 246. 246. 246.
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211	IN. ₹ .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0 -0.1515 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.0005 0.1714 0.0005 0.1709 0.0004 0.1709 0.0004 0.1709 0.0003 0.1694	POJ/PT . 010036 CP8 0.0669 0.0669 0.0659 0.0657 0.0655 0.0655	S = 1 9112 CAF G.1061 0.1045 0.1012 0.1042 0.1042 0.1055 0.1040	RUN 246 • 246 • 246 • 246 • 246 •
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315 0.08 0.0049	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211 -0.0524	IN.= .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085 0.0113	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0 -0.1515 0 -0.1387 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.003 0.1714 0.0001 0.1676 0.0005 0.1700 0.0004 0.1709	POJ/PT - 010036 CP8 - 0.0669 - 0.0664 0.0658 0.0657 0.0655 0.0655	S = 1 9112 CAF G-1061 0-1045 0-1042 0-1042 0-1055 0-1040 0-1039	RUN 246. 246. 246. 246. 246. 246. 246.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315 0.08 0.0049 -0.43 -0.0277	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211 -0.0524 0.1705	IN.= .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085 0.0113 0.0101	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1277 0 -0.1387 0 -0.1429 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.0005 0.1714 0.0005 0.1700 0.0004 0.1709 0.0004 0.1709 0.0003 0.1694 0.0013 0.1694	POJ/PT - 010036 - CP8 - 0.0669 - 0.0664 - 0.0658 - 0.0657 - 0.0655 - 0.0654 - 0.0656	S = 1 9112 C45 G-1061 0-1045 0-1042 0-1042 0-1055 0-1040 0-1039 0-1048	RUN 246. 246. 246. 246. 246. 246. 246. 246.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315 0.08 0.0049 -0.43 -0.0277 -0.94 -0.0558	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211 -0.0524 0.1705 0.3505	1N.= .486 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085 0.0113 0.0101 0.0106	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0 -0.1515 0 -0.1387 0 -0.1411 0 -0.1370 0	90: DEG.F RUN NO CR CAT 0.004 0.1730 0.003 0.1714 0.005 0.1676 0.005 0.1709 0.001 0.1694 0.003 0.1694 0.001 0.1704 0.001 0.1704 0.001 0.1704	POJ/PT - 010036 - CP8 - 0.0669 - 0.0669 - 0.0658 0.0657 0.0655 0.0654 0.0654 0.0657 0.0657	S = 1 9112 C47 G-1061 0-1045 9-1012 0-1042 0-1042 0-1045 0-1048 0-1046 0-1056	RUN 246. 246. 246. 246. 246. 246. 246. 246.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315 0.08 0.0049 -0.43 -0.0277 -0.94 -0.0558 -1.45 -0.0864	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211 -0.0524 0.1705 0.3505 0.5502 0.7653 1.1777	1N.= .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085 0.0113 0.0101 0.0106 0.0105 0.0103	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0 -0.1515 0 -0.1387 0 -0.1411 0 -0.1370 0	90: DEG.F RUN NO CR CAT 0.0004 0.1730 0.0005 0.1676 0.0005 0.1699 0.0004 0.1709 0.0003 0.1694 0.0018 0.1704 0.0012 0.1703	POJ/PT - 010036 - CP8 - 0.0669 - 0.0669 - 0.0658 0.0657 0.0655 0.0654 0.0654 0.0657 0.0657	S = 1 9112 C47 G-1061 0-1045 9-1012 0-1042 0-1042 0-1045 0-1048 0-1046 0-1056	RUN 246. 246. 246. 246. 246. 246. 246. 246.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.15 0.2567 3.15 0.1869 2.13 0.1242 1.60 0.0906 1.09 0.0610 0.58 0.0315 0.08 0.0049 -0.43 -0.0277 -0.94 -0.0558 -1.45 -0.0864 -1.95 -0.1183	RE PER MHG PTS= CM -1.7490 -1.2546 -0.8343 -0.6110 -0.4155 -0.2211 -0.0524 0.1705 0.3505 0.5502 0.7653	1N.= .488 .4068 PS CS 0.0041 0.0069 0.0072 0.0099 0.0081 0.0085 0.0113 0.0101 0.0105 0.0103	CY -0.0912 0 -0.1168-0 -0.1181 0 -0.1438 0 -0.1277 0 -0.1515 0 -0.1429 0 -0.1411 0 -0.1370 0 -0.1519 0	90: DEG.F RUN NO CR CAT 0.004 0.1730 0.003 0.1714 0.005 0.1676 0.005 0.1709 0.001 0.1694 0.003 0.1694 0.001 0.1704 0.001 0.1704 0.001 0.1704	POJ/PT - 010036 - CP8 - 0.0669 - 0.0669 - 0.0658 0.0657 0.0655 0.0656 0.0656 0.0657 0.0659 0.0657	S = 1 9112 C47 G-1061 0-1045 9-1012 0-1042 0-1042 0-1045 0-1040 0-1039 0-1046 0-1060	RUN 246. 246. 246. 246. 246. 246. 246. 246.

нав	EL 946.2	ÇONI	FIG00	00 HACI	H 4.00	PHÌ =	30•	
Q=	4.56 PSI	RE PER	IN.= .48	E06 T0= 9	90. DEĠ.F	P01/P1	rs =	20•
P0=	321.0 CH	HG PTS=	.4068 P	SI	RUN NO	. 01003	59113	
ALPHA	CN	:CM	cs	ĊY	ÇR CAT	CPB	CAF	RUÑ
4.15	0.2505	-1.7118	-0.0022		0026 0-1722			247.
3.14	0-1324	-1.2332	0.0001		.0023 0.1755			247.
2-13	0.1197	-0.8121	0.0027		.0014 0.1728			247.
1.60	0.0827	-0.5574	0.0041		.0015 0.1753			247.
	0.0562	-0.3911			.0015 0.1751			247.
0.58	0.0248	-0.1790	0.0056		.0016 0.1725			247.
0.07	-0.0030	0.0019	0.0056		.0017 0.1760			247.
	-0.0316	0.1862	0.0021		.0017 0.1735			247.
	-0.0628	0.3943			.0018 0.1721			247.
	-0-0903	0.5704			0023 0:1732			247.
	-0-1180	0.7496	0.0047		.0008 0.1753			247.
	-0.1842	1.2025	0.0038		0001 0:1764			247.
-3.98	-0.2524	1.6783	0.0016	-0.0653 0.	.0004 0-1787	.0.0666	0.1121	247.
	EL 946.2		FIG00		1 4.00	PHI =		40
	EL 946.2 4.56 PS1		FIG00 IN.= .48		1 4.00 70. DEG.F	PHI =		40 .
Q=		RE PER	IN.= .48	E06 ,T0= 9	O. DEG.F		rs =	40.
Q=	4.56 PS1	RE PER	IN.= .48	E06 ,T0= 9	O. DEG.F	P0J/P1	rs =	40 . RÙN
Q= PÓ= ALPHA	4.56 PSI 321.0 CH	RE PER HG PTS=	IN.= .48 .4058 P	E06 T0= 9 \$1 CY	PO. DEG.F RUN NO CR CAT	POJ/P1 • 010036 CPB	S = 69114 CAF	
Q= PÕ= ALPHA	4.56 PSI 321.0 CM	RE PER HG PTS=	IN.= .48 .4058 P CS -0.0069	E06 T0= 9 S1 CY -0:0077-0	RUN NO. CR CAT	POJ/P1 010036 CPB 0.0671	TS = 69114 CAF 0.1095	RÙN
Q= PÓ= ALPHA 4•15	4.56 PS1 321.0 CM CN 0.2324	RE PER HG PTS= CM -1.5759	IN.= .48 .4058 P CS -0.0069 -0.0084	E06 T0= S S1 CY -0.0077-0. 0.0042 0.	PO. DEG.F RUN NO CR CAT	POJ/P1 - 010036 - CPB - 0.0671 - 0.0673	S =	RÙN 248•
Q= PO= ALPHA 4.15 3.14	4.56 PS1 321.0 CM CN 0.2324 0.1680	RE PER HG PTS= CM -1.5759 -1.1328	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059	E06 T0= S CY -0.0077-0. 0.0042 00.0218-0.	RUN NO. CR CAT 0011 0-1765	POJ/P1 - 010036 - CPB - 0.0671 - 0.0673 - 0.0668	CAF 0.1095 0.1114 0:1080	RÙN 248 • 248 •
Q= PO= ALPHA 4.15 3.14 2.12 1.60	4.56 PST 321.0 CM CN 0.2324 0.1680 0.1053	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0078	CY -0.0077-0. 0.0042 00.0218-00.0044 0.	PO. DEG.F RUN NO CR CAT .0011 U-1765 .0004 0-1787	POJ/PI 010036 CPB 0.0671 0.0673 0.0668 0.0663	CAF 0.1095 0.1114 0:1080 0.1099	RÙN 248 • 248 • 248 •
Q= PO= ALPHA 4.15 3.14 2.12 1.60	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0078 -0.0067	CY -0.0077-0. 0.0042 00.0218-00.0147 0.	PO. DEG.F RUN NO CR CAT .0011 U-1765 .0004 0-1787 .0006 0-1748 .0002 0-1761	POJ/P1 - 010036 - CPB - 0.0671 - 0.0673 - 0.0668 - 0.0663 - 0.0659	CAF 0.1095 0.1114 0.1080 0.1099 0.1100	RÙN 248 • 248 • 248 • 248 •
Q= PO= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0078 -0.0067	CY -0.0077-0. 0.0042 00.0248 00.0147 00.0497-00.0376-0.	RUN NO. CR CAT .0011 0-1765 .0004 0-1787 .0006 0-1748 .0002 0-1761 .0001 0-1759 .0005 0-1744	POJ/P1 - 010036 - CPB - 0.0671 - 0.0673 - 0.0663 - 0.0663 - 0.0657 - 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1100 0.1087 0.1100	RÙN 248. 248. 248. 248. 248.
Q= PO= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0078 -0.0067 -0.0029	CY -0.0077-0. 0.0042 00.0248 00.0147 00.0497-00.0376-0.	RUN NO. CR CAT .0011 0-1765 .0004 0-1787 .0006 0-1748 .0002 0-1761 .0001 0-1759 .0005 0-1744	POJ/P1 - 010036 - CPB - 0.0671 - 0.0673 - 0.0663 - 0.0663 - 0.0657 - 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1100 0.1087 0.1100	RÛN 248. 248. 248. 248. 248.
Q= P0= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07 -0.44	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144 -0.0220	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524 0.3130	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0078 -0.0067 -0.0029 -0.0071	CY -0.0077-0. 0.0042 00.0248-00.0044 00.0147 00.0497-00.0376-00.0079-0.	RUN NO CR CAT .0011 0-1765 .0004 0-1787 .0006 0-1748 .0002 0-1761 .0001 0-1759 .0005 0-1744	POJ/P1 - 010036 - CPB - 0.0671 - 0.0663 - 0.0663 - 0.0657 - 0.0657 - 0.0656	CAF 0.1095 0.1114 0.1080 0.1099 0.1100 0.1087 0.1100 0.1099	RUN 248 • 248 • 248 • 248 • 248 • 248 •
Q= P0= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07 -0.44 -0.95	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144 -0.0220 -0.0484	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524 0.3130 0.4583	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0067 -0.0029 -0.0071	CY -0.0077-0. 0.0042 00.0218-00.0147 00.0497-00.0079-00.0489-0.	RUN NO CR CAT .0011 0-1765 .0004 0-1787 .0006 0-1748 .0002 0-1759 .0005 0-1744 .0-1756 .0011 0-1755	POJ/P1 - 010036 - CPE - 0.0671 - 0.0673 - 0.0663 - 0.0657 - 0.0657 - 0.0656 - 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1007 0.1100 0.1087 0.1099 0.1083	RUN 248. 248. 248. 248. 248. 248. 248. 248.
Q= P0= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07 -0.44 -0.95 -1.45	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144 -0.0220 -0.0484 -0.0732	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524 0.3130 0.4583 0.7967	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0067 -0.0029 -0.0071 -0.0071	CY -0.0077-0. 0.0042 00.0218-00.0147 00.0497-00.0497-00.0497-0.	RUN NO CR CAT .0011 0.1765 .0004 0.1787 .0006 0.1761 .0002 0.1761 .0001 0.1756 .0011 0.1756	POJ/P1 - 010036 - CPE - 0.0671 - 0.0673 - 0.0663 - 0.0657 - 0.0657 - 0.0657 - 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1007 0.1087 0.1099 0.1083 0.1096	RÜN 248. 248. 248. 248. 248. 248. 248. 248.
Q= P0= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07 -0.44 -0.95 -1.45 -1.96 -2.97	4.56 PST 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144 -0.0220 -0.0484 -0.0732 -0.1170 -0.1335 -0.1966	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524 0.3130 0.4583 0.7967 0.8625 1.2843	IN.= .48 .4058 P CS -0.0069 -0.0084 -0.0059 -0.0067 -0.0029 -0.0071 -0.0071 -0.0032 -0.0110 -0.0045 -0.0037	CY -0.0077-0. 0.0042 00.0218-00.0044 00.0147 00.0497-00.076-00.0497-00.0497-00.0497-0.	RUN NO CR CAT .0011 U-1765 .0004 0-1787 .0006 0-1748 .0002 0-1761 .0001 0-1759 .0011 0-1756 .0011 0-1753 .0014 0-1761 .0012 0-1761	POJ/PI 010036 CPB 0.0671 0.0673 0.0668 0.0657 0.0657 0.0657 0.0657 0.0657 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1100 0.1087 0.1109 0.1099 0.1083 0.1096 0.1164 0.1136	RÜN 248. 248. 248. 248. 248. 248. 248. 248.
Q= P0= ALPHA 4.15 3.14 2.12 1.60 1.10 0.58 0.07 -0.44 -0.95 -1.45 -1.96 -2.97	4.56 PSI 321.0 CM CN 0.2324 0.1680 0.1053 0.0689 0.0417 0.0144 -0.0220 -0.0484 -0.0732 -0.1170 -0.1335	RE PER HG PTS= CM -1.5759 -1.1328 -0.7112 -0.4603 -0.2890 -0.1126 0.1524 0.3130 0.4583 0.7967 0.8625 1.2843	IN.= .48 .4058 P C5 -0.0069 -0.0084 -0.0059 -0.0078 -0.0071 -0.0071 -0.0071 -0.0032 -0.0110 -0.0045	CY -0.0077-0. 0.0042 00.0218-00.0044 00.0147 00.0497-00.076-00.0497-00.0497-00.0497-0.	RUN NO CR CAT .0011 U-1765 .0004 0-1787 .0006 0-1748 .0002 0-1759 .0005 0-1744 .0011 0-1756 .0011 0-1755 .0011 0-1755 .0012 C-1753	POJ/PI 010036 CPB 0.0671 0.0673 0.0668 0.0657 0.0657 0.0657 0.0657 0.0657 0.0657	CAF 0.1095 0.1114 0.1080 0.1099 0.1100 0.1087 0.1109 0.1099 0.1083 0.1096 0.1164 0.1136	RÜN 248. 248. 248. 248. 248. 248. 248. 248.

,也可以为什么,我们是一个,我们是我们的一个,我们是一个人,我们是一个人,我们是我们的,我们是我们的,我们们就是我们的,我们的我们的我们的我们的我们的我们的我们 第一个人,我们是我们是我们的,我们是我们是我们的,我们是一个人,我们是我们的,我们就是我们的,我们就是我们的,我们就是我们的我们的我们的,我们就是我们的我们的,我

MOL	DEL 946.2	CONI	IG000	0 MA	ACH 4.0	0	PHI =	30.		
Q=	4.56 PSI	RE PER	IN.= .48E	=0f 30	90. D	EG.F	P0J/P	rs = :	100.	
P0=	321.0 CM	HG PTS=	.4068 PS	I		RUN NO	01003	69115		
ALPHA	CN	ĊМ	cś	CA	CR.	CAT	CPŜ	CAF	RUN	i
4.14	0.1931	-1-2956	-0.0350	0.2133-	-0-0003	0.1872	0.0675	0.119	7 249.	
3.13	0.1271		-0.0315			0.1844				
2.11	0.0637		-0.0280			0.1841				
1.58	0.0300	-0.1796	-0.0276	0.1300-	-0.0001	0.1841	0.0661	0.118	0 249.	
1.09	0.0023	0.0048	-0.0254	0.1148-	-0.0012	0.1826	0.0659	0.116	7 249.	
0.57	-0.0346	0.2718	-0.0285	0.1458-	-0.0003	-0.1814	0.0657	0.115	6 249.	
0.06	-0.0554	0.3779	-0.0267	0.1236-	-0.0013	0.1823	0.0656	0.116	B 249.	,
-0.45	-0.0923	0.6443	-0.0298			0.1811				
	-0.1163		-0.0247	0.1063						
	-0.1373	* *	-0.0200			0.1830				
	-0-1746		-0.0226			0.1829				
	-0.2089		-0.0233:			0.1841				
	-0.2343		-0.0205			0.1862				
-4.00	-0.3018	2.0199	-0,0192	0.0600	0.0049	0.1884	0.0659	0.122	5 249.	•
	-									
MOE	DEL 946.2	CÓNI	FIG000	0 MA	ACH 4.0	0	PHI =	45.		
Q=	4.56 PSI	RE PER	IN.= .485	06 T0≖	90. DI	EG.F	P0J/P1	rs =	•	
P0=	= 321.0 CM	HG PTS=	.4068 PS	ī		RUN NO	01003	69116		
ALPHA	CN	CM	.cs	CY	CR	CAT	CP8	CAF	RUN	ì
4.26	0.2638	-1-7750	-0.0077	0.0371-	-n- nn2n	0.1845	00670	0.1179	5 250	
3.25			-0.0055			0.1885				
2.23	0.1308	-0.8549		-0.0082-						
1.72	0.0960		-0.0066			0.1839				
1.20	0.0662	_	-0.0058			0.1872				
0.69	0.0400		-0.0034	0.0049			0.0653			
0.17	0.0161		0.0050	-0.0727-						
	~0.0236		-0.0060			0.1848				
	-0.0446	0.2773		-0.0672						
	-0.0793		-0.0015	-0.0060-						
-1.86	-0.1099	0.7231	0.0002	-0.0192	0.0005	0.1848	0.0659	0.1189	9 250.	
-2.86	-0.1724	1.1454	0.0014	-0.0283	0.0001	0.1876	0.0662	0.121	4 250.	
	-0-2421	1.6364	0.0081	-0.0819	0.0010	0-1915	0-0666	0.1249	9 250.	

HOD	EL 946+2	CON	FIG000	O M/	ACH 4.00	0	PHI =	45.	
Q=	4.56 PSI	RE PER	IN.= .48E	06 TO=	90. D	EG.F	POJ/P	TS =	10.
P0=	32140 ČM	HG PTS=	.4068 PS	1		RUN NO	01003	69117	
ALPHA	CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.26	0.2611	-1.7668	-0.0136		-0.0004				
3.25	0.1930		-0.0118		0.0007				
2.23	0.1287		-0.0087		0.0008				
1.71	0.0866		-0.0174		0.0015				
1.20	0.0620		-0.0134		0::0013				251.
0.69	0.0369		-0.0088		0.0012				251.
	-0.0021		-0.0137		0.0019				251.
	-0.0238		-0.0076		0.0012				
	-0.0514		-0.0039	-0.0035					
	-0.0849		-0.0060		0.0018				
-		0.7082		-C-0150					
	-0.1728		~0.0015	-0.0121					
-3.88	-0.2461	1.0000	0.0053	-0.0683	0.0021	0.1810	0.0001	0.1202	251.
•	EL 946.2 4.56 PSI	CONI	FIG000		ACH 4.00	-	PHI =	45. TS = :	20.
-	1150 / 51	116 1,614	1.110- 1102		,00				
₽0≥	321.0 CH	HG PTS≖	.4068 PS	I		RUN-NO	01003	69118	
ALPHA	CN	CM	CS	CY	CR	CAT	CP8	CAF	RUN
4.26	0.2559	-1.7383	-0.0203	0.1209-	-0.0019	0.1841	0.0673	0.1168	252.
3.25	0.1893	-1.2718	-0.0151		-0,0014				252.
2.23	0.1243	-0.8276	-0.0164	0.0887-	-0.0002	0.1825	0.0666	0.1158	252.
1.71	0.0851	-0.5459	-0.0195	0-1225	0.0006	0-1811	0.0661	0.1150	252.
1.20	0.0604	-0.4016	-0.0137	0.0638-	-0.0007	0.1818	0.0658	0.1160	252.
0.69	0.0244	-0.1476	~0.020i		0.0001				252.
0.18	0.0053	-0.0516	-0.0097	0.0349	-0.CO11	0.1809	0.0655	0.1153	252.
	-0.0307		-0,0143	0.0826-	-0.0003	0.1855	0.0655	0.1200	252.
	-0.0630		-0.0160		-0.0005				252.
-1.35	-0.0974		-0.0190		-0.0013				252.
	-0.1121		-0.0079		0.0002				252.
	-0.1778		-0.0052		0.0002				252.
-3.88	-0.2480	1.6572	0.0019	-0.0529	0.0012	0.1922	0.0667	0.1255	252.

SERVICE CONTINUES OF THE PROPERTY OF THE PROPE

HOD	EL 946.2	CON	FIG.	.0000	M	ACH 4.0	o	PHI =	45.	
Q =	4.56 PSI	RE PER	IN.=	-48E06	5 TO=	90. D	EG.F	601/5	TŠ =	40.
P0=	321.0 CM	HG PTS=	. 406	SB PSI			RUN NO.	. 01003	6 911 9	-
ALPHA	CN	CM	C.S	5	CY	CR	CAT	CPB	CAF	RUN
4.25	0.2449	-1.6649	-0.02	298	0.1861	0.0003	0.1897	0.0678	0.1219	
3.24		-1.1849	-0.02	280			0.1876			
2.23	0.1132	-0.7533	-0.03	241			0.1904			
1.71	0.0768	-0.5019	~0.02	218			0.1865			
	0.0494	-0.3272					0.1873			
0.68	0.0104	-0.0357	-0.02	282	0.1872-	-0.0009	0.1871	0.0657	0.1214	
0.18	-0.0092	C.0562	-0.01				0.1876			
-0.34	-0.0491	0.3537	-0.02	266	0.1733	0.0013	0.1887	0.0656	0.1231	
	-0.0687	0.4463	-0.01	75	0.0850	0.0011	0.1905	0.0657	0.1248	
-1.36	-0.1098	0.7549	-0.02	272			0.1904			
-1.85	-0.1258	G.8158	-0.01	164	0.0789	0.0023	0.1909	0.0658	0.1250	253 •
-2.88	-0.1892	1.2393	-0.01	42	0:0675	0.0034	0.1925	0.0661	0.1265	
-3.89	-0.2612	1.7500	-0.00	71	8800.0	0.0038	0-1928	0.0666	0.1262	253.
				_						
	EL 946.2			•0000		ICH 4.00		PHI =		nn.
	EL 946.2 4.56 PSI							_	45. TS = 1	.00•
Ç=		RE PER	ĮN.=	•48F)6			EG.F	_	TS = 1	00.
Ç=	4.56 PSI	RE PER	ĮN.=	.48E)6			EG.F	POJ/P	TS = 1	00 . RUN
C= PO= Alpha	4.56 PSI 321.0 CM CN	RE PER HG PTS= CM	IN.= .406 CS	•48F)6 8 PSI	. TO=	90. Öl	EG.F RUN NO. CAT	POJ/P 010030 CP8	TS = 1 59120 CAF	RUN
Q= PO= ALPHA 4.24	4.56 PSI 321.0 CM CN 0.2114	RE PER HG PTS= CM -1.4230	.406 CS	•48E)6 8 PSI	. TO=	90. 01 CR -0.0005	EG.F RUN NO.	POJ/P 010030 CP8 0.0675	TS = 1 89120 CAF 0.1340	RUN 254.
Q= PO= ALPHA 4.24 3.24	4.56 PSI 321.0 CM CN 0.2114 0.1436	RE PER HG PTS= CM -1.4230 -0.9431	.406 CS -0.06	•48F)6 8 PSI 6 644	CY 0.4442- 0.3986	90. 00 CR -0.0005 0.	EG.F RUN NO. CAT 0.2015 0.1944	POJ/P 010030 CP8 0.0675 0.0674	TS = 1 59120 CAF 0.1340 0.1270	RUN 254 • 254 •
Q= PO= ALPHA 4.24 3.24 2.22	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972	.406 CS -0.06 -0.05	•48F)6 8 PSI 644 96 645	CY 0.4442- 0.3986 0.3474	90. 08 CR 0.0005 0. 0.0011	EG.F RUN NO. CAT 0.2015 0.1944 0.1936	POJ/P 010030 CP8 0.0675 0.0674 0.0667	TS = 1 59120 CAF 0.1340 0.1270 0.1269	RUN 254 • 254 • 254 •
Q= PO= ALPHA 4.24 3.24 2.22 1.70	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719	.406 CS -0.06 -0.05 -0.05	•48E36 •8 PSI •644 •96 •45	CY 0.4442- 0.3986 0.3474 0.3460	90. 08 CR 0.0005 0. 0.0011	CAT 0.2015 0.1944 0.1936 0.1945	POJ/P 010030 CP8 0.0675 0.0674 0.0667	TS = 1 59120 CAF 0.1340 0.1270 0.1269 0.1283	RUN 254 • 254 • 254 • 254 •
PO= ALPHA 4.24 3.24 2.22 1.70 1.18	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719 -0.0920	.406 CS -0.06 -0.05 -0.05 -0.05	•48E36 •8 PSI •44 •96 •45 •35 •23	CY 0.4442- 0.3986 0.3474 0.3460 0.3360	90. 00 CR 0.0005 0.0011 0.0009 0.0007	CAT 0.2015 0.1944 0.1936 0.1945 0.1941	POJ/P* 010030 CP8 0.0675 0.0674 0.0667 0.0661	TS = 1 69120 CAF 0.1340 0.1270 0.1269 0.1283 0.1282	RUN 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719	.406 CS -0.05 -0.05 -0.05 -0.05	.48F76 .8 PSI .44 .96 .45 .35 .23 .19	CY 0.4442- 0.3474 0.3460 0.3360 0.3358	90. 00 CR 0.0005 0. 0.0011 0.0009 0.0007	CAT 0.2015 0.1944 0.1936 0.1945	POJ/P 010030 CPB 0.0675 0.0674 0.0667 0.0661 0.0659	TS = 1 S9120 CAF 0.1340 0.1270 0.1269 0.1283 0.1282 0.1282	RUN 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437	RE PER HG PTS= CH -1.4230 -0.9431 -0.4972 -0.2719 -0.0920 0.1200	.406 CS -0.05 -0.05 -0.05 -0.05 -0.05	.48F)6 .8 PSI 	CY 0.4442- 0.3986 0.3474 0.3460 0.3358 0.3118-	90. 01 CR 0.0005 0. 0.0011 0.0009 0.0007 0.0015	CAT 0.2015 0.1944 0.1936 0.1941 0.1936	POJ/P 010030 CP8 0.0675 0.0674 0.0661 0.0659 0.0656	TS = 1 59120 CAF 0.1340 0.1270 0.1269 0.1283 0.1282 0.1280 0.1266	RUN 254. 254. 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16 -0.34	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437 -0.0896	RE PER HG PTS= CH -1.4230 -0.9431 -0.4972 -0.2719 -0.0920 0.1200 0.3112 0.5811	.406 CS -0.06 -0.05 -0.05 -0.05 -0.05 -0.05	.48E)6 8 PSI 644 696 645 635 623 619	CY 0.4442- 0.3986 0.3474 0.3360 0.3358 0.3118- 0.3695	90. 01 CR 0.0005 0.0011 0.0009 0.0007 0.0015 0.0003	CAT 0.2015 0.1946 0.1946 0.1946 0.1920 0.1942	POJ/P 010030 CP8 0.0675 0.0674 0.0661 0.0659 0.0656 0.0654 0.0653	TS = 1 59120 CAF 0.1340 0.1270 0.1269 0.1282 0.1282 0.1280 0.1286	RUN 254. 254. 254. 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16 -0.34 -0.85	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719 -0.0920 0.1200 0.3112 0.5811 0.6990	-0.06 -0.05 -0.05 -0.05 -0.05 -0.05 -0.05 -0.05	.48E)6 8 PSI 644 696 645 623 623 619 649 666	CY 0.4442- 0.3986 0.3474 0.3360 0.3358 0.3118- 0.3695 0.2904-	90. 01 CR 0.0005 0.0011 0.0007 0.0015 0.0003 0.0010	CAT 0.2015 0.1944 0.1945 0.1946 0.1946 0.1920	POJ/P 010030 CP8 0.0675 0.0674 0.0661 0.0659 0.0656 0.0654 0.0653 0.0653	TS = 1 69120 CAF 0.1340 0.1270 0.1269 0.1283 0.1280 0.1266 0.1289 0.1283	RUN 254. 254. 254. 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16 -0.34 -0.85 -1.36	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437 -0.0896 -0.1028 -0.1351	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719 -0.0719 0.1200 0.3112 0.5811 0.6990 0.9185	-0.06 -0.05 -0.05 -0.05 -0.05 -0.05 -0.05 -0.04 -0.04	.48E76 8 PSI 644 696 645 623 619 94 649 666	CY 0.4442- 0.3986 0.3474 0.3460 0.3358 0.3118- 0.3695 0.2904- 0.2913	90. 01 CR 0.0005 0.0011 0.0007 0.0007 0.0015 0.0003 0.0010	CAT 0.2015 0.1944 0.1936 0.1945 0.1942 0.1942 0.1945	POJ/P 010030 CP8 0.0675 0.0674 0.0661 0.0669 0.0656 0.0654 0.0653 0.0653	TS = 1 69120 CAF 0.1340 0.1270 0.1269 0.1283 0.1280 0.1289 0.1283 0.1283	RUN 254. 254. 254. 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16 -0.34 -0.85 -1.36 -1.89	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437 -0.0896 -0.1028	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719 -0.0920 0.1200 0.3112 0.5811 0.6990	-0.06 -0.05 -0.05 -0.05 -0.05 -0.04 -0.04 -0.04 -0.04	.49F76 .8 PSI .44 .96 .45 .23 .19 .94 .64 .65 .65	CY 0.4442- 0.3986 0.3474 0.3460 0.3358 0.3118- 0.3695 0.2904- 0.2913	90. 08 CR 0.0005 0. 0.0011 0.0009 0.0005 0.0003 0.0010 0.0002 0.0001	CAT 0.2015 0.1944 0.1945 0.1945 0.1946 0.1920 0.1942 0.1936	POJ/P 010030 CP8 0.0675 0.0674 0.0661 0.0659 0.0654 0.0653 0.0653 0.0653	TS = 1 59120 CAF 0.1340 0.1270 0.1269 0.1282 0.1282 0.1283 0.1282 0.1283 0.1292	RUN 254. 254. 254. 254. 254. 254. 254. 254.
PO= ALPHA 4.24 3.24 2.22 1.70 1.18 0.68 0.16 -0.34 -0.85 -1.36 -1.89 -2.88	4.56 PSI 321.0 CM CN 0.2114 0.1436 0.0787 0.0455 0.0171 -0.0139 -0.0437 -0.0806 -0.1028 -0.1351 -0.1674	RE PER HG PTS= CM -1.4230 -0.9431 -0.4972 -0.2719 -0.0920 0.3112 0.5811 0.6990 0.9185 1.1338	IN -= -406 -0.05 -0.05 -0.05 -0.05 -0.04 -0.04 -0.04	.49F76 .8 PSI 	CY 0.4442- 0.3986 0.3474 0.3460 0.3358 0.3118- 0.3695- 0.2913 0.2975- 0.2537	90. 08 CR 0.0005 0. 00011 0.0009 0.00015 0.0003 0.0010 0.0002 0.0007 0.0020	CAT 0.2015 0.1944 0.1936 0.1945 0.1946 0.1946 0.1946 0.1946 0.1945 0.1945	POJ/P 010030 CP8 0.0675 0.0674 0.0667 0.0659 0.0653 0.0653 0.0653 0.0653	TS = 1 59120 CAF 0.1340 0.1270 0.1269 0.1282 0.1282 0.1282 0.1283 0.1292 0.1301 0.1324	RUN 254. 254. 254. 254. 254. 254. 254. 254.

MO	DEL 946.2	CDNI	FIG0000	· MA	CH 4.00)	PHI =	50.	
Ó≈	4.56 PSI	RE PER	IN.= -48E0	6 To=	90° °06	G.F	POJ/P	TS =	•
Po	= 321.0 CM	HG PYS=	.4048 PSI			RUN NO.	01003	69121	
ALPHA	CN	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
4.09	0.2567	-1.7341	-0.0043	0.0154-	0.0013	0.1889	0.0664	0.1225	255.
3.08		-1.2490	-0.0032	0.0030-	0.0003	0.1855	0.0867	0.1188	
2.07			-0.0036	0.0043-	0.0013				
1.54	0.0898	-0.5879	-0.0025	-0.0067-			0.0655		
1.03	0.0589	-0.3833	-0.0047	0.0158	0.0007				
0.51	0.0306			-0.0041			0.0651		
0.01				-0.0252-					
	-0:0291	0.1925		-0.0012			0.0651		
	-0.0574			-0.0164					
	~0.0909			0.0773-					
	-0.1166			-0.0116					
	-0.1774			-0.0174					
-4.05	-0.2507	1.6846	-0.0024	-0.0061	0.0013	0.1938	0.0565	0.1273	255.
ea	DEL 946.2	CÚNI	=1G0000	MA	ICH 4.00)	PHI =	50.	
Q=	4.56 PSI	RE PER	IN.= .48E0	6 TO=	80% DE	G.F	P0J/P1	rs =	10.
PO	= 321.0 CH	HG PTS=	.4068 PSI			RUN NO.	01003	59122	
ALPHA	CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.09	0.2546	-1.7311	-0.0103	0.0550-	0.0001	0.1844	0.0678	0.1166	256.
3.08			-0.0693	0.0453					
2.06			-0.0087		0.0003				
1.55			-0.0067	0.0128					
1.02			-0.0131	0.0788	0.0019	0.1819	0.0657	0.1162	256.
0,52			-0.0155	0.1035	0.0026	0.1851	0.0655	0.1196	256.
	-0.0020	0,0102			0.0019				
	-0.0326		-0.0110	0.0606	0.0022	0.1840	0.0655	0.1186	256.
	-0.0666	0.4510	-0.0169	0.1196	0.0019	0.1874	0.0655	0.1218	
	-0.0942	0.6232	-0.0142	0.0915					
-2.02	-0.1197	0.7830	-0.0102	0.0498	0.0030	0.1862	0.0659	0.1202	
-3.04	-0.1804	1.1797	-0.0095	0.0441					256.
	-0.2511	1 4701	-0.0067	0 0223	0.0034	0.1903	0.0667	0.1237	256.

HODEL 946.2	CONF	IG0000	. HA	CH 4.00	PHI = 50.	
Q= 4.56 PSI	RE PER	IN.= .48E0	5 TO=	90: DEG.F	= 279\L09	20•
PO= 321.0 C	MHG PTS=	-4068 PSI		RUN NO	0100369123	
ALPHA CN	CM	cs	CY	CR CAT	CPB CAF	.RUN
4.09 0.2495	-1.7053	-0-0171	0-1051-	0-0017 0-1874	0.0676 0.1198	257.
3.08 0.1826	-1.2348.	,			0.0675 0.1212	
2.06 0.1193	-0.8050				0.0668 0.1186	
1.54 0.0859	-0.5853				0.0662 0.1163	
1.04 0.0537	-0.3655				0.0659 0.1187	
0.52 0.0239	-0.1666	-0:0162	0.0902	0.0017 0.1866	0.0657 0.1209	257.
0.01 -0.0078	0.0498	-0.0255	0.1849-	0.0006 0.1887	0.0656 0.1232	257.
-0.49 -0.0317		-0.0136	0.0648-	0.0003 0.1867	0.0656 0-1211	257.
-1.01 -0.0605	0.3732				0.0657 0.1205	
-1.52 -0.0925	0.5911	-0.0159			0.0658 0.1237	
-2.02 -0.1218		-0.0163			0.0660 0.1242	
-3.03 -0.1840		-0.0144			0.0663 0.1229	
-4.05 -0.2538	1.6873	-0.0125	0.0569	0.0009 0.1919	0.0668 0.1252	257.
MODEL 946.2 Q= 4.56 PSI		FIG0000		CH 4.00 90. DEG.F	PHI = 50. POJ/PTS =	40•
	RE PER	IN.= .48E0		90. DEG.F	•	40•
Q= 4.56 PSI	RE PER	IN.= .48E0		90. DEG.F	POJ/PTS =	40• . RUN
Q= 4.56 PSI PO= 321.0 G ALPHA CN	RE PER MHG PTS≃ CM	IN.= .48E0 .4068 PSI CS	6 T0=	90. DEG.F RUN NO CR CAT	POJ/PTS = . 0100369124 CPB CAF	RUN
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.09 0.2391	RE PER MHG PTS≃ CM -1.6327	IN.= .48E0 .4068 PSI CS -0.0287	6 TO= CY 0.1865	90. DEG.F RUN NO CR CAT 0.006Y 0.1953	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274	RUN 258.
Q= 4.56 PSI PO= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701	RE PER MHG PTS= CM -1.6327 -1.1450	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260	6 TO= CY 0.1865 0.1576-	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216	RUN 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273	CY 0.1865 9.1576- 0.1669	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0005 0.1898	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274	RUN 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257	CY 0.1865 0.1576- 0.1669 0.1494	90. DEG.F RUN NO CR CAT 0.0067. 0.1953 0.0011 0.1895 0.0005 0.1898 0.0012 0.1894	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231	RUN 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0271	CY 0.1865 0.1576- 0.1669 0.1494 0.1614	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0005 0.1898 0.0012 0.1894 0.0026 0.1889	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671: 0.1227	RUN 258. 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0271	CY 0.1865 9.1576- 0.1669 0.1494 0.1614 0.0991	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.005 0.1898 0.0012 0.1894 0.0026 0.1889 0.0023 0.1907	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230	RUN 258. 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424 0.51 0.0152	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105 0.0956	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0271 -0.0201	CY 0.1865 9.1576- 0.1669 0.1494 0.1614 0.0991 0.1494	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0005 0.1898 0.0012 0.1894 0.0026 0.1889 0.0023 0.1907 0.0021 0.1904	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230	RUN 258. 258. 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424 0.51 0.0152 00.0158	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105 0.0956 0.2892	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0271 -0.0201 -0.0254	CY 0.1865 9.1576- 0.1669 0.1694 0.1614 0.0991 0.1494 0.1502	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0025 0.1898 0.0026 0.1889 0.0023 0.1907 0.0021 0.1904 0.0018 0.1899	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230 0.0658 0.1249	RUN 258. 258. 258. 258. 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424 0.51 0.0152 00.0158 -0.50 -0.0451	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105 0.0956 0.2892	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0271 -0.0201 -0.0254 -0.0259 -0.0288	CY 0.1865 9.1576- 0.1669 0.1649 0.1614 0.0991 0.1494 0.1502 0.1817	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0025 0.1894 0.0026 0.1894 0.0026 0.1894 0.0021 0.1904 0.0018 0.1899 0.0015 0.1899	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230 0.0658 0.1249 0.0658 0.1246	RUN 258. 258. 258. 258. 258. 258. 258. 258.
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424 0.51 0.0152 00.0158 -0.50 -0.0451 -1.01 -0.0790	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105 0.0956 0.2892 0.5257	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0251 -0.0254 -0.0259 -0.0259 -0.0288 -0.0234	CY 0.1865 9.1576- 0.1669 0.1494 0.1614 0.0991 0.1494 0.1502 0.1817 0.1284 0.1368	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0025 0.1889 0.0026 0.1889 0.0023 0.1907 0.0021 0.1904 0.0018 0.1899 0.0024 0.1913 0.1921	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230 0.0658 0.1249 0.0658 0.1249 0.0658 0.1249 0.0658 0.1274 0.0659 0.1255 0.0660 0.1261	RUN 258 • 25
Q= 4.56 PSI P0= 321.0 C ALPHA CN 4.09 0.2391 3.07 0.1701 2.06 0.1062 1.54 0.0725 1.03 0.0424 0.51 0.0152 00.0158 -0.50 -0.0451 -1.01 -0.0790 -1.52 -0.1043	RE PER MHG PTS= CM -1.6327 -1.1450 -0.7093 -0.4829 -0.2832 -0.1105 0.0956 0.2892 0.5257 0.6765 0.8811 1.2606	IN.= .48E0 .4068 PSI CS -0.0287 -0.0260 -0.0273 -0.0257 -0.0251 -0.0254 -0.0259 -0.0259 -0.0288 -0.0234	CY 0.1865 0.1576 0.1669 0.1494 0.1614 0.0991 0.1494 0.1502 0.1817 0.1284 0.1368 0.1257	90. DEG.F RUN NO CR CAT 0.006Y 0.1953 0.0011 0.1895 0.0025 0.1899 0.0026 0.1889 0.0023 0.1907 0.0021 0.1904 0.0018 0.1899 0.0024 0.1932 0.0024 0.1913 0.1921 0.0016 0.1947	POJ/PTS = . 0100369124 CPB CAF 0.0680 0.1274 0.0678 0.1216 0.0671 0.1227 0.0663 0.1231 0.0660 0.1230 0.0658 0.1249 0.0658 0.1249 0.0658 0.1244 0.0659 0.1255	RUN 258. 258. 258. 258. 258. 258. 258. 258.

	IODI	EL 9	46.2		CON	FIG.	•0000		M	ACH	4.0	0	PHI =	50	•	
Q)= 4	4.56	PSI	RE	PER	IN.=	-48E0	6	TO=	90	DI	EG.F	POJ/P	TS, =	100.	
ρ	0=	321	.0 CH	KG	PTS=	-40	68 PSI					RUN NO	. 01003	69125		
ALPH	ĮΑ	CI	¥	Ċ	H	C	s	CY		ε	R	CAT	CPB	CAF		RUN
4.0	7	0.2	າດດ	-1-	4281	-0.0	627	0.4	314.	- a. ∩	1013	0.2010	0-0678	0.13	32	259.
3.0		0.14			_	-0.0						0.1962				259.
		0.0				-0.0						0:1952				259.
		0.0				-0.0						0.1974				259.
1.0		0.0				-0.0						0.1967				259.
0.5	io -	-0.0				-0.0						0.1952				259.
-0.		-0.0	517	0.	3799	-0.0	626					0.1972				259.
-0.5	2 -	-0-0	794	0-	5528	-0.0	601	0.4	020-	-0.0	001	0.1979	0:0655	J-13	25	259.
~1.0	2 -	-0.10	23	0.	808	-0.0	520					0.1960				259.
-1.5	i3 -	-0.13	361	0.	9114	-0.0	566	0.3	662	0.0	010	0:1994	0.0655	0.13	38	259.
-2.0	3 -	-0.1	536	1.	0873	-0.0	540	0.3	385	0.0	800	0-1988	0.0656	0.13	3 2	259.
-3.0	5 -	-0.2	237	ı.	4828	-0.0	505	0.3	071	0.0	049	0.2002	0.0659	0.13	42	259.
-4.0	16 -	-0.29	950	1.	9843	-0.0	444	0.2	518	0.0	017	0:2028	0.0667	0.13	6 L	259.
		EL 94					-0000				4.00		PHI =		•	
Ų	= 4	•-56	PSI	RE	PER	IN.=	-48E0	б `	TO=	90	. DE	EG.F	POJ/P	TS =	•	
ρ	0=	321	.0 CM	HG	PTS=	- 40	68 PSI					RUN NO.	01003	69126		
ALPH	A	CI	1	С	H	C	S	CY		C	R	CAT	CPB	CAF		RUN
3.9	6	0.2	519	-1.	7049	-0.00	050	0.0	228-	-0.0	023	0.1620	0.0663	0.09	57	260.
2.9	5	0.18	304	-1.	1964	-0.00	033					0.1585				260.
1.9	3	0.11	190	-0.	7900	-0.00	028					0.1588				260.
1.4	0	0.08	324	-0.	5399	-0.00	066					0.1580				260.
0.9	0	0.05	513	-0-	3313	-0.0	057					0.1594				260.
0.3	9	0.0	217	-0.	1368	-0.0	186					0.1611				260.
-0.1	2 -	-0.00)66	0.	0421	-0.00	073	.0.0	518-	-0.0	019	0.1598	0.0649	0.09	49	260.
-0.6	3 -	-0.03	387	0.	2581	-0.0	123	0.1	049-	-9.0	024	0.1637	0.0649	0.09	88	260.
-1.1	4 -	-0.06	552	0.	4200	-0.00	039	0.0	216-	-0.0	017	0.1613	0.0650	0.09	63	260.
-1.6				0.	6096	-0.00	035	0.0	174-	-0.0	022	0.1603	0.0651	0.09	51	260.
-2.1						-0.00		-0.0	111-	-0.0	010	0.1628	0.0653	0.097	75	260.
-3.l						-0.0						0.1632				260.
_4 1	9 -	-0.29	590	1.	7324	0.00	010 -	-0-0	200	6.0	DIT	0.1695	0.0652	0.103	33	260.

MODEL 946.2	CON	-1G00	00 M	ICH 4.00	PHI =	75.	
Q= 4.56 PSI	RE PER	IN.= .48	E06 T0=	90. DEG.1	F POJ/P	TS # 1	10.
PO= 321.0 C	HG PTS=	.4068 P	SI	RU	4 NÓ. 01003	6 9 /L27`	
ALPHA CN	CH	cs	CY	CR C	AT CPB	CAF	RUN
3.96 0.2566	-1.7622	-0.0112	0.0565	0.0005 0.	1648 0.0671	0.0977	261.
2.95 0.1887	-1-2853	-0.0080			1613 0.0668		26 i •
1.93 0.1239	-0.8446	-0.0104			1630 0.0661		261.
1.41 0.0883		-0.0082			1620 0.0657		261.
0.90 0.0578	-0.4030				1635 0.0654		261.
0.39 0.0295		-C.0085			1636 0.0653		261.
-0.12 -0.0010		-0.0101			1638 0.0653		261.
-0.63 -0.0319	_	-0.0179			1653 0.0652		261.
-1.13 -0.0584		-0.0070			1653 0.0653		261.
-1.64 -0.0920		-0.0177			1633 0.0654 1681 0.0655		261. 261.
-2.15 -0.1185 -3.17 -0.1846		-0.0069 -0.0091			1722 0.0657		261.
-4.19 -0.2544		-0.0031			1760 0.0664		261.
-4.17 -0.2344	4.0173	-0.0020	-040144	0.0034 0.	£10(1 U£0804	041073	201.
MODEL 946.2	CONI	=iG00	00 H	ECH 4.00	PHI =	75.	
MODEL 946.2		iG00					
MODEL 946.2 Q= 4.56 PSI		FiG00		1CH 4.00 90. DEG.1			20•
	RE PER	IN.= .48	E06 T0=	90. DEG.1		rs = a	20•
Q= 4.56 PST	RE PER	IN.= .48	E06 T0=	90. DEG.1	F POJ/P	rs = a	20• RUN
Q= 4.56 PST PO= 321.0 CM	RE PER IHG PTS= CM	IN.≈ .48 .4068 P	E06 TO= SI CY	90. DEG.1 . RUI	F POJ/P N NO. 01003 NT CP8	TS = 3 69128 CAF	RUN
Q= 4.56 PST PO= 321.0 CM ALPHA CN 3.96 0.2584	RE PER HHG PTS= CM -1.7937	IN.= .48 .4068 P CS -0.0156	E06 TO= SI CY 0.0700	90. DEG.1 . RUI CR C/	F POJ/P	TS = 369128 CAF 0.1029	RUN
Q= 4.56 PST PO= 321.0 CM	RE PER HHG PTS= CM -1.7937 -1.3076	IN.≈ .48 .4068 P	E06 T0= SI CY 0.0700- 0.05÷2	90. DEG.1 RUI CR C/ -0.0005 0.	F POJ/P N NO. 01003 NT CP8 1701 0.0672	TS = 3 69128 CAF 0.1029 0.1007	RUN 262•
Q= 4.56 PST P0= 321.0 CM ALPHA CN 3.96 0.2584 2.95 0.1900	RE PER HHG PTS= CM -1.7937 -1.3076 -0.8265	IN.= .48 .4068 P CS -0.0156 -0.0146	E06 T0= SI CY 0.0700- 0.05+2 0.0973	90 DEG -1 RUI CR C/ -0.0005 0. 0.0001 0. 0.0002 0.	F POJ/P N NO. 01003 AT CP8 1701 0.0672 1678 0.0671	TS = 3 69128 CAF 0.1029 0.1007 0.1018	RUN 262 • 262 •
Q= 4.56 PST PO= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208	RE PER HHG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184	E06 T0= SI CY 0.0700- 0.0542 0.0973 0.0494	90. DEG.1 RUI CR C/ -0.0005 0. 0.0001 0. 0.0002 0. 0.0008 0.	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0671	TS = 3 69128 CAF 0.1029 0.1007 0.1018 0.1025	RUN 262 • 262 • 262 • 262 •
Q= 4.56 PST P0= 321.0 CM ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887	RE PER HHG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0135	E06 T0= SI CY 0.0700 0.0542 0.0973 0.0494 0.0452 0.0405	90 DEG -1 RUI CR CA -0.0005 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0667 1683 0.0665 1685 0.0660 1686 0.0657	TS =	RUN 262 • 262 • 262 • 262 • 262 • 262 •
Q= 4.56 PST P0= 321.0 CN ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622	RE PER HHG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0135 -0.0125	E06 T0= SI CY 0.0700 0.0542 0.0973 0.0494 0.0452 0.0405 0.1697	90. DEG.1 RUI CR C. -0.0005 0. 0.0002 0. 0.0008 0. -0.0007 0. 0.0004 0. -0.0022 0.	POJ/P N NO. 01003 AT CP8 1701 0.0672 1678 0.0671 1683 0.0665 1685 0.0657 1700 0.0655	TS =	RUN 262 • 262 • 262 • 262 • 262 • 262 •
Q= 4.56 PSI P0= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622 0.38 0.0323 -0.12 -0.0019 -0.63 -0.0263	RE PER HG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581 -0.0185 0.1252	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0125 -0.0118 -0.0249 -0.0109	E06 T0= SI CY 0.0700 0.0542 0.0973 0.0494 0.0452 0.0405 0.1697 0.0289	90+ DEG+1 RUI CR C -0.0005 0. 0.0001 0. 0.0002 0. 0.0007 0. 0.0004 0. -0.0022 0. 0.0006 0.	POJ/P N NO. 01003 AT CP8 1701 0.0672 1678 0.0675 1685 0.0665 1686 0.0657 1700 0.0655 1705 0.0654	TS =	RUN 262 • 262 • 262 • 262 • 262 • 262 • 262 •
Q= 4.56 PSI P0= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622 0.38 0.0323 -0.12 -0.0019 -0.63 -0.0263 -1.14 -0.0596	RE PER HIG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581 -0.0185 0.1252 0.3524	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0125 -0.0118 -0.0249 -0.0109 -0.0254	E06 T0= SI CY 0.0700 0.0542 0.0973 0.0494 0.0452 0.0405 0.1697 0.0289 0.1758	90. DEG.1 RUI CR C. -0.0005 0. 0.0001 0. 0.0002 0. 0.0007 0. 0.0004 0. -0.0022 0. 0.0006 0. -0.0010 0.	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0671 1683 0.0665 1685 0.0657 1700 0.0655 1705 0.0654 1703 0.0654	TS =	RUN 262 • 262 • 262 • 262 • 262 • 262 • 262 • 262 • 262 •
Q= 4.56 PSI P0= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622 0.38 0.0323 -0.12 -0.0019 -0.63 -0.0263 -1.14 -0.0596 -1.65 -0.0861	RE PER HG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581 -0.0185 0.1252 0.3524 0.5117	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0125 -0.0118 -0.0249 -0.0109 -0.0254 -0.0170	E06 T0= SI CY 0.0700- 0.05*2 0.0973 0.0494 0.0452- 0.0405 0.1697- 0.0289 0.1758- 0.0931-	90. DEG.1 RUI CR C. -0.0005 0. 0.0002 0. 0.0008 0. -0.0007 0. 0.0006 0. -0.0010 0. -0.0010 0.	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0671 1683 0.0665 1686 0.0657 1700 0.0655 1700 0.0654 1703 0.0654 1733 0.0654	TS =	RUN 262. 262. 262. 262. 262. 262. 262. 262
Q= 4.56 PSI P0= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622 0.38 0.0323 -0.12 -0.0019 -0.63 -0.0263 -1.14 -0.0596 -1.65 -0.0861 -2.15 -0.1160	RE PER HG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581 -0.0185 0.1252 0.3524 0.5117 0.7115	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0125 -0.0118 -0.0249 -0.0109 -0.0170 -0.0140	E06 T0= SI CY 0.0700- 0.05*2 0.0973 0.0494 0.0452- 0.0405 0.1697- 0.0289 0.1758- 0.0931- 0.0609	90. DEG.1 RUI CR C/ 0.0005 0. 0.0001 0. 0.0008 0. 0.0007 0. 0.0004 0. 0.0006 0. 0.0006 0. 0.0004 0. 0.00013 0.	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0667 1683 0.0665 1686 0.0657 1700 0.0655 1705 0.0654 1733 0.0654 1745 0.0656	TS =	RUN 262. 262. 262. 262. 262. 262. 262. 262
Q= 4.56 PSI P0= 321.0 CP ALPHA CN 3.96 0.2584 2.95 0.1900 1.93 0.1208 1.40 0.0887 0.90 0.0622 0.38 0.0323 -0.12 -0.0019 -0.63 -0.0263 -1.14 -0.0596 -1.65 -0.0861	RE PER HG PTS= CM -1.7937 -1.3076 -0.8265 -0.6181 -0.4518 -0.2581 -0.0185 0.1252 0.3524 0.5117 0.7115 1.1563	IN.= .48 .4068 P CS -0.0156 -0.0146 -0.0184 -0.0125 -0.0118 -0.0249 -0.0109 -0.0254 -0.0170	E06 T0= SI CY 0.0700- 0.05*2 0.0973 0.0494 0.0452- 0.0405 0.1697- 0.0289 0.1758- 0.0931- 0.0609 -0.0043	90. DEG.1 RUI CR CI 0.0005 0. 0.0002 0. 0.0007 0. 0.0004 0. 0.0022 0. 0.0006 0. 0.0006 0. 0.0010 0. 0.0013 0. 0.0014 0.	POJ/P N NO. 01003 NT CP8 1701 0.0672 1678 0.0671 1683 0.0665 1686 0.0657 1700 0.0655 1700 0.0654 1703 0.0654 1733 0.0654	TS =	RUN 262. 262. 262. 262. 262. 262. 262. 262

MC	DEL 946.2	CON	FIG0000	H	ACH 4.00	PHI =	75	
Q=	4.56 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	POJ/PT	S = 40	•
PO)= 321.0 CM	HG PTS=	.4068 PSI		RUN N	0. 010036	9129·	
ALPHA	CN CN	CM	cs	CY	CR CAT	СРВ	CAF	RUN
3.95	0.2532	-1.7619	-0.0329	0.1921	0.0012 0.177	0.0671	0.1099	263.
2.95			-0.0298		0.0018 0.177			263.
1.93	0.1214	-0.8447	-0.0273	0.1450	0.0019 0.177	0.0667	0.1107	263.
1.40	0.0842	-0.5864	-0.0359	0.2320	0.0013 0.177	0.0661	0.1117	263.
0.90	0.0534	-0.3782	-0.0387	0.2612	0.0009 0.179	2 0.0658	0.1134	263.
0.38	0.0241	-0.1906	-0.0382	0.2586	-0.0001 0.178	3 0.0657	0.1126	263.
	-0.0039	-0.0129	-0.0283	0.1573	0.0021 0.179	5 0.0656	0.1139	263.
-0.63	-0.0338	0.1835	-0.0301	0.1772	0.0011 0.179	7 0.0656	0.1141	263.
-1.15	-0.0617	0.3543	-0.0239	0.1123	0.0017 0.182	2 0.0656	0.1166	263.
-1.65	-0.0950	0.5858	-0.0383	0.2570	0.0018 0.1839	0.0656	0.1183	263.
-2.15	-0.1208	0.7446	-0.0277	0.1503	0.0024 0.182	0.0557	0.1169	263.
-3.17	-0.1859	1.1897	-0.0240		0.0025 0.181			263.
-4.19	-0.2569	1.6880	-0.0174	0.0549	0.0041 0.189	0.0668	0.1222	263.
МО	DEL 946.2	CON	FIG0000	H/	ACH 4.00	PHI =	75.	
Q=	4.56 PSI	KE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PT	s = 100.	
PO	= 321.0 CM	MG PTS=	.4068 PSI		RUN N	0. 010036	9130	
ALPHA	CN	CM	CS	ÇY	CR CAT	ÇPB	CAF	RUN
3.95	0.2438	-1.6967	-0.0692	0.4395	0.0009 0.1909	0-0671	0-1238	264.
2.94		-	-0.0687		-0.0001 0.192			264。
1.93			-0.0676	0.4285		0.0667		264.
1.40			-0.0681		0.0011 0.189			264.
0.89			-0.0721		0.0006 0.1883			264.
0.38			-0.0770		0.0001 0.189			264.
	-0.0181		-0.0696		0.0013 0.1923			264.
	-0.0468		-0.0644		0.0019 0.1948			264.
	-0.0770		-0.0673		0.0014 0.1890			264.
	-0.1078		-0.0701		0.0010 0.1910			264.
	-0.1343		-0.0667		0.0011 0.191			264.
	-0.2013		-0.0625		0.0017 0.1956			264.
	-0.2723		-0-0535		0-0027 0-199			264.

MODEL 946.2	ÇONI	FIG00	00 M	ACH 4200	PHI = 90.	
Q= 4.56 PSI	RE PER	IN.= .48	E06 T0=	90. DEG.F	POJ/PTS =	•
PO= 321.0 CM	HG PTS=	-4068 P	21	RUN	NG. 01003(eai31	
ALPHA CN	CH	.CS .	CY	CR CAT	CPB CAF	ŖUN.
4.11 0.2569	-1.7324	-0.0048	0.0193	0.0010 0.16	88 0.0665 0.102	265.
3.10 0.1858	-1.2235	-0.0047			83 0.0665 0.101	
2.08 0.1249	-0.8205	-0.0033			15 0.0658 0.105	
1.56 0.0908	-0.5932	-0.0091	0.0642	0.0003 0.16	78 0.0654 0.1024	4 265.
1.05 0.0601	-0.3880	-0.0079			12 0.0652 0.106	
0.53 0.0299		0.0041			45 0.0651 0.1094	
0.02 0.0017		-0.0028			33 0.0651 0.108	
-0.49 -0.0284		-0.0062			07 0.0651 0.105	
-1.00 -0.0573		-0.0014			29 0.0652 0.107	
-1.50 -0.0862		-0.0047			16 0.0653 0.106	
-2.01 -0-1163		-0.0011			37 0.0353 0.108	
-3.02 -0.1830		-0.0510			57 0.0655 0.110	
-4.04 -0.2516		0.0015			88 0.0663 0.112	
MODEL 946-2	CONI	FIC00	CO M	ACH 4-00	PHI = 90.	
Q= 4.56 PSI	RE PER	IN.= .48	E06 T0≃	90. DEG.F	POJ/PTS =	10.
PO= 321.0 CM	HG PTS=	-4068 P	SI	RUN	NO. 0100369132	
ALPHA CN	CM	cs	CY	CR CAT	CPB CAF	RUN
4.10 0.2599	-1-7606	-0.0096	0.0397	0-0032 0-17	04-0-0670 0-103	4 266.
3.09 0.1894		-0.0095			74 0.0669 0.100	
2.08 0.1259		-0.0081			45 0.0663 0.098	
1.56 0,0926		-0.0187			58 0.0659 0.099	
1.05 0.0618		-0.0269			81 0.0656 0.102	
0.53 0.0316		-0.0066			52 0.0656 0.099	
0.02 0.0028		-0.0064			63 0.0654 0.100	
-0.48 -0.0267		-0.0087			86 0.0653 0.103	
-1.00 -0.0556		-0.0038			83 0.0654 0.102	
-1.50 -0.0864		-0.0120			07 0.0655 0.105	
-2.00 -0.1166		-0.0071			04 0.0655 0.1049	
-3.02 -0.1820		-0.0071			73 0.0657 0.111	
-4.04 -0.2512		-0-0034			'66 '0-0665 0-110'	

MO	DEL 946.2	CDN	FIG0500	, H	ACH 4.0	O .	PHI =	90.	
Q=	4,56 PSI	RE PER	IN.= 348EC	6 TO=	90. D	EG.F	POJ _S b	TS = :	20.
PŌ:	× 321.0 CM	HG PŤŠz	.4068 PSI		-	RUN-NO.	010 <u>0</u> 3	69133	
						242	500	c. c	0.114
ALPHA	CN	"CH-"	C\$.	CY	CR	CAT	CP8	CAF	RUN
4.10	0.2616	-1.7755	~0.0133	010516	0.0012	0.1671	0.0670	0.1001	267
3.10			-0.0133	0.0508				0.1019	
2.08	0.1283	-0.8518	-0.0154	0.0716	G-0005	0-1698	0.0665	0.1033	267.
156	0.0930	~0.6138	-0.0201	0.1216-	-0.0001	0.1697	0.0660	^.103ř	267.
1.05	0.0622	0.4088		0-1558	-0.0007	0.1695	0.065?	0.1038	267.
0.54	0.0340		-0.0257	0.1751	0.0004	0-1682	0.0656	0.1027	267.
0.02	0.0044		-0.0245			0.1778			267.
-0.48	-0.0263		-0.0231			0.1715			
-1.00	-0.0559	0.3584	-0:0170			0.1724			
-1.51	-0.0879		-0.0157			0.1747			267.
-2-00	-0-1155		-0.0156			0.1745			
	-0.1809		-0.0131			0.1789			
-4.04	-0.2514	1.6925	-010095	C-6170	0.0034	C.1843	0.0667	0.1176	267.
		•	J.		,				
			-						
MG	DEL 946.2	GÒNI	FIG. :0000	H	IÇH 4.01	0	PHI =	90.	
Q =	4.56 PSI.	ŘE PÊR	IN.= .48E0	6 TÒ≂	90. DI	ĔĢ•F	POJ/P	rs = 4	40.
00.	- 23i 0 Cri	die Tarel	.4068 PŠI			RUN NO.	01.002	(0126	
FU.	- 32116. CF	ING TIST	*4000 F31		•	KON NO	01003	37137	
ÂLPHA									
	CN -	ĈМ	.CŚ	CY	ÇR	CAT	СРВ	CAF	RUN
4.11	_		.CŚ -0.0266		2				
	CN 0.2599 0.1875	-1.7619		0.1347	0.0028	CAT 0.1713 0.1720	0.0673	0-1040	258.
3.10	0.2599; -0.1875	-1.7619 -1.2396	-0.0266	0.1347 0.1583	0.0028 0.0022	0.1713	0.0673 0.0673	0-1040 0-1047	258.
3.10 2.08	0.2599 0.1875 0.1260	-1.7619 -1.2396 -0.8307	-0.0266 -0.0290	0.1347 0.1583 0.1464	0.0028 0.0022 0.0022	0.1713 0.1720	0.0673 0.0673 0.0668	0.1040 0.1047 0.1048	258 • 268 •
3.10 2.08	0.2599 0.1875 0.1260 0.0913	-1.7619 -1.2396 -0.8307 -0.5987	-0.0266 -0.0290 -0.0276	0.1347 0.1583 0.1464 0.2670	0.0028 0.0022 0.0022 0.0015	0.1713 0.1720 0.1716	0.0673 0.0673 0.0668 0.0663	0-1040 0-1047 0-1048 0-1090	258. 268. 268.
3.10 2.08 1.56	0.2599 0.1875 0.1260 0.0913 0.0588	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758	-0.0266 -0.0290 -0.0276 -0.0393	0.1347 0.1583 0.1464 0.2670 0.1975	0.0028 0.0022 0.0022 0.0015	0.1713 0.1720 0.1716 0.1753	0.0673 0.0673 0.0668 0.0663 0.0659	0.1040 0.1047 0.1048 0.1090 0.1091	258. 268. 268. 268.
3.10 2.08 1.56 1.04 0.53	0.2599 0.1875 0.1260 0.0913 0.0588	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885	-0.0266 -0.0290 -0.0276 -0.0393 -0.0322	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020	0.1713 0.1720 0.1716 0.1753 0.1750	0.0673 0.0673 0.0668 0.0663 0.0659 0.0657	0.1040 0.1047 0.1048 0.1090 0.1091 0.1090	268 • 268 • 268 • 268 • 268 •
3.10 2.08 1.56 1.04 0.53 0.02	0.2599 0.1875 0.1260 0.0913 0.0588 0.0297	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885 -0:0147	-0.0266 -0.0290 -0.0276 -0.0393 -0.0322 -0.0272	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467 0.2513	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020 0.0020	0.1713 0.1720 0.1716 0.1753 0.1750 0.1747	0.0673 0.0673 0.0668 0.0663 0.0659 0.0657	0.1040 0.1047 0.1048 0.1090 0.1091 0.1090 0.1166	248. 268. 268. 268. 268. 268.
3.10 2.08 1.56 1.04 0.53 0.02 -0.49	0.2599 0.1875 0.1260 0.0913 0.0586 0.0297 0.0031	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885 -0.0147 0.1889	-0.0266 -0.0290 -0.0296 -0.0393 -0.0322 -0.0272 -0.0378	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467 0.2513 0.2612	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020 0.0020	0.1713 0.1720 0.1716 0.1753 0.1750 0.1747 0.1821	0.0673 0.0673 0.0668 0.0663 0.0659 0.0657 0.0655 0.0655	0.1040 0.1047 0.1048 0.1090 0.1090 0.1090 0.1166 0.1140	248. 268. 268. 268. 268. 268. 268.
3.10 2.08 1.56 1.04 0.53 0.02 -0.49 -0.99	0.2599 0.1875 0.1260 0.0913 0.0588 0.0297 0.0021 -0.0287	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885 -0.1889 0.3821	-0.0266 -0.0290 -0.0276 -0.0393 -0.0322 -0.0272 -0.0378 -0.0388	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467 0.2513 0.2612 0.2006 0.1358	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020 0.0020 0.0020 0.0026 0.0036	0.1713 0.1720 0.1716 0.1753 0.1750 0.1747 0.1821 0.1821 0.1755 0.1755	0.0673 0.0673 0.0668 0.0663 0.0659 0.0657 0.0655 0.0655 0.0655	0.1040 0.1047 0.1048 0.1090 0.1091 0.1090 0.1166 0.1140 0.1100 0.1121	258. 268. 268. 268. 268. 268. 268. 268.
3.10 2.08 1.56 1.04 9.53 0.02 -0.49 -0.99 -1.50	0.2599 0.1875 0.1260 0.0913 0.0588 0.0297 0.0021 -0.0287 -0.0582 -0.0903 -0.01198	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885 -0.0147 0.1889 0.23821 0.5961 0.7207	-0.0266 -0.0290 -0.0276 -0.0393 -0.0322 -0.0272 -0.0378 -0.0388 -0.0328 -0.0267 -0.0278	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467 0.2513 0.2612 0.2006 0.1358 0.1468	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020 0.0020 0.0020 0.0026 0.0036	0.1713 0.1720 0.1716 0.1753 0.1750 0.1747 0.1821 0.1755 0.1755 0.1777	0.0673 0.0668 0.0663 0.0659 0.0657 0.0655 0.0655 0.0656	0.1040 0.1047 0.1048 0.1090 0.1090 0.1090 0.1160 0.1140 0.1121 0.1131	268. 268. 268. 268. 268. 268. 268. 268.
3.10 2.08 1.56 1.04 9.53 0.02 -0.49 -0.99 -1.50 -2.00 -3.02	0.2599 0.1875 0.1260 0.0913 0.0586 0.0297 0.0021 -0.0287 -0.0582 -0.0903	-1.7619 -1.2396 -0.8307 -0.5987 -0.3758 -0.1885 -0.0147 0.1881 0.25961 0.7907 1.2081	-0.0266 -0.0290 -0.0276 -0.0393 -0.0322 -0.0272 -0.0378 -0.0388 -0.0328 -0.0267	0.1347 0.1583 0.1464 0.2670 0.1975- 0.1467 0.2513 0.2612 0.2006 0.1358 0.1468 0.1211	0.0028 0.0022 0.0022 0.0015 -0.0011 0.0020 0.0020 0.0026 0.0036 0.0036	0.1713 0.1720 0.1716 0.1753 0.1750 0.1747 0.1821 0.1821 0.1755 0.1777	0.0673 0.0668 0.0663 0.0659 0.0657 0.0655 0.0655 0.0656 0.0656 0.0656	0.1040 0.1047 0.1048 0.1090 0.1090 0.1090 0.1160 0.1140 0.1121 0.1131	268. 268. 268. 268. 268. 268. 268. 268.

MODEL 946.2	CONF	1G0000	HAC	H 4.00	PHI =	90.	
Q= 4.56 PSI	RE PER	IN.= .48E06	TO=	90. DEG.F	POJ/PT	S = 100.	
PO= 321.0 CM	HG PTS=	-4068 PSI		RUN NO.	010036	9135	
ALPHA CH	CH	ćs	CY	CR CAT	CPB	CAF	RUN
4.11 0.2615	-1.7721			.0016 0.1792			269.
3.10 0.1871	~1.2350			0-0004 0-1799			269.
2.08 0.1250	-0.8187			.0019 0.1795			269.
1.56 0.0903	-0.5853			0.0007 0.1796			269.
1.05 0.0570	-0.3550			0.0007 0.1792			269.
0.54 0.0300	-0.1884			0.0203 0.1815			269.
3.02 -0.0008		-0.0789		0.1851			269.
-0.48 -0.0303		-0.0705		0.0013 0.1847			269•
-0.99 -0.0617		-0.0691 -0.0785		0.0018 0.1821			269. 269.
-1.50 -0.0932 -2.00 -0.1208				0.0027 0.1845			269.
-3.03 -3.1868		-0.0701 -0.0700:		0.0038 0.1935			269.
-4.04 -0.2580		-0.0628		0.0031 0.1928			269.
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		50002					••••
MODEL 946.2	CONF	IG0000	HAC	CH 4.00	PHE =	60.	
MODEL 946.2 Q= 4.56 PSI		IG0000 IN.= .48E0		CH 4.00	PH! =		
Q= 4.56 PSI	RE PER	IN.= .48E00		90. DEG.F	P0 J/ P1	is = .	
	RE PER	IN.= .48E00		90. DEG.F	_	is = .	
Q= 4.56 PSI	RE PER	IN.= .48E00		90. DEG.F	P0 J/ P1	is = .	RUŃ
Q= 4.56 PS1 PD= 321.0 CR	RE PER SHG PTS=	IN.= .48E00 .4)68 PSI CS	5 T0=	90. DEG.F RUN NO. CR CAT	POJ/P1 . 010036 CPB	S = . 9136 CAF	RUN 270 •
Q= 4.56 PSI PD= 321.0 CR ALPHR CN 4.11 0.2614	RE PER	IN.= .48E06 .4)68 PSI CS -0.0116	CY 0.0657216	90. DEG.F RUN NO.	POJ/P1 010036 CPB 0.0671	S = . 9136 CAF 0.1190	***
Q= 4.56 PSI PD= 321.0 CR ALPHA CN 4.11 0.2614 3.10 0.1931	RE PER SHG PTS= CH -1.7761 -1.2939	IN.= .48E06 .4)68 PSI CS -0.0116 -0.0083	CY 0.0657 ²¹ 6 -0.0397-0	90. DEG.F RUN NO. CR CAT 3.0006 0.1861	POJ/P1 010036 CPB 0.0671 0.0667	S =	270.
Q= 4.56 PSI PD= 321.0 CR ALPHA CN 4.11 0.2614 3.10 0.1931	RE PER HHG PTS= CH -1.7761	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084	CY 0.0657 ² C 0.0397-0	90. DEG.F RUN NO. CR CAT 3.0006 0.1861 3.0012 0.1882 3.0002 0.1893	POJ/PI 010036 CPB 0.0671 0.0667 0.0658	S =	270 • 270 •
Q= 4.56 PSI PO= 321.0 CP ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285	RE PER SHG PTS= CH -1.7761 -1.2939 -0.8565	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090	CY 0.0657 ² C 0.0397-0 0.0408 C	90. DEG.F RUN NO. CR CAT 3.0006 0.1861 3.0012 0.1882	POJ/PT . 010036 CPB 0.0671 0.0667 0.0658 0.0654	S =	270. 270. 270.
Q= 4.56 PSI PO= 321.0 CP ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936	RE PER SHG PTS= CH -1.7761 -1.2939 -0.8565 -0.6225	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133	CY 0.0657*** 0.0397-0 0.0408 0 0.0478 0 0.0935-0	90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1882 0.0002 0.1893 0.0003 0.1851	POJ/PT . 010036 . CPB 0.0671 0.0667 0.0658 0.0654	S =	270. 270. 270. 270.
Q= 4.56 PSI PO= 321.0 CF ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604	RE PER GH PTS= CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039	CY 0.0657 0.0397 0.0408 0.0478 0.0935 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.00000 0.00000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.0000 0.000000	90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1882 0.0002 0.1893 0.0003 0.1851 0.0037 0.1845	POJ/PT 010036 CPB 0.0671 0.0667 0.0658 0.0654	CAF 0.1190 0.1216 0.1235 0.1198 0.1194 0.2186	270. 270. 270. 270. 270. 270.
Q= 4.56 PSI PO= 321.0 CF ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604 0.54 0.0343	RE PER GHG PTS= CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937 -0.2351	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039 -0.0081	CY 0.0657 C 0.0397 C 0.0408 C 0.0478 C 0.0935 C 0.0488 C	90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1862 0.0002 0.1893 0.0003 0.1851 0.0037 0.1845 0.0009 0.1636	POJ/P1 010036 CPB 0.0671 0.0658 0.0654 0.0651 0.0650	CAF 0.1190 0.1216 0.1235 0.1198 0.1194 0.1186 0.1156	270 • 270 •
Q= 4.56 PSI PO= 321.0 CF ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604 0.54 0.0343 0.03 0.0034	RE PER CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937 -0.2351 -0.0253 0.1557	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039 -0.0081	CY 0.0657 0.0397 0.0408 0.0478 0.0935 0.0000 0.00488 0.020660 0.179 0.1179	90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1862 0.0002 0.1893 0.0003 0.1851 0.0003 0.1859 0.0009 0.1836 0.0009 0.1836	POJ/P1 010036 CPB 0.0671 0.0658 0.0654 0.0651 0.0650 0.0651 0.0651	CAF 0.1190 0.1216 0.1235 0.1198 0.1196 0.1156 0.1208 0.1227	270. 270. 270. 270. 270. 270. 270. 270.
Q= 4.56 PSI PO= 321.0 CP ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604 0.54 0.0343 0.03 0.0034 -0.48 -0.0252	RE PER CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937 -0.2351 -0.0253 0.1557	IN.= .48E06 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039 -0.0081 -0.0056 -0.0147	CY 0.0657 CO 0.0397 CO 0.0408 CO 0.0478 CO 0.0408 CO 0.0206 CO 0.1179 CO 0.1274 CO	90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1862 0.0002 0.1893 0.0003 0.1851 0.0003 0.1845 0.0009 0.1836 0.0005 0.1859 0.0005 0.1859 0.0005 0.1879 0.0018 0.1897	POJ/P1 010036 CPB 0.0671 0.0658 0.0654 0.0651 0.0650 0.0651 0.0652 0.0652	CAF 0.1190 0.1216 0.1235 0.1198 0.1196 0.1156 0.1208 0.1227 0.1243	270. 270. 270. 270. 270. 270. 270. 270.
Q= 4.56 PSI PO= 321.0 CP ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604 0.54 0.0343 0.03 0.0034 -0.48 -0.0252 -0.99 -0.0619 -1.50 -0.0916 -2.00 -0.1130	RE PER CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937 -0.2351 -0.0253 0.1557 0.4202 0.6140 0.7297	IN.= .48E00 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039 -0.0081 -0.0056 -0.0147 -0.0154 -0.0032	CY 0.065770 0.0397-0 0.0408 0 0.0478 0 0.0478 0 0.0408-0 0.0408-0 0.0206-0 0.1274 0 0.7055 0	90. DEG.F RUN NO. CR CAT 3.0006 0.1861 0.0012 0.1882 0.0002 0.1893 0.0003 0.1851 0.0037 0.1845 0.0009 0.1836 0.0002 0.1806 0.0005 0.1859 0.0005 0.1879 0.0018 0.1897 0.0018 0.1887	POJ/PI 010036 CPB 0.0671 0.0667 0.0658 0.0654 0.0651 0.0650 0.0651 0.0652 0.0654 0.0654	CAF 0.1190 0.1216 0.1235 0.1198 0.1196 0.1156 0.1156 0.1227 0.1243 0.1231	270. 270. 270. 270. 270. 270. 270. 270.
Q= 4.56 PSI PO= 321.0 CP ALPHA CN 4.11 0.2614 3.10 0.1931 2.08 0.1285 1.55 0.0936 1.05 0.0604 0.54 0.0343 0.03 0.0034 -0.48 -0.0252 -0.99 -0.0619 -1.50 -0.0916	RE PER CH -1.7761 -1.2939 -0.8565 -0.6225 -0.3937 -0.2351 -0.0253 0.1557 0.4202 0.6140 0.7297 1.1540	IN.= .48E00 .4768 PSI CS -0.0116 -0.0083 -0.0084 -0.0090 -0.0133 -0.0039 -0.0081 -0.0056 -0.0147 -0.0154 -0.0032 -0.0013	CY 0.0657\(\)0.0397-0 0.0408 (0.0478 (0.0935-0 0.0408-0 0.0206-0 0.1179-0 0.1274 (0.0055 (0.0041 (90. DEG.F RUN NO. CR CAT 0.0006 0.1861 0.0012 0.1862 0.0002 0.1893 0.0003 0.1851 0.0003 0.1845 0.0009 0.1836 0.0005 0.1859 0.0005 0.1859 0.0005 0.1879 0.0018 0.1897	POJ/PI 010036 CPB 0.0671 0.0667 0.0658 0.0654 0.0651 0.0650 0.0650 0.0651 0.0652 0.0654 0.0654 0.0654	CAF 0.1190 0.1216 0.1235 0.1198 0.1196 0.1156 0.1156 0.1227 0.1243 0.1231 0.1251	270. 270. 270. 270. 270. 270. 270. 270.

HOD	EL 946.2	CONI	FIG000	00 M	CH 4-00		PHI =	60.	
Q= <u>.</u>	4.56 PSI	ŘE PER	IN.= .486	06 TO=	90. DEG	•F	POJ/PI	rs =	10.
70=	321-0 CM	HG PTS=	.4068 PS	51 -	R	UN NG.	01003	59137	
ALPHA	CN	CM	· CS	CY	CR (CAT	СРВ	CAF	RUN
4.11	0.2592	-1.7686	-0.0187	0.1077	0.0007 0	.1841	0.0667	0.1174	271.
3.10	0.1895	-1.2764	-0.0147	0.0725	0.0020 0	.1826	0.0667	0.1158	
.2.08	0.1264	-0.8496	-0.0141	0.0747	0.0018 0	-1824	0.0662	0.1162	
1.55	0.0885	-0.5829	-0.021Z		0.0014 0				
1,05	0.0624	-0.4257	-0.0118		0.0021 0				
0.53	0.0345	-0.2516	-0.0082		0.0055 0				
0 2 0 2	0.0037		-0.0096		0.0051 0				
	-0.0278		-0.0123		0.0011 0				
	-0.0563		-0.0110		0.0028 0				
	-0.0865		-0.0048		0.0025 0				
	-0.1151		-0.0976.		0.0022 0				
	-0.1773				0.0061 D				
-4.04	-0.2496	1.6610	0.0007	-0.0348	9.0063 0	-1896	0.0665	0.1232	271 c
	EL 946.2		FIG000		ACH 4-00 90- BEG	•F	PHI =	¥	20.
Q=	4•56 PSI	RE PER	IN-= -488	E06 70=	-	. F		¥	20.
Q=	4•56 PSI	RE PER		E06 70=	90. DEG			rs =	20.
Q=	4•56 PSI	RE PER	IN-= -488	E06 70=	90. DEG		P03/P1	rs =	20 . RUN
Q= PO= Alpha	4•56 PSI 321•0 CH	RE PER HG PTS=	IN.= .488	E06 TO=	90. DEG	UŅ NO:	P03/P1 010036 CPB	rs = 59139 CAF	RUN
Q= PO= ALPHA 4.10	4•56 P\$1 321•0 CH	RE PER HG PTS= CH -1.7407	IN-= -488 -4068 PS	E06 TO= SI CY 0.1444	90. DEG RI CR (UN NO. CAT ~1930	P03/P1 01:0036 CPB 0.0674	TS = 59139 CAF 0.1256	RUN 5 273.
Q= P0= ALPHA 4.10 3.10	4•56 PŞI 321•0 CH CN 0•2549	RE PER HG PTS= CM -1.7407 -1.2574	IN.= .488 .4968 PS CS -0.0244	E06 TO= SI CY 0.1444 0.1167	90. DEG	UN NO. CAT .1930 .1927	P03/P1 010036 CPB 0.0674 0.0672	TS = 59139 CAF 0.1256 0.1258	RUN 273. 273.
Q= PO= ALPHA 4.10 3.10 2.08	4.56 PSI 321.0 CM CN 0.2549 0.1865	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296	IN-= -488 -4968 PS CS -0.0244 -0.0212	CY 0.1444 0.1167 0.0873	90. DEG RI CR (UN NO. CAT .1930 .1927 .1960	P03/P1 010030 CPB 0.0674 0.0672 0.0665	CAF 0.1256 0.1255 0.1235	RUN 273. 273. 273.
Q= PO= ALPHA 4.10 3.10 2.08 1.55	4-56 PSI 321-0 CM CN 0-2549 0-1865 0-1233	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296 -0,5845	IN-= -488 -4068 PS CS -0.0244 -0.0212 -0.0176	CY 0.1444 0.1167 0.0873 0.0916	90. DEG RI CR (0.0070 G 0.0070 G 0.0070 G 0.0070 G	UN NO. CAT .1930 .1927 .1960 .1919	P03/P1 010030 CPB 0.0674 0.0672 0.0665 0.0659	(S = 59139 CAF 0.1256 0.1255 0.1235	RUN 273. 273. 273. 273.
Q= PO= ALPHA 4.10 3.10 2.08 1.55 1.05	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296 -0.5845 -0.3659	IN-= -488 -4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180	CY 0.1444 0.1147 0.0873 0.0916 0.1176 0.0674	90. DEG RI 0.0070 G 0.0070 G 0.0 S 0.0015 G 0.0058 D 0.0018 D	UN NO. CAT .1930 .1927 .1900 .1919 .1912 .1903	POJ/P1 G10036 CPB 0.0674 0.0672 0.0665 0.0659 0.0656	CAF 0.1256 0.1255 0.1259 0.1254	RUN 273. 273. 273. 273. 273. 273.
Q= PO= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552	RE PER HG PTS= CH -1.7407 -1.2574 -0.8296 -0.5845 -0.3659 -0.2002 0.0596	IN-= -488 -4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239	CY 0.1444 0.1147 0.0873 0.0916 0.1176 0.0674 0.1681	90. DEG RI 0.0070 0 0.0 5 0 0.0015 0 0.0018 0 0.0018 0 0.0018 0	UN NO. CAT .1930 .1927 .1960 .1919 .1912 .1903 .1923	P03/P1 010036 CPB 0.0674 0.0675 0.0659 0.0656 0.0655 0.0655	CAF 0.1256 0.1256 0.1255 0.1260 0.12549 0.1270	RUN 273. 273. 273. 273. 273. 273. 273.
Q= P0= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54 0.02 -0.49	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552 0.0285 -0.0077 -0.0338	RE PER HG PTS= CH -1.7407 -1.2574 -0.8296 -0.5845 -0.3659 -0.2002 0.0596 0.2181	IN-= -488 -4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239 -0.0159	CY 0.1444 0.1167 0.0876 0.1176 0.0674 0.1681 0.0888	90. DEG RI CR 0.0070 G 0.05 G 0.0015 G 0.0018 G 0.0018 G 0.0018 G 0.0018 G	UN NO. -1930 -1927 -1960 -1919 -1912 -1903 -1923 -1902	P03/P1 010036 CPB 0.0674 0.0672 0.0659 0.0656 0.0655 0.0653	CAF CAF 0.1256 0.1255 0.1255 0.1254 0.1249	RUN 273. 273. 273. 273. 273. 273. 273. 273.
Q= P0= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54 0.02 -0.49 -1.00	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552 0.0285 -0.0077 -0.0338 -0.0628	RE PER HG PTS= CH -1.7407 -1.2574 -0.8296 -0.5845 -0.3659 -0.2002 0.0596 0.2181 0.4021	IN-= .488 .4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239 -0.0159 -0.0116	CY 0.1444 0.1167 0.0873 0.0916 0.1176 0.0674 0.1681 0.0888 0.0461	90. DEG RI CR 0.0070 G 0.05 0 0.05 0 0.0058 0 0.0058 0 0.0058 0 0.0058 0 0.0058 0	.1930 .1927 .1960 .1919 .1912 .1903 .1903 .1902	P03/P1 010036 CPB 0.0674 0.0672 0.0655 0.0655 0.0655 0.0653 0.0653	CAF CAF 0.1256 0.1255 0.1255 0.1260 0.1249 0.1270 0.1249	RUN 273. 273. 273. 273. 273. 273. 273. 273.
Q= P0= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54 0.54 0.02 -0.49 -1.00 -1.50	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552 0.0285 -0.0077 -0.0338 -0.0628 -0.0891	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296 -0.3659 -0.2002 0.0596 0.2181 0.4021 0.5598	IN-= .488 .4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239 -0.0159 -0.0116 -0.0089	CY 0.1444 0.1167 0.0873 0.0916 0.1176 0.0674 0.1681 0.088 0.0461 0.0187	90. DEG RI CR 0.0070 G 0.0075 G 0.0015 G 0.0018 G 0.0018 G 0.0018 G 0.0018 G 0.0018 G	UN NO. 1930 .1937 .1960 .1919 .1913 .1903 .1902 .1883 .1900	PO3/P1 010036 CPB 0.0674 0.0672 0.0659 0.0659 0.0655 0.0653 0.0653 0.0654 0.0656	CAF CAF C.1256 0.1256 0.1255 0.1256 0.1259 0.1249 0.1249 0.1249	RUN 273. 273. 273. 273. 273. 273. 273. 273.
Q= P0= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54 0.02 -0.49 -1.00 -1.50	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552 0.0285 -0.0077 -0.0338 -0.0628 -0.0891 -0.1211	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296 -0.5845 -0.3659 -0.2002 0.0596 0.2181 0.4528 0.7819	IN-= .488 .4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239 -0.0159 -0.0166 -0.0089 -0.0112	CY 0.1444 0.1167 0.0873 0.0916 0.1176 0.0674 0.1681 0.088 0.0461 0.0187 0.0475	90. DEG RI CR 0.0070 G 0.0075 G 0.0015 G 0.0058 D 0.0018 D 0.0030 D 0.0052 D 0.0054 D 0.0054 D 0.0054 D	UN NO. 1930 .1927 .1960 .1919 .1912 .1903 .1902 .1883 .1900 .1917	PO3/P1 010036 CPB 0.0674 0.0672 0.0655 0.0655 0.0655 0.0653 0.0653 0.0654 0.0656	CAF 0.1256 0.1255 0.1256 0.1256 0.1256 0.1244 0.1260	RUN 273. 273. 273. 273. 273. 273. 273. 273.
Q= P0= ALPHA 4.10 3.10 2.08 1.55 1.05 0.54 0.02 -0.49 -1.00 -1.50 -2.01 -3.02	4.56 PSI 321.0 CM CN 0.2549 0.1865 0.1233 0.0872 0.0552 0.0285 -0.0077 -0.0338 -0.0628 -0.0891	RE PER HG PTS= CM -1.7407 -1.2574 -0.8296 -0.5845 -0.3659 -0.2002 0.0596 0.2181 0.4021 0.5598 0.7819 1.2113	IN-= .488 .4068 PS CS -0.0244 -0.0212 -0.0176 -0.0180 -0.0201 -0.0145 -0.0239 -0.0159 -0.0116 -0.0089	CY 0.1444 0.1167 0.0873 0.0916 0.1176 0.0674 0.1681 0.0888 0.0475 0.0308	90. DEG RI CR 0.0070 G 0.0075 G 0.0015 G 0.0018 G 0.0018 G 0.0018 G 0.0018 G 0.0018 G	.1930 .1927 .1960 .1919 .1912 .1903 .1903 .1902 .1883 .1900 .1917 .1963	PO3/P1 010036 CPB 0.0674 0.0672 0.0665 0.0656 0.0655 0.0653 0.0653 0.0654 0.0656	CAF 0.1256 0.1256 0.1256 0.1256 0.1256 0.1249 0.1228 0.1228 0.1249 0.1240	RUN 273. 273. 273. 273. 273. 273. 273. 273.

MODEL 946.2	CONFIG.	.0000 . H	ACH 4.00	PHI = 60c	
Q= 4.56 PSI R	E PER IN.	-48E06 TÛ=	90. DEG.,F	POJ/PTS = 4	0.
PO= 321.0 CHHG	PTS= .40	68 PSI	RUN NO.	0100369138	•
ALPHA CN	CH C	s cy	CR CAT	CPB CAF	RUN
4.11 0.2507 -1	.7237 -0.0	361 0.2184	-0.0006 0.1839	0.0676 0.1164	272.
	.2340 -0.0		0.0012 0.1836		272.
	.8062 -0.C		-0.0001 0.1871		272.
	-5356 -0.0		-0.0010 0.1902		272.
	.3533 -0.0		0.0023 0.1844		272.
	1.1753 -0:0		0.0030 0.1849		272.
	0.0156 -0.0		0.0011 0.1977		272.
	.2070 -0.0		0.0039 0.1884		272.
	-4138 -0.0		0.0035 0.1889		272.
	0.6639 -0.0		0.0031 0.1897		
	-7889 -0.0		0.0013 0.1875		272.
	.2369 -0.0		0.0031 0.1934		272.
~4.04 -0.2592 1	.7188 -0.0	0.0436	0.0106 0.1954	0.0666 0.1288	272.
MODEL 946.2 Q= 4.56 PSI R	CONFIG.		ACH 4.00	PHI = 60. POJ/PTS = 10	·O.
				•	:0 .
	E PER IN.=		90. DEG.F	•	
Q= 4.56 PSI R PO= 321.0 CMHG	E PER IN.= PTS= .40	• •48E06 TO=	90. DEG.F	POJ/PTS = 10	70. RUN
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN	E PER IN.= PTS= .40	-48E06 TO= -68 PSI -S CY	90. DEG.F	POJ/PTS = 10 0100369140 CPB CAF	
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1	PTS= .40	.48E06 TO= 068 PSI .S CY 0723 0.4761	90. DEG.F RUN NO. CR CAT	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245	RUN
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1	PTS= .40 CM C	.48E06 T0= 068 PSI S CY 0723 0.4761 0695 0.4532	90. DEG.F RUN NO. CR CAT 0.0043 0.1919	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255	RUN 274.
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0	PTS= .40 CM	.48E06 T0= 068 PSI S CY 0723 0.4761 0695 0.4532 060 0.4282	90. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234	RUN 274• 274•
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0	PTS= .40 CM	.48E06 T0= 068 PSI S CY 0723 0.4761 0695 0.4532 060 0.4282	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282	RUN 274 • 274 • 274 •
Q= 4.56 PSI R P0= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0	PTS= .40 CM	.48E06 T0= 068 PSI S CY 0723 0.4761 0695 0.4532 060 0.4282 060 0.4292	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265	RUN 274 • 274 • 274 • 274 •
Q= 4.56 PSI R P0= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0	PTS= .40 CM	.48E06 T0= .68 PSI .S CY .723 0.4761 .695 0.4532 .660 0.4282 .660 0.4292 .634 0.4075 .611 0.3860	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923	POJ/PTS = 10 . 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0656 0.1297	RUN 274. 274. 274. 274. 274.
Q= 4.56 PSI R P0= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0 0.02 -0.0343 0	PTS= .40 CM	.48E06 T0= .68 PSI .5 CY .723 0.4761 .695 0.4532 .660 0.4232 .660 0.4232 .634 0.4075 .611 0.3860 .659 0.4398	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923 0.0074 0.1953 0.0028 0.1971 0.0056 0.1940	POJ/PTS = 10 .0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0656 0.1297 0.0653 0.1318 0.0652 0.1288	RUN 274. 274. 274. 274. 274. 274. 274.
Q= 4.56 PSI R P0= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0 0.02 -0.0343 0 -0.49 -0.0651 0	PTS= .40 CM .5742 -0.0 .0711 -0.0 .6341 -0.0 .3670 -0.0 .1841 -0.0 .0074 -0.0	.48E06 T0= .68 PSI .S CY .723 0.4761 .695 0.4532 .660 0.4232 .660 0.4232 .634 0.4075 .611 0.3860 .659 0.4398 .660 0.4426	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923 0.0074 0.1953 0.0028 0.1971	POJ/PTS = 10 .0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0656 0.1297 0.0653 0.1318 0.0652 0.1288	RUN 274. 274. 274. 274. 274. 274. 274. 274.
Q= 4.56 PSI R P0= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0 0.02 -0.0343 0 -0.49 -0.0651 0 -1.00 -0.0889 0	PTS= .40 CM .5742 -0.0 .0711 -0.0 .6341 -0.0 .3670 -0.0 .1841 -0.0 .0074 -0.0 .2400 -0.0	.48E06 T0= .68 PSI .5 CY .723 0.4761 .695 0.4532 .660 0.4282 .660 0.4282 .661 0.3860 .659 0.4398 .660 0.4426	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923 0.0074 0.1953 0.0028 0.1971 0.0056 0.1940	POJ/PTS = 10 .0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0658 0.1297 0.0653 0.1318 0.0653 0.1328 0.0653 0.1327	RUN 274. 274. 274. 274. 274. 274. 274. 274.
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0 0.02 -0.0343 0 -0.49 -0.0651 0 -1.00 -0.0889 0 -1.51 -0.1233 0	PTS= .40 CM .5742 -0.0 .0711 -0.0 .6341 -0.0 .3670 -0.0 .1841 -0.0 .0074 -0.0 .2400 -0.0 .4461 -0.0	.48E06 T0= 668 PSI 723 0.4761 6695 0.4532 660 0.4282 660 0.4292 6611 0.3860 6559 0.4398 660 0.4426 6550 0.3337 6628 0.4176	PO- DEG-F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923 0.0024 0.1953 0.0028 0.1971 0.0056 0.1940 0.0037 0.1979 0.0049 0.1962 0.0102 0.1981	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0673 0.1255 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0653 0.1327 0.0653 0.1327 0.0654 0.1308 0.0656 0.1325	RUN 274. 274. 274. 274. 274. 274. 274. 274.
Q= 4.56 PSI R PO= 321.0 CMHG ALPHA CN 4.09 0.2292 -1 3.09 0.1592 -1 2.07 0.0954 -0 1.54 0.0571 -0 1.04 0.0236 -0 0.52 0.0007 -0 0.02 -0.0343 0 -0.49 -0.0651 0 -1.00 -0.0889 0 -1.51 -0.1233 0 -2.02 -0.1571 1 -3.03 -0.2156 1	PTS= .40 CM .5742 -0.0 .0711 -0.0 .6341 -0.0 .3670 -0.0 .1841 -0.0 .2400 -0.0 .2400 -0.0 .4461 -0.0 .5772 -0.0	.48E06 T0= 668 PSI 723 0.4761 6695 0.4532 660 0.4282 660 0.4292 6611 0.3860 6559 0.4398 660 0.4426 660 0.4426 660 0.4558	PO. DEG.F RUN NO. CR CAT 0.0043 0.1919 0.0030 0.1928 0.0007 0.1900 0.0023 0.1943 0.0020 0.1923 0.0074 0.1953 0.0028 0.1971 0.0056 0.1940 0.0037 0.1979 0.0049 0.1962	POJ/PTS = 10 0100369140 CPB CAF 0.0674 0.1245 0.0666 0.1234 0.0662 0.1282 0.0658 0.1265 0.0656 0.1297 0.0653 0.1318 0.0653 0.1327 0.0654 0.1308 0.0656 0.1325 0.0666 0.1351	RUN 274. 274. 274. 274. 274. 274. 274. 274.

	MOD	EL 946.2	CON	FIG.	.0000	HA	CH 4.5	0	PHI =	•	
	Q=	3.77 PSI	RE-PER	IN.=	-48E06	5 TO=	90. D	EG.F	FOJ/P	TS =	•
	P0=	400.0 CM	HG PTS=	. 26	59 PSI			RUN NO.	01003	69161	
ALP	НА	CN	-CH	C.	s	CY	CR	,CAT	CPB	CAF	RUN
4.	06	0.2619	-1.8129	-0.00	037	0.0170-	0.0058	0.1631	0.0529	0.1102	275.
3.	06	0.1922	-1.3118	-0.00	044			0.1614			275.
2.	04	0.1296	-0.8855	-0.00	050			0.1595			275.
1.	52	0.0918	-0.6207	-0.00	049			0.1611			275.
1.	01	0.0597	-0.3978	-0.00	041	0.0169-	0.0020	0.1580	0.0517	0.1063	275.
0.	51	0.0348	-0.2513	-0.00	040	0.0160-	0.0042	0-1577	0.0514	0.1062	275.
-0.		0.0042	-0.0439	-0.00	040	0.0162-	0.0034	0.1589	0.0512	0.1077	275.
-9.	51	-0.0350	0.2509	-0.00	047	0.0217-	0.0025	0.1574	0.0512	0.1062	275.
-1.	02	-0.0598	0.3996	-0.00	062	0.0369-	0.0029	0.1572	0.0513	0.1059	275.
-1.	52	-0.0962	0.6662	-0.00	054	0,0255-	0.0020	0.1540	0.0513	0.1027	275.
-2.	02	-0.1153	0.7569	-0.00	061	0.0361-	0.0024	.0.1566	0.0514	0.1051	275.
-3.	04	-0.1765	1.1691	-0.00	083	0.0552-	0.	0.1562	0.0516	0.1046	275.
-4.	05	-0.2492	1.6972	-0.00	067	0.0411-	0.0015	0.1589	0-0520	0.1069	275.
	HÓĐ	EL 946.2	2011								
				FIG.	.0000		CH 4.5		PHI =	•	
	Q=	3.77 PSI	RE PER				90. DI		PHI =	• TS = J	.0.
	-		RE PER	IN.=	-48E06			EG•F			.0.
	P0=	3.77 PSI	RE PER	IN.=	.48E06			EG•F	POJ/P		O.
ALP	PO=	3.77 PSI : 400.0 CM	RE PER HG PTS≃ CM	IN.= .265	.48E06 59 PSI	6 TO=	90. D	EG•F RUN NO. CAT	POJ/P	69144 CAF	RUN
ALP	P0= HA 06	3.77 PSI 400.0 CM CN 0.2516	RE PER HG PTS= CM -1.7372	IN.= .265 C:	.48E06 59 PSI S	CY 0.0077-	90. DI CR Q. 0040	EG.F RUN NO. CAT 0.1842	POJ/P 010030 CPB 0-0522	69144 CAF 0-1320	RUN 276•
ALP 4. 3.	PO=	3.77 PSI 400.0 CM CN 0.2516 0.1848	RE PER HG PTS= CM -1.7372 -1.2621	IN.= .269 C: -0.00	-48E06 59 PSI S 026 034	CY 0.0077- 0.0145-	90. D CR 0.0040 0.0023	EG.F RUN NO. CAT 0.1842 0.1779	POJ/P 010030 CPB 0.0522 0.0525	CAF 0.1320 0.1255	RUN 276. 276.
ALP 4. 3.	P0= HA 06 05 04	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207	RE PER HG PTS= CM -1.7372 -1.2621 -0.8209	IN.= .269 .269 .000 -0.00 -0.00	-48E06 59 PSI S 026 034 041	CY 0.0077- 0.0145- 0.0202-	90. DECR 0.0040 0.0023 0.0056	EG.F RUN NO. CAT 0.1842 0.1779 0.1746	POJ/P 010030 CPB 0.0522 0.0525 0.0522	CAF 0.1320 0.1255 0.1224	RUN 276. 276. 276.
4. 3. 2.	PO= HA 06 05 04 52	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886	RE PER HG PTS= CM -1.7372 -1.2621 -0.8209 -0.6137	-0.00 -0.00 -0.00	-48E06 59 PSI 5 026 034 041 039	CY 0.0077- 0.0145- 0.0202- 0.0186-	90. DECR 0.0040 0.0023 0.0056 0.0053	EG.F RUN NO. CAT 0.1842 0.1779 0.1746 0.1732	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519	0.1320 0.1355 0.1224 0.1212	RUN 276. 276. 276. 276.
4. 3. 2.	PO= HA 06 05 04 52 01	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190	IN-= -265 -0.00 -0.00 -0.00 -0.00	-48E06 59 PSI 026 034 041 039	CY 0.0077- 0.0145- 0.0202- 0.0186- 0.0157-	90. 09 CR 0.0040 0.0023 0.0056 0.0053	CAT 0.1842 0.1779 0.1746 0.1732 0.1746	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519 0.0517	0.1320 0.1255 0.1224 0.1212 0.1229	RUN 276. 276. 276. 276. 276.
4. 3. 2. 1.	P0= HA 06 05 04 52 01	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190 -0.2603	IN.= -269 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	-48E06 59 PSI 026 034 041 039 038	CY 0.0077- 0.0145- 0.0202- 0.0186- 0.0157- 0.0176	90. 09 CR 0.0040 0.0023 0.0056 0.0053 0.0045 0.0002	CAT 0.1842 0.1779 0.1746 0.1732 0.1746 0.1742	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519 0.0517 0.0516	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1226	RUN 276. 276. 276. 276. 276.
ALP 4. 3. 2. 1.	PO= HA 06 05 04 52 01 50	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332 0.0112	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190 -0.2603 -0.1275	IN.= -269 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	-48E06 59 PSI 026 034 041 039 038 038	CY 0.0077- 0.0145- 0.0186- 0.0157- 0.0176 0.0304-	90. Di CR 0.0040 0.0023 0.0056 0.0053 0.0045 0.0002	CAT 0.1842 0.1779 0.1746 0.1732 0.1746 0.1742	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519 0.0517 0.0516 0.0514	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1226 0.1208	RUN 276. 276. 276. 276. 276. 276.
4.3.2.1.0.	PO= HA 06 05 04 52 01 50	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332 0.0112 -0.0438	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190 -0.2603 -0.1275 0.3240	IN.= -269 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	-48E06 59 PSI 026 034 041 039 038 038 054	CY 0.0077- 0.0145- 0.0186- 0.0186- 0.0176 0.0304- 0.0296-	90. Di CR 0.0040 0.0023 0.0056 0.0053 0.0045 0.0002	CAT 0.1842 0.1749 0.1746 0.1732 0.1746 0.1742 0.1722	POJ/P 010030 CP8 0.0522 0.0525 0.0522 0.0519 0.0517 0.0516 0.0514	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1226 0.1208 0.1211	RUN 276. 276. 276. 276. 276. 276. 276.
ALP 4. 3. 2. 1. 1. 0.	PO= HA 06 05 04 52 01 50	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332 0.0112 -0.0438 -0.0543	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190 -0.2603 -0.1275 0.3240 0.3259	IN.= -269 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	.48E06 59 PSI 026 034 039 038 038 054 053	CY 0.0077- 0.0145- 0.0186- 0.0157- 0.0176 0.0304- 0.0296- 0.0264-	90. Di CR 0.0040 0.0023 0.0056 0.0055 0.0045 0.0002 0.0014 0.0038	CAT 0.1842 0.1779 0.1746 0.1732 0.1746 0.1742 0.1725 0.1704	POJ/P 010030 CPB 0.0522 0.0525 0.0526 0.0517 0.0516 0.0514 0.0514	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1226 0.1208 0.1211 0.1190	RUN 276. 276. 276. 276. 276. 276. 276. 276.
ALP 4.3. 2.1. 1.0.	PO= HA 06 05 04 52 01 50 52 02	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332 0.0112 -0.0438 -0.0543 -0.0865	RE PER HG PTS= CM -1.7372 -1.2621 -0.8209 -0.6137 -0.3190 -0.2603 -0.1275 0.3240 0.329 0.5485	IN.= -265 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	.48E06 59 PSI 026 034 041 039 038 054 053 053	CY 0.0077- 0.0145- 0.0202- 0.0186- 0.0157- 0.0176 0.0304- 0.0296- 0.0264- 0.0249-	90. DECR. 0.0040 0.0023 0.0055 0.0045 0.002 0.0014 0.0038 0.0009 0.0039	CAT 0.1842 0.1779 0.1746 0.1732 0.1746 0.1742 0.1722 0.1725 0.1704 0.1717	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519 0.0514 0.0514 0.0514	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1208 0.1211 0.1190 0.1202	RUN 276. 276. 276. 276. 276. 276. 276.
ALP 4.3. 2.1. 1.0. -01.	P0= CHA 06 05 04 52 01 50 52 02 52 02	3.77 PSI 400.0 CM CN 0.2516 0.1848 0.1207 0.0886 0.0494 0.0332 0.0112 -0.0438 -0.0543	RE PER HG PTS= CM -1.7372 +1.2621 -0.8209 -0.6137 -0.3190 -0.2603 -0.1275 0.3240 0.3259	IN.= -269 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	-48E06 59 PSI 026 034 041 039 038 038 053 053 053	CY 0.0077- 0.0145- 0.0202- 0.0186- 0.0157- 0.0176 0.0304- 0.0296- 0.0249- 0.0249-	90. DECR. 0.0040 0.0023 0.0045 0.0045 0.0014 0.0038 0.0009 0.0039 0.0037	CAT 0.1842 0.1779 0.1746 0.1732 0.1746 0.1742 0.1725 0.1704	POJ/P 010030 CPB 0.0522 0.0525 0.0522 0.0519 0.0514 0.0514 0.0514 0.0514 0.0514	CAF 0.1320 0.1255 0.1224 0.1212 0.1229 0.1226 0.1208 0.1211 0.1190 0.1202 0.1184	RUN 276. 276. 276. 276. 276. 276. 276. 276.

MODEL 946.2	CONF	IG0000	HA	CH 4.5	0	PHI =	•	
Q= 3.77 PSI	RE PER	IN.= .48E0	5 TO=	90. DI	EG.F	POJ/P	TS =	20•
PO= 400.0 C!	HG PTS=	.2659 PSE			RUN NO	01.003	69145	
ALPHA CN	CM	cs	CY	CR	CAT	CP8	CAF	RUN
4.06 0.2459	-1.7041	-0.0063	0.0423-					
3.05 0.1789	-1.2271	-0.0055	0.0328-	0.0059	0.1738	0.0526	0.1212	277•
2.04 0.1148	-0.7887	-0.0062	0.0369-	0.0048	0.1706	0.0524	0.1182	
1.52 0.0814	-0.5653	-0.0068	0.0414-					
1.01 0.0550	-0.3972		0.0416-					
0.50 0.0230		-0.0067	0.0407-					
-00.0004	-0.0409		0.0390-					
-0.51 -0.0425		-0.0067	0.0409-					
-1.03 -0.0788		-0.0074	0.0466-					
-1.53 -0.1051		-0.0081	3.0519-					
-2.02 -0.1199		-0.0090	0.0594-					
-3.04 -0.1840		-0.0096	0.0657-					
-4.050.2581	1.7500	-0.0087	0.0568-	0.0002	0.1682	0.0518	0.1165	277.
MODEL 946.2 Q= 3.77 PSI		FIG0000 IN.= .48E0		CH 4.51		PHI =	• TS =	40.
	RE PER				EG.F		rs =	40.
Q= 3.77 PSI	RE PER	IN.= .48E0			EG.F	P0J/P	rs =	40. RUN
0= 3.77 PSI P0= 400.0 CI ALPHA CN	RE PER HHG PTS= CM	IN.= .48E0 .2659 PSI CS	6 TO=	90. DI	EG.F RUN NO. CAT	POJ/P - 01003 - CPB	TS = 6 91 46 CAF	RUN
0= 3.77 PSI P0= 400.0 CI ALPHA CN 4.05 0.2314	RE PER MHG PTS= CM -1.6007	IN.= .48E0 .2659 PSI CS -0.0059	6 TO= CY 0.0389-	90. DI CR	EG.F RUN NO. CAT 0.1778	POJ/P 01003 CPB 0.0525	TS = 6 91 46 CAF 0.1254	RUN • 278•
0= 3.77 PSI P0= 400.0 CI ALPHA CN	RE PER HHG PTS= CM -1.6007 -1.1388	IN.= .48E0 .2659 PSI CS	6 TO= CY 0.0389- 0.0473-	90. DI CR 0.0013	EG.F RUN NO. CAT	POJ/P 010036 CPB 0.0525 0.0526	TS = 69146 CAF 0.1254 0.1263	RUN 278.
0= 3.77 PSI P0= 400.0 CP ALPHA CN 4.05 0.2314 3.05 0.1659	RE PER HHG PTS= CM -1.6007 -1.1388	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058	6 TO= CY 0.0389- 0.0473-	90. DI CR 0.0013 0.0002 0.0004	EG.F RUN NO. CAT 0.1778 0.1789 0.1770	POJ/P 010030 CPB 0.0525 0.0526 0.0524	TS = 69146 CAF 0.1254 0.1263 0.1246	RUN 278. 3 278. 5 278.
Q= 3.77 PSI PO= 400.0 CR ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058	CY 0.0389- 0.0473- 0.0350-	90. DI CR 0.0013 0.0002 0.0004 0.0005	CAT 0.1778 0.1778 0.1770 0.1742	POJ/P 010030 CPB 0.0525 0.0526 0.0524 0.0521	TS = 69146 CAF 0.1254 0.1263 0.1246	RUN 278. 3 278. 5 278. 2 278.
Q= 3.77 PSI P0= 400.0 CP ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064	CY 0.0389- 0.0473- 0.0397 0.0400 0.0384-	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0021	CAT 0.1778 0.1779 0.1770 0.1742 0.1738 0.1725	POJ/P . 01003 CPB 0.0525 0.0526 0.0524 0.0521 0.0519 0.0517	TS = 69146 CAF 0.1254 0.1263 0.1246 0.1220	RUN 278. 3 278. 5 278. 2 278. 2 278. 3 278.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064	CY 0.0389- 0.0473- 0.0350- 0.0397 0.0400 0.0384- 0.0336-	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008	CAT 0.1778 0.1778 0.1779 0.1742 0.1742 0.1738 0.1725 0.1660	POJ/P . 01003 CPB 0.0525 0.0526 0.0524 0.0521 0.0517 0.0515	TS = 69146 CAF 0.1254 0.1256 0.1246 0.1220 0.1220 0.1216	RUN 278. 3 278. 5 278. 6 278. 6 278. 7 278.
0= 3.77 PSI P0= 400.0 CM ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434 0.50 0.0055 -0.01 -0.0192 -0.52 -0.0613	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668 0.1124 0.4301	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064 -0.0064 -0.0062 -0.0056 -0.0079	CY 0.0389- 0.0473- 0.0350- 0.0397 0.0400 0.0384- 0.0336- 0.0522-	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0021 0.0019	CAT 0.1778 0.1778 0.1779 0.1742 0.1742 0.1725 0.1660 0.1720	POJ/P . 01003 . CPB 0.0525 0.0526 0.0524 0.0521 0.0517 0.0515 0.0514	TS = 69146 CAF 0.1254 0.1256 0.1246 0.1220 0.1220 0.1220	RUN 278. 3 278. 5 278. 6 278. 6 278. 7 278. 7 278.
0= 3.77 PSI P0= 400.0 CP ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434 0.50 0.0055 -0.01 -0.0192	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668 0.1124 0.4301 0.6115	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064 -0.0064 -0.0062 -0.0056 -0.0079 -0.0086	CY 0.0389- 0.0473- 0.0397 0.0400 0.0384- 0.0336- 0.0522- 0.0574	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0021 0.0019 0.0011	CAT 0.1778 0.1778 0.1779 0.1770 0.1742 0.1738 0.1725 0.1660 0.1720	POJ/P . 01003 CPB 0.0525 0.0524 0.0521 0.0517 0.0517 0.0514 0.0514	TS = 69146 CAF 0.1254 0.1256 0.1246 0.1222 0.1226 0.1208 0.1145	RUN 278. 278. 278. 278. 278. 278. 278. 278.
Q= 3.77 PSI P0= 400.0 CP ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434 0.50 0.0055 -0.01 -0.0192 -0.52 -0.0613 -1.02 -0.0890 -1.52 -0.1039	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668 0.1124 0.4301 0.6115 0.6599	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064 -0.0062 -0.0056 -0.0079 -0.0086 -0.0094	CY 0.0389- 0.0473- 0.0350- 0.0397 0.0400 0.0384- 0.0336- 0.0522- 0.0574 0.0641-	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0011 0.0011	CAT 0.1778 0.1778 0.1779 0.1770 0.1742 0.1738 0.1725 0.1660 0.1720 0.1716	POJ/P O1003 CPB 0.0525 0.0524 0.0521 0.0517 0.0517 0.0514 0.0514	TS = 69146 CAF 0.1254 0.1256 0.1246 0.1222 0.1222 0.1228 0.1145 0.1203 0.1183	RUN 278. 278. 278. 278. 278. 278. 278. 278.
Q= 3.77 PSI P0= 400.0 CR ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434 0.50 0.0055 -0.01 -0.0192 -0.52 -0.0613 -1.02 -0.0890 -1.52 -0.1039 -2.03 -0.1330	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668 0.1124 0.4301 0.6115 0.6599 0.8550	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064 -0.0064 -0.0065 -0.0056 -0.0079 -0.0086 -0.0094	CY 0.0389- 0.0473- 0.0350- 0.0397 0.0400 0.0384- 0.0336- 0.0522- 0.0574 0.0641-	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0011 0.0011 0.0012	CAT 0.1778 0.1778 0.1779 0.1770 0.1742 0.1738 0.1725 0.1660 0.1716 0.1697 0.1724	POJ/P 010036 CPB 0.0525 0.0526 0.0524 0.0519 0.0517 0.0517 0.0514 0.0514	TS = 69146 CAF 0.1254 0.1263 0.1246 0.1208 0.1208 0.1208 0.1208 0.1208	RUN 278. 278. 278. 278. 278. 278. 278. 278.
Q= 3.77 PSI P0= 400.0 CP ALPHA CN 4.05 0.2314 3.05 0.1659 2.03 0.1032 1.52 0.0626 1.01 0.0434 0.50 0.0055 -0.01 -0.0192 -0.52 -0.0613 -1.02 -0.0890 -1.52 -0.1039	RE PER HHG PTS= CM -1.6007 -1.1388 -0.7117 -0.4184 -0.3295 -0.0668 0.1124 0.4301 0.6115 0.6599 0.8550 1.2560	IN.= .48E0 .2659 PSI CS -0.0059 -0.0067 -0.0058 -0.0064 -0.0062 -0.0056 -0.0079 -0.0086 -0.0094	CY 0.0389- 0.0473- 0.0350- 0.0397 0.0400 0.0384- 0.0336- 0.0522- 0.0574 0.0641- 0.0642- 0.0504	90. DI CR 0.0013 0.0002 0.0004 0.0005 0.0008 0.0011 0.0011 0.0012 0.0009 0.0001	CAT 0.1778 0.1778 0.1779 0.1770 0.1742 0.1738 0.1725 0.1660 0.1716 0.1697 0.1724	POJ/P 01003 CPB 0.0525 0.0526 0.0524 0.0519 0.0517 0.0515 0.0514 0.0514 0.0514	TS = 69146 CAF 0.1254 0.1263 0.1246 0.1226 0.1206 0.1206 0.1206 0.1206 0.1206 0.1206	RUN 278. 278. 278. 278. 278. 278. 278. 278.

-								
ŧ	10DEL 946.2	СОМ	FIG0000	MACH 4.	50	PHI =	•	
(]= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/PT	'S = 100.	
	0= 400.0 CI	MHG PTS=	.2659 PSI		RUN NO	. 010036	9147	
ALPI	IA CN	CM	CS	CY CR	CAT	CPB	CAF	RUN
4.0	4 0.1891	-1.2813	-0.0066	0.0445-0.004				279.
3-0	0.1251	-0.8348	-0.0058	0.0384-0.003	8 0.1865	0.0526	0.1339	279.
2.0	0.0638	-0.4279	-0.0064	0.0414-0.003	3 0.1846	0.0523	0.1323	279.
1.5	0.0275	-0.1751	-0.0063	0.0424-0.000	5 0.1862	0.0521	0.1341	279.
0.9	9 -0.0161	0.1610	-0.0055	0.0312-0.002	9 0-1848	0.0518	0.1330	279.
0 - 4	8 -0.0380	0.2927	-0.0055	0.0327-0.002	0 0-1843	0.0518	0.1326	279.
-0.0	0.0558	0.3707	~0.0055	0.0311-0.002	4 0.1838	0.0517	0.1322	279.
-0.5	2 -0.0820	0.5336	-0.0062	0.0365-0:001	5 0-1820	0.0515	0-1305	279.
-1.0	4 -0.1226	0.8394	-0.0062	0.0368-0.000	6 0-1806	0-0513	0.1293	279.
-1.5	4 -0.1490	1.0013	-0.0077	0.0471-G.001				279.
-2.0	4 -0.1695	1.1190	-0.0069	0.0421-0.000	1 0.1798	0.0511	0.1287	279.
-3.0	5 -0.2321	1.5448	-0.0068	0.0396 0.000				279.
-4.0	6 -0.3048	2.0731	-0.0067	0.0406 0.000	7 0.1866	0.0510	0.1356	279.
	10DEL 946.2	CONF	IG0000	MACH 4.	50	PHI =	15.	
C	= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/PT	s = .	
F	0= 400.0 C	HG PTS=	-2659 PSI		RUN NO	• 011036	9102	
ALPI	IA CN	CM	cs	CY CR	CAT	СРВ	CAF	RUN
4.0	8 0.2585	-1.7765	-0.0094	0.0557-0.002	7 0-1788	0-0526	0-1262	280.
3.0	8 0.1886		-0.0069	0.0382-0.003				280.
2.0		-0.8439		0.0500-0.002				280.
1.5			-0.0049	0.0230-0.000				280.
1.0	4 0.0612	-0.4087	-0.0040	0.0149-0.001				280.
0.5		-0.1962			0 0.1727			280.
0.0		-0.0141		0.0101-0.000				280.
	9 -0.0266		-0.0086	0.0543-0.000				280.
	0 -0.0592		-0.0050	0. 278-0.001				280.
	0 -0.0870		-0.0027	0.0097-0.000				280.
	1 -0.1170		-0.0033	0.0137 0.000				280.
-3.0	1 -0.1787		-0.0035	0.0185-0.001				280.
-4-0	3 -0.2515	1.7265		-0.0433 0.GUL				280.

MDDEL 946.2	CONF	160000	MACH 4.5	50 PHI	× 15.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90. C	EG.F POJ/	PTS = 10.	
PO= 400.0 CM	HG PTS=	.2659 PSI		RUN NO. 0110	369103	
ALPHA CN	CM	cs	CY CR	CAT CP8	CAF	RUN
4.09 0.2572	-1.7783	-0.0104	0.0621-0.0026	5 0.1774 U.052	5 0.1249	281.
3.08 0.1877	-1.2818	-0.0094		5 0.1784 0.052		281.
2.06 0.1239	-0.8422	-0.0076		0.1749 0.052		281.
1.55 0.0891	-0.6065			3 0.1734 0.051		281
1.03 0.0600	-0.4151			2 0.1761 0.051		281
0.53 0.0271	-0.1843			0.1714 0.051		281.
0.02 0.0023	-0.0307			0.1725 0.051		281.
-0.49 -0.0264		-0.0092		0.1722 0.051		281.
-1.00 -0.0569		-0.0027		0.1718 0.051		281.
-1.50 -0.0881		-0.0044		5 0.1716 0.051 1 0.1713 0.051		.281. 281.
-2.01 -0.1185 -3.01 -0.1808	1.2095	-0.0035		6 0.1713 0.051 6 0.1736 0.052		281.
-4.03 -0.2506		-0.0015		7 0.1644 0.052		281.
-4.03 -0.2300	1.1005	-0.0045	0.0302 0.001	0.1044 0.032	4 0.1120	201.
MODEL 946.2 Q= 3.77 PSI	CONF RE PER	IG0000 IN.= .48E0			= 15. PTS = 20.	
	RE PER				PTS = 20.	
Q= 3.77 PSI	RE PER	IN.= .48E0		DEG.F POJ/	PTS = 20. 369104	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN	RE PER IHG PTS= CH	IN.= .48E00 .2659 PSI CS	6 TO= 90. [CY CR	POJ/ RUN NO. 0110 CAT CPB	PTS = 20. 369104 CAF	2UN 282•
Q= 3.77 PSI PO= 400.0 CM	RE PER	IN.= .48E00 .2659 PSI CS -0.0187	6 TO= 90. E CY CR 0.1420-0.0026	DEG.F 20J/	PTS = 20. 369104 CAF 7 0.1254	
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.08 0.2460	RE PER IHG PTS= CM -1.6957	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170	6 TO= 90. E CY CR 0.1420-0.0026 0.1261-0.0018	DEG.F POJ/ RUN NO. 0110 CAT CPB	PTS = 20. 369104 CAF 7 0.1254 7 0.1218	282.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793	RE PER IHG PTS= CM -1.6957 -1.2230	IN.= .48E06 .2659 PSI CS -0.0187 -0.0170 -0.0167	6 TO= 90. E CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029	DEG.F POJ/ RUN NO. 0110 CAT CPB 5 0.1781 0.052 8 0.1745 0.052	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217	282. 282. 282. 282.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129	RE PER IHG PTS= CM -1.6957 -1.2230 -0.7625	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154	CY CR 0.1420-0.0026 0.1220-0.0029 0.1094-0.0022	CAT CPB 5 0.1781 0.052 8 0.1745 0.052 9 0.1741 0.052	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219	282 • 282 • 282 • 282 •
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808	RE PER IHG PTS = CM -1.6957 -1.2230 -0.7625 -0.5532	IN.= .48E06 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0022	CAT CPB 5 0.1781 0.052 8 0.1745 0.052 9 0.1741 0.052 2 0.1740 0.052	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188	282 • 282 • 282 • 282 • 282 •
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039	RE PER IHG PTS = CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048	IN.= .48E06 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0136 -0.0143	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0020 0.0952-0.0019 0.1012-0.0019	CAT CPB 5 0.1781 0.052 8 0.1745 0.052 9 0.1741 0.052 2 0.1740 0.052 5 0.1740 0.051 6 0.1720 0.051 6 0.1730 0.051	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213	282 · 282 ·
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039 -0.49 -0.0357	RE PER IHG PTS = CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048 0.2210	IN.= .48E06 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0136 -0.0143 -0.0138	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0020 0.0952-0.0019 0.1012-0.0013	CAT CPE 5 0.1781 0.052 8 0.1745 0.052 9 0.1741 0.052 2 0.1740 0.052 5 0.1740 0.051 6 0.1720 0.051 6 0.1730 0.051 2 0.1683 0.051	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213 6 0.1167	282 · 282 ·
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039 -0.49 -0.0357 -1.00 -0.0643	RE PER CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048 0.2210 0.4080	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0136 -0.0143 -0.0138	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0029 0.0952-0.0019 0.0957-0.0012 0.0957-0.0013	CAT CPE 5 0.1781 0.052 8 0.1745 0.052 9 0.1741 0.052 2 0.1740 0.052 5 0.1707 0.051 4 0.1720 0.051 3 0.1730 0.051 2 0.1683 0.051	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213 6 0.1167 6 0.1193	282 · 282 ·
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039 -0.49 -0.0357 -1.00 -0.0643 -1.50 -0.0906	RE PER CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048 0.2210 0.4080 0.5712	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0143 -0.0143 -0.0141 -0.0121	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0020 0.0952-0.0014 0.1012-0.0018 0.0957-0.0018 0.0974-0.0018	CAT CPB CAT CPB CAT CPB COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.051 PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213 6 0.1167 6 0.1193 7 0.1188	282 · 282 ·	
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039 -0.49 -0.0357 -1.00 -0.0643 -1.50 -0.0906 -2.02 -0.1247	RE PER THG PTS= CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048 0.2210 0.4080 0.5712 0.8109	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0136 -0.0143 -0.0138 -0.0138	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0020 0.0952-0.0019 0.1012-0.0019 0.0957-0.0012 0.0974-0.0019 0.0790 0.0000	CAT CPB CAT CPB CAT CPB COLTAIN 0.052 COLTAIN 0.052 COLTAIN 0.052 COLTAIN 0.052 COLTAIN 0.051	PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213 6 0.1167 6 0.1193 7 0.1188 9 0.1185	282. 282. 282. 282. 282. 282. 282. 282.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2460 3.07 0.1793 2.06 0.1129 1.54 0.0808 1.03 0.0502 0.52 0.0200 0.02 -0.0039 -0.49 -0.0357 -1.00 -0.0643 -1.50 -0.0906	RE PER IHG PTS= CM -1.6957 -1.2230 -0.7625 -0.5532 -0.3465 -0.1437 0.0048 0.2210 0.4080 0.5712 0.8109 1.2189	IN.= .48E00 .2659 PSI CS -0.0187 -0.0170 -0.0167 -0.0154 -0.0138 -0.0143 -0.0143 -0.0141 -0.0121	CY CR 0.1420-0.0026 0.1261-0.0018 0.1220-0.0029 0.1094-0.0029 0.0952-0.0019 0.0957-0.0012 0.0957-0.0012 0.0953-0.0003 0.0953-0.0003	CAT CPB CAT CPB CAT CPB COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.052 COLTAIL 0.051 PTS = 20. 369104 CAF 7 0.1254 7 0.1218 4 0.1217 1 0.1219 9 0.1188 8 0.1202 7 0.1213 6 0.1167 6 0.1193 7 0.1188 9 0.1185 0 0.1206	282. 282. 282. 282. 282. 282. 282. 282.	

MO	DEL 946.2	CON	FIG0000	М	ACH 4.50	PHI = 15.	
Q=	3.77 PSI	RE PER	IN.= .48E0	= 67 ∂	90. DEG.F	POJ/PTS = 40.	
PO	= 400.0 CM	HG PTS=	.2659 PSI		RÚN N	0. 0110369105	
ALPHA	CN	-CM	cs	CY	CR CAT	CPB CAF	RUN
4.02	0.2333	-1.6059	-0.0218	0-1619	0-0007 0-183	1 0.0526 0.1304	283.
3.07			-0.0193			0 0.0528 0.1252	283 •
2.06			-0.0187			0 0.0526 0.1234	283.
1.53			-0.0170			4 0.0520 0.1284	283.
1.03	0.0391	-0.2731	-0.0172			2 0.0519 0.1253	283.
0.52	0.0115	-0.0903	-0.0156	0.1034	0.0025 0.175	3 0.0518 0.1236	283.
0.01	-0.0141	0.0723	-0.0160	0.1078	0.0013 0.177	9 0.0517 0.1262	283.
-0.50	-0.0459	0.2851	-0.0154	0.1021	0.0020 0.174	7 0.0516 0.1231	283.
-1.00	-0.0731	0.4607	-0.0153	0.1020	0.0021 0.174	3 0.0517 0.1227	283.
-1.51	-0.1061	0.6889	-0.0159	0.1077	0.0016 0.174	1 0.0517 0.1224	283•
-2.01	-0-1377	0.9050	-0.0162	0.1143	0.0016 0.178	3 0.0518 0.1265	283.
-3.02	-0.1938	1.2808	-0.0149	0.0997	0.0024 0.174	5 0.0518 0.1228	283.
-4.03	-0.2645	1.7860	-0.0150	0.1070	0.0025 0.177	1 0.0519 0.1252	283.
	DEL 946.2		FIG0000		ACH 4.50 '	PHI = 15.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO×	90. DEG.F	POJ/PTS = 100.	
PO	= 400.0 CM	HG. PTS=	.2659 PSI		RUN N	0. 0110369106	
ALPHA	CN	CM	cs	CY	CR CAT	CPB CAF	RUN
4.08	0.1918	-1.2909	-0.0304	0-2209-	-0.0004 0.193	5 0.0532 0.1403	284.
3.06			-0.0271			0 0.0532 0.1369	284.
2.05			-0.0239			0 0.0528 0.1352	284.
1.53			-0.0237			4 0.0522 0.1342	284.
1.03	0.0027	0.0014	-0.0221	0.1456	0.0012 0.186	0 0.0520 0.1339	284.
	-0.0280		-0.0205			2 0.0519 0.1324	284.
0.	-0.0568		-0.0200			9 0.0518 0.1352	284.
-0.50	-0.0854	0.5816	-0.0203			6 0.0516 0.1350	284.
-1.01	-0.1.112	0.7426	-0.0198			2 0.0515 0.1347	284.
-1.51	-0.1442	0.9675	-0.0204			0 0.0514 0.1346	284.
-2.02	-0-1748	1.1736	-0.0188	0.1189	0.0018 0.185	7 0.0514 0.1343	284 .
-3.03	-0.2327	1.5657	-0.0164	0.0997	0.0019 0.184	9 0.0513 0.1336	284.
-4.04	-0.3077	2.1133	-0.0119	0.0651	0.0026 0.187	5 0.0514 0.1361	284 -

HODEL 94	46.2 CON	FIG0000	MAI	CH 4.50		PHE =	30.	
Q= 3.77	PSI RE PER	IN.= .48E0	6 10=	90. DEG	.F	POJ/PT	S =	•
PO= 400	.O CMHG PTS=	.2659 PSI		R	UN NO.	011036	9107	
ALPHA C	ч см	cs	CY	CR (CAT	CP8	CAF	RUN
4.16 0.26	624 -1.7998	-0.0066	0.0439-	0.0015 0	.1727 0	.0524	0.1202	285.
3:15 0:19		-0.0085		0.0017 0				285.
2.13 0.17		-0.0089		0.0018 0.	-			285.
1.51 0.09		-0.0070		O•0032 O∙				285.
1.12 0.00		-0.0078		0.0032 0				285.
0.60 0.03		-0.0065		0.0002 0				285.
7.09 0.00		-0.0046		C. 0004 O.				285.
-0.42 -0.03		-0.0041		G. 0003 O.				285.
-0.92 -0.09		-0.0041		0.0009 0				285.
-1.44 -0.08		-0.0050		0.0002 0.				285.
-1.94 -0.13 -2.94 -0.13		-0.0037 -0.0013		0.0014 0.				285.
-3.95 -0.24				0.0006 0. 0.0016 0.				285. 285.
-3.75 -0.2	430 1,0194	0.0022	-0.0235	O-DOID O	• 1 100 0	+0523	0.11//	285•
MODEL 94		FIG0000		CH 4.50		PHI =	30•	
MODEL 94 Q= 3.77		FIG0000 IN.= .48E0		CH 4.50 90. DEG		PHI = PO J/ PT		10.
Q= 3.77		IN.= .48E0		90. DEG		POJ/PT	S = .	10.
Q= 3.77	PSI RE PER	IN.= .48E0		90. DEG	.F	POJ/PT	S = .	10 . RUN
Q= 3.77 PO= 400.	PSI RE PER •0 CMHG PTS= v CM	IN.= .48E0 .2659 PSI	6 TO=	90. DEG	.F UN NO. Cat	POJ/PT 011036 CPB	S = . 9108 CAF	
Q= 3.77 PO= 400. ALPHA CR	PSI RE PER •0 CMHG PTS= • CM 581 -1.7789	IN.= .48E0 .2659 PSI CS	6 TO= CY 0.0463-	90. DEG. RI CR (0.0021 0.	.F UN NO. CAT .1700 0	POJ/PT 011036 CPB •0527 •0528	S = 9108 CAF 0.1173	RUN
Q= 3.77 PO= 400. ALPHA CR	PSI RE PER O CMHG PTS= O CM OM OM OM OM OM OM OM OM OM	IN.= .48E0 .2659 PSI CS -0.0079	6 TO= CY 0.0463-	90. DEG. RI CR (.F UN NO. CAT .1700 0	POJ/PT 011036 CPB •0527 •0528	S = 9108 CAF 0.1173	RUN 286•
Q= 3.77 PO= 400. ALPHA CN 4.15 0.29 3.15 0.19	PSI RE PER O CMHG PTS= O CM OM OM OM OM OM OM OM OM OM	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105	6 TO= CY 0.0463 0.0711 0.0432 0.0333	90. DEG RI CR (0.0021 0. 0.0023 0. 0.0031 0. 0.0038 0.	.F UN NO. CAT .1700 0 .1707 0 .1712 0	POJ/PT 011036 CPB -0527 -0528 -0525	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203	RUN 286 • 286 •
Q= 3.77 P0= 400. ALPHA CN 4.15 0.25 3.15 0.15 2.13 0.12 1.61 0.08 1.10 0.06	PSI RE PER O CMHG PTS= O CM OM OM OM OM OM OM OM OM OM	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0075 -0.0064 -0.0064	6 T0= CY 0.0463 0.0711 0.0432 0.0333 0.0332	90. DEG RI CR (0.0021 0. 0.0023 0. 0.0031 0. 0.0038 0. 0.0013 0.	.F UN NO. CAT .1700 O .1707 O .1712 O .1725 O .1691 O	POJ/PT 011036 CPB -0527 -0528 -0525 -0522	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171	RUN 286 • 286 • 286 • 286 •
Q= 3.77 P0= 400. ALPHA CN 4.15 0.25 3.15 0.15 2.13 0.11 1.61 0.08 1.10 0.06 0.59 0.03	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 391 -0.5998 506 -0.4113 330 -0.2331	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0075 -0.0064 -0.0064	CY 0.0463 0.0711 0.0432 0.0333 0.0332 0.0215	90. DEG RI CR (0.0021 0. 0.0023 0. 0.0031 0. 0.0038 0. 0.0013 0. 0.0013 0.	.F UN NO. 1700 O .1707 O .1712 O .1725 O .1691 O	POJ/PT 011036 CPB • 0527 • 0528 • 0525 • 0522 • 0520 • 0518	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1167	RUN 286 • 286 • 286 • 286 • 286 •
Q= 3.77 P0= 400. ALPHA CA 4.15 0.25 3.15 0.15 2.13 0.13 1.61 0.08 1.10 0.06 0.59 0.03 0.09 0.00	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 391 -0.5998 506 -0.4113 330 -0.2331 032 -0.0299	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0075 -0.0064 -0.0064 -0.0051 -0.0060	CY 0.0463 0.0711 0.0432 0.0333 0.0335 0.0335	90. DEG RI CR (0.0021 0 0.0023 0 0.0031 0 0.0031 0 0.0038 0 0.0013 0 0.0001 0 0.0002 0	FUN NO. CAT .1700 0 .1707 0 .1712 0 .1725 0 .1691 0 .1686 0 .1740 0	POJ/PT 011036 CPB •0527 •0528 •0525 •0525 •0520 •0518 •0518	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1167 0.1222	RUN 286 • 286 • 286 • 286 • 286 • 286 •
Q= 3.77 P0= 400. ALPHA CA 4.15 0.25 3.15 0.15 2.13 0.12 1.61 0.08 1.10 0.06 0.59 0.03 0.09 0.00 -0.42 -0.02	PSI RE PER O CMHG PTS= O CMHG PTS= O CM O CMHG PTS= IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0064 -0.0064 -0.0061 -0.0060 -0.0040	6 T0= CY 0.0463 0.0711 0.0432 0.0333 0.0335 0.0335 0.0146	90. DEG RI CR (0.0021 0 0.0023 0 0.0031 0 0.0031 0 0.0038 0 0.0013 0 0.0001 0 0.0001 0 0.0002 0 0.0009 0	FUN NO. CAT .1700 0 .1707 0 .1712 0 .1725 0 .1691 0 .1686 0 .1740 0	POJ/PT 011036 CPB •0527 •0528 •0525 •0522 •0520 •0518 •0518	S = 9108 CAF 0.1173 0.1179 0.1180 0.1171 0.1167 0.1222 0.1189	RUN 286 • 286 • 286 • 286 • 286 • 286 • 286 •	
Q= 3.77 P0= 400. ALPHA CA 4.15 0.25 3.15 0.15 2.13 0.12 1.61 0.08 1.10 0.00 0.59 0.03 0.09 0.00 -0.42 -0.02 -0.92 -0.05	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 391 -0.5998 506 -0.4113 330 -0.2331 330 -0.2331 330 -0.2365 0.1660 0.3657	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0064 -0.0064 -0.0051 -0.0060 -0.0040 -0.0021	6 T0= CY 0.0463 0.0711 0.0432 0.0333 0.0325 0.0335 0.01460.0032	90. DEG RI CR (0.0021 0 0.0023 0 0.0031 0 0.0038 0 0.0038 0 0.0013 0 0.0001 0 0.0002 0 0.0002 0 0.0009 0 0.0003 0	FUN NO. 1700 0 1707 0 1712 0 1725 0 1691 0 1686 0 1740 0 1706 0	POJ/PT 011036 CPB •0527 •0528 •0525 •0522 •0520 •0518 •0518 •0516	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1167 0.1222 0.1189 0.1169	RUN 286 • 286 • 286 • 286 • 286 • 286 • 286 •
Q= 3.77 P0= 400. ALPHA CN 4.15 0.25 3.15 0.15 2.13 0.12 1.61 0.08 1.10 0.09 0.59 0.03 0.09 0.00 -0.42 -0.02 -0.92 -0.03 -1.43 -0.08	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 360 -0.4113 330 -0.2331 330 -0.2331 332 -0.0299 0.1660 562 0.3657 860 0.5598	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0064 -0.0064 -0.0051 -0.0060 -0.0040 -0.0021 -0.0029	6 T0= CY 0.0463-(0.0711-(0.0432-(0.0333-(0.0215-(0.0335-(0.0146-(0.0032(0.0049()	90. DEG RI CR (0.0021 0.0023 0.0023 0.0031 0.0038 0.0013 0.00013 0.00013 0.00001 0.00002 0.00003 0.000003 0.000003 0.000003 0.00000000	.F UN NO. 1700 0 .1707 0 .1712 0 .1725 0 .1691 0 .1686 0 .1740 0 .1706 0	POJ/PT 011036 CPB .0527 .0528 .0525 .0522 .0518 .0518 .0516 .0517	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1167 0.1189 0.1169 0.1179	RUN 286 • 286 • 286 • 286 • 286 • 286 • 286 • 286 •
Q= 3.77 PO= 400. ALPHA CR 4.15 0.29 3.15 0.19 2.13 0.12 1.61 0.08 1.10 0.06 0.59 0.03 0.09 0.06 -0.42 -0.02 -0.92 -0.05 -1.43 -0.08 -1.94 -0.11	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 391 -0.5998 506 -0.4113 330 -0.2331 -0.0293 265 0.1660 562 0.3657 360 0.5598 162 0.7617	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0075 -0.0064 -0.0061 -0.0060 -0.0040 -0.0021 -0.0029 -0.0057	CY 0.0463 0.0711 0.0432 0.0333 0.0332 0.0355 0.0356 0.0049: 0.0049: 0.00330:	90. DEG RI CR 0.0021 0. 0.0023 0. 0.0031 0. 0.0038 0. 0.0013 0. 0.0001 0. 0.0002 0. 0.0009 0. 0.0009 0. 0.0003 0. 0.0003 0. 0.0003 0.	.F UN NO. 1700 0 1707 0 1712 0 1725 0 1691 0 1740 0 1706 0 1706 0	POJ/PT 011036 CPB .0527 .0528 .0525 .0522 .0520 .0518 .0518 .0517 .0518	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1222 0.1189 0.1169 0.1179 0.1188	RUN 286 • 286 • 286 • 286 • 286 • 286 • 286 • 286 • 286 •
Q= 3.77 P0= 400. ALPHA CN 4.15 0.25 3.15 0.15 2.13 0.12 1.61 0.08 1.10 0.09 0.59 0.03 0.09 0.00 -0.42 -0.02 -0.92 -0.03 -1.43 -0.08	PSI RE PER O CMHG PTS= N CM 581 -1.7789 907 -1.2997 251 -0.8452 891 -0.5998 506 -0.4113 330 -0.2331 032 -0.0299 0.1660 0.3657 360 0.5598 162 0.7617 764 1.1742	IN.= .48E0 .2659 PSI CS -0.0079 -0.0105 -0.0075 -0.0064 -0.0051 -0.0060 -0.0040 -0.0021 -0.0029 -0.0057 -0.0033	CY 0.0463 0.0711 0.0432 0.0333 0.0215 0.0335 0.0146 0.0032 0.0049 0.0330 0.0146	90. DEG RI CR (0.0021 0.0023 0.0023 0.0031 0.0038 0.0013 0.00013 0.00013 0.00001 0.00002 0.00003 0.000003 0.000003 0.000003 0.00000000	.F UN NO. 1700 0 1707 0 1712 0 1725 0 1691 0 1686 0 1740 0 1766 0 1686 0	POJ/PT 011036 CPB -0527 -0528 -0525 -0520 -0518 -0516 -0517 -0518 -0519	S = 9108 CAF 0.1173 0.1179 0.1188 0.1203 0.1171 0.1167 0.1189 0.1179 0.1188 0.1176	RUN 286 • 286 • 286 • 286 • 286 • 286 • 286 • 286 •

MODEL 946.2	CONI	FIG0000	MACH 4.5	0	PHI =	30.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90. D	EG.F	P0J/P1	rs =	20•
PO= 400.0 CF	HG PTS=	.2659 PSI		RUN NO.	01103	59109	
ALPHA: CN	CĤ	cs	CY CR	CAT	CP8	CAF	RUN
4.15 0.2531	-1.7457		0.1124-0.0020				
3-14 0-1347 2-13 0-1178	-1.2592		0.0987-0.0022				287. 287.
	-0.1931	-0.0124	0.0750-0.0024 0.0650-0.0012				
1.61 0.0852 1.10 0.0575		-0.0099	0.0553-0.0012				
0.60 0.0240	-	-0.0128	0.0831-0.0013				
0.08 0.0009		-0.0020	0.0433-0.0039				
-0.42 -0.0329		-0.0075	0.0366 0.0004				
-0.93 -0.0606		-0.0089	0.0507-0.0002				
-1.44 -0.0903		-0.0070	0.0329 0.0003				
-1.95 -0.1206		-0.0072	0.0363-0.0010				287.
-2.95 -0.1803	1.1956	-0.0054	0.0239 0.0001	0.1685	0.0521	0.1164	287.
-3.96 -0.2533	1.7238	-0.0039	0.0200 0.0017	0.1721	0.0524	0.1197	287.
MODEL 946.2	CONI				PH1 =	30 .	40
MODEL 946.2 Q= 3.77 PSI		=IG0000 IN.= .48E0			PH1 =		40.
	RE PER	IN.= .48E0	6 TO= 90. D		POJ/P	rs =	40.
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90. D	EG.F	POJ/P	rs =	40 . RUN
Q= 3.77 PSI PO= 400.0 CM	RE PER HG PTS=	IN.= .48E0 .2659 PSI	6 TO= 90. D	EG.F RUN NO. CAT	POJ/P3 011036 CPB	rs = 59110 CAF	RUN
Q= 3.77 PSI PO= 400.0 CH ALPHA CN	RE PER HG PTS= CM -1.6652	IN.= .48E0 .2659 PSI CS	6 TO= 90. D	RUN NO. CAT	POJ/P1 011036 CPB 0.0529	TS = 59110 CAF 0.1238	RUN 288•
Q= 3.77 PSI PO= 400.0 CH ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096	RE PER HHG PTS= CM -1.6652 -1.1755	IN.= .48E0 .2659 PSI CS -0.0184	6 TO= 90. D CY CR 0.1167 0.0006	EG.F RUN NO. CAT 0.1767	POJ/P1 - 011036 - CPB - 0.0529 - 0.0530	TS = 59110 CAF 0.1238 0.1229	RUN 288•
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147	6 TO= 90. D CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0813 0.0001	CAT 0.1767 0.1759 0.1751 0.1748	POJ/PT - 011036 - CPB - 0.0529 - 0.0530 - 0.0528 0.0523	TS = 59110 CAF 0.1238 0.1229 0.1223 0.1225	RUN 288 • 288 • 288 •
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155	6 TO= 90. D CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0813 0.0001 0.0907 0.0001	CAT 0.1767 0.1759 0.1751 0.1748 0.1745	POJ/PI 011036 CPB 0.0529 0.0528 0.0528 0.0523 0.0523	CAF 0.1238 0.1229 0.1223 0.1225 0.1224	RUN 288. 288. 288. 288.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149	6 T0= 90. D CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.09313 0.0001 0.0907 0.0001 0.0861-0.0012	CAT CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1753	POJ/PT 011036 CPB 0.0529 0.0530 0.0528 0.0523 0.0523 0.0520 0.0518	CAF 0.1238 0.1229 0.1223 0.1225 0.1225 0.1235	RUN 288. 288. 288. 288. 288.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122	6 T0= 90. D CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0813 0.0001 0.0907 0.0001 0.0861-0.0012 0.0661 0.0018	CAT CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1753	POJ/PT 011036 CPB 0.0529 0.0530 0.0528 0.0523 0.0523 0.0528 0.0518	CAF 0.1238 0.1229 0.1223 0.1225 0.1224 0.1235	RUN 288. 288. 288. 288. 288. 288.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101 -0.43 -0.0415	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540 0.2627	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122 -0.0104	6 T0= 90. D CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.09313 0.0001 0.0907 0.0001 0.0861-0.0012 0.0661 0.0018 0.0493-0.0014	CAT CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1777 0.1743	POJ/PT 011036 CPB 0.0529 0.0528 0.0528 0.0523 0.0528 0.0518 0.0518	CAF 0.1238 0.1229 0.1223 0.1225 0.1225 0.1235 0.1259	RUN 288 • 288 • 288 • 288 • 288 • 288 • 288 •
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101 -0.43 -0.0415 -0.93 -0.0754	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540 0.262' 0.	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122 -0.0104 -0.0126	CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0813 0.0001 0.0907 0.0001 0.0861-0.0012 0.0661 0.0018 0.0493-0.0014 0.0699 0.0029	CAT CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1773 0.1777 0.1743 0.1769	POJ/PT 011036 CPB 0.0529 0.0528 0.0528 0.0523 0.0520 0.0518 0.0518 0.0516	CAF 0.1238 0.1229 0.1223 0.1225 0.1225 0.1235 0.1259 0.1227	RUN 288. 288. 288. 288. 288. 288. 288. 288
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101 -0.43 -0.0415 -0.93 -0.0754 -1.44 -0.1030	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540 0.2627 0.06600	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122 -0.0104 -0.0126 -0.0085	CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0913 0.0001 0.0907 0.0001 0.0861-0.0012 0.0661 0.0018 0.0493-0.0014 0.0699 0.0029 0.0341 0.0022	CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1757 0.1777 0.1743	POJ/PI 011036 CPB 0.0529 0.0528 0.0523 0.0523 0.0520 0.0518 0.0516 0.0516	CAF 0.1238 0.1229 0.1223 0.1225 0.1224 0.1235 0.1259 0.1253 0.1257	RUN 288. 288. 288. 288. 288. 288. 288. 288
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101 -0.43 -0.0415 -0.93 -0.0754 -1.44 -0.1030 -1.95 -0.1340	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540 0.2627 0. 0.6700 0.8858	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122 -0.0104 -0.0126 -0.0085 -0.0100	CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0913 0.0001 0.0907 0.0001 0.0661 0.0018 0.0493-0.0014 0.0699 0.0029 0.0341 0.0022	CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1777 0.1743 0.1769 0.1734	POJ/PI 011036 CPB 0.0529 0.0528 0.0523 0.0523 0.0520 0.0518 0.0518 0.0516 0.0518	CAF 0.1238 0.1229 0.1223 0.1225 0.1224 0.1235 0.1253 0.1257 0.1257	RUN 288. 288. 288. 288. 288. 288. 288. 288
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.16 0.2422 3.14 0.1728 2.13 0.1096 1.61 0.0753 1.10 0.0423 0.59 0.0166 0.08 -0.0101 -0.43 -0.0415 -0.93 -0.0754 -1.44 -0.1030	RE PER SHG PTS= CM -1.6652 -1.1755 -0.7435 -0.5108 -0.2852 -0.1189 0.0540 0.2627 0.06700 0.8858 1.2871	IN.= .48E0 .2659 PSI CS -0.0184 -0.0175 -0.0159 -0.0147 -0.0155 -0.0149 -0.0122 -0.0104 -0.0126 -0.0085	CY CR 0.1167 0.0006 0.1102 0.0004 0.0939-0.0004 0.0913 0.0001 0.0907 0.0001 0.0861-0.0012 0.0661 0.0018 0.0493-0.0014 0.0699 0.0029 0.0341 0.0022	CAT 0.1767 0.1759 0.1751 0.1748 0.1745 0.1773 0.1743 0.1769 0.1734 0.1734	POJ/PI 011036 CPB 0.0529 0.0528 0.0523 0.0523 0.0518 0.0518 0.0516 0.0518 0.0518	CAF 0.1238 0.1229 0.1223 0.1225 0.1224 0.1235 0.1259 0.1227 0.1253 0.1217 0.1217	RUN 288. 288. 288. 288. 288. 288. 288. 288

MODFL 946.2	CONF	IG0000	MACH	4.50	= 1H9	30.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 70= 9	O. DEG.F	79/109	S = 100	•
PU= 400.0 CH	HG PTS=	-2659 PSI		RUN NO.	. 011036	9111	
ALPHA CN	CH	cs	CY	CR CAT	CP8	CAF	RUN
4.14 0.2001	-1.3509	-0.0388	0.2687-0.	0005 0.1860	0.0332	0.1328	289.
3.13 0.1342	-0.8819	-0.0352		0001 0-1865			289.
2.12 0.0715	-0.4539	-0.0342	0.2276-0.	0009 0.1826	0.0529	0.1297	289.
1.11 0.0137	-0.0693	-0.0304	0.1949-0.	0017 0.1845	0.0524	0.1321	289.
0.58 -0.0211		-0.0312		0011 0-1858			289.
0.07 -0.0471		-0.0272		0018 0.1838			289.
-9.43 -0.0772		-0.0272		0025 0.1848			289.
-0.94 -0.1041		-0.0273		0013 0.1828			289.
-1.45 -0.1358		-0.0247		0018 0.1809			289.
-1.95 -0.1676		-0.0249		0023 0.1819			289•
-2.46 -0.2002		-0.0237		0023 0.1815			289,
-2.96 -0.2295		-0.0197		0021 0-1839			289.
-3.98 -0.2991	2.0472	-0.0155	0.0749 0.	0013 0.1845	0.0519	0.1325	289.
MODEL 946.2 Q= 3.77 PSI	CONF	FIG0000		4.50 0. DEG.F	PHI =	45. is =	•
	RE PER		06 TO= 9	O. DEG.F		rs =	•
Q= 3.77 PSI	RE PER	IN.= .48E0	06 TO≖ 9	O. DEG.F	POJ/PT	rs =	• RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN	RE PER IHG PTS=	IN.= .48E(.2659 PS)	06 TO= 9	O. DEG.F RUN NO CR CAT	POJ/P1 - 011036 - CP8	TS = 59112 CAF	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621	RE PER IHG PTS= CM -1.8044	IN.= .48E0 .2659 PSI CS -0.0014	06 TO= 9 CY -0.0146-0.	0. DEG.F RUN NO CR CAT 0010 0.1747	POJ/P1 . 011036 CP8 0.0527	S = 59112 CAF 0.1220	
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923	RE PER HG PTS= CM -1.8044 -1.3026	IN.= .48E0 .2659 PSI CS -0.0014 9.0006	06 T0= 9 CY -0.0146-00.0323-0.	0. DEG.F	POJ/PT . 011036 CP8 0.0527 0.0528	S = 59112 CAF 0.1220 0.1204	RUN 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277	RE PER IHG PTS= CM -1.8044	IN.= .48E0 .2659 PSI CS -0.0014	CY -0.0146-00.0323-00.0375-0.	0. DEG.F RUN NO CR CAT 0010 0.1747	POJ/PI . 011036 CP8 0.0527 0.0528 0.0524	CAF 0.1220 0.1220 0.1204 0.1195	RUN 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924	RE PER HG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169	IN.= .48E0 .2659 PSI CS -0.0014 0.0006 0.0014	CY -0.0146-00.0375-00.0552-0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719	POJ/PT . 011036 CP8 0.0527 0.0528 0.0524 0.0519	CAF 0.1220 0.1204 0.1295 0.1180	RUN 290 - 290 - 290 -
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924	RE PER HG PTS= CM -1.8044 -1.3026 -0.8579	IN.= .48E0 .2659 PSi CS -0.0014 0.0006 0.0014 0.0038	CY -0.0146-00.0323-00.0375-00.0552-0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719 0009 0.1699	POJ/PT . 011036 CP8 0.0527 0.0528 0.0524 0.0519 0.0518	CAF 0.1220 0.1204 0.1295 0.1180 0.1233	RUN 290 - 290 - 290 - 290 -
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615	RE PER HG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068	IN.= .48E0 .2659 PSi CS -0.0014 9.0006 0.0014 0.0038 0.0039	CY -0.0146-00.0323-00.0375-00.0552-00.0495-0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719 0009 0.1699 0018 0.1751	POJ/PT . 011036 CP8 0.0527 0.0528 0.0524 0.0519 0.0518 0.0516	CAF 0.1220 0.1220 0.1204 0.1295 0.1180 0.1233 0.1258	RUN 290. 290. 290. 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615 0.55 0.0311	RE PER HG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068 -0.2060	IN.= .48E0 .2659 PSi CS -0.0014 9.0006 0.0014 0.0038 0.0039 0.0035	CY -0.0146-00.0323-00.0375-00.0552-00.0495-00.0588-0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719 0009 0.1699 0018 0.1751 0001 0.1774	POJ/PT . 011036 CP8 0.0527 0.0528 0.0524 0.0519 0.0518 0.0516 0.0515	CAF 0.1220 0.1220 0.1204 0.1195 0.1180 0.1233 0.1258 0.1222	RUN 290. 290. 290. 290. 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615 0.55 0.0311 0.04 0.0028	RE PER IHG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068 -0.2060 -0.0183	IN.= .48E0 .2659 PS CS -0.0014 9.0006 0.0014 0.0038 0.0039 0.0035 0.0051	CY -0.0146-00.0323-00.0375-00.0552-00.0495-00.0588-00.0804-00.0809 0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719 0009 0.1699 0018 0.1751 0001 0.1774 0003 0.1736 0031 0.1714	POJ/PT . 011036 . CP8 0.0527 0.0528 0.0524 0.0519 0.0516 0.0516 0.0515	CAF 0.1220 0.1220 0.1204 0.1195 0.1180 0.1233 0.1238 0.1222 0.1200 0.1207	RUN 290. 290. 290. 290. 290. 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615 0.55 0.0311 0.04 0.0028 -0.47 -0.0266 -0.98 -0.0554 -1.48 -0.0885	RE PER IHG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068 -0.2060 -0.0183 0.1778	IN.= .48E0 .2659 PS CS -0.0014 9.0006 0.0014 0.0038 0.0039 0.0035 0.0051	CY -0.0146-00.0323-00.0375-00.0552-00.0495-00.0588-00.0804-00.0809 0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1749 0009 0.1699 0018 0.1774 0003 0.1774 0003 0.1774 0003 0.1774 0005 0.1722	POJ/PT . 011036 . CP8 0.0527 0.0528 0.0524 0.0519 0.0516 0.0515 0.0514 0.0515	CAF 0.1220 0.1220 0.1204 0.1295 0.1180 0.1233 0.1258 0.1222 0.1200 0.1207 0.1199	RUN 290. 290. 290. 290. 290. 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615 0.55 0.0311 0.04 0.0028 -0.47 -0.0266 -0.98 -0.0554	RE PER IHG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068 -0.2060 -0.0183 0.1778 0.3637 0.5907	IN.= .48E0 .2659 PSi CS -0.0014 0.0006 0.0014 0.0038 0.0039 0.0035 0.0077 0.0078 0.0080 0.0086	CY -0.0146-00.0323-00.0375-00.0552-00.0552-00.0588-00.0808-00.0809 00.0817 0.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1733 0007 0.1719 0009 0.1699 0018 0.1751 0001 0.1774 0003 0.1736 0010 0.1736 0010 0.1736 0010 0.1736 0010 0.1736	POJ/PT . 011036 CP8 0.0527 0.0528 0.0524 0.0519 0.0518 0.0516 0.0515 0.0515 0.0516 0.0518	CAF 0.1220 0.1204 0.1195 0.1180 0.1233 0.1258 0.1252 0.1200 0.1207 0.1199 0.1220	RUN 290. 290. 290. 290. 290. 290. 290. 290.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.11 0.2621 3.10 0.1923 2.09 0.1277 1.56 0.0924 1.06 0.0615 0.55 0.0311 0.04 0.0028 -0.47 -0.0266 -0.98 -0.0554 -1.48 -0.0885	RE PER IHG PTS= CM -1.8044 -1.3026 -0.8579 -0.6169 -0.4068 -0.2060 -0.0183 0.1778 0.3637 0.5907	IN.= .48E0 .2559 PSi CS -0.0014 9.0006 0.0014 0.0038 0.0039 0.0035 0.0051 0.0077 0.0078	CY -0.0146-C0.0323-O0.0375-O0.0552-O0.0552-O0.0588-O0.0804-O0.0809 O0.0802 O0.0817 O0.1263 O.	O. DEG.F RUN NO CR CAT 0010 0.1747 0002 0.1749 0009 0.1699 0018 0.1774 0003 0.1774 0003 0.1774 0003 0.1774 0005 0.1722	POJ/PT - 011036 CP8 0.0527 0.0528 0.0524 0.0519 0.0516 0.0515 0.0514 0.0515	CAF 0.1220 0.1204 0.1195 0.1180 0.1233 0.1258 0.1222 0.1200 0.1207 0.1199 0.1220 0.1231	RUN 290. 290. 290. 290. 290. 290. 290.

M	DDEL 946.2	CON	FIG0000	AM C	CH 4.50)	PHI =	45.	
Q:	= 3.77 PSI	RE PER	IN.= .48E	=0 T 80	90. DE	G.F	POJ/P	rs = 10	1.
P	0= 400.0 CH	HG PTS=	.2659 PS	ī		RUN NO.	01103	69113	
ALPH	A CN -	CM	cs	CY	CR	CAT	СРВ	CAF	. RUN
4.1	2 0.2569	-1.7700	-0.0064	0.0280-	0.0022	0-1720	0-0525	0.1195	291.
3.1			-0:0060	0.0219-					291.
2.0			-0.0021	-0.0136-					291.
1.5	7 0.0867		-0.0049	0.0123-	0.0015	0.1718	0.0522	0.1196	291.
1.0	6 0.0573	-0.3840	-0.0043	0.0087-	0.0023	0.1711	0.0520	0.1191	291.
0.5	5 0.0279	-0.1911	-0.0037	0.0017-	0.0032	0.1719	0.0518	0.1200	291.
0.0	4 0.0030	-0.0338	-0.0033	0.0090-	0.0021	0.1740	0.0518	0.1222	291.
-0.4	7 -0.0318	0.2106	-0.0015	-0.0110-	0.0036	0.1689	0.0517	0-1173	291.
	8 -0.0602	0.3958	0.0001	-0.0260-					291.
-1.4	B -0.0899	0.5930	-0.0008	-0.0142					291.
	9 -0.1215		-0.0002	-0.0221					291.
	0.1833		0.0021	-0.0409					291.
-4.0	0 -0.2527	1.7258	0.0036	-0-0489	0.0011	0-1742	0.0524	0.1218	291.
	DDEL 946.2		FIG0000		CH 4.50		PHI =	45.	
Q:	= 3.77 PSI	RE PER	IN.= .48E0)6 <u> </u>	90. DE	G.F	POJ/P	rs = 20	•
P	-								
	U- 40030 CR	HG PTS=	.2659 PS	Ī		RUN NO.	01103	59114	
ALPH		HG PTS=	•2659 PS	CY	CR	RUN NO.	011036 CPB	59114 CAF	RUN
	A CN	СМ	cs	CY	CR	CAT	СРВ	CAF	
4.1	A CN D 0.2527	CM -1.7441	CS -0.0125	CY 0.0715-	CR -0.0015	CAT 0.1710	CP8	CAF 0.1185	292•
4.10 3.10	A CN 0 0.2527 0 0.1834	CM -1.7441 -1.2472	CS -0.0125 -0.0110	CY 0.0715- 0.0587-	CR -0.0015 -0.0007	CAT 0.1710 0.1695	CPB 0.0525 0.0527	CAF 0.1185 0.1168	292 • 292 •
4.10 3.10 2.0	A CN D 0.2527 D 0.1834 B 0.1184	CM -1.7441 -1.2472 -0.7972	CS -0.0125 -0.0110 -0.0118	CY 0.0715- 0.0587- 0.0640-	CR -0.0015 -0.0007 -0.0012	CAT 0.1710 0.1695 0.1682	CPB 0.0525 0.0527 0.0526	CAF 0.1185 0.1168 0.1157	292•
4.10 3.10	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847	CM -1.7441 -1.2472 -0.7972 -0.5711	CS -0.0125 -0.0110	CY 0.0715- 0.0587-	CR -0.0015 -0.0007 -0.0012 -0.0014	CAT 0.1710 0.1695 0.1682 0.1677	CP8 0.0525 0.0527 0.0526 0.0521	CAF 0.1185 0.1168 0.1157 0.1156	292 • 292 • 292 •
4.10 3.10 2.00 1.5	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800	CS -0.0125 -0.0110 -0.0118 -0.0110	CY 0.0715- 0.0587- 0.0640- 0.0566-	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023	CAT 0.1710 0.1695 0.1682 0.1677 0.1728	CPB 0.0525 0.0527 0.0526 0.0521 0.0519	CAF 0.1185 0.1168 0.1157 0.1156 0.1209	292 • 292 • 292 • 292 •
4.10 3.10 2.00 1.50 1.00	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090	CY 0.0715- 0.0587- 0.0640- 0.0566- 0.0411-	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1708	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190	292 • 292 • 292 • 292 • 292 •
4.10 3.11 2.00 1.5 1.00 0.50	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558 5 0.0233	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600 0.0275	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090 -0.0114	CY 0.0715- 0.0587- 0.0640- 0.0566- 0.0411- 0.0603-	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023 -0.0031 -0.0002	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1708	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518 0.0518	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190 0.1162	292 • 292 • 292 • 292 • 292 • 292 •
4.10 3.10 2.00 1.50 1.00 0.50 0.00	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558 5 0.0233 3 -0.0050	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600 0.0275 0.2200	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090 -0.0114 -0.0077	CY 0.0715- 0.0587- 0.0566- 0.0411- 0.0603- 0.0297-	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023 -0.0031 -0.0002	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1708 0.1700 0.1692	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518 0.0518	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190 0.1162 0.1176	292. 292. 292. 292. 292. 292. 292.
4.10 3.10 2.00 1.50 1.00 0.50 0.00 -0.40	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558 5 0.0233 3 -0.0050 7 -0.0339	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600 0.0275 0.2200 0.4031	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090 -0.0114 -0.0077	CY 0.0715- 0.0587- 0.0566- 0.0511- 0.0603- 0.0297- 0.0285-	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023 -0.0031 -0.0002 -0.0035 0.0007	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1708 0.1700 0.1692 0.1700	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518 0.0516 0.0517	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190 0.1162 0.1176 0.1183	292. 292. 292. 292. 292. 292. 292.
4.10 3.10 2.00 1.50 1.00 0.50 0.00 -0.40 -0.40	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558 5 0.0233 3 -0.0050 7 -0.0339 8 -0.0622	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600 0.0275 0.2200 0.4031 0.6228	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090 -0.0114 -0.0077 -0.0077	CY 0.0715- 0.0587- 0.0640- 0.0561- 0.0603- 0.0297- 0.0285- 0.0150	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023 -0.0031 -0.0002 -0.0035 -0.0007	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1700 0.1692 0.1700 0.1694	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518 0.0518 0.0516 0.0517	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190 0.1162 0.1176 0.1183 0.1176	292. 292. 292. 292. 292. 292. 292. 292.
4.10 3.10 2.00 1.55 1.00 0.55 0.00 -0.44 -0.90	A CN 0 0.2527 0 0.1834 8 0.1184 7 0.0847 6 0.0558 5 0.0233 3 -0.0050 7 -0.0339 6 -0.0622 8 -0.0947	CM -1.7441 -1.2472 -0.7972 -0.5711 -0.3800 -0.1600 0.0275 0.2200 0.4031 0.6228 0.7979	CS -0.0125 -0.0110 -0.0118 -0.0110 -0.0090 -0.0114 -0.0077 -0.0061 -0.0064	CY 0.0715- 0.0587- 0.0640- 0.0566- 0.0411- 0.0603- 0.0297- 0.0285- 0.0150	CR -0.0015 -0.0007 -0.0012 -0.0014 -0.0023 -0.0031 -0.0005 -0.0007 -0.0005 -0.0003	CAT 0.1710 0.1695 0.1682 0.1677 0.1728 0.1708 0.1700 0.1692 0.1715 0.1745	CPB 0.0525 0.0527 0.0526 0.0521 0.0519 0.0518 0.0518 0.0516 0.0517 0.0518 0.0519	CAF 0.1185 0.1168 0.1157 0.1156 0.1209 0.1190 0.1162 0.1176 0.1183 0.1176 0.1197 0.1224	292. 292. 292. 292. 292. 292. 292. 292.

MODEL 946.2	CONF	1G0000	MAC	H 4.50	PHI =	45.	
Q= 3.77 PSI	RE PER	IN-= .48E0	6 TO=	90. DEG.F	POJ/PTS	= 40.	
PO= 400.0 CF	HG PTS=	-2659 PSI		RUN NO.	01103691	115	
ALPHA CN	CH	ES	CY	CR CAT	CP8	AF RUN	
4.12 0.2447	-1.6944	-0.0211		.0005 0.1788			
3.10 0.1744	-1.1895			.0019 0.1746			
2.08 0.1110	-0.7524			0.0014 0.1762			
1.56 0.0734	-0.4880			0.0005 0.1830			
1.05 0.0447	-0.3010			0.0003 0.1735			
0.54 0.0158	-0.1078			0.0006 0.1741 0.0024 0.1749			
0.03 -0.0120 -0.47 -0.0424		~0.0152 -0.0136		0.0024 0.1749			
-0.97 -0.0424		-0.0136		0.0022 0.1742			
-1.48 -0.1023		-0.0131		0.0018 0.1757			
-1.99 -0.1343		-0.0123		.0016 0.1795			
-2.99 -0.1930	1.2874			0.0030 0.1794			
-4.01 -0.2639		-0.0081		0.0038 0.1839			
MODEL 946.2		FIG0000		H 4.50	PHI =		
MODEL 946.2 Q= 3.77 PSI		IG0000 IN.= .48E0		SH 4.5 0 90. DEG.F	PHI = POJ/PTS		
	RE PER	IN.= .48E0	6 10=	90. DEG.F		= 100.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 10=	90. DEG.F	POJ/PTS	= 100.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER MHG PTS=	IN.= .48E0 .2659 PSI CS	6 10= CY	90. DEG.F RUN NO. CR CAT	POJ/PTS 0110369	= 100. L16 CAF RUN	
Q= 3.77 PSI PO= 400.0 C	RE PER	IN.= .48E0 .2659 PSI CS -0.0470	6 TO= CY 0-3206-0	90. DEG.F RUN NO.	POJ/PTS 0110369 CPB (= 100. L16 CAF RUN -1349 294.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.09 0.2109	RE PER MHG PTS= CM -1.4364	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452	6 TO= CY 0.3206-0 0.3010 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880	POJ/PTS 0110369 CPB (0+0531 0 0+0532 0	= 100. L16 CAF RUN -1349 294.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453	RE PER MHG PTS= CM -1.4364 -0.9688	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440	CY 0.3206-0 0.3010 0 0.2883 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880	POJ/PTS 0110369 CPB (0.0531 0. 0.0532 0. 0.0528 0.	= 100. L16 CAF RUN .1349 2941332 294.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486	CY 0.3206-0 0.3010 0 0.2883 0 0.3202 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865	POJ/PTS 01103699 CPB (0.0531 0.0532 0.0528 0.0528 0.0523 0.0522 0.052	= 100. 116 CAF RUN 1349 294. 1332 294. 1337 294. 1385 294.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486	CY 0.3206-0 0.3010 0 0.2883 0 0.3202 0 0.2533 0 0.2681 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861	POJ/PTS 01103699 CPB (0.0531 0 0.0532 0 0.0528 0 0.0528 0 0.0521 0 0.0519 0	= 100. 116 CAF RUN 1349 294. 1332 294. 1337 294. 1385 294. 1331 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398	CY 0.3206-0 0.3010 0.2883 0.3202 0.2533 0.2681 0.2528-0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861 0.0006 0.1853	POJ/PTS 01103699 CP8 0 0.0531 0 0.0532 0 0.0528 0 0.0523 0 0.0521 0 0.0519 0 0.0517 0	= 100. 116 CAF RUN .1349 2941337 2941337 2941385 2941331 2941341 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166 0.54 -0.0143 0.03 -0.0432 -0.48 -0.0746	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091 0.5224	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398 -0.0412	CY 0.3206-0 0.3010 0.2883 0.3202 0.2533 0.2681 0.2528-0 0.2660-0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861 0.0006 0.1853 0.0008 0.1862	POJ/PTS 01103699 CPB 0 0.0531 0 0.0532 0 0.0528 0 0.0523 0 0.0523 0 0.0521 0 0.0519 0 0.0517 0 0.0516 0	= 100. 116 CAF RUN .1349 2941332 2941337 2941331 2941331 2941341 2941336 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166 0.54 -0.0143 0.03 -0.0432 -0.48 -0.0746 -0.98 -0.1030	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091 0.5224 0.7061	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398 -0.0412 -0.0376	CY 0.3206-0 0.3010 0.2883 0.3202 0.3202 0.2681 0.2538-0 0.2660-0 0.2322-0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865 0.0007 0.1908 0.0005 0.1861 0.0006 0.1853 0.0008 0.1862 0.0010 0.1869	POJ/PTS 01103699 CPB 0.0531 0.0532 0.0528 0.0523 0.0523 0.0521 0.0519 0.0517 0.0516 0.0515 0.0515 0.0515 0.0515 0.0515 0.0515 0.0515	= 100. 116 CAF RUN .1349 2941332 2941337 2941331 2941331 2941341 2941336 2941346 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166 0.54 -0.0143 0.03 -0.0432 -0.48 -0.0746 -0.98 -0.1030 -1.49 -0.1340	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091 0.5224 0.7061 0.9122	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398 -0.0412 -0.0376 -0.0374	CY 0.3206-0 0.3010 0.2883 0.3202 0.2533 0.2681 0.2528-0 0.2660-0 0.2322-0 0.2284 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1864 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861 0.0006 0.1853 0.0008 0.1862 0.0010 0.1869 0.0020 0.1862	POJ/PTS 01103699 CPB 0.0531 0.0532 0.0528 0.0528 0.0521 0.0519 0.0517 0.0516 0.0515 0.	= 100. 116 CAF RUN .1349 2941332 2941337 2941385 2941385 2941341 2941336 2941346 2941353 2941353 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166 0.54 -0.0143 0.03 -0.0432 -0.48 -0.0746 -0.98 -0.1030 -1.49 -0.1340 -2.00 -0.1618	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091 0.5224 0.7061 0.9122 1.0901	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398 -0.0412 -0.0376 -0.0374	CY 0.3206-0 0.3010 0 0.2883 0 0.3202 0 0.2533 0 0.2681-0 0.2660-0 0.2322-0 0.2284 0 0.2298 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1865 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861 0.0006 0.1852 0.0008 0.1862 0.0008 0.1862 0.0010 0.1869	POJ/PTS 01103693 CPB 0.0531 0.0532 0.0528 0.0528 0.0521 0.0519 0.0517 0.0516 0.0515	= 100. 116 CAF RUN .1349 2941337 2941337 2941341 2941341 2941346 2941353 2941353 2941354 294.	
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.09 0.2109 3.09 0.1453 2.07 0.0824 1.55 0.0397 1.04 0.0166 0.54 -0.0143 0.03 -0.0432 -0.48 -0.0746 -0.98 -0.1030 -1.49 -0.1340	RE PER MHG PTS= CM -1.4364 -0.9688 -0.5379 -0.2363 -0.0893 0.1191 0.3091 0.5224 0.7061 0.9122 1.0901 1.5260	IN.= .48E0 .2659 PSI CS -0.0470 -0.0452 -0.0440 -0.0486 -0.0399 -0.0419 -0.0398 -0.0412 -0.0376 -0.0374	CY 0.3206-0 0.3010 0 0.2883 0 0.3202 0 0.2533 0 0.2681 0 0.2528-0 0.2660-0 0.2322-0 0.2284 0 0.2208 0 0.1742 0	90. DEG.F RUN NO. CR CAT 0.0001 0.1880 0.0001 0.1864 0.0009 0.1864 0.0007 0.1908 0.0005 0.1852 0.0003 0.1861 0.0006 0.1853 0.0008 0.1862 0.0010 0.1869 0.0020 0.1862	POJ/PTS 01103699 CP8 0.0531 0.0532 0.0528 0.0528 0.0521 0.0519 0.0517 0.0516 0.0515 0.0515 0.0515 0.0515 0.0515 0.0515 0.0515 0.0517 0.0515 0.0517 0.0515 0.0517	= 100. 116 CAF RUN .1349 2941332 2941337 2941385 2941341 2941341 2941346 2941353 2941347 2941354 294.	

HOI	DEL. 94632	CON	FIG0000) ห	ACH 4.5	0	PHI =	60.	
Q=	3.77 PSI	RE PER	IN.= .46E0	o6 TO=	90. D	EG•F	POJ/P	TS =	•
P0=	= 400.0 CM	HG PTS≃	- 2659 PSI	Ī		RUN NO	01103	69117	
AĹPHA	CN	CM.	-CS	CY	CR	CAT	СРВ	CAF	RUN
4.00	0.2554	-1.7535	-0.0068	0.0496	-0.0006	0.1699	0.0530	0.1169	295.
2.99	0.1875	-1.2713	-0.0029	0.0134	-0.0007	0.1708	0.0529	0.1179	295.
1.98	0.1194	-0.7976	-0.0022	0.0050	-0.0002	0.1717	0.0524	0.1194	295.
1.45		-0.5685	-0:0044	0.0245	0.0007	0.1695	0.0517	0.1178	.295 •
0.95			-0.0026	0.0088	0.0003	0.1729	0.0516	0.1212	295.
0.44	0.0258		-0.0050	0.0306	0.	0.1690	0.0515	0.1176	295。
	-0.0051		-0.0039			0.1681			295.
	-0.0325		-0.0015	0.0014	0.0006	0.1699	0.0514	0.1186	295.
-1.09	-0.0635	0.4204	-0.0036	0.0225	0.0009	0.1690	0.0514	0.1176	295.
-1-59	-0.0923		-0.0005	-0.0045					295.
	-0.1233		-0.0026			0.1714			2,95.
	-0.1843		0.0007	-0.7142					
-4.11	-0.2557	1.7489	0.	-0.0064	0.0013	0.1745	0.0522	0.1223	295.
)EL 946.2		FIG0000		ACH 4.50	-	PHI =	60.	
Q=	3.77 PSI	RE PER	IN.= .48E0)6 TO=	90. DI	EG.F	POJ/P1	rs = :	10.
P0=	= 400.0 CM	HG PTS=	-2659 PSI	I		RUN NO.	01103	59118	
ALPHA	CN	CM	CS	CY	CR	CAT	CP8	CAF	RUN
4.00	0.2516	-1.7353	-0.0113	0-0746	0.0001	0.1688	0.0528	0.1160	296.
2.99	0.1843		-0.0094			0.1697			296•
1.97			-0.0086			0.1692			296.
1.45	0.0832		-0.0081			0.1698			296.
0.94	0.0529	-0.3559	-0.0091			0.1703			296.
0.44	0.0242		-0.0059			0.1707			296.
	-0.0047		-0.0076			0.1727			296.
-0.59	-0.0356		-0.0064			0.1643			296.
-1.09	-0.0658	0.4327	-0.0041			0.1706			296.
-1.59	-0.0968	0.6406	-0.0063	0.0311-			0.0517		296.
-2.10	-0.1256	0.8266	-0.0047	0.0183-	-0.0004	0.1717			296.
	-0.1875	1.2540	-0.0059			0.1740			296.
-4.12	-0.2588	1.7663	-0.0033	0.0100	0.0019	0.1748	0.0524	0.1225	296.

MODEL 946.2	CONF	IĢ0000	H.	ICH 4.50	p	PHI =	60.	
Q= 3.77 PSI	RE PÊR	IN.= .48E00	5 TO=	90. DI	EG.F	P0J/P1	rs = 2	20.
PO= 400.0 CH	HG PTS=	.2659 PSI			RUN NO.	01103	59119	-
ALPHA CN	CH	cs	CY	CR	CAT	СРВ	CAF	.RUN
4.00 0.2527	-1.7531	-0.0137	0.0811	0.0001	0.1735	0.0527	0.1208	297.
2.99 0.1826	-1.2472				0.1714			297.
1.97 0.1180	-0.8031				0.1695			297.
1.45 0.0816	-0.5492				0.1686			297.
0.94 0.0533	-0.3684				0.1662			297.
0.43 0.0202	-0-1406				0.1727			297.
-0.07 -0.0050		-0.0109			0.1729			297.
-0.58 -0.0373		-0.0123			0.1661			297.
-1.09 -0.0668		-0.0086 -0.0108			0.1709			297. 297.
-1.59 -0.0978 -2.10 -0.1287		-0.0108			0.1734			297 .
-3.10 -0.1287	1.2477			-	0.1742			297.
-4.12 -0.2585		-0.0070			0.1795			297.
MODEL 946.2	CONF	1Ğ• •0000	8/	NCH 4.5	D	PHI ≂	60.	
MODEL 946.2 Q= 3.77 PSI		IG0000 IN.= .48E0		NCH 4.50		PHI =		•0•
	RE PER	IN.= .48E0			EG.F		rs = 4	•0•
Q= 3.77 PSI	RE PER	IN.= .48E0			EG.F	PGJ/P	rs = 4	+0• RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN	RE PER HHG PTS=	IN.= .48E00 .2659 PSI CS	6 T0≃ CY	90. D	EG.F RUN NO.	PGJ/P 011030 CPB	TS = 4 69120 Caf	
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.99 0.2423	RE PER	IN.= .48E00 .2659 PSI CS -0.0262	6 TO≃ CY 0.1684	90. Di	EG.F RUN NO	PGJ/P1 011030 CPB 0.0534	TS = 4 69120 CAF 0-1223	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.99 0.2423	RE PER HHG PTS= CM -1.6792	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235	6 TO= CY 0.1684 0.1401	99. Di CR 0.0014 0.0014	EG.F RUN NO. CAT 0.1757	PGJ/P1 011036 CPB 0.0534 0.0534	TS = 4 69120 CAF 0.1223 0.1231	RUN 298.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.99 0.2423 2.99 0.1764	RE PER HHG PTS= CM -1.6792 -1.2097	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231	CY 0.1684 0.1401 0.1388	90. DECR 0.0014 0.0014 0.0025	EG.F RUN NO. CAT 0.1757 0.1765	PGJ/PT 011036 CPB 0.0534 0.0534 0.0529	TS = 4 69120 CAF 0.1223 0.1231 0.1215	RUN 298. 298.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235	CY 0.1684 0.1401 0.1388 0.1390	90. DECR 0.0014 0.0025 0.0021	EG.F RUN NO. CAT 0.1757 0.1765 0.1744	PGJ/PT 011036 CPB 0.0534 0.0534 0.0529 0.0521	TS = 4 69120 CAF 0.1223 0.1231 0.1215 0.1230	RUN 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0256 -0.0228	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396	90. Di CR 0.0014 0.0015 0.0021 0.0024 0.0021	CAT 0.1757 0.1765 0.1744 0.1751 0.1770 0.1760	PGJ/P 011030 CPB 0.0534 0.0534 0.0529 0.0521 0.0518 0.0517	CAF 0.1223 0.1231 0.1215 0.1230 0.1252 0.1252	RUN 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097 0.0791	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0236 -0.0228	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416	90. Di CR 0.0014 0.0025 0.0021 0.0024 0.0021 0.0018	CAT 0.1757 0.1757 0.1765 0.1744 0.1751 0.1760 0.1760	PGJ/P 01103 CPB 0.0534 0.0534 0.0529 0.0521 0.0518 0.0517	CAF 0.1223 0.1231 0.1230 0.1230 0.1252 0.1243 0.1190	RUN 298. 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132 -0.58 -0.0434	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097 0.0791 0.2821	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0228 -0.0228 -0.0228	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416 0.1207	90. Di CR 0.0014 0.0025 0.0021 0.0024 0.0021 0.0018 0.0008	CAT 0.1757 0.1757 0.1760 0.1760 0.1760 0.1813	PGJ/P 011030 CPB 0.0534 0.0534 0.0521 0.0521 0.0518 0.0517 0.0516 0.0515	CAF 0.1223 0.1231 0.1231 0.1230 0.1252 0.1243 0.1190 0.1298	RUN 298. 298. 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132 -0.58 -0.0434 -1.09 -0.0722	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097 0.0791 0.2821 0.4682	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0228 -0.0228 -0.0228 -0.0206 -0.0189	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416 0.1207 0.1038	90. Di CR 0.0014 0.0025 0.0021 0.0024 0.0021 0.0018 0.0008	CAT 0.1757 0.1757 0.1765 0.1744 0.1751 0.1760 0.1760 0.1813 0.1685	PGJ/P 01103 CPB 0.0534 0.0534 0.0521 0.0518 0.0517 0.0516 0.0515	CAF 0.1223 0.1231 0.1230 0.1232 0.1230 0.1252 0.1243 0.1190 0.1298 0.1169	RUN 298. 298. 298. 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132 -0.58 -0.0434 -1.09 -0.0722 -1.59 -0.1054	RE PER HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2017 -0.1097 0.0791 0.2821 0.4682 0.6956	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0256 -0.0228 -0.0228 -0.0206 -0.0189 -0.0232	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416 0.1207 0.1038 0.1452	90. Di CR 0.0014 0.0025 0.0021 0.0021 0.0018 0.0008 0.0011 0.0032	CAT 0.1757 0.1757 0.1765 0.1744 0.1751 0.1760 0.1760 0.1813 0.1685 0.1809	PGJ/P 011030 CPB 0.0534 0.0534 0.0529 0.0518 0.0517 0.0516 0.0516 0.0517	CAF 0.1223 0.1231 0.1215 0.1230 0.1252 0.1243 0.1190 0.1298 0.1169	RUN 298. 298. 298. 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132 -0.58 -0.0434 -1.09 -0.0722 -1.59 -0.1054 -2.10 -0.1363	RE PER HHG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097 0.0791 0.2821 0.4682 0.6956 0.9030	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0228 -0.0228 -0.0228 -0.0206 -0.0189 -0.0232 -0.0205	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416 0.1207 0.1038 0.1452 0.1212	90. DE CR 0.0014 0.0025 0.0021 0.0026 0.0018 0.0018 0.0018 0.0018 0.0032 0.0023	CAT 0.1757 0.1765 0.1744 0.1751 0.1770 0.1760 0.1813 0.1883 0.1809 0.1799	PGJ/P 011036 CPB 0.0534 0.0529 0.0521 0.0518 0.0517 0.0516 0.0517	CAF 0.1223 0.1231 0.1215 0.1230 0.1252 0.1243 0.1190 0.1298 0.1169 0.1292 0.1280	RUN 298. 298. 298. 298. 298. 298. 298. 298.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.99 0.2423 2.99 0.1764 1.97 0.1119 1.45 0.0747 0.95 0.0437 0.43 0.0156 -0.08 -0.0132 -0.58 -0.0434 -1.09 -0.0722 -1.59 -0.1054	RE PER 4HG PTS= CM -1.6792 -1.2097 -0.7605 -0.5017 -0.2904 -0.1097 0.0791 0.2821 0.4682 0.6956 0.9030 1.2867	IN.= .48E00 .2659 PSI CS -0.0262 -0.0235 -0.0231 -0.0235 -0.0256 -0.0228 -0.0228 -0.0206 -0.0189 -0.0232	CY 0.1684 0.1401 0.1388 0.1390 0.1618 0.1396 0.1416 0.1207 0.1038 0.1452 0.1212	90. DE CR 0.0014 0.0025 0.0021 0.0024 0.0018 0.0018 0.0011 0.0032 0.0023 0.0023	CAT 0.1757 0.1757 0.1765 0.1744 0.1751 0.1760 0.1760 0.1813 0.1685 0.1809	PGJ/P 011036 CPB 0.0534 0.0534 0.0529 0.0518 0.0517 0.0516 0.0515 0.0517 0.0519 0.0519	CAF 0.1223 0.1231 0.1215 0.1230 0.1252 0.1243 0.1190 0.1298 0.1292 0.1280 0.1285	RUN 298. 298. 298. 298. 298. 298. 298. 298.

M	ODEL	. 946.	2 (0)	VFIG.	•0000	M	ACH 4.5	0	PHI =	60.	
Q	= 3.	-77 PS	RE PE	R IN.=	-48E0	6 10=	90. D	EG.F	P0J/P	TS = 1	100-
P	0= 4	00.0	HHG PTS	26	59 PSI			RUN NO	01103	69121	
ALCH	A	CN	CM	С	s	CY	CR	CAT	CPB	CAF	RUN
3.9	9 (.2233	-1.542	3 -0.0	574	0.3910	0.0010	0.1846	0.0529	0.131	7 299.
2.9	8 (1561	-1.058	7 -0.0	555	0.3735	0.0009	0.1824	0.0531	0.1294	4 299.
1.9	7 (0.0893	-0.591	-0.0	589	0.4025	-0.0004	0.1835	0.0528	0.130	7 299.
1.4	5 (0.0543	-0.347	0.0	555	0.3747	0.0017	0.1869	0-0525	0-1349	5 299•
0.9	4 (0.0242	-0.145	9 -0.0	532			0.1829			
0.4	3 -0	0.0082	0.075	2 -0.0	546	0.3683	0.0016	0.1849	0.0520	0.1330	299.
-0.0	8 -0	.0370	0.261	1 -0.0	546	0.3717	0.0013	0.1855	0.0517	0.133	7 299.
-0.5	9 -0	0.0652	0.446	7 -0.0	535	0.3573	0.0003	0-1830	0.0515	0.1314	4 299.
~1.0	9 -0	0.0968	0.658	0.0	520	0.3433	-0.0007	0.1878	0.0515	0.1364	4 299.
-1.6	0 -0	1277	0.863	0.0	509	0.3331	0.0015	0.1869	0.0515	0.1353	3 299.
-2.1	2 -0	1552	1.036	7 -0.0	500	0.3241	0.0018	0.1800	0.0517	0.1283	3 299.
-3.1	2 -0	2204	1.494	5 -0.0	461	0.2895	0.0011	0.1896	0.0520	0-1376	5 299.
-4.1	2 -0	2869	1.959	0.0	414	0.2470	0.0022	0.1933	0.0525	0.1409	9 299.
		. 946.2		FIG.	•0000		4CH 4.5		PHI =	75 .	
		. 946.2 .77 PS]			.0000 .48E0		90. D	EG.F	POJ/P	TS =	•
Q	= 3.	.77 PS		R IN.=				EG.F		TS =	•
Q	= 3. 0= 4	.77 PS	RE PE	R IN.=	.48E0			EG.F	POJ/P	TS =	• RUN
Q	= 3. 0= 4 A	.77 PS]	RE PE	R IN.= = .26 C	.48E0 59 PSI S	6 TO=	90. D	EG.F RUN NO.	POJ/P 011030 CPB	TS = 69122 CAF	RUN
Q P ALPH	= 3. 0= 4 A 0 0	.77 PS] 100.0 (RE PEI	R IN.= = .26 C	•48E0	6 TO=	90. DS CR -0.0010	EG.F RUN NO. CAT 0.1595	POJ/P 011030 CPB 0.0527	TS = 69122 CAF	RUN 7 300.
Q P ALPH 4-1	= 3. 0= 4 A 0 0 8 0	.77 PS1 400.0 (CN	RE PEI CMHG PTS CM -1.780	R IN.= = .26 C 0.0	.48E0	6 TO= CY -0.0241-	90. DS CR -0.0010	EG.F RUN NO. CAT 0.1595 0.1567	POJ/P 011030 CPB 0.0527 0.0527	TS = 69122 CAF 0.1067	RUN 7 300. 9 300.
Q P ALPH 4-1 3-0	= 3.0 0= 4 A 0 0 8 0 7 0	.77 PS) .00.0 (CN).2595	CMHG PTS: CM -1.780 -1.286	R IN.= = .26 C 0.0 0.0 0.0 0.0	.48E0	CY -0.0241-	90. D: CR -0.0010 -0.0019 -0.0035	EG.F RUN NO. CAT 0.1595 0.1567 0.1569	POJ/P 011036 CPB 0.0527 0.0527 0.0523	TS = 69122 CAF 0.1067 0.1039 0.1046	RUN 7 300. 9 300. 5 300.
P ALPH 4.1 3.9 2.0	= 3. 0= 4 A 0 0 8 0 7 0 5 0	.77 PS) .00.0 (CN).2595).1907	CM PTS: CM -1.780' -1.2860.843'	R IN.= = .26 C 0.0 0.0 0.0 0.0 0.0	.48E0	CY -0.0241- -0.0272- -0.0480-	90. D: CR -0.0010 -0.0019 -0.0035 -0.0015	EG.F RUN NO. CAT 0.1595 0.1567 0.1569 0.1585	POJ/P . 011036 CPB 0.0527 0.0527 0.0523 0.0519	TS = 69122 CAF 0.1067 0.1039 0.1046 0.1067	RUN 7 300. 9 300. 5 300. 7 300.
P ALPH 4.1 3.9 2.0 1.5	= 3.4 0= 4 A 0 0 8 0 7 0 5 0 4 0	.77 PS) .00.0 (CN 0.2595 0.1907 0.1262	CMHG PTS CM -1.780 -1.286 -0.843 -0.586	R IN.= 26 C - 0.0 - 0.0 - 0.0 - 0.0 - 0.0 - 0.0	.48E0	CY -0.02410.02720.0480-	90. DECR -0.0010 -0.0019 -0.0015 -0.0019	CAT 0.1595 0.1567 0.1569 0.1585 0.1587	POJ/P . 011030 CPB 0.0527 0.0527 0.0523 0.0519 0.0516	TS = 69122 CAF 0.1067 0.1039 0.1046 0.1067	RUN 7 300. 9 300. 5 300. 7 300.
P ALPH 4.1 3.9 2.0 1.5 1.0 0.5	= 3. 0= 4 A 0 0 8 0 7 0 5 0 4 0 2 0	CN 0.2595 0.1907 0.1262 0.0894 0.0621 0.0310 0.0007	CM -1.780 -1.286 -0.843 -0.586 -0.413 -0.206 -0.002	R IN.= = .26 C 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	-48E0	CY -0.02410.02720.05870.05240.0524-	90. D: CR -0.0010 -0.0019 -0.0015 -0.0019 -0.0011 -0.0009	CAT 0.1595 0.1569 0.1569 0.1585 0.1587 0.1589	POJ/P . 011030 . CPB . 0.0527 0.0527 0.0523 0.0519 0.0516 0.0515 0.0514	TS = 69122 CAF 0.1067 0.1040 0.1067 0.1070	RUN 7 300. 9 300. 5 300. 7 300. 6 300. 6 300.
P ALPH 4.1 3.9 2.0 1.5 1.0 0.5 0.0	= 3. 0= 4 A 0 0 8 0 7 0 5 0 4 0 2 0 8 0	CN 0.2595 0.1907 0.1262 0.0621 0.0310 0.0007	CM -1.780 -1.286 -0.843 -0.546 -0.413 -0.206 -0.002 0.176	R IN.= = .26 C 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	-48E0	CY -0.02410.02720.05870.05240.05240.0524-	90. D: CR -0.0010 -0.0019 -0.0015 -0.0019 -0.0019 -0.0019	CAT 0.1595 0.1569 0.1569 0.1587 0.1589 0.1587 0.1589	POJ/P . 01103 . CPB 0.0527 0.0527 0.0523 0.0519 0.0516 0.0515 0.0514	TS = 69122 CAF 0.1067 0.1067 0.1070 0.1070 0.1070	RUN 7 300. 9 300. 9 300. 1 300. 1 300. 1 300. 2 300.
4.1 3.9 2.0 1.5 1.0 0.5 0.0	= 3 c 0 = 4 A 0 0 8 0 7 0 6 7 0 6 6 7 0 6 7 0 7 0 7 0 7 0 7 0 7 0 7 0 7 0 7 0 7 0	CN CN 0.2595 0.1907 0.1262 0.0894 0.0621 0.0310 0.007 0.0270	CM -1.780 -1.286 -0.843 -0.586 -0.413 -0.206 -0.002 0.176 0.377	2 IN.= = .26 C 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	-48E0	CY -0.02410.02720.04800.05840.05240.05240.0524-	90. D: CR -0.0010 -0.0019 -0.0015 -0.0011 -0.0009 -0.0064 -0.0031	CAT 0.1595 0.1569 0.1569 0.1587 0.1589 0.1574 0.1575 0.1591	POJ/P . 01103 CPB 0.0527 0.0523 0.0516 0.0516 0.0515 0.0514 0.0513	TS = 69122 CAF 0.1067 0.1076 0.1076 0.1076 0.1076 0.1076	RUN 7 300. 9 300. 9 300. 1 300. 1 300. 1 300. 2 300. 3 300.
4.1 3.9 2.0 1.5 1.0 0.5 0.0	= 3 < 0 = 4	CN 0.2595 0.1907 0.1262 0.0894 0.0621 0.0310 0.0007 0.0270 0.0574	CM -1.780 -1.286 -0.843 -0.586 -0.413 -0.206 -0.002 0.176 0.377	2 IN.= = .26 C 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	-48E0	CY -0.02410.02720.04800.05870.05240.05240.07050.0792-	90. D: CR -0.0010 -0.0019 -0.0015 -0.0011 -0.0009 -0.0064 -0.0031	CAT 0.1595 0.1567 0.1569 0.1589 0.1574 0.1575 0.1591 0.1578	POJ/P . 01103 . CPB 0.0527 0.0527 0.0523 0.0519 0.0515 0.0514 0.0513 0.0514	TS = 69122 CAF 0.1067 0.1039 0.1046 0.1070 0.1074 0.1061 0.1062 0.1078	RUN 7 300. 9 300. 5 300. 6 300. 7 300. 6 300. 6 300. 2 300. 8 300.
P ALPH 4.1 3.9 2.0 1.5 1.0 0.5 0.0 -0.4 -0.9 -1.5	= 3. 0 = 4 A 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	CN CN 0.2595 0.1907 0.1262 0.0894 0.0621 0.0007 0.0270 0.0574 0.0888 0.1196	CM -1.780 -1.286 -0.843 -0.586 -0.413 -0.002 0.176 0.377 0.589	C IN.= 26 C .0.0 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00 - 0.00	-48E0 59 PSI S 006 011 033 042 041 021 057 071 079 074	CY -0.02410.02720.04800.05240.05240.06060.0705-	90. 09 CR -0.0010 -0.0019 -0.0015 -0.0019 -0.0006 -0.00064 -0.0031 -0.0023 -0.0008	CAT 0.1595 0.1567 0.1569 0.1587 0.1589 0.1574 0.1575 0.1578 0.1578	POJ/P O11036 CPB 0.0527 0.0527 0.0523 0.0519 0.0516 0.0515 0.0514 0.0514 0.0514	TS = 69122 CAF 0.1067 0.1076 0.1076 0.1076 0.1076 0.1076 0.1076 0.1076	RUN 7 300. 9 300. 9 300. 9 300. 1 300. 1 300. 2 300. 9 300. 9 300.
P ALPH 4-1 3-9 2-0 1-5 1-0 0-5 0-0-4 -0-9 -1-5 -2-0	= 3. 0 = 4 A 0 0 0 088 0 0 0 0 0 0 0 0 0 0 0	CN 0.2595 0.1907 0.1262 0.0894 0.0621 0.0310 0.0007 0.0270 0.0574	CM -1.780 -1.286 -0.843 -0.586 -0.413 -0.206 -0.002 0.176 0.377	C C C C C C C C C C C C C C C C C C C	-48E0 59 PSI S 006 011 033 042 041 021 057 071 079 074	CY -0.02410.02720.04800.05870.05240.05240.07050.0792-	90. 09 CR -0.0010 -0.0019 -0.0015 -0.0019 -0.0004 -0.0031 -0.0023 -0.0008 -0.0008	CAT 0.1595 0.1567 0.1569 0.1587 0.1589 0.1574 0.1579 0.1578 0.1578 0.1578 0.1578	POJ/P O1103 CPB 0.0527 0.0527 0.0523 0.0519 0.0516 0.0515 0.0514 0.0513 0.0514 0.0515 0.0517	TS = 69122 CAF 0.1067 0.1070 0.1070 0.1070 0.1070 0.1070 0.1070 0.1070 0.1070	RUN 7 300. 9 300. 9 300. 9 300. 1 300. 1 300. 2 300. 9 300. 9 300. 9 300.

MODEL 946.2	CONF	ig000	00 HA	CH 4.50	PHI =	75.	
0= 3.77 PS1	RE PER	IN.= .48E	=01 40°	90. DEG.F	POJ/P	TS =	10.
PO= 400.0 C	HHG PTS=	.2659 ps	13	RUN	NO. 01103	69123	
ALPHA CN	CH	cs	CY	CR CAT	CPB	CAF	RUN
4.10 0.2597	-1.7899	-0.0040	-0.0014-	0.0015 0.15	98 0.0530	0.1067	301.
3.08 0.1916	-1.3038	-0.0008	-0.0315-	0.0037 0.15	84 0.0531	0.1053	301.
2.07 0.1253		0.0005		0.0022 0.15			
1.55 0.0900	-0.6004			0.0052 0.16			
1.05 0.0612	-0.4121			0.0050 0.15			
0.53 0.0308	-0.2098			0.0023 0.16			
0.03 0.0001	-0.0021	0.0013		0.0021 0.16			
-0.48 -0.0275	0.1754			0.0032 0.15			
-0.99 -0.0568	0.3656			0.0024 0.16			
-1.50 -0.0872	0.5662	0.0053		0.0016 0.16			
-2.00 -0.1179	0.7720			0.0014 0.16			
-3.01 -0.1800	1.2000	0.0064		0.0002 0.16			
-4.02 -0.2526	1.7261	0.0136	-0.1434-	0.0002 0.16	73 0.0524	0.1147	301.
MODEL 946.2 Q= 3.77 PS1	CONF RE PER	IG000		CH 4.50 90. DEG.F	PHI =		20.
_	RE PER		E06 T0=	90. DEG.F	_	TS =	20 .
Q= 3.77 FS1	RE PER	IN.= .486	E06 T0=	90. DEG.F	PO J /P	TS =	20 . RUN
Q= 3.77 PS1 PO= 400.0 C ALPHA CN	RE PER MHG PTS=	IN.= .486 .2659 PS	CY CY	90. DEG.F RUN CR CAT	POJ/P NO. 01103 CPB	TS = 69124 CAF	RUN
Q= 3.77 PS1 PO= 400.0 C ALPHA CN 4.10 0.2624	RE PER MHG PTS= CM -1.8216	IN.= .488 .2659 PS CS -0.0078	E06 T0= SI CY 0.0092-	90. DEG.F RUN CR CAT	POJ/P NO. 01103 CPB	TS = 69124 CAF 0.1088	RUN 302.
Q= 3.77 PS1 PO= 400.0 C ALPHA CN	RE PER MHG PTS=	IN.= .488 .2659 PS CS -0.0078 -0.0070	CY 0.0092~ 0.006-	90. DEG.F RUN CR CAT	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530	TS = 69124 CAF 0.1088 0.1072	RUN 302. 302.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270	RE PER MHG PTS= CM -1.8216 -1.3123	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075	CY 0.0092- 0.0066- 0.0146-	90. DEG.F RUN CR CAT 0.0014 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526	TS = 69124 CAF 0.1088 0.1072 0.1093	RUN 302. 302. 302.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072	CY 0.0092- 0.0066- 0.0146- 0.0142-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084	RUN 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052	CY 0.0092- 0.0066- 0.0146- 0.01420.0036-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1088	RUN 302. 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0042	CY 0.0092- 0.0066- 0.0146- 0.01420.00360.0054-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16 0.0055 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 23 0.0517	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1088 0.1105	RUN 302. 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625 0.53 0.0314	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289 -0.2178 -0.0190	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0042	CY 0.0092~ 0.0066- 0.0146- 0.01420.00360.0054-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16 0.0055 0.16 0.0022 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 23 0.0517 53 0.0516	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1088 0.1105 0.1137	RUN 302. 302. 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625 0.53 0.0314 0.02 0.0014 -0.49 -0.0270 -0.99 -0.0559	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289 -0.2178 -0.0190 0.1659 0.3539	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0042 -0.0022 -0.0035 -0.0002	CY 0.0092- 0.0066- 0.01460.00360.00540.02670.0118-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16 0.0055 0.16 0.0022 0.16 0.0021 0.16 0.0037 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 23 0.0517 53 0.0516 26 0.0516	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1084 0.1105 0.1137 0.1110	RUN 302. 302. 302. 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625 0.53 0.0314 0.02 0.0014 -0.49 -0.0270 -0.99 -0.0559 -1.50 -0.0870	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289 -0.2178 -0.0190 0.1659 0.3539 0.5621	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0042 -0.0022 -0.0035 -0.0002 -0.0023	CY 0.0092- 0.0066- 0.0146- 0.01420.00540.02670.01180.03970.0189-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16 0.0055 0.16 0.0022 0.16 0.0021 0.16 0.0037 0.16 0.0010 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 03 0.0517 53 0.0516 26 0.0516 56 0.0516	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1086 0.1105 0.1137 0.1110 0.1140	RUN 302. 302. 302. 302. 302. 302. 302. 302.
Q= 3.77 FS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625 0.53 0.0314 0.02 0.0014 -0.49 -0.0270 -0.99 -0.0559 -1.50 -0.0870 -2.00 -0.1192	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289 -0.2178 -0.0190 0.1659 0.3539 0.5621 0.7841	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0022 -0.0025 -0.0023 0.0004	CY 0.0092- 0.0066- 0.0146- 0.01420.00540.02670.01890.0443-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0055 0.16 0.0022 0.16 0.0021 0.16 0.0037 0.16 0.0015 0.16 0.0010 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 23 0.0517 53 0.0516 26 0.0516 26 0.0516 27 0.0516 43 0.0517	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1085 0.1137 0.1137 0.1140 0.1141	RUN 302. 302. 302. 302. 302. 302. 302. 302.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.10 0.2624 3.08 0.1921 2.07 0.1270 1.55 0.0924 1.04 0.0625 0.53 0.0314 0.02 0.0014 -0.49 -0.0270 -0.99 -0.0559 -1.50 -0.0870	RE PER MHG PTS= CM -1.8216 -1.3123 -0.8582 -0.6256 -0.4289 -0.2178 -0.0190 0.1659 0.3539 0.5621	IN.= .488 .2659 PS CS -0.0078 -0.0070 -0.0075 -0.0072 -0.0052 -0.0022 -0.0025 -0.0023 0.0004	CY 0.0092- 0.0066- 0.0146- 0.01420.00540.02670.01180.01890.0443-	90. DEG.F RUN CR CAT 0.0014 0.16 0.0024 0.16 0.0033 0.16 0.0019 0.16 0.0055 0.16 0.0022 0.16 0.0021 0.16 0.0037 0.16 0.0010 0.16	POJ/P NO. 01103 CPB 16 0.0527 02 0.0530 19 0.0526 06 0.0523 08 0.0520 23 0.0517 53 0.0516 56 0.0516 57 0.0516 43 0.0517 89 0.0520	TS = 69124 CAF 0.1088 0.1072 0.1093 0.1084 0.1088 0.1105 0.1137 0.1140 0.1141 0.1126	RUN 302. 302. 302. 302. 302. 302. 302. 302.

н	DEL 946.2	CONF	160900	MACH ÷	.50	PHI =	75.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6- TQ= 90.	DEG.F	POJSPT	S = 40.	
PC)= 400.0 CM	HG PTS=	.2659 PSI		RUN NO	. 011036	9125	
ALPHA	A CN	СН	cs	CY CR	CAT	СРВ	CAF	RUN
4.09		-1.8041		0.0731 0.00				303.
3.08		-1.2898		0.1086 0.00				303.
2.07		-0.7966		0.1511-0.00				303.
1.55		-0.5864		0.0611-0.00				303.
1.03		-0.4158		0.0639 0.00				303.
0.52		-0.2034		0.0682 0.00				303.
	2 -0.0015	-0.0000		0.0366-0.00				303.
	0.0300 0.0596		-0.0133 -0.0128	0.0486 0.00				303. 303.
	0.0396		-0.0128	0.0290 0.00				303.
	-0.1233		-0.0106	0.0259 0.00				303.
	-0.1836		-0.0079	0.0007 0.00				303.
	2 -0.2566			-0.0809 0.00				303.
MC	DEL 946.2	CONF	1G0000	MACH 4	•50	PHI =	75.	
Q=	= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/PT	S = 100.	
PC)= 400.0 CM	HG PTS=	.2659 PSI		RUN NO	. 011036	9126	
ALPHA	A CN	CM	CS	CY CR	CAT	CPB	CAF	RUN
4.09	0.2488	-1.7267	-0.0540	0.3335 0.00	01 0.1814	0.0528	0.1286	304.
3.08		-1.2218		0.3356-0.00				304.
2.06	0.1129	-0.7579	-0.0551	0.3534-0.00				304.
1.54	0.0773	-0,5137	-0.0530	0.3405-0.00	17 0-1789	0.0525	0.1265	304.
1.03	0.0466	-0.3053	-0.0508	0.3198-0.00	03 0.1805	0.0522	0.1282	304.
0.53		-0.1058		0.3137-0.00				304.
	2 -0.0133		-0.0496	0.3122 0.00				304.
	0.0433		-0.0476	0.2914-0.00				304.
	0.0744		-0.0497	0.3117-0.00				304.
	-0.1052		-0.0474	0.2883-0.00				304.
	-0.1359		-0.0451	0.2704 0.00				304.
	-0.1969		-0.0423	0.2443 0.00				304.
-4.02	2 -0.2703	1.8261	-0.0347	0.1782 0.00	26 O•1885	0.0527	U•1358	304.

MODEL 946-2	CONFIG	0000	· MACH	4.50	PHI =	90.	
Q= 3.77 PS1	RE PER IN	48 £05	70= 9	O. DEG.F	279/169		
PO= 400.0 C	MHG PTS= .:	2659 PSI		RUN NO	0170366	7526	
ACPHA CN	CH	CS	CY	CR CAT	CPS	CAF	RUN
4.07 0.2582	-1.7713 -0	.0051 0	.0356-0,	2017 0.1686	0.0524	0.1162	305.
3.06 0.1904	-1.2860 -0.	.0050 0	.0340-0.	0021 0.1665	0.0526). <u>1139</u>	305.
2.05 0.1249	-0.8326 -0.	.0049 0	.032600.	0019 0.1659	0.0522		305.
1.52 0.0869	-0.5666 -0.			0013 0.1717			305.
1.01 0.0600	-0.3984 -0.			0012 0.1670			305.
0.51 0.0291	-0.1911 -0.			0011 0.1668			305.
-0. 0.0014	-0.0113 -0.			0003 0.1710			305.
-0.51 -0.0295	0.1959 -0.			0008 0-1649			305.
~1.01 -0.0596	0.3932 -0.			0014 0,1661			305.
-1.52 -0.0881	0.5777 -0.		-0114 0.		0.0514		305.
-2.03 -0.1197	0.7902 -0.			0037 0.1687			305.
-3.03 -0.1829	1.2289 -0.			0047 0.1695			305.
-4.04 -0.2538	1.7393 0.	.0005 -0	-0123-0-	0015 0.1761	0.0523 0	1.1239	305.
						_	
MODEL 946.2 Q= 3.77 PSI	CONFIG.			4.50 0. DEG.F	± 1H9	90. = 10.	
	RE PER IN			O. DEG.F		i = 10.	
Q= 3.77 PSI	RE PER IN	48E06	10 ≖ 9	O. DEG.F	279/609	10. 9128	RUN
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER IN.	= .48E06 2659 PSI CS	T0= 90	O. DEG.F RUN NO CR CAT	POJ/PTS . 0110369 CPB	5 = 10. P128 CAF	-
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER IN. MHG PTS= .2 CH	.= .48E06 2659 PSI CS	T0= 9(CY (O. DEG.F RUN NO	POJ/PTS . 0110369 . CPB . 0.0531 0	5 = 10. P128 CAF 0.1099	RUN 306.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.07 0.2572	RE PER IN. MHG PTS= .2 CM -1.7651 -0.	-= .48E06 2659 PSI CS .0080 0	TO= 9(CY (.0370-0.1	O. DEG.F RUN NO. CR CAT 0022 0.1630	POJ/PTS . 0110369 . CPB 0.0531 0	6 = 10. P128 CAF 0.1099	306.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868	RE PER IN. MHG PTS= .2 CM -1.7651 -0. -1.2861 -0.	48E06 2659 PSI CS .0080 0 .0094 0	TO= 9(CY (.0370-0.1 .0536-0.1 .0413-0.1	O. DEG.F RUN NO. CR CAT 0022 0.1630 0027 0.1653	POJ/PTS O110369 CPB 0.0531 0 0.0530 0 0.0526 0	10. 0128 CAF 0.1099 0.1123	306. 306.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247	RE PER IN. HHG PTS= .2 CH -1.7651 -0. -1.2861 -0. -0.8326 -0.	48E06 2659 PSI CS .0080 0 .0094 0 .0079 0	TO= 96 CY (*.0370-0.6* .0536-0.6* .0413-0.6* .0399-0.6*	O. DEG.F RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647	POJ/PTS O110369 CPB 0.0531 0 0.0530 0 0.0526 0 0.0520 0	0 = 10. 0128 CAF 0.1099 0.1123 0.1121	306. 306. 306.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868	RE PER IN. HHG PTS= .2 CM -1.7651 -0. -1.2861 -0. -0.8326 -0. -0.5644 -0.	48E06 2659 PSI CS .0080 0 .0094 0 .0079 0	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6	O. DEG.F RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645	POJ/PTS O110369 CPB 0.0531 0 0.0530 0 0.0526 0 0.0520 0 0.0518 0	0.10. 0.128 CAF 0.1099 0.1123 0.1121 0.1124	306. 306. 306.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598	RE PER IN. HHG PTS= .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -0.	48E06 2659 PSI CS .0080 0 .0094 0 .0079 0 .0078 0 .0076 0 .0046 0	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0407-0.6 .0103-0.6 .0072-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645 0018 0.1672 0010 0.1655	POJ/PTS O110369 CPB 0.0531 9 0.0530 0 0.0526 0 0.0520 0 0.0518 0 0.0517 0 0.0516 0	CAF 0.1099 0.1123 0.1121 0.1124 0.1154 0.1138	306. 306. 306. 306. 306. 306.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598 0.51 0.0290	RE PER IN. HHG PTS= .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -00.1907 -0.	48E06 48E06 	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0407-0.6 .0103-0.6 .0072-0.6 .0078-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1645 0019 0.1645 0018 0.1672 0010 0.1655 0021 0.1653 0014 0.1680	POJ/PTS O110369 CPB 0.0531 9 0.0530 0 0.0520 0 0.0520 0 0.0518 0 0.0517 0 0.0516 0	CAF 0.1099 0.1123 0.1121 0.1124 0.1154 0.1138 0.1137	306. 306. 306. 306. 306.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598 0.51 0.0290 -00.0004	RE PER IN. HHG PTS= .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -00.1907 -0. 0.0031 -0.	48E06 2659 PSI CS .0080	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0407-0.6 .0103-0.6 .0072-0.6 .0078-0.6 .0210-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645 0018 0.1672 0010 0.1653 0021 0.1653 0014 0.1680 0019 0.1663	POJ/PTS O110369 CPB 0.0531 9 0.0536 0 0.0526 0 0.0517 0 0.0516 0 0.0516 0 0.0515 0	CAF 0.1099 0.1123 0.1121 0.1124 0.1154 0.1138 0.1137 0.1165	306. 306. 306. 306. 306. 306. 306.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598 0.51 0.0290 -00.0004 -0.51 -0.0312 -1.01 -0.0590 -1.51 -0.0883	RE PER IN. HHG PTS= .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -00.1907 -0. 0.0031 -0. 0.2093 -0. 0.3885 -0. 0.5812 -0.	48E06 48E06 	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0407-0.6 .0103-0.6 .0072-0.6 .0210-0.6 .0201-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645 0010 0.1655 0021 0.1653 0014 0.1680 0019 0.1663	POJ/PTS O110369 CPB 0.0531 0 0.0526 0 0.0526 0 0.0517 0 0.0516 0 0.0516 0 0.0516 0	CAF 1.1099 1.1123 1.1124 1.1124 1.1138 1.1137 1.1165 1.1148	306. 306. 306. 306. 306. 306. 306.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598 0.51 0.0290 -00.0004 -0.51 -0.0312 -1.01 -0.0590 -1.51 -0.0883 -2.03 -0.1199	RE PER IN. THIS PTS = .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -00.1907 -0. 0.0031 -0. 0.2093 -0. 0.3885 -0. 0.5812 -0. 0.7920 -0.	48E06 2659 PSI CS .0080 0 .0094 0 .0079 0 .0078 0 .0076 0 .0046 0 .0046 0 .0046 0 .0046 0	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0407-0.6 .0072-0.6 .0078-0.6 .0210-0.6 .0237-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645 0018 0.1672 0010 0.1653 0021 0.1653 0014 0.1680 0019 0.1661	POJ/PTS O110369 CPB 0.0531 9 0.0530 0 0.0526 0 0.0526 0 0.0517 0 0.0516 0 0.0516 0 0.0517 0	CAF 1.1099 1.1123 1.1124 1.1154 1.1137 1.1165 1.1148 1.1145	306. 306. 306. 306. 306. 306. 306. 306.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.07 0.2572 3.06 0.1902 2.05 0.1247 1.53 0.0868 1.02 0.0598 0.51 0.0290 -00.0004 -0.51 -0.0312 -1.01 -0.0590 -1.51 -0.0883	RE PER IN. HHG PTS= .2 CH -1.7651 -01.2861 -00.8326 -00.5644 -00.3967 -00.1907 -0. 0.0031 -0. 0.2093 -0. 0.3885 -0. 0.5812 -0.	48E06 48E06 659 PSI CS 0080 0 0094 0 0079 0 0078 0 0076 0 0046 0 0046 0 0046 0 0046 0 0046 0 0056 0 0056 0 0056 0	TO= 96 CY .0370-0.6 .0536-0.6 .0413-0.6 .0399-0.6 .0103-0.6 .0072-0.6 .0210-0.6 .0210-0.6 .0337-0.6 .0171-0.6	RUN NO. CR CAT 0022 0.1630 0027 0.1653 0025 0.1647 0019 0.1645 0010 0.1655 0021 0.1653 0014 0.1680 0019 0.1663	POJ/PTS O110369 CPB 0.0531 0 0.0526 0 0.0526 0 0.0517 0 0.0516 0 0.0516 0 0.0517 0 0.0516 0 0.0517 0	CAF 1.1099 1.1123 1.1124 1.1154 1.1137 1.1165 1.1148 1.1145 1.1172	306. 306. 306. 306. 306. 306. 306.

H	DDEL 946.2	CONF	IG0000	н	CH 4.50)	PHI =	90.	
Q	= 3.77 PSI	RE PER	IN.= .48E0	=0 1	90. DE	ÉG.F	P0J/P	rs = 20).
P	0= 400.0 CM	HS PTS=	.2659 PSI			RUN NO	01103	69129	
ALPH	A CN	СИ	cs	CY	CR	CAT	CPB	CAF	RUN
4.0	7 0.2609	-1.7963	-0-0139	0.0721-	0.0021	0-1618	0.0532	0.1086	307.
3.0		-1.2974		0.0624-					307.
2.0	5 0.1268	-0.8475	-0.0123	0.0611-	0.0012	0.1635	0.0528	0-1108	307.
1.5		-0.5675	-0.0122	0.0628-	0.0018	0.1633	0.0523	0.1110	307.
1.0	1 0.0620	-0.4144	-0.0121	0.0617-	0.0017	0.1676	0.0521	0.1155	307•
0.5	1 0.0304	-0.2019	-0.0105	0.0485-					307.
-0.	0.0018	-0.0146	-0.0118	0.0584-					307.
-0.5	0 -0.0282	0.1852	-0.0103	0.0463-					307.
-1.0	1 -0.0576		-0.0101	0.0440-					307.
-1.5	2 -0.0884	0.5816	-0.0101	0.0438-					307.
-2.0	3 -0.1185	.0.7807	-0.0100	0.0424-					307.
	3 -0.1817		-0.0084	0.0257-					307.
-4.0	4 -0.2557	. 1.7594	-0.0056	0.0028-	0.0020	0.1766	0.0526	0-1240	307.
М	ODEL 946.2	CONF	·1G0000	MA	ICH 4.50)	PH1 =	90.	
Q	= 3.77 PSI	RE PER	IN.= .48E0	5 TO=	90. DE	G.F	P0J/P	rs ≈ 40	
P	0= 400.0 CM	HG PTS=	.2659 PSI		•	RUN NO.	01103	59130	
ALPH	A CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.0	7 0.2605	-1.7962	-0-0149	0.0892-	0.0001	0-1726	0.0530	0.1197	308.
3.0	-	-1.3023		0.1311-					308.
2.0		-0.8388		0.1328-	0.0011	0.1671	0.0529	0-1142	308.
1.5		-0.5955		0.1379	0.0008	0.1698	0.0524	0.1174	308.
1.0		-0.3877	-0.0237	0.1356	0.0016	0.1681	0.0522	0.1159	308.
0.5		-0.1903		0.1497					308.
-0.	-0.0009		-0.0192	0.0929					308.
	0 -0.0286		-0.0205	0.1059	0.0013	0.1703	0.0516	0.1187	308.
	1 -0.0610	0.4076	-0.0233	0.1340	0.0007	0.1716	0.0517	0.1199	308.
-1.5	2 -0.0911	0.6084	-0.0232	0.1327-	0.0004	0.1729	0.0518	0.1211	308.
-2.0	3 -0-1197	0.7924	-0.0202	0.1020-					308.
-3.0	3 -0.1821	1.2230	-0.0187	0.0866	0.0006	0.1764	0.0521	0.1243	308.
-4.0	4 -0.2545	1.7482	-0.0158	0.0626-	0.0006	0.1786	0.0528	0.1258	308.

i	ופנוא	EL 946.2	CONI	FIG000	AH C	CH 4.50	0	PHI =	90.	
4	Q= :	3.77 PS1	RE PER	IN 48E	06 TO=	90. DE	EG.F	POJ/P1	rs = 100	•
	P0=	400.0 CH	HG PTS=	-2659 PS	ī		RUN NO	01103	69131	
ALP	HA	CN	CM	CS	CY	CR	CAT	CP8	CAF	RUN
4.		0.2604		-0.0606			0.1773			309.
3.		0.1919		-0.0620			0.1780			309.
2.		0.1248		-0.0619					0.1248	309.
l.		0.0877		-0.0618			0.1787			309.
	C2	0.0584		-0.0646			0.1771			309.
0.		0.0283		-0.0644	0.4385-				0.1264	309•
Q.		-0.0026	0.0243	-0.0615			0.1810			309.
		-0.0318		-0.0628			0.1808			309.
		-0.0635		-0.0627			0.1821			309.
		-0.0920		-0.0611			0.1832			309.
-2.	03	-0.1236	0.8298	-0.0611	0.4039-	-0.0014	0.1904	0.0522	9.1383	309.
-3.	03 ·	-0.1876	1.2767	-0.0553			0.1897			309.
-4,	Ú4 ·	-0.2593	1.7933	-0.0524	0.3209-	-0.0011	0.1905	0.0529	0.1375	309.
i	HODI	EL 946.2	CONI	FIG. 3.00) на	ICH 3.00		PHI =	•	
	Q=	6.37 PSI	RE PER	IN.= .48E	06 TO=	90. DI	EG.F	P01/P	TS =	•
-	P0=	193.0 CM	HG PTS=	1.0109 PS	ſ		RUN NO	01203	59102	
ALP	HA	CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.	03	0.4736	-4.3132	-0.0131	0-1347-	-0.0011	0.3138	0.1075	0.2063	310.
3.		0.3502		-0.0176			0.3126			310.
2.		0,2284		-0.0124			0.3087			310.
1.		0.1603		-0.0114			0.3096			310.
0.		0.1049		-0.0109			0.3085			310.
0.	_	0.0521		-0.0141			0.3090			310.
		-0.0032		-0.0136			0.3052			310.
-		-0.0560		-0.0140			0.3049			310.
		-0.1190		-0.0131			0.3056			310.
		-0.1812		-0.0121			0.3055			310.
	-	-0.2289	-	-0.0121			0.3050			310.
		-0.3490		-0.0115		-	0.3054			310.
		-0.4759		-0.0068			0.3078			310.

M	DDEL 9	46.2	CONI	IG.	3.000		ĤACI	3.0	0	PHI =	•		
Q:	6.37	PSI R	E PER	IN.=	-48E06	.	(3 = S	9Ö. D	ÉG.F	P0 J/ P	TS =	.01	
PI)= 193	.O CHHG	PTS=	1.016	129 PSI				RUN NO	- G2203	69103		
ALPH	4 C	N	CM	C:	5	CY		CŘ	CAT	СРВ	CAF		RUN
4.0			-2677							0-1089			311.
3.0			.1568							0.1082			311.
1.99			•0629							0.1071			311.
1.4			•4299							0.1962			311.
9.9	–		•9726							0.1054			311.
	0.0		.3944							0.1044			311.
	5 -0.0		.0775							0.1033			311.
	7 -0.0		.5193							0.1023			311.
	3 -C.1		•0335							.0.1020			311.
	3 -0.1	-	.6076					_		0.1020			311.
	-0.2		•0664	_						0.1021			311.
	-0.3		-1467							0.1027			311.
-4-17	2 -0.4	779 4	•3074	-0.00	960	0.034	₹2~O.	0015	0.3151	0.1035	0.211	6	311.
	DEL 9			:IG. IN.=	3.000 .48E06	, Tí		3.0		PHI =	TS =	20.	
Q:	= 6.37		E PER	IN.=	•48E06	, Tá			EG•F	-	•	20.	
Q: Pt	= 6.37)= 193	PSI R	E PER	IN.=	•48E06 9 PSI			00. D	EG.F RUN NO	POJ/P	69104	20.	DIIN
Q:	= 6.37)= 193	PSI R	E PER	IN.=	•48E06 9 PSI	CY			EG•F	60 1/ b.	•	20.	RUN
Q: P(ALPH/	= 6.37)= 193 A CI	PSI R .O CMHG	E PER PTS= CM	IN.= 1.010	•48E06 9 PSI	CY	0= 9	0. D	EG.F RUN NO CAT	POJ/P • 012030 CPB	69104 CAF		
Q: Pt	= 6.37 D= 193 A CI	PSI R .0 CMHG N 526 -4	E PER	IN.= 1.010 CS	•48E06 99 PSI	CY 0+15	0= 9	O. D. CR C002	EG.F RUN NO CAT 0.3308	POJ/P • 012030 CPB 0-1090	69104 CAF 0.221	3	312.
Q: P(ALPH/ 4.02	= 6.37 D= 193 A CI 2 0.41 1 0.3	PSI R •0 CMHG N 526 -4 334 -3	E PER PTS= CM •1982	IN.= 1.010 CS -0.01	•48E06	CY 0.150 0.14	0= 9 03 0. 54-0.	CR C002 0003	EG.F RUN NO CAT 0.3308 0.3303	POJ/P • 012030 CPB 0.1090 0.1084	69104 CAF 0.2211	3 O	312. 312.
Q: P(ALPH/ 4.02 3.01	= 6.37 D= 193 A CI 2 0.4: 1 0.3: 0 0.2:	PSI R .0 CMHG N 526 -4 334 -3 143 -2	E PER PTS= CM •1982 •1137	IN.= 1.010 CS -0.01 -0.01	•48E06	CY 0.150 0.149 0.189	0= 9 03 0. 54-0. 52 0.	CR .0002 .0003	EG.F RUN NO CAT 0.3308 0.3303 0.3256	POJ/P • 012030 CPB 0-1090	CAF 0.2210 0.2220 0.2180	8 0 4	312.
Q: P(ALPH/ 4.02 3.01 1.99	= 6.37 D= 193 A CI 2 0.41 1 0.31 0 0.27	PSI R O CMHG N 526 -4 334 -3 143 -2 496 -1	PTS= CM -1982 -1137 -0281	IN.= 1.016 CS -0.01 -0.01 -0.01	.48E06	CY 0.15 0.14 0.18 0.17	03 0. 54-0. 52 0. 24 0.	CR C002 0003 0001	EG.F RUN NO CAT 0.3308 0.3303 0.3256	POJ/P - 012030 CPB 0-1090 0-1084 0-1072	0.221 0.221 0.222 0.218 0.219	8 0 4	312. 312. 312. 312.
Q: P(ALPH/ 4.02 3.01 1.99 1.41	= 6.37 0= 193 A CI 2 0.4! 1 0.3: 0 0.2: 7 0.1: 6 0.0:	PSI R 0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0	PTS= CM .1982 .1137 .0281 .4388	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01	•48E06	CY 0.15 0.14 0.18 0.17	03 0. 54-0. 52 0. 24 0. 02-0.	CR C002 0003 0001 0001	EG.F RUN NO CAT 0.3308 0.3303 0.3256 0.3256	POJ/P . 012030 CPB 0.1090 0.1084 0.1072 0.1062	0.221 0.221 0.222 0.218 0.219 0.219	8 0 4 4	312. 312. 312.
Q: P(ALPH/ 4.02 3.03 1.99 1.47 0.96	= 6.37 0= 193 A CI 2 0.4! 1 0.3: 0 0.2: 7 0.1: 6 0.0:	PSI R 0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0	E PER PTS= CM .1982 .1137 .0281 .4388 .8925	IN.= 1.016 CS -0.01 -0.01 -0.01 -0.01 -0.01	•48E06	CY 0.15 0.14 0.18 0.17 0.16 0.16	03 0. 54-0. 52 0. 24 0. 02-0. 63-0.	CR C002 0003 0001 0001 0003	EG.F RUN NO CAT 0.3308 0.3303 0.3256 0.3256 0.3253 0.3241	POJ/P . 012030 CPB 0.1090 0.1084 0.1072 0.1062 0.1054	69104 CAF 0.221 0.222 0.218 0.219 0.219	3 0 4 4 9	312. 312. 312. 312. 312.
Q: P(ALPH/ 4.02 3.03 1.99 1.47 0.96 0.49	= 6.37 D= 193 A Cl 2 0.44 1 0.33 D 0.22 7 0.16 6 0.06 5 0.00	PSI R 0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0 140 0	E PER PTS= CM .1982 .1137 .0281 .4388 .8925 .3874	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	•48E06	CY 0.15 0.14 0.18 0.16 0.16 0.16	03 0. 54-0. 52 0. 24 0. 02-0. 63-0. 10-0.	CR C002 0003 0001 0001 0003 0011 0004	EG.F RUN NO CAT 0.3308 0.3308 0.3256 0.3256 0.3250 0.3251 0.3211	POJ/P - 012030 CPB 0.1090 0.1084 0.1072 0.1062 0.1054 0.1045 0.1034 0.1025	0.2216 0.2216 0.2226 0.2186 0.2196 0.2196 0.2196 0.2176	3 0 4 4 9 6 6 6	312. 312. 312. 312. 312.
Q: P(ALPH/ 4.02 3.03 1.93 1.94 0.96 0.49 -0.07 -0.56	= 6.37 D= 193 A Cl 2 0.44 1 0.33 D 0.22 7 0.11 6 0.06 5 0.07	PSI R 0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0 140 0 702 0	E PER PTS= CM .1982 .1137 .0281 .4388 .8925 .3874	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	•48E06	CY 0.150 0.149 0.189 0.160 0.160 0.149 0.149	03 0. 54-0. 52 0. 24 0. 22-0. 53-0. 10-0. 70-0.	CR C002 0003 0001 0003 0001 0004 0008	EG.F RUN NO CAT 0.3308 0.3303 0.3256 0.3256 0.3253 0.3241 0.3211 0.3215	POJ/P . 012030 CPB 0.1090 0.1084 0.1072 0.1062 0.1054 0.1045 0.1034 0.1025 0.1019	CAF 0.221 0.222 0.218 0.219 0.219 0.219 0.219 0.219 0.219	8 0 4 4 9 6 6 6	312. 312. 312. 312. 312. 312.
Q: P(ALPH/ 4.04 3.01 1.99 1.4* 0.90 0.4! -0.01 -0.01 -1.09 -1.59	= 6.37 D= 193 A CI 2 0.44 1 0.33 9 0.27 7 0.10 5 0.00 7 -0.00 3 -0.01 9 -0.1	PSI R -0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0 140 0 349 1 860 1	E PER PTS= CM .1982 .1137 .0281 .4388 .4387 .0463 .5569	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	•48E06	CY 0.150 0.149 0.189 0.160 0.160 0.149 0.149	03 0. 54-0. 52 0. 24 0. 22-0. 53-0. 10-0. 70-0.	CR C002 0003 0001 0003 0001 0004 0008	EG.F RUN NO CAT 0.3308 0.3303 0.3256 0.3256 0.3253 0.3241 0.3211 0.3215	POJ/P - 012030 CPB 0.1090 0.1084 0.1072 0.1062 0.1054 0.1045 0.1034 0.1025	CAF 0.221 0.222 0.218 0.219 0.219 0.219 0.219 0.219 0.219	8 0 4 4 9 6 6 6 6 2 5	312. 312. 312. 312. 312. 312. 312. 312.
Q: P6 ALPH/ 4.04 3.03 1.47 0.96 0.49 -0.05 -1.05 -1.05 -2.10	= 6.37 D= 193 A CI 2 0.44 1 0.33 D 0.27 7 0.16 6 0.00 5 0.00 3 -0.01 D -0.10 D -0.10 D -0.10	PSI R -0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0 140 0 349 1 860 1	E PER PTS= CM .1982 .1137 .0281 .4388 .4388 .8925 .3874 .0463 .5569 .1518	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48E06	CY 0.150 0.149 0.160 0.160 0.160 0.140 0.142 0.129 0.139	03 0. 54-0. 524 0. 63-0. 63-0. 70-0. 22-0. 52-0.	CR C002 0003 0001 0001 0003 0011 0004 0008 0008 0005	EG.F RUN NO CAT 0.3308 0.3323 0.3256 0.3253 0.3241 0.3216 0.3216 0.3185 0.3190	POJ/P O12036 CPB O.1090 0.1084 0.1072 0.1062 0.1054 0.1045 0.1034 0.1025 0.1019 0.1017	CAF 0.221: 0.222: 0.218: 0.219: 0.219: 0.219: 0.219: 0.219: 0.217:	8 0 4 4 9 6 6 6 6 6 8 8	312. 312. 312. 312. 312. 312. 312. 312.
Q: P6 ALPH/ 4.03.03 1.49 0.49 -0.07 -0.56 -1.56 -2.10 -3.13	= 6.37 D= 193 A CI 2 0.44 1 0.33 9 0.27 7 0.10 5 0.00 7 -0.00 3 -0.01 9 -0.1	PSI R -0 CMHG N 526 -4 334 -3 143 -2 496 -1 899 -0 346 -0 140 0 349 1 860 1 413 2 597 3	E PER PTS= CM .1982 .1137 .0281 .4388 .8925 .3874 .0463 .5569 .1518	IN.= 1.010 CS -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01 -0.01	.48E06 9 PSI 36 30 80 86 51 .56 .28 .32 .27 .13	CY 0.150 0.149 0.160 0.160 0.160 0.140 0.140 0.140 0.120 0.130	03 0. 54-0. 524 0. 224 0. 63-0. 63-0. 63-0. 52-0.	CR C002 0003 0001 0001 0003 0011 0004 0008 0008 0005 0005	CAT 0.3308 0.3303 0.3256 0.3256 0.3253 0.3241 0.3211 0.3215 0.3185 0.3190 0.3185	POJ/P - 012030 CPB 0.1090 0.1084 0.1072 0.1065 0.1054 0.1045 0.1034 0.1025 0.1019 0.1017	CAF 0.221: 0.222: 0.218: 0.219: 0.219: 0.219: 0.217: 0.217: 0.216:	8 0 4 4 9 6 6 6 6 8 3 3	312. 312. 312. 312. 312. 312. 312. 312.

HODEL 946.2	CONFIG. 3.0	00 HACH 3.00	РНІ∷≟ ъ	
Q= 6.37 PSI	RE PER IN48	E06 Tòa 90. DEG.F	POJ/PTS = 40:	
PO= 193.0 CM	1HG PTS= 1.0109 P	SI RUN A	ID: 0120369105	
ALPHA CŃ	CH CS	CY CR CAT	CPB CAF	หมห
4.01 0.4335	-4-0822 -0-0139	0.1526.0.0003 0.334		313.
3.00 0.3143	-2.9976 -0.0133	0.1467 0.0003 0.333		313.
1.98 0.1969	-1.9293 -0.0160	0.1663 0.0007 0.329		313.
1.46 0.1347	-1.3652 -0.0150	0.1584 0.0006 0.329		313.
0.95 0.0810	-0.8760 -0.0137	0.1464 0.0006 9.325		313.
0.44 0.0248	-0.3636 -0.0132	0.1423 0.0006 0.325		313.
-0.08 -0.0415	0.2474 -0.0117	0-1311 0-6001 0-325		313.
-0.58 -0.0910	0.6921 -0.0108	0.1230-0.0006 0.321	8 0.1022 0.2196	313.
-1.09 -0.1480	1.2108 -0.0103	0.1191-0.0007 0.319	7 0.1014 0.2183	313:
-1.60 -0.2042	1.7233 -0.0117	0.1304-0.0007 0.321	2 0.1012 0.2200	313.
-2.10 -0.2570	2.1975 -0.0112	0.1264 0.0001.0.322	6 0.1012 0.2214	313.
-3.12 -0.3779	3.3067 -0.0098	0.1124-0.9006 0.321	2 0.1020 0.2192	313.
-4.14 -0.5031	4.4520 -0.0032-	0.0536-0.0002 0.321	7 0.1027 0.2190	313.
MODEL 946.2		~	PHI = .	
Q= 6.37 P\$I	RE PER IN.= .48	E06 T0≥ 90. DEG.F	POJ/PTS = 100.	
PO= 193.0 CM	IHG PTS= 1.0109 P	SÎ RUN N	0120369106	
ALPHA CN	CH ES	CY CR CAT	CPB CAF	RUN
3.98 0.3730	-3.6810 -0.0168	0.1746 0.0008 0.340	0 0-1085 0-2315	314.
2.97 0.2573	-2.6280 -0.0140	0.1505 0.0004 0.329	0 0-1079 0-2211	314.
1.96 0.1380	-1.5423 -0.0102	0.1161 0.0007 0.330		314.
1.43 0.0699	-0.9167 -0.0110	0.1243 0.0003 0.331		314.
0.91 0.0197	-0.4649 -0.0096	0.1122 0.0014 0.326		314.
0.41 -0.0382	0.9647 -0.0087	0.1043-0.0002 0.323		314.
-0.10 -0.0927	0.5638 -0.0088	0.1034 0.0002 0.323		314.
-0.61 -0.1480				314.
-1.13 -0.2153		0.1015 0.0006 0.219	4 0.1017 0.2177	
	1.0597 -0.0087	0.1015 0.0006 0.319		
	1.0597 -0.0087 1.6865 -0.0082	0.0974-0.0003 0.320	1 0.1012 0.2190	314.
-1.64 -0.2673	1.0597 -0.0087 1.6865 -0.0082 2.1528 -0.0082	0.0974-0.0003 0.320 0.0985-0.0006 0.320	1 0.1012 0.2190 7 0.1006 0.2200	314. 314.
	1.0597 -0.0087 1.6865 -0.0082 2.1528 -0.0082 2.6144 -0.0086	0.0974-0.0003 0.320 0.0985-0.0006 0.320 0.1014 0.0001 0.317	1 0.1012 0.2190 7 0.1006 0.2200	314.

H	ODE	L-94	6.2		4	CON	FIG.	3	.000		ĸ	ACH 3.0	00	•	PHI =	4	·5.		
Q	= 6.	. 37	PSI	R	E !	PER	IÑ.	z.	48E04	6	TO=	90. [EG.F		POJ/P	TS =	k	•	
P	e= :	193.	0 Ç	HHG	P.	rs=	1.0	1.09	PSI				RUN N	10.	01203	6910	57		
ALPH	Ā	CN	!	- (H			CS		CY	F	CR	CAT		СРВ	CA	\F		RUN
4.0	8 (0.47	74	-4	.33	387	~0.	020	3	0.1	909	0.0014	0.333	39	0.1090	0.2	2249		315.
3.0	7 (0.35	46.	-3	.2	172	-0.	018	1	0.1	718	0.0000	0.328	39	0.1068	0.2	221		315.
2.0	5 (23	45	-2	.12	262	-0.	015	0	0.5	443	0.0009	0.325	6	0.1045	0.2	211		315.
1.5	3 (2.17	19	-1.	•50	606	-0.	014	6	0.1	402	0.0012	0.322	8-	0.1041	0.2	2187		315.
1.0	1 (0.10	91	-0	-91	352	-07	015	1	O,ì	488	0.0003	ŀ Ó.321	7	Ó:1041	0.2	2176		315.
0,5	1 (0.09	47				-0.			0.1	179	0.0003	0.319	6	0.1039	0.2	2156		315.
~0 ⋅ `	~(3.00	13				-0.			0.1	07.7	0.0008	0.319	13	0.1035	0.2	158		315.
-9.5							-0.								0.1031				315.
-1.0				-1.	•06	889	-0.	QÒ5	9	0.0	662	0,0000	0.317	6	0.1931	0.2	144		315.
-1.5	3 -{	1.7	05	Į.	-5/	\ 59	-0.	005	0	0.0	588	0.0013	0.318	12	0.1035	0.2	147		315.
-2.0	5 -(.23	35	Ž.	.12	225	-0,	800	9	9.0	1984:	0.0008	0.317	2	0.1038	0.2	134		315.
-3.0				3.	.10	816	0.	001	8 -	-0.0	043	0.0009	0.317	1	0.1052	0.2	2118		315.
-4.0	7 -().46	78	. 4	"Ž	¥55	0 ž	011	6 -	-0-0	951	0.0013	0.318	32	0.1081	0.2	100		315.
H	ODEi	94	6.2		(ONF	IG.	3	000		H	ACH 3%C	10		PHI =	4	5.		
Q	= 6.	37	PSI	RI	E F	ER	IN.	= •	48E0	5	₹0≈	90.	EG.F		607\6.	TS ≖	: :	10.	
p	0= 1	L93 s	0 C	MHG	-P1	ŗs=	1.0	<u>1</u> 09	PSI			`	RUN N	0.	01203	6910	8		
ALPH	A	CN		(CM		i	cs		CY		CR	CAT		CP8	CA	F		RUN
4.0	8 (.47	02	-4	.30	52	-0.	028	9	0.2	525	0.0026	0.336	2	0.1096	0.2	266		316.
3.0		.34					-0.			0.1	971	0.0016	0.332	9	0.1084	0.2	245		316.
2.0						_	-0.		-	0.1	548	0.0006	0.327	9	0.1062	0-2	217		316.
165		1.16					-0.								0.1051				316.
1.0	2 (.10	44	-0.	.97	154	-0.	016	7						0.1048				316.
0.5	0 0	.04	70	-0.	45	9 R	-0-	113	1						0.1045				316.
-0.		oõ.		ō.	.02	251	-0-	009	9						0.1038				316.
-0.5				ő.	.59	73	-0.	311	7		965				0.1032				316.
-1.0							-0-					-			0.1029				316.
-1.5							-0.								0.1031				316.
-2.0			-				-0.								0.1033				316.
-3.0			• • • • • • • • • • • • • • • • • • • •				0.		-						0.1045				316.
-4.0						44	0.0								0.1075				316.

MOD	EL 946.2	CON	FIG. 3.000	, M	ACH 3:00	PHI =	45.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 T0=	90. DEG.F	60 <u>1</u> /6	TS = 20.	
P0=	193.0 CH	HG PTS=	1.0109 PSI		RUN	NO. 01203	69109	
ALPHA	CN	CM	cs	CY	CR CAT	СРВ	CAF	ŖUN
4.08	0.4660	-4.2913	-0.0333	0.2736	0.0042 0.33	93 0.1091	0.25.1	317.
3.07	0.3438		-0.0271		0.0028 0.33			317.
2.04	0.2243		-0.0247		0.0007 0.32			317.
1.52	0.1589		-0.0251		0.0010 0.32			31.7•
1.02	0.1025		-0.0259		0.0005 0.32			317.
	0.0457		-0.0204		0.0008 0.32			317.
	-0.0077		-0.0194		0.0011 0.32			317.
	-0.0680		-0.0201		-0.0005 0.32			317.
	-0-1243		-0.0186		0.0001 0.32			317.
	-0.1821		-0.0169		-0.0004 0.32			317.
	-0.2371 -0.3573		-0.0167 -0.0171		-0.0001 D.32			317.
	-0.4808		-0.0171		0.0011 0.32			317.
-4.07	-0.4600	7.3173	-0.0114	0.1314	C-0024 0-32	48 0-1016	0.2112	317.
	EL 946.2		FIG. 3.000		ACH 3.00	PH1 =		
•				•	200 12001			
P0=	193.0 CM	HG PTS=	1.0109 PSI		RUN	NO. 01203	69110	
AL PHA	CN	CM	CS	CY	CR CA1	СРВ	CAF	RUN
4.07	0.4558	-4.2366	-0.0452	0.3440	0.0074 0.34	19 0.1098	0.2322	318.
3.06	0.3337	-3.1269	-0.0403		0.0038 0.33			318.
2.04	0-2154	-2.0521	-0.0367	0.2599	0.0017 0.32	93 0.1064	0.2229	318.
1.52	0.1541	1 /070					~ ~~~~	318.
1.01			-0.0363	0.2581	0.0008 0.32	82 0.1054	0.2229	210.
	0.0959	-0.9580	-0.0330	0.2270	0.0007 0.32	61 0.1049	0.2212	318.
0.50	0.0959 0.0335	-0.9680 -0.3956	-0.0330 -0.0351	0.2270	0.0007 0.32	61 0.1049 59 0.1044	0.2212 0.2215	
0.50 -0.02	0.0959 0.0335 -0.0195	-0.9680 -0.3956 0.0811	-0.0330 -0.0351 -0.0298	0.2270 0.2470 0.1902	0.0007 0.32 0.0009 0.32 0.0012 0.32	61 0.1049 59 0.1044 20 0.1036	0.2212 0.2215 0.2184	318.
0.50 -0.02 -0.52	0.0959 0.0335 -0.0195 -0.0771	-0.9680 -0.3956 0.0811 0.6070	-0.0330 -0.0351 -0.0298 -0.0284	0.2270 0.2470 0.1902 0.1753	0.0007 0.32 0.0009 0.32 0.0012 0.32 0.0004 0.32	61 0.1049 59 0.1044 20 0.1036 08 0.1031	0.2212 0.2215 0.2184 0.2176	318. 318. 318. 318.
0.50 -0.02 -0.52 -1.04	0.0959 0.0335 -0.0195 -0.0771 -0.1394	-0.9680 -0.3956 0.0811 0.6070 1.1783	-0.0330 -0.0351 -0.0298 -0.0284 -0.0317	0.2270 0.2470 0.1902 0.1753 0.2073	0.0007 0.32 0.0009 0.32 0.0012 0.32 0.0004 0.32 -0.0001 0.32	61 0.1049 59 0.1044 20 0.1036 08 0.1031 23 0.1027	0.2212 0.2215 0.2184 0.2176 0.2196	318. 318. 318. 318. 318.
0.50 -0.02 -0.52 -1.04 -1.54	0.0959 0.0335 -0.0195 -0.0771 -0.1394 -0.1999	-0.9680 -0.3956 0.0811 0.6070 1.1783 1.7294	-0.0330 -0.0351 -0.0298 -0.0284 -0.0317 -0.0345	0.2270 0.2470 0.1902 0.1753 0.2073- 0.2367-	0.0007 0.32 0.0009 0.32 0.0012 0.32 0.0004 0.32 -0.0001 0.32	61 0.1049 59 0.1044 20 0.1036 08 0.1031 23 0.1027 12 0.1022	0.2212 0.2215 0.2184 0.2176 0.2196 0.2190	318. 318. 318. 318. 318.
0.50 -0.02 -0.52 -1.04 -1.54 -2.04	0.0959 0.0335 -0.0195 -0.0771 -0.1394 -0.1999 -0.2521	-0.9680 -0.3956 0.0811 0.6070 1.1783 1.7294 2.2006	-0.0330 -0.0351 -0.0298 -0.0284 -0.0317 -0.0345 -0.0323	0.2270 0.2470 0.1902 0.1753 0.2073- 0.2367- 0.2139	0.0007 0.32 0.0009 0.32 0.0012 0.32 0.0004 0.32 -0.0001 0.32 -0.0002 0.32 0.0012 0.32	61 0.1049 59 0.1044 20 0.1036 08 0.1031 23 0.1027 12 0.1022 08 0.1025	0.2212 0.2215 0.2184 0.2176 0.2196 0.2190 0.2183	318. 318. 318. 318. 318. 318.
0.50 -0.02 -0.52 -1.04 -1.54 -2.04	0.0959 0.0335 -0.0195 -0.0771 -0.1394 -0.1999	-0.9680 -0.3956 0.0811 0.6070 1.1783 1.7294 2.2006 3.2852	-0.0330 -0.0351 -0.0298 -0.0284 -0.0317 -0.0345	0.2270 0.2470 0.1902 0.1753 0.2073- 0.2367- 0.2139 0.2211	0.0007 0.32 0.0009 0.32 0.0012 0.32 0.0004 0.32 -0.0001 0.32	61 0.1049 59 0.1044 20 0.1036 08 0.1031 23 0.1027 12 0.1022 08 0.1025 19 0.1041	0.2212 0.2215 0.2184 0.2176 0.2196 0.2190 0.2183 0.2179	318. 318. 318. 318. 318.

HODEL 946.2	CON	FIG. 3.000) HA	ICH 3.00	PHI = 45.	
Q= 6.37 PSI	RE PER	IN.= .48E0	±07 ∂0	90. DEG.F	P0J/PTS = 10	00-
P0= 193.0 C	MHG PTS≃	1.0109 PSI	ī.	RUN NO	0. 0120369111	
ALPHA CN	CĦ	cs	CY	CR CAT	CPB CAF	RUN
4.05 0.4192	-4.0136	-0.0962	0.7097	0.0094 0.3433	0.1096 0.2336	319,
3.04 0.2973	-2.9076	-0.0892	0.6428	0.0032 0.3356	0.1085 0.2270	319.
2.02 0.1795	-1.8420	-0:0850	0 6036-	0.0011 0.3324	G.1067 0.2256	319.
1.49 0.1128	-1.2398	-0.0829			0.1054 0.2233	319.
0.99 0.0577		-0.0778			2 0.1051 0.2231	319.
0.46 -0.0103		-0.0816			0.1043 0.2212	319-
-0.03 -0.0680		-0.0765			0.1032 0.2192	319.
-0.55 -0.1289		-0.0765	0.5127	0-0012 0-3203	0.1027 0.2177	319.
-1.05 -0.1822		-0.0709			0.1025 0.2191	319.
-1.57 -0.2465		-0.0723			0.1021 0.2184	319.
-2.06 -0.2996		-0.0704			0.1019 0.2182	319.
-3.08 -0.4177		-0.0717			0.1036 0.2202	319.
~4.10 -0.5410	4.7289	-0.0678	0.4444	0.0037 0.3224	0.1057 0.2167	319.
MODEL 946.2	•	FIG. 3.000		CH 3.00	PHI = 90.	
MODEL 946.2 Q= 6.37 PSI	•	FIG. 3.000 IN.= .48E0		CH 3.00 90. DEG.F	PHI = 90. POJ/PTS =	•
	RE PER	IN.= .48E0	?6 TO=	90. DEG.F		•
Q= 6.37 PSI	RE PER	IN.= .48E0	?6 TO=	90. DEG.F	POJ/PTS =	• RUN
Q= 6.37 PSI PO= 193.0 C	RE PER MHG PTS≃ CM	IN.= .48E0	26 TO=	90. DEG.F RUN NO CR CAT	POJ/PTS = 0. 0120369112 CPB CAF	• RUN 320•
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823 3.09 0.3579	RE PER MHG PTS≃ CM -4.3891	IN.= .48E0 1.0109 PSI	CY 0.0961-	90. DEG.F RUN NO CR CAT 0.0036 0.3331	POJ/PTS =	
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823	RE PER MHG PTS≃ CM -4.3891	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065	CY 0.0961- 0.0553-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297	POJ/PTS = 0. 0120369112	320.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823 3.09 0.3579	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065	CY 0.0961- 0.0553- 0.0354-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3247	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1066 0.2251	320. 320.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044	CY 0.0961- 0.0553- 0.0354- 0.0331-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3247 0.0028 0.3239	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1046 0.2251 0.1039 0.2207	320. 320. 320.
Q= 6.37 PSI PO= 193.0 CO ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746 -1.0444	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0043	CY 0.0961- 0.0553- 0.0354- 0.0331- 0.0464- 0.0416-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3247 0.0029 0.3247 0.0028 0.3239 0.0027 0.3250 0.0030 0.3198	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1040 0.2209 0.1039 0.2159	320. 320. 320. 320. 320.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746 -1.0444 -0.5232 -0.0181	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0043 -0.0059 -0.0048 -0.0079	CY 0.0961- 0.0553- 0.0354- 0.0331- 0.0464- 0.0416-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3257 0.0029 0.3250 0.0027 0.3250 0.0030 0.3198 0.0022 0.3201	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1040 0.2209 0.1039 0.2159 0.1037 0.2163	320. 320. 320. 320. 320. 320.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021 -0.50 -0.0553	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746 -1.0444 -0.5232 -0.0181 0.5009	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0059 -0.0048 -0.0079 -0.0026	CY 0.0961- 0.0554- 0.0354- 0.0331- 0.0464- 0.0416- 0.0737- 0.0223-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3247 0.0028 0.3239 0.0027 0.3250 0.0030 0.3198 0.0022 0.3201 0.0024 0.3219	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1040 0.2299 0.1039 0.2159 0.1037 0.2163	320. 320. 320. 320. 320. 320.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021 -0.50 -0.0553 -1.00 -0.1123	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746 -1.0444 -0.5232 -0.0181 0.5009 1.0179	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0043 -0.0059 -0.0048 -0.0079 -0.0026 0.0001	CY 0.0961- 0.0554- 0.0354- 0.0464- 0.0737- 0.02230.0059-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3259 0.0027 0.3259 0.0030 0.3198 0.0022 0.3201 0.0024 0.3219 0.0015 0.3185	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1040 0.2251 0.1040 0.2199 0.1040 0.2299 0.1039 0.2159 0.1037 0.2163 0.1036 0.2182 0.1037 0.2148	320. 320. 320. 320. 320. 320. 320.
Q= 6.37 PSI P0= 193.0 CM ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021 -0.50 -0.0553 -1.00 -0.1123 -1.51 -0.1697	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5744 -0.5232 -0.0181 0.5009 1.0179 1.5380	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0043 -0.0059 -0.0048 -0.0079 -0.0026 0.0001 0.0029	CY 0.0961- 0.0553- 0.0354- 0.0361- 0.0416- 0.0737- 0.02230.0059-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3250 0.0027 0.3250 0.0030 0.3198 0.0022 0.3201 0.0024 0.3219 0.0015 0.3185	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 C.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1039 0.2159 0.1037 0.2163 0.1036 0.2182 0.1037 0.2148 0.1038 0.2147	320. 320. 320. 320. 320. 320. 320. 320.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021 -0.50 -0.0553 -1.00 -0.1123 -1.51 -0.1697 -2.02 -0.2263	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5746 -1.0444 -0.5232 -0.0181 0.5009 1.0179 1.5380 2.0533	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0059 -0.0048 -0.0079 -0.0026 0.0001 0.0029 0.0031	CY 0.0961- 0.0553- 0.0354- 0.0331- 0.0464- 0.0737- 0.02230.00590.0301-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3247 0.0028 0.3239 0.0027 0.3250 0.0030 0.3198 0.0022 0.3201 0.0024 0.3219 0.0015 0.3185 0.0018 0.3185	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 0.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1036 0.2159 0.1036 0.2163 0.1036 0.2148 0.1038 0.2147 0.1040 0.2156	320. 320. 320. 320. 320. 320. 320. 320.
Q= 6.37 PSI P0= 193.0 CM ALPHA CN 4.10 0.4823 3.09 0.3579 2.06 0.2380 1.55 0.1736 1.03 0.1152 0.53 0.0578 0.01 0.0021 -0.50 -0.0553 -1.00 -0.1123 -1.51 -0.1697	RE PER MHG PTS= CM -4.3891 -3.2516 -2.1586 -1.5744 -0.5232 -0.0181 0.5009 1.0179 1.5380	IN.= .48E0 1.0109 PSI CS -0.0110 -0.0065 -0.0044 -0.0059 -0.0059 -0.0079 -0.0026 0.0001 0.0029 0.0031 0.0051	CY 0.0961- 0.0553- 0.0354- 0.0331- 0.0464- 0.0737- 0.02230.00590.03010.0503-	90. DEG.F RUN NO CR CAT 0.0036 0.3331 0.0049 0.3297 0.0029 0.3247 0.0028 0.3239 0.0027 0.3250 0.0030 0.3198 0.0024 0.3219 0.0024 0.3219 0.0025 0.3185 0.0015 0.3185 0.0016 0.3195	POJ/PTS = 0. 0120369112 CPB CAF 0.1053 C.2278 0.1046 0.2251 0.1039 0.2207 0.1040 0.2199 0.1039 0.2159 0.1037 0.2163 0.1036 0.2182 0.1037 0.2148 0.1038 0.2147	320. 320. 320. 320. 320. 320. 320. 320.

MODEL 946.2				
HODEL 34012	CONFIG. 3	3.000 ' MACH 3.00	0 PHS = \$0.	
Q= 6.37 PSI	. RE PER IN.=	.48E06 TO= 90. Di	EG.F POJ/PTS = 10.	
PO= 193.0 CM	HG PTS= 1.0109	129	RUN NÖ. 0120369113	
ALPHA CN	CH CS	CY CR	CAT CPB CAF	RUN
4.10 0.4796	-4.3704 -0.018		0.3372 0.1055 0.2317	321.
3.09 0.3552	-3.2319 -0.019		0.3319 0.1044 0.2275	321.
2.96 0.2348	-2.1358 -0.012		0.3286 0.1038 0.2249	321.
1.54 0.1700	-1.5465 -0.013		0.3252 0.1039 0.2213	321.
1.03 9.1126	-1.0246 -0.009	95 0.0479-0.0034	0.3244 0.1039 0.2205	321.
0.51 0.0524	-0.4791 -0.000		0.3228 0.1040 0.2188	321.
0.01 -0.0019	0.0126 -0.009	99 0.0534-0.0028	0.3204 0e1039 0.2165	321.
-0.50 -0.0625	0.5631 -0.009	97 0.0536-0.0031	0.3205 0.1039 0.2166	321.
-1.00 -0.1181	1.0670 -0.012	20 0.0794-0.0030	0.3216 0.1038 0.2178	321.
-1.51 -0.1770	1.6016 -0.000	08 -0.0315-0.0022	0.3215 0.1038 0.2177	321.
-2.02 -0.2353	2.1307 -0.00	15 -0.0217-0.0021	0.3207 0.1038 0.2169	321.
-3.04 -0.3511	3.1841 0.000	06 -0.0420-0.0022	0.3227 0.1041 0.2186	321.
-4.05 -0.4774	4.3360 0.007	76 -0.1043-0.0025	0.3200 0.1053 0.2147	321.
MDDEL 946.2	******	3.000 HACH 3.0	0 PHI = 90.	
	CONFIG. 3	3.000 NACH 3.0	u rni = 90.	
Q= 6.37 PSI	RE PER IN.=			
Q= 6.37 PSI		.48E06 TO= 90. D		
Q= 6.37 PSI	RE PER IN.=	.48E06 TO= 90. D	FS.F POJ/PTS = 20.	RUN
Q= 6.37 PSI PO= 193.0 CM ALPHA CN	RE PER IN.= . HG PTS= 1.0109 CH CS	.48E06 TO= 90. D 9 PSI CY CR	FS.F POJ/PTS = 20. RUN NO. 0120369114 CAT GPB CAF	RUN
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020	.48E06 TO= 90. D 9 PSI CY CR 07 0.1151-0.0922	FS.F POJ/PTS = 20. RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333	RUN 322:
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585	RE PER IN.= . HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019	.48E06 TO= 90. G 9 PSI CY CR 07 0.1151-0.0022 96 0.1051-0.0021	FS.F POJ/PTS = 20. RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306	RUN 322: 322:
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585 2.06 0.2377	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019	.48E06 TO= 90. G 9 PSI CY CR 07 0.1151-0.0022 96 0.1051-0.0021 93 0.1033-0.0034	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270	RUN 322: 322: 322:
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4626 3.09 0.3585 2.06 0.2377 1.54 0.1720	RE PER IN.= HG PTS= 1.0109 CM CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.020	CY CR 07 0.1151-0.0022 96 0.1051-0.0034 9 0.1313-0.0042	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235	RUN 322: 322: 322: 322:
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145	RE PER IN.= HG PTS= 1.0109 CM CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.020 -1.0443 -0.019	CY CR 07 0.1151-0.0022 96 0.1051-0.0021 93 0.1033-0.0034 18 0.1313-0.0042 56 0.0691-0.0014	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1039 0.2236	RUN 322: 322: 322: 322: 322:
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.021 -1.0443 -0.019 -0.5031 -0.021	CY CR 07 0.1151-0.0922 96 0.1051-0.0021 93 0.1033-0.0034 18 0.1313-0.0042 56 0.0691-0.0014 14 0.1267-0.0029	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1039 0.2236 0.3260 0.1040 0.2221	RUN 322. 322. 322. 322. 322.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548 0.01 -0.0018	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.021 -1.0443 -0.019 -0.5031 -0.020 0.0120 -0.020	CY CR O7 0.1151-0.0922 96 0.1651-G.0021 93 0.1033-0.0034 18 0.1313-0.0042 0.0691-0.0014 0.1267-0.0029 0.1144-0.0016	FS.F POJ/PTS = 20. RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1039 0.2236 0.3260 0.1040 0.2221 0.3244 0.1040 0.2204	RUN 322. 322. 322. 322. 322. 322.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4826 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548 0.01 -0.0018 -0.50 -0.0611	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.020 -1.0443 -0.019 -0.5031 -0.020 0.0120 -0.020 0.5512 -0.018	CY CR O7 0.1151-0.0922 96 0.1651-G.0021 93 0.1033-0.0034 18 0.1313-0.0042 56 0.0691-0.0014 14 0.1267-0.0029 03 0.1144-0.0016 15 0.0948-0.0041	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1039 0.2236 0.3260 0.1040 0.2221 0.3244 0.1040 0.2204 0.3237 0.1042 0.2195	RUN 322. 322. 322. 322. 322. 322. 322.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4626 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548 0.01 -0.0018 -0.50 -0.0611 -1.01 -0.1208	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.021 -1.0443 -0.019 -0.5031 -0.021 0.0120 -0.020 0.5512 -0.018 1.0946 -0.020	CY CR O7 0.1151-0.0022 O6 0.1051-0.0031 O 1033-0.0034 O 1044-0.0014 O 1267-0.0029 O 1144-0.0016 O 0948-0.0041 O 1108-0.0018	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1040 0.2236 0.3260 0.1040 0.2221 0.3244 0.1040 0.2204 0.3237 0.1042 0.2195 0.3238 0.1041 0.2197	RUN 322. 322. 322. 322. 322. 322. 322. 322
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4626 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548 0.01 -0.0018 -0.50 -0.0611 -1.01 -0.1208 -1.51 -0.1778	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.020 -1.0443 -0.019 -0.5031 -0.020 0.0120 -0.020 0.5512 -0.018 1.0946 -0.020 1.6096 -0.020	CY CR OT 0.1151-0.0022 06 0.1051-0.0021 03 0.1033-0.0034 18 0.1313-0.0042 06 0.0691-0.0014 14 0.1267-0.0029 03 0.1144-0.0016 05 0.0948-0.0041 0.1108-0.0018	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1040 0.2236 0.3260 0.1040 0.2221 0.3244 0.1040 0.2204 0.3237 0.1042 0.2195 0.3238 0.1041 0.2197 0.3250 0.1038 0.2212	RUN 322. 322. 322. 322. 322. 322. 322. 322
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.10 0.4626 3.09 0.3585 2.06 0.2377 1.54 0.1720 1.04 0.1145 0.52 0.0548 0.01 -0.0018 -0.50 -0.0611 -1.01 -0.1208	RE PER IN.= HG PTS= 1.0109 CH CS -4.3975 -0.020 -3.2628 -0.019 -2.1639 -0.019 -1.5677 -0.021 -1.0443 -0.019 -0.5031 -0.021 0.0120 -0.020 0.5512 -0.018 1.0946 -0.020	CY CR OT 0.1151-0.0022 O 0.1051-0.0021 O 0.1033-0.0034 O 0.1313-0.0042 O 0.0691-0.0014 O 0.1267-0.0029 O 0.1144-0.0016 O 0.1084-0.0041 O 0.1084-0.0018 O 0.1684-0.0036	RUN NO. 0120369114 CAT CPB CAF 0.3384 0.1050 0.2333 0.3350 0.1043 0.2306 0.3309 0.1038 0.2270 0.3275 0.1040 0.2235 0.3275 0.1040 0.2236 0.3260 0.1040 0.2221 0.3244 0.1040 0.2204 0.3237 0.1042 0.2195 0.3238 0.1041 0.2197	RUN 322. 322. 322. 322. 322. 322. 322. 322

MO	DEL 946.2	CON	FIG. 3.000	на	CH 3.00	PHI =	90.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 T0≈	90. DEG.₽	901/6	TS = 4	0.
PO	= 193.0 CH	HG PTS=	1-0109 PSI		RUN	NO. 01203	69115	
ALPHA	CN	CH	cs	CY	CR CAT	СРВ	CAF	RUN
4-10	0.4852	-404178	-0.0364	0.2025	0.0002 0.34	19 0-1049	0-2370	323.
3.08	0.3598	-3.2722	-0.0362	0.2017-	0.0019 0.33	68 0-1045	0.2323	323،
2.06			-0.0375		0.0014 0.33			323.
1.54			-0.0390		0,0010 0.33			323.
1.03			-0.0346		0.0024 0.32			323.
0.52			-0.0404		0.0019 0.32			323.
	-0.0038		-0.0394		0.0026 0.32			323.
	-0.0617		-0.0435		ē.0028 0.32			323.
	-0-1228		-0.0425		0-0020 0-32			323.
	-0.1821		-0.0457		0.0016 0.32			323.
	-0.2396		-0.0456		0.0045 0.32			323.
	-0.3573 -0.4840		-0.0460 -0.0441		0.0035 0.32			323.
-4.00	-0.4840	4.3937	-0.0441	0.2810-	9.0049 0.32	12 0.1049	0.5103	323.
	DEL 946.2 6.37 PSI		FIG. 3.000 IN.= .48E0		CH 3.00	PHI = POJ/P	90. TS = 10	0.
0=	6.37 PSI	RE PER			90. DEG.F	_	rs = 10	0.
Q= P0	6.37 PSI = 193.0 CM	RE PER	IN.= .48E0	6 To=	90. DEG.F	POJ/P1	rs = 10 69116	
0=	6.37 PSI = 193.0 CM	RE PER	IN.= .48E0		90. DEG.F	POJ/P1	rs = 10	O. RUN
Q= PO Alphà	6.37 PSI = 193.0 CM	RE PER HG PTS=	IN.= .48E0 1.0109 PSI CS	6 T0=	90. DEG.F RUN CR CAT	POJ/P ¹ NO. 012030 CPB	TS = 10 59116 CAF	RUN
Q= P0 ALPHÅ 4.09	6.37 PSI = 193.0 CM CN 0.4891	RE PER HG PTS= CM -4.4520	IN.= .48E0 1.0109 PSI CS -0.0951	6 T0= CY 0.5894	90. DEG.F RUN CR CAT 0.0022 0.34	POJ/P NO. 012030 CPB 47 0.1044	TS = 10 59116 CAF 0.2403	RUN 324.
Q= PO ALPHÀ 4.09 3.08	6.37 PSI = 193.0 CM CN 0.4891 0.3664	RE PER HG PTS= CM -4.4520 -3.3369	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965	6 TO= CY 0.5894 0.6028-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33	POJ/P NO. 012036 CPB 47 0.1044 80 0.1039	TS = 10 59116 CAF 0.2403 0.2341	RUN 324 • 324 •
Q= P0 ALPHÅ 4.09 3.08 2.06	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455	RE PER HG PTS= CH -4.4520 -3.3359 -2.2460	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970	CY 0.5894 0.6028- 0.6074-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0039 0.33	POJ/P1 NO. 012036 CPB 47 0.1044 80 0.1039	TS = 10 59116 CAF 0.2403 0.2341 0.2269	RUN 324 • 324 • 324 •
Q= PO ALPHÀ 4.09 3.08	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806	RE PER HG PTS= CH -4.4520 -3.3359 -2.2460 -1.6607	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965	CY 0.5894 0.6028- 0.6074- 0.6240-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0039 0.33 0.0068 0.32	POJ/P1 NO. 012030 CPB 47 0.1044 80 0.1039 04 0.1035 88 0.1037	TS = 10 59116 CAF 0.2403 0.2341 0.2269 0.2251	RUN 324. 324. 324.
PO ALPHÀ 4.09 3.08 2.06 1.54	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195	RE PER HG PTS= CM -4.4520 -3.3359 -2.2460 -1.6607 -1.1052	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6301-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0039 0.33	POJ/P1 NO. 012030 CPB 47 0.1044 80 0.1039 04 0.1035 88 0.1037 63 0.1037	TS = 10 59116 CAF 0.2403 0.2341 0.2269 0.2251 0.2226	RUN 324 • 324 • 324 •
Q= PO ALPHA 4.09 3.08 2.06 1.54 1.03 0.52	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195	RE PER HG PTS= CM -4.4520 -3.3359 -2.2460 -1.6607 -1.1052 -0.5393	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6301- 0.6285-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0039 0.33 0.0068 0.32 0.0041 0.32	POJ/PT NO. 012030 CPB 47 0.1044 80 0.1035 88 0.1037 63 0.1037 73 0.1035	TS = 10 59116 CAF 0.2403 0.2341 0.2269 0.2251 0.2226 0.2238	RUN 324. 324. 324. 324. 324.
Q= P0 ALPHA 4.09 3.08 2.06 1.54 1.03 0.52 0.01	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195 0.0579	RE PER HG PTS= CM -4.4520 -3.3359 -2.2460 -1.6607 -1.1052 -0.5393 0.0261	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993 -0.0991	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6285- 0.5557- 0.5835-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0039 0.33 0.0068 0.32 0.0041 0.32 0.0033 0.32 0.0013 0.32 0.0013 0.32	POJ/P NO. 012030 CPB 47 0.1044 80 0.1039 04 0.1035 88 0.1037 63 0.1037 73 0.1035 29 0.1031 21 0.1033	S = 10 59116 CAF 0.2403 0.2341 0.2269 0.2251 0.2226 0.2238 0.2198 0.2186	RUN 324. 324. 324. 324. 324.
P0 ALPHA 4.09 3.08 2.06 1.54 1.03 0.52 0.01 -0.50 -1.01	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195 0.0579 -0.0031 -0.0665 -0.1285	RE PER HG PTS= CM -4.4520 -3.3369 -2.2460 -1.052 -0.5393 0.0261 0.6121 1.1800	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993 -0.0991 -0.0922 -0.0947 -0.0928	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6285- 0.5557- 0.5835- 0.5666	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0068 0.32 0.0068 0.32 0.0013 0.32 0.0013 0.32 0.0013 0.32 0.0005 0.32	POJ/P NO. 012030 CPB 47 0.1044 80 0.1039 04 0.1035 88 0.1037 63 0.1037 73 0.1035 29 0.1031 21 0.1033 12 0.1029	S = 10 59116 CAF 0.2403 0.2341 0.2251 0.2251 0.2238 0.2198 0.2188 0.2188	RUN 324. 324. 324. 324. 324. 324. 324.
Q= P0 ALPHA 4.09 3.08 2.06 1.54 1.052 0.01 -0.50 -1.01	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195 0.0579 -0.0031 -0.0665 -0.1285 -0.1869	RE PER HG PTS= CM -4.4520 -3.3369 -2.2460 -1.6607 -1.1052 -0.5393 0.0261 0.6121 1.1800 1.7093	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993 -0.0991 -0.0922 -0.0947 -0.0928 -0.0977	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6285- 0.5557- 0.5835- 0.5666 0.6169	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0068 0.32 0.0041 0.32 0.0033 0.32 0.0013 0.32 0.0013 0.32 0.0007 0.32 0.0007 0.32	POJ/P NO. 012030 CPB 47 0.1044 80 0.1039 04 0.1035 88 0.1037 73 0.1035 29 0.1031 21 0.1033 12 0.1029 15 0.1029	S = 10 59116 CAF 0.2403 0.2341 0.2251 0.2251 0.2238 0.2188 0.2188 0.2188	RUN 324. 324. 324. 324. 324. 324. 324. 324.
9= P0 ALPHA 4.09 3.08 2.06 1.54 1.03 0.52 0.01 -0.50 -1.01 -1.51 -2.04	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195 0.0579 -0.0031 -0.0665 -0.1285 -0.1869 -0.2466	RE PER HG PTS= CH -4.4520 -3.3359 -2.2460 -1.6607 -1.1052 -0.5393 0.0261 0.6121 1.1800 1.7093 2.2486	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993 -0.0991 -0.0922 -0.0947 -0.0928 -0.0927 -0.0928	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6301- 0.6285- 0.5557- 0.5836- 0.5666 0.6169	90. DEG.F RUN CR CAT 0.0022 0.34 9.0010 0.33 0.0039 0.33 0.0068 0.32 0.0041 0.32 0.0013 0.32 0.0013 0.32 0.0005 0.32 0.0007 0.32 0.0007 0.32 0.0004 0.32	POJ/P1 NO. 012036 CPB 47 0.1044 80 0.1035 88 0.1037 63 0.1037 73 0.1035 29 0.1031 21 0.1033 12 0.1029 15 0.1029	S = 10 S9116 CAF 0.2403 0.2341 0.2269 0.2226 0.2228 0.2198 0.2188 0.2188 0.2188 0.2188	RUN 324. 324. 324. 324. 324. 324. 324. 324.
PO ALPHA 4.09 3.08 2.06 1.54 1.03 0.52 0.01 -0.50 -1.51 -2.04 -3.04	6.37 PSI = 193.0 CM CN 0.4891 0.3664 0.2455 0.1806 0.1195 0.0579 -0.0031 -0.0665 -0.1285 -0.1869	RE PER HG PTS= CH -4.4520 -3.3359 -2.2460 -1.6607 -1.1052 -0.5393 0.0261 0.6121 1.1800 1.7093 2.2486 3.3041	IN.= .48E0 1.0109 PSI CS -0.0951 -0.0965 -0.0970 -0.0986 -0.0993 -0.0991 -0.0922 -0.0947 -0.0928 -0.0977	CY 0.5894 0.6028- 0.6074- 0.6240- 0.6301- 0.6285- 0.5557- 0.5835- 0.5660- 0.6498 0.6617-	90. DEG.F RUN CR CAT 0.0022 0.34 0.0010 0.33 0.0068 0.32 0.0041 0.32 0.0033 0.32 0.0013 0.32 0.0013 0.32 0.0007 0.32 0.0007 0.32	POJ/P1 NO. 012036 CPB 47 0.1044 80 0.1039 04 0.1037 63 0.1037 73 0.1035 29 0.1031 21 0.1039 12 0.1029 15 0.1029 17 0.1035	CAF 0.2403 0.2341 0.2269 0.2251 0.2226 0.2238 0.2198 0.2188 0.2185 0.2185 0.2182	RUN 324. 324. 324. 324. 324. 324. 324. 324.

SOCKET STREET ST

MODEL 946.2	соні	FIG. 2.4!	50 M	KCH 3.00		PHI =	•	
Q= 6.37 PSI	RE PER	IN.= .481	E06 T0=	90. DEG.	F	POJ/P	rs =	•
PU= 193.0 CM	HG PTS=	1.0109 PS	sı	RU	N NO.	01203	69117	
ALPHA CN	СН	cs	CY	C: C	AT	CPB	CAF	RUN
4.01 0.4039		0.0076		0.0042 0.2				
3.00 0.2981		-0.0069		C.0047 0.				
1.98 0.1940		-0.9666		0.0044 0.				
1.46 0.1368		-0.9050		0.0048 0.2				
0.94 0.0881		-0.0049		0.0049 0.3				
0.43 0.0420		-0.0043		0.0046 0.				
-0.08 -0.0050		-0.0051		0.0047 0.2				
-0.60 -0.0604		-0.0049		0.0043 0.2				
-1.10 -0.1031		-0.0057		0.0048 0.7				
-1.62 -0.1527 -2.11 -0.2013		-0.0051 -0.0055		0.0041 0.2				
-3.13 -0.3946		-0.0033		0.0042 0.2				
-4.15 -0.4156		0.0021		0.0053 0.3				325.
7015 001150	340027	010021	4405,1	0.0000			****	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
MODEL 946.2	CONI	FIG. 2.4!	50 H	ACH 3.00		. H4.	•	
MODEL 946.2 Q= 6.37 PSI		FIG. 2.4! IN.= .48!		ACH 3.00 90. DEG.I	F	PHI =		10.
	RE PER	IN.= .48	E06 TO=	90. DES.			rs =	10.
Q= 6.37 PSI	RE PER	IN.= .48	E06 TO=	90. DES.I		P0J/P	rs =	10.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN	RE PER HG 'PTS= CH	IN.= .488 1.0169 PS	E06 T0= SI CY	90. DES.I	.OW W	POJ/P? 012036 CPB	rs = 59118 Caf	RUŅ
Q= 6.37 PSI PO= 193.0 CM	RE PER HG 'PTS= CH -3:4678	IN.= .488 1.0169 PS CS -0.0013	E06 T0= S1 CY 0~0031	90. DES.I RUI CR C	N NO. AT 3024	POJ/P1 012036 CP8 0.1124	TS = 59118 CAF 0-1829	RUN_ 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885	RE PER HG 'PTS= CH -3.4678 -2.5293	IN.= .488 1.0169 PS CS -0.0013 -0.0014	E06 T0= SI CY 0~0031 0~0037	90. DES.I RUI CR C/ 0.0043 0.	N NO. AT 3024 3002	POJ/P1 012036 CPB 0.1124 0.1114	TS = 59118 CAF 0.1829 0.1888	RUN 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860	RE PER HG 'PTS= CH -3.4678 -2.5293	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002	CY 0.0031 0.0037 -0.0078	90 - DES -1 RUI CR CI 0.0043 0 - 0.0044 0 - 0.0041 0 -	N NO. AT 3024 3002 2979	POJ/PT 012036 CPB 0-1124 0-1114- 0-1100	TS = 59118 CAF 0.1829 0.1888 0.1879	RUN 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255	RE PER HG 'PTS= CH -3.4678 -2.5293 -1.6376 -1.1076	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002	CY 0.0031 0.0037 -0.0078 -0.0193	90 - DES -1 RUI CR C/ 0.0043 0-1 0.0044 0-2 0.0041 0-0 0.0037 0-2	N NO. AT 3024 3002 2979 2971	POJ/P7 012036 CPB 0.1124 0.1114 0.1100 0.1093	TS = 59118 CAF 0.1829 0.1888 0.1879 0.1878	RUN 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255	RE PER CH -3.4678 -2.5293 -1.6376 -1.1076 -0.7818	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002	CY 0.0031 3.0037 -0.0078 -0.0193 -0.0080	90 - DES -1 RUI CR CI 0.0043 0 - 0.0044 0 - 0.0041 0 -	N NO. AT 3024 3002 2979 2971 2966	POJ/P? 012036 CPB 0-1124 0-1114- 0-1100 0-1093 0-1092	TS = 59118 CAF 0.1829 0.1888 0.1879 0.1878	RUN 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -1.1076 -0.7818 -0.3002	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -0.	CY 0.0031 0.0037 -0.0078 -0.0103 -0.0080 -0.0178	90 - DES -1 RUI CR C/ 0.0043 0 -1 0.0044 0 -2 0.0041 0 -1 0.0037 0 -2 0.0042 0 -2	N NO. AT 3024 3002 2979 2971 2966 2955	POJ/P? 012036 CPB 0-1124 0-1110 0-1093 0-1092 0-1093	CAF 0-1899 0-1888 0-1879 0-1878 0-1874 0-1862	RUN 326. 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861 0.43 0.0315	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -1.1076 -0.7818 -0.3002	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -00.0003 0.0007 -0.6001	CY 0.0031 0.0037 -0.0078 -0.0103 -0.0080 -0.0178 -0.9125	90 - DES - I RUI CR C/ 0.0043 0 - 0.0044 0 - 0.0041 0 - 0.0037 0 - 0.0042 0 -	N NO. AT 3024 3002 2979 2971 2966 2955 2969	POJ/P? 012036 CP8 0.1124 0.1110 0.1093 0.1092 0.1093 0.1092	CAF 0.1899 0.1888 0.1879 0.1874 0.1862	RUN 326. 326. 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861 0.43 0.0315 -0.09 -0.0155	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -1.1076 -0.7818 -0.3002 0.1061	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -00.0003 0.0007 -0.6001	CY 0.0031 0.0037 -0.0078 -0.0193 -0.0178 -0.0125 -0.0130 -0.0137	90. DES.1 RUI CR C. 0.0043 0. 0.0044 0. 0.0041 0. 0.0037 0. 0.0042 0. 0.0042 0. 0.0039 0. 0.0032 0. 0.0032 0. 0.0032 0.	N NO. AT 3024 3002 2979 2971 2966 2955 2969 2948 2953	POJ/P? 012036 CP8 0.1124 0.1114 0.1100 0.1093 0.1093 0.1093 0.1092 0.1093	CAF CAF 0.1899 0.1888 0.1878 0.1878 0.1878 0.1868	RUN 326. 326. 326. 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861 0.43 0.0315 -0.09 -0.0155 -0.60 -0.0641	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -0.7818 -0.3002 0.1061 0.5248	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -00.0003 0.0007 -0.6001 0. 0.0001	CY 0.0031 0.0037 -0.0078 -0.0103 -0.0080 -0.0178 -0.0125 -0.0137 -0.0166	90. DES.1 RUI CR C. 0.0043 0. 0.0044 0. 0.0041 0. 0.0037 0. 0.0042 0. 0.0042 0. 0.0039 0. 0.0032 0. 0.0032 0. 0.0040 0. 0.0045 0.	N NO. AT 3024 3002 2979 2971 2966 2955 2969 2948 2953 2923	POJ/P7 012036 CP8 0.1124 0.1114 0.1100 0.1093 0.1093 0.1093 0.1092 0.1090 0.1085 0.1075	CAF CAF 0.1829 0.1888 0.1878 0.1878 0.1868 0.1858	RUN 326. 326. 326. 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861 0.43 0.0315 -0.09 -0.0155 -0.60 -0.0641 -1.10 -0.1111	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -1.1076 -0.3002 0.1061 0.5248 0.9295 1.3139	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -00.0003 0.0007 -0.6001 0. 0.0001	CY 0.0031 0.0037 -0.0078 -0.0103 -0.0080 -0.0178 -0.0137 -0.0136 -0.0137	90. DES.1 RUI CR C/ 0.0043 0. 0.0044 0. 0.0041 0. 0.0042 0. 0.0042 0. 0.0042 0. 0.0049 0. 0.0049 0. 0.0049 0. 0.0049 0. 0.0049 0. 0.0049 0.	N NO. AT 3024 3002 2979 2976 2955 2969 2948 2953 2923 2938	POJ/P1 012036 CPB 0.1124 0.1114 0.1100 0.1093 0.1092 0.1093 0.1095 0.1095 0.1075	CAF 0.1829 0.1888 0.1879 0.1874 0.1868 0.1878 0.1858 0.1848	RUN 326. 326. 326. 326. 326. 326. 326. 326.
Q= 6.37 PSI PO= 193.0 CM ALPHA CN 4.00 0.3960 2.99 0.2885 1.97 0.1860 1.45 0.1255 0.94 0.0861 0.43 0.0315 -0.09 -0.0155 -0.60 -0.0641 -1.10 -0.1111 -1.61 -0.1563	RE PER HG PTS= CH -3.4678 -2.5293 -1.6376 -1.1076 -0.3002 0.1061 0.5248 0.9295 1.3139	IN.= .488 1.0169 PS CS -0.0013 -0.0014 -0.0002 -00.0003 0.0007 -0.6001 0.0003 -0.0001 0.0003	CY 0.0031 0.0037 -0.0078 -0.0103 -0.0180 -0.0178 -0.0137 -0.0137 -0.0166 -0.0121 -0.0327	90. DES.1 RUI CR C. 0.0043 0. 0.0044 0. 0.0041 0. 0.0037 0. 0.0042 0. 0.0042 0. 0.0039 0. 0.0032 0. 0.0032 0. 0.0040 0. 0.0045 0.	N NO. 3024 3002 2979 2971 2966 2955 2948 2953 2948 2938 2941	POJ/P1 012036 CPB 0-1124 0-1114 0-1100 0-1093 0-1092 0-1093 0-1095 0-1075 0-1067	CAF 0.1899 0.1888 0.1879 0.1878 0.1877 0.1858 0.1858 0.1858 0.1858	RUN 326. 326. 326. 326. 326. 326. 326. 326

MO	DEL 946.2	COM	FIG. 2.4	50 M	ACH 3.00)	PHI =	•	
Q=	6.37 PSI	RE PER	IN.= .48	E06 T0=	90. DE	G.F	POJ/P	rs = 20).
PΩ	= 193.0 CM	=279 AH	1 - 01 09 P	51		RIIN NO	. 01203	69119	
	- 27530 011			٠.			. 01203		
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	ÇAF	RUN
4.09	0.3838	-3.3866	-0.0028		0-0044				327.
2.99	0.2789	-2.4708	-0.0029	0.0175	0-0037	0.3060	0.1117	0.1943	327.
1.96	0.1773	-1.5903	-9.0013	0.0021	0.0034	0.3037	0.1102	0.1935	327.
1.44	0.1167	-1.0610	-0.0006	-0.0045	0.0038	0.3055	0.1092	0.1962	327.
0.93	0.0697	-0.6544	-0.0010	-0.0020	0.0032	0.3025	0.1091	0.1934	327.
0.42	0.0211	-0.2375	-0.0003	-0.009Ô	0.0043	0.3022	0.1093	0.1928	327.
-0.09	-0.0250	0.1634	0.0002	-0.0128	0.0033	0.3009	0.1094	0.1914	327.
-0.60	-0.0652	0.4974	-0.0001	-0.0115	0-0041	0.2960	0.1094	0.1866	327.
-1.11	-0.1165	0.9436	0.0009	-0.0212					327.
-1.62	-0.1719	1.4313	0.0010	-0.0228	0.0034	0.2991	0.1077	0.1914	327.
-2.12	-0.2120	1.7713	0.0007	-C.0208	0.0046	0.2994	0.1069	0.1925	327.
	-0.3162	2.6764		-0.0364					327.
-4.16	-0.4255		0.0078	-0.0842	0.0044	0.2994	G.1076	0.1918	327-
МО	DFL 946.2	CON	F1G. 2.4	50 M	ACH 3.00	5	PHI =	•	
Q=	6.37 PSI	RE PER	IN.= .43	=0f 70=	90. DE	G.F	401\b.	rs = 40).
PO:	= 193.0 CM	HG PTS=	1.0109 P	sı		RUN NO.	01203	69120	
ALPHA	CN	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
3.90	0.3639	-3.2626	-0.0031	0.0174	0.0045	0.3136	0.1131	0.2005	328.
2.98	0.2598	-2.3509	-0.0015		0-0046				328 -
1.95	0.1565	-1.4551	-0.0002	-0.0088	0.0040	0.3056	0.1101	9.1955	328.
1.43	0.1044	-1.0061	-0.	-0.0115					328.
0.92	0.0540	-0.5708	0.0001	-0.0130	0.0037	0-3034	0.1090	0.1944	328.
0.41	0.0105	-0.1927	0.0015	-0.0271	0.0041	0.3029	0.1091	0.1938	328.
-0.10	-0.0390	0.2315	0.0012	-0.0246	0.0045	0.3044	0.1093	0.1950	328.
-0.61	-0.0877	0.6516	0.0013	-0.0273					328.
-1.13	-0.1364	1.0678	0.0015	-0.0290	0.0039	0-2994	0.1088	0.1906	328.
-1.63	-0.1867	1.5113	0.0016	-0.0308	0.0040	0.2982	0.1078	0.1904	328.
-2.14	-0.2320	1.8948	0.0022	-0.0365	0.0040	0.2996	0.1070	0.1926	328.
-3.15	-0.3327	2.7599	0.0038	-0.0511	0.0041	0.2972	0.1064	0.1908	328,
-4.17	-0.4421	3.7183	0.0084	-0.0920	0.0042	0.2995	0.1076	0.1918	328 •

HODEL 94	6.2 CON	FIG. 2.450	АК	CH 3.00)	PHI =	•	
Q= 6.37	PSI RE PER	IN.= :48E0	6 TO=	90. DE	G-F	P0J/P	rs = 10	00-
PO= 193.	O CHHG PTS=	10109 PSI			RUN NO.	01203	5922 1	
ALPHA CA	е си	CS	CY	CR	CAT	ÇPB	CAF	RUN
3.97 0.30		-0.0014		0.0042				329.
2.95 0.19	-		-0-0028					329.
1.93 0.09			-0.0103					329.
1:40 0.04			-0.0169					329.
0.90 -0.00			-0.0106					329.
0.38 -0.05			-0.0253					329.
-0.13 -0.10			-0.0311					329.
-0.64 -0.15			-0-0338					329.
-1.15 -0.19 -1.65 -0.24			-0.0316 -0.0372					329. 329.
			-0.0379	-				329. 329.
-2.16 -0.28 -3.19 -0.38			-0.0638					329•
-4.20 -0.49			-0.1117					329.
-7.20 -0.45	700 4.0543	0.0103	-0+1111	D. UU 10	0.2770	0.1000	0.1720	327.
MODEL 94	16.2 CON	FIG. 2:450		ACH 3.00		PHI =	45.	
Q= 6.37	PSI RE PER	IN.= .48E0	6 TO=	90. DE	G.F	601\b.	rs =	•
PO= 193	O CHHG PTS=	1.0109 PŞI			RIJN NO.	01203	69122	
ALPHA C	K CH	CS	EY	CR	CAT.	CPB	CAF	RUN
4.07 0.41	l67. −3 - 6308	-0-0132	0.1054	0.0043	Ď-2981	0.3306	A 1975	330.
	NTE _2 4702			0.0073	0 4 2 7 0 1	0. 1100	O + 10 + 2	
3.07 0.30	312 -5+01A3	-0.0136		0.0042				330.
		-0.0136 -0.0108	0.1105		0.2950	0.1101	0.1849	330. 330.
3.07 0.30	23 -1.7521		0.1105 0.0845	0.0042	0.2950 0.2946	0.1101 0.1097	0.1849 0.1849	
3.07 0.30 2.03 0.20)23 -1.7521 150 -1.2543	-0.0108	0.1105 0.0845 0.0971 0.0725	0.0042 0.0037 0.0040 0.0043	0.2950 0.2946 0.2920 0.2943	0.1101 0.1097 0.1094 0.1094	0.1849 0.1849 0.1825 0.1849	330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14	023 -1.7521 650 -1.2543 661 -0.8309	-0.0108 -0.0119	0.1105 0.0845 0.0971 0.0725 0.0775	0.0042 0.0037 0.0040 0.0043 0.0047	0.2950 0.2946 0.2920 0.2943 0.2941	0.1101 0.1097 0.1094 0.1094 0.1096	0.1849 0.1849 0.1825 0.1849 0.1845	330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09	023 -1.7521 650 -1.2543 661 -0.8369 642 -0.3798 018 0.0138	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043	0.2950 0.2946 0.2920 0.2943 0.2941 0.2922	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826	330. 330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09 0.48 0.04 -0.03 -0.00 -0.54 -0.09	023 -1.7521 650 -1.2543 661 -0.8309 642 -0.3798 013 0.0138 600 0.4319	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807 0.0522	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043 0.0046	0.2950 0.2946 0.2920 0.2943 0.2941 0.2922 0.2927	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096 0.1093	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826 0.1834	330. 330. 330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09 0.48 0.04 -0.03 -0.00	023 -1.7521 650 -1.2543 661 -0.8309 642 -0.3798 013 0.0138 600 0.4319 001 0.8657	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102 -0.0070 -0.0069	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807 0.0522 0.0516	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043 0.0046 0.0050	0.2950 0.2946 0.2920 0.2943 0.2941 0.2922 0.2927 0.2907	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096 0.1093 0.1089	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826 0.1834	330. 330. 330. 330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09 0.48 0.04 -0.03 -0.00 -0.54 -0.09 -1.05 -0.10 -1.56 -0.19	023 -1.7521 650 -1.2543 661 -0.8309 642 -0.3798 013 0.0138 600 0.4319 001 0.8657 1.3070	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102 -0.0070 -0.0069 -0.0058	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807 0.0522 0.0516 0.0394	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043 0.0050 0.0050	0.2950 0.2946 0.2930 0.2943 0.2941 0.2922 0.2927 0.2907	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096 0.1093 0.1089 0.1087	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826 0.1834 0.1818	330. 330. 330. 330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09 0.48 0.04 -0.03 -0.00 -0.54 -0.09 -1.05 -0.10 -1.56 -0.19	023 -1.7521 650 -1.2543 661 -0.8309 642 -0.3798 013 0.0138 500 0.4319 001 0.8657 511 1.3070 1.7322	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102 -0.0070 -0.0069 -0.0058 -0.0058	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807 0.0522 0.0516 0.0394 0.0430	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043 0.0046 0.0050 0.0053 0.0049	0.2950 0.2946 0.2920 0.2943 0.2941 0.2922 0.2927 0.2907 0.2905 0.2877	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096 0.1093 0.1089 0.1087 0.1086	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826 0.1834 0.1818 0.1818	330. 330. 330. 330. 330. 330. 330.
3.07 0.30 2.03 0.20 1.50 0.14 3.01 0.09 0.48 0.04 -0.03 -0.00 -0.54 -0.09 -1.05 -0.10 -1.56 -0.19	023 -1.7521 050 -1.2543 061 -0.8309 042 -0.3798 013 0.0138 0500 0.4319 001 0.8657 011 1.3070 099 1.7322 035 2.6385	-0.0108 -0.0119 -0.0094 -0.0098 -0.0102 -0.0070 -0.0069 -0.0058	0.1105 0.0845 0.0971 0.0725 0.0775 0.0807 0.0522 0.0516 0.0394 0.0430	0.0042 0.0037 0.0040 0.0043 0.0047 0.0043 0.0050 0.0050 0.0053 0.0049	0.2950 0.2946 0.2920 0.2943 0.2941 0.2922 0.2927 0.2907 0.2905 0.2877 0.2906	0.1101 0.1097 0.1094 0.1094 0.1096 0.1096 0.1093 0.1089 0.1087 0.1088	0.1849 0.1849 0.1825 0.1849 0.1845 0.1826 0.1834 0.1818 0.1818 0.1790 0.1818	330. 330. 330. 330. 330. 330.

P	1008	L 946.2	2	CONI	FIG.	2.450	K	ACH 3.0	ο,	PHI =	45.		
C	i= 6	5.37 PS	R	E PER	IN.=	-48E9	5 TO≈	90. Di	EG•F	P01/P	TS =	10.	
٤	-0=	193.0	MHG	PTS=	1.01	09 PSI			RUN NO	. 01203	69123		
ALPH	Ai	CN	(CM-	C	S	CY	CR	CAT	СРВ	CAF		RUN
4.0		0.4086		-5889					0.2986				331.
3.0	15	0.3015		.6477					0.2981				331.
2.0		0.1951		.7173					0-2977				331.
1.5		0.1335	_	.1793					0.2960				331.
		0.0868		.7740					0.2940				331.
0.4	_		-	.3292					0.2937				331.
		0.0102		.0651					0.2952				331.
		0.0578		4755					0.2949				331.
		-0.1085		.9153					0.2921				331.
		-0.1595		.3567					0.2867				331.
		-0.2113		-8093					0.2900				331.
	-	-0.3077	_	-6428					0.2928				331.
-4.1	.0 -	-0.4186	3.	.6126	-0.00	J20 -	-0.0129	0.0025	0.2907	0.1094	C-18L	3	331.
24	1008	L 946.2	:	CONI	ig.	2.450	M	ACH 3.00	0	PHI =	45.		
ç)= 6	5:37 PS	R	E PER	IN.=	-48E0	5 TO=	90• ĎI	EG.F	POJ/P	rs =	2Õ.	
F	-0=	193.0	MHG	PTS=	1.010	D9 PSI			RUN NO.	01203	69124		
ALPH	ĮA	CN	-	CM	C	S	CY	CR	CAT	CP8	CAF		RUN
4.0	16	0.4051	-3	.5823	-0.02	249	0.1679	0.0075	0.3044	0.1100	0.194	4	332.
3.0		0.2962		.6218					0.3022				332.
2.0		0.1894		.6871					0.3008				332.
1.5		0.1291	_	.1579			0.1699	0.0052	0.3008	0.1091	0.191	7	332.
0.9		0.0811		.7441					0.2997				332.
0.4		0.0316		.3133					0.2986				332.
		-0-0174		.1123					0,3001				332.
	-	-0.0627	-	.4968					0.2989				332.
_		-0.1133		.9375					0.2978				332.
		0.1619		.3545					0.2958				332.
		-0.2113		.7809					0.2947				332 •
-3.0	8 -	0.3099	2	.6329	-0.0	132	0.0690	0.0021	0.2960	0.1088	0.187	2	332.
		-0.4213	3	.6079	-0.00	080	0.0223	0.0004	0.2946	0-1095	0.185	2	332.

MODEL 946.2	CONF	IG. 2.450	HA	Cir 3*00	PHI =	45.	
Q= 6.37 PS1	RE PER	IN.= .48E0	5 TO=	90. DEG.F	79/209	S = 40.	
PO= 193.0 CF	HG PTS=	1.0109 PSI		RUN NO.	012036	9125	
ALPHA CN	СН	cs	CY	CR CAT	СРВ	CAF	RUN
4.05 0.3948	-3.5258	- · ·		0.0114 0.3063			333.
3.04 0.2852	-2.5587			0.0109 0.3058			333.
2.02 ().1778	-1.6185			C. CO85 0.3070			333.
1.50 0.1195	-1.1088 -0.7137			0.0069 0.3034 0.0065 0.3022			333. 333.
0.47 0.0168	-0.2109			0.0050 0.3022			333°
-0.03 -0.0270	0.1595			0.0046 0.3010			333.
-0.55 -0.0781		-0.0295		0.0042 0.2999			333.
-1.06 -0.1282	1.0347			0.0034 0.3005			333.
-1.57 -0.1752	1.4353			0.0027 0.3003			333.
-2.07 -0.2216	1.8315	-0.0262		0.0019 0.2991			333.
-3.09 -0.3214	2.6916	-0.0251	0.1380		0.1087		333.
-4.11 -0.4288	3.6241	-0.0191	0.0827-	0.0012 0.2956	0-1096	0-1860	333.
HODEL 946.2		IG. 2.450		CH 3.00	PHI =		
MODEL 946.2 Q= 6.37 PSI		IG. 2.450 IN.= .48E0		CH 3.00 90. DEG.F		45. 'S = £00.	
	RE PER	IN.= .48E0	6 TO=	90. DEG.F		'S = 100.	
Q= 6.37 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	P0J/PT	'S = 100.	RÚN
Q= 6.37 PS1 PO= 193.0 CA ALPHA CN	RE PER	IN.= .48E0 1.0109 PSI CS	6 TO=	90. DEG.F RUN ND.	POJ/PT . 012036 . CPB	S = £00. 9126 CAF	RÚN 334•
Q= 6.37 PS1 PO= 193.0 CF	RE PER MHG PTS=	IN.= .48E0 1.0109 PSI CS -0.0896	6 TO= CY 0.6144	90. DEG.F RUN NO. CR CAT	POJ/PT . 012036 . CPB 0.1082	S = £00. 9126 CAF 0.2002	
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752	CY 0.6144 0.5408 0.4806	90. DEG.F RUN ND. CR CAT 0.0194 0.3065 0.0162 0.3060 0.0116 0.3037	POJ/PT . 012036 . CPB 0.1082 0.1076 0.1077	S = k00. 9126 CAF 0.2002 0.1984 0.1960	334. 334. 334.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751	CY 0.6144 0.5408 0.4806 0.4828	90. DEG.F RUN ND. CR CAT 0.0194 0.3085 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045	POJ/PT . 012036 CPB 0.1082 0.1076 0.1077 0.1080	S = k00. 9126 CAF 0.2002 0.1984 0.1960 0.1966	334. 334. 334. 334.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269	RE PER CM -3.2869 -2.2942 -1.3469 -0.8224 -0.3879	IN.= .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725	CY 0.6144 0.5408 0.4806 0.4828 0.4594	90. DEG.F RUN NO. CR CAT 0.0194 0.3085 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025	POJ/PT . 012036 . CPB 0.1082 0.1076 0.1077 0.1080 0.1082	S = k00. 9126 CAF 0.2002 0.1984 0.1960 0.1966 0.1943	334. 334. 334. 334.
Q= 6.37 PSI PO= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229	RE PER CM -3.2869 -2.2942 -1.3469 -0.8224 -0.3879 -0.0419	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502	90. DEG.F RUN NO. CR CAT 0.0194 0.3085 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0058 0.3005	POJ/PT . 012036 . CP8 0.1082 0.1076 0.1077 0.1080 0.1082 0.1085	S = k00. 9126 CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920	334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224 -0.3879 -0.419 0.4520	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715 -0.0724	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502 0.4624	90. DEG.F RUN NO. CR CAT 0.0194 0.3085 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0058 0.3005 0.0047 0.3012	POJ/PT . 012036 . CP8 0.1082 0.1076 0.1077 0.1080 0.1082 0.1085 0.1085	S = 100. 9126 CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920 0.1927	334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707 -0.57 -0.1165	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224 -0.3879 -0.4520 0.8419	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715 -0.0724 -0.0694	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502 0.4624 0.4352	90. DEG.F RUN NO. CR CAT 0.0194 0.3065 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0088 0.3005 0.0047 0.3012 0.0039 0.3001	POJ/PT . 012036 . CPB 0.1082 0.1076 0.1077 0.1080 0.1082 0.1085 0.1085 0.1087	CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920 0.1927 0.1914	334. 334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707 -0.57 -0.1165 -1.08 -0.1663	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224 -0.8279 C.0419 0.4520 0.8419 1.2676	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715 -0.0724 -0.0696	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502 0.4624 0.4352 0.4398	90. DEG.F RUN NO. CR CAT 0.0194 0.3065 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0088 0.3005 0.0047 0.3012 0.0039 0.3001 0.0021 0.3008	POJ/PT . 012036 . CPB 0.1082 0.1076 0.1077 0.1080 0.1085 0.1085 0.1087 0.1085	CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920 0.1927 0.1914 0.1923	334. 334. 334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707 -0.57 -0.1165 -1.08 -0.1663 -1.60 -0.2152	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224 -0.8224 -0.8224 0.4520 0.8419 1.2676 1.6855	IN.= .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0724 -0.0694 -0.0696 -0.0683	CY 0.6144 0.5408 0.4806 0.4828 0.4502 0.4502 0.4624 0.4352 0.4398 0.4277	90. DEG.F RUN NO. CR CAT 0.0194 0.3065 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0081 0.3005 0.0047 0.3012 0.0039 0.3001 0.0021 0.3008 0.0050 0.301*	POJ/PT . 012036 . CPB 0.1082 0.1076 0.1077 0.1080 0.1085 0.1085 0.1087 0.1085 0.1085	CAF 0.2002 0.1984 0.1960 0.1966 0.1920 0.1927 0.1914 0.1923 0.1933	334. 334. 334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707 -0.57 -0.1165 -1.08 -0.1663 -1.60 -0.2152 -2.09 -0.2587	RE PER CH -3.2869 -2.2942 -1.3469 -0.8224 -0.3879 0.4520 0.8419 1.2676 1.6855 2.0529	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715 -0.0724 -0.0696 -0.0696 -0.0683 -0.0674	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502 0.4624 0.4352 0.4358 0.4277 0.4209-	90. DEG.F RUN ND. CR CAT 0.0194 0.3085 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0081 0.3025 0.0047 0.3012 0.0039 0.3001 0.0021 0.3008 0.0005 0.301* 0.0002 0.2994	POJ/PT - 012036 - CPB - 0.1082 - 0.1077 - 0.1080 - 0.1085 - 0.1085 - 0.1085 - 0.1085 - 0.1085 - 0.1085 - 0.1085 - 0.1085	S = 100. 9126 CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920 0.1927 0.1914 0.1923 0.1923 0.1933 0.1913	334. 334. 334. 334. 334. 334. 334. 334.
Q= 6.37 PSI P0= 193.0 CP ALPHA CN 4.02 0.3566 3.02 0.2449 2.00 0.1370 1.47 0.0771 0.95 0.0269 0.45 -0.0229 -0.06 -0.0707 -0.57 -0.1165 -1.08 -0.1663 -1.60 -0.2152	RE PER HG PTS= CM -3.2869 -2.2942 -1.3469 -0.8224 -0.3879 C.0419 0.4520 0.8419 1.2676 1.6855 2.0529 2.8880	IN = .48E0 1.0109 PSI CS -0.0896 -0.0817 -0.0752 -0.0751 -0.0725 -0.0715 -0.0724 -0.0696 -0.0696 -0.0683 -0.0674	CY 0.6144 0.5408 0.4806 0.4828 0.4594 0.4502 0.4624 0.4352 0.4352 0.4377 0.4209- 0.4156-	90. DEG.F RUN NO. CR CAT 0.0194 0.3065 0.0162 0.3060 0.0116 0.3037 0.0092 0.3045 0.0081 0.3025 0.0081 0.3025 0.0080 0.3006 0.0047 0.3012 0.0039 0.3001 0.0021 0.3008 0.0005 0.301*	POJ/PT . 012036 CPB 0.1082 0.1076 0.1077 0.1080 0.1085 0.1085 0.1087 0.1086 0.1082 0.1081 0.1080	S = k00. 9126 CAF 0.2002 0.1984 0.1960 0.1966 0.1943 0.1920 0.1927 0.1914 0.1923 0.1933 0.1913 0.1902	334. 334. 334. 334. 334. 334. 334.

	DEL 946.2	CON	FIG. 2.450	H	ACH 3-00	PHI =	90.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PT	'S = •	
20	= 193.0 CM	HG PTS=	1.0109 PSI		RUN NO	. 012036	9127	
ALPHA	CN	CM	CS	CY	CR CAT	CP8	CAF	RUN
4.07	0.4150	-3.5979	-0.0092	0.0786	0.0063 0.3020	0-1111	0.1909	335.
3.06	0.3085	-2.6686	-0.0084	0.0740	0.0062 0.3007	0.1101	0.1906	335.
2.04	0.2043	-1.7657	-0.0067		0.0064 0.2943			335.
1-51			-0.0073		0.0057 0.2998			335.
1.00			-0.0043		0.0069 0.3000			335.
0.49			-0.0039		0.0067 0.2978			335.
	-0.0009		-0.0111		0.0065 0.3008			335.
	-0-0508		-0,0065		0.0066 0.2967			335.
	-0.1015		-0.0086		0.0060 0.2962			335.
	-0.1513		-0.0082		0.0065 0.2947			335.
	-0-1997		-0.0052		0.0070 0.2950			335.
	-0.3053		-0.0010		0.0065 0.2928			335.
-4.09	-0-4154	3.8010	0.0048	-0.0434	0.0070 0.2966	0-1111	0.1822	335.
HO	DEL 946.2	CON	FIG. 2.450		NCU 2 00	0217		
	JCE 71002	CUM	-10. 2.430	m/	ACH 3.00	SHI =	90.	
Q=	6.37 PSI		IN.= .48E0		90. DEG.F	POJ/PT		
-	6.37 PSI	RE PER	•	6 TO=	90. DEG.F		'S = 10.	
-	6.37 PSI = 193.0 CM	RE PER	IN.= .48E0	6 TO=	90. DEG.F	POJ/PT	'S = 10.	RUN
PO ALPHA	6.37 PSI = 193.0 CM	RE PER HG PYS=	IN.= .48E0 1.9109 PSI CS	6 TO=	90. DEG.F RUN NO CR CAT	POJ/PT • 012036 CPB	S = 10. 9128 CAF	RUN
PO	6.37 PSI = 193.0 CM CN 0.4114	RE PER HG PYS= _CM- _3.5582	IN.= .48E0	6 TO= CY 0.1133	90. DEG.F RUN NO CR CAT 0.0079 U.3042	POJ/PT - 012036 - CPB - 0-1108	S = 10. 9128 CAF 0.1934	RUN 336.
PO ALPHA 4.07	6.37 PSI = 193.0 CM CN 0.4114 0.3040	RE PER HG PYS= CM- -3.5582 -2.6297	IN.= .48E0 1.9109 PSI CS ~0.0170	6 TO= CY 0.1133 0.1097	90. DEG.F RUN NO CR CAT	POJ/PT • 012036 CPB 0•1108 0•1100	S = 10. 9128 CAF 0.1934 0.1937	RUN
PO ALPHA 4.07 3.07	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993	RE PER HG PYS= CM- -3.5582 -2.6297 -1.7216	IN.= .48E0 1.9109 PSI CS -0.0170 -0.0163	CY 0.1133 0.1097 0.0862	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089	S = 10. 9128 CAF 0.1934 0.1937 0.1911	RUN 336. 336.
PO ALPHA 4.07 3.07 2.04	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426	RE PER HG PTS= CM- -3.5582 -2.6297 -1.7216 -1.2325	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0138	CY 0.1133 0.1097 0.0862 0.0785	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089 0.1088	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905	RUN 336. 336. 336.
PO ALPHA 4.07 3.07 2.04	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919	RE PER HG PTS= CM- -3.5582 -2.6297 -1.7216 -1.2325 -0.7944	IN.= .48E0 1.0109 PSI CS ~0.0170 ~0.0163 ~0.0138 ~0.0126	CY 0.1133 0.1097 0.0862 0.0785 0.0581	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993	POJ/PT . 012036 CPB 0.1108 0.1109 0.1088 0.1091	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1905	RUN 336. 336. 336.
PO ALPHA 4.07 3.07 2.04 1.52 1.00 0.50	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919	RE PER HG PTS= CM3.5582 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0138 -0.0126 -0.0105	CY 0.1133 0.1097 0.0862 0.0785 0.0581 0.1412	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089 0.1088 0.1091 0.1093	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1905 0.1933	RUN 336. 336. 336. 336.
PO ALPHA 4.07 3.07 2.04 1.52 1.50 0.50 -0.02	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919 0.0430 -0.0063 -0.0571	RE PER HG PYS= CM- -3.5582 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733 0.0516	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0138 -0.0126 -0.0105 -0.0186	CY 0.1133 0.1097 0.0862 0.0785 0.0581 0.1412 0.1344	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996 0.0063 0.3026	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089 0.1091 0.1093 0.1092	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1905 0.1903 0.1886	RUN 336. 336. 336. 336. 336.
PO ALPHA 4.07 3.07 2.04 1.52 1.00 0.50 -0.02 -0.54 -1.04	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919 0.0430 -0.0063 -0.0571 -0.1064	RE PER HG PTS= CM -3.5682 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733 0.0516 0.4910 0.9159	IN.= .48E0 1.0109 PSI CS ~0.0170 ~0.0163 ~0.0126 ~0.0126 ~0.0105 ~0.0186 ~0.0190 ~0.0093 ~0.0157	CY 0.1133 0.1097 0.0862 0.0785 0.0581 0.1412 0.1344 0.0472	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996 0.0063 0.3026 0.0054 0.2978	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089 0.1088 0.1091 C.1093 0.1092 0.1091	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1905 0.1933 0.1886 0.1888	RUN 336. 336. 336. 336. 336. 336.
PO ALPHA 4.07 3.07 2.04 1.52 1.00 0.50 -0.02 -0.54 -1.04	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919 0.0430 -0.0063 -0.0571	RE PER HG PYS= CM3.5682 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733 0.0516 0.4910 0.9159 1.3634	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0138 -0.0126 -0.0105 -0.0186 -0.0190 -0.0093 -0.0136	CY 0.1133 0.1097 0.0862 0.0788 0.0788 0.1412 0.1344 0.0472 0.111(0.0908	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996 0.0063 0.3026 0.0054 0.2978 0.0059 0.2978 0.0059 0.2979 0.0069 0.3001 0.0050 0.2968	POJ/PT . 012036 CPB 0.1108 0.1100 0.1089 0.1088 0.1091 0.1093 0.1092 0.1091 0.1087 0.1084	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1933 0.1886 0.1888 0.1914 0.1884	RUN 336. 336. 336. 336. 336. 336. 336.
PO ALPHA 4.07 3.07 2.04 1.52 1.00 0.50 -0.02 -0.54 -1.04 -1.55 -2.06	6.37 PSI = 193.0 CM	RE PER HG PYS= CM3.5582 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733 0.0516 0.4910 0.9159 1.3634 1.7763	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0126 -0.0126 -0.0105 -0.0186 -0.0190 -0.0093 -0.0157 -0.0136 -0.0123	CY 0.1133 0.1097 0.0862 0.0785 0.0581 0.1412 0.1444 0.0472 0.111(0.0908 0.0787	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996 0.0063 0.3026 0.0054 0.2978 0.0059 0.2979 0.0049 0.3001 0.0050 0.2968 0.0056 0.2963	POJ/PT - 012036 CPB 0.1108 0.1100 0.1089 0.1088 0.1091 0.1092 0.1092 0.1091 0.1087 0.1084 0.1085	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1933 0.1886 0.1888 0.1914 0.1884 0.1878	RUN 336. 336. 336. 336. 336. 336. 336. 336
PO ALPHA 4.07 3.07 2.04 1.52 1.00 0.50 -0.02 -0.54 -1.04 -1.55 -2.06 -3.07	6.37 PSI = 193.0 CM CN 0.4114 0.3040 0.1993 0.1426 0.0919 0.0430 -0.0063 -0.0571 -0.1064 -0.1581	RE PER HG PYS= CM3.5582 -2.6297 -1.7216 -1.2325 -0.7944 -0.3733 0.0516 0.4910 0.4910 0.4910 1.3634 1.7763 2.6730	IN.= .48E0 1.0109 PSI CS -0.0170 -0.0163 -0.0138 -0.0126 -0.0105 -0.0186 -0.0190 -0.0093 -0.0136	CY 0.1133 0.1097 0.0862 0.0785 0.0581 6.1412 0.1344 0.0472 0.1116 0.0908 0.0787 0.0721	90. DEG.F RUN NO CR CAT 0.0079 0.3042 0.0077 0.3037 0.0072 0.2999 0.0065 0.2993 0.0062 0.2996 0.0063 0.3026 0.0054 0.2978 0.0059 0.2978 0.0059 0.2979 0.0069 0.3001 0.0050 0.2968	POJ/PT - 012036 CPB 0.1108 0.1100 0.1089 0.1088 0.1091 0.1092 0.1091 0.1087 0.1085 0.1091	S = 10. 9128 CAF 0.1934 0.1937 0.1911 0.1905 0.1933 0.1886 0.1888 0.1888 0.1895	RUN 336. 336. 336. 336. 336. 336. 336.

				•			
MOD	EL 946.2	COM	FIG. 2.450	H	ACH 3.00	PHI =	90.
Q=	6.37 PSI	RE PER	IN.= .48E0	6 T0=	90. DES.F	POJ/PTS	z 20 ₀
₽0≂	: 193.0 CM	NG PTS=	1.0109 PSI		RUN NO	0. 01203691	29
AILPHA	CN	CM	cs	CY	CR CAT	CPS C	AF RUN
4.08	0.4138	-3.5870	-0.0214	0.1193	0.9106 0.3048	0.1107 0.	1938 337.
3.06	0.3046	-2.6304	-0.0225	0.1322	0.0097 0.3042	2 0.1100 0.	1542 337.
2.04	0.1991		-0.0217	0.1295	0.0084 0.3012	2 0.1092 0.	1920 337.
1.52	0.1446		-0.0222	0.1355	0.0077 0.3024	0.1094 0.	1930 337.
1.01	0.0939	-0.8123	-0.0192	0.1073	0.0067 0.2992	2 0.1094 0.	1.897 337.
	0.0436		-0:0247		0.0065 0.3013		
	-0.0057	0.0458	-0.0209	0.1249	G.0055 0.2999	0.1095 0.	1904 337.
	-0.0560		-0.0248		U. 0056 0.3003		
	-0.1072		-0-0295	0.2104	0.0050 0.300	0.1091 P.	1916 337.
	-0.1589		-0.0257	0.1709	0.0044 0.300	0.1089 0.	1911 337.
	-0.2041		-0.0235		0.0042 0.3004		
	-0.3102	2.6712	-0.0237	0.1478	0.0018 0.3009	0.1093 0.	1917 337.
	-0.4222		-0.0197		0.0016 0.3004		
HOO)EL 946.2	CONI	FIG. 2.450). M :	ACH 3-00	PHI =	90.
	0EL 946.2 6.37 PSI		FIG. 2.450 IN.= .48E0		ACH 3.00 90. DEG.F	PHI = POJ/PTS	•
Q=	6.37 PSI	RE PER		ė T0=	90. DEG.F	-	= 40.
Q=	6.37 PSI = 193.0 CK	RE PER	IN.= .48E0	ė T0=	90. DEG.F	POJ/PTS	= 40.
Q= PC=	6.37 PSI = 193.0 CK CN	RE PER HG PTS=	IN.= .48E0	6 TO=	90. DEG.F	POJ/PTS 0. 012036#1 CPB C	= 40. 30 ** AF RUN
Q= PG= ALPHA	6.37 PSI = 193.0 CK CN 0.4119	RE PER HG PTS= CH -3.5690	IN.= .48E0 1.0109 PSI	CY 0.1838	90. DEG.F RUN NI CK CAT	POJ/PTS 0. 012036%1 CPB C 0.1108 0.	= 40. 30 AF RUŅ 1973 338.
Q= PC= ALPHA 4,08	6.37 PSI = 193.0 CK CN 0.4119 0.3031	RE PER HG PTS= CH -3.5690 -2.6984	IN.= .48E0 1.0109 PSI CS -0.0354	CY 0.1838 0.1974 0.2348	90. DEG.F RUN NO CK CAT 0.0142 0.308 0.0132 0.305 0.0116 0.302	POJ/PTS 1. 012036%1 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338.
Q= PG= ALPHA 4.08 3.06	6.37 PSI = 193.0 CM CN 0.4119 0.3031 0.1989	RE PER SHG PTS= CH -3.5690 -2.6984 -1.7075	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364	CY 0.1838 0.1974 0.2348	90. DEG.F RUN NO Ck CAT 0.0142 0.308 0.0132 0.305	POJ/PTS 1. 012036%1 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338.
Q= PG= ALPHA 4.08 3.06 2.04	6.37 PSI = 193.0 CM CN 0.4119 0.3031 0.1989	RE PER HG PTS= CH -3.5690 -2.6984 -1.7075 -1.2124	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399	CY 0.1838 0.1974 0.2348 0.2706	90. DEG.F RUN NO CK CAT 0.0142 0.308 0.0132 0.305 0.0116 0.302	POJ/PTS 1. 012036#1 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0. 5 0.1092 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956	RE PER CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430	CY 0.1838 0.1974 0.2348 0.2706 0.2339	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020	POJ/PTS 1. 012036#1 CPB C 0.1108 0. 0.1101 0. 2.0.1094 0. 5.0.1092 0. 6.0.1093 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956	RE PER SHG PTS= CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239	90. DEG.F RUN NO Ck CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0084 0.3030 0.0074 0.3014 0.0061 0.3020	POJ/PTS - 012036#1 CPB C - 0.1108 0 0.1101 0 0.1094 0 0.1093 0 0.1093 0 0.1093 0 0.1093 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1934 338. 1934 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 ~0.03	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458	RE PER CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497	IN-= .48E0 1.0109 PSI C5 -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0064 0.3030 0.0074 0.3014 0.0061 0.3020 0.0055 0.3000	POJ/PTS 0. 012036#1 CPB C 0.1108 0. 0.1101 0. 2. 0.1094 0. 5. 0.1092 0. 6. 0.1093 0. 6. 0.1093 0. 6. 0.1095 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1934 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 -0.03 -0.52	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458 -0.0059	RE PER CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497 0.4532	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404 -0.0383	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382 0.2577	90. DEG.F RUN NO CK CAT 0.0142 0.3086 0.0132 0.3056 0.0116 0.3026 0.0090 0.3026 0.0064 0.3036 0.0074 0.3016 0.0061 0.3026 0.0055 0.300	POJ/PTS 0. 012036#1 CPB C 0.1108 0. 0.1101 0. 2.0.1094 0. 5.0.1092 0. 6.0.1093 0. 6.0.1092 0. 6.0.1093 0. 7.0.1093 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1934 338. 1934 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 -0.03 -0.52 -1.04	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458 -0.0059 -0.0529	RE PER CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497 0.4532 0.9108	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404 -0.0383 -0.0396	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382 0.2577 0.2453	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0061 0.3020 0.0061 0.3020 0.0061 0.3020 0.0055 0.3000 0.0041 0.3000 0.0027 0.3000	POJ/PTS 0. 012036#1 CPB C 0.1108 0. 0.1101 0. 2.0.1094 0. 5.0.1092 0. 6.0.1093 0. 6.0.1093 0. 6.0.1093 0. 7.0.1093 0. 7.0.1093 0. 1.0.1091 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1921 338. 1934 338. 1934 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 -0.03 -0.52 -1.04 -1.55	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458 -0.0059 -0.0529 40.1060	RE PER CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497 0.4532 0.9108 1.3480	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404 -0.0383 -0.0396 -0.0418	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382 0.2577 0.2453 0.2477	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0064 0.3030 0.0055 0.3000 0.0041 0.3000 0.0027 0.3000 0.0017 0.301	POJ/PTS 1. 01203691 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0. 5 0.1092 0. 6 0.1093 0. 6 0.1092 0. 3 0.1095 0. 7 0.1093 0. 1 0.1091 0. 3 0.1091 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1934 338. 1914 338. 1914 338. 1910 338. 1910 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 ~0.03 -0.52 -1.04 -1.55 -2.06	6.37 PSI = 193.0 CK CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458 -0.0059 -0.0529 40.1060 -0.1572	RE PER HG PTS= CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497 0.4532 0.9108 1.3480 1.7608 2.6637	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404 -0.0383 -0.0418 -0.0405 -0.0410 -0.0394	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382 0.2577 0.2453 0.2477	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0064 0.3030 0.0074 0.3010 0.0055 0.3000 0.0041 0.3000 0.0027 0.3000 0.0017 0.3011 0.0001 0.3011	POJ/PTS 1. 01203691 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0. 5 0.1092 0. 6 0.1093 0. 6 0.1095 0. 7 0.1091 0. 3 0.1091 0. 0 0.1095 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1934 338. 1908 336. 1910 338. 1910 338. 1910 338.
Q= PG= ALPHA 4.08 3.06 2.04 1.51 1.01 0.50 -0.03 -0.52 -1.04 -1.55 -2.06 -3.07	6.37 PSI = 193.0 CM CN 0.4119 0.3031 0.1989 0.1413 0.0956 0.0458 -0.0059 -0.0529 -0.11060 -0.1572 -0.2052	RE PER HG PTS= CH -3.5690 -2.6984 -1.7075 -1.2124 -0.8216 -0.3937 0.0497 0.4532 0.9108 1.3480 1.7608 2.6637	IN.= .48E0 1.0109 PSI CS -0.0354 -0.0364 -0.0399 -0.0430 -0.0391 -0.0404 -0.0383 -0.0396 -0.0418 -0.0405 -0.0410	CY 0.1838 0.1974 0.2348 0.2706 0.2339 0.2462 0.2239 0.2382 0.2577 0.2453 0.2477	90. DEG.F RUN NO CK CAT 0.0142 0.3080 0.0132 0.3050 0.0116 0.3020 0.0090 0.3020 0.0064 0.3030 0.0055 0.3000 0.0041 0.3000 0.0027 0.3000 0.0017 0.301	POJ/PTS 1. 01203691 CPB C 0 0.1108 0. 0 0.1101 0. 2 0.1094 0. 5 0.1092 0. 6 0.1093 0. 6 0.1095 0. 7 0.1091 0. 3 0.1091 0. 0 0.1095 0.	= 40. 30 AF RUN 1973 338. 1949 338. 1928 338. 1934 338. 1944 338. 1921 338. 1934 338. 1908 336. 1910 338. 1910 338. 1910 338.

KOD	EL 946.2	CONF	IG. 2.450	H.	ACH 3.00)	PHI =	90.	
Q=	6.37 P3I	RE PER	IN.= .48E0	6 T0=	90° DE	G.F	P0J/P	TS = 100	٠.
P0=	193.0 CF	HG PTS=	1.0109 PSI		•	RUN NO.	01203	69131	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.08	0.4111	_2 6356	-0.0883	0 4001	0.0218	0.2051	n inge	0.1983	339.
3.06	0.2996	-2.5615			0.0212				339.
2.04	0.1964	-1.6748			0-0165				339.
1.52	0.1410	-1.2018			0.0132				339.
1.00	0.0998	-0.7738			0.0103				339.
0.49		-0.3536			0.0078				339.
	-0,0066		-0.1030		0.0065				339.
	-0-0551		-0.1068		0.0044				339.
	-0.1059		-0.1005	0.6464	0.0027	0.2965	0.1038	0.1877	339.
-	-0.1562		-0.0993	0.6274	-0.0002	0.3004	0.1085	0.1919	339.
-2.06	-0.2029	1.7259	-0.0964	0.5953	-0.0030	0.3015	0.1083	0.1932	339.
-3.08	-0.3063	2.6095	-0.0914	0.5389	-0.0076	0.3004	0.1089	0.1915	339.
-4.10	-0.4/196	3.5983	-0.0866	0.4899	-0,0100	0.3018	0.1111	0.1906	339.
	EL 946.2 6.37 PSI		Tig. 2.000		ACH 3.00		PHI =	• TS =	•
-					90. U				•
PQ=	193.0 CI	HG PTS=	1.0109 PSI			RUN NO.	. 01203	69132	
ALPHA	CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
10.27	1.3546	-11.9487	-0.0136	0.1027	0.0067	0.3040	0.1194	0-1845	340.
9.24	1.1703	-10.3132	-0.0004	0.0633	0.0063	0.3074	0.1201	0.1873	340.
8.20	0.9872	-8.6731	-0.0123	0.0918	0.0067	0.3047	0.1192	0.1855	340.
7.16	0.8252	-7.2263	-0.0097	0.0698	0.0060	0.2978	0.1157	0.1821	340.
6.13	0.6760	-5.9039	0.0082	0.0572	0.0064	0.2933	0.1122	0.1811	340.
5.10	0.5447	-4.7466	-0.0072		0.0061				340.
4.08	0.4223		-0.0073		0.0062				340.
3.05	0.3101	-2.6876	-0.0060		0.0066				340.
2.93	0•20≥5		-0.0057		0.0059				340.
1.50	0.1428		-0.0072		0.0060				340.
0.99	0.0915		-0.0066		0.0064				340.
0.48	0.0429		-0.0074		0.0061				340.
	-0.0050		-0.0064		0.0058				340.
	-0.0477		-0.0063		0.0062				340.
	-0.0989		-C~0066		0.0063				340.
	-0.1459		-0.0064		0.9064				340.
	-0.2021		-0.0063		0.0071				340 •
	-0.2500		-0.0047		0.0068				340.
	-0.3038		-0.0037		0.0072				340.
	-0.3626		~0.0036 -0.0036		0.0068				340.
-4.11	-0.4189	2.04/0	-0.0034	0.0121	0.0069	0.4710	0.1048	0.1050	340.

HODEL 946.2	CONI	FIG. 2.0	00 н	СН 3.00	PHI = .	
Q= 6.37 PSI	KE PER	IÑ.≃ .481	E06 10=	90. DEG.F	E STA\LOG	10.
PO* 193.0 C	MHG PTS=	1-0109 P	SI	RUN	NO. 0120369133	
ALPHA CN	CH	cs	CY	CR CA	T CPS CAF	RUN
10-25 1-3272	-11.7154	-0.0160			154 C.1189 O.1965	
9-23 1-1497	-10-1415				195 0.1192 0.2002	
8.19 0.9674	-8.5148				081 0.1179 0.1901	
7.16 0.8113		-0.0066			063 0-1147 0-1916	
6.12 0.65 ⁷ 3 5.10 0.5341		-0.0050 -0.0049			035 0.1118 0.1917 020 0.1110 0.1910	
4.07 0.4155		-0.0041			037 0.1115 0.1922	
3.05 0.3027	-2.6628				008 0.1111 0.1897	
2.02 0.1962		-0.0025			030 0.1106 0.1924	
1.50 0.1356		-0.0036			013 0.1098 0.1915	
0.99 0.0878	-0.7959	-0.0030	0.0155	0.0038 0.2	993 0.1095 0.1898	
0.48 0.0374	~0.3550				007 0-1089 0-1918	
-0.63 -0.0095		-0-0028			977 0.1084 0.1894	
-0.54 -0.0547		-0.0031			956 0.1079-0.1877	
-1.65 -0.1026		-0.0036			961 0.1075 0.1887	
-1.57 -0.1554 -2.10 -0.2075		-0.0054			950 0.1073 0.1877	
-3.09 -0.3065		-0.0018			940 0.1073 0.1867 941 0.1074 0.1867	
-4.10 -0.4149		0.0001			919 0.1077 0.1842	
*****	303.10	0.000.	0.011,	0.0000 0.2	363 05 LOTE WEED-2	344.
MODEL 946.2	CONF	1G. 2.00	00 M	ACH 3.00	PHI = .	
MODEL 946.2 Q= 6.37 PSI		IG. 2.00		1CH 3.00 90. DEG.F		20•
	RE PÉR	[N.= -481	E06 TO=	90. DEG.F		20.
Q= 6.37 PSI	RE PÉR	[N.= -481	E06 TO=	90. DEG.F	POJ/PTS = NO. 0120369134	20 . Run
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 10.24 1.3015	RE PËR MHG PTS=	IN.= .481 1.0109 PS	E06 TO= S1 CY	90. DEG.F RUN CR CA	POJ/PTS = NO. 0120369134	•
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276	RE PER MHG PTS= CM -11.4957 -9.9580	IN.= :481 1.0109 PS CS -0.0139 -0.0129	CY 0.1064 0.1051	90. DEG.F RUN CR CA 0.0067 0.3 0.0072 0.3	POJ/PTS = NO. 0120329134 E CPB CAF 180 0.1186~0.1994 168 0.1189 0.1979	RUN 342+ 342+
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519	RE PER MHG PTS= CM -11.4957 -9.9580 -8.3967	IN-= :488 1.0109 PS CS -0.0139 -0.0129 -0.0065	CY 0.1064 0.1051 0.0462	90. DEG.F RUM CR CA 0.0067 0.3 0.0072 0.3 0.0060 0.3	POJ/PTS = NO. 0120349134 F CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 021938	RUN 342+ 342+ 342+
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958	RE PÉR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134	IN.= _488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058	CY 0.1064 0.1051 0.0462 0.0408	90. DEG.F RUW CR CA 0.0067 0.3 0.0060 0.3 0.0060 0.3 0.0057 G.3	POJ/PTS = NO. 0120369134 5	RUN 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 J.15 0.7958 6.12 0.6517	RE PÉR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410	IN-= _488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042	CY 0.1064 0.1051 0.0462 0.0468 0.0268	90. DEG.F RUN CR CA 0.0067 0.3 0.0072 0.3 0.0050 0.3 0.0057 6.3 0.0058 0.3	POJ/PTS = NO. 0120369134 T CPB CAF 180 0.1186~0.1994 168 0.1189 0.1979 113 0.1175 0.11938 078.0.1145 0.1933	RUN 342 • 342 • 342 • 342 •
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 7.15 0.7958 6-12 0.6517 5.09 0.5212	RE PER MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971	IN-= .468 1.0109 PS CS -0.0139 -0.0129 -0.0055 -0.0052 -0.0042	CY 0.1064 0.1051 0.0462 0.0408 0.0268 0.0268	90. DEG.F RUM CR CA 0.0067 0.3 0.0072 0.3 0.0057 0.3 0.0058 0.3 0.0058 0.3	POJ/PTS = NO. 0120329134 E CPB CAF 180 0.1186~0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078 0.1145 0.1932 044 0.1112 0.1932	RUN 342. 342. 342. 342. 342.
Q= 6.37 PS1 PO= 193.0 Cf ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043	RE PÊR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5782	IN-= :488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042 -0.0042	CY 0.1064 0.1051 0.0462 0.0408 0.0268 0.0268 0.0252 0.0201	90. DEG.F RUM CR CA 0.0067 0.3 0.0060 0.3 0.0057 0.3 0.0058 0.3 0.0059 0.3	POJ/PTS = NO. 0120329134 E CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 115 0.1175 0.1933 078 0.1145 0.1933 049 0.1117 0.1932 044 0.1112 0.1932 034 0.1116 0.1918	RUN 342. 342. 342. 342. 342. 342.
Q= 6.37 PS1 PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 7.15 0.7958 6-12 0.6517 5.09 0.5212	RE PÉR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096	IN.= :488 1.0109 PS CS -0.0139 -0.0129 70.0065 -0.0058 -0.0042 -0.0042 -0.0042 -0.0042	CY 0.1064 0.1051 0.0462 0.0468 0.0268 0.0262 0.0261 0.0167	90. DEG.F RUM CR CA 0.0067 0.3 0.0060 0.3 0.0057 0.3 0.0058 0.3 0.0055 0.3 0.0059 0.3	POJ/PTS = NO. 0120369134 T CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 044 0.1112 0.1932 044 0.1112 0.1932 996 0.1112 0.1884	RUN 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PS1 PO= 193.0 Cl ALPHA CN 10.24 1.3015 9.22 1.1276 B.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933	RE PÊR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5782	IN.= .468 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042 -0.0042 -0.0029 -0.0029	CY 0.1064 0.1051 0.0468 0.0268 0.0268 0.0252 0.0167 0.0113	90. DEG.F RUN CR CA 0.0067 0.3 0.0072 0.3 0.0057 0.3 0.0058 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3	POJ/PTS = NO. 0120369134 T CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 0.11938 078 0.1117 0.11932 044 0.1112 0.1932 044 0.1112 0.1932 049 0.1116 0.1184 996 0.1117 0.1884	RUN 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884	RE PÉR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096 -1.6939	IN-= :488 1.0109 PS CS -0.0139 -0.0129 -0.0055 -0.0058 -0.0042 -0.0042 -0.0029 -0.0029 -0.0029	CY 0.1064 0.1051 0.0462 0.0408 0.0262 0.0252 0.0251 0.0167 0.0113 0.0088	90. DEG.F RUM CR CA 0.0067 0.3 0.0050 0.3 0.0057 6.3 0.0055 0.3 0.0055 0.3 0.0059 0.3 0.0053 0.2 0.0057 0.2	POJ/PTS = NO. 0120369134 T CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 044 0.1112 0.1932 044 0.1112 0.1932 996 0.1112 0.1884	RUN 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 Cl ALPHA CN 10.24 1.3015 9.22 1.1276 B.18 0.9519 1.15 0.7558 G.12 0.6517 S.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.0791 0.47 0.0339	RE PÊR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5782 -2.6096 -1.6939 -1.2144	IN.= :488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042 -0.0042 -0.0042 -0.0029 -0.0020 -0.0020 -0.0014	CY 0.1064 0.1051 0.0462 0.0268 0.0252 0.02C1 0.0167 0.0113 0.0088 0.0030 0.0030	90. DEG.F RUM CR CA 0.0067 0.3 0.0072 0.3 0.0057 0.3 0.0058 0.3 0.0059 0.3 0.0059 0.3 0.0053 0.2 0.0057 0.2 0.0057 0.2 0.0057 0.2	POJ/PTS = NO. 0120369134 T CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 049 0.1112 0.1932 044 0.1112 0.1932 044 0.1112 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1100 0.1898 998 0.1087 0.1898	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.0791 0.47 0.0339 -0.04 -0.0106	RE PÉR MHG PTS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -1.6939 -1.2144 -0.7409 -0.3510 0.0265	IN.= .468 1.0109 PS CS -0.0139 -0.0129 -0.0058 -0.0058 -0.0042 -0.0042 -0.0029 -0.0029 -0.0020 -0.0013 -0.0013	CY 0.1064 0.1051 0.0462 0.0408 0.0252 0.0167 0.0113 0.0088 0.0030 0.0022 0.0045	90. DEG.F RUN CR CA 0.0067 0.3 0.0057 0.3 0.0057 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3	POJ/PTS = NO. 01203è9134 E CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 115 0.1175 0.1938 078. 0.1145 0.1933 044 0.1117 0.1932 044 0.1112 0.1932 034 0.1116 0.1938 996 0.1120 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1007 0.1886 984 0.1087 0.1886	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.0791 0.47 0.0339 -0.04 -0.0106 -0.54 -0.0668	RE PÊR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096 -1.6997 -1.2144 -0.7409 -0.3510 0.0265 0.5241	IN.= :488 1.0109 PS CS -0.0139 -0.0129 -0.0055 -0.0058 -0.0042 -0.0042 -0.0029 -0.0029 -0.0020 -0.0014 -0.0013 -0.0016 -0.0010	CY 0.1064 0.1051 0.0462 0.0408 0.0262 0.0262 0.0167 0.0113 0.0088 0.0030 0.0025 0.0025	90. DEG.F RUM CR CA 0.0067 0.3 0.0050 0.3 0.0057 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3 0.0057 0.2 0.0047 0.2 0.0047 0.2 0.0047 0.2 0.0047 0.2	POJ/PTS = NO. 01203-9134 E CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 115 0.1175 0.1933 078 0.1145 0.1933 049 0.1117 0.1932 034 0.1116 0.1918 996 0.1112 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1107 0.1888 991 0.1007 0.1888 984 0.1087 0.1888 984 0.1087 0.1888	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7558 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.0791 0.47 0.0339 -0.04 -0.0106 -0.54 ~0.0668 -1.06 ~0.1095	RE PÉR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096 -1.6939 -1.2144 -0.7409 -0.3510 0.0265 0.5241 0.8851	1.0109 PS CS -0.0139 -0.0129 -0.0055 -0.0058 -0.0042 -0.0042 -0.0029 -0.0029 -0.0020 -0.0014 -0.0013 -0.0016 -0.0010	CY 0.1064 0.1051 0.0462 0.0468 0.0252 0.0261 0.0167 0.0113 0.0088 0.0030 0.0022 0.0045 -0.0003	90. DEG.F RUM CR CA 0.0067 0.3 0.0050 0.3 0.0058 0.3 0.0058 0.3 0.0059 0.3 0.0057 0.2 0.0057 0.2 0.0047 0.2 0.0047 0.2 0.0047 0.2 0.0048 0.2 0.0048 0.2 0.0049 0.2 0.0049 0.2	POJ/PTS = NO. 01203-9134 T CPB CAF 180 0.1186 0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 044 0.1112 0.1932 044 0.1112 0.1932 049 0.1112 0.1884 991 0.1107 0.1884 991 0.1100 0.1891 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1070 0.1888	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.991 0.47 0.0339 -0.04 -0.0668 -1.06 -0.1095 -1.56 -0.1591	RE PÉR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096 -1.6939 -1.2144 -0.7409 -0.3510 0.0265 0.5241 0.8851 1.3126	1.0109 PS CS -0.0139 -0.0129 70.0065 -0.0058 -0.0042 -0.0042 -0.0029 -0.0027 -0.0021 -0.0016 -0.0010 -0.0016 -0.0010 -0.0014	CY 0.1064 0.1051 0.0462 0.0268 0.0252 0.0201 0.0167 0.0113 0.0088 0.0030 0.0030 0.0031 -0.0048	90. DEG.F RUN CR CA 0.0067 0.3 0.0072 0.3 0.0057 0.3 0.0059 0.3 0.0059 0.3 0.0053 0.2 0.0057 0.2 0.0057 0.2 0.0051 0.2 0.0051 0.2 0.0059 0.3 0.0059 0.3	POJ/PTS = NO. 01203-9134 T CPB CAF 180 0.1186-0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 049 0.1117 0.1932 044 0.1112 0.1932 044 0.1112 0.1932 049 0.1112 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1006 0.1898 984 0.1087 0.1898 984 0.1087 0.1898 983 0.1081 0.1882 943 0.1075 0.1868 943 0.1075 0.1868 943 0.1075 0.1868 943 0.1076 0.1868	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PS1 PO= 193.0 Cf ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.0791 0.47 0.0339 -0.04 -0.0106 -0.54 ~0.0668 -1.06 -0.1095 -1.56 -0.1591 -2.07 -0.2077	RE PER MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5782 -2.6096 -1.6397 -1.2144 -0.7409 -0.3510 0.0265 0.5241 0.8851 1.3126 1.7368	IN.= :488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042 -0.0029 -0.0022 -0.0029 -0.0016 -0.0016 -0.0010 -0.0016 -0.0017 -0.0007	CY 0.1064 0.1051 0.0462 0.0408 0.0263 0.0252 0.0167 0.0113 0.0088 0.0030 0.0020 0.0045 -0.0003	90. DEG.F RUM CR CA 0.0067 0.3 0.0057 0.3 0.0058 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.2 0.0057 0.2 0.0057 0.2 0.0057 0.2 0.0059 0.3	POJ/PTS = NO. 01203-9134 T CPB CAF 180 0.1186 0.1094 168 0.1189 0.1979 115 0.1175 0.1938 078 0.1145 0.1933 049 0.1117 0.1932 044 0.1112 0.1932 034 0.1116 0.1938 996 0.1112 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1007 0.1886 993 0.1081 0.1898 943 0.1087 0.1898 943 0.1087 0.1898 943 0.1087 0.1898 943 0.1087 0.1898 943 0.1085 0.1886 939 0.1075 0.1868 939 0.1075 0.1868	RUN 342. 342. 342. 342. 342. 342. 342. 342.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.24 1.3015 9.22 1.1276 8.18 0.9519 1.15 0.7958 6.12 0.6517 5.09 0.5212 4.06 0.4043 3.04 0.2933 2.02 0.1884 1.49 0.1329 0.99 0.991 0.47 0.0339 -0.04 -0.0668 -1.06 -0.1095 -1.56 -0.1591	RE PÉR MHG PYS= CM -11.4957 -9.9580 -8.3967 -7.0134 -5.7410 -4.5971 -3.5762 -2.6096 -1.6939 -1.2144 -0.7409 -0.3510 0.0265 0.5241 0.8851 1.3126	IN.= :488 1.0109 PS CS -0.0139 -0.0129 -0.0065 -0.0058 -0.0042 -0.0029 -0.0022 -0.0029 -0.0016 -0.0016 -0.0010 -0.0016 -0.0017 -0.0007	CY 0.1064 0.1051 0.0462 0.0468 0.0262 0.0267 0.0113 0.0088 0.0030 0.0022 0.0045 -0.0003 -0.0046	90. DEG.F RUM CR CA 0.0067 0.3 0.0060 0.3 0.0057 0.3 0.0058 0.3 0.0059 0.3 0.0057 0.2 0.0057 0.2 0.0051 0.2 0.0051 0.2 0.0050 0.3 0.0053 0.2 0.0057 0.2 0.0057 0.2 0.0059 0.2 0.0059 0.2	POJ/PTS = NO. 01203-9134 T CPB CAF 180 0.1186-0.1994 168 0.1189 0.1979 113 0.1175 0.1938 078.0.1145 0.1933 049 0.1117 0.1932 044 0.1112 0.1932 044 0.1112 0.1932 049 0.1112 0.1884 991 0.1107 0.1884 991 0.1107 0.1884 991 0.1006 0.1898 984 0.1087 0.1898 984 0.1087 0.1898 983 0.1081 0.1882 943 0.1075 0.1868 943 0.1075 0.1868 943 0.1075 0.1868 943 0.1076 0.1868	RUN 342. 342. 342. 342. 342. 342. 342. 342.

HODEL 946.2	CONF	IG. 2.00	io K	ICH 3400	PH1 =	•	-
Q= 6.37 PSI	RE PER	IN.= .48E	06 TO=	90. BEG.F	P0J/P1	rs = 40.	•
PQ= 193.0 C	MHG PTS=	1.0109 PS	ī	RŪN	NO. 01203	59135	
ALPHA CN	CM	cs	£Y	ĈR CA	T CPB	C-F	RŲN
10.23 1.2655	-11.2047				166 0.1185 155 0.1185		343. 343.
9.21 1.0916	-9.6686 -821518				134 0.1167		343.
8.17 0.9201 7.14 0.7674	-6.7994				090 0.1139		343.
6.11 0.6233	-5.5288				070 0.1115		343.
5.08 0.4995	-4.4564				054 0.1112		343.
4.06 0.3835	-3.4466		0.0265	0.0058-0.3	036 0.1118	0.1918	343.
3.04 0.2734	-2.4874	-0.0027			033 0.1114		343.
2.01 0.1701	-1.5877	-0.0020			010 0.1105		343.
1.48 0.1147	-1,1054				983 0.1095		343.
0.97 0.0652	-0.6737				980 0.1088		343.
0.47 0.0105	-0.1911				986 0:1082		343. 943.
-0.06 -0.0305		-0.0014			948 0.1075 961 0.1067		343.
-0.55 -0.0791		-0.0013			924 0.1061		343.
-1.07 -0.1312	1.0260	-0.0011			912 0.1056		343.
-1.57 -0.1781 -2.08 -0.2251		0.0004			916 0.1055		343:
-3.10 -0.3309	2.7642	0.0011			937 0.1059		343.
-4.12 -0.4392		0.0010			907 0.1067		343.
MODEL 946.2	CONF	1G. 2,00		ACK 3.00	PHI =	•	
MODEL 946.2 Q= 6.37 PSI		IG. 2,00		90. DEG.F	-	• TS ≈ 100	•
	RE PER	IN.= .486	=07 00= SI	90. DEG.F	POJ/P	69136	
Q= 6.37 PSI	RE PER	IN.= .486	06 TO=	90. DEG.F	POJ/P		RUN
Q= 6.37 PSE PO= 193.0.0	RE PER	IN.= .486 1.0109 PS	06 TO= SI CY 0.0564	90. DEG.F RUN CR CA 0.0060 0.3	POJ/P NO. 01203 T CPB	69136 CAF 0-2111	RUN 344.
Q= 6.37 PSF PO= 193.0.C ALPHA CN	RE PER MHG PTS= CM -10.5338 -7.0345	IN.= .486 1.0109 PS CS -0.0078 -0.0092	CY 0.0564 0.0716	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3	POJ/P NO. 01203 T CPB 288 0.1177 223 0.1173	69136 CAF 0-2111 0-2051	RUN 344. 364.
Q= 6.37 PSF PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116	CY 0.0564 0.0857	90. DEG.F RUM CR CA 0.0060 0.3 0.0068 0.3 0.0070 0.3	POJ/P NO. 01203 T CPB 1288 0.1177 1223 0.1173	69136 CAF 0,2111 0,2051 0,1986	RUN 344. 366. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058	CY 0.0564 0.0716 0.0857 0.0396	90. DEG.F RUM CR CA 0.0060 0.3 0.0068 0.3 0.0070 0.3 0.0066 0.3	POJ/P 1 NO. 01203 1	69136 CAF 0,2111 0,2051 0,1986 0,1992	RUN 344. 364. 344.
Q= 6.37 PSI PO= 193.0.0 ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047	CY 0.0564 0.0716 0.0857 0.0396 0.0321	90. DEG.F RUM CR CA 0.0060 0.3 0.0068 0.3 0.0070 0.3 0.0060 0.3 0.0063 0.3	POJ/P 1 NO. 01203 T CP8 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106	CAF 0-2111 0-2051 0-1986 0-1992 0-2030	RUN 344. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.0 ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041	CY 0.0564 0.0716 0.0857 0.0326 0.0271	90. DEG.F RUM CR CA 0.0060 0.3 0.0068 0.3 0.0066 0.3 0.0066 0.3 0.0066 0.3	POJ/P 1 NO. 01203 1 CP8 1288 0.1177 1223 0.1173 133 0.1147 1114 0.1126 136 0.1106	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004	RUN 344. 366. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0272	90. DEG.F RUN CR CA 0.0060 0.3 0.0060 0.3 0.0060 0.3 0.0066 0.3 0.0061 0.3 0.0061 0.3 0.0061 0.3	POJ/P 1 NO. 01203 1 CPB 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 111 0.1108	69136 CAF 0,2111 0,2051 0,1986 0,1992 0,2030 0,2004 0,1962	RUN 344. 366. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 4.03 0.3229 3.00 0.2145	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0924	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0272 0.0136	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3 0.0066 0.3 0.0063 0.3 0.0061 0.3 0.0061 0.3 0.0069 0.3	POJ/P 1 NO. 01203 T CPB 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 111 0.1108 1074 0.1112	69136 CAF 0,2111 0,2051 0,1986 0,1992 0,2030 0,2004 0,1962 0,1961	RUN 346. 346. 344. 344. 344. 344.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105	RE PER MHG PTS= CM -10.5338 -3.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -3.0498 -1.1919	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0024 -0.9022	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0136 0.0122	90. DEG.F RUM CR CA 0.0060 0.3 0.0068 0.3 0.0066 0.3 0.0063 0.3 0.0061 0.3 0.0061 0.3 0.0059 J.3 0.0059 J.3	POJ/P 1 NO. 01203 T CP8 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 111 0.1108 1074 0.1112 1071 0.1110	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1961 0-1927	RUN 364. 364. 344. 344. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0041 -0.0037 -0.0024 -0.9022 -0.0038	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0126 0.0122 0.00270	90. DEG.F RUN CR CA 0.0060 0.3 0.0066 0.3 0.0066 0.3 0.0066 0.3 0.0061 0.3 0.0059 J.3 0.0059 J.3 0.0059 0.3	POJ/P NO. 01203 T CP8 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 1074 0.1112 1071 0.1113 1031 0.1103	CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1961 0-1927 0-1941	RUN 346. 346. 344. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2633	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0924 -0.9022 -0.0038 -0.0037	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0136 0.0122 0.0270 0.0270	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3 0.0070 0.3 0.0063 0.3 0.0063 0.3 0.0061 0.3 0.0059 0.3 0.0059 0.3 0.0059 0.3	POJ/P 1 NO. 01203 T CPB 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 111 0.1108 1074 0.1112 1071 0.1110 1031 0.1103 1031 0.1090 1001 0.1087	69136 CAF 0.2111 0.2051 0.1986 0.1992 0.2004 0.1961 0.1961 0.1961 0.1941 0.1913	RUN 344. 344. 344. 344. 344. 344. 344.
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2509	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0041 -0.0037 -0.0024 -0.9022 -0.0038	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0136 0.0122 0.0126 0.0260	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3 0.0066 0.3 0.0066 0.3 0.0063 0.3 0.0061 0.3 0.0065 0.3 0.0069 0.3 0.0069 0.3 0.0069 0.3 0.0069 0.3	POJ/P NO. 01203 T CP8 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 1074 0.1112 1071 0.1113 1031 0.1103	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1961 0-1927 0-1941 0-1913 0-1903	RUN 344. 344. 344. 344. 344. 344. 344. 344
Q= 6.37 PSI PO= 193.0.0 ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038 0.43 -0.0542	RE PER **HHG PTS** CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6623 -0.2633 0.2509 0.6299	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0024 -0.9022 -0.0038 -0.0037 -0.0036	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0136 0.0122 0.0270 0.0262 0.0264 0.0268 0.0368	90. DEG.F RUN CR CA 0.0060 0.3 0.0060 0.3 0.0070 0.3 0.0066 0.3 0.0061 0.3 0.0059 J.3 0.0059 J.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0043 0.2 0.0043 0.2 0.0043 0.2	POJ/P NO. 01203 T CPB 1288 0.1177 1233 0.1173 133 0.1147 114 0.1122 136 0.1106 1074 0.1112 1071 0.1110 1031 0.1103 1031 0.1090 1001 0.1087 1982 0.1078 1982 0.1078	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2004 9-1962 0-1961 0-1961 0-1913 0-1993 0-1864	RUN 344. 344. 344. 344. 344. 344. 344. 344
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038 0.43 -0.0542 -0.08 -0.0985	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2633 0.2509 0.6299 1.0555 1.4471	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0024 -0.9022 -0.0038 -0.0037 -0.0036 -0.0037	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0242 0.0136 0.0122 0.0270 0.0262 0.0266 0.0268 0.0302 0.0255	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3 0.0066 0.3 0.0063 0.3 0.0069 0.3 0.0059 J.3 0.0059 J.3 0.0049 0.3 0.0049 0.3 0.0043 0.3 0.0043 0.3 0.0043 0.3 0.0043 0.3 0.0043 0.2 0.0040 0.2	POJ/P NO. 01203 T CPB 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 111 0.1108 1074 0.1110 1031 0.1103 1001 0.1037 1982 0.1079 1982 0.1079 1982 0.1068 1936 0.1054	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1961 0-1927 0-1941 0-1913 0-1884 0-1884 0-1882	RUN 344. 344. 344. 344. 344. 344. 344. 344
Q= 6.37 PSI PO= 193.0 C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038 0.43 -0.0542 -0.08 -0.0985 -0.58 -0.1472 -1.10 -0.1933 -1.61 -0.2428	RE PER MHG PTS= CK -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2633 0.2599 1.0555 1.4471 1.8807	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0037 -0.0038 -0.0037 -0.0039 -0.0039 -0.0049	CY 0.0564 0.0716 0.0857 0.0396 0.0321 0.0271 0.0272 0.0126 0.0268 0.0302 0.0255 0.0366	90. DEG.F RUN CR CA 0.0060 0.3 0.0066 0.3 0.0063 0.3 0.0063 0.3 0.0069 0.3 0.0049 0.3 0.0049 0.3 0.0043 0.3 0.0049 0.3 0.0040 0.2 0.0040 0.2 0.0040 0.2 0.0040 0.2	POJ/P NO. 01203 T CPB 2288 0.1177 223 0.1173 7114 0.1122 136 0.1106 111 0.1108 1074 0.1110 1031 0.1103 1031 0.1090 1001 0.1087 1982 0.1078 1982 0.1068 1922 0.1058 1933 0.1050	69136 CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1962 0-1961 0-1927 0-1941 0-1913 0-1884 0-1864 0-1863	RUN 344. 344. 344. 344. 344. 344. 344. 344
Q= 6.37 PSI PO= 193.0.C ALPHA CN 10.20 1.1778 9.18 1.0081 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038 0.43 -0.0542 -0.08 -0.0985 -0.58 -0.1472 -1.10 -0.1933 -1.61 -0.2428 -2.12 -0.2906	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2633 0.2509 0.6299 1.0555 1.4471 1.8807 2.2952	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0041 -0.0037 -0.0036 -0.0037 -0.0036 -0.0037 -0.0049 -0.0049 -0.0053	CY 0.0564 0.0716 0.0857 0.0321 0.0271 0.0242 0.0136 0.0122 0.0246 0.0268 0.0302 0.0255 0.0366 0.0401	90. DEG.F RUN CR CA 0.0060 0.3 0.0066 0.3 0.0066 0.3 0.0066 0.3 0.0069 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.2 0.0049 0.2 0.0049 0.2 0.0049 0.2	POJ/P NO. 01203 T CPB 1288 0.1177 1223 0.1173 133 0.1147 114 0.1122 136 0.1106 1074 0.1112 1071 0.1110 1031 0.1030 1031 0.1030 1031 0.1030 1031 0.1030 1031 0.1050 1032 0.1058 1033 0.1050 1033 0.1050	CAF 0-2111 0-2051 0-1986 0-1992 0-2030 0-2004 9-1962 0-1961 0-1927 0-1941 0-1913 0-1893 0-1884 0-1884 0-1885 0-1883 0-1890	RUN 344. 344. 344. 344. 344. 344. 344. 344
Q= 6.37 PSI PO= 193.0 C ALPHA CN 10.20 1.1778 9.18 1.0081. 8.14 0.8360 7.11 0.6850 6.08 0.5551 5.05 0.4339 4.03 0.3229 3.00 0.2145 1.98 0.1105 1.46 0.0499 0.95 0.0038 0.43 -0.0542 -0.08 -0.0985 -0.58 -0.1472 -1.10 -0.1933 -1.61 -0.2428	RE PER MHG PTS= CM -10.5338 -7.0345 -7.5040 -6.1727 -5.0551 -4.0091 -3.0498 -2.1041 -1.1919 -0.6625 -0.2633 0.2509 0.6299 1.0555 1.4471 1.8807 2.2533 3.1893	IN.= .486 1.0109 PS CS -0.0078 -0.0092 -0.0116 -0.0058 -0.0047 -0.0037 -0.0038 -0.0037 -0.0039 -0.0039 -0.0049	CY 0.0564 0.0716 0.0857 0.0395 0.0321 0.0271 0.0242 0.0136 0.0122 0.0270 0.0262 0.0266 0.0302 0.0255 0.0366 0.0401 -0.0011	90. DEG.F RUN CR CA 0.0060 0.3 0.0068 0.3 0.0060 0.3 0.0061 0.3 0.0069 0.3 0.0069 0.3 0.0069 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3 0.0049 0.3	POJ/P NO. 01203 T CPB 2288 0.1177 223 0.1173 7114 0.1122 136 0.1106 111 0.1108 1074 0.1110 1031 0.1103 1031 0.1090 1001 0.1087 1982 0.1078 1982 0.1068 1922 0.1058 1933 0.1050	CAF 0-2111 0-2051 0-1986 0-1992 0-2004 0-1962 0-1961 0-1927 0-1941 0-1913 0-1903 0-1884 0-1884 0-1885 0-1889 0-1862	RUN 344. 344. 344. 344. 344. 344. 344. 344

AND THE MENTAL MANUEL OF THE PROPERTY OF THE P

MO	DEL 946.2	CON	FIG. 2.00	0 M	ACH 3.01	0	PHI ≈	15.	
Qæ	6.37 PSI	RE PER	IN.= .48E	±07 30	90. D	EG.F	PQJ/P	TS =	•
PO	≈ 193.0 CM	HG PTS=	1.0109 PS	ī		RUN NO.	01203	69137	
ALPHÂ	CN	CH	cs	CY	CR	CAT	CPB.	CAF	RUN
4.05	0.4126	-3.5R72	-0.0095	0.0589	-0.0003	0.2980	0-1107	0.1873	345%
3.04	0.3058	~2.6515	-0.0073	0.0399	-0.0010	0.2971	0.1100	0.1871	345.
2.02	-0-1993	~1.7226	-0.0065	0.0365	-0.0005	0.2963	0.1094	0.1869	345.
1.49	0.1365	~1.1692	-0.0069	0.0435	-0.0014	0.2962	0.1089	0.1873	345.
0.99	0.0943	-0.8163	-0.0047	0.0221	0.	0.2929	0.1087	.0.1842	345.
0.47	0.0454	<i>=</i> ∂.3937	-0.0043	0.0192	-0.G005	0.2933	0.1086	0.1848	345.
-0.04	-0.0038	0.0318	-0.0025		0.0002				345.
-0.54	-0.0478	0.4082	-0.0004	-0.0169					345.
	-0.1024		-0.0016	-0.0053					345.
	-0.1462		-0.0002	-0.0192					345.
	-0-1948		-0.0008	-0:0128					345.
	-0.2990	2.5847		-0.0592					345.
-4.11	-0.4084	3.5400	0.0094	-0.1010	0.0014	0.2916	0.1103	0.1813	345.
	DEL 946.2		FIG. 2.00		ACH 3.00		PHI =	15.	
Q=	6.37 PSI	RE PER	IN.= .48E	06 TO=	90. DI	EG•F	901/9	rs = :	LO.
PO	= 193.0 CM	HG PTS=	1.0109 PS	I		RUN NO	01203	69138	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.04	0.4017	-3.5256	~0.0058	0-0246	0.0001	0-3012	0-1111	0.1901	346.
3.04			-0.0047		-0.0009				346.
2.01			-0.0046		-0.0012				346.
1.49			-0.0036	0.0059	-0.0002	0.2965	0.1097	0.1858	346.
0.98		-0.7942	-0.0041	0.0118-	-0.0006	0-2960	0.1093	0.1867	346.
0.47	0.0416	-0.3990	-0.0039	0.0093	-0.0007	0.2842	0.1089	0.1753	346.
	-0.0022		-0.0027	-0.0028-					346.
-0.55	-0.0563		-0.0028	-0.0017-					346.
-1.06	-0.1065	0.8872	-0.0066		-0.0010				346.
	-0-1645	1.3973	-0.0052	0.0203-	-0.0008	0-2912	0.1078	0.1834	346.
-2.08	-0.2013	1.7050	-0.0036		-0.0005				346.
-3.09	-0.3064	2.6231	-0.0048		-0.0004				346.
-6 11	-0.4155	3.5770	-0.0070	0.0363	0.0003	0.2014	0-1087	0.1827	346.

MC	DEL 946.2	CONF	IG. 2.000) MA	CH 3.0	3	PHI =	15.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 TO=	90. D	EG.F	P0J/P	TS =	20.
PC)= 193.0 CH	HG PTS=	1.0109 PSi	ī		RUN NO	01203	69139	
AL:PHA	. CN	CM	cs	CY	CR	CAT	CPE	CAF	RUN
		-							
4.04	0.3938	-3.4898	-0.0098			0.3044			
3.03		-2.5861				0.3017			
2.01	0.1864		-0.0096			0.3008			
1.48		-1.1798		0.0515-					
0.97			-0.0071			0.3009			
0.46		-0.3325		0.0450-					
	-0.0168		-0.0082	0.0419-					
	-0.0648		-0.0076	0.0351-					
	-0.1123		-0.0078	0.0345-					
	-0.1597		-0.0075	0.0290-					
	-0.2091		-0.0082	0.0369-					
	-0.3138		-0.0074	0.0294					
-4.12	-0-4242	3.6292	-0.0085	0.0401	0.0010	0.2945	0.1080	0.1865	347.
Ж	DEL 946.2	CONF	IG. 2.000) HA	CH 3.00)	PHI =	15.	
Q=	6.37 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	G.F	POJ/P	rs =	40.
PC	= 193.0 Cì	HG. PTS=	1:0109 PSI		•	RUN NO	. 01203	5 91 40	
AĽPHĄ	CN CN	CH	CS	CY	CŖ	CAT	CPB	CAF	RUN
4.03	0.3769	-3.3937	~0.0203	0.1477-	0.0018	0-3072	0.1114	0.1958	348.
3.02	* *	-2.4871		0.1340-					
2.00		-1.6024		0.1091-					
1.48		-1.1239		0.0970-					
0.97		-0.6764		0.0854-			_		
0.45									
	0.0178			0.0708-	0.0019	0.2953	0.1083	0.1869	348-
-0.06		-0.2691	-0.0127	0.0708-					
	-0.0350	-0.2691 0.1959	-0.0127 -0.0139	0.0809-	0.0020	0.2931	0.1077	0.1854	348.
-0.57	-0.0350° -0.0848	-0.2691 0.1959 0.6266	-0.0127 -0.0139 -0.0132	0.0809- 0.0715-	0.0020 0.0010	0.2931 0.2926	0.1077 0.1070	0.1854 0.1856	348 • 348 •
-0.57 -1.07	-0.0350 -0.0848 -0.1372	-0.2691 0.1959 0.6266 1.0817	-0.0127 -0.0139 -0.0132 -0.0128	0.0809- 0.0715- 0.0650-	0.0020 0.0010 0.0004	0.2931 0.2926 0.2930	0.1077 0.1070 0.1066	0.1854 0.1856 0.1865	348. 348. 348.
-0.57 -1.07 -1.59	-0.0350 -0.0848 -0.1372 -0.1790	-0.2691 0.1959 0.6266 1.0817 1.4392	-0.0127 -0.0139 -0.0132 -0.0128 -0.0121	0.0809- 0.0715- 0.0650- 0.0549	0.0020 0.0010 0.0004 0.0003	0.2931 0.2926 0.2930 0.2915	0.1077 0.1070 0.1066 0.1063	0.1854 0.1856 0.1865 0.1853	348. 348. 348. 348.
-0.57 -1.07 -1.59 -2.09	-0.0350 -0.0848 -0.1372	-0.2691 0.1959 0.6266 1.0817 1.4392 1.8330	-0.0127 -0.0139 -0.0132 -0.0128	0.0809- 0.0715- 0.0650-	0.0020 0.0010 0.0004 0.0003 0.0006	0.2931 0.2926 0.2930 0.2915 0.2918	0.1077 0.1070 0.1066 0.1063 0.1061	0.1854 0.1856 0.1865 0.1853 0.1857	348. 348. 348. 348.

MODEL 946.2	CONFI	G. 2.000	M.	ICH 3.00	•	PHI =	15.	
Q= 6.37 PSI	RE PER I	N.= .48E06	-T0=	96. DE	G.F	P03/P1	rs = to	00.
PO= 193.0 C	MHG PTS= 1	.0169 PSI			RUN NO.	01203	69141	
ALPHA CN	CH	CS	CY	CŔ	CAT	СРВ	CAF	RUN
4.01 0.3199	-3.0241 -	0.0443	0.3342~	0.0035	C.3121	0.1112	0.2008	349.
2.99 0.2168	-2.1243 -			0.0038				349.
1.97 0.1146	-1.2316 -			0.0045				349.
1.45 0.0550	-0.7074 -			0.0042				349.
0.93 0.0104	20.3244 −			0.0036				349.
0.44 -0.0404	0:1240 -			0.0015				349.
-0.09 -0.0922	0.5751 -						0.1872	349.
-0.59 -0.1353	0.9425 -			0.0010				349.
-1.10 -0.1933	1.4568 -		0.1292-		0.2958			349.
-1.61 -0.2359	1.8169 -			0.0014				349. 349.
-2.12 -0.2870	2-2697 -			0.0013			0.1832	
-3.13 -0.3897	3.1618 4.1337			0.0029				349.
-4.15 -0.5005	4.1331 -	0.0102	0.000%	U. 0049	0.2730	0.1000	0.1010	247.
MODEL 946.2		G. 2.000 N.= .48E06		90. DE		= IH9	-	
MODEL 946.2 Q= 6.37 PSI		G. 2.000 N.= .48E06		90. DE		- IH4	-	•
	RE PER I	N.= .48E06		90. DE	G.F		rs =	•
Q= 6.37 PSI	RE PER I	N.= .48E06		90. DE	G.F	P0J/P	rs =	• RUN
Q= 6.37 PSI PO= 193.0 C ALPHA CN	RE PER II MHG PTS= 1 CM	N.= .48E06 .0109 PSI CS	. 70≈ CY	90. DE	EG.F RUN NO. CAT	POJ/P ³ 01203 <i>0</i> CP8	TS = 59142 CAF	• RUN 350•
Q= 6.37 PSI PO= 193.0 C	RE PER II	N.= .48E06 .0109 PSI CS 0.0119	. 70≈ CY	90. DE GR 0.0013	G.F RUN NO. CAT 0.3012	POJ/P ³ 01203 <i>0</i> CP8	TS = 59142 CAF 0.1902	
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059	RE PER II MHG PTS= 1 CM -3.5844 -	N.= .48E06 .0109 PSI CS 0.0119 0.0098	CY 0.0838 0.0667-	90. DE GR 0.0013	CAT 0.3012 0.2989	POJ/P1 012036 CPB 0.1109 0.1099	TS = 59142 CAF 0.1902 0.1890	350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059	RE PER II MHG PTS= 1 CM -3.5844 -1 -2.6485 -1	N.= .48E06 .0109 PSI CS 0.0119 0.0098 9.0089	CY 0.0838 0.0667- 0.0593	90. DE GR 0.0013	CAT 0.3012 0.2989 0.2983	POJ/P1 012030 CPB 0.1109 0.1099 0.1091	CAF 0.1902 0.1890 0.1893	350. 350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993	RE PER II MHG PTS= 1 CM -3.5844 -1 -2.6485 -1 -1.7189 -1	N.= .48E06 .0109 PSI CS 0.0119 0.0098 9.0089 0.0084	CY 0.0838 0.0667- 0.0593 0.0543	90. DE GR 0.0013 0.	CAT 0.3012 0.2989 0.2983 0.2961	POJ/P1 012030 CPB 0.1109 0.1099 0.1091 0.1087	CAF 0.1902 0.1890 0.1893 0.1874	350. 350. 350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426	RE PER II MHG PTS= 1 CM -3.5844 -1 -2.6485 -1 -1.7189 -1 -1.2302 -1	N.≃ .48E06 .0109 PSI CS 0.0119 0.0098 0.0089 0.0084 0.0066 0.0073	CY 0.0838 0.0667- 0.0593 0.0543 0.0383	90. DE CR 0.0013 0.0013 0.0010 0.0015 0.0008	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946	POJ/P1 012036 CPB 0.1109 0.1099 0.1091 0.1087 0.1085 0.1084	CAF 0.1902 0.1890 0.1893 0.1874 0.1867 0.1861	350. 350. 350. 350. 350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940	RE PER 11 CM -3.58442.64851.71891.23020.80960.3776 0.0534	N.= .48E06 .0109 PSI CS 0.0119 0.0098 0.0089 0.0084 0.0066 0.0073 0.0075	CY 0.0838 0.0667- 0.0593 0.0543 0.0383 0.0450 0.0437	90. DE CR 0.0013 0.0010 0.0015 0.0008 0.0002	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946 0.2965	POJ/P1 012036 CP8 0.1109 0.1091 0.1087 0.1085 0.1084 0.1085	CAF 0.1902 0.1893 0.1874 0.1867 0.1861 0.1880	350. 350. 350. 350. 350. 350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940 0.47 0.0438	RE PER II MHG PTS= 1 CM -3.5844 - -2.6485 - -1.7189 - -1.2302 - -0.8096 - -0.3776 - 0.0534 - 0.4384 -	N.= .48E06 .0109 PSI CS 0.0119 0.0098 0.0089 0.0084 0.0066 0.0073 0.0075 0.0044	CY 0.0838 0.0667- 0.0593 0.0543 0.0450 0.0437	90. DE CR 0.0013 0.0013 0.0010 0.0015 0.0008 0.0002 0.0018	CAT 0.3012 0.2983 0.2983 0.2961 0.2953 0.2946 0.2965	POJ/P1 012036 CP8 0.1109 0.1099 0.1091 0.1085 0.1084 0.1085 0.1087	CAF 0.1902 0.1890 0.1893 0.1874 0.1867 0.1861 0.1880 0.1878	350. 350. 350. 350. 350. 350.
Q= 6.37 PSI P0= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940 0.47 0.0438 -0.04 -0.0066	RE PER II MHG PTS= 1 CM -3.58442.64851.71891.23020.8096 0.3776 0.0534 0.4384 0.8711	N.= .48E06 .0109 PSI CS 0.0119 0.0098 9.0089 0.0084 0.0066 0.0073 0.0075 0.0044 0.0039	CY 0.0838 0.0667- 0.0593 0.0543 0.0450 0.0437 0.0172 0≈0128	90. DE CR 0.0013 0.0013 0.0015 0.0015 0.0008 0.0002 0.0018	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946 0.2965 0.2965	POJ/P1 012036 CP8 0.1109 0.1099 0.1091 0.1085 0.1085 0.1087 0.1088	CAF 0.1902 0.1890 0.1893 0.1874 0.1861 0.1880 0.1878 0.1852	350. 350. 350. 350. 350. 350. 350.
Q= 6.37 PSI P0= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940 0.47 0.0438 -0.04 -0.0066 -0.56 -0.0510 -1.06 -0.1009 -1.58 -0.1510	RE PER II MHG PTS= 1 CM -3.5844 -1 -2.6485 -1 -1.7189 -1 -1.2302 -1 -0.8096 -1 -0.3776 -1 0.4384 -1 0.8711 -1 1.3053 -1	N.≈ .48E06 .0109 PSI CS 0.0119 0.0098 9.0089 0.0084 0.0066 0.0073 0.0075 0.0044 0.0039 0.0029	CY 0.0838 0.0667- 0.0593 0.0543 0.0450 0.0437 0.0172 0.0128 0.0038	90. DE CR 0.0013 0.0010 0.0015 0.0008 0.0002 0.0016 0.0015 0.0013	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946 0.2965 0.2965 0.2940 0.2932	POJ/PT 012036 CPB 0.1109 0.1099 0.1091 0.1087 0.1085 0.1088 0.1088	CAF 0.1902 0.1890 0.1893 0.1874 0.1861 0.1880 0.1878 0.1852 0.1843	350. 350. 350. 350. 350. 350. 350.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940 0.47 0.0438 -0.04 -0.0066 -0.56 -0.0510 -1.06 -0.1009 -1.58 -0.1510 -2.09 -0.2012	RE PER II CM -3.5844 -1 -2.6485 -1 -1.7189 -1 -1.2302 -1 -0.8096 -1 -0.3776 -1 0.0534 -1 0.0534 -1 0.4384 -1 1.3053 -1 1.7368 -1	N.= .48E06 .0109 PSI CS 0.0119 0.0098 9.0089 0.0084 9.0066 0.0073 0.0075 0.0044 0.0039 0.0029 0.0019	CY 0.0838 0.0667- 0.0593 0.0543 0.0450 0.0437 0.0172 0.0172 0.0128 0.0038	90. DE CR 0.0013 0.0010 0.0015 0.0008 0.0002 0.0016 0.0015 0.0013	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946 0.2965 0.2965 0.2952 0.2932	POJ/PT 012036 CPB 0.1109 0.1099 0.1091 0.1085 0.1084 0.1085 0.1088 0.1089 0.1089	CAF 0.1902 0.1890 0.1893 0.1874 0.1867 0.1861 0.1880 0.1878 0.1878 0.1878	350. 350. 350. 350. 350. 350. 350. 350.
Q= 6.37 PSI P0= 193.0 C ALPHA CN 4.06 0.4131 3.04 0.3059 2.02 0.1993 1.49 0.1426 0.98 0.0940 0.47 0.0438 -0.04 -0.0066 -0.56 -0.0510 -1.06 -0.1009 -1.58 -0.1510	RE PER II MHG PTS= 1 CM -3.5844 -1 -2.6485 -1 -1.7189 -1 -1.2302 -1 -0.8096 -1 -0.3776 -1 0.4384 -1 0.8711 -1 1.3053 -1	N.= .48E06 .0109 PSI CS 0.0119 0.0098 9.0089 0.0084 0.0066 0.0073 0.0075 0.0044 0.0039 0.0029 0.0019 -0.0017	CY 0.0838 0.0667- 0.0593 0.0543 0.0383 0.0450 0.0437 0.0172 0.0172 0.0128 0.0038 0.0060 0.0043	90. DE CR 0.0013 0.0010 0.0015 0.0008 0.0002 0.0016 0.0015 0.0013	CAT 0.3012 0.2989 0.2983 0.2961 0.2953 0.2946 0.2965 0.2965 0.2965 0.2932 0.2925 0.2918	POJ/PT 012036 CPB 0.1109 0.1099 0.1091 0.1085 0.1085 0.1086 0.1089 0.1089 0.1092	CAF 0.1902 0.1890 0.1893 0.1874 0.1867 0.1861 0.1880 0.1878 0.1878 0.1878 0.1878	350. 350. 350. 350. 350. 350. 350.

	EL 946.2	CON	FIG. 2.0)0¢ Mi	CH 3.00	PHI = 30.	
Q=	6.37 PSI	RE PER	IN.= .48	3E06 T0=	90. DEG.F	POJ/PTS =	10-
P0:	= 193.0 CM	HG PTS=	1.0109 P	Sî	RUN NO	. 0120369143	
ALPHA	CN	CH	cs	CY	CR CAT	CPB CAF	RUN
4.06	0.4040	-3.5370	-0.0135	0.0888	0.0014 0.3052	0.1112 0.193	9 351.
3.03		-2.6018	-0.0114		0.0001 0.3029		
2.02			-0.0086		0.0006 0.2996		
1.50			-0.0084		0.0003 0.3008		
0.97			-0.0079		0.0004 0.2967		
	0.0371		-0.0081		0.0002 0.2994		
	-0.0093		-0.0050		0.0003-0.2968		
	-0.0592		-0.0045		0.0004 0.2943		
	-0.1085		-0.0031		0.0009 0.2883		
	-9-1588		-9.0033		A.0006 0.2824		
	-0.2113		-0.0037		0.0003 0.2939		
	-0.3072		-0.0005		0.0013 0.2948		
-4.11	-0.4179	3.6042	0.0007	-0.0382	0.0018 0.2934	0.1100 0.183	5 351.
MOI	DEL 946.2	CON	FIG. 2.0	000 84	NCH 3.00	PHI = 30.	
	_						20.
	6.37 PŜI		IN.= .48		90. DEG.F	POJ/PTS =	20.
Q=	_	RE PER	IN.= .48	3E06 TO=	90. DEG.F		20•
Q=	6.37 PŠI	RE PER	IN.= .48	3E06 TO=	90. DEG.F	POJ/PTS =	20. RUN
Q= P0:	6.37 PŠI = 193.0 CM CN	RE PER HG PTS=	IN.= .48	3E06 T0= PSI CY	90. DEG.F RUN NO	POJ/PTS = - 0120369144 - CPB CAF	RUN
=Q PO: ALPHA	6.37 PŚI = 193.0 CM CN 0.3947	RE PER HG PTS= CM -3.4835	IN.= .48 1.0109 F	3E06 TO= PSI CY 0-1494	90. DEG.F RUN NO CR CAT	POJ/PTS = - 0120369144 CPB CAF 0-1110 0-196	RUN 6 352.
=Q :09 ALPHA 4.04	6.37 PŠI = 193.0 CM CN 0.3947 0.2901	RE PER HG PTS= CM -3.4835 -2.5718	IN.= .46 1.0109 F CS -0.0216	0.1494 0.1237	90. DEG.F RUN NO CR CAT 0.0015 0.3076	POJ/PTS = - 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194	RUN 6 352. 8 352.
Q= РО: ALPHA 4.04 3.03	6.37 PŠI = 193.0 CM CN 0.3947 0.2901 0.1865	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716	IN.= .46 1.0109 F CS -0.0216 -0.0190	0-1494 0-1237 0-1009	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192	RUN 6 352. 8 352. 3 352.
Q= РО: АLРНА 4.04 3.03 2.01	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020	IN.= .48 1.0109 F CS -0.0216 -0.0190 -0.0164	0-1494 0-1237 0-1009 0-0868	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052 0.0004 0.3020	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 C.192 0.1091 0.192	RUN 6 352. 8 352. 3 352. 3 352.
Q= PO: ALPHA 4.04 3.03 2.01 1.49	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626	IN.= .48 1.0109 F CS -0.0216 -0.0190 -0.0164 -0.0148	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.9009 0.3052 0.0004 0.3020 -0.0003 0.3014 0.0002 0.2989 0.0006 0.2998	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192 0.1091 0.192 0.1088 0.190 0.1085 0.191	RUN 6 352. 8 352. 3 352. 1 352. 3 352.
Q= PO: ALPHA 4.04 3.03 2.01 1.49 0.97 0.46	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738	IN.= .48 1.0109 F CS -0.0216 -0.0190 -0.0164 -0.0148 -0.0130 -0.0108	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.9009 0.3052 0.0004 0.3020 -0.0003 0.3014 0.0002 0.2989 0.0006 0.2998 0.0006 0.2998	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192 0.1091 0.192 0.1088 0.190 0.1085 0.191 0.1082 0.190	RUN 6 352. 8 352. 3 352. 1 352. 3 352. 8 352.
Q= PO: ALPHA 4.04 3.03 2.01 1.49 0.97 0.46 -0.05	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814 0.0336	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738	IN.= .48 1.0109 F CS -0.0216 -0.0190 -0.0164 -0.0148 -0.0130 -0.0108	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454 0.0237	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.9009 0.3052 0.0004 0.3020 -0.0003 0.3014 0.0002 0.2989 0.0006 0.2998 0.0006 0.2998 0.0006 0.2998	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192 0.1091 0.192 0.1085 0.191 0.1085 0.191 0.1082 0.190 0.1080 0.190	RUN 6 352. 8 352. 3 352. 3 352. 1 352. 3 352. 8 352.
Q= P0: ALPHA 4.04 3.03 2.01 1.49 0.46 -0.05 -0.56 -1.07	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814 0.0336 -0.0151 -0.0650 -0.1141	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738 0.5070 0.9315	IN.= .48 1.0109 F CS -0.0190 -0.0164 -0.0130 -0.0108 -0.0108 -0.0085	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454 0.0237 -0.0022	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052 0.0004 0.3020 -0.0003 0.3014 0.0002 0.2989 0.0006 0.2988 0.0006 0.2998 0.0006 0.2998 0.0001 0.2983 0.0002 0.2966	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192 0.1091 0.192 0.1085 0.191 0.1082 0.190 0.1080 0.190 0.1080 0.190	RUN 6 352. 8 352. 3 352. 3 352. 1 352. 8 352. 8 352. 9 352.
Q= P0: ALPHA 4.04 3.03 2.01 1.49 0.46 -0.05 -0.56 -1.07	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814 0.0336 -0.0151 -0.0650	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738 0.5070 0.9315 1.3665	IN.= .48 1.0109 F CS -0.0190 -0.0164 -0.0130 -0.0108 -0.0108 -0.0059 -0.0066	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454 0.0237 -0.0022 0.0045	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052 0.0004 0.3020 0.0003 0.3014 0.0002 0.2988 0.0004 0.2998 0.0004 0.2998 0.0001 0.2983 0.0002 0.2966	POJ/PTS = . 0120369144 CPB CAF 0.1110 0.196 0.1105 0.194 0.1097 0.192 0.1080 0.190 0.1082 0.190 0.1080 0.190 0.1080 0.190 0.1076 0.138 0.1073 0.189	RUN 6 352. 8 352. 3 352. 3 352. 1 352. 8 352. 8 352. 9 352. 4 352.
Q= PO: ALPHA 4.04 3.03 2.01 1.49 0.97 0.46 -0.05 -0.56 -1.07 -1.58 -2.09	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814 0.0336 -0.0151 -0.0650 -0.1141 -0.1642 -0.2157	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738 0.5070 0.9315 1.3665 1.8155	IN.= .48 1.0109 F CS -0.0216 -0.0190 -0.0164 -0.0148 -0.0108 -0.0108 -0.0065 -0.0065	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454 0.022 0.0045 0.0041	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052 0.0004 0.3029 0.0003 0.3014 0.0002 0.2989 0.0006 0.2998 0.0006 0.2998 0.0006 0.2983 0.0000 0.2983 0.0000 0.2983 0.0000 0.2983	POJ/PTS = - 0120369144 CPB	RUN 6 352. 8 352. 3 352. 3 352. 3 352. 8 352. 9 352. 4 352. 0 352.
Q= P0: ALPHA 4.04 3.03 2.01 1.49 0.97 0.46 -0.05 -0.56 -1.07 -1.58 -2.09 -3.10	6.37 PSI = 193.0 CM CN 0.3947 0.2901 0.1865 0.1320 0.0814 0.0336 -0.0151 -0.0650 -0.1141 -0.1642	RE PER HG PTS= CM -3.4835 -2.5718 -1.6716 -1.2020 -0.7626 -0.3466 0.0738 0.5070 0.9315 1.3665 1.8155 2.6936	IN.= .48 1.0109 F CS -0.0190 -0.0164 -0.0130 -0.0108 -0.0108 -0.0059 -0.0066	CY 0.1494 0.1237 0.1009 0.0868 0.0698 0.0505 0.0454 0.022 0.0045	90. DEG.F RUN NO CR CAT 0.0015 0.3076 0.0009 0.3052 0.0004 0.3020 0.0003 0.3014 0.0002 0.2988 0.0004 0.2998 0.0004 0.2998 0.0001 0.2983 0.0002 0.2966	PDJ/PTS = . 0120369144 CPB	RUN 6 352. 8 352. 3 352. 3 352. 1 352. 8 352. 8 352. 9 352. 4 352. 0 352.

MODEL 946.2	CONF	IG. 2.000	" MA	CH 3.00		= 1K9	30.	
Q= 6.37 PSI	RE PER	IN.= .48E06	T0=	90. DE	g.F	19\L09	'S = 40	•
PO= 193.0 C	HHG P1S=	1.0109 PŠI		1	RUN NO.	012036	9145	
ALPHA CH	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.04 0.3808	-3.4075	-0.0337	0.2338	0.0036	0.3043	0.1110	0.1932	353.
3.02 0.2774	-2.5096	-0.0299	0.1986	0.0011	0.3062	0.1105	0.1957	353.
2.00 0.1740	-1.6125	-0.0277	0.1815-	0.0009	0.3022	0.1098	0.1924	353.
1.48 0.1202	-1.1489		0.1767-	-0.0012	0.3015	0.1090	0.1925	353.
0.57 0.0709	-0.7197	-0.0226	0.1331-	-0.0022	0.2998	0.1088	0.1911	353.
0.45 0.0201	-0.2757	-0.0205	0-1123-	-0.0007	0.2982	0.1082	0.1899	353.
-0.07 -0.0307	0.1642	-0.0184		-0.0009				353.
-0.57 -0.0798	0.5923	-0.0159	0.0596	0.0007	0.2966	0.1072	0.1894	353.
-1.08 -0.1298	1.0269	-0.0133		0.0012				353.
-1-59 -0.1799	1.4627	-0.0124		0.0013				∙353∙
-2.09 -0.2318	1.9163	-0.0136		0.0002				353.
-3.10 -0.3314		-0.0093		0.0022				353.
-4.13 -0.4423	3.7589	-0.0092	0.0048	0.0035	0.2974	0.1091	0.1882	353.
MODEL 946.2		FIG. 2.000		ACH 3.00		= 1H9		1 _
Q= 6.37 PSI	RE PER	IN.= .48EQ		90. DE	G.F	P01/P1	TS = 100) .
	RE PER	IN.= .48EQ		90. DE	G.F		TS = 100) .
Q= 6.37 PSI	RE PER	IN.= .48EQ		90. DE	G.F	P01/P1	TS = 100	Run
Q= 6.37 PSI PO= 193.0 C ALPHA CN	RE PER KHG PTS=	IN.= .48EQ	6 TO=	90. DE	G.F RUN, NO. CAT	POJ/P1 012030 CPB	TS = 100 69146 CAF	•
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290	RE PER KHG PTS= CM -3.0696	IN.= .48EQ	6 TO= CY 0.5072	90. DE	G.F RUN, NO. CAT C.3118	POJ/P1 012030 CPB 0-1109	TS = 100 69146 CAF 0.2008	RUN-
Q= 6.37 PSI PO= 193.0 C ALPHA CN	RE PER KHG PTS= CM -3.0696 -2.1977	IN.= .48EQ 1.0109 PSI CS -0.0716	6 TO= CY 0.5072 0.4757	90. DE CR 0.0052	G.F RUN, NO. CAT 0.3118 0.3111	POJ/P1 O12030 CPB O.1109 O.1104	TS = 100 69146 CAF 0.2908 0.2007	RUN- 354*•
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283	RE PER CM -3.0696 -2.1977 -1.3223	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673	6 TO= CY 0.5072 0.4757 0.4388	90. DE CR 0.0052 0.0005	CAT 0-3118 0-3042	POJ/P1 - 012036 - CPB - 0.1109 - 0.1104 - 0.1096	TS = 100 69146 CAF 0.2008 0.2007 0.1947	RUN- 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627	CY 0.5072 0.4757 0.4388 0.4327	90. DE CR 0.0052 0.0005 -0.0049	CAT 0.3118 0.3111 0.3042 0.3028	POJ/P1 . 012036 . CPB 0.1109 0.1104 .0.1096 0.1087	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941	RUN- 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529	CY 0.5072 0.4757 0.4388 0.4327 0.3751	90. DE CR 0.0052 0.0005 -0.0049	CAT 0.3118 0.3111 0.3042 0.3028 0.3010	POJ/Pi - 012030 - CPB - 0.1109 - 0.1104 - 0.1095 - 0.1087 - 0.1083	IS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927	RUN- 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.3436	90. DE CR 0.0052 0.0005 -0.0049 -0.0056	G.F RUN, NO. CAT 0.3118 0.3111 0.3042 0.3028 0.3010	POJ/P7 . 012030 CPB 0.1109 0.1104 0.1096 0.1087 0.1083 0.1078	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 0.1899	RUN- 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205 0.42 -0.0319	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686 0.5041	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.3406 0.3051 0.2709	90. DE CR 0.0052 0.0005 -0.0049 -0.0056 -0.0040 -0.0021 -0.0001	CAT 0.3118 0.3111 0.3042 0.3028 0.3010 0.2977 0.2968 0.2934	POJ/Pi - 012030 - CPB - 0.1109 - 0.1096 - 0.1087 - 0.1083 - 1078 - 0.1069 - 0.1069	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 C.1899 0.1899 0.1871	RUN- 354. 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205 0.42 -0.0319 -0.0815	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686 0.5041 0.9528	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529 -0.0496	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.3406 0.3051 0.2709 0.2272	90. DE CR 0.0052 0.0005 -0.0049 -0.0056 -0.0021 -0.0001 0.0011 0.0023	CAT C.3118 C.3111 C.3111 C.3028 C.3028 C.3010 C.2977 C.2968 C.2934 C.2890	POJ/Pi - 012030 - CPB - 0.1109 - 0.1094 - 0.1087 - 0.1083 - 1078 - 0.1069 - 0.1063 - 0.1063 - 0.1062	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 C.1899 0.1899 0.1871 0.1828	RUN- 354. 354. 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205 0.42 -0.0319 -0.08 -0.0815 -0.60 ~0.1327	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686 0.5041 0.9528 1.4071 1.8461	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529 -0.0496 -0.0496 -0.0426 -0.0413	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.34051 0.2709 0.2272 0.2098	90. DE CR 0.0052 0.0005 -0.0049 -0.0056 -0.0011 -0.0001 0.0011 0.0023 0.0032	G.F RUN, NO. CAT 0.3118 0.3111 0.3042 0.3028 0.3010 0.2977 0.2968 0.2974 0.2934 0.2890 0.2996	POJ/Pi - 012036 CPB 0.1109 0.1104 -0.1096 0.1087 0.1083 0.1078 0.1069 0.1062 0.1062	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 0.1899 0.1899 0.1871 0.1828 0.1934	RUN- 354. 354. 354. 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205 0.42 -0.0319 -0.08 -0.0815 -0.60 ~0.1327 -1.10 -0.1846 -1.61 -0.2351 -2.13 -0.2907	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686 0.5041 0.9528 1.4071 1.8461 2.3371	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529 -0.0496 -0.0467 -0.0426 -0.0413 -0.0393	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.3406 0.2709 0.2272 0.2098 0.1891	90. DE CR 0.0052 0.0005 -0.0049 -0.0056 -0.0021 -0.0001 0.0011 0.0023 0.0032 0.0032	CAT C.3118 O.3111 O.3042 O.3028 O.3010 O.2977 O.2968 O.2930 O.2930 O.2930 O.2930	POJ/Pi - 012036 CPB 0.1109 0.1104 0.1096 0.1087 0.1083 0.1078 0.1069 0.1062 0.1061	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 C.1899 0.1899 0.1871 0.1828 0.1934 0.1850	RUN- 354. 354. 354. 354. 354. 354. 354. 354.
Q= 6.37 PSI PO= 193.0 C ALPHA CN 4.01 0.3290 3.00 0.2283 1.98 0.1274 1.45 0.0705 0.94 0.0205 0.94 0.0205 0.42 -0.0319 -0.08 -0.0815 -0.60 -0.1327 -1.10 -0.1846 -1.61 -0.2351	RE PER CM -3.0696 -2.1977 -1.3223 -0.8283 -0.3909 0.0686 0.5041 0.9528 1.4071 1.8461 2.3371 3.1922	IN.= .48EQ 1.0109 PSI CS -0.0716 -0.0673 -0.0627 -0.0619 -0.0561 -0.0529 -0.0496 -0.0496 -0.0426 -0.0413	CY 0.5072 0.4757 0.4388 0.4327 0.3751 0.3406 0.3051 0.2709 0.2272 0.2098 0.1891 0.1479	90. DE CR 0.0052 0.0005 -0.0049 -0.0056 -0.0011 -0.0001 0.0011 0.0023 0.0032	CAT C.3118 O.3111 O.3042 O.3028 O.3010 O.2977 O.2968 O.2934 O.2934 O.2996 O.2954	POJ/Pi - 012030 CPB 0.1109 0.1104 0.1096 0.1087 0.1083 0.1078 0.1063 0.1062 0.1062 0.1062 0.1062	TS = 100 69146 CAF 0.2008 0.2007 0.1947 0.1941 0.1927 C.1899 0.1899 0.1871 0.1828 0.1934 0.1850 0.1895	RUN- 354. 354. 354. 354. 354. 354. 354. 354.

HO	DEL 946.2	CON	FIG. 2.	DOD MACE	1 3.00	PHI = 4	·5.
Q=	6.37 PSI	RE PER	IN.= .4	BE06 TO= 9	90. DEG.F	279\L09	• • .
۶0:	= 193.0 C	MHG PTS=	1.0109	22	RUN NO	. 012036914	•7
ALPHA	CN	СМ	cs	CY	CR CAT	CPB CA	AF RUN
	1.3292	-11.6228	-0.0407	0.3516-0	.0ò20 0.3180	0.1177 0.2	
9.22		-10.1107			0018 0.3170		
8.18	0.9832		-0.0373		0022 0-3183		
7.15 6.12	0.8272 0.6799		-0.0313 -C.0254		.0009 0.3167 .0010 0.3123		
5.09			-0.0231		0025 0-3104		
4.06	0.4226		-0.0180		0012 0.3049		
3.04	0.3092		-0.0155		0021 0.3020		
2.02	0.2023	-1.7491	-0.0122		0019 0-2989		
1.49	0.1454	~1.2594			0012 0-2980		
	0.0921	-0-7902			0028 0-2995		
0.47			-0.0079		0020 0-2993		
	-0.0031 -0.0509		-0.0045		.0021 0.2972 .0013 0.2978		
	-0.1001		-0.0012		0017 0.2967		
	-0.1542		-0.0019		0018 0-2973		
-2.08	-0.2011	1.7353			0015 0.2979		
	-0.3033	2:6266	0.0092	-0.0989-0	0008 0-2964	0-1089 0-1	.876 355.
-4.11	-0.4118	3.5695	0.0128	-0.1321-0.	.0010 O.2986	0.1103 0.1	894 355.
	DEL 946.2 6.37 PSI	CONI RE PER	FIG. 2.0 IN.= .48		1 3.00 10. DEG.F	PHI = 4	.5. : 10.
Q=		RE PER	IN.= .48	1E06 TO= 9	00. DEG.F		10.
Q=	6.37 PSI	RE PER	IN.= .48	1E06 TO= 9	00. DEG.F	= 279\LO9	. 10 . 8
Q= P0:	6.37 PSI : 193.0 CP CN	RE PER	IN.= .48 1.0109 F	1E06 TO= 9	10. DEG.F RŲN NO	POJ/PTS = • 012036914 CPB CA	: 10. 8 .F RUN
Q= PO: ALPHA 10.25 9.22	6.37 PSI 193.0 CP CN 1.3C96 1.1361	RE PER ING PTS=	IN.= .48 1.0109 F -CS -0.0492	SE06 TO= 9 SI CY 0.4131 0.	DO. DEG.F RỤN NO CR CAT	POJ/PTS = - 012036914 - CPB CA - 0.1178 0.2	10. 8 F RUN 070 356.
Q= PO: ALPHA 10.25 9.22 8.18	6.37 PSI E 193.0 CP CN 1.3696 1.1361 0.9653	RE PER HHG PTS= CM -11.4726 -9.9635 -8.4647	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545	CY 0.4131 0.0.4936-0.0.4651-0.	RUN NO CR CAT .0006 0-3248 .0008 0-3222 .0007 0-3218	POJ/PTS = . 012036914	8 IO. 8 RUN 070 356. 038 356. 021 356.
Q= PO: ALPHA 10.25 9.22 8.18 7.14	6.37 PSI E 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134	RE PER HHG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361	IN.= .48 1.0109 F -CS -0.0492 -0.0570 -0.0545 -0.0406	CY 0.4131 0. 0.4936-0. 0.4551-0.	PO. DEG.F RUN NO CR CAT .0006 0.3248 .0008 0.3228 .0007 0.3218	POJ/PTS = . 012036914	8 F RUN 070 356- 038 356- 021 356- 016 356-
Q= PO: ALPHA 10.25 9.22 8.18 7.14 6.11	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654	RE PER HG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0.	RUN NO CR CAT .0006 0-3248 .0008 0-3222 .0007 0-3218 .0005 0-3209 .0006 0-3165	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1174 0.1	10. 8 IF RUN 1070 356. 038 356. 021 356. 016 356. 991 356.
Q= PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08	6.37 PSI E 193.0 CP CN 1.3096 1.1361 0.9653 0.8134 0.6654 0.5336	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.48294 -4.6665	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303	CY 0.4131 0. 0.4936-9. 0.4651-0. 0.2909-0.	RUN NO CR CAT .0006 0-3248 .0006 0-3222 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128	POJ/PTS = . 012036914	10. 8 F RUN 070 356. 038 356. 021 356. 016 356. 971 356.
Q= PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.2463-0. 0.1887-0.	CR CAT .0006 0-3248 .0008 0-3228 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128 .0019 0-3133	POJ/PTS = . 012036914 CPB	8 RUN 070 356- 038 356- 021 356- 016 356- 991 356- 991 356- 975 356- 002 356-
Q= PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08	6.37 PSI E 193.0 CP CN 1.3096 1.1361 0.9653 0.8134 0.6654 0.5336	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.48294 -4.6665	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.0201	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.1867-0.	RUN NO CR CAT .0006 0-3248 .0006 0-3222 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1174 0.1 0.1153 0.1 0.1131 0.1	8 RUN 356. 038 356. 021 356. 091 356. 975 356. 002 356. 964 356.
PO= ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026	RE PER CM -11.4726 -9.9635 -8.4636 -5.8294 -4.6665 -3.6241 -2.6305	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.0201 -0.0141	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.1454-0. 0.0889-0.	RUN NO CR CAT .0006 0.3248 .0008 0.3228 .0007 0.3218 .0005 0.3209 .0006 0.3165 .0013 0.3128 .0019 0.3133 .0028 0.3077	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1174 0.1 0.1153 0.1 0.1131 0.2 0.1113 0.1 0.1099 0.1	10. 8 AF RUN 1070 356. 1038 356. 1016 356. 1016 356. 1017 356. 1018 356. 1019 356. 1019 356. 1019 356. 1019 356. 1019 356. 1019 356. 1019 356.
PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04 2.01 1.48	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839	RE PER HG PTS= CM -11.4726 -9.96358.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6505 -1.7177 -1.1796 -0.7531	IN.= .48 1.0109 F -CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.0201 -0.0107 -0.0088	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.0889-0. 0.0594-0. 0.0594-0.	RUN NO CR CAT .0006 0-3248 .0008 0-3228 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3162 .0019 0-3133 .0028 0-3077 .0033 0-3038 .0027 0-2993 .0035 0-3017	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1153 0.1 0.1153 0.1 0.1153 0.1 0.1099 0.1 0.1087 0.1	10. 8 F RUN 070 356. 038 356. 021 356. 91 356. 975 356. 902 356. 964 356. 938 356. 938 356. 939 356.
Q= P0° ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 4.06 2.01 1.48 0.97 0.46	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839 0.0363	RE PER CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6305 -1.7177 -1.1796 -0.7531 -0.3429	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0205 -0.0201 -0.0107 -0.0068 -0.0063	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.1887-0. 0.1854-0. 0.0889-0. 0.0594-0. 0.0194-0.	RUN NO CR CAT .0006 0-3248 .0008 0-3222 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3123 .0028 0-3077 .0033 0-3038 .0027 0-2993 .0031 0-3014	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1197 0.2 0.1174 0.1 0.1153 0.1 0.1131 0.2 0.1131 0.2 0.1131 0.1 0.1099 0.1 0.1089 0.1 0.1087 0.1	10. 8 F RUN 070 356. 038 356. 021 356. 091 356. 991 356. 975 356. 002 356. 938 356. 938 356. 938 356. 938 356.
PO- ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04 1.48 0.97 0.46	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839 0.0363 -0.0092	RE PER CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6905 -1.7177 -1.1796 -0.7531 -0.3429 0.0494	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0353 -0.0303 -0.0245 -0.0201 -0.0107 -0.0088 -0.0063 -0.0023	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.1887-0. 0.0889-0. 0.0594-0. 0.0194-00.0186-0.	CR CAT .0006 0-3248 .0007 0-3218 .0005 0-3209 .0006 0-3162 .0019 0-3133 .0028 0-3077 .0031 0-3038 .0027 0-2993 .0035 0-3017 .0031 0-3014 .0031 0-3014	POJ/PTS = . 012036914 CPB	10. 8 F RUN .070 356. 038 356. 021 356. 016 356. 991 356. 002 356. 002 356. 964 356. 938 356. 904 356. 939 356. 939 356.
PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04 2.01 1.48 0.97 0.46 -0.056	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1334 0.0839 0.0363 0.0032 -0.0092 -0.0596	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6505 -1.7177 -1.1796 -0.7531 -0.3429 0.0494 0.4856	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.0201 -0.0107 -0.0088 -0.0063 -0.0063 -0.0063	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.1887-0. 0.0889-0. 0.0894-0. 0.0194-0. 0.0194-00.0186-0.	CR CAT .0006 0-3248 .0008 0-3228 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128 .0019 0-3133 .0028 0-3077 .0031 0-3013 .0031 0-3014 .0031 0-3019 .0030 0-2930	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1174 0.1 0.1133 0.1 0.1131 0.2 0.1113 0.1 0.1089 0.1 0.1087 0.1 0.1085 0.1 0.1085 0.1 0.1084 0.1	10. 8 F RUN 070 356. 038 356. 021 356. 91 356. 975 356. 975 356. 964 356. 938 356. 938 356. 938 356. 938 356. 939 356. 930 356. 930 356.
PO: ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04 2.01 1.48 0.97 0.46 -0.05 -0.56 -1.07	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839 0.0363 -0.0092 -0.0596 -0.1125	RE PER ARG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6305 -1.7177 -1.1796 -0.7531 -0.3429 0.0494 0.4856 0.9476	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0245 -0.0201 -0.0107 -0.0088 -0.0023 -0.0023 -0.0024	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.3391-0. 0.2909-0. 0.1454-0. 0.0889-0. 0.0594-0. 0.0594-0. 0.0194-00.01865-00.0345-0.	RUN NO CR CAT .0006 0.3248 .0008 0.3228 .0007 0.3218 .0005 0.3209 .0006 0.3165 .0013 0.3128 .0019 0.3133 .0028 0.3077 .0033 0.3038 .0027 0.2930 .0031 0.3014 .0031 0.3014 .0031 0.3014 .0031 0.3014 .0031 0.2930 .0025 0.2937	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1193 0.2 0.1153 0.1 0.1153 0.1 0.1153 0.1 0.1099 0.1 0.1089 0.1 0.1085 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1	10. 8 F RUN 070 356. 038 356. 021 356. 091 356. 991 356. 995 356. 996 356. 938 356. 904 356. 939 356. 929 356. 939 356. 845 356.
PO* ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 3.04 2.01 1.48 0.97 0.46 -0.05 -0.56 -1.07	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839 0.0363 -0.0092 -0.0596 -0.1125 -0.1614	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6505 -1.7177 -1.1796 -0.7531 -0.3429 0.0494 0.4856	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.0201 -0.0107 -0.0088 -0.0063 -0.0063 -0.0063	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.2909-0. 0.2463-0. 0.1867-0. 0.1854-0. 0.0889-0. 0.0141-0. 0.0194-00.0186-00.0262-00.0492-0.	CR CAT .0006 0-3248 .0008 0-3228 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128 .0019 0-3133 .0028 0-3077 .0031 0-3013 .0031 0-3014 .0031 0-3019 .0030 0-2930	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1197 0.2 0.1197 0.2 0.1174 0.1 0.1153 0.1 0.1153 0.1 0.1131 0.2 0.1131 0.2 0.1131 0.1 0.1099 0.1 0.1089 0.1 0.1087 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1080 0.1	10. 8 F RUN 1070 356. 1038 356. 1021 356. 1016 356. 1975 356. 1002 356. 1938 356. 1938 356. 1938 356. 1939 356. 1939 356. 1939 356. 1939 356. 1939 356. 1939 356. 1939 356. 1939 356. 1939 356.
PO3 ALPHA 10.25 9.22 8.18 7.14 6.11 5.08 4.06 2.01 1.48 0.97 0.46 -0.05 -1.07 -1.57 -1.57 -1.57	6.37 PSI 193.0 CP CN 1.3C96 1.1361 0.9653 0.8134 0.6654 0.5336 0.4142 0.3026 0.1953 0.1334 0.0839 0.0363 -0.0092 -0.0596 -0.1125	RE PER 4RG PTS= CM -11.4726 -9.9635 -8.4647 -7.1361 -5.8294 -4.6665 -3.6241 -2.6505 -1.7177 -1.1796 -0.7531 -0.3429 0.4496 0.9476 1.3709 1.7877	IN.= .48 1.0109 F CS -0.0492 -0.0570 -0.0545 -0.0406 -0.0353 -0.0303 -0.0245 -0.021 -0.0107 -0.0088 -0.0063 -0.0063 -0.0064 -0.0012 -0.0014 -0.0012	CY 0.4131 0. 0.4936-0. 0.4651-0. 0.2909-0. 0.2463-0. 0.1887-0. 0.0889-0. 0.0594-0. 0.0194-00.0186-00.0345-00.0345-00.0492-00.0953-0.	RUN NO CR CAT .0006 0-3248 .0008 0-3222 .0007 0-3218 .0005 0-3209 .0006 0-3165 .0013 0-3128 .0028 0-3077 .0033 0-3038 .0027 0-2993 .0031 0-3017	POJ/PTS = . 012036914 CPB CA 0.1178 0.2 0.1184 0.2 0.1193 0.2 0.1193 0.2 0.1131 0.2 0.1131 0.2 0.1113 0.1 0.1099 0.1 0.1089 0.1 0.1085 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1084 0.1 0.1085 0.1 0.1084 0.1 0.1085 0.1 0.1086 0.1 0.1086 0.1 0.1080 0.1 0.1079 0.1 0.1079 0.1	8 F RUN 070 356. 038 356. 021 356. 911 356. 975 356. 902 356. 964 356. 938 356. 904 356. 939 356. 929 356. 939 356. 845 356. 889 356. 8915 356. 896 356.

HODEL 946.2	CONF	IG. 2.00	O MACH	3.00	PHI =	45.	
C= 6.37 PSI	RE PER	:N.= .486	06 <u>†</u> 0= 9	O. DEG.F	POJ/PTS	× 20.	
PO= 193.0 C	MHG PTS=	1.0109 PS	1	RUM NO	0120369	149	
ALPHA CN	CH	cs	CY	CR -CAT	-CPB	CAF	RUN
10.25 1.2972	-11.3855	-0.0493				•	
9.22 1.1217	~9.8530			0007 0.3240 0011 0.3248			357. 357.
8.18 0.9551	-8-3925			0002 0.3279			357.
7.14 0.8054	-7.0814			0015 0.3242			357.
5.11 0.6589	-5.7871			0029 0-3198			357-
5.08 0.5291	-4.6486	-0:0427	0.3423 0.	0022 0.3204	0.1156 0	-2048	357.
4.06 0.4109	-3.6171			0001 0.3130			357.
3.94 0.2975	-2.6272			0023 0.3082			357.
2.01 0.1915	-1.7082			0032 0-3052			-357.
1.48 0.1329 0.97 0.0851	-1-1984			0033 0.3052			357.
0.46 0.0318	-0.7886 -0.3182			0029 0.3013			357. 357.
-0.06 -0.0112	0.0435			0023 0-2962			357.
-0.36 -0.0638	0.5044			2023 0.2986			357.
-1.07 -0.1162	0.9607			6020 0.2993			357.
-1.58 -0.1705	1.4379			0024 0.2982			357.
-2.09 -0.2160	1.8304			0013 0-2970			357.
-3.10 -0.3182	2.7174	0.0042	-0.0954-0.	0011 0.2399	0.1076 0	-1923 -	357.
-4.12 -0.4295	3-6895	0.0070		0002 0.3012			357.
MODÉL 946.2 0= 6.37 PSI	CONF RE PER		•	3.00 0.0EG.F	* 1H9	45.	
Q= 6.37 PSI	RE PER	IN.= .48E	06 TO= 9	ð. DEG.F	POJ/PTS	= 40.	
Q= 6.37 PSI PO= 193.0 CI	RE PER HHG PTS≖ .	IN.= .48E 1 ₋ 0109 PS	06 TO= 9	Ö• DEG•F KUN HO•	POJ/PTS • 612036 9	= 40. 150	
Q= 6.37 PSI	RE PER	IN.= .48E	06 TO= 9	ð. DEG.F	POJ/PTS • 612036 9	= 40.	RUN
Q= 6.37 PSI PO= 193.0 CI	RE PER HHG PTS≖ .	IN.= .48E 1.0109 PS CS	06 TO= 9 I CY	Ö• DEG•F KUN HO•	POJ/PTS . 012036# CP8	= 40. 150 CAF	RUN 358:
Q= 6.37 PSI PO= 193.0 CI ALPHA CH	RE PER HHG PTS≖ . -CM	IN.= .48E 1.0109 PS CS -0.1004	06 TO= 9 I CY 0.8506 O.	Ö. DEG.F RUN HO. CR C4T	POJ/PTS . 0120369 CPS 0.1177 0	= 40. 150 CAF -2106	
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405	RE PER HHG PTS= - -CM -11.1802	IN.= .48E 1.0109 PS CS -0.1004 -0.1022	06 TO= 9 CY 0.8506 0. 0.8713 0. 0.8813 0.	0. DEG.F RUN HO. CR CAT 0019 0:3283 0024 0:3283 0044 0:3282	POJ/PTS 0120369 CPS 0.1177 0 0.1187 0 0.1199 0	# 40. 150 CAF .2106 .2100 .2084	358. 358. 358.
Q= 6.37 PSI PO= 193.0 CF ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876	RE PER HHG PTS= -CM -11.1802 -9.7054 -8.2975 -6.9493	IN.= .48E i_0109 PS CS -0.1004 -0.1022 -r;.0960 -0.0858	06 TO= 9 I CY 0.8506 0. 0.8713 0. 0.8213 0. 0.7165 0.	0. DEG.F RUN NO. CR CAT 0019 0:3283 0024 0:3283 0044 0:3282 0080 0:3229	POJ/PTS . 0120369 CPS 0.1177 0 0.1187 0 0.1199 0 0.1196 0	= 40. 150 CAF .2106 .2100 .2084	358. 358. 358.
Q= 6.37 PSI PD= 193.0 CI ALPHA CH 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443	RE PER HHG PTS= -CM -11.1802 -9.7054 -8.2975 -6.9493	IN.= .48E I.0109 PS CS -0.1004 -0.1022 -7.0960 -0.0858 -0.0745	06 TO= 9 I CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0.	0. DEG.F RUN NO. CR CAT 0019 0:3283 0024 0:3284 0044 0:3282 0080 0:3239	POJ/PTS . 0120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0	= 40. 150 CAF .2106 .2100 .2084 .2083 .2058	358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155	RE PER	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -7.0960 -0.0745 -0.0618	06 TO= 9 1 CY 0.8506 C. 0.8713 O. 0.8813 O. 0.7165 O. 0.4046 C. 0.4775 O.	CR CAT 0019 0:3283 0024 0:3283 0024 0:3282 0080 0:3282 0080 0:3236 0085 0:3146	POJ/PTS . 0120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1178 0	= 40. 150 CAF .2106 .2100 .2084 .2033 .2058 .1988	358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CF ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985	RE PER HHG PTS= -CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -7.0960 -0.0858 -0.0745 -0.0524	CY 0.8506 C. 0.8713 C. 0.8713 C. 0.7165 C. 0.6046 C. 0.4076 C. 0.3831 C.	0. DEG.F RUH HO. CR CAT 0019 0:3288 0044 0.3288 0044 0.3282 0080 0.3229 0083 0.3236 0065 0.3146	POJ/PTS O120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1178 0 0.1134 0	= 40. 150 CAF .2106 .2004 .2033 .2058 .1988	358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CF ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.7405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 0.2856	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0858 -0.0745 -0.0618 -0.0524 -0.0435	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0. 0.4775 0. 0.3831 0. 0.2968 0.	CR CAT 0019 0:3283 0024 0:3283 0024 0:3282 0080 0:3229 0083 0:3236 0085 0:3145 0033 0:3115 0001 0:3093	POJ/PTS O120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1158 9 0.1134 0 0.1114 0	= 40. 150 CAF ,2106 ,2100 ,2083 ,2083 ,2058 ,1988 ,1988	358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 Cl ALPHA CH 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 0.2856 2.00 0.1799	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5530 -2.5612 -1.6457	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0960 -0.0858 -0.0745 -0.0618 -0.0524 -0.0524 -0.0378	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0. 0.4775 0. 0.3831 0. 0.2968 0.	CR CAT 0019 0.3283 0024 0.3283 0024 0.3282 0080 0.3229 0083 0.3236 0065 0.3146 0033 0.3115 0001 0.3093 00026 0.3062	POJ/PTS O120369 CPS 0.1177 0 0.1187 0 0.1199 0 0.1178 0 0.1158 0 0.1114 0 0.1101 0	= 40. 150 CAF .2106 .2100 .2084 .2033 .2058 .1988 .1981 .1979	358. 358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CR ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 9.2856 2.00 0.1799 1.47 0.1249	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612 -1.6783	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -7.0960 -0.0858 -0.0745 -0.0618 -0.0524 -0.0435 -0.0378	CY 0.8506 C. 0.8713 O. 0.8713 O. 0.6046 O. 0.4775 O. 0.3831 O. 0.2968 O. 0.2465-O. 0.2121-O.	CR CAT 0019 0.3283 0024 0.3283 0044 0.3282 0080 0.3729 0083 0.3146 0033 0.3115 0001 0.3093 0026 0.3062 0038 0.3044	POJ/PTS 0120369 CPS 0.1177 0 0.1197 0 0.1198 0 0.1178 0 0.1178 0 0.1134 0 0.1114 0 0.11093 0	= 40. 150 CAF ,2106 .2100 .2084 .2033 .2058 .1988 .1981 .1979 .1979	358: 358: 358: 358: 358: 358: 358: 358:
Q= 6.37 PSI PO= 193.0 CF ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 0.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612 -1.6457 -1.1783 -0.7321	IN.= .48E 1.0109 PS CS -0.1004 -0.1002 -7.0960 -0.0858 -0.0745 -0.0524 -0.0435 -0.0378 -0.0378 -0.0378	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0. 0.4775 0. 0.3831 0. 0.2968 0. 0.2465-0. 0.2121-0. 0.2121-0.	CR CAT 0019 0.3283 0024 0.3283 0024 0.3283 0044 0.3282 0080 0.3729 0083 0.3236 0065 0.3146 0033 0.3145 0001 0.3062 0038 0.3062 0038 0.3064 0057 0.3063	POJ/PTS 0120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1134 0 0.1134 0 0.1101 0 0.1017 0 0.1017 0 0.1017 0 0.1017 0 0.1017 0	= 40. 150 CAF ,2106 ,2106 ,2084 ,2084 ,2088 ,1988 ,1988 ,1981 ,1979 ,1961 ,1936	358: 358: 358: 358: 358: 358: 358: 358:
Q= 6.37 PSI PO= 193.0 CR ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 9.2856 2.00 0.1799 1.47 0.1249	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612 -1.6783	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0858 -0.0745 -0.0618 -0.0524 -0.0378 -0.0378 -0.0341 -0.0321	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0. 0.4775 0. 0.3831 0. 0.2968 0. 0.2465-0. 0.2121-0. 0.2010-0. 0.1826-0.	CR CAT 0019 0.3283 0024 0.3283 0044 0.3282 0080 0.3729 0083 0.3146 0033 0.3115 0001 0.3093 0026 0.3062 0038 0.3044	POJ/PTS O120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1158 0 0.1114 0 0.1101 0 0.1093 0 0.1093 0 0.1082 0	= 40. 150 CAF ,2106 ,2100 ,2083 ,2083 ,2058 ,1988 ,1991 ,1979 ,1961 ,1951 ,1936	358: 358: 358: 358: 358: 358: 358: 358:
Q= 6.37 PSI PD= 193.0 CF ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 9.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742 0.45 0.0209	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5630 -2.5612 -1.6457 -1.1783 -0.7321 -0.2646	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0958 -0.0745 -0.0618 -0.0524 -0.0435 -0.0378 -0.0361 -0.0321 -0.0301	CY 0.8506 C. 0.8713 O. 0.813 O. 0.7165 O. 0.6046 C. 0.4775 O. 0.3831 O. 0.2965 O. 0.2465 O. 0.2121 O. 0.1826 O. 0.1826 O. 0.1395 O.	CR CAT 0019 0.3283 0024 0.3283 0024 0.3282 0080 0.3729 0083 0.3125 0005 0.3145 0001 0.3093 0026 0.3062 0039 0.3064 0057 0.3063	POJ/PTS 0120369 CPS 0.1137 0 0.1137 0 0.1138 0 0.1138 0 0.1134 0 0.1114 0 0.1010 0 0.1093 0 0.1087 0 0.1087 0	= 40. 150 CAF .2106 .2100 .2084 .2033 .2038 .1988 .1981 .1979 .1976 .1976 .1936 .1994	358. 358. 358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CI ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 0.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742 0.45 0.0209 -0.06 -0.0309	RE PER -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612 -1.6457 -1.1783 -0.7321 -0.2646 0.1869 0.6704	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0858 -0.0745 -0.0618 -0.0524 -0.0378 -0.0378 -0.0378 -0.0378 -0.0378 -0.0388 -0.0388 -0.0388 -0.0388	CY 0.8506 C. 0.8713 C. 0.8813 C. 0.7165 C. 0.6046 C. 0.4775 C. 0.3831 C. 0.2968 C. 0.2465 C. 0.2121 C. 0.2121 C. 0.1325 C. 0.1182 C. 0.1180 C.	CR CAT 0019 0.3283 0024 0.3282 0080 0.3729 0083 0.3236 0065 0.3146 0033 0.3115 0001 0.3093 0026 0.3093 0026 0.3093 0026 0.3093 0026 0.3093 0026 0.3093	POJ/PTS 0120369 CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1134 0 0.1134 0 0.1101 0 0.10101 0 0.1082 0 0.1087 0 0.1087 0 0.1077 0	= 40. 150 CAF ,2106 .2106 .2084 .2033 .2058 .1988 .1988 .1981 .1979 .1961 .1994 .1904 .1904	358. 358. 358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PD= 193.0 CI ALPHA CH 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 9.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742 0.45 0.0209 -0.06 -0.0309 -0.57 -0.0854 -1.08 -0.1336 -1.59 -0.1847	RE PER -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5630 -2.5612 -1.6457 -1.1783 -0.7321 -0.2646 0.1869 0.6704 1.0862 1.5312	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -0.0858 -0.0745 -0.0618 -0.0524 -0.0341 -0.0321 -0.0301 -0.0258 -0.0125	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.4775 0. 0.3831 0. 0.2968 0. 0.2465-0. 0.2121-0. 0.1826-0. 0.1826-0. 0.1880-0. 0.0388-0. 0.0085-0.	CR CAT 0019 0.3283 0024 0.3283 0024 0.3289 0040 0.3229 0083 0.3236 0065 0.3145 0001 0.3093 0026 0.3062 0038 0.3062 0038 0.3062 0038 0.3062 0036 0.2983 0026 0.2983 0026 0.2983	CPS 0.1177 0 0.1187 0 0.1187 0 0.1196 0 0.1178 0 0.1158 0 0.1114 0 0.1101 0 0.1093 0 0.1087 0 0.1087 0 0.1077 0 0.1075 0 0.1075 0 0.1076 0	= 40. 150 CAF ,2106 ,2100 ,2084 ,2033 ,2058 ,1981 ,1979 ,1961 ,1954 ,1996 ,1914 ,1906	358. 358. 358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PO= 193.0 CR ALPHA CN 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 0.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742 0.45 0.0209 -0.06 -0.0309 -0.57 -0.0854 -1.08 -0.1336 -1.59 -0.1847 -2.10 -0.2366	RE PER HHG PTS= CM -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5430 -2.5612 -1.6457 -1.1783 -0.7321 -0.2646 0.1869 0.6704 1.0862 1.5312 1.9822	IN.= .48E 1.0109 PS CS -0.1004 -0.1022 -7.0960 -0.0858 -0.0745 -0.0618 -0.0324 -0.0321 -0.0321 -0.0321 -0.0328 -0.0259 -0.0259 -0.0259 -0.0259	CY 0.8506 C. 0.8713 O. 0.8713 O. 0.8713 O. 0.6046 O. 0.4775 O. 0.3831 O. 0.2968 O. 0.2121-O. 0.1826-O. 0.1826-O. 0.1826-O. 0.1826-O. 0.180-O. 0.0388-O. 0.0065-O. 0.0005	CR CAT 0019 0:3283 0024 0:3283 0044 0:3282 0080 0:3729 0083 0:3126 0065 0:3146 0033 0:3115 0001 0:3093 00026 0:3062 0038 0:3044 0057 0:3023 0050 0:2983 0026 0:2989 0011 0:2985 0008 0:2983	CPS 0.1177 0 0.1187 0 0.1196 0 0.1178 0 0.1178 0 0.1178 0 0.1178 0 0.1101 0 0.10101 0 0.1087 0 0.1087 0 0.1075 0 0.1075 0 0.1076 0	= 40. 150 CAF .2106 .2100 .2084 .2033 .2058 .1988 .1979 .1961 .1979 .1961 .1914 .1914 .1914 .1906	358. 358. 358. 358. 358. 358. 358. 358.
Q= 6.37 PSI PD= 193.0 CI ALPHA CH 10.23 1.2703 9.21 1.1016 8.16 0.9405 7.13 0.7876 6.10 0.6443 5.07 0.5155 4.05 0.3985 3.03 9.2856 2.00 0.1799 1.47 0.1249 0.97 0.0742 0.45 0.0209 -0.06 -0.0309 -0.57 -0.0854 -1.08 -0.1336 -1.59 -0.1847	RE PER -11.1802 -9.7054 -8.2975 -6.9493 -5.6903 -4.5637 -3.5630 -2.5612 -1.6457 -1.1783 -0.7321 -0.2646 0.1869 0.6704 1.0862 1.5312	IN.= .48E 1.0109 PS CS -0.1004 -0.1002 -7.0960 -0.0858 -0.0745 -0.0378 -0.0378 -0.0378 -0.0301 -0.0301 -0.0321 -0.0301 -0.0125 -0.0238 -0.0161 -0.0125 -0.0092	CY 0.8506 0. 0.8713 0. 0.813 0. 0.7165 0. 0.6046 0. 0.4775 0. 0.3831 0. 0.2968 0. 0.2465-0. 0.2121-0. 0.1326-0. 0.1180-0. 0.0388-0. 0.0388-0. 0.0065-00.0200 00.0399 0.	CR CAT 0019 0.3283 0024 0.3283 0024 0.3289 0040 0.3229 0083 0.3236 0065 0.3145 0001 0.3093 0026 0.3062 0038 0.3062 0038 0.3062 0038 0.3062 0036 0.2983 0026 0.2983 0026 0.2983	POJ/PTS 0120369 CPS 0.1177 0 0.1197 0 0.1198 0 0.1198 0 0.1114 0 0.1101 0 0.1016 0 0.1087 0 0.1087 0 0.1073 0 0.1073 0 0.1075 0 0.1073 0 0.1076 0 0.1076 0	= 40. 150 CAF .2106 .2106 .2084 .2084 .2058 .1988 .1981 .1979 .1961 .1936 .1904 .1904 .1914 .1914 .1914	358. 358. 358. 358. 358. 358. 358. 358.

			•	•				
MODEL 946.2	CONI	FIG. 2.00	0 H	IČH 3.00	0	SHI =	45.	
Q= 6.37 PSI	RE PER	IH .= .48E	06 TO≠	90. 0	G.F	501\b.	rs = 10	0•
PO= 193.0 CM	HG PTS=	1.0109 PS	1		RUN- NO.	01203	6 91 51 -	
ALPHA CN	CM	. cs	CY	CR	CAT	CPB	EAF	RUŅ
10.20 1.2151	-10.7823	-0.1838			0.3297			359.
9.18 1.0523	-9.3500	-0.1877	1.5869	0.0163	9.3292	0.1183	0.2109	359.
8.14 0.8870	-7.8990	-0.1774			0.3320			359.
7.11 0.7440		-0.1546			0.3256			359.
5.08 0.6039	-5.4262	-0.1357			0.3209			359.
5.05 0.4772	-4-3169				0.3186			359.
4.03 0.3593		-0.1022			0.3145			359.
3.01 0.2490		-0.0933			0.3088			359.
1.98 0.1450		-0.0847			0,3074			359 .
1.45 0.0821		-0.0803			0.3030			359.
0.96 0.0363	-0.4978				0.3017			359.
0.43 -0.0247	0.0426				0.3016			359.
-0.06 -0.0694		-0.0668			0.2975			359•
-0.58 -0.1267	0.9394	-0.0609			0.2972			359.
-1.08 -0.1740	1.3588	-0.0563			0.2939			359.
-1.61 -0.2326		-0.0537·			0.2905			359.
	2.3049				0.2954			359•
-3.13 -0.3828 -4.15 -0.4915		-0.0463 -0.0422			0.3079 0.2988			359. 359.
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		000122	001702	0000.5		401 011		0071
MODEL 946.2	CON	FIG. 2.00	D M	ACH 3.00	0	PHI =	60.	
Q= 6.37 PSI	RE PER	IN.= .48E	06 TO=	90. D	EG.F	POJ/P	TS =	•
PO= 193.0 CM	HG PTS=	1.0109 PS	I		RUN NO	01203	69152	
ALPHA CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.01 0.4097	-3 .E400	-0.0070	0.0525	0.0060	0.3021	0.1007	0.1923	360.
3.00 0.3025		-0.0063			0.3034			360
1.98 0.1981		-0.0003			0.2987			360.
1.45 0.1396		-0.0044	_	-	0.2982			360.
0.93 0.0880		-0.0056			0.2976			360 •
0.43 0.0400		-0.0050			0.2987			360.
-0.08 -0.0062		-0.0014	-0.0008					360.
-0.60 -0.0552	0.4741		-0.0403					360.
-1.09 -0.1035	0.8928		-0.0454					360•
-1.62 -0.1577		-0.0011			0.2954			360.
-2.12 -0.2022	1.7467		-0.0659					360.
-3.13 -0.3068	2.6587		-0.1017					360.
-4.15 -0.4171	3.6215		-0.1723					360.
							-	

Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 10. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369153 ALPHA CN CM CS CY CR CAT CPB CAF RUN 4.00 0.4037 -3.5299 -0.0157 0.1048 0.0062 0.3061 0.1115 0.1946 361. 3.00 0.2966 -2.5935 -0.0120 0.0682 0.0052 0.3030 0.1107 0.1923 361. 1.97 0.1927 -1.6903 -0.0082 0.0334 0.0052 0.3017 0.1096 0.1922 361. 1.94 0.1342 -1.1018 -0.0085 0.0334 0.0052 0.3017 0.1096 0.1922 361. 0.94 0.0842 -0.7476 -0.0077 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.43 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2982 0.1083 0.1899 3610.58 -0.0631 0.5272 -0.0029 -0.0146 0.0052 0.2982 0.1084 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2967 0.1084 0.1863 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2943 0.1079 0.1894 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 NACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CH CS CY CR CAY CPB CAF RUN
ALPHA CN CM CS CY CR CAT CPB CAF RUN 4.00 0.4037 -3.5299 -0.0157 0.1048 0.0062 0.3061 0.1115 0.1946 361. 3.00 0.2966 -2.5935 -0.0120 0.0682 0.0052 0.3000 0.1107 0.1923 361. 1.97 0.1927 -1.6903 -0.0082 0.0334 0.0052 0.3017 0.1096 0.1922 361. 0.94 0.0842 -1.1818 -0.0085 9.0373 0.0057 0.3030 0.1088 0.1942 361. 0.94 0.0842 -0.7476 -0.0077 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.643 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1084 0.1896 3610.58 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2987 0.1084 0.1863 3611.09 -0.1125 0.9544 0.0006 -0.0166 0.0052 0.2969 0.1085 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0052 0.2945 0.1084 0.1861 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0059 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 MACH 3.00 PHI = 60. PO= 193.0 CMHG PTS= 1.0109 P5I RUN NO. 0120359154 ALPHA CN CM CS CY CR CAT CPB CAF RUN
4.00 0.4037 -3.5299 -0.0157 0.1048 0.0062 0.3061 0.1115 0.1946 361. 3.00 0.2966 -2.5935 -0.0120 0.0682 0.0052 0.3030 0.1107 0.1923 361. 1.97 0.1927 -1.6903 -0.0082 0.0334 0.0052 0.3017 0.1096 0.1922 361. 1.44 0.1342 -1.1818 -0.0085 9.0373 0.0057 0.3030 0.1088 0.1942 361. 0.94 0.0842 -0.7476 -0.0977 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.43 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2982 0.1083 0.1899 3610.58 -0.0631 0.5272 -0.0029 -0.0146 0.0052 0.2967 0.1084 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2945 0.1084 0.1883 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1885 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361.
3.00 0.2966 -2.5935 -0.0120 0.0682 0.0052 0.3030 0.1107 0.1923 361. 1.97 0.1927 -1.6903 -0.0082 0.0334 0.0052 0.3017 0.1096 0.1922 361. 1.44 0.1342 -1.1818 -0.0085 0.0373 0.0057 0.3030 0.1088 0.1942 361. 0.94 0.0842 -0.7476 -0.0077 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.643 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2987 0.1084 0.1863 3610.58 -0.0531 0.5272 -0.0029 -0.0146 0.0052 0.2967 0.1084 0.1863 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2945 0.1084 0.1863 3611.09 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.16 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 MACH 3.00 PHI = 60. PO= 193.0 CMHG PTS= 1.0109 P5I RUN NO. 0120369154 ALPHA CN CH CS CY CR CAT CPB CAF RUN
1.97 0.1927 -1.6903 -0.0082 0.0334 C.0052 0.3017 C.1096 0.1922 361. 1.44 0.1342 -1.1818 -0.0085 9.0373 0.0057 0.3030 0.1088 0.1942 361. 0.94 0.0842 -0.7476 -0.0077 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.43 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 C.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2987 0.1084 0.1863 3610.58 -0.0631 0.5272 -0.0029 -0.0146 0.0052 0.2969 0.1085 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2945 0.1084 0.1861 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 MACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CHHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CH CS CY CR CAT CPB CAF RUN
1.44 0.1342 -1.1818 -0.0085
0.94 0.0842 -0.7476 -0.0077 0.0299 0.0045 0.2980 0.1084 0.1896 361. 0.43 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2967 0.1084 0.1863 3610.58 -0.0631 0.5272 -0.0029 -0.0146 0.0052 0.2969 0.1085 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2945 0.1084 0.1861 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2
0.43 0.0339 -0.3096 -0.0076 0.0331 0.0051 0.2982 0.1083 0.1899 3610.08 -0.0144 0.1073 -0.0058 0.0156 0.0054 0.2967 0.1084 0.1863 3610.58 -0.0631 0.5272 -0.0029 -0.0146 0.0052 0.2969 0.1085 0.1883 3611.09 -0.1125 0.9544 0.0006 -0.0468 0.0062 0.2945 0.1084 0.1861 3611.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 MACH 3.00 PHI = 60. PO= 193.0 CMHG PTS= 1.0109 P51 RUN NO. 0120369154 ALPHA CN CH CS CY CR CAY CPB CAF RUN
-0.08 -0.0144
-0.58 -0.0531
-1.09 -0.1125
-1.61 -0.1617 1.3803 0.0018 -0.0585 0.0050 0.2973 0.1079 0.1894 3612.11 -0.2107 1.8050 0.0032 -0.0704 0.0052 0.2923 0.1078 0.1845 3613.14 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 MACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CM CS CY CR CAY CPB CAF RUN
-2.11 -0.2107
-3.16 -0.3162 2.7246 0.0078 -0.1113 0.0060 0.2962 0.1081 0.1881 3614.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 NACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CM CS CY CR CAY CPB CAF RUN
-4.16 -0.4270 3.6915 0.0145 -0.1765 0.0067 0.2974 0.1098 0.1876 361. MODEL 946.2 CONFIG. 2.000 NACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN.= .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CM CS CY CR CAY CPB CAF RUN
MODEL 946.2 CONFIG. 2.000 NACH 3.00 PHI = 60. Q= 6.37 PSI RE PER IN. = .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CH CS CY CR CAY CPB CAF RUN
Q= 6.37 PSI RE PER IN. = .48E06 TO= 90. DEG.F POJ/PTS = 20. PO= 193.0 CMHG PTS= 1.0109 PSI RUN NO. 0120369154 ALPHA CN CH CS CY CR CAT CPB CAF RUN
ALPHA CN CH CS CY CR CAY CPB CAF RUN
· · · · · · · · · · · · · · · · · · ·
4.01 0.4027 -3.5381 -0.0260 0.1727 0.0075 0.3128 0.1116 0.2012 362.
2.99 0.2952 -2.5994 -0.0212 0.1262 0.0068 0.3088 0.1107 0.1981 362.
1.97 0.1921 -1.7022 -0.0169 0.0896 0.0061 0.3057 0.1094 0.1963 362.
1.45 0.1332 -1.1934 -0.0150 0.0689 0.0044 0.3044 0.1086 0.1958 362.
0.94 0.0849 -0.7744 -0.0132 0.0567 0.0046 0.3010 0.1001 0.1929 362.
0.43 0.1346 -0.3392 -0.0112 0.0340 0.0064 0.2987 0.1081 0.1905 362.
-0.09 -0.0165 0.1067 -0.0098 0.0219 0.0051 0.3006 0.1082 0:1925 362.
-0.60 -0.0651
-1.10 -0.1170 0.9807 -0.0021 -0.0556 0.0059 0.2992 0.1081 0.1911 362.
-1.10 -0.1170
-1.10 -0.1170
-1.10 -0.1170

MOD	EL 946.2	CON	FIG. 2.00) H	ACH 3.00	P	HI =	60.	
Q=	6.37 PSI	RE PER	IN.= .48E	06 TO=	90. DEG.F	. 6	0J/P1	'S =	40-
P0=	193.0 CM	HG PTS=	1.0109 PS	t	RUN	NO. 0	12036	9155	
ĀLPHĀ	CN	CM	CS	CY	CR CA	T	CPB	CAF	RUN
4.00	0.3954	-3.4984	-0.0447	0.2953	0.0103 0.3	095 0.	1129	0.1974	363.
2.99	0.2896	-2.5761	-0:0379	0.2299	0.0088 0.3	089 0.	1112	0.1977	
1.97	0.1866	-1.6837	-0.0317	0.1760	0.0059 0.3	049 0.	1100	0.1950	363.
1-44	0.1296	-1.1936	-0.0328		0.0053 0.3				
	0.0810		-0.0270		0.0037 0.2				
0.42			-0.0226		0.0040 0.2				
	-0.0240	0.1447			0.0049-0.2				
	-0.6771		-0.0190		0.0074 0.2				
	-0.1316		-0.0225		0.0068 0.2				
	-0.1793		-0.0143		0.0056 0.2				
	-0.2360	,	-0.0215		0,0046 0.3				
		2.8222			0.0066 0.2				
-4.16	-0.4423	3.7927	-0.0067	-0.0514	0.0073 0.2	901 0.	1089	0.1812	363.
	EL 946.2		FIG. 2.00		ACH 3.00 90. DEG.F		HI = 0J/PT	60. 'S = 1	.00•
Q=	6.37 PSI	RE PER		06 TO=	90. DEG.F		OJ/PT	'S = 1	.00•
Q=	6.37 PSI	RE PER	IN.= .48E	06 TO=	90. DEG.F	P I NO. 0	OJ/PT	'S = 1	.00• RUN
Q= P0=	6.37 PSI 193.0 CM	RE PER HG PTS= CM	IN.= .48E	06 TO= I CY	90. DEG.F	P NO. 0	0J/PT 12036 CPB	S = 1 9156 CAF	RUN
Q= PO= Alpha	6.37 PSI 193.0 CM	RE PER HG PTS= CM -3.3730	IN.= .48E0	06 TO= I CY 026689	90. DEG.F RUN CR CA	P I NO. 0 IT II33 0.	OJ/PT 12036 CPB 1118	S = 1 9156 CAF 0.2015	RUN 364.
Q= P0= ALPHA 3.99	6.37 PSI 193.0 CM CN 0.3734	RE PER HG PTS= CM -3.3730 -2.4469	IN.= .48E0 1.0109 PS CS -0.0997	06 T0= I CY 0.6689 0.6198	90. DEG.F RUN CR CA 0.0131 0.3	P I NO. 0 IT I33 0.	0J/PT 12036 CPB 1118 1109	S = 1 9156 CAF 0.2015 0.1975	RUN 364. 364.
Q= P0= ALPHA 3.99 2.98	6.37 PSI 193.0 CM CN 0.3734 0.2667	RE PER HG PTS= CM -3.3730 -2.4469 -1.560	IN.= .48E0 1.0109 PS CS -0.0997 -0.0944	CY 0.6689 0.6198 0.5488	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3	PI NO. 0	0J/PT 12036 CPB 1118 1109 1093	S = 1 9156 CAF 0.2015 0.1975	RUN 364. 364. 364.
Q= PO= ALPHA 3.99 2.98 1.95 1.41	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862	CY 0.6689 0.6198 0.5488 0.5330	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3	P NO. 0 1 NO. 0 1133 O. 1084 O. 1044 O.	0J/PT 12036 CPB 1118 1109 1093 1082	S = 1 9156 CAF 0.2015 0.1975 0.1951	RUN 364. 364. 364. 364.
Q= PO= ALPHA 3.99 2.98 1.95 1.41	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363	IN-= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842	06 T0= CY 0.6689 0.6198 0.5488 0.5330 0.5373 0.5059	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0005 0.2 0.0018 0.3	1 NO. 0 133 O. 1084 O. 1044 O. 1048 O. 1954 O.	0J/PT 12036 CPB 1118 1109 1093 1082 1077 1073	S = 1 9156 CAF 0.2015 0.1951 0.1966 0.1877 0.1961	RUN 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.11	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842 -0.0844 -0.0613 -0.0754	CY 0.6689 0.6198 0.5488 0.5330 0.5373 0.5059 0.4464	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0005 0.2 0.0018 0.3 0.0057 0.2	NO. 0 1133 0. 1084 0. 1044 0. 1048 0. 1954 0. 1957 0.	0J/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069	CAF 0.2015 0.1951 0.1961 0.1961 0.1888	RUN 364. 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.11	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533 -0.1138	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401 0.8865	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842 -0.0844 -0.0613 -0.0754 -0.0784	CY 0.6689 0.6188 0.5330 0.5373 0.5059 0.4464 0.4736	90. DEG.F RUM CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0057 0.3 0.0057 0.2	NO. 0 1133 0. 1084 0. 1048 0. 1048 0. 1954 0. 1957 0.	OJ/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069 1071	CAF 0.2015 0.1951 0.1961 0.1868 0.1906	RUN 364. 364. 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.11 -0.61 -1.12	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533 -0.1138 -0.1656	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401 0.8865 1.3405	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842 -0.0844 -0.0613 -0.0754 -0.0784 -0.0708	CY 0.6689 0.6188 0.5330 0.5373 0.5059 0.4464 0.4736 0.3940	90. DEG.F RUM CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0057 0.3 0.0057 0.2 0.0078 0.2 0.0091 0.3	NO. 0 1133 0. 1084 0. 1048 0. 1048 0. 1954 0. 1957 0. 1957 0.	OJ/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069 1071 1072	CAF 0.2015 0.1956 0.1959 0.1961 0.1868 0.1906 0.1888	RUN 364. 364. 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.61 -1.12 -1.64	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533 -0.1138 -0.1656 -0.2192	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401 0.8865 1.3405 1.8093	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842 -0.0813 -0.0754 -0.0754 -0.0708 -0.0709	CY 0.6689 0.6198 0.5488 0.5330 0.5373 0.5059 0.4464 0.4736 0.3940 0.3968	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0057 0.2 0.0078 0.2 0.0091 0.2 0.0091 0.2 0.0101 0.2	1 NO. 0 1 NO. 0 1 NO. 0 1084 O. 1044 O. 1048 O. 1954 O. 1957 O. 1957 O. 1960 O.	0J/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069 1071 1072 1072	CAF 0.2015 0.1975 0.1951 0.1966 0.1877 0.1961 0.1888 0.1965	RUN 364. 364. 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.11 -0.61 -1.64 -2.14	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533 -0.1138 -0.1656 -0.2192 -0.2654	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401 0.8865 1.8093 2.2068	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0844 -0.0813 -0.0754 -0.0784 -0.0708 -0.0709 -0.0673	CY 0.6689 0.6198 0.5488 0.5330 0.5373 0.5059 0.4464 0.4736 0.3968 0.3661	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0057 0.2 0.0018 0.3 0.0057 0.2 0.0091 0.2 0.0101 0.2 0.0101 0.2 0.0107 0.2	1 NO. 0 1 133 0. 1084 0. 1044 0. 1048 0. 1954 0. 1957 0. 1977 0. 1960 0.	0J/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069 1071 1072 1072	CAF 0.2015 0.1975 0.1951 0.1961 0.1888 0.1966 0.1888 0.1966	RUN 364. 364. 364. 364. 364. 364. 364. 364.
Q= P0= ALPHA 3.99 2.98 1.95 1.41 0.92 0.41 -0.11 -0.61 -1.64 -2.14 -3.16	6.37 PSI 193.0 CM CN 0.3734 0.2667 0.1637 0.1080 0.0565 0.0021 -0.0533 -0.1138 -0.1656 -0.2192	RE PER HG PTS= CM -3.3730 -2.4469 -1.560 -1.0864 -0.6363 -0.1532 0.3401 0.8865 1.8093 2.2068 3.1031	IN.= .48E6 1.0109 PS CS -0.0997 -0.0944 -0.0862 -0.0842 -0.0813 -0.0754 -0.0754 -0.0708 -0.0709	CY 0.6689 0.6198 0.5488 0.5330 0.5373 0.5059 0.4464 0.4736 0.3968 0.3968 0.3661 0.3310	90. DEG.F RUN CR CA 0.0131 0.3 0.0090 0.3 0.0031 0.3 0.0021 0.3 0.0057 0.2 0.0078 0.2 0.0091 0.2 0.0091 0.2 0.0101 0.2	1 NO. 0 11 NO. 0 11 NO. 0 11 NO. 0 10 N	0J/PT 12036 CPB 1118 1109 1093 1082 1077 1073 1069 1071 1072 1072 1074 1068	S = 1 9156 CAF 0.2015 0.1975 0.1951 0.1966 0.1888 0.1906 0.1888 0.1865 0.1865 0.1874	RUN 364. 364. 364. 364. 364. 364. 364. 364.

MUD	EL 946.2	CONF	iG. 2.0)O H	ICH 3.00	PHI =	75.	
Q=	6.37 PSI	RE PER	IN.= .48	=GT 60	90. DEG.F	P0J/P	TS =	•
P0=	193.0 CM	HG PTS=	1.0109 P	SI .	RUN N	0. 01303	69102	
ALPHA	CN	CH	cs	CY	CR CAT	ČЬВ	CAF	RUN
4.01	0.4111	-3.5782	-0.0134	0.1197	0.0046 0.278	6 0.1089	0-1697	365.
2.99	0.3036	-2.6358	-0.0095	0.0832	0.0037 0.277	2 0.1088	0.1684	365.
1.97	0.1987	-1.7232	-0.0062		0.0036 0.275			
1.44	0.1418		-0.0056		0.0049 0.267			
0.93	C.0891		-0.0096		0.0035 0.267			
	0-0412		-0.0044		0.0033 0.272			
	-0.0094	_	-0.0071		0.0039 0.271			
	-0.0582		-0.0051		0.0036 0.270			
	0.1057		0.0018		0.0046 0.271			
	-0.1580	1.3667			0.0044 0.271			
	-0.2061	1.7836			0.0042 0.271			
	-0.3121	2.7084			0.0045 -0.270			
-4.13	-0.4225	3.6764	0.0157	-0.1492	0.0050 0.270	0 0-1048	0.1002	365.
	EL 946.2		FIG. 2.00		ACH 3.00 90. DEG.F	PHI =		10.
Q=		RE PER	IN-= -48	E06 TO=	90. DEG.F		TS =	10.
Q= P0=	6.37 PŞI 193.0 CM	RE PER	IN.= .489	=07 60=	90. DEG.F	POJ/P	TS = 69103	
Q=	6.37 PŞI	RE PER	IN-= -48	E06 TO=	90. DEG.F	POJ/P	TS =	10 . Run
Q= P0= Alpha	6.37 PSI 193.0 CM	RE PER HG PTS=	IN.= .488 1.0109 P:	CY 51 506 TO=	90. DEG.F RUN N	POJ/P 10. 01303 CPB	TS = 69103 CAF	กกม
Q= PO= ALPHA 4.01	6.37 PŞI 193.0 CM CN 0.4093	RE PER HG PTS= CM -3.5783	IN.= .488 1.0109 P: CS -0.0185	E06 TO= SI CY 0°-1320	90. DEG.F RUN N CR CAT 0.0046 0.291	POJ/P 10. 01303 CPB 2 0.1101	TS = 69103 CAF 0-1811	RUN . 366•
Q= PO= ALPHA 4.01 2.99	6.37 PSI 193.0 CM CN 0.4093 0.3009	RE PER HG PTS= CM -3.5783 -2.6288	IN.= .488 1.0109 P: CS -0.0185 -0.0179	CY 0.1320 0.1258	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288	POJ/P 10. 01303 CPB 2 0.1101 12 0.1097	TS = 69103 CAF 0.1811 0.1785	RUN 366• 366•
Q= PO= ALPHA 4.01 2.99 1.97	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146	CY 0.1320 0.1258 0.0927	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088	TS = 69103 CAF 0-1811 0-1785 0-1782	RUN 366. 366.
Q= PO= ALPHA 4.01 2.99 1.97 1.43	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195	CY 0'.1320 0.1258 0.0927 0.1426	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.288	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 0 0.1083	TS = 69103 CAF 0-1811 0-1785 0-1782 0-1787	RUN 366. 366. 366.
Q= PO= ALPHA 4.01 2.99 1.97 1.43 0.94	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0148 -0.0195 -0.0124	CY 0.1320 0.1258 0.0927 0.1426 0.0756	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.287 0.0036 0.284	POJ/P 10. 01303 CPB 2 0.1101 22 0.1097 0 0.1088 0 0.1083 9 0.1080	TS = 69103 CAF 0.1811 0.1785 0.1782 0.1787	RUN 366. 366. 366. 366.
Q= PO= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0119	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.284 0.0038 0.285	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 0 0.1083 9 0.1080 6 0.1080	TS = 69103 CAF 0-1811 0-1782 0-1782 0-1787 0-1769	RUN 366. 366. 366. 366. 366.
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43 -0.08	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387 -0.0099	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497 0.0703	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0119 -0.0108	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.284 0.0038 0.285 0.0040 G.281	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 0 0.1083 9 0.1080 6 0.1080 9 0.1083	TS = 69103 CAF 0-1811 0-1785 0-1782 0-1787 0-1769 0-1776	RUN 366. 366. 366. 366. 366. 366.
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43 -0.08 -0.59	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497 0.0703 0.5065	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0119 -0.0108 -0.0093	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584 0.0429	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.287 0.0038 0.287 0.0036 0.284 0.0038 0.285 0.0040 G.281 0.0041 0.283	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 0 0.1083 9 0.1080 9 0.1083 5 0.1085	TS = 69103 CAF 0-1811 0-1782 0-1782 0-1787 0-1776 0-1776	RUN 366. 366. 366. 366. 366. 366.
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.43 -0.08 -0.59 -1.10	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387 -0.0099 -0.0602	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.703 0.5065 0.9457	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0119 -0.0108	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584 0.0429 0.0708	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.285 0.0036 0.285 0.0040 G.281 0.0041 0.283 0.0043 0.286	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 9 0.1080 9 0.1080 9 0.1083 5 0.1085	TS = 69103 CAF 0.1811 0.1782 0.1782 0.1787 0.1776 0.1776 0.1736 0.1749	RUN 366. 366. 366. 366. 366. 366.
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43 -0.08 -0.59 -1.10 -1.62	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387 -0.0099 -0.0602 -0.1108 -0.1532	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497 0.0703 0.5065 0.9457 1.4001	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0148 -0.0195 -0.0124 -0.0119 -0.0108 -0.0093 -0.0121	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584 0.0429 0.0708 0.0430	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.287 0.0038 0.287 0.0036 0.284 0.0038 0.285 0.0040 G.281 0.0041 0.283	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1088 9 0.1080 9 0.1083 5 0.1085 9 0.1084 3 0.1080	TS = 69103 CAF 0.1811 0.1782 0.1782 0.1769 0.1776 0.1776 0.1749 0.1749	RUN 366. 366. 366. 366. 366. 366. 366.
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43 -0.08 -0.59 -1.10 -1.62 -2.12	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387 -0.0099 -0.0602 -0.1108	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497 0.0703 0.5065 0.9457 1.4001 1.8040	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0119 -0.0108 -0.0093 -0.0121 -0.0091	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584 0.0429 0.0708 0.0430 0.0202 -0.0159	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.285 0.0037 0.287 0.0038 0.285 0.0036 0.284 0.0038 0.285 0.0040 G.281 0.0041 0.283 0.0043 0.285 0.0043 0.285 0.0043 0.285	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1083 9 0.1080 6 0.1080 9 0.1085 5 0.1085 13 0.1080 15 0.1080	TS = 69103 CAF 0.1811 0.1785 0.1787 0.1769 0.1776 0.1749 0.1743 0.1747	RUN 366. 366. 366. 366. 366. 366. 366. 36
Q= P0= ALPHA 4.01 2.99 1.97 1.43 0.94 0.43 -0.08 -0.59 -1.10 -1.62 -2.12 -3.14	6.37 PSI 193.0 CM CN 0.4093 0.3009 0.1959 0.1362 0.0884 0.0387 -0.0099 -0.602 -0.1108 -0.1532 -0.2099	RE PER HG PTS= CM -3.5783 -2.6288 -1.7155 -1.1932 -0.7809 -0.3497 0.0703 0.5065 0.9457 1.4001 1.8040 2.7392	IN.= .488 1.0109 PS CS -0.0185 -0.0179 -0.0146 -0.0195 -0.0124 -0.0108 -0.0093 -0.0211 -0.0091 -0.0068	CY 0.1320 0.1258 0.0927 0.1426 0.0756 0.0700 0.0584 0.0429 0.0708 0.0430 0.0202 -0.0159	90. DEG.F RUN N CR CAT 0.0046 0.291 0.0038 0.288 0.0037 0.287 0.0038 0.285 0.0036 0.284 0.0038 0.285 0.0040 0.281 0.0041 0.283 0.0043 0.286 0.0048 0.282 0.0050 0.285	POJ/P 10. 01303 CPB 2 0.1101 2 0.1097 0 0.1083 9 0.1080 6 0.1080 9 0.1085 5 0.1085 13 0.1080 15 0.1080	TS = 69103 CAF 0.1811 0.1785 0.1787 0.1769 0.1776 0.1749 0.1743 0.1747	RUN 366. 366. 366. 366. 366. 366. 366. 36

HODEL	946•2		CONF	=1G.	2.000	M	ICH 3.01	0	PHI =	75.		
Q= 6.	37 PSI	RE	PER	IN.=	.48E0	5 TO=	90. DI	EG.F	POJ/P	rs =	20.	-
PO= 1	193 O CM	iG P	TS=	1.010	129 60			RUN NG	01303	69104		
ALPHA	CN	СМ	I	C:	5	CY	CR	CAT	СРВ	CAF	-	RUN
4.61 0	.4113	-3.6	097	-0.02	289			0.2989				367.
	3037			-0.0				0.2967				367.
	1984			-0.02				0.2962				367.
	1416			-0.03				0.2935				367.
0.92 0				-0.01				0.2933				367.
0.42 0				-0.0				0.2914				367.
-0.10 -0				-0.0				0.2904				367.
-0,59 -0				-0.0				0.2901				367.
-1.11 -0				-0.0				0.2899				367.
-1.62 -0	- , -		_	-0.03				0.2899				367.
-2.14 -0				-0.01				0.2913				367.
-3.14 -0 -4.16 -0				-0.00				0.2918 0.2912				367. 367.
-4-10 ~0	1.4213	3.0	740	-0.00	j4 (~	.0.0334	0.0000	0.2912	0.1092	0.102		301.
MODEL	. 946•2		CONF	·16.	2.000	М	ICH 3.00)	PHI =	75.		
Q= 6.	37 PSI	RE	PER	IN:=	-48E06	T0=	90. DE	G.F	POJ/P	rs =	40*	
P0= 1	93.0 CM	IG .P	TS=	1.010	9 PSI			RUN NO.	01303	S 9105		
ALPHA	CN	CM	I	C:	5	CY	CR	CÁT	CPB	CAF		RUN
4.01 0	·4120	-3'-6	303	-0.04	53	0.2843	0.0087	0.3076	0.1106	0.1970	0	368.
	3029			-0.04				0.3054				368.
	.1982	_		-0.03	_			0.3015		-		368.
	0.1431	- ,		-0.03				0.3006				368.
	0.0932			-0.0				0.2977				368.
	0.0402			-0.03	_			0.2959				368.
-0.09 -0				-0.03				0.2948				368.
-0.60 -0				-0.0				0.2937				368.
-1.10 -0				-0.03				0.2962				368.
-1.63 -0				-0.03				0.2950				368.
-2.13 -0	-2216	1.8	917	-0.03	308	0.1475	0.0071	0.2948	0.1070	0.1879	9	368.
-3.14 -0	-3238	2.7	784	-0.02	82	0.1285	0.0059	0.2944	0.1072	0.1872	2	368.
-4.16 -0	4345	3.7	451	-0.02	235	0.0841	0.0061	0.2957	0.1081	0.1876	5	368.

eren de la compressión del compressión de la compressión de la compressión de la compressión del compressión de la compressión de la compressión de la compr

MODEL 946.2	CONFIC	S. 2.000	H	CH 3-00)	PHI =	75.	
Q= 6.37 PSI	RE PER IN	4.= .48E06	T0=	90. DE	G.F	POJ/P	rs = 10	00.
PO= 193.0 C	HG PTS= 1.	.0109 PSI			RUN NO.	01303	5 91 06-	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
3.99 0.4036	-3.5928 -0	0.1055	0.6880	0.0119	0.3124	0.1106	0.2018	369.
2.98 0.2961	-2.6583 -0	0.0999		0.0084				369.
1.96 0.1916	-1.7576 -0			0.003L				369•
1.44 C.1340	-1.2636 -0			0.0002				369.
0.93 0.0830	-0.8227 -0			0.0004				369.
0.42 0.0298	-0.3527 -0			0.0016				369.
-0.10 -0.0280	0.1663 -0			0.0055				369.
-0.60 -0.0878	0.7086 -0			0.0078				369.
-1.12 -0.1423	1.1888 -0	: - :		0.0098				369.
-1.62 -0.1920	1.6196 -0			0.0111				369.
-2.13 -0.2437 -3.15 -0.3466	2.0638 -0 2.9508 -0			0.0093				369.
-4.17 -0.4558	3.8976 -0			0.0078				369. 369.
-4-11 -0-4330	. 2.0310 -(0.0004	0.4000	0.0000	U+2777	0.1012	0.1011	207.
MGDEL 946.2	CONFIC	G. 2.000	н	ICH 3.00)	PHI =	90.	
Q= 6.37 PSI	RE PER I	N.= .48EU6	5 TO=	90. DE	EG.F	POJ/P	rs =	•`
Q= 6.37 PSI PO= 193.0 CR			5 TO=	90. DE		POJ/P	_	•`
•			5 TO=	90. DE			_	•` RUN
PO= 193.0 SP ALPHA CN 10.22 1.3668	HRG PTS= 1. CM -12.0726 -0	.0109 PSI CS 0.0064	CY 0.0404	CR 0.0036	RUN NO. CAT 0.3319	. 013030 CPB 0.12G8	59107 CAF 0-2110	370.
PO= 193.0 CN ALPHA CN 10.22 1.3668 9.20 1.1863	CH -12.0726 -(.0109 PSI CS 0.0064 0.0142	CY 0.0404 0.1160	CR 0.0036 0.0041	CAT 0.2319 0.3309	013030 CPB 0.12G8 0.1211	0.2098	370. 370.
PO= 193.0 CN ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977	CH -12.0726 -(-10.4742 -(-8.7824 -(.0109 PSI CS 0.0064 0.0142 0.0085	CY 0.0404 0.1160 0.0580	CR 0.0036 0.0041 0.0042	CAT 0.3319 0.3309 0.3260	CPB 0.12G8 0.1211 0.1202	CAF 0.2110 0.2098 0.2058	370. 370. 370.
PO= 193.0 CN ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145	CY 0.0404 0.1160 0.0580 0.1177	CR 0.0036 0.0041 0.0042 0.0045	CAT 0.3319 0.3309 0.3260 0.3173	CPB 0.12G8 0.1211 0.1202 0.1171	0.2110 0.2098 0.2058 0.2002	370. 370. 370.
PO= 193.0 CN ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066	CY 0.0404 0.1160 0.0580 0.1177 0.0443	CR 0.0036 0.0041 0.0042 0.0045 0.0050	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128	59107 CAF 0.2110 0.2098 0.2058 0.2002 0.1956	370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0060	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086	0.2110 0.2098 0.2058 0.2002 0.1956 0.2009	370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0050	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3095	. 013030 CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086	0.2110 0.2098 0.2098 0.2098 0.2002 0.1956 0.2009 0.2009	370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121	CH -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295	CR 0.0036 0.0041 0.0045 0.0050 0.0050 0.0050 0.0051	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3095 0.3090 0.3034	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1086	0.2110 0.2110 0.2098 0.2098 0.2002 0.1956 0.2009 0.2004 0.1945	370. 370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051	CH -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449	CR 0.0036 0.0041 0.0042 0.0050 0.0050 0.0050 0.0051 0.0050	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3095 0.3094 0.3040	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1086 0.1089 0.1082	0.2110 0.2098 0.2058 0.2002 0.1956 0.2009 0.2004 0.1945 0.1958	370. 370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419	CH -12.0726 -0 -10.4742 -0 -8.7824 -0 -7.2888 -0 -5.9686 -0 -4.7814 -0 -2.7131 -0 -1.7768 -0 -1.2278 -0	.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0050 0.0051 0.0053	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3095 0.3094 0.3040 0.3042	. 013036 CPB 0.12C8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1089 0.1082 0.1078	0.2110 0.2098 0.2058 0.2002 0.1956 0.2004 0.1945 0.1958 0.1958	370. 370. 370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.7887 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0837	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0050 0.0051 0.0053 0.0051	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3094 0.3044 0.3042 0.3038	. 013030 CPB 0.12C8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079	0.2110 0.2098 0.2058 0.2002 0.1956 0.2009 0.2009 0.2004 0.1945 0.1958 0.1958	370. 370. 370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.3747 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0041	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0837 0.0198	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0050 0.0051 0.0053 0.0051 0.0052	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3094 0.3044 0.3042 0.3038 0.3030	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079 0.1082	0.2110 0.2098 0.2058 0.2002 0.1956 0.2009 0.2009 0.2009 0.1945 0.1958 0.1958 0.1959	370. 370. 370. 370. 370. 370. 370. 370.
PO= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.0056	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-2.7131 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.3747 -(0.0483 -(.0109 PSI CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0041 0.0054	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0837 0.0198 0.0340	CR 0.0036 0.0041 0.0045 0.0050 0.0050 0.0051 0.0053 0.0051 0.0052 0.0050	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3090 0.3034 0.3040 0.3042 0.3043 0.3043 0.3025	CPB 0.12G8 0.1211 0.1292 0.1171 0.1128 0.1086 0.1089 0.1089 0.1082 0.1079 0.1082 0.1086	0.2110 0.2098 0.2098 0.2002 0.1956 0.2009 0.2004 0.1945 0.1958 0.1959 0.1949	370. 370. 370. 370. 370. 370. 370. 370.
P0= 193.0 CN ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.0056 -0.58 -0.0549	CM -12.0726 -(-10.4742 -(-8.7824 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.3747 -(0.0483 -(0.4743 -(CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0041 0.0054 0.0033	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0483 0.0483 0.0198 0.0340 0.0137	CR 0.0036 0.0041 0.0042 0.0050 0.0050 0.0051 0.0053 0.0053 0.0051 0.0052 0.0051	CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3094 0.3044 0.3042 0.3042 0.3042 0.3030 0.3025 0.3037	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079 0.1082 0.1079 0.1082 0.1086 0.1090	0.2110 0.2098 0.2058 0.2002 0.1956 0.2009 0.2004 0.1945 0.1958 0.1958 0.1959 0.1949 0.1939	370. 370. 370. 370. 370. 370. 370. 370.
P0= 193.0 SN ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.0056 -0.58 -0.0549 -1.09 -0.1070	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-7.2888 -(-7.131 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.3747 -(0.0483 -(0.9267 -(CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0076 0.0114 0.00114 0.0054 0.0033 0.0055	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0480 0.0198 0.0198 0.0353	CR 0.0036 0.0041 0.0042 0.0050 0.0050 0.0051 0.0053 0.0051 0.0052 0.0051 0.0055	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3094 0.3044 0.3042 0.3038 0.3030 0.3025 0.3037 0.3022	CPB 0.12G8 0.1211 0.1202 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079 0.1082 0.1079 0.1082 0.1090	CAF 0.2110 0.2098 0.2058 0.2002 0.1956 0.2009 0.2004 0.1945 0.1958 U.1964 0.1959 0.1949 0.1949	370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370.
P0= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.0056 -0.58 -0.0549 -1.09 -0.1070 -1.59 -0.1550	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(0.7887 -(0.3747 -(0.4743 -(0.9267 -(1.3406 -(CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0041 0.0054 8.0033 0.0055	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0198 0.0340 0.0353 0.0353	CR 0.0036 0.0041 0.0042 0.0050 0.0050 0.0051 0.0053 0.0051 0.0052 0.0051 0.0056 0.0051	RUN NO. CAT 0.3319 0.3309 0.3260 0.3173 0.3085 0.3095 0.3095 0.3094 0.3042 0.3038 0.3037 0.3025 0.3037 0.3022 0.3017	CPB 0.12G8 0.1211 0.1202 0.1171 0.112e 0.1086 0.1089 0.1082 0.1079 0.1082 0.1079 0.1080 0.1080	0.2110 0.2098 0.2098 0.2098 0.2009 0.1956 0.2009 0.2004 0.1945 0.1958 0.1958 0.1959 0.1949 0.1949 0.1932 0.1932	370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370.
P0= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.056 -0.58 -0.0549 -1.09 -0.1070 -1.59 -0.1550 -2.10 -0.2039	CH -12.0726 -(-10.4742 -(-8.7824 -(-7.9888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(-0.7887 -(0.0483 -(0.4743 -(0.4743 -(1.3406 -(1.7667 -(CS 0.0064 0.0142 0.0085 0.0145 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0054 0.0054 0.0055 0.0055 0.0050 0.0058	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0480 0.0137 0.0340 0.0137 0.0353 0.0294 0.0181	CR 0.0036 0.0041 0.0042 0.0045 0.0050 0.0050 0.0051 0.0052 0.0051 0.0052 0.0051 0.0053	RUN NO. CAT 0.3319 0.3320 0.3260 0.3173 0.3085 0.3095 0.3095 0.3094 0.3042 0.3038 0.3025 0.3027 0.3022 0.3017 0.3020	CPB 0.12G8 0.1211 0.1212 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079 0.1082 0.1079 0.1089 0.1089 0.1089	CAF 0.2110 0.2098 0.2058 0.2058 0.2009 0.2009 0.2004 0.1958 0.1958 0.1959 0.1949 0.1949 0.1949 0.1932 0.1928	370. 370. 370. 370. 370. 370. 370. 370.
P0= 193.0 SM ALPHA CN 10.22 1.3668 9.20 1.1863 8.16 0.9977 7.12 0.8306 6.09 0.6820 5.06 0.5475 4.04 0.4254 3.02 0.3121 1.99 0.2051 1.47 0.1419 0.95 0.0912 0.44 0.0433 -0.08 -0.0056 -0.58 -0.0549 -1.09 -0.1070 -1.59 -0.1550	CM -12.0726 -(-10.4742 -(-8.7824 -(-7.2888 -(-5.9686 -(-4.7814 -(-3.7060 -(-2.7131 -(-1.7768 -(-1.2278 -(0.7887 -(0.3747 -(0.4743 -(0.9267 -(1.3406 -(CS 0.0064 0.0142 0.0085 0.0066 0.0037 0.0040 0.0051 0.0070 0.0076 0.0114 0.0054 0.0055 0.0055 0.0055	CY 0.0404 0.1160 0.0580 0.1177 0.0443 0.0179 0.0202 0.0295 0.0449 0.0480 0.0837 0.0198 0.0340 0.0137 0.0353 0.0294 0.0181 0.0009	CR 0.0036 0.0041 0.0042 0.0050 0.0050 0.0051 0.0053 0.0051 0.0052 0.0051 0.0056 0.0051	RUN NO. CAT 0.3319 0.3309 0.3260 0.317 0.3085 0.3095 0.3095 0.3095 0.3034 0.3042 0.3038 0.3030 0.3025 0.3037 0.3022 0.3024	CPB 0.12G8 0.1211 0.1292 0.1171 0.1128 0.1086 0.1089 0.1082 0.1079 0.1082 0.1086 0.1090 0.1089 0.1089	CAF 0.2110 0.2098 0.2058 0.2058 0.1956 0.2009 0.2004 0.1958 0.1958 0.1959 0.1949 0.1949 0.1949 0.1949 0.1933 0.1935	370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370. 370.

	MOE	EL	9.46	. 2	(CONF	1G.	2.0	000	H	ACH 3.	00		PHI =	90.	•	
	Q=	6.3	37 P	S 1	RE	PER	IN.	41	BE06	.TO=	90.	DEG.	F	POJ/P	TS ≖	10.	
	P0=	19	3.0	CMHG	P	T5=	1.0	109 1	P 5 1			RU	4 NB	. 01303	69108		
AL	PHA		CN		CH		(s		CY	CR	Ç	A.F	CPB	CAF		RUN
10	-22	.1.	364				-0.0		(.1541	0.008	5 0.3	3368	0.1204	0.216	5	371.
9	-20	ı.	181	8 -1	0.4	352	-0.0	118		.0474	0.008	6 0.3	3312	0.1207	0.210	14	371.
8	-16	0.	995	0 -	8.7	567	-0.6	206		.1366	0.007	6 D.3	3257	0.1199	0.205	9	371.
7	•13	٥.	827	6 -	7.2	808	-0.0	3223	C	-1636	0.006	8 0.3	3194	0.1165	0.202	9	371.
	.09		678				-0.0							0.1120			371.
5	-07	0.	545	7 -	4.7	678	-0.0	175						0.1089			371.
4	.04	٥.	423	2 -	3.6	895	-0.0	136		-0714	0.005	1 0.3	3104	0.1091	0.201	.3	371.
3	•02	0.	309	0 -	2.6	883	-0.0	113						0.1086			371.
	.00		202				-0.0							0.1077			371.
	-47		139		1.2	139	-0.0	094						0.1076			371.
			.087				-0.0							0.1076			371.
	•45		038				-0.0							0.1079			371.
			.011				-0.0							0.1084			.371.
			061				-0.0							0.1087			371.
			111				-0.0							0.1086			371.
-1	•60	-0.	162	6	1.4	070	-0.0	1095		0.0414	0:005	4 0.3	3029	0.1084	0-194	5	371.
-2	.10	-0.	211	5	1.8	321	-0.0	100						0.1083			371.
-3	-12	-0.	318	0	2.7	623	-9-0	093	0	-0403	0.004	7 0.3	3028	0.1086	0.194	-2	371.
-4	-14	-0.	429	9	3.7	443	-0.6	052	•	0057	0.095	2 0.3	3023	0.1098	0.192	25	371.
			946 37 P				IG.				ACH 3.		=	= 1H9	90. TS =		
	Q=	6.3	37 P.	SI	RE	PER	IK.	- 41	8E06		ACH 3. 90.	DEG.		POJ/P	TS ≠	20.	
••	Q= P0=	6.3	37 P 93.0		RE I	PER	IK.=	- 41 109 1	8E06	¥0≈	90.	DEG. F	N NO	POJ/P • 01303	59109 5		
AL	Q=	6.3	37 P.	SI	RE	PER	IK.=	- 41	8E06			DEG.	N NO	POJ/P	TS ≠		RUN
-	Q= P0=	6.3 : 19	37 P 93.0	S I CMHG	RE P	PER TS=	IK.=	- 41 109 1 S	8E06 >SI	TO=	90. CR	DEG. (RU!	N NO	POJ/P • 01303	TS = 69109 CAF	20.	
10	Q= PO= PHA	6.3	87 P 93.0 CN	SI CMHG	RE 1 - P' - CM 2.0	PER TS=	IK.:	- 40 109 1 S 0330	8E06 >SI	10= CY 0•2289	90. CR 0.010	DEG. F RU! C/	N NO AT 3409	P0J/P • 01303 CPB	TS = 59109 CAF 0-220	20.	RUN
10	Q= PO= PHA •22	6.3 : 19	37 P 93.0 CN .367	SI CMHG 01 11	RE 1 CH 2-0	PER TS= 767	IR.:	* •49 109 1 :S 0330 0392	8E06 >SI	10= CY 0-2289 0-2755	90. CR 0.010	DEG. 6 RU! C/	N NO AT 3409 3338	POJ/P - 01303 - CPB - 0-1202 - 0-1206	TS = 59109 CAF 0-220 0-213	20 . 97	RUN 372. 372.
10 9 8	Q= PO= PHA •22 •20	6.3 19	37 P 93.0 CN .367	SI CMHG 0 -1 1 -1 5 -	RE 1 CH 2.0 0.4	PER TS= 767 511 675	1.00 (0 -0.0	- 46 109 1 330 3392 3301	8E06 >SI	TO= CY 0.2289 0.2755 0.1923	90. CR 0.010 0.010	DEG. 6 RU! C/ 18 0-3 16 0-3	N NO AT 3409 3338 3297	POJ/P • 01303 CPB 0•1202	TS = 59109 CAF 0.220 0.213 0.210	20. 7 3	RUN 372.
10 9 8 7	Q= PO= PHA •22 •20 •16 •13	6.3 19	37 P. 93.0 CN .3676.184	SI CMHG 0 -1 1 -1 5 -	RE 1 CH 2.0 0.4 8.7	PER TS= 767 511 675 857	1.00 -0.0 -0.0 -0.0	330 330 330 392 301 3140	8E06 PSI	TO= CY 0.2289 0.2755 0.1923	90. CR 0.010 0.010 0.009 0.008	DEG. 6 RUI C/ 88 0-3 66 0-3 19 0-3	N NO AT 3409 3338 3297 3204	POJ/P - 01303 - CPB - 0.1202 - 0.1206 - 0.1194 - 0.1163	TS = 59109 CAF 0.220 0.213 0.210 0.204	20. 7 3 3	RUN 372. 372. 372. 372.
10 9 8 7 6	Q= PO= PHA •22 •20	6.3 19	37 P 33.0 CN 367 184 996 830 682	SI CMHG 0 -1 1 -1 5 - 5 - 7 -	RE 1 CM 2.0 0.4 8.7 7.2	PER TS= 767 511 675 857 761	1.00 -0.0 -0.0 -0.0 -0.0	330 330 3392 3301 3140	8E06 PSI	TO= CY 0.2289 0.2755 0.1923 0.0445 0.0068	90. CR 0.010 0.010 0.009 0.008	RUI C/ (8 0.3 (6 0.3 (9 0.3 (1 0.3	N NO. 3409 3338 3297 3204 3197	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123	TS = 69109 CAF 0.220 0.213 0.210 0.204 0.207	20. 27. 33. 33. 22. 74.	RUN 372. 372. 372. 372. 372.
10 9 8 7 6	Q= PO= PHA •22 •20 •16 •13 •10	6.3 19	37 P. 93.0 CN .3676.184	CMHG 0 -1 1 -1 5 - 7 - 1 -	RE 1 CM 2.0 0.4 8.7 7.2 5.9	PER 767 511 675 857 761	1.00 -0.0 -0.0 -0.0	330 330 3392 3301 3140 3143	8E06	TO= CY 0.2289 0.2755 0.1923 0.0445 0.0068	90. CR 0.010 0.010 0.009 0.008 0.007	RUI C/ (8 0.3 (6 0.3 (9 0.3 (1 0.3 (1 0.3 (9 0.3	N NO. 3409 3338 3297 3204 3197 3104	POJ/P - 01303 - CPB - 0.1202 - 0.1206 - 0.1194 - 0.1163	TS = 59109 CAF 0.220 0.213 0.210 0.204 0.207	20.	RUN 372. 372. 372. 372. 372.
10 9 8 7 6 5	PHA -22 -20 -16 -13 -10 -07	6.3 19	37 P 33.0 CN 367 184 996 830 682	CMHG 0 -1 1 -1 5 - 7 - 1 -8	RE 1 CH 2.0 0.4 8.7 7.2 5.9 4.7	PER 767 511 675 857 761 970	1.00 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	330 330 3392 3301 3140 3143 3143	8E06	TO= CY 0-2289 0-2755 0-1923 0-0445 0-0068 0-0405	90. CR 0.010 0.010 0.009 0.009 0.005 0.005	RUI C/ 8 0-3 6 0-3 1 0-3 1 0-3 2 0-3	N NO. 3409 3338 3297 3204 3197 3104 3117	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123 0-1091 0-1087	TS = 59109 CAF 0.220 0.213 0.210 0.204 0.207 0.201 0.201	20. 07 03 03 02 04 2	RUN 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4	PHA -22 -20 -16 -13 -10 -07	6.3 19 1. 1. 0. 0. 0.	37 P 93.0 CN 184 1996 830 682 549 424	CMHG 0 -1 1 -1 5 - 7 - 1 -8 8 - 4 -	RE 1 CM 2.0 0.4 8.7 7.2 5.9 4.7 3.7	PER TS= 767 511 675 857 761 970 045 112	1.00 -0.0 -0.0 -0.0 -0.0 -0.0	330 3392 3301 3140 3143 3143 3215	8E06	CY 0.2289 0.2755 0.1923 0.0445 0.0068 0.0405 0.1148	90. CR 0.010 0.010 0.009 0.008 0.007 0.005 0.005	RUI (8 0.3 (6 0.3 (1 0.3 (1 0.3 (2 0.3 (5 0.3	N NO 3409 3338 3297 3204 3197 3104 3117 3096	POJ/P O1303 CPB 0.1202 0.1206 0.1194 0.1163 0.1123 0.1091	CAF 0.220 0.213 0.210 0.204 0.207 0.201 0.203 0.201	20. 07 03 03 02 04 20 00	RUN 372. 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4 3	PHA -22 -20 -16 -13 -10 -07 -04	6.3 1.1 1.1 0.0 0.0	37 P 93.0 CN .367 .184 .996 .830 .682 .549	CMHG 0 -1 1 -1 5 - 7 - 8 - 4 - 7 -	RE 1 CH 2.0 0.4 8.7 7.2 5.9 4.7 2.7	PER TS= 767 511 675 857 761 970 045 112 627	1.00 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	330 3392 3301 3140 3143 3143 3215 3217	8E06 >SI	TO= CY 0.2289 0.2755 0.1923 0.0445 0.0465 0.1148 0.1202	90. CR 0.010 0.010 0.009 0.005 0.005 0.005	RUI 68 0-3 19 0-3 11 0-3 12 0-3 15 0-3 10 0-3	N NO 3409 3338 3297 3204 3197 3104 3117 3096	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123 0-1091 0-1083 0-1076	S9109 CAF 0.220 0.213 0.210 0.204 0.207 0.203 0.201 0.203 0.201	20. 07 03 03 03 02 24 22 00 03 03	RUN 372. 372. 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4 3 1	PHA -22 -20 -16 -13 -10 -07 -04 -02	6.3 1.1 1.1 0.0 0.0	37 P. 33.0 CN .367 .184 .996 .830 .682 .549 .424 .311	SI CMHG 01 11 55 77 11 18 44 79	RE 1 2.0 0.4 8.7 7.2 5.9 4.7 2.7	PER TS= 767 511 675 857 761 970 045 112 627 788	1.00 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	330 330 3392 3301 3140 3143 3215 3217 3217 3217	8E06	CY 0.2289 0.2755 0.1923 0.0445 0.0068 0.1148 0.11202 0.1074 0.1053	90. CR 0.010 0.010 0.009 0.008 0.007 0.005 0.004 0.004	RUI 60 0.3 11 0.3 12 0.3 15 0.3 10 0.3 10 0.3 10 0.3 10 0.3	NO. 3409 3338 3297 3204 3197 3104 3117 3096 3074	POJ/P O1303 CPB 0.1202 0.1206 0.1194 0.1163 0.1123 0.1091 0.1087	S9109 CAF 0.220 0.213 0.210 0.204 0.207 0.201 0.203 0.201 0.199 0.200	20. 7 13 13 12 14 12 13 13 13 13 13 13 13 13 13 13	RUN 372. 372. 372. 372. 372. 372. 372. 372
10 9 8 7 6 5 4 3 1	PHA -22 -20 -16 -13 -10 -07 -04 -02 -99	6.3 1.1 1.1 0.0 0.0	37 P. 33.0 CN 367 184 996 830 682 549 424 311 202	SI CMHG 01 11 55 77 11 18 44 99	RE 1 CM 2.0 0.4 8.7 7.2 5.9 4.7 3.7 2.7 1.7	PER TS= 767 511 675 761 970 045 112 627 788 528	1.03 1.03 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	330 330 3392 3301 3140 3143 3215 3217 3217 3218 3227	8E06	CY 0.2289 0.2755 0.1923 0.0445 0.0465 0.148 0.1202 0.1074 0.1053	90. CR 0.010 0.010 0.005 0.005 0.005 0.004 0.004 0.004	DEG. RUI 8 0.3 6 0.3 9 0.3 1 0.3 1 0.3 2 0.3 5 0.3 6 0.3 7 0.3	4 NO 3409 3338 3297 3204 3197 3104 3117 3096 3074 3077	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1163 0-1091 0-1087 0-1083 0-1076 0-1073	TS = 59109 CAF 0.220 0.213 0.204 0.207 0.201 0.203 0.201 0.199 0.198	20. 27. 23. 22. 24. 29. 20. 30. 30. 30. 30. 30. 30. 30. 3	RUN 372. 372. 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4 3 1 1	PHA .22 .20 .16 .13 .10 .07 .04 .02 .99 .47 .96 .44	6.3 19 1. 1. 0. 0. 0. 0. 0.	37 P 93.0 CN .367 .184 .996 .830 .682 .549 .424 .311 .202 .146 .097	SI CMHG 0 -11 -15 -57 -71 -78 -77 -79 -71 -71 -71 -71 -71 -71 -71 -71 -71 -71	RE 1 CH 2-0 0-4: 8-7: 7-2: 5-9 4-7: 3-7: 2-7: 1-2: 0-8:	PER TS= 767 511 675 761 970 045 112 627 788 528 891	18.3 1.0 0 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6	330 330 330 330 330 330 3140 3143 3215 3217 3217 3218 3227 3164	8E06	CY 0.2289 0.2755 0.1923 0.0445 0.0465 0.148 0.1202 0.1074 0.1053	90. CR 0.010 0.010 0.009 0.005 0.005 0.004 0.004 0.004	DEG. RUI C/ 8 0.3 6 0.3 9 0.3 1 0.3 1 0.3 2 0.3 5 0.3 7 0.3 3 0.3	NO. 3409 3338 3297 3204 3197 3104 3117 3096 3074 3074 3054	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123 0-1091 0-1083 0-1073 0-1073	TS = 59109 CAF 0.210 0.210 0.204 0.207 0.201 0.201 0.199 0.196	20. 07 13 13 12 14 22 14 20 13 18 18 18 13	RUN 372. 372. 372. 372. 372. 372. 372. 372
10 9 8 7 6 5 4 3 1 1 0	PHA .22 .20 .16 .13 .10 .07 .96 .47 .96 .44 .07	6.3 19 1. 1. 0. 0. 0. 0. 0. 0.	37 P 93.0 CN -367 -184 -996 -830 -682 -549 -424 -311 -202 -146 -097	SI CMHG 01 11 5 77 88 77 96 1	RE 1 CH 2.0 0.4! 8.7(7.2(5.9) 4.7(3.7(2.7) 1.7(1.7(1.7()	PER TS= 767 511 675 761 970 970 970 972 8891 592	18.3 1.0 0 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6	2 .46 109 (1 2330) 2330) 2143 2215 2217 2201 2198 2227 2164	8E06	CY 0.2289 0.2755 0.1923 0.0445 0.0068 0.1148 0.1202 0.1074 0.1053 0.0750 0.0750	90. CR 0.010 0.010 0.009 0.005 0.005 0.004 0.004 0.004 0.004	DEG. 8 RUI 8 0.3 66 0.3 9 0.3 11 0.3 12 0.3 15 0.3 16 0.3 17 0.3 18 0.3	NO. 3409 3338 3297 3204 3197 3104 3117 3096 3074 3074 3054 3039 3024	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123 0-1091 0-1087 0-1087 0-1073 0-1073 0-1073	TS = 59109 CAF 0.210 0.213 0.204 0.207 0.201 0.199 0.208 0.196 0.196 0.196	20. 27 33 33 22 44 20 33 38 33 33 33 33 33 33 33 33 33 33 33	RUN 372. 372. 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4 3 1 1 0 0	Q= PO= PHA .22 .20 .16 .13 .10 .07 .04 .99 .47 .96 .44 .07	6.3 19 1.1 0.0 0.0 0.0 0.0	37 P 93.0 CN .367. 184. 996. 830. 549. 424. 311. 202. 146. 097.	SI CMHG 01 11 55 57 11 44 77 94 11 12	RE 1 CH 2.0 0.4! 8.7/ 7.2/ 5.9 4.7/ 1.7/ 1.2/ 0.8/ 0.3/ 0.0/ 0.5	PER TS= 767 511 675 761 970 970 970 112 627 788 891 592	1000 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	3300 3392 3301 3140 3143 31215 3215 3217 3198 3227 3164 3118 3227	8E06 >SI	CY 0.2289 0.2755 0.1923 0.0465 0.0465 0.1148 0.1074 0.1053 0.1053 0.1053	90. CR 0.010 0.010 0.009 0.005 0.005 0.004 0.004 0.004 0.004	RUI 8 0 - 3 9 0 - 3 1 0 - 3	N NO. 3409 3338 3297 3204 3104 3104 3104 3104 3077 3054 3074 3039 3039	POJ/P - 01303 CP8 0-1206 0-1194 0-1163 0-1123 0-1087 0-1087 0-1073 0-1073 0-1073	CAF 0.220 0.213 0.210 0.201 0.203 0.201 0.203 0.201 0.199 0.198 0.196 0.195	20. 77 93 93 93 93 93 93 93 93 93 93	RUN 372. 372. 372. 372. 372. 372. 372. 372
10 9 8 7 6 5 4 3 1 1 0 0 -0	Q= PO= PHA .22 .16 .13 .10 .07 .04 .02 .99 .47 .94 .07 .58	6.3 19 1.1 0.0 0.0 0.0 0.0 0.0	37 P 93.0 CN .367. 184. 996. 830. 549. 5424. 311. 2022. 146. 097. 044.	SI CMHG 01 111 55 77 84 77 96 11	RE 1 CH 2.00.4! 8.7/ 7.2! 5.99 4.7/ 1.2.7/ 1.2.7/ 1.2.7/ 1.2.0.8/ 0.3/ 0.0/ 0.5/ 0.9/	PER 767 511 675 761 970 015 627 788 891 592 157	1.00 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -	2 .41 109 1 2300 2300 2140 2140 2150 2217 2010	8E06 PSI () () () () () () () () () () () () ()	CY 0.2289 0.2755 0.0468 0.0465 0.1148 0.1074 0.1053 0.0710 0.0234 0.1235	90. CR 0.010 0.010 0.009 0.005 0.005 0.004 0.004 0.004 0.004 0.004 0.004 0.004	DEG. 6 RUI 8 0.3 6 0.3 1	N NO. 3409 3338 3297 3204 3197 3104 3197 8054 8037 8039 8039 8039 8037	POJ/P - 01303 CP8 0-1202 0-1204 0-1163 0-1163 0-1083 0-1076 0-1073 0-1073 0-1076 0-1078	TS = 59109 CAF 0.220 0.213 0.204 0.207 0.201 0.199 0.196 0.196 0.195 0.195	20. 27. 23. 24. 25. 26. 27. 28. 33. 33. 33. 33. 33. 33. 33. 3	RUN 372. 372. 372. 372. 372. 372. 372. 372.
10 98 76 65 54 31 10 00 -00	Q= PO= PHA .22 .16 .13 .10 .07 .04 .02 .99 .47 .96 .47 .58 .08 .59	6.3 1.1 0.0 0.0 0.0 0.0 0.0 0.0	37 P 23.0 CN 3677-184 1996 8300 6822 549 424 311: 2022 146 0977- 0059 110	SI CMHG	RE P CM 2-0-4-7 7-2-7 7-2-7 1-2-7 1-2-7 1-2-9 10-5-9 11-4	PER **	1.00 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -	3330 3392 3301 3143 301 301 301 301 301 301 301 301 301 30	88E06 25I	CY 0.2289 0.2755 0.1923 0.0465 0.0068 0.1262 0.1074 0.1053 0.1355 0.0710 0.0234	90. CR 0.010 0.010 0.009 0.005 0.005 0.004 0.004 0.004 0.004 0.004 0.004	DEG. 8 RUI 66 0.3 9 0.3 1 0.3 1 0.3 2 0.3 3 0.3 3 0.3 3 0.3 3 0.3	N NO 3409 3338 3297 3204 3197 3104 3117 8096 8077 8039 8024 8037 8048 8034	POJ/P - 01303 CPB 0.1202 0.1206 0.1194 0.1193 0.1091 0.1087 0.1083 0.1073 0.1073 0.1076 0.1081 0.1085 0.1084	TS = 59109 CAF 0.220 0.213 0.210 0.204 0.207 0.201 0.199 0.200 0.198 0.196 0.196 0.195 0.196 0.195	20. 27. 27. 28. 29. 29. 30. 30. 30. 30. 30. 30. 30. 30	RUN 372. 372. 372. 372. 372. 372. 372. 372.
10 9 8 7 6 5 4 3 1 1 0 0 0 -0 -1 -1 -2	Q= PO= PHA .22 .20 .16 .13 .10 .07 .96 .47 .96 .44 .07 .58 .59 .10	6.3 1.1 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	37 P 23.0 CN 367-184 1996 830 682 549 424 311 202 146 007 1007 1007 110 162	SI CMHG 01 11 55 57 11 18 47 11 12 39 4	RE P CM 2-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0	PER 767 767 7611 675 761 970 045 1127 788 528 157 528 157 599 144 789	1.00 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -0.6 -	3300 3392 3301 3140 3113 3215 3217 3217 3218 3217 3218 3218 3218 3218 3218 3218 3218 3218	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	CY (-2289 (-2755 (-1923 (-0445 (-0465 (-1148 (-1074 (-1074 (-1235	90. CR 0.010 0.009 0.008 0.005 0.005 0.004 0.004 0.004 0.004 0.004 0.004 0.004	DEG. 6 RUI 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	N NO 3409 3338 3297 3204 3197 3107 8074 8077 8054 8034 8034 8034 8034 8034	POJ/P - 01303 CPB 0-1202 0-1206 0-1194 0-1163 0-1123 0-1087 0-1083 0-1076 0-1081 0-1085 0-1086 0-1086	TS = 59109 CAF 0.220 0.213 0.210 0.204 0.201 0.201 0.203 0.201 0.201 0.196 0.196 0.195 0.195 0.195	20. 77 13 13 12 14 20 13 18 18 18 18 18 18 18 18 18 18	RUN 372. 372. 372. 372. 372. 372. 372. 372.

MODEL 946.2	CONF	IG. 2.000	HA	ICH 3-60	PHI = 90.	
Q= 6.37 PSI	RE PER	IN.= .48E06	T0*	90. DEG.F	P0J/PTS = 40	•
PO= 193.0 CMH	G PTS= 1	1.0109 PSI		RÛN HO	. 0130369110	
ALPHA CN	CM	cs	£¥	CR CAT	CPB CAF	RUN
	12.1188 -				0.1198 0.2204	373.
	10.4738				0.1201 0.2147	373.
	-8.8003 - -7.3241 -				0-1187 0-2102	373. 373.
	-5.9917 -				0.1131 0.2044	373.
	-4.8064 -				0.1100 0.2075	373.
	-3.7200 -				-0.1086-0.2006	373.
3.02 0.3122	-2.7165 -	-0.0381	0.2127	0.0062 0.3096	0.1081 0.2015	373.
	-1.7884 -				0.1078 0.1997	373.
	-1:3003 -				0.1076 0.1993	373.
	-0.8794 -				0.1074 0.1972	373.
	-0.4047 -				0.1074 0.1959	373.
-0.07 -0.0082 -0.57 -0.0634	0.0701				0.1074 0.1951 0.1079 0.1950	373. 373.
-1.09 -0.1182	1.0417				. C.1080 O.1940	373.
-1.60 -0.1699	1.4872				0.1079 0.1945	373.
-2.11 -0.2215	1.9315 -				0.1050 0.1938	373.
-3.12 -0.3230	2.8121 -				0-1085 0-1947	373.
-4.14 -0.4349	3.7911 -				0.1093 0.1935	373.
MODEL 946.2	CONF	IG. 2.000	М	CH 3.00	PHE ≈ 90.	
MODEL 946.2 Q= 6.37 PSI				90. DEG.F	PHE = 90. POJ/PTS = 100	•
	RE PER	IN.= .48E06		90. DEG.F		
Q= 6.37 PSI	RE PER	IN.= .48E06		90. DEG.F RUN NO	PoJ/PTS = 100	• aun
Q= 6.37 PSI PO= 193.0 CMH	RE PER	IN.= .48E06 1.0109 PŠI CS	. TO=	90. DEG.F RUN NO CR CAT	PoJ/PTS = 100	
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 -	RE PER 1 IG PTS=-1 CM -12-1309 -	IN.= .48E06 1.0109 PŠI CS -0.1267 -0.1270	CY 0.8790 0.8782	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360	POJ/PTS = 100 • 0130369111 CPB CAF 0-1177 0-2195 0-1176 0-2184	RUN 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118	RE PER 1 G PTS=-1 CM -12-1309 - -10-5011 - -8-8966 -	IN.= .48E06 1.0109 PŠI CS -0.1267 -0.1270 -0.1222	CY 0.8790 0.8782 0.8406	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313	POJ/PTS = 100 . 0130369111 CPB CAF 0-1177 0-2195 0-1176 0-2184 0-1167 0-2145	RUN 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7-13 0.8461	RE PER 1 CM -12.130910.50118.89667.4210 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1197	CY 0.8790 0.8782 0.8406 0.8195	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258	POJ/PTS = 100 Ol30369111 CPB CAF 0-1177 0-2195 0-1176 0-2184 0-1167 0-2145 0-1149 0-2109	RUN 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965	RE PER 1 IG PTS=1 CM -12.1309 - -10.5011 - -8.8966 - -7.4210 - -6.0990 -	IN.= .48E06 1.0109 PŠI CS -0.1267 -0.1270 -0.1222 -0.1197 -0.1144	CY 0.8790 0.8782 0.8406 0.8195 0.7650	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154	POJ/PTS = 100 Ol30369111 CPB CAF 0-1177 0-2195 0-1176 0-2184 0-1167 0-2145 0-1149 0-2109 0-1127 0-2027	374 - 374 - 374 - 374 - 374 -
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593	RE PER 1 G PTS=1 CM 12.1309 - 10.5011 - -8.8966 - -7.4210 - -6.0990 - -4.8853 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1197 -0.1144 -0.1055	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154	POJ/PTS = 100 D130369111 CPB CAF 0.1177 0.2195 0.1176 0.2184 0.1167 0.2145 0.1149 0.2109 0.1127 0.2027 0.1095 0.2050	RUN 374 • 374 • 374 • 374 • 374 •
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336	RE PER 1 IG PTS=1 CM -12.1309 - -10.5011 - -8.8966 - -7.4210 - -6.0990 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1272 -0.1197 -0.1144 -0.1055 -0.0991	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831 0.6214	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3145 0.0081 0.3129	POJ/PTS = 100 Olidos Olidos Olidos CPB	374 - 374 - 374 - 374 - 374 -
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198	RE PER 1 CM 12.1309 - 10.5011 - 8.8966 - 7.4210 - 6.0990 - 4.8853 - 3.7815 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1276 -0.1222 -0.1197 -0.1144 -0.1055 -0.0991	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831 0.6214	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3159 0.0081 0.3129 0.0053 0.3099	POJ/PTS = 100 D130369111 CPB CAF 0.1177 0.2195 0.1176 0.2184 0.1167 0.2145 0.1149 0.2109 0.1127 0.2027 0.1095 0.2050	RUN 374. 374. 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1991	RE PER 1 CM 12.130910.50118.89667.42106.09904.88533.78152.7893 -	IN.= .48E06 1.0109 PŠI CS -0.1267 -0.1270 -0.1227 -0.1197 -0.1164 -0.1055 -0.0991 -0.0995	CY 0.8790 0.8782 0.8406 0.81650 0.6831 0.6214 0.6285 0.6307 0.6111-	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.013 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3154 0.0092 0.3155 0.0081 0.3129 0.0053 0.3099 0.0025 0.3070 0.0006 0.3037	POJ/PTS = 100 Olidos Olidos	RUN 374. 374. 374. 374. 374. 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1021 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1491 0.95 0.0961	RE PER 1 G PTS= 1 CM 12.1309 - 10.5011 8.8966 7.4210 4.8853 4.8853 1.8681 - 1.3230 - 0.8635	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1197 -0.1144 -0.1055 -0.0993 -0.0995 -0.0975	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831 0.6214 0.6285 0.6307 0.6111- 0.6000-	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3145 0.0081 0.3129 0.0053 0.3099 0.0053 0.3099 0.0025 0.3070 0.0006 0.3037	POJ/PTS = 100 Olidos Olifo Olifo CPB CAF Olifo Olifo Olifo Olifo Olifo Olifo Olifo Olifo	RUN 374. 374. 374. 374. 374. 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1021 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1691 0.95 0.0961 0.45 0.0422	RE PER 1 CM 12.1309 - 10.50118.89667.42106.09904.88532.78931.86811.32300.86350.86350.3868 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1122 -0.1197 -0.1144 -0.1055 -0.0991 -0.0995 -0.0975 -0.0971	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831 0.6214 0.6285 0.6307 0.6111- 0.6060	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3145 0.0092 0.3145 0.0081 0.3129 0.0053 0.3070 0.0006 0.3037 0.0008 0.3023 0.0008 0.3023	POJ/PTS = 100 Ol30369111 CP8 CAF 0.1177 0.2195 0.1176 0.2184 0.1167 0.2145 0.1149 0.2145 0.1149 0.2109 0.1095 0.2050 0.1080 0.2049 0.1075 0.2023 0.1066 0.2004 0.1064 0.1973 0.1065 0.1958 0.1065 0.1933	RUN 374- 374- 374- 374- 374- 374- 374- 374-
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1491 0.95 0.0961 0.45 0.0422 -0.07 -0.0153	RE PER 1 CM 12.13090.50110.88567.42106.09904.88532.78931.86811.32300.86350.3864 - 0.1334 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1144 -0.1055 -0.0991 -0.0995 -0.0975 -0.0971 -0.0950 -0.0964	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6831 0.6214 0.6285 0.6307 0.6111- 0.6060- 0.5856 0.6000- 0.5856	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.31545 0.0092 0.3145 0.0098 0.3129 0.0053 0.3099 0.0025 0.3070 0.0006 0.3037 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023	POJ/PTS = 100 Ol30369111 CP8 CAF 0-1177 0-2195 0-1176 0-2184 0-1167 0-2145 0-1149 0-2109 0-1127 0-2027 0-1095 0-2050 0-1080 0-2049 0-1075 0-2023 0-1066 0-2004 0-1064 0-1973 0-1065 0-1958 0-1066 0-1943	RUN 374. 374. 374. 374. 374. 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1491 0.95 0.0961 0.45 0.0422 -0.07 -0.0153 -0.50 -0.0733	RE PER 1 G PTS= 1 CM 12.1309 - 10.50118.89667.42106.098533.78152.78931.8681 - 1.32300.86350.3868 - 0.1334 0.65590.5559	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1197 -0.1164 -0.1055 -0.0991 -0.0995 -0.0975 -0.0971 -0.09764	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6214 0.6285 0.6301 0.6000 0.5855	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3165 0.0081 0.3129 0.0053 0.3099 0.0025 0.3099 0.0025 0.3037 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023	POJ/PTS = 100 Olidos 1177	RUN 374. 374. 374. 374. 374. 374. 374. 374.
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1491 0.95 0.0961 0.45 0.0422 -0.07 -U.0153 -0.50 -0.0733 -1.08 -0.1272	RE PER 1 CM 12.1309 - 10.50118.89647.42104.88532.7893 - 1.86810.86350.3868 - 0.1334 - 0.6559 - 1.1315 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1276 -0.1222 -0.1197 -0.1144 -0.1055 -0.0991 -0.0995 -0.0975 -0.0975 -0.0971 -0.0964 -0.0979	CY 0.8790 0.8782 0.8406 0.8195 0.7650 0.6214 0.6285 0.6307 0.6111- 0.6006 0.5855 0.6006 0.6168	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3145 0.0081 0.3129 0.0053 0.3099 0.0053 0.3099 0.0050 0.3070 0.0006 0.3037 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.00090 0.30090 0.0090 0.30090	POJ/PTS = 100 Ol30369311 CPB CAF 0.1177 0.2195 0.1176 0.2185 0.1167 0.2145 0.1167 0.2145 0.1127 0.2027 0.1095 0.2050 0.1080 0.2049 0.1075 0.2023 0.1066 0.2004 0.1064 0.1973 0.1065 0.1958 0.1065 0.1933 0.1066 0.1943 0.1074 0.1928 0.1076 0.1901	RUN 374. 374. 374. 374. 374. 374. 374. 374
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1691 0.95 0.0961 0.45 0.0422 -0.07 -0.0153 -0.50 -0.0733 -1.08 -0.1272 -1.60 -0.1802	RE PER 1 G PTS= 1 CM 12.1309 - 10.50118.89667.42106.09904.88532.78931.86811.32300.86350.3868 - 0.1334 - 0.6559 - 1.1315 - 1.13892 - 1.13892 - 1.138921.889	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1122 -0.1197 -0.1144 -0.1055 -0.0991 -0.0995 -0.0975 -0.0971 -0.0970 -0.0979 -0.0979	CY 0.8790 0.8782 0.8466 0.8195 0.7650 0.6831 0.6214 0.6225 0.6307 0.6111- 0.6060 0.5855 0.6006 0.6168 0.6168	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.3154 0.0092 0.3145 0.0092 0.3145 0.0093 0.3070 0.0060 0.3037 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023	POJ/PTS = 100 Ol30369111 CP8 CAF 0.1177 0.2195 0.1176 0.2184 0.1167 0.2145 0.1149 0.2109 0.1127 0.2027 0.1095 0.2050 0.1080 0.2049 0.1075 0.2023 0.1066 0.2004 0.1064 0.1973 0.1065 0.1978 0.1065 0.1958 0.1065 0.1958 0.1066 0.1943 0.1074 0.1928 0.1076 0.1901 0.1079 0.1920	RUN 374- 374- 374- 374- 374- 374- 374- 374-
Q= 6.37 PSI PO= 193.0 CMH ALPHA CN 10.22 1.3753 - 9.20 1.1921 - 8.16 1.0118 7.13 0.8461 6.10 0.6965 5.07 0.5593 4.05 0.4336 3.02 0.3198 1.99 0.2128 1.46 0.1491 0.95 0.0961 0.45 0.0422 -0.07 -U.0153 -0.50 -0.0733 -1.08 -0.1272	RE PER 1 CM 12.1309 - 10.50118.89647.42104.88532.7893 - 1.86810.86350.3868 - 0.1334 - 0.6559 - 1.1315 -	IN.= .48E06 1.0109 PSI CS -0.1267 -0.1270 -0.1222 -0.1197 -0.1144 -0.1055 -0.0993 -0.0993 -0.0995 -0.0975 -0.0971 -0.0970 -0.0970 -0.0979	CY 0.8790 0.8792 0.8406 0.8195 0.7650 0.6831 0.6214 0.6285 0.6307 0.6111- 0.6060 0.5855 0.6306 0.6168 0.6168 0.6168	90. DEG.F RUN NO CR CAT 0.0250 0.3372 0.0214 0.3360 0.0133 0.3313 0.0114 0.3258 0.0097 0.31545 0.0092 0.3155 0.0081 0.3129 0.0053 0.3099 0.0025 0.3070 0.0006 0.3037 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0008 0.3023 0.0009 0.3002 0.0090 0.3002 0.0093 0.2978 0.0093 0.2978 0.0093 0.2978 0.0093 0.2978	POJ/PTS = 100 Ol30369311 CPB CAF 0.1177 0.2195 0.1176 0.2185 0.1167 0.2145 0.1167 0.2145 0.1127 0.2027 0.1095 0.2050 0.1080 0.2049 0.1075 0.2023 0.1066 0.2004 0.1064 0.1973 0.1065 0.1958 0.1065 0.1933 0.1066 0.1943 0.1074 0.1928 0.1076 0.1901	RUN 374. 374. 374. 374. 374. 374. 374. 374

HODE	EL 946.2	CONF	FIG. 2.00	00 MJ	ICH 4:50)	PHI =	•	
Q= 3	3.77 PSI	RE PER	IN.= .48E	06 TO=	90. DI	EG.F	POJ/P	TS =	•
9 0=	400-0 CM	HG PTS=	.2659 95	51		RUN NO.	01303	69113	
ALPHA	CN	CM	ES	CY	CR	ÇÄT	CPB	CAF	RUN
4-08	0.3692	-3.0809	-0.0046	0.0168	0.0011	0.2127	0.0506	0.1621	375.
3.07	0-2740	-2.2746	-0.0041	0.0095	0.0009	0.2066	0.0507	0.1559	375.
2.06	0.1787	-1.4766	-0.0051	0.0176	1000.0	0.2035	0.0504	0-1532	375.
1.54	0.1281	-1.0570	-0.0044	0.0123-	-0.0006	0.2022	0.0501	0.1521	
1.03	0.0805	-0.6525	-0.0037	0.0065-	-0.0005	0.2022	0-0499	0-1522	375.
0.53	0.0372	-0.2945	-0.0046			0.2020			
0.01	0.0067	-0.0630	-0.0032			0.2001			
-0.49	-0.0438	0.3710	-0.0049			0.2016			
-0.99	-0.0728	0.5778	-0.0035			0:1996			
-1.49	-0-1248	1.0272	-0.0036			0.1996			
-2.00 -	-0.1624		-0.0029	-0.0016					
	-0.2577		-0.0009	-0.0173					
	-0.3545		0.0052	-0.0695					
	EL 946.2		FIG. 2.00	-	ICH 4.50		PHI =	• TS =	10 .
P0=	400.0 CM	HG PTS=	.2659 PS	S 1	•	RUN NO.	01303	69114	-
ALPHA	CN	СМ	cs	CÝ	ER	CAT	EP8	CAF	RUN
4.08	0.3605	-3-0241	-0.0059	0.0271-	-0 0004	0-2146	0-0506	0: 1440	376.
3.07	0.2567		-0.0054			0.2114			
2.06	0.1742		-0.0041			0.2098			
1.55	0.1237		-0.0042			0.2084			
	G-0875		-0.0027	-0.0016					
0.52	0.0384		-0.0020	-0.0016					
	-0.0035		-0.0020	-0.0039					
_	-0.0454		-0.0015	-0.0095					
	-0.0816		-0.0001	-0.0223					
	-0.1249		-0,0002	-0.0214					376.
-	-0.1683	1.3589		-0.0260					
	-0-2579	2.1085		-0.0429					376.
	-0.3547	2.9277	0.0029	-0.0794					
	~ ~ ~ ~ ~ ~ .		~ 3 ~ ~ ~ ~ ~	~ ~ W 1 3 7 7	E	U-CULL	7 - 7 J U U	マウレンとす	310.

dom	EL 946.2	CON	FIG. 2.0	go ñ	ACH 4.5	0	PHI ≅	•	
Q=	3.77 PSI	RE PER	IN.= .48	E06 TO=	90. D	EG.F	POJ/P	TS ≃	20.
5.Ú=	400-D CH	HG PTS=	.2659 P	S I		RUN NO	01303	69115	
ALPHA	ÇN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.08	0.3547	-2.9933	-0.0119	0.0817	0.0004	0.2180	0.0511	0.1669	377.
3.07			-0.0106			0.2133			
2.05			-0.0070			0.2130			
	0.1207	_	-0.0079			0.2088			
1.02			-0.0040			0.2102			
	0.0268		-0.0049			0.2071			
	-0.0137		-0.0051			0.2054			
	-0.0499		-0.0028			0.2066			
	-0.0832		-0.0014	-0.0121					
	-0.1322		-0.0023	-0.0013					
	-0.1699		-0.0017	-0.0062					
	-0.2594		-0.0004	-0.0164					
-4.02	-0.3562	2.9212	0.0024	-0.0402	0.0012	0.2053	0.0498	0.1555	377.
	3.77 PSI		FIG. 2.0:		ACH 4-50 90. DI		2HI =	• rs =	40.
Q=		RE PER	IN.= .48	E06 TO=		EG.F			40.
Q=	3.77 PSI	RE PER	IN.= .48	E06 TO=		EG.F	POJ/P		40 . RUN
Q= PO= ALPHA	3.77 PSI 400.0 CM	RE PER HG PTS=	IN.= .489 .2659 P:	CY	90. DI	EG.F RUN NO	POJ/P - 013030 - CP8	69116 CAF	RUN
Q= P0=	3.77 PSI 400.0 CM CN 0.3373	RE PER HG PTS= CH -2.8667	IN.= .48(.2659 P: CS -0.0123	E06 T0= SI CY 0.0865	90. DI CR 0.0036	EG.F RUN NO. CAT 0.2217	POJ/P - 013036 - CP8 - 0.0513	69116 CAF G.1703	RUN 3784
Q= PO= ALPHA 4.07 3.07	3.77 PSI 400.0 CM CN 0.3373	RE PER HG PTS= CH -2.8667 -2.0965	IN.= .489 .2659 P:	E06 T0= SI CY 0.0865 0.0678	90. Di CR 0.0036 0.0044	EG.F RUN NO. CAT 0.2217 0.2169	POJ/P 013036 CP8 0.0513 0.0513	69116 CAF G-1703 O-1655	RUN 3 378: 378:
Q= PO= ALPHA 4.07 3.07 2.05	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553	RE PER HG PTS= CH -2.8667 -2.0965 -1.3392	IN.= .48 .2659 P: CS -0.0123 -0.0102	CY 0.0865 0.0678 0.0641	90. Di CR 0.0036 0.0044 0.0039	EG.F RUN ND CAT 0.2217 0.2169 0.2182	POJ/P 013036 CP8 0.0513 0.0513 0.0510	69116 CAF G.1703 O.1655	RUN 3784 378. 378.
Q= PO= ALPHA 4.07 3.07	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033	RE PER HG PTS= CM -2.8667 -2.0965 -1.3392 -0.9026	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0097	CY 0.0865 0.0678 0.0641 0.0424	90. Di CR 0.0036 0.0044 0.0039 0.0040	EG.F RUN NO. CAT 0.2217 0.2169	POJ/P 013036 CP8 0.0513 0.0513 0.0510 0.0507	CAF G-1703 0-1655 0-1671 0-1690	RUN 3784 3784 3784
Q= PO= ALPHA 4.07 3.07 2.05 1.54	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642	RE PER HG PTS= CM -2.8667 -2.0965 -1.3392 -0.9026 -0.5931	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0097 -0.0076	CY 0.0865 0.0678 0.0641 0.0424 0.0467	90. DI CR 0.0036 0.0044 0.0039 0.0040 0.0042	CAT 0.2217 0.2169 0.2182 0.2197	POJ/P 013030 CP8 0.0513 0.0513 0.0510 0.0507 0.0505	CAF G.1703 0.1655 0.1671 0.1690 0.1647	RUN 378. 378. 378. 378.
Q= PO= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642	RE PER HG PTS= CH -2.8667 -2.0965 -1.3392 -0.9026 -0.5931 -0.3270	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0097 -0.0074 -0.0075	CY 0.0855 0.0678 0.0641 0.0424 0.0467 0.0255	90. DI CR 0.0036 0.0044 0.0039 0.0040 0.0042 0.0043	CAT 0.2217 0.2169 0.2182 0.2197 0.2152	POJ/P 013030 CP8 0.0513 0.0513 0.0510 0.0507 0.0505 0.0503	69116 CAF G.1703 O.1655 O.1671 O.1690 O.1647 O.3514	RUN 378. 378. 378. 378. 378. 378.
Q= PO= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52 0.01	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642 0.0309	RE PER HG PTS= CH -2.8667 -2.0965 -1.3392 -0.9026 -0.5931 -0.3270 0.1158	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0097 -0.0074 -0.0075 -0.0053	CY 0.0865 0.0641 0.0424 0.0467 0.0255 0.0130	90. DI CR 0.0036 0.0044 0.0039 0.0040 0.0042 0.0043 0.0024	CAT 0.2217 0.2169 0.2182 0.2197 0.2152 0.2118	POJ/P 013030 CP8 0.0513 0.0513 0.0510 0.0507 0.0505 0.0503 0.0502	69116 CAF G.1703 O.1655 O.1671 O.1690 O.1647 O.3514	RUN 378. 378. 378. 378. 378. 378. 378.
Q= P0= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52 0.01 -0.49	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642 0.0309 -0.0211	RE PER HG PTS= CM -2.8667 -2.8667 -1.3392 -0.9026 -0.5931 -0.3270 0.1158 0.4736	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0097 -0.0074 -0.0075 -0.0053 -0.0039	CY 0.0865 0.0641 0.0424 0.0467 0.0255 0.0130 0.0218	90. DI CR 0.0036 0.0044 0.0039 0.0040 0.0042 0.0043 0.0024	CAT 0.2217 0.2169 0.2182 0.2197 0.2152 0.2118 0.2118	POJ/P - 013030 - CP8 - 0.0513 - 0.0513 - 0.0507 - 0.0505 - 0.0503 - 0.0502 - 0.0499	CAF G.1703 0.1655 0.1671 0.1647 0.1647 0.1646	RUN 378. 378. 378. 378. 378. 378. 378. 378.
Q= PO= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52 0.01 -0.49 -1.00 -1.51	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642 0.0309 -0.0211 -0.0644 -0.1077 -0.1483	RE PER HG PTS= CN -2.8667 -2.0965 -1.3392 -0.9026 -0.5931 -0.3270 0.1158 0.4736 0.8256 1.1562	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0074 -0.0075 -0.0053 -0.0039 -0.0048 -0.0033 -0.0034	CY 0.0865 0.0678 0.0641 0.0424 0.045 0.0255 0.0130 0.0218 0.0098 0.0105	90. DI CR 0.0036 0.0044 0.0039 0.0040 0.0043 0.0024 0.0032 0.0045 0.0034	CAT 0.2217 0.2169 0.2182 0.2197 0.2152 0.2118 0.2118 0.2116 0.2101 0.2111	POJ/P - 013030 - CP8 - 0.0513 - 0.0513 - 0.0505 - 0.0505 - 0.0503 - 0.0502 - 0.0498 - 0.0498 - 0.0497	69116 CAF G-1703 O-1655 O-1671 O-1647 O-1647 O-1616 O-1647 O-1603 O-1617	RUN 378. 378. 378. 378. 378. 378. 378. 378.
Q= PO= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52 0.01 -0.49 -1.51 -2.00	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642 0.0309 -0.0211 -0.0644 -0.1077 -0.1483 -0.1844	RE PER HG PTS= CN -2.8667 -2.0965 -1.3392 -0.9026 -0.5931 -0.3270 0.1158 0.4736 0.8256 1.1562	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0074 -0.0075 -0.0053 -0.0039 -0.0048 -0.0033	CY 0.0865 0.0678 0.0641 0.0424 0.0467 0.0255 0.0130 0.0218 0.0098 0.0105	90. Di CR 0.0036 0.0044 0.0039 0.0042 0.0043 0.0024 0.0032 0.0045 0.0045 0.0036	CAT 0.2217 0.2169 0.2182 0.2197 0.2152 0.2118 0.2118 0.2146 0.2101 0.2103	POJ/P 013036 CPB 0.0513 0.0510 0.0507 0.0505 0.0503 0.0502 0.0498 0.0497 0.0495	69116 CAF G-1703 O-1655 O-1671 O-1697 O-1647 O-1616 O-1647 O-1603 O-1617	RUN 378. 378. 378. 378. 378. 378. 378. 378.
Q= PO= ALPHA 4.07 3.07 2.05 1.54 1.02 0.52 0.01 -0.49 -1.00 -1.51 -2.00 -3.01	3.77 PSI 400.0 CM CN 0.3373 0.2463 0.1553 0.1033 0.0642 0.0309 -0.0211 -0.0644 -0.1077 -0.1483	RE PER HG PTS= CH -2.8667 -2.0965 -1.3392 -0.9026 -0.5931 -0.3270 0.1158 0.4736 0.4736 0.1562 1.4503 2.1706	IN.= .488 .2659 PS CS -0.0123 -0.0102 -0.0074 -0.0075 -0.0053 -0.0039 -0.0048 -0.0033 -0.0034	CY 0.0865 0.0678 0.0641 0.0424 0.045 0.0255 0.0130 0.0218 0.0098 0.0105	90. Di CR 0.0036 0.0044 0.0039 0.0045 0.0043 0.0024 0.0035 0.0036 0.0036	CAT 0.2217 0.2169 0.2182 0.2197 0.2152 0.2118 0.2118 0.2116 0.2101 0.2113 0.2109 0.2106	POJ/P 013036 CPB 0.0513 0.0513 0.0510 0.0507 0.0505 0.0503 0.0502 0.0499 0.0498 0.0497 0.0495	69116 CAF G-1703 O-1655 O-1671 O-1697 O-1647 O-1616 O-1647 O-1616 O-1614 O-1611	RUN 378. 378. 378. 378. 378. 378. 378. 378.

MOS	DEL 946.2.	CON	FIG. 2.0)GO M	ACH 4.5	0	PHI =	•	•
Q=	3.77 PSI	RE PER	IN.= .48	3E06 TO=	90. D	EG.F	P0J/P	TS = 10	0.
P0=	400-0 CM	HG PTS=	• 2659 F	ŞI-		RUN NO	. 01303	69117	
ALPHA	CN	CH	cs	CY	CR	CAT	CP8	CAF	RUN
4.06	0.2908	-2.4985	-0.0130	0.0954	0.0031	,0-2338	0.0513	0.1824	379.
3.06	0.1984	-1.7143	-0.0109	0.0766	0.0032	0.2319	0.0513	0-1866	379.
2.04	0.1132		-0.0096			0.2286			379.
1.52	0-0639	-0.6093	-0.0065			0.2288			379.
	0.0249		-0.0067			0.2300			379.
	-0.0256		-0.0052			0.2270			379.
	-0.0604		~0.0053			0.2238			379.
	-0.1052		-0.0047			0.2237			.379.
	-0.1386		-0.0024			0.2234			379.
	-0.1877		-0.0017	-0.0015					379.
	-0.2210		-0.0027			0.2214			379.
		2.4607		-0.0039					379.
-4.03	-0.4043	3.2524	0.0022	-0.0341	0.0033	0.2223	0.0497	0-1727	379.
	EL 946.2		*IG. 2.0		10H 4.56		PHI =	15.	
				000 M/ 606 TÓ=			PHI =		•
Q=		RE PER	IN.= .48	E06 TÓ=			P0 J/P	rs =	•
Q=	3.77 PSI	RE PER	IN.= .48	E06 TÓ=		EG.F	P0 J/P	rs =	• RUN
Q= P0=	3.77 PSI	RE PER HG PTS= CM	IN.= .48	CY CY	90. DI	EG.F RUN NO. CAT	P0J/P	TS = 59118 CAF	-
Q= PO= AEPHA 4.09	3.77 PSI 400.0 CM ÇN	RE PER HG PTS= CM	.2659 P CS -0.0035	E06 TO= SI CY 0.0097	90. DE	EG.F RUN NO. CAT 0.2376	P0J/P . 013030 CP8	TS = 69118 CAF 0.1865	380.
Q= PO= A£PHA	3.77 PSI 400.0 CM CN 0.3688	RE PER HG PTS= CM -3.0753	.2659 P CS -0.0035	CY CY	90. DECR	EG.F RUN NO. CAT 0.2376 0.2311	POJ/P 013030 CP8 0.0511 0.0510	FS = 69118 CAF 0.1865 0.1300	380. 380.
Q= PO= AEPHA 4.09 3.09	3.77 PSI 400.0 CM CN 0.3688 0.2757	RE PER HG PTS= CM -3.0753 -2.2879	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015	E06 T0= SI CY 0.0097 -0.0000	90. DI CR 0.0026 0.0024 0.0023	EG.F RUN NO. CAT 0.2376 0.2311 0.2305	POJ/P 013036 CP8 0.0511 0.0510 0.0507	TS = 59118 CAF 0.1865 0.1300 0.1799	380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56	3.77 PSI 600.0 CM CN 0.3688 0.2757 0.1856	RE PER HG PTS= CH -3.0753 -2.2879 -1.5369	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0007	CY 0.0097 -0.0000 -0.0031 -0.0062	90. DI CR 0.0026 0.0024 0.0023 0.0016	EG.F RUN NO. CAT 0.2376 0.2311 0.2305	POJ/P 013036 CP8 0.0511 0.0510 0.0507	CAF 0.1865 0.1300 0.1799 0.1832	380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56	3.77 PSI 400.0 CM CN 0.3688 0.2757 0.1856 0.1284	RE PER HG PTS= CM -3.0753 -2.2879 -1.5369 -1.0555	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0007 -0.0014	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030	90. DECR 0.0026 0.0024 0.0023 0.0016 0.0028	CAT 0.2376 0.2311 0.2305 0.2336	POJ/P 013030 CP8 0.0511 0.0510 0.0507 0.0503 0.0501	CAF 0.1865 0.1300 0.1799 0.1832 0.1817	380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56 1.05	3.77 PSI 600.0 CM CN 0.3688 0.2757 0.1856 0.1284 0.0867	RE PER HG PTS= CM -3.0753 -2.2879 -1.5369 -1.0555 -0.7140	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0007 -0.0014	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.00090.0191	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0021	CAT 0.2376 0.2311 0.2305 0.2336 0.2318 0.2286 0.2286	POJ/P 013030 CP8 0.0511 0.0510 0.0507 0.0503 0.0501 0.0499 0.0498	CAF 0.1865 0.1800 0.1799 0.1832 0.1817 0.1787	380. 380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56 1.05 0.54 0.04	3.77 PSI 600.0 CM CN 0.3688 0.2757 0.1856 0.1284 0.0867 C.0402 0.0006 -0.0318	RE PER HG PTS= CH -3.0753 -2.2879 -1.5369 -1.0555 -0.7140 -0.3205 -0.0001 0.2501	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0014 -0.0012 0.0010 -0.0013	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.00090.0191 -0.0050	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0021	CAT 0.2376 0.2311 0.2336 0.2336 0.2318 0.2286 0.2282 0.2278	POJ/P 013030 CP8 0.0511 0.0510 0.0507 0.0503 0.0501 0.0499 0.0498 0.0497	CAF CAF 0.1865 0.1300 0.1799 0.1832 0.1817 0.1787 0.1784	380. 380. 380. 380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56 1.05 0.54 0.04 -0.47 ~0.97	3.77 PSI 400.0 CM CN 0.3688 9.2757 0.1856 0.1284 0.0857 G.0402 0.0006 -0.0318 -0.0810	RE PER HG PTS= CH -3.0753 -2.2879 -1.5369 -1.0555 -0.7140 -0.3205 -0.0001 0.2501 0.6652	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0014 -0.0012 0.0010 -0.0013 0.0031	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.00090.0191 -0.0050 -0.0391	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0021 0.0027	CAT 0.2376 0.2311 0.2305 0.2336 0.2318 0.2286 0.2282 0.2278 0.2289	POJ/P 013030 CP8 0.0511 0.0510 0.0507 0.0503 0.0501 0.0499 0.0498 0.0497	CAF CAF 0.1865 0.1300 0.1799 0.1832 0.1817 0.1787 0.1784 0.1781	380. 380. 380. 380. 380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56 1.05 0.54 0.04 -0.47 -0.97 -1.48	3.77 PSI 400.0 CM CN 0.3688 9.2757 0.1856 0.1284 0.0867 0.0402 0.0006 -0.0318 -0.0810 -0.1219	RE PER HG PTS= CH -3.0753 -2.2879 -1.5369 -1.0555 -0.7140 -0.3205 -0.0001 0.2501 0.6652 1.0010	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0017 -0.0014 -0.0012 0.0013 0.0031 0.0049	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.0009 -0.0191 -0.0526	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0021 0.0027 0.0020 0.0025	CAT 0.2376 0.2311 0.2305 0.2336 0.2318 0.2286 0.2286 0.2289 0.2278 0.2256	POJ/P 013036 CPB 0.0511 0.0510 0.0507 0.0503 0.0501 0.0499 0.0499 0.0497 0.0496	CAF 0.1865 0.1300 0.1799 0.1832 0.1817 0.1787 0.1784 0.1781 0.1794 0.1761	380. 380. 380. 380. 380. 380. 380. 380.
Q= P0= AEPHA 4.09 3.09 2.08 1.56 1.05 0.54 0.047 -0.47 -0.47 -1.48 -1.98	3.77 PSI 400.0 CM CN 0.3688 9.2757 0.1856 0.1284 0.0857 C.0402 0.0006 -0.0318 -0.0810 -0.1219 -0.1611	RE PER HG PTS= CM -3.0753 -2.2879 -1.5369 -1.0555 -0.7140 -0.3205 -0.0001 0.2501 0.6652 1.0010 1.3238	IN.= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0014 -0.0012 0.0010 -0.0013 0.0031 0.0049 0.0056	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.0009 -0.0191 -0.0050 -0.0594	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0021 0.0021 0.0027 0.0020	CAT 0.2376 0.2311 0.2305 0.2336 0.2318 0.2286 0.2282 0.2278 0.2289 0.2256 0.2281	POJ/P 013036 CP8 0.0511 0.0510 0.0507 0.0503 0.0501 0.0499 0.0499 0.0497 0.0495 0.0495	CAF 0.1865 0.1300 0.1799 0.1832 0.1817 0.1787 0.1784 0.1781 0.1761 0.1786	380. 380. 380. 380. 380. 380. 380. 380.
Q= PO= AEPHA 4.09 3.09 2.08 1.56 1.05 0.54 0.047 -0.47 -0.47 -1.48 -1.98 -2.99	3.77 PSI 400.0 CM CN 0.3688 9.2757 0.1856 0.1284 0.0867 0.0402 0.0006 -0.0318 -0.0810 -0.1219	RE PER HG PTS= CH -3.0753 -2.2879 -1.5369 -1.0555 -0.7140 -0.3205 -0.0001 0.2501 0.6652 1.0010	IN-= .48 .2659 P CS -0.0035 -0.0021 -0.0015 -0.0014 -0.0012 0.0013 0.0031 0.0049 0.0056 0.0066	CY 0.0097 -0.0000 -0.0031 -0.0062 0.0030 0.0009 -0.0191 -0.0526	90. DE CR 0.0026 0.0024 0.0023 0.0016 0.0028 0.0010 0.0027 0.0027 0.0025 0.0025 0.0019	CAT 0.2376 0.2311 0.2305 0.2318 0.2286 0.2282 0.2289 0.2289 0.2281 0.2290	POJ/P .013036 CP8 0.0510 0.0510 0.0507 0.0503 0.0501 0.0499 0.0498 0.0497 0.0495 0.0497	CAF 0.1865 0.1300 0.1799 0.1832 0.1817 0.1784 0.1781 0.1781 0.1786 0.1786	380. 380. 380. 380. 380. 380. 380. 380.

AND THE SECOND S

MODEL	946.2	CON	FIG. 2.0	00 н	ACH 4.50	PHI = 15.	
Q= 3.	77 PSI	RE PER	IN.= .48	=07 30E	90. DEG.F	POJ/PTS = 10.	
P0= 4	100.0 CM	HG PTS=	•2659 P	12	RUN NO	. 0130369119	
ALPHA	CN	CM	CS	CY	CR CAT	CPB CAF	RUN
4.10	3602	-3.0099	-0.0048	0.0192	0.0026 0.2379	0.0508 0.1871	381.
	2686		-0.0038			0.0509 0.1805	381.
	1771		-0.0036			0.0506 0.1788	381.
1.56		-1.1338				0.0504 0.1759	381.
1.05		-0.6870	-0.0009			0.0502 0.1759	381.
0.54	0.0380	-0.3268	0.0009	-0.0206	0.0021 0.2288	0.0501 0.1787	381.
0.04	0.0047	-0.0596	0.0023	-0.0369	0.0028 0.2209	0.0500 0.1709	381.
-0.48 -0	0.0446	0.3519	-0.0037	0.0159	0.0015 0.2209	0.0499 0.1710	381.
-0.97 -0	0.0805	0.6397	0.0010	-0.0246	0.0027 0.2247	0.0498 0.1749	381.
-1.48 -0	0.1247	1.0028	0.0036	-0.0478	0.0020 0.2244	0.0497 0.1747	381.
-1.98 -	0.1614	1.3023	0.0065	-0.0728	0.0019 0.2224	0.0496 0.1728	381.
-2.99 -0		2.0695	0.0067	-0.071:1	0.0037 0.2233	0.0497 0 736	381.
-4.00 -0	3525	2.9164	0.0096	-0.0927	0.0022 0.2243	0.0500 0.1743	381.
MODE	946.2	-CON	FIG. 2.0	00 M	ACH 4.50	PHI = 15.	
Q= 3.	.77 PSI	RE PER	IN.= .48	E06 T0=	90. DEG.F	POJ/PTS = 20.	
P0= 4	400.0 CM	HĞ PTS≈	.2659 P	st	RUN NO	0130369120	
ÁLPHA	CN	CM	cs	CY	CR CAT	CP8 CAF	RUN
0.14	0-0730	-0.7500	0:9416	-7.5665	-0.0060 2.6583	-0.1261 2.7845	382.
3.09			-0.0074			"0.0510 0.1/£79	382.
2.08		-	-0.0067			0.0507 0.1717	382.
1.56			-0.0045			0.0505 0.1748	382.
1.05			-0.0049			0.0503 0.1703	382.
0.55			-0.0053			0.0502 0.1686	382.
0.03 -0			-0.0058			0.0500 0.1744	382.
-0.48 -0			-0.0051			0.0500 0.1697	382.
-0.97 -0			-0.0010			0.0498 0.1693	382.
-1.48 -			-0.0010			0.0497 0.1738	382.
-1.98 -0			0.0007			0.0496 0.1703	382.
-2.99 -0	0.2572	2.0902				0.0496 0.1710	382.
-4.00 -0	3578	2 9470	0.0068			0.0496 0.1706	382.

. HODEL 94	6.2 CONI	FIG. 2.000	H	ACH 4.50)	PHI =	15.	
Q= 3.77 (PSI RE PER	IN.= .48E06	5 TO=	90. DE	G.F	POJ/P	rŝ =	40.
PO= 400.	D CHHG PTS=	•2659 PSI			RUN NO.	01303	69121	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.09 0.33	59 -2.8315	-0,0148	0.0985	0.0047	0.2331	0.0496	0.1835	383.
3.08 0.24		-0.0112		0.0058				
2.08 0.15		-0.0105		0.0044				
1.56 0.09		-0.0108		0.0043				
1.05 0.060		-0.0101		0.0037				
0.54 0.014		-0.0106		0.0011				
0.04 -0.024				0.0010				
-0.47 -0.05				0.0042				
-0.97 -0.09	17 0.6902	-0.0022 -	-0.0098					
-1.48 -0.13		-0.0011 -	-0.0195					
-1.98 -0.180 -2.99 -0.269			-0.0163					
			0.0348					
-4.00 -0.36	16 3.0018	0.0045 ~	0.0617	0-0062	0-5174	0.0498	0.1622	383.
HODEL 948	•	IG. 2.000		CH 4.50		PHI =	_	
Q= 3.77 i	PSI RE PER	IN.= .48E06	50 =	90. DE	G.F	POJ/P1	rs = 1	00•
PO= 400.0	CHHG PTS=	•2659 PSI			RUŅ NO.	013036	59122	
ALPHA CŃ	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.08 0.29	38 -2,4993	-0.0260	0.1902	Ó. 0011	0-2407	0-0511	0-189A	384.
3.08 0.201			0.1581					384.
2.07 0.112			0.1556					384.
1.53 0.067	70 -0.6259		0.1252					384.
1.04 0.027	76 ~0.3017			0.0038				384.
0.54 -0.00			0.0814	0.0038	0.2296	0.0503	0-1794	384.
0.03 -0.061			0.1071					384.
-0.48 -0.096			0.0757					384.
-0.98 -0.138	~			0.0005				384.
-1.49 -0.182	25 -1.4161		0.0590					384.
-1.99 -0.216	1.6867		0.0137					384.
-3.00 -0.308	36 2.4630		0.0036					384.
-4.01 -0.403	3.2606		0.0100					384.

THE SECOND SECON

HCD	EL 946.2	CONF	IG. 2.00	O MA	CH 4.50	•	PHI =	30.	-
Q= ;	3.77 PSI	RE PER	IN.= .488	=01 60	90. DS	G.F	POJSPI	rs =	•
۲0=	400.0 CH	HG PTS=	.2659 P.S	31		SAN KO	01303	59123	
ALPHA	CN	CH	cs	ĆΑ	CR	CAT	CP8	CAF	RUN
4.06	0.3671	-3.0557	.0.0042	-0.0547-	0.	0.2141	0.0495	0.1647	385.
	0.2723	-2.2533	0.0030	-0.9438-	0,0017	0.2175	0.0508	0.1668	385.
2.04	0.1804	-1.4878		-0.0415-	0.0009	0.2077	0.0505	0.1572	385
1.52	0.1204	-0.9735	-0.0032	0.0194	0.0018	0.2047	0.0502	0.1545	
1.02	0.0861	-0.7059	0.0012	-0.0235-	0.0013	0.1922	0.0500	0.1422	385.
0.51	0.0425	-0.3526	0.0011	-0.0254-					
0.01	-0.0016		-0.0038			0.2016			
-0.51	-0.0322		0.0053	-0.0677-					
	-0.0890	0.7397				0.2035			
	-0.1234		0.0010	-0.0285-					
	-0.1624		-0.0010	-0.0053-					
		2.1098		-0.0021-					
-4.03	-0.3552	2.9492	-0.0006	~0 ₀ 0086	0.0005	0.1973	0.0502	0.1471	385.
	EL 946.2 3.77 PSI		FIG. 2.00 IN.= .481		ACH 4.58	D EG.F	PHI =	30. rs =	10.
Q=	3.77 PSI	RE PER		06 TO=		EG.F		rs =	10.
Q=	3.77 PSI	RE PER	IN.= .488	06 TO=		EG.F	POJ/P	rs =	10 . RUN
Q= PO= Alpha	3.77 PSI 400.0 CH	RE PER HG PTS=	IN.= .488 .2659 PS	E06 T0=	90. DI	EG.F RUN NO.	POJ/P	TS = 69124 CAF	RUN
Q= PO= Alpha 4.06	3.77 PSI 400.0 CM CN 0.3607	RE PER HG PTS= CH -3.0141	.2659 PS CS 0.0008	E06 T0=	90. DI	EG.F RUN NO. CAT 0.2101	POJ/P1 013030 CP8 0.0506	rs = 69124 Caf 0.1595	RUN 386.
Q= PO= Alpha	3.77 PSI 400.0 CH	RE PER HG PTS= CH -3.0141 -2.2422	IN.= .488 .2659 PS	E06 T0= SI CY -0.0294	90. DI CR 0.	EG.F RUN NO. CAT 0-2101 G.2032	POJ/P* 013030 CP8 0.0506 0.0508	TS = 69124 CAF 0.1595	RUN 386. 386.
Q= PO= ALPHA 4.06 3.05	3.77 PSI 400.0 CM CN 0.3607 0.2684	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588	.2659 PS CS 0.0008 -0.0016	CY -0.0294 -0.0062-	90. DI CR 0. 0.0004 -0.6008	EG.F RUN NO. CAT 0-2101 G.2032	POJ/P 013030 CP8 0.0506 0.0508 0.0508	TS = 69124 CAF 0.1595 0.1524 0.1502	RUN 386. 386. 386.
Q= PO= ALPHA 4.06 3.05 2.04	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020	CY -0.0294 -0.0062- 0.0083	90. DI CR 0. 0.0004 0.6008 0.0002	EG.F RUN NO. CAT 0-2101 G-2032 9-2008	POJ/P 013030 CP8 0.0506 0.0508 0.0508 0.0508	TS = 69124 CAF 0.1595 0.1524 0.1502	RUN 386. 386. 386.
Q= PD= ALPHA 4.06 3.05 2.04 1.51	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942	IN-= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036	CY -0.0294 -0.0062- 0.0062- 0.0083 0.0749- 0.0428-	90. DI CR 0. 0.0004 -0.6008 0.0002 -0.0012	CAT 0-2101 0-2032 0-2008 0-2008 0-2003 0-1981	POJ/P 013030 CP8 0.0506 0.0508 0.0508 0.0503 0.0501 0.0500	TS = 69124 CAF 0.1595 0.1524 0.1502 0.1502 0.1502	RUN 386. 386. 386. 386. 386.
Q= PO= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942 -0.3213 -0.0594	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0100 -0.0071 -0.0014	CY -0.0294 -0.00620.0063 0.0749- 0.0428-	90. DI CR 0. 0.004 -0.6008 0.0002 -0.0012 -0.0014	CAT 0-2101 0-2032 0-2008 0-2008 0-2003 0-1981 0-1968	POJ/P 013030 CP8 0.0506 0.0508 0.0508 0.0503 0.0501 0.0500 0.0500	TS = 69124 CAF 0.1595 0.1502 0.1502 0.1502 0.1482	RUN 386. 386. 386. 386. 386. 386.
Q= P0= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50 -0.	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036 -0.0428	RE PER HG PTS= CH -3.0141 -2.2428 -1.4588 -1.0187 -0.5942 -0.3213 -0.0594	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0100 -0.0071 -0.0014 -0.0050	CY -0.0294 -0.0090 -0.0063 0.0749 0.0428 -0.0121	90. DI CR 0. 0.004 0.0002 0.0012 0.0014 0.0003	CAT 0-2101 0-2101 0-2032 0-2008 0-2008 0-2003 0-1981 0-1968 0-1999	POJ/P 013030 CP8 0.0506 0.0506 0.0503 0.0503 0.0501 0.0500 0.0499 0.0498	TS = 69124 CAF 0.1595 0.1502 0.1502 0.1482 0.1489 0.1501	RUN 386. 386. 386. 386. 386. 386.
Q= P0= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50 -0G.52 -1.02	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036 -0.0428 -0.0843	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942 -0.3213 -0.0594 0.3292 0.6643	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0100 -0.0071 -0.0014 -0.0050 -0.0030	CY -0.0294 -0.0090 -0.0062- 0.0083 0.0749- 0.0428- 0.0121- 9.0216- 0.000-	90. DI CR 0. 0004 -0.0008 0.0002 -0.0012 -0.0014 -0.0003 -0.0005	CAT 0-2101 0-2101 0-2032 0-2008 0-2008 0-2003 0-1981 0-1968 0-1999 0-1964	POJ/P 013030 CP8 0.0506 0.0508 0.0503 0.0501 0.0500 0.0499 0.0498 0.0497	TS = 69124 CAF 0.1595 0.1524 0.1502 0.1502 0.1482 0.1489 0.1501	RUN 386. 386. 386. 386. 386. 386. 386.
Q= P0= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50 -00.52 -1.02 -1.52	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036 -0.0428 -0.0843 -0.1307	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942 -0.3213 -0.0594 0.3292 0.6643 1.0558	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0014 -0.0050 -0.0030 -0.0066	CY -0.0294 -0.0090 -0.0062- 0.0083 0.0749 0.04280.0121- 9.0216- 0.0000- 0.0353	90. DI CR 0. 0004 0. 0002 0. 0012 0. 0014 0. 0003 0. 0005 0. 0006	CAT 0.2101 0.2032 0.2008 0.2008 0.2008 0.1981 0.1968 0.1999 0.1964 0.1989	POJ/P 013030 CP8 0.0506 0.0508 0.0501 0.0501 0.0501 0.0500 0.0499 0.0498 0.0497 0.0496	TS = 69124 CAF 0.1595 0.1502 0.1502 0.1502 0.1489 0.1489	RUN 386. 386. 386. 386. 386. 386. 386. 386.
Q= PD= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50 -0G.52 -1.52 -1.52 -2.02	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036 -0.0428 -0.0428 -0.0843 -0.1307 -0.1659	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942 -0.3213 -0.05942 0.3292 0.6643 1.0558 1.3366	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0100 -0.0050 -0.0050 -0.0030 -0.0066 -0.0037	CY -0.0294 -0.00900.0062- 0.0083 0.0749- 0.04280.0121- 0.0216- 0.0000- 0.0353 0.0060	90. DI CR 0. 0004 -0.0002 -0.0012 -0.0014 -0.0005 -0.0006 0.0006	CAT 0.2101 0.2032 0.2008 0.2006 0.2003 0.1981 0.1969 0.1989 0.1989	POJ/P 013030 CP8 0.0506 0.0508 0.0503 0.0501 0.0500 0.0499 0.0497 0.0496 0.0495	TS = 69124 CAF 0.1595 0.1592 0.1502 0.1502 0.1482 0.1483 0.1483 0.1483	RUN 386. 386. 386. 386. 386. 386. 386. 386.
Q= PD= ALPHA 4.06 3.05 2.04 1.51 1.00 0.50 -0G.52 -1.02 -1.52 -2.02 -3.03	3.77 PSI 400.0 CM CN 0.3607 0.2684 0.1748 0.1222 0.0724 0.0371 0.0036 -0.0428 -0.0843 -0.1307	RE PER HG PTS= CH -3.0141 -2.2422 -1.4588 -1.0187 -0.5942 -0.3213 -0.0594 0.3292 0.6643 1.0558 1.3366 2.0836	IN.= .488 .2659 PS CS 0.0008 -0.0016 -0.0020 -0.0036 -0.0014 -0.0050 -0.0030 -0.0066	CY -0.0294 -0.00900.0062- 0.0083 0.0749- 0.04280.0121- 9.0216- 0.0050 0.0353 0.0060 0.0163	90. DI CR 0. 0004 -0.0002 -0.0012 -0.0014 -0.0005 -0.0006 -0.0006	CAT 0.2101 0.2032 0.2008 0.2008 0.2008 0.1981 0.1968 0.1999 0.1964 0.1989	POJ/P 013030 CPB 0.0506 0.0508 0.0503 0.0501 0.0500 0.0499 0.0497 0.0496 0.0495 0.0495	TS = 69124 CAF 0.1595 0.1502 0.1502 0.1502 0.1482 0.1483 0.1463 0.1463	RUN 386. 386. 386. 386. 386. 386. 386. 386.

HOE	EL 946.2	СОМ	FIG. 2.000	M	NCH 4.50	j	PHI =	30.	
Q=	3,77 PSI	RE PER	IN.= .48E0	6 T0≖	90. DE	G.F	P0J/P	rs =	20.
P0=	400.0 CH	HG P.TS=	.2659 PSI			RUN NO.	01303	69125	
ALPHA	CN	СМ	CS	CY	CR	CAT	СРВ	CAF	RUN
4.05	0.3541		-0.0081		0.0001				
3.05	0.2634		-0.0077		0.0003				
2.04	0.1732		-0.0080		0.0006	-			
1.52	0.1106		-0.0154		.0003 م				
1.01		,	-0.0117		0.0002				
0.51	0.0406		-0.0076	0.0327-			0.0508		
-02	0.0029		-0.0061		0.0005				
	-0.0469	0.3482			0.0002				
_	-0.0896	0.6986			-0.0006				
	-0-1270		-0.0104		0.0006				
		1.3802			0.0010				
	-0.2590		~0.0081		0.0012				
-4.04	-0.3583.	2-9384	-0.0100	0.0535	0.0013	0.2053	0.0499	0-1555	387•
	PÉL 946.2		FIG. 2.000		ACH 4.50		-	30 .	
			FIG. 2.000 IN ₀ = .48E0				-	30. rs =	40.
Q=	3.77 PSI	RE PER		6 TO=	90. DE	G•F	-	rs =	40.
Q=	3.77 PSI = 400.0 CM	RE PER	IN.= .48E0	6 TO=	90. DE	G•F	P0J/P1	rs =	40 . RUN
Q= PO= Alpha	3.77 PSI = 400.0 CM	RE PER HG PTS≃ CM:	IN.= .48E0 .2659 PSI	6 TO=	90. DE	G.F RUN NO. CAT	POJ/P1 013030 CP6	rs = 69126 C4F	RUN
Q= PO= Alpha	3.77 PSI = 400.0 CM CN 0.3438	RE PER HG PTS≃ CM: -2.9055	IN.= .48E0 .2659 PSI CS	6 TO= CY 0.1032	90. DE	G.F RUN NO. CAT 0.2201	POJ/P1 013030 CP6	rs = 69126 CAF 0.1692	RUN 3'88 •
Q= PO= ALPHA 4.05 3.05	3.77 PSI = 400.0 CM CN 0.3438	RE PER HG PTS= CM: -2.9055 -2.1508	IN.= .48E0 .2659 PSI CS -0.0163	6 TO= CY 0.1032 0.0863	90. DE	G.2201 G.2189	POJ/P1 013030 CP6 0.0509 0.0510	rs = 59126 CAF 0.1692 0.1679	RUN 388 •
Q= PO= ALPHA 4.05 3.05 2.04	3.77 PSI = 400.0 CM CN 0.3438 0.2540	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146	6 TO= CY 0.1032 0.0863 0.1012	90. DE CR 0.0046 0.0048	G.F RUN NO. CAT 0.2201 0.2189 0.2150	POJ/P1 013030 CP6 0.0509 0.0510 0.0509	rs = 69126 CAF 0.1692 0.1679 0.1641	RUN 388 • 388 •
Q= PO= ALPHA 4.05 3.05 2.04 1.51	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162	CY 0.1032 0.0863 0.1012 0.1154	90. DE CR 0.0046 0.0048 0.0032	G.F RUN NO. CAT 0.2201 0.2189 0.2150 0.2163	POJ/P1 013030 CP6 0.0509 0.0510 0.0509 0.0506	rs = 69126 CAF 0.1692 0.1679 0.1641 (1.1658	RUN 388 • 388 • 388 •
Q= PO= ALPHA 4.05 3.05 2.04 1.51	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179	6 TO= CY 0.1032 0.0863 0.1012 0.1154 0.1228	90. DE CR 0.0046 0.0048 0.0032 0.0036	CAT 0-2201 0-2189 0-2150 0-2163 0-2113	POJ/P1 013030 CP6 0.0509 0.0510 0.0509 0.0506 0.0503	TS = 69126 CAF 0.1692 0.1679 0.1641 G.1658 0.1610	RUN 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186	6 TO= CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451	90. DE CR 0.0046 0.0048 0.0032 0.0036 0.0040	CAT 0.2201 0.2189 0.2150 0.2163 0.2113 0.2109	POJ/P1 013030 CP6 0.0509 0.0510 0.0509 0.0506 0.0503 0.0502	TS = 69126 CAF 0.1692 0.1679 0.1641 (1.1658 0.1610 0.1607	RUN 388 • 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208	CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451 0.0959	90. DE CR 0.0046 0.0048 0.0032 0.0036 0.0040 0.0013	CAT 0.2201 0.2189 0.2150 0.2163 0.2113 0.2109 0.2102	POJ/P 013030 CP6 0.0509 0.0509 0.0506 0.0503 0.0502 0.0501	TS = 69126 CAF 0.1692 0.1641 0.1641 0.1600 0.1607	RUN 388 • 388 • 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215 -0.0133 -0.0544 -0.0967	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510 0.3842 0.7305	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208 -0.0158 -0.0172 -0.0166	6 TO= CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451 0.0959 0.1044	90. DE CR 0.0046 0.0032 0.0036 0.0040 0.0013 0.0037	CAT 0.2201 0.2189 0.2150 0.2163 0.2113 0.2109 0.2102 0.2111	POJ/P 013030 CP6 0.0509 0.0509 0.0506 0.0503 0.0502 0.0501 0.0499	CAF 0.1692 0.1692 0.1641 (0.1658 0.1610 0.1601 0.1601	RUN 388 • 388 • 388 • 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01 -0.51 -1.02	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215 -0.0133 -0.0544 -0.0967	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510 0.3842	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208 -0.0158 -0.0172 -0.0166	6 TO= CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451 0.0959 0.1044 0.0969	90. DE CR 0.0046 0.0032 0.0036 0.0040 0.0013 0.0037 0.0035	CAT 0.2201 0.2189 0.2150 0.2113 0.2109 0.2102 0.2111	POJ/P 013030 CP6 0.0509 0.0509 0.0506 0.0503 0.0502 0.0501 0.0499 0.0498	CAF 0.1692 0.1692 0.1641 0.1640 0.1600 0.1601 0.1612	RUN 388 • 388 • 388 • 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01 -0.51 -1.02 -1.52	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215 -0.0133 -0.0544 -0.0967 -0.1369 -0.1766	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510 0.3842 0.7305 1.0568 1.3849	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208 -0.0158 -0.0172 -0.0166 -0.0166 -0.0146	6 T0= CY 0.1032 0.0863 0.1012 0.1154 0.1238 0.1451 0.0959 0.1044 0.0969 0.0943	90. DE CR 0.0046 0.0032 0.0036 0.0040 0.0013 0.0037 0.0035 0.0021	CAT 0.2201 0.2189 0.2150 0.2113 0.2109 0.2102 0.2111 0.2136 0.2071	POJ/P 013030 CP6 0.0509 0.0510 0.0509 0.0503 0.0502 0.0501 0.0499 0.0498 0.0496	CAF 0.1692 0.1672 0.1641 0.1658 0.1607 0.1601 0.1612 0.1638 0.1575	RUN 388 • 388 • 388 • 388 • 388 • 388 • 388 • 388 •
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01 -0.51 -1.05 -1.52 -2.03 -3.03	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215 -0.0133 -0.0544 -0.0967 -0.1369 -0.1766 -0.2697	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510 0.3842 0.7305 1.0568 1.3849 2.1651	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208 -0.0158 -0.0172 -0.0166 -0.0166 -0.0166	CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451 0.0959 0.1044 0.0969 0.0943 0.0772 0.0889	90. DE CR 0.0046 0.0048 0.0032 0.0036 0.0040 0.0013 0.0037 0.0035 0.0021 0.0032 0.0023	CAT 0-2201 0-2189 0-2150 0-2163 0-2109 0-2102 0-2111 0-2136 0-2071 0-2094 0-2098	POJ/P1 013030 CP6 0.0509 0.0510 0.0509 0.0503 0.0502 0.0501 0.0499 0.0498 0.0494	CAF 0.1692 0.1679 0.1641 0.1607 0.1601 0.1612 0.1638 0.1575 0.1600 0.1605	RUN 388. 388. 388. 388. 388. 388. 388. 388
Q= P0= ALPHA 4.05 3.05 2.04 1.51 1.01 0.50 -0.01 -0.51 -1.05 -1.52 -2.03 -3.03	3.77 PSI = 400.0 CM CN 0.3438 0.2540 0.1628 0.1102 0.0671 0.0215 -0.0133 -0.0544 -0.0967 -0.1369 -0.1766	RE PER HG PTS= CM: -2.9055 -2.1508 -1.3953 -0.9581 -0.6042 -0.2180 0.0510 0.3842 0.7305 1.0568 1.3849 2.1651	IN.= .48E0 .2659 PSI CS -0.0163 -0.0146 -0.0162 -0.0179 -0.0186 -0.0208 -0.0158 -0.0172 -0.0166 -0.0166 -0.0146	CY 0.1032 0.0863 0.1012 0.1154 0.1228 0.1451 0.0959 0.1044 0.0969 0.0943 0.0772 0.0889	90. DE CR 0.0046 0.0048 0.0032 0.0036 0.0040 0.0013 0.0037 0.0035 0.0021 0.0032	CAT 0-2201 0-2189 0-2150 0-2163 0-2109 0-2102 0-2111 0-2136 0-2071 0-2094 0-2098	POJ/P1 013030 CP6 0.0509 0.0510 0.0509 0.0503 0.0502 0.0501 0.0499 0.0498 0.0494	CAF 0.1692 0.1679 0.1641 0.1607 0.1601 0.1612 0.1638 0.1575 0.1600 0.1605	RUN 388. 388. 388. 388. 388. 388. 388. 388

	MOD	EL 946.2	CONI	FIG. 2.000) , N	ICH 4.50)	PHI =	30.	
	Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	EG _* F	POJ/P1	rs = 100	i.
	PO=	400.0 CI	MHG PTS=	-2659 PSI	I		RUN NO	01303	69127	-
ALP	HA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.	05	0.3040	-2.5959	-0:0347	0.2453	0.0034	0.2350	0.0510	0.1840	389.
3.	04	0.2128	-1.8326	-0.0391	0.2815	0.0025	0.2296	0.0511	0.1785 -	389.
2.	02	0.1254	-1.1136	-0.0386	0.2782	0.0040	0.2271	0.0510	0:1761	389.
ı.	51	0.0785	-0.7350	-0.0387					0.1732	389.
1.	00	0.0346	-0.3670	-0.0382	0.2683	0.0017	0.2262	0.0504	0.1759	389.
0.	49	-0.0064	-0.0346	-0.0368	0.2541	0.0015	0.2257	0.0502	0.1755	389.
-0.	01	-0.0433	0.2583			0.0039				389
-0.	52	-0.0858		-0.0443		0.0026				389.
		-0.1279	0.9444			0.0023				389.
									0.1724	389.
		-0.2116	1.6419	-0.0334 -0.0329		0.0019				.389.
				-0.0318					0.1694	
				-0.0335	0.2188				0.1753	
	MOD	EL 946.2	CON	FIG. 2.000) Hi	ACH 4.50	0	PHI =	45.	`
	Q=	3.77 PSI	RE PER	IN.= .48E0)6 TO=	90. DE	EG.F	POJ/P	rs = `	•
	₽0=	400.0 C	MHG PTS=	.2659 PS	i	•	RÙN NO	01303	69128	
ALP	HA	CN	CH	cs	CY	CR	CAT	СРВ	CÁF	RUN
4.	06	0.3639	-3-0253	-0.0048	0.0265	0.0017	0.2393	0-0507	0.1886	390.
	05	0.2716		-0.0009	-0.0110					390.
	04	0.1786		0.0013	-0.0295					. 390 •
	51	0.1282		0.0025	-0.0424					390.
	02	0.0883	-0.7312		-0.0682					390.
	51	-		-0.0005	-0.0059					390.
-0.		0.0013	-0.0151		-0.0685					390.
		-0.0411	0.3368		-0.0750					390.
		-0.0851	0.6981		-0.0840					390.
		-0.1312	1.0866	-	-0.0673					390.
		-0.1512	1.3605		-0.1476					390.
		-0.2562	2:1147		-0.1771					390.
-		-0.3499	2,9027						0.1806	390.

MOI	DEL 946.2	CON	FIG. 2.00	00 M	ACH 4.51	0	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .48E	06 T0≖	90. DI	EG.F	POJ/P	TS =	10.
P0:	= 400.0 CM	HG PTS=	.2659 PS	i		RUN NO	. 01303	69129	
ALPHA	CÑ	CM	cs	CY.	CR	CAT	CPB	CAF	RUN
4-05	0.3587	-2.9917	-0.0097	0.0648	0.0018	0.2293	0.0512	0.1781	391.
3.06	0.2654	-2.2036	-0.0090		0.0011				
2.04	0.1762	-1.4618	-0.0064		-0.0009				
1.52		-0.9963	-0.0103	0.0672	0.0019	0.2239	0.0505	0.1734	391.
1.02	0.0762	-0.6265	-0.0132	0.0985	-0.0016	0.2246	0.0502	0.1744	391.
0.51	0.0388	-0.3294	-0.0067		0.0012				
-0.	-0.0015	0.0016	-0.0055	0.0232	0.0009	0.2183	0.0499	0.1683	391.
-0.50	-0.9490	0.4005	-0.0093		0.0006				
-1.01	-0.0865	0.6963	-0.0029	-0.0053					
-1.51	-0,1309	1.0664	-0.0058		0.0012				
	-0.1724	1-4049	-0.0035	-0.0014					
-3.03	-0.2583		0.0001	-0.0313					
-4.04	-0.3553	2.9420	0.0004	-0.0309					
HOI	DEL 946.2	C01/4	FIG. 2.00	10 M	4CH 4.50	0,	PH1 =	45.	
Q=	3.77 PSI	RE PER	IN.≈ .48E	06 TO=	90. 06	EG.F	P0J/P1	rs =	20.
P0=	= 400.0 CM	HG / PTS=	.2659 PS	I		RÙN NO.	. 01303	69130	
ALPHA	CN	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
4.05	0.3529	-2-9494	-0.0163	0-1134	0.0019	0-2268	0.0510	0-1758	392 •.
3.05			-0.0141		0.0005				
2.04			-0.0150		0.0005				
1.52			-0.0194		-0.0012				
1.02			-0.0208		-0.0015				
0.51			-0.0144		0.0013				
0.01	0.0046		-0.0036	-0.0168					
	-0.0425		-0.0058		0.0020				
	-0.0890	•	-0.0107		0.0004				
		1.1252			0.0007				
	-0-1724		-0.0056		0.0004				
	-0.2615		-0.0050			0.2177			

THE PARTY OF THE P

MODEL 946.2	CONFIG	2.000	AH	CH 4.50	PHI =	-45•	
Q= 3.77 PSI	RE PER IN	1.= .48E06	10=	90. DEG.F	PÓJ/PTS	= 40.	
PO= 400.0 C	HG PŢS= .	2659 PSI		RUN NO	• 01,303 <i>6</i> 9	131	
ALPHA CN	CM	cs	CY	CR CAT	CPB	CAF	RUN
4.05 0.3456	-2.8999 -0	.0253 (0-1807	J.9044 0.2287	0.0512 0	.1775 3	193 0
3.05 0.2512	-2.1043 -0	0.0236	0.1601	0.0025 0.2241	0.0513 0		193.
2.04 0.1622	-1.3653 -0			0.0056 0.2209			193.
1.52 0.1091	-0.9233 -0			0.0014 0.2189			93.
1.01 0.0540	-0.5516 -0			0.0042 0.2211			193.
0.51 0.0211	-0-1923 -0			0.0007 0.2187			193.
-00.0147	0.0862 -0			0.0005 0.2163			193.
-0.50 -0.0536	9.4018 -0			0.0033 0.2153			193
-1.01 -0.1031	0.8223 -0			0.0002 0.2176			393.
-1.52 -0.1400	1.1121 -0			0.0039 0.2122			193.
-2.02 -0.1845 -3.03 -0.2706	1.4876 -0 2.2016 -0			3.9023 0.2171 0.0048 0.2167			193. 193.
-4.04 -0.3713	3.0574 -0			0.0048 0.2287			193.
-4.04 -0.3113	240714 -0	0.0104	0.0331	0-000 :0-2210	0.0502 0	•1(no)	37.3.
MODEL 946.2 Q= 3.77 PS1		5. 2.000 H.= .48E06		CH 4.50 90. DEG.F	РНІ = 2 7 9\L09	45. = 100.	
Q= 3.77 PSI		1.= .48E06		90. DEG.F		= 100.	
Q= 3.77 PSI	RE PER IN	1.= .48E06		90. DEG.F	POJ/PTS	= 100.	RUN
Q= 3.77 PS1 P0= 400.0 C	RE PER IN	4.= .48E06 .2659 PSI CS	TO=	90. DEG.F RUN NO CR CAT	POJ/PTS - 0130369 - CPB	= 100. 132 CAF	RUN 394.
Q= 3.77 PS1 P0= 400.0 CF ALPHA CN 4.05 0.3094	RE PER IN MHG PTS= • CM -2•6072 -0	4.= .48E06 .2659 PSI CS	T0= CY 0.4091	90. DEG.F RUN NO CR CAY 0.0027 0.2334	POJ/PTS - 0130369 - CPB - 0.0512 0	= 100. 132 CAF .1821 3	
Q= 3.77 PS1 P0= 400.0 C	RE PER IN	.2659 PSI CS 0.0549 (T0= CY 0.4091 0.4120	90. DEG.F RUN NO CR CAT	POJ/PTS - 0130369 - CPB - 0.0512 0 0.0514 0	= 100. 132 CAF .1821 3	394.
Q= 3.77 PS1 P0= 400.0 CALPHA CN 4.05 0.3094 3.05 0.2151	RE PER IN MHG PTS= • CM -2.6072 -0 -1.8115 -0	CS 0.0549 0.0552	T0= CY 0.4091 0.4120 0.3905	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2316	POJ/PTS - 0130369 CPB 0-0512 0 0-0514 0	= 100. 132 CAF .1821 2 .1802 3	394. 394.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291	RE PER IN MHG PTS= . CM -2.6072 -0 -1.8115 -0 -1.1074 -0	CS 0.0549 0.0552 0.0536 0.0481	TO= CY 0.4091 0.4120 0.3905 0.3377	90. DEG.F RUN NO CR CAY 0.0027 0.2334 0.0019 0.2316 0.0019 0.2286	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0	= 100. 132 CAF .1821 : .1802 : .1775 :	394. 394.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843	RE PER IN MHG PTS= . CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0	CS 0.0549 0.0552 0.0536 0.0481	T0= CY 0.4091 0.4120 0.3905 0.3377 0.3036	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2316 0.0019 0.2286 0.0010 0.2283	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0 0.0504 0	= 100. 132 CAF .1821 3 .1802 3 .1775 3 .1755 3	394. 394. 394.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417	RE PER IN MHG PTS= . CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3977 -0	CS 0.0549 0.0552 0.0536 0.0481 0.0447 0.0418 0.0528	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.3812-	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2236 0.0010 0.2286 0.0010 0.2263 0.0006 0.2239 0.0035 0.2230 0.2224	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0 0.0507 0 0.0502 0 0.0500 0	= 100. 132 CAF .1821 .1802 .1775 .1755 .1735 .1728	394. 394. 394. 394. 394.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417 0.49 0.0018	RE PER IN MHG PTS= CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3977 -0 0.3756 -0 0.5872 -0	CS 0.0549 0.0552 0.0536 0.0481 0.0447 0.0418 0.0528 0.0383	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.3812- 0.2266	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2236 0.0010 0.2286 0.0010 0.2263 0.0035 0.2230 0.0224 0.0029 0.2213	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0 0.0504 0 0.0502 0 0.0500 0 0.0500 0	= 100. 132 CAF .1821 .1802 .1775 .1755 .1735 .1728 .1728	394. 394. 394. 394. 394. 394.
Q= 3.77 PS1 P0= 400.0 CI ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417 0.49 0.0018 -0.01 -0.0508	RE PER IN MHG PTS= CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3977 -0 0.3756 -0 0.5872 -0 1.0078 -0	CS 0.0549 0.0552 0.0536 0.0481 0.0447 0.0418 0.0528 0.0383	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.3812- 0.2266 0.2878	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2286 0.0010 0.2286 0.0010 0.2239 0.0035 0.2230 0.0029 0.2213 0.0019 0.2113	POJ/PTS - 0130369 CPB 0.0512 0 0.0511 0 0.0507 0 0.0507 0 0.0504 0 0.0502 0 0.0500 0 0.0499 0	= 100. 132 CAF -1821 -1802 -1775 -1755 -1735 -1728 -1728 -1725 -1714 -1693	394. 394. 394. 394. 394. 394. 394.
Q= 3.77 PS1 P0= 400.0 CF ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417 0.49 0.0018 -0.01 -0.0508 -0.52 -0.0801 -1.02 -0.1297 -1.52 -0.1645	RE PER IN MHG PTS= CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3977 -0 0.3756 -0 0.5872 -0 1.0078 -0 1.2841 -0	CS 0.0549 0.0552 0.0536 0.0481 0.0447 0.0418 0.0528 0.0383 0.0441 0.0363	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.3812- 0.2266 0.2878 0.2097	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2236 0.0010 0.2239 0.0035 0.2230 0.0029 0.2213 0.0019 0.2132 0.0029 0.213	POJ/PTS - 0130369 CPB 0-0512 0 0-0514 0 0-0517 0 0-0507 0 0-0504 0 0-0502 0 0-0509 0 0-0499 0 0-0499 0	= 100. 132 CAF .1821 .1802 .1775 .1755 .1735 .1735 .1728 .1728 .1725 .1714 .1693 .1713	394. 394. 394. 394. 394. 394. 394.
Q= 3.77 PS1 P0= 400.0 C ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417 0.49 0.0018 -0.01 -0.0508 -0.52 -0.0801 -1.02 -0.1297 -1.52 -0.1645 -2.03 -0.2135	RE PER IN MHG PTS= . CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3777 -0 0.3756 -0 0.5872 -0 1.2841 -0 1.2841 -0	CS 0.0549 0.0552 0.0536 0.0447 0.0447 0.0418 0.0528 0.0528 0.05383 0.0441	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.3812- 0.2660 0.2678 0.2678	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2286 0.0010 0.2263 0.0006 0.2239 0.0035 0.2230 0. 0.2210 0.0029 0.2213 0.0019 0.2192 0.0021 0.2218	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0 0.0504 0 0.0502 0 0.0509 0 0.0499 0 0.0499 0 0.0497 0 0.0496 0	= 100. 132 CAF .1821 .1802 .1775 .1755 .1725 .1728 .1725 .1714 .1693 .1713 .1691	394. 394. 394. 394. 394. 394. 394.
Q= 3.77 PS1 P0= 400.0 CF ALPHA CN 4.05 0.3094 3.05 0.2151 2.03 0.1291 1.51 0.0843 1.00 0.0417 0.49 0.0018 -0.01 -0.0508 -0.52 -0.0801 -1.02 -0.1297 -1.52 -0.1645	RE PER IN MHG PTS= CM -2.6072 -0 -1.8115 -0 -1.1074 -0 -0.7450 -0 -0.3977 -0 0.3756 -0 0.5872 -0 1.0078 -0 1.2841 -0	CS 0.0549 0.0552 0.0536 0.0447 0.0447 0.0418 0.0528 0.0383 0.0441 0.0363 0.0405	TO= CY 0.4091 0.4120 0.3905 0.3377 0.3036 0.2685 0.2685 0.2266 0.2267 0.2268 0.22535 0.2531	90. DEG.F RUN NO CR CAT 0.0027 0.2334 0.0019 0.2236 0.0010 0.2239 0.0035 0.2230 0.0029 0.2213 0.0019 0.2132 0.0029 0.213	POJ/PTS - 0130369 CPB 0.0512 0 0.0514 0 0.0511 0 0.0507 0 0.0504 0 0.0502 0 0.0500 0 0.0499 0 0.0499 0 0.0497 0 0.0497 0	= 100. 132 CAF .1821 .1802 .1775 .1755 .1755 .1728 .1728 .1725 .1714 .1693 .1713 .1691	394. 394. 394. 394. 394. 394. 394.

M	DDEL 946.2	CONI	FIG. 2.000) Hi	NCH 4.50	0	PHI =	60.	
0 :	= 3.77 PSI	RE PER	IN.= .48E0	6 To=	90. DE	EG.F	POJ/P	rs =	•
Pi	D= 400.0 CH	HG PTS=	.2659 PSI			RUN NO.	01303	69133	
ALPH	A CN	CM	CS ~	CY	CR	CAT	CPB	CAF	RUN
4.1	0.3715	-3.0921	-0.0175	0.1410	0.0028	0.2471	0.0506	0.1965	395.
3.1			-0.0147			0.2416			395.
2.0			-0.0103			0.2435			395.
1.5		- ;	-0.0096	0.0627	0.0041	0.2395	0.0506	0.1888	395.
	0.0888	-0-7267	-0.0098	0.0703	0.0024	0.2426	0.0501	0.1925	395.
0.5	5 0.0472	-0.3918	-0.0060	0.0309	0.0039	0.2385	0.0499	0.1886	395.
0.0	0.0028	-0.0222	-0.0057	0.0342	0.0028	0.2372	0.0498	0.1875	395.
-0.4	5 -0.0352			-0.0443	0.0042	0.2358	0.0497	0.1861	395.
-0.9	7 -0.0832	0.6866	-0.0033	0.0164	0.0037	0.2377	0.0496	0.1881	395.
-1.4	7 -0.1261	1.0406	-0.0005	-0.0091	0.0039	0.2364	0.0497	0.1867	395.
-1.9	7 -0-1621	1.3338	0.0049	-0.0590	0.0029	0.2379	0.0497	0.1882	395.
-2.9	9 -0.2584	2.1408	0.0081	8580.0-	0.0044	0.2384	0.0499	0.1885	395.
-3.9	9 -0.3543	2.9501	0.0193	-0.1856	0.0034	0.2385	0.0504	0.1881	395.
м	DDEL 946.2	ČONI	FIG. 2.000	M/	ICH 4.50)	PHI =	60.	
Ç:	= 3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	EG∙ F	POJ/P	TS = 1	10.
P	0= 400.0 CF	HG PTS=	.2659 PSI			RUN NO	01303	69134	
ALPH	A CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.0	9 0.3677	-3-0721	-0.0235	0-1841	0-0028	0.2342	0-0507	0-1835	396.
3.0			-0.0208			0.2346			396.
2.0			-0.0140			0.2320			396.
1.5			-0.0172			0.2325			396.
1.0			-0.0122			0.2297			396.
0.5			-0.0098			0.2284			396.
0.0			-0.0045	0.0082	0.0028	0.2242	0.0499	0.1743	396.
-	6 -0.0424	0.3441				0.2244			396.
	7 -0.0868		-0.0047			0,2276			396.
	7 -0.1347		-0.0089			0.2279			396.
	8 -0.1713			-0.0490					396.
	9 -0.2613		0.0080	-0.0993	0.0019	0.2282	0.0499	0.1783	396.
		2.9756							

BEN MINDER BERTHANDER BENERAL MINDER MINDER BENERAL BENERAL BENERAL MINDER BENERAL BENERAL BENERAL GRADER BENERAL BENE

MODE	L 946.2	COM	FIG. 2.0	00 H	ACH 4.50	= IH9	50.
Q= 3	-77 PSI	RE FER	IN.= -48	E06 T0=	90. DEG.F	POJ/PTS :	20.
F 0=	400.0 CM	HG PTS=	.2659 P	SI	RUN NO	01303691	35
ALPHA	C).	CM	cs	CY	CR CAT	CPB C	KF . RUN
4.10	0.3632	-3.0364	-0.0326	0.2535	0.0029 0.2287	7 0.0510 O.	i778 397.
3.10	0.2705	-2.2525	-0.0250		0.0013 0.2289		
2.08	0-1771	-1.4704	-0.0200	0.1315	0.0035 0.2249	0.0507 0.3	1743 397.
1.56			-0.0192		-0.0008 0.2239		
1.06			-0.0142		0:0032 0:2225		
	0.0447		-0.0097		0.0027 0.2271		
G.03 -			-0.0090		0.0017 0.2230		
-0.46 -			-0.0173		0.0006 0.2233		
-0.97 -			-0:0050		0.0014 0.2204		
-1.48 -			-0.0059		0.0015 0.2207		
-1.98			-0.0030		0.0017 0.7209		
-2.98 -		2.1596			0.0020 0.2241		
-4.00 -	0.3610	2.9989	0.0131	-0.1581	0:0035 0.2228	0.0503 0.	1725 397.
	L 946,2		FIG. 2.0 IN.= .48		ACH 4.50 90. DEG.F	PHI = (50. * 40.
Q= 3		RE PER	IN.= .48	E06 TO=	90. DEG.F		* 40.
Q= 3	.77 PSI	RE PER	IN.= .48	E06 TO=	90. DEG.F	POJ/PTS :	* 40.
Q= 3 PO= Alpha	.77 PSI 400.0 CM CN	RE PER HG PTS=	IN.= .48 .2659 P	E06 T0=	90. DEG.F RUN NO	POJ/PTS : 0. 01303691; CPB C	* 40. 36 AF RUN
Q= 3 PO= ALPHA 4.10	.77 PSI 400.0 CM	RE PER HG PTS= CM -2.9923	IN.= .48	E06 T0= SI CY 0.3207	90. DEG.F RUN NO CR CAT	POJ/PTS : 0. 01303691; CPB C	* 40. 36 AF RUN 1843 398.
Q= 3 PO= ALPHA 4.10 3.09	.77 PSI 400.0 CM CN 0.3571	RE PER HG PTS= CM -2.9923 -2.1957	IN.= .48 .2659 P CS -0.0425	E06 T0= SI CY 0.3207 0.2723	90. DEG.F RUN NO CR CAT 0.0055 0.2351	POJ/PTS : 0. 01303691; CPB C: 0.0508 0.	* 40. 36 AF RUN 1843 398. 1772 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08	.77 PSI 400.0 CM CN 0.3571 0.2630	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151	IN.= .48 .2659 P CS -0.0425 -0.0374	EE06 T0= CY 0.3207 0.2723 0.2260	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281	POJ/PTS : CPB C 0.0508 0. 0.0509 0. 0.0507 0.	* 40. 36 AF RUN 1843 398. 1772 398. 1748 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56	CN 0.3571 0.2630 0.1696	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324	E06 T0= SI CY 0.3207 0.2723 0.2260 0.3088	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281 0.0061 0.2255	POJ/PTS CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0.	* 40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56	CN 0.3571 0.2630 0.1696 0.1139	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.6230	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406	E06 T0= SI CY 0.3207 0.2723 0.2260 0.3088 0.2420	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281 0.0061 0.2255 0.0018 0.2248	POJ/PTS CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55	CN 0.3571 0.2630 0.1696 0.1139 0.0745	RE PER HG PTS= CH -2.9923 -2.1957 -1.4151 -0.9450 -0.6230 -0.2906	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281 0.0061 0.2255 0.0018 0.2246 0.0013 0.2217	POJ/PTS CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0. 0.0500 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1718 398. 1707 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55 0.04 -	CN 0.3571 0.2630 0.1696 0.1139 0.0745 0.0330 0.0064	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.6230 -0.2906 0.0295 0.4479	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332 -G.0246 -0.0189 -0.0256	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549 0.0993 0.1707	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281 0.0061 0.2256 0.0018 0.2246 0.0013 0.2211 0.0047 0.2219 0.0049 0.2206 0.0031 0.2195	POJ/PTS 0. 01303691 CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0. 0.0509 0. 0.0499 0. 0.0498 0.	* 40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1718 398. 1707 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55 0.040.47	CN 0.3571 0.2630 0.1696 0.1139 0.0745 0.0330 0.064 0.0558	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.6250 -0.2906 0.0295 0.4479 0.7776	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332 -0.0256 -0.0189 -0.0256	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549 0.0993 0.1707 0.1058	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2281 0.0061 0.2255 0.0018 0.2246 0.0013 0.2211 0.0047 0.2219 0.0049 0.2206 0.0031 0.2195 0.0027 0.2196	POJ/PTS 0. 01303691 CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0. 0.0500 0. 0.0498 0. 0.0498 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1718 398. 1707 398. 1707 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55 0.04 -	CN 0.3571 0.2630 0.1696 0.1139 0.0745 0.0330 0.0064 0.0558 0.0966	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.2906 0.0295 0.4479 0.7776 1.0963	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332 -0.0256 -0.0189 -0.0256 -0.0191 -0.0101	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549 0.0993 0.1707 0.1058 0.0140	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2283 0.0018 0.2246 0.0018 0.2216 0.0047 0.2219 0.0049 0.2206 0.0031 0.2195 0.0027 0.2195 0.0048 0.2182	POJ/PTS 0. 01303691 CPB C 0.0508 0. 0.0509 0. 0.0504 0. 0.0502 0. 0.0502 0. 0.0500 0. 0.0498 0. 0.0498 0. 0.0497 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1718 398. 1707 398. 1707 398. 1697 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55 0.04 - -0.47 - -0.98 - -1.48 - -1.98 -	CN 0.3571 0.2630 0.1696 0.1139 0.0745 0.0330 0.0064 0.0558 0.0966 0.1360 0.1797	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.6230 -0.2906 0.0295 0.4479 0.7776 1.0963 1.4615	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332 -G.0246 -0.0189 -0.0256 -0.0191 -0.0118	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549 0.0993 0.1707 0.1058 0.0140 0.0357	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2263 0.0061 0.2255 0.0018 0.2246 0.0013 0.2217 0.0047 0.2219 0.0049 0.2006 0.0031 C.2195 0.0027 0.2196 0.0027 0.2182 0.0048 0.2182 0.0056 C.2214	POJ/PTS 0. 01303691 CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0. 0.0500 0. 0.0499 0. 0.0498 0. 0.0498 0. 0.0498 0. 0.0498 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1716 398. 1707 398. 1699 398. 1699 398.
Q= 3 PO= ALPHA 4.10 3.09 2.08 1.56 1.06 0.55 0.04 -	CN 0.3571 0.2630 0.1696 0.1139 0.0745 0.0330 0.0064 0.0558 0.0966 0.1360 0.1797	RE PER HG PTS= CM -2.9923 -2.1957 -1.4151 -0.9450 -0.6230 -0.2906 0.0295 0.4479 0.7776 1.0963 1.4615 2.2251	IN.= .48 .2659 P CS -0.0425 -0.0374 -0.0324 -0.0406 -0.0332 -G.0246 -0.0189 -0.0256 -0.0191 -0.0118	CY 0.3207 0.2723 0.2260 0.3088 0.2420 0.1549 0.0993 0.1707 0.1058 0.0140 0.0357 -0.0093	90. DEG.F RUN NO CR CAT 0.0055 0.2351 0.0033 0.2283 0.0018 0.2246 0.0018 0.2216 0.0047 0.2219 0.0049 0.2206 0.0031 0.2195 0.0027 0.2195 0.0048 0.2182	POJ/PTS CPB C 0.0508 0. 0.0509 0. 0.0507 0. 0.0504 0. 7 0.0502 0. 0.0500 0. 0.0499 0. 0.0498 0. 0.0498 0. 0.0498 0. 7 0.0498 0.	40. 36 AF RUN 1843 398. 1772 398. 1748 398. 1743 398. 1715 398. 1718 398. 1707 398. 1699 398. 1699 398. 1685 396. 1717 398.

Ħ	ODEL 946.2	CON	FIG. 2.90	00 H	ACH 4.5	0	PHI =	60.		
Q	= 3.77 PSI	RE PER	IN.= .488	06 TO=	90. G	EG.F	POJ/P	1 5 = 1	100.	
^ 8	0= 400.9 C	MHG PTS∓	.2659 PS	51 ·		RUN NO	01303	69 <u>1</u> 37		
ALPH	IA CN	CM	cs	CY	CR	CAT	СРВ	CAF		RUN
4.0	9 0.3306	-2.7766	-0,0792			0.2294				399.
3.0	9 0.2391	-2.0067	-0.0740	0.5513	0.0028	0.2356	0.0504	0.185	2 .	399.
2.0		∸1.2808	-0.0639	0.4598	0.0050	0.2315	0.0505	0.181	0	399.
1.5			~0.0639			0.2304				395.
1.0		2	-0.0561			0.2320				399.
	4 0.0126		-0.0583			0.2294				399.
	4 -0.0254		-0.0484			0.2250				399.
	7 -0.0741		-0.0539			0.2284				399.
	9 -0-1190		-0.0483			0.2213				399.
	8 -0.1569		-0.0352	0.1806	0.0037	0.2241	0.0496	0-174	5	399.
	9 -0.2007		-0.0418	0.2522	0.0045	0.2303	0.0496	C 180.	7	399.
		2.4074				0.2218				399.
-4.0	0 -0.3916	.3.2250	-9.0313	0.1749	0-0063	D-2294	9-0502	0.1792	2	399.
	ODEL 946.2 = 3.77 PSI		FIG. 2.00		ACH 4.51	-	PHI =		•	
٥	0= 400.0 CI	MHG DTC=	. 2650 PG	:1		PHN NO.	01303	KQSBR		
•	U- 40000 U		*2037 13	••		KOII NO	. 01363	07230		
ALPH	A CN	CH	CS	CY	CR-	CAT	CPB	CAF		RUN
4.0	9 0.3707	-3.0922	-0.0061	0.0431	0-0034	0.2369	0.0503	0.186	Ś	400.
3.0	9 0.2775	-2.3037	-0.0058			0.2335				400.
2.0	7 0.1828	-1.5089	-0.0022	0.0060						400.
1.5	6 0.1298	-1.0634	-0.0092	0.0750-	0.0001	0.2332	0.0502	0.1830)	400.
1.0	4 0.0862	-0.7063	-0.0022			0.2330				400.
0.5	3 0.0452	-0.3741	-0.0005	-0.0079	0.0020	0.2314	0.0499	0.1819	5	400.
0.0	3 0.0039	-0.0339	0.0088	-0.0948	0-0040	0.2325	0.0498	0.1827	7	400.
-0.4	7 -0.0364	0.2964	0.0104	-0.1098	0.0041	0.2279	0.0497	0.1782	2	400 .
-0.9	8 -0.0818	0.6715	0.0103	-0.1061						400.
	8 -0.1266	1.0431	0.0100	-0.1040	0.0043	0.2291	0.0497	0.1794	4	400.
-1.9	9 -0-1709	1.4136	0.0111	-0.1143	0.0031	0.2275	0.0498	0.1777	7	400.
	9 -0.2607	2.1645		-0.1483						400.
, ,	0 -0.3625	3.0329	0.0191	-0 1942	00040	0.2295	0.0504	0.1791		400.

THE STATE OF THE PROPERTY OF T

MODEL 946.2	CONF	FIG. 2.0)0 H	ACH 4.50)	PHI =	75.	
Q= 3.77 PSI	RE PER	IN.= .48	E06 10=	90. DE	G.F	P0J/P	TS ≈	10.
PO= 400.0 CH	HG PTS=	•2659 PS	12	-	RUN NO.	. 91303	69239	
ALPHA CN	CH	εs	CY	CR	CAT	СРВ	CAF	RUN
4.09 0.3705	-3.0994	-0.0120	0.0831	0.0034	0.2298	0.0504	0-1795	401-
3.09 0.2767	-2.3017	-0.0086	0.0526	0.0011	0.2278	0.0505	0-1774	401.
2.07 0.1800	-1.4890	8500.0-		0.0025				
1.56 0.1285		-0.0133		0.0018				
1.04 0.0806		-0.0158		0.0019				
0.54 0.0421		-0.0056		0.0026				
0.04 0.0025		0.0017	-0.0467					
-0.47 -0.0410		ს.005 6	-0.0840					
-0.98 -0.0851		0.0021	-0.0498					
-1.48 -0.1286	1.0589	0.0001	-0.0248					
-1.98 -0.1719	1.4186	0.0024	-0.0504					
	2:1875		-0.0926					
-4.00 -0.3599	3.0039	0.0229	-0.2333	0.0028	0.2177	0.0505	0.1672	401.
MODEL 946.2 Q= 3.77 PSI		FIG. 2.00		NCH 4.50 90. DE		PHI =		20•
MODEL 946.2 Q= 3.77 PSI PO= 400.0 CF	RE PER	IN.= .481	E06 T0=	90. DE	S.F	_	rs =	20•
Q= 3.77 PSI	RE PER	IN.= .481	E06 T0=	90. DE	S.F	POJ/P	rs =	20• RUN
Q= 3.77 PSI PO= \$00.0 CM	RE PER IHG PTS= CH	IN.= .481 .2659 PS	E06 T0= SI CY	90. DE	G.F RUN NO. CAT	POJ/P 01303 CPB	TS = 69140 CAF	RUN
Q= 3.77 PSI PO= \$00.0 CM ALPHA CN 4.69 0.3704	RE PER IHG PTS= CH -3.1012	IN -= .481	E06 T0= SI CY 0 ~ \ 223	90. DE	G.F RUN NO. CAT 0.2257	POJ/P 01303 CPB 0-0503	TS = 69140 CAF 0.1754	RUN 402+
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753	RE PER HG PTS= CH -3.1012 -2.2909	IN = .481 .2659 PS CS -0.0180	E06 T0= SI CY 0 ~ \ 223	90. DE CR 0.0035 0.0043	G.F RUN NO. CAT 0.2257 0.2253	POJ/P 01303 CPB 0-0503	TS = 69140 CAF 0.1754	RUN 402+
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753	RE PER HG PTS= CH -3.1012 -2.2909 -1.4925	IN = .488 .2659 PS CS -0.0180 -0.0187	E06 T0= SI CY 0.1223 0.1240 0.0783	90. DE CR 0.0035 0.0043	CAT 0.2257 0.2253 0.2219	P0J/P 013030 CP8 0.0503 0.0504 0.0503	TS = 69140 CAF 0.1754 0.1716	RUN 402+ 402+ 402+
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803	RE PER ING PTS= CN -3.1012 -2.2909 -1.4925 -1.0616	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135	E06 T0= SI CY 0.1223 0.1240 0.0783	90. DE CR 0.0035 0.0043 0.	CAT 0.2257 0.2253 0.2219 0.2220	POJ/P 013030 CPB 0.0503 0.0504 0.0503 0.0502	TS = 69140 CAF 0.1754 0.1716 0.1718	RUN 402 • 402 • 402 • 402 •
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133	CY 0.1223 0.1240 0.0783 0.0660 -0.0147	90. DE CR 0.0035 0.0043 0.	CAT 0-2257 0-2253 0-2219 0-2220 0-2201	POJ/P 013030 CPB 0.0503 0.0504 0.0503 0.0502 0.0502	TS = 69140 CAF 0.1754 0.1716 0.1718	RUN 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0862	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133 -0.0039 -0.0187 -0.0065	CY 0.1223 0.1240 0.0783 0.0660 -0.0147 0.1339 0.0128	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.0080 0.0022	CAT 0.2257 0.2253 0.2253 0.2219 0.2220 0.2201 0.2203 0.2170	POJ/P 01303 CP8 0.0503 0.0504 0.0503 0.0502 0.0502 0.0498 0.0498	CAF 0.1754 0.1716 0.1716 0.1716 0.1705 0.1672	RUN 402. 402. 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0862 0.54 0.0408	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020 0.3575	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133 -0.0039 -0.0187 -0.0065 -0.0071	CY 0 0 1223 0 0 1240 0 0 0783 0 0 0660 -0 0 0147 0 1 339 0 0 0128 0 0 0201	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.008 0.0022 0.0030	CAT 0.2257 0.2253 0.2259 0.2220 0.2201 0.2203 0.2170 0.2125	POJ/P 01303 CPB 0.0503 0.0504 0.0503 0.0502 0.0500 0.0498 0.0498 0.0698	CAF C.1754 C.1754 C.1716 C.1716 C.1705 C.1672	RUN 402. 402. 402. 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= \$00.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0862 0.54 0.0408 0.03 -0.0006 -0.48 -0.0438 -0.97 -0.0837	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020 0.3575 0.6852	IN.= .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0039 -0.0187 -0.0065 -0.0071 -0.0013	CY 0.1223 0.1240 0.0783 0.0660 -0.0147 0.1339 0.0128 0.0201 -0.0383	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.008 0.0022 0.0030 0.0037	CAT 0.2257 0.2253 0.2219 0.2201 0.2201 0.2170 0.2170 0.2125	POJ/P 01303 CPB 0.0503 0.0504 0.0503 0.0502 0.0500 0.0498 0.0498 0.0498	CAF C.1754 C.1754 C.1716 C.1718 C.1705 C.1672 C.1712	RUN 402. 402. 402. 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0462 0.54 0.0408 0.03 -0.0006 -0.48 -0.0438 -0.97 -0.0837 -1.48 -0.1303	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020 0.3575 0.6852 1.0700	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133 -0.0039 -0.0187 -0.0065 -0.0071 -0.0013 -0.0026	CY 0.1223 0.1240 0.0783 0.0660 -0.0147 0.1339 0.0128 0.0201 -0.0383 -0.0250	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.0088 0.0022 0.0030 0.0037 0.0019	CAT 0.2257 0.2253 0.2219 0.2220 0.2201 0.2203 0.2170 0.2125 0.2210 0.2209	POJ/P 01303 CPB 0.0503 0.0504 0.0502 0.0500 0.0498 0.0498 0.0498 0.0498	CAF C.1754 C.1754 C.1716 C.1716 C.1705 C.1672 C.1712	RUN 402. 402. 402. 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0462 0.54 0.0408 0.03 -0.0006 -0.48 -0.0438 -0.97 -0.0837 -1.48 -0.1303	RE PER HG PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020 0.3575 0.6852 1.0700	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133 -0.0039 -0.0187 -0.0065 -0.0071 -0.0013 -0.0026	CY 0.1223 0.1240 0.0783 0.0660 -0.0147 0.1339 0.0128 0.0201 -0.0383 -0.0250 -0.0158	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.0082 0.0022 0.0030 0.0037 0.0019 0.0020	CAT 0.2257 0.2253 0.2219 0.2220 0.2201 0.2203 0.2170 0.2125 0.2210 0.2209 0.2193	POJ/P 01303 CPB 0.0503 0.0504 0.0503 0.0502 0.0500 0.0498 0.0498 0.0498 0.0497	TS = 69140 CAF 0.1754 0.1716 0.1701 0.1705 0.1627 0.1627 0.1712 0.1696	RUN 402. 402. 402. 402. 402. 402. 402. 402.
Q= 3.77 PSI PO= \$00.0 CM ALPHA CN 4.69 0.3704 3.09 0.2753 2.07 0.1803 1.55 0.1282 1.64 0.0862 0.54 0.0408 0.03 -0.0006 -0.48 -0.0438 -0.97 -0.0837	RE PER ING PTS= CN -3.1012 -2.2909 -1.4925 -1.0616 -0.7157 -0.3384 -0.0020 0.3575 0.6852 1.0700 1.4224 2.1910	IN = .488 .2659 PS CS -0.0180 -0.0187 -0.0135 -0.0133 -0.0039 -0.0187 -0.0065 -0.0071 -0.0013 -0.0026	CY 0.1223 0.1240 0.0783 0.0660 -0.0147 0.1339 0.0128 0.0201 -0.0383 -0.0250	90. DE CR 0.0035 0.0043 0.0026 0.0027 0.008 0.0022 0.0037 0.0037 0.0019 0.0020 0.0028	CAT 0-2257 0-2253 0-2219 0-2201 0-2203 0-2170 0-2125 0-2219 0-2209 0-2209	POJ/P 013030 CPB 0.0503 0.0504 0.0503 0.0502 0.0500 0.0498 0.0498 0.0498 0.0497 0.0497	CAF 0.1754 0.1716 0.1718 0.1701 0.1705 0.1627 0.1712 0.1712 0.1712	RUN 402. 402. 402. 402. 402. 402. 402. 402.

3 M ,	DEL 946.2	CON	F.G. 2.000	H	ACH 450		PHI =	75.	
ð:	5.77 PSI	RE PER	IN.= .48E0	6 ∙70≖	90. DE	G.F	POJ/P	rs =	40.
PO	= 400.0 C	HG PTS=	.2659 PSI			RUN NO.	01303	69141	
ALPHA	CN CN	CM	CS ·	EY	CR	CAT	€₽В	CAF	RUN
4.09	0.3674	-3.0818	-0.0336	-0.2416	0.0061	0.2249	0.0504	0.1745	403.
3.09			-0.0280		0.0069				
2.07	0.1758	-1.4601	-0.0257		0.0051				
1.55	0.1254	-1.0416	-0:0269	0.1714	0.0045	0.2210	0.0501	0.1708	403.
1.06	0.0841	-0.7016	-0.0228		G. 0015				
0.53	0.0381	-0.3244	-0.0241	0.1472	0.0047	0.2222	0.0498	0.1725	403.
0.03	-0.0040	0.0224	-0.0206		0.0048				
	3 -0:0476	0.3824	-0.0197		·0.0037				
-0.99	-0.0927	0.7580	-0.0184		0.0044				
	0.1363		-0.0204		0.0051				
	-0-1784		-0.0169		0.0040				
	-0.2689		-0.0128		0.0041				
-4.00	-0.3703	3.0889	-0-0074	0.0019	0.0042	0.2204	.0.0504	0.1700	403.
• • • • • • • • • • • • • • • • • • • •	DEL 946.2	•	FIG. 2.000		ACH 4.50		PHI =	75.	
• • • • • • • • • • • • • • • • • • • •	DEL 946.2 3.77 PSI	•	FIG. 2.000 IN.= .48E0		90. DE			75. TS = 1	.00•
Q=	: 3.77 PSI	RE PER	-		90. DE	G.F		rs = 1	00.
Q=	= 3.77 PSI == 400.0 CF	RE PER	IN.= .48E0		90. DE	G.F	P0J/P	rs = 1	00• RUN
Q= PC	= 3.77 PSI D= 400.0 CM	RE PER IHG PTS=	IN.= .48E0	S T0=	90. DE	G.F RUN NO.	POJ/P 013030 CPB	TS = 1 69142 CAF	RUN
Q= PC	: 3.77 PSI)≈ 400.0 CM CN 3 0.3527	RE PER IHG PTS= CM -2.9579	IN.= .48E0 .2659 PSI CS	CY 0.5228	90. DE	G.F RUN NO. CAT 0.2426	POJ/P 013030 CPB 0.0503	TS = 1 69142 CAF 0.1923	RUN 404.
Q= PC ALPHA 4.08	= 3.77 PSI ⇒ 400.0 CM CN 3 0.3527 0.2581	RE PER HG PTS= CM -2.9579 -2.1560	.2659 PSI CS -0.0706	CY 0.5228 0.4558	90. DE	G.F RUN NO. CAT 0.2426 0.2287	POJ/P 013030 CPB 0.0503 0.0503	TS = 1 69142 CAF 0.1923 0.1785	RUN 404. 404.
Q= PC ALPHA 4.08 3.09	= 3.77 PSI = 400.0 CM CN 3 0.3527 0 0.2581 7 0.1656	RE PER HG PTS= CM -2.9579 -2.1560	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607	CY 0.5228 0.4558 0.4197	90. DE	G.F RUN NO. CAT 0.2426 0.2287 0.2285	POJ/P 013030 CPB 0.0503 0.0503 0.0503	TS = 1 69142 CAF 0.1923 0.1785 0.1782	RUN 404. 404. 404.
Q= PC ALPHA 4.08 3.09 2.07 1.55	2 3.77 PSI 2 400.0 CM CN 3 0.3527 0 0.2581 7 0.1656	RE PER HG PTS= CM -2.9579 -2.1560 -1.3861	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739	CY 0.5228 0.4558 0.4197 0.5551	90. DE	G.F RUN NO. CAT 0.2426 0.2287 0.2285	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497	TS = 1 69142 CAF 0.1923 0.1785 0.1782 0.1790	RUN 404. 404. 404.
Q= PC ALPHA 4.08 3.09 2.07 1.55	= 3.77 PSI == 400.0 CM CN 3 0.3527 0 0.2581 7 0.1656 6 0.1077 0 0.0682	RE PER HG PTS= CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5771	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083	90. DE	G.F RUN NO. CAT 0.2426 0.2287 0.2285 0.2286 0.2223 0.2149	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0497 0.0496	TS = 1 69142 CAF 0.1923 0.1785 0.1782 0.1790 0.1727 0.1653	RUN 404. 404. 404. 404. 404.
Q= PO ALPHA 4.08 3.09 2.07 1.55 1.64 0.53	= 3.77 PSI = 400.0 CM CN 3 0.3527 0.2581 7 0.1656 6 0.1077 0.0682 0.0238 3 -0.0202	RE PER HG PTS= CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5771 -0.2111 0.1555	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739 -0.0577 -0.0595 -0.0660	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083 0.47200	90. DE	G.F RUN NO. CAT 0.2426 0.2287 0.2285 0.2286 0.2223 0.2149 0.2208	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0496 0.0496	TS = 1 69142 CAF 0.1923 0.1782 0.1782 0.1790 0.1797 0.1653 0.1712	RUN 404. 404. 404. 404. 404.
Q= P0 ALPHA 4.08 3.09 2.07 1.55 1.04 0.53 0.03 -0.47	= 3.77 PSI = 400.0 CM CN 0.3527 0.2581 0.1656 0.1077 0.0682 0.0238 0.0238 0.0202 0.0623	RE PER HG PTS= CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5771 -0.2111 0.1555 0.5030	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739 -0.0577 -0.0595 -0.0660 -0.0595	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083 0.47200	90. DE	G.F RUN NO. CAT 0.2426 0.2285 0.2285 0.2286 0.2223 0.2149 0.2208 0.2220	POJ/P 013030 CPB 0.0503 0.0503 0.0593 0.0497 0.0496 0.0496 0.0496	TS = 1 69142 CAF 0.1923 0.1782 0.1782 0.1790 0.1727 0.1653 0.1712	RUN 404. 404. 404. 404. 404. 404.
Q= P0 ALPHA 4.08 3.09 2.07 1.55 1.04 0.53 0.03 -0.47 -0.99	= 3.77 PSI = 400.0 CM CN 3 0.3527 0.2581 7 0.1656 6 0.1077 0.0682 6 0.0238 6 0.0238 6 0.0202 7 0.0623 7 0.0623	RE PER CH -2.9579 -2.1560 -1.3861 -0.8933 -0.5771 -0.2111 0.1555 0.5030 0.8707	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739 -0.0577 -0.0595 -0.0660 -0.0595 -0.0554	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083 0.47200 0.4042 0.3679	90. DE CR 0.0043 0.0032 0.0034 0.0014 0.0016 0.0017 0.0001 0.0032	G.F RUN NO. CAT 0.2426 0.2285 0.2285 0.2286 0.2223 0.2149 0.2208 0.2220 0.2333	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0497 0.0496 0.0497	CAF 0.1923 0.1782 0.1782 0.1790 0.1727 0.1653 0.1712 0.1723	RUN 404. 404. 404. 404. 404. 404. 404.
Q= P0 ALPHA 4.08 3.09 2.07 1.55 1.04 0.53 -0.47 -0.99 -1.49	= 3.77 PSI = 400.0 CM CN CN 3 0.3527 0.2581 7 0.1656 6 0.1077 0.0682 9 0.0238 9 -0.0202 7 -0.0623 9 -0.1067 9 -0.1518	RE PER CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5711 0.1555 0.5030 0.8707 1.2435	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0577 -0.0595 -0.0660 -0.0595 +0.0554 -0.0570	CY 0.5228 0.4558 0.4197 0.5551 0.3958 0.4720 0.4042 0.3679 0.3836	90. DE CR 0.0043 0.0032 0.0034 0.0014 0.0017 0.0001 0.0032 0.0039 0.0039	G.F RUN NO. CAT 0.2426 0.2287 0.2285 0.2283 0.2149 0.2208 0.2220 0.2233 0.2158	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0497 0.0496 0.0497 0.0497 0.0497	CAF 0.1923 0.1782 0.1782 0.1790 0.1727 0.1653 0.1712 0.1723 0.1736	RUN 404. 404. 404. 404. 404. 404. 404. 404.
9- P0 ALPHA 4.08 3.09 2.07 1.55 1.64 0.53 0.03 -0.47 -1.49	2 3.77 PSI 2 400.0 CM CN 3 0.3527 0 0.2581 7 0.1656 6 0.1077 9 0.0682 9 0.0238 8 -0.0202 7 -0.0623 9 -0.1067 9 0.1518 9 -0.1920	RE PER CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5771 -0.2111 0.1555 0.5030 0.8707 1.2435 1.5750	IN-= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0739 -0.0577 -0.0595 -0.0660 -0.0595 -0.0554 -0.0570 -0.0496	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083 0.4720 0.4042 0.3679 0.3836 0.3120	90. DE	G.F RUN NO. CAT 0.2426 0.2287 0.2286 0.2223 0.2149 0.2230 0.2233 0.2158 0.2158	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0497 0.0496 0.0497 0.0496 0.0496	CAF 0.1923 0.1785 0.1782 0.1790 0.1727 0.1653 0.1712 0.1736 0.1662	RUN 404. 404. 404. 404. 404. 404. 404. 404
9- P0 ALPHA 4.08 3.09 2.07 1.55 1.04 0.53 0.03 -0.47 -1.49 -1.49	= 3.77 PSI = 400.0 CM CN CN 3 0.3527 0.2581 7 0.1656 6 0.1077 0.0682 9 0.0238 9 -0.0202 7 -0.0623 9 -0.1067 9 -0.1518	RE PER HG PTS= CM -2.9579 -2.1560 -1.3861 -0.8933 -0.5771 -0.2111 0.1555 0.5030 0.8707 1.2435 1.5750 2.3541	IN.= .48E00 .2659 PSI CS -0.0706 -0.0638 -0.0607 -0.0577 -0.0595 -0.0660 -0.0595 +0.0554 -0.0570	CY 0.5228 0.4558 0.4197 0.5551 0.3904 0.4083 0.4720 0.4042 0.3679 0.3836 0.3120 0.3034	90. DE CR 0.0043 0.0032 0.0034 0.0014 0.0017 0.0001 0.0032 0.0039 0.0039	CAT 0.2426 0.2287 0.2285 0.2286 0.2223 0.2149 0.2233 0.2158 0.2158 0.22199	POJ/P 013030 CPB 0.0503 0.0503 0.0503 0.0497 0.0497 0.0496 0.0496 0.0496 0.0496	CAF 0.1923 0.1785 0.1782 0.1790 0.1727 0.1653 0.1712 0.1736 0.1662 0.1703 0.1711	RUN 404. 404. 404. 404. 404. 404. 404. 404

MODEL 946.2	CONFI	G 2-000	. Na	IČH 4.50)	PHI =	90.	
Q= 3.77 PSI	RE PER E	N-≐ -48E0	6 TO=	90. DE	EG.F	POJ/P	rs =	•
PO= 400.0 CI	HHG PTS=	.2659 PSI			RUN NO.	01303	59143	
ALPHA CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
3.86 0.3629	-3.0300 -	0.0069	0.0496	0.0042	0.2416	0.0503	0.1914	405.
2.87 0.2701	-2.2425 -	0.0076		0.0031				405.
1.85 0.1749	-1.4425 -	8300.0	0.0515	0.0018	0.2392	0.0503	0.1889	405.
1.34 0.1241	-1.0201 -	0.0058	0.0407-	-0.0007	0.2372	0.0502	0.1871	405.
0.83 0.0804	-0.6581 -	0.0161		-0.0007				405.
0.32 0.0366	-0.2998 -			0.0025				405.
-0.18 -0.2057	0.0482 -			0.0032				405.
-0.70 -0.0487	0.4016 -	–		0.0020				405.
-1.22 -0.1945	1.5816 -		46.3345					405.
-1.70 -0.1355	1-1199 -			0.0034				405.
-2.20 -0.1785	1.4783 -		0.0888					405.
-3.21 -0.2720	2.2631 -		0.0137					405.
-4.22 -0.3678	3.0762	0.0069	-0.0677	0.0017	0.2383	0.0502	0.1887	405.
MODEL 946.2 Q= 3.77 PSI	CONFI RE PER I	G. 2.000		90. DE		PHI =	90• (IS = _1(D.
	RE PER 1	_)6 TO=		G•F		rs = _`1(D
Q= 3.77 PSI	RE PER 1	N.= .48E0)6 TO=		G•F	POJ/P	rs = _`1(D RUN
Q= 3.77 PSI PO= 400.0 CI	RE PER 1	N.= .48E0 .2659 PSI	06 T0=	90. DE	EG.F RUN NO. CAT	POJ/P1 013030 CPB	rs = 10 59144.	
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER 1 MHG PTS= CM	N.= .48E0 .2659 PSI CS 0.0112	06 T0= CY 0.0683	90. DE	RUN NO. CAT 0.2375	POJ/P1 013030 CPB 0.0503	rs = 10 59144. CAF 0-1871	RUN 406:
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 3.87 0.3658	RE PER 1 MHG PTS= CM -3.0599 -	N.= .48E0 .2659 PSI CS 0.0112	06 T0= CY 9.0683 0.0778	90. DE CR 0.0037	EG.F RUN NO. CAT 0.2375 0.2377	POJ/P 013030 CPB 0.0503 0.0504	TS = 10 59144 CAF 0.1871 0.1873	RUN
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 3.87 0.3658 2.87 0.2692	RE PER I MHG PTS= CM -3.0599 - -2.2341 -	0.0112 0.0120 0.0285	06 T0= CY 0.0683 0.0778 0.1769-	90. DE CR 0.0037 0.0025	EG.F RUN NO. CAT 0.2375 0.2377 2.4902-	POJ/P1 013030 CPB 0.0503 0.0504 -0.1318	TS = 1(59144. CAF 0.1871 0.1873 2.6219	RUN 406: 406:
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735	RE PER I MHG PTS= CM -3.0599 - -2.2341 - -1.4136 -	0.0112 0.0120 0.0285	06 T0= CY 0.0683 0.0778 0.1769-	90. DE CR 0.0037 0.0025 0.0096 0.0019	CAT 0.2375 0.2377 2.4902- 0.2344	POJ/P1 013030 CPB 0.0503 0.0504 -0.1318 0.0502	TS = 10 59144 CAF 0.1871 0.1873 2.6219 0.1842	RUN 406: 406: 406:
Q= 3.77 PSI PO= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364	RE PER 1 MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 -	0.0112 0.0120 0.0285 0.0044 0.0032	06 T0= CY 9.0683 0.0778 0.1767- 0.0080 -0.0017 0.0431	90. DE CR 0.0037 0.0025 0.0096 0.0019 0.0019	CAT 0.2375 0.2377 2.4902- 0.2344 0.2338 0.2349	POJ/P 013030 CP8 0.0503 0.0504 0.1318 0.0502 0.0500 0.0498	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851	RUN 406. 406. 406. 406. 406.
Q= 3.77 PSI P0= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066	RE PER 1 MHG PTS= CM -3.0599 - -2.2341 - -1.4136 - -1.0195 - -0.6561 -	0.0112 0.0120 0.0285 0.0044 0.0032	06 T0= CY 0.0683 0.0778 0.1769- 0.0007 0.0017 0.0431 0.1186	90. DE CR 0.0037 0.0025 0.0019 0.0019 0.0020 0.0020	CAT 0.2375 0.2377 2.4902- 0.2344 0.2348 0.2349 0.2346	POJ/P 013030 CP8 0.0503 0.0504 0.1318 0.0502 0.0500 0.0498 0.0497	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848	RUN 406. 406. 406. 406. 406. 406.
Q= 3.77 PSI P0= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066 -0.20 -0.0487	RE PER 1 MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 - 0.0554 - 0.4030 -	0.0112 0.0120 0.0285 0.0044 0.0032 0.0077 0.0152	06 T0= CY 0.0683 0.0778 0.1769- 0.0080 -0.0017 0.0431 0.1186 0.1120	90. DE CR 0.0037 0.0025 0.0096 0.0019 0.0019 0.0020 0.0007	CAT 0.2375 0.2377 2.4902- 0.2344 0.2348 0.2349 0.2348	POJ/P 013030 CP8 0.0503 0.0504 0.1318 0.0502 0.0500 0.0498 0.0497	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848 0.1801	RUN 406. 406. 406. 406. 406. 406. 406.
Q= 3.77 PSI P0= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066 -0.20 -0.0487 -1.20 -0.0933	RE PER 1 MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 - 0.0554 - 0.4030 - 0.7711 -	0.0112 0.0120 0.0285 0.0044 0.0032 0.0077 0.0152 0.0140	06 T0= CY 0.0683 0.0778 0.1769- 0.0007 0.0431 0.1186 0.1120 0.1141-	90. DE CR 0.0037 0.0025 0.0019 0.0019 0.0019 0.0020 0.0007 0.0002	CAT 0.2375 0.2377 2.4902- 0.2346 0.2348 0.2349 0.2346 0.2398	POJ/P 013030 CPB 0.0503 0.0504 -0.1318 0.0502 0.0500 0.0498 0.0497 0.0497	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848 0.1801 0.1897	RUN 406. 406. 406. 406. 406. 406. 406. 406.
Q= 3.77 PSI P0= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066 -0.20 -0.0487 -1.20 -0.0933 -1.71 -0.1378	RE PER 1 MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 - 0.0554 - 0.4030 - 0.7711 - 1.1397 -	0.0112 0.0112 0.0120 0.0285 0.0044 0.0032 0.0077 0.0152 0.0140 0.0143	0.0683 0.0778 0.1767- 0.0080 -0.0017 0.0431 0.1186 0.1120 0.1141- 0.0469	90. DE CR 0.0037 0.0025 0.0096 0.0019 0.0029 0.0007 0.0007 0.0002	CAT 0.2375 0.2377 2.4902- 0.2344 0.2338 0.2349 0.2349 0.2349 0.2398	POJ/P ³	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848 0.1801 0.1897	RUN 406: 406: 406: 406: 406: 406: 406: 406:
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066 -0.20 -0.0487 -1.20 -0.0933 -1.71 -0.1378 -2.20 -0.1784	RE PER I MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 - 0.0554 - 0.4030 - 0.7711 - 1.1397 - 1.4773 -	0.0112 0.0112 0.0120 0.0285 0.0044 0.0032 0.0077 0.0152 0.0140 0.0143 0.0074 0.0019	06 T0= CY 0.0683 0.0778 0.1767- 0.0080 -0.0017 0.0431 0.1186 0.1120 0.1141- 0.0469 -0.0065	90. DE CR 0.0037 0.0025 0.0096 0.0019 0.0002 0.0007 0.0002 0.0003 0.0003	CAT 0.2375 0.2377 2.4902- 0.2344 0.2338 9.2349 0.2346 0.2394 0.2343 0.2366	POJ/P ³ O13036 CPB 0.0503 0.0504 0.1318 0.0502 0.0500 0.0498 0.0497 0.0497 0.0497	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848 0.1801 0.1897 0.1846 0.1868	RUN 406: 406: 406: 406: 406: 406: 406: 406:
Q= 3.77 PSI P0= 400.0 CF ALPHA CN 3.87 0.3658 2.87 0.2692 -0.02 0.1735 1.34 0.1240 0.83 0.0802 0.32 0.0364 -0.19 -0.0066 -0.20 -0.0487 -1.20 -0.0933 -1.71 -0.1378	RE PER 1 MHG PTS= CM -3.05992.23411.41361.01950.65610.2979 - 0.0554 - 0.4030 - 0.7711 - 1.1397 -	0.0112 0.0120 0.0285 0.0044 0.0032 0.0077 0.0152 0.0140 0.0143 0.0074 0.0019	06 T0= CY 0.0683 0.0778 0.1767- 0.0080 -0.0017 0.0431 0.1186 0.1120 0.1141- 0.0469 -0.0065	90. DE CR 0.0037 0.0025 0.0019 0.0019 0.0020 0.0007 0.0002 0.0004 0.0003 0.0010 0.0011	CAT 0.2375 0.2377 2.4902- 0.2344 0.2338 9.2349 0.2346 0.2298 0.2343 0.2366 0.2340	POJ/P 013030 CPB 0.0503 0.0504 0.1318 0.0502 0.0500 0.0498 0.0497 0.0497 0.0497 0.0497 0.0498 0.0499	CAF 0.1871 0.1873 2.6219 0.1842 0.1838 0.1851 0.1848 0.1801 0.1846 0.1868 0.1868	RUN 406: 406: 406: 406: 406: 406: 406: 406:

	100	EL 94	46.2		CONF	IG.	2.000	0	Mi	ACH 4.5	0	FHI =	90.		
C)= :	3.77	PSI	RE	PER	1N.=	.48E	06	T0=	90. D	EG.F	-PQJ/P	TS =	20.	÷
	• <u>0</u> =	400	.O CĤ	HG F	rs=	-26	59 PS	Į.			RUN NO	. 01303	69145		
ALPH	ĮĄ.	CI	4	C,	4	C	s	-GY	ı	CR	CAT	CPB	CAF	•	~ RUN
3.8	37	0.3	66 4	-3.0	647	-0.0	171	0.1	064	0.0038	0.2378	·00503	0.187	5	407.
2.8	37	0.2	713	-2.2	2521	-0.0	164				0.2365				407 -
1.8	-	0.1		-1.4	504	-0.0	156				0.2324				407.
1.3		0.13	246	_	-	-0.0					0.2318				407.
0.8	13	0.0	808			-0.0					0.2268				407.
0.3	_	0.0				-0.0					0.2293				407.
	_	-0.0				-0.0					0.2170				407.
		-0.04				-0.0					0.2282				407.
		-0.0				-0.0					0.2306				407.
		-0-1				-0.0					0.2287				407.
		-0 • 3.				-0.0					0.2310				407.
		0.7				0.0					0.0093				407.
	-	-0.1	770	1 - 4	677	-0.00	77				0.2310				4C7.
		-0-2	722	2.2	2678	-0.0	979				0.2298				407.
-4.2	22 .	-03	712	3.1	100	-0.0	005	-0.0	298	0.0012	0.2299	0.0502	0.179	6	407.
	-	EL 94			CONF	16•	2.000			ACH 4.5		PHL =	90.		
()= :	3.77	PSI	RE	PER	IN.≃	.48E€	06	T0=	90. D	EG.F	POJ/P	TS. =	40.	
F	•0=	400	.O CM	HG F	PTS=	. 26	59 PS	Ī			RUN NO	01303	89146		
ALPH	iA	C	4	CH	1	C	S	CY	•	CR	CAT	CPB	CAF		RUN
3.8	37	0.3	561	-3.0	0640	-0.03	316	0.2	128	0.0063	0.2428	0.0503	0.192	5	408.
2.8		0.2				-0.0					0:2356				408 •
1.8		0.1		-1.4	632	-0.0	273	0.1	725	0.0040	0-2359	0.0503	0.185	6	.604
1.3		0.1	243	-1.1	237	-0.Ö	247	0.1	517	0.0020	0-2294	0.0501	0.179	4	408.
-0.1	8	0.0	806	-0.6	6644	-0.0	229	0.1	402	0.0032	0.0017	0.0705	-0.068	8	408.
0.3		0.0				-0.0					0.2314				408.
_	_	-0.0				-0.0					0.2366				408.
_		-0.0				-0.0					0.2306				408.
		-0.0				-0.0					0.2330				408.
		-0.1				-0.0					0.2306				408.
	_	-0.1				-0.0	-				0.2344				408.
		-0 -2				-0.0	-				0.2304				408.
		-3.4				-0.0					0.1885				408.

HODEL 946.2	CONFIG.	2.000 M	ACH 4.50	PHI = 90.	
Q= 3.77 PSI	RE PER IN.	48E06 TO=	90. DEG.F	POJ/PTS = 100.	
PO= 400.0 C	HG PTS= .2	659 PSI	RUN NO	. 0130369147	
ALPHA CN	СМ	CS CY	CR CAT	CPB CAF	RUN
3.87 0.3653	-3.0543 -0.	0665 0.4668	0.0053 0.2413	0-0502 0-1911	409.
2.87 0.2701	-2.2424 -0.			0.0503 0.1898	409.
1.85 G.1757	~1.4506 -0.		0.0029 0.2390		409
1.33 0.1233	-1.0152 -9.		0.0028 0.2341		409.
0.83 0.0812	-0.6577 -0.		6.0010 D.2437		409.
0.32 0.0374	-0.3078 -0.		0.0036 0.2359		409.
-0.19 <0.0072	0.0619 -0.		0.0035 0.2383		409.
-0.69 -0.0483	0.4036 5.		0.0259 0.1349		409.
-1.20 -0.0954	0.7927 -0.	0625 0.4284	0.0025 0.2387	0-0496 C-1891	409.
-1.70 -0.1392	1.1560 -0.		0.0013 9.2381		409.
-2.21 -0.1805	1.4973 -0.		0.0032 0.2376		409.
-3.21 -0.2749	2.2894 -0.		0.0020 0.2393		409.
-4-22 -0.3739	3.1315 -0.		0.0020 0.2379		409.
MODEL 946.2	CONFIG.	2.450 H	ACH -4.50	PHI = .	
Q= 3.77 PSI	RE PER IN.	= .48E06 TO=	90. DEG.F	POJ/PTS = .	
PQ= 400.0 C	HG PTS= .2	659 PSI	RUN NO	. 0140369103	
ALPHA CN	CH	CS CY	CR CAT	CPB CAF	RUN
3.98 0.3594	-2.9929 -0.	0162 0-1259	0.0021 0.2204	0.0515 0.1689	410.
2.98 0.2655	-2.1998 -0.		0.0022 0.2186		410.
1.96 0.1731	-1.4261 -0.		0.0024 0.2170		410.
1.45 0.1254	-1.0410 -0.		0.0032 0.2127		410.
0.94 0.0763	-0.6213 -0.		0.0020 0.2170		410.
0.43 0.0358	-0.2979 -0.		0.0015 0.2154		410.
-0.07 -0.0047	0.0380 -0.		0.0016 0.2152		410.
-0.57 -0.0466	0.3817 -0.		0.0017 0.2164		410.
-1.09 -0.0957	0.7985 -0.		0.0012 0.2164		410.
	1.0957 -0.		0.0020 0.2132		410.
-2.09 -0.1709	1.4019 -0.		0.0015 0.2158		410
-3.11 -0.2619	2.1594 -0.		0.0017 0.2157		410.
-4-11 -0-3557	2.9515 -0.		0-0025 0-2154		410-

	HOD	DEL 946.2	CON	FIG.	2.450	M	ACH 4.5	D	PHI =	•	
	Q=	3.77 PS1	RE PER	IN.=	-48E06	5 TO=	90. D	EG.F	POJ/P	TS =	10.
	PO:	= 400.0 CM	HG :PTS≠	• 26	59 PSI			RUN NO	. 01403	6 9 104	
ALP	HA	CN	CM	C	s	CY	CR	CAT	CP8	CAF	RUN
3.	98	0.3506	-2.9320	-0.0	144	0.1131	9-0015	0.2267	0.0500	0.176	7 411.
2.	98	0.2596	-2.1650	-0.0	108	0.0844	0-0022	0.2234	0-0511	0.172	2. 411.
1.	96	0.1700	-1.4217	-0.0	134	0.1054	0.0006	0.2217	0.0509	0.170	8 411.
1.	45	0.1166	-0.9739	-0.0	ilo	0.0859	0.0013	0.2204	0.0507	0.169	7 411.
0.	94	0.0704	-0.5867	-0.0	127	G.0980	0.0002	0.2218	0.0505	0-171	
0.	43	0.0285	-0.2490	-0.0	144	0.1134	0.0022	0.2217	0.0504	0.171	3 411.
		-0.0077	0.0496	-0.0	130	0.1004	0.0010	0.2183	0.0503	0.168	
-0.	59	-0.0582	0.4711	-0.0	162			ù-2199			
-1.	C9	-0.0944	0.7603	-0.0	148			0.2181			
-1.	59	-0.1291	1:0312	-0.0	150	0-1151	0-0021	ชิง2148	0-0499	0.164	
-2.	09	-0.1725	1.3933	-0.0	174			0.2190			
-3.	10	-0.2606	2:1276	-0.0				0.2172			
		-0.3573	2.9458	-0.0	187	0.1477	0.0019	0.2186	0.0501	0.168	5 411.
	ĤOD	DEL 946.2	CONF	=iĢ∙	2.450	H.	ACH 4.50	0	PHL =	· •	
		JEL 946.2	CONI RE PER	•	-		ACH 4.50		PHL =		20.
	Q=		RE PER	IN.=	-48E06			EG.F	_	rs =	20.
	Q= P0=	3.77 PSI	RE PER	IN.=	-48E06	. TO=		EG.F	POJ/P	rs =	20 . Run
ALP	Q= P0= HA	3.77 PSI = 400.0 CM	RE PER	. 26	.48E06 59 PSI	T0=	90. 'DI	EG.F RUN NÖ	POJ/P - 01403 CPB	TS = 69105 CAF	RUN
ALP	Q= P0= HA	3.77 PSI = 400.0 CM CN 0.3447	RE PER HG :PTS= CM	IN.= .26 C:	.48E06 59 PSI S	CY 0.0980	90. 'DI	EG.F RUN NO. CAT 0.2270	POJ/P - 01403 CPB	TS = 69105 CAF 0.1761	RUN L 412.
ALP 3. 2.	Q= PO= HA 97 97	3.77 PSI = 400.0 CM CN 0.3447 0.2523	RE PER HG :PTS= CM -2.8940 -2.1192	IN.= .26 C: -0.0 -0.0	_48E06 59 PSI S 127 114	CY 0.0980 0.0878	90. DI CR 0.0015 0.004	EG.F RUN NO. CAT 0.2270 2252	POJ/P . 014036 CPB 0.0510 0.0511	TS = 69105 CAF 0.1761 0.1741	RUN L 412. L 412.
ALP 3. 2.	Q= P0= HA 97	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470	RE PER HG :PTS= CM -2.8940	IN.= .26 C: -0.0 -0.0	_48E06 59 PSI S 127 114 100	CY 0.0980 0.0878 0.0745	90. DE CR C.0015 0.004 0.0024	EG.F RUN NO. CAT 0.2270 2252 0.2223	POJ/P . 01403 CPB 0.0510 0.0511 0.0509	TS = 69105 CAF 0.1761 0.1741	RUN L 412. L 412. 4 412.
ALP 3. 2. 1.	Q= PO= HA 97 97 97	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135	RE PER HG :PTS= CM -2.8940 -2.1192 -1.2136 -0.9707	IN.= .26	.48E06 59 PSI S 127 114 100	CY 0.0980 0.0878 0.0745 0.0642	90. DE CR G.0015 0.002 0.0024 0.0014	CAT 0.2270 2252 0.2236	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0506	TS = 69105 CAF 0.1761 0.1741 0.1714	RUN L 412. L 412. 4 412.
3. 2. 1.	Q= PO= HA 97 97 94 93	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716	RE PER HG :PTS= CM -2.8940 -2.1192 -1.2136 -0.9707 -0.6236	IN.= -26 C: -0.0 -0.0 -0.0 -0.0	-48E06 59 PSI S 127 114 100 093 102	CY 0.0980 0.0678 0.0745 0.0642 0.0747	90. DE CR G.0015 0.004 0.0014 0.002	CAT 0.2270 2252 0.2236 0.2236	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0506 0.0504	TS = 69105 CAF 0.1761 0.1741 0.1714 0.1730	RUN L 412. L 412. 4 412. D 412. L 412.
ALP 3. 2. 1. 0.	Q= PO= HA 97 97 97 44 93	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716 0.0283	RE PER HG PTS= CM -2.1192 -1.2136 -0.9707 -0.6236 -0.2689	IN.= -26 -0.0 -0.0 -0.0 -0.0 -0.0	-48E06 59 PSI 127 114 100 093 102	CY 0.0980 0.0878 0.0745 0.0642 0.0747 0.0621	90. DE CR G.0015 0.004 0.0024 0.0014 0.0002 0.0010	CAT 0.2270 2252 0.2223 0.2236 0.2205	POJ/P . 01403 CP8 0.0510 0.0511 0.0509 0.0504 0.0504 0.0503	TS = 69105 CAF 0.1761 0.1741 0.1730 0.1700	RUN L 412. L 412. L 412. O 412. L 412. O 412.
ALP 3. 2. 1. 0. 0.	Q= PO= HA 97 97 97 44 93 42 08	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716	RE PER HG PTS= CM -2.8940 -2.1192 -1.2136 -0.9707 -0.6236 -0.2689 0.1247	IN.=	-48E06 59 PST S 127 114 110 093 102 088	CY 0.0980 0.0878 0.0745 0.0642 0.0747 0.0621 0.0574	90. DE CR	CAT 0.2270 2252 0.2233 0.2236 0.2205 0.2204 0.2187	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0506 0.0504 0.0503 0.0502	TS = 69105 CAF 0.1761 0.1714 0.1717 0.1730 0.1700 0.1689	RUN 412. 412. 412. 412. 412. 412. 412. 412.
ALP 3.2.1.0.0.0.	Q= P0= HA 97 97 97 44 93 42 08 58	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716 0.0283 -0.0179 -0.0564	RE PER HG PTS= CM -2.1192 -1.2136 -0.9707 -0.6236 -0.2689	IN.= -26 -0.9 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	.48E06 59 PSI 127 114 100 1093 102 108 108 108 108 108 108	CY 0.0980 0.0878 0.0745 0.0642 0.0747 0.0621 0.0574 0.0517	90. DE CR G.0015 0.0024 0.0014 0.0002 0.0010 0.0010 0.0010 0.0011	CAT 0.2270 2252 0.2233 0.2205 0.2204 0.2187 0.2187	POJ/P . 01403 CPB 0.0510 0.0501 0.0506 0.0504 0.0503 0.0502 0.0502	TS = 69105 CAF 0.1761 0.1714 0.1736 0.1700 0.1689	RUN 412. 412. 412. 412. 412. 412. 412. 412.
ALP 3.2.1.0.0.0.	Q= PO= HA 97 97 44 93 42 08 58	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716 0.0283 -0.0179 -0.0564 -0.0932	RE PER HG PTS= CM -2.8940 -2.1192 -1.2136 -0.9707 -0.6236 -0.2689 0.1247 0.4512 0.7232	IN.= -26 C0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -	.48E06 59 PSI 127 114 100 093 102 088 082 075	CY 0.0980 0.0878 0.0745 0.0642 0.0745 0.0517 0.0517	90. DE CR	CAT 0.2270 2252 0.2236 0.2295 0.2204 0.2187 0.2185 0.2168	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0506 0.0504 0.0503 0.0502 0.0502	TS = 69105 CAF 0.1761 0.1714 0.1730 0.1700 0.1689 0.1683	RUN 412. 412. 412. 412. 412. 412. 5412. 5412. 7412.
ALP 3.2.1.0.0.0.	Q= P0= HA 97 97 97 44 93 42 08 58	3.77 PSI = 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716 0.0283 -0.0179 -0.0564	RE PER HG PTS= CM -2.8940 -2.1192 -1.2136 -0.9707 -0.6236 -0.2689 0.1247 0.4512	IN.= -26 C0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -	-48E06 59 PST S 127 114 100 093 102 088 075 068	CY 0.0980 0.0878 0.0745 0.0642 0.0745 0.0517 0.0517 0.0442 0.0515	90. DE CR 0.0015 0.0024 0.0014 0.0010 0.0010 0.0010 0.0010 0.0019 0.0014	CAT 0.2270 2252 0.2233 0.2205 0.2204 0.2187 0.2187	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0504 0.0503 0.0502 0.0502 0.0501	TS = 69105 CAF 0.1761 0.1741 0.1730 0.1700 0.1689 0.1683	RUN 412. 412. 412. 412. 412. 412. 412. 412
ALP 3.2.1.0.0.001112.	Q= PO= HA 97 97 44 93 42 08 58 10 59	3.77 PSI 400.0 CM CN 0.3447 0.2523 0.1470 0.1135 0.0716 0.0283 -0.0179 -0.0564 -0.0932 -0.1423	RE PER HG PTS= CM -2.8940 -2.1192 -1.2136 -0.9707 -0.6236 -0.2689 0.1247 0.4512 0.7232 1.1399	IN.= -26 -0.9 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0 -0.0	-48E06 59 PST S 127 114 100 093 102 088 075 068	CY 0.0980 0.0878 0.0745 0.0642 0.0747 0.0621 0.0514 0.0515 0.0442 0.0515 0.0387	90. DE CR C. 0015 0.004 0.0024 0.0010 0.0010 0.0010 0.0019 0.0019 0.0014 0.0021	CAT 0.2270 2252 0.2223 0.2236 0.2205 0.2204 0.2187 0.2188 0.2168 0.2196	POJ/P . 01403 CPB 0.0510 0.0511 0.0509 0.0506 0.0504 0.0502 0.0502 0.0501 0.0501	TS = 69105 CAF 0.1761 0.1714 0.1730 0.1700 0.1683 0.1683 0.1683 0.1685 0.1685	RUN 412. 412. 412. 412. 412. 5412. 5412. 7412. 7412. 7412.

MODEL 946.2	CONF	IG. 2.450	M	ACH 4.50		PHI =	•	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 T0≖	90. DEG.	,F	POJ/PT	'S =	40.
PO= 400.0 CM	HG PTS=	.2659 951		RU	UN NO.	014036	9106	
ALPHA CN	CM	cs	CY	CA C	CAT	СРВ	CAF	RŲN
3.97 0.3287	-2.7784	-0.0130		0.0041 0.				
2.97 0.239?	-2.0270			0.0030 0.				
1.96 0.1498		-0.0097		0.0038 0.				
1.44 0.1005	-0.8825			0.0046 0.		_		
0.94 0.0629	-0.5791			0.0047 0.				
0.42 C.0195		-0.0084		0.0036 0.				
-0.08 -0.0181		-0.0086		0.0037-0.				
-0.60 -0.0643		-0.0102		0.0026 0.				
-1.09 -0.1106		-0.0072		0.0033 0.				
-1.59 -0.1525 -2.10 -0.2016		-0.0074		0.0046 0.				
-3.11 -0.2797	2.2492	-0.0083		0.0043 0.				
-4.12 -0.3721		-0.0064		0.0043 0.				
-4.12 -0.3721	3.0208	-0.0004	0.0410	0.0051 0.	•2230 L	/• U477	0.1122	413.
MODEL 946.2 Q= 3.77 PS1		FIG. 2.450 IN.= .48E0		ACH 4.50 90. DEG.		PHI =	• rs = 1	.00•
	RE PER	IN.= .48E0		90. DEG.		POJ/PI	rs = 1	.00•
Q= 3.77 PS1	RE PER	IN.= .48E0		90. DEG.	•F	POJ/PI	rs = 1	.00 . RUN
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN	RE PER IHG PTS=	IN.= .48E0	6 TO=	90. DEG. RU CR C	.F UN NO. CAT	POJ/P1 014036 CPB	S = 1 59107 CAF	RUN
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837	RE PER IHG PTS= CM -2.4253	.2659 PSI	6 TO= CY 0.0889	90. DEG.	.F UN NO. CAT .2338 (POJ/P1 014036 CPB	TS = 1 69107 CAF 0.1829	RUN 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN	RE PER HG PTS= CM -2.4253 -1.7032	IN.= .48E0 .2659 PSI CS -0.0114	6 TO= CY 0.0889 0.0731	90. DEG. RU CR C 0.0024 0. 0.0032 0.	.F UN NO. CAT .2338 0	POJ/P1 014036 CPB 0-0510	(S = 1 69107 CAF 0.1829	RUN 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971	RE PER HG PTS= CM -2.4253 -1.7032 -0.9913	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094	6 TO= CY 0.0889 0.0731 0.0796	90. DEG. RU CR C	.F UN NO. CAT .2338 (.2319 (POJ/PT 014036 CPB 0.0510 0.0510	(S = 1 69107 CAF 0.1829 0.1808 0.1794	RUN 414. 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103	RE PER HG PTS= CM -2.4253 -1.7032 -0.9913 -0.9767	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104	CY 0.0889 0.0731 0.0796 0.0733	90. DEG. RU CR C 0.0024 0. 0.0032 0. 0.0028 0.	.F UN NO. CAT .2338 0 .2319 0 .2301 0	POJ/PT 014036 CPB 0.0510 0.0510 0.0507	S = 1 69107 CAF 0.1829 0.1808 0.1794 0.1800	RUN 414. 414. 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497	RE PER IHG PTS= CM -2.4253 -1.7032 -0.913 -0.9767 -0.3120	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096	CY 0.0889 0.0731 0.0796 0.0733 0.0532	90. DEG. RU CR C 0.0024 0. 0.0032 0. 0.0028 0. 0.0029 0.	.F UN NO. .2338 (.2319 (.2301 (.2306 (POJ/PT 014036 CPB 0.0510 0.0510 0.0507 0.0506	S = 1 69107 CAF 0.1829 0.1808 0.1794 0.1800	RUN 414. 414. 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264	RE PER IHG PTS= CM -2.4253 -1.7032 -0.913 -0.9767 -0.3120 0.0925	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594	90. DEG. RU CR C 0.0024 0. 0.0032 0. 0.0028 0. 0.0029 0. 0.0036 0. 0.0031 0. 0.0019 0.	.F UN NO. .2338 0 .2319 0 .2301 0 .2306 0 .2284 0 .2298 0	POJ/PT 014036 CPB 0.0510 0.0510 0.0507 0.0506 0.0506 0.0505	S = 1 9107 CAF 0.1829 0.1808 0.1794 0.1798 0.1798	RUN 414. 414. 414. 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264 0.42 -0.0212	RE PER IHG PTS= CM -2.4253 -1.7032 -0.9913 -0.9767 -0.3120 0.0925 0.4809	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075 -0.0068	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594 0.0404	90. DEG. RU CR C 0.0024 0. 0.0032 0. 0.0028 0. 0.0029 0. 0.0036 0. 0.0031 0. 0.0019 0. 0.0033 0.	.F UN NO. .2338 0 .2319 0 .2306 0 .2306 0 .2284 0 .2298 0	POJ/PT 014036 CPB 0.0510 0.0510 0.0507 0.0506 0.0506 0.0506	S = 1 09107 CAF 0.1829 0.1808 0.1794 0.1798 0.1798 0.1798	RUN 414. 414. 414. 414. 414. 414.
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264 0.42 -0.0212 -0.09 -0.0675 -0.60 -0.1023 -1.10 -0.1442	RE PER IHG PTS= CM -2.4253 -1.7032 -0.9767 -0.9120 0.0925 0.4809 0.7466 1.0904	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075 -0.0068 -0.0085 -0.0063 -0.0064	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594 0.0404 0.0411	90. DEG. RU CR	.F UN NO. 2338 0 .2319 0 .2301 0 .2306 0 .2284 0 .2298 0 .2297 0	POJ/PT 014036 CPB 0.0510 0.0507 0.0506 0.0506 0.0505 0.0504 0.0503	CAF 0.1829 0.1808 0.1794 0.1800 0.1792 0.1793 0.1793	RUN 414. 414. 414. 414. 414. 414. 414. 414
Q= 3.77 PS1 P0= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264 0.42 -0.0212 -0.09 -0.0675 -0.60 -0.1023 -1.10 -0.1442 -1.60 -0.1876	RE PER IHG PTS= CM -2.4253 -1.7032 -0.913 -0.9767 -0.3120 0.0925 0.4809 0.7466 1.0904 1.4461	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075 -0.0068 -0.0085 -0.0063 -0.0064 -0.0049	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594 0.0404 0.0411 0.0289	90. DEG. RU CR 0.0024 0. 0.0032 0. 0.0028 0. 0.0036 0. 0.0031 0. 0.0019 0. 0.0033 0. 0.0028 0. 0.0029 0.	.F UN NO. 2338 0 2319 0 2301 0 2306 0 2298 0 2297 0 2297 0	POJ/PT 014036 CPB 0.0510 0.0507 0.0506 0.0506 0.0506 0.0504 0.0503 0.0501	CAF 0.1829 0.1809 0.1794 0.1792 0.1792 0.1793 0.1776 0.1805	RUN 414. 414. 414. 414. 414. 414. 414. 414
Q= 3.77 PS1 PO= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264 0.42 -0.0212 -0.09 -0.0675 -0.60 -0.1023 -1.10 -0.1442 -1.60 -0.1876 -2.11 -0.2238	RE PER IHG PTS= CM -2.4253 -1.7032 -0.913 -0.9767 -0.0120 0.0925 0.4809 0.7466 1.0904 1.4461 1.7293	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075 -0.0068 -0.0063 -0.0063 -0.0064 -0.0049 -0.0058	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594 0.0404 0.0401 0.0289 0.0363	90. DEG. RU CR	.F UN NO. .2338 0 .2319 0 .2301 0 .2306 0 .2284 0 .2297 0 .2297 0 .2294 0	POJ/PT 014036 CPB 0.0510 0.0507 0.0506 0.0506 0.0504 0.0503 0.0501 0.0501	S = 1 09107 CAF 0.1829 0.1808 0.1794 0.1792 0.1793 0.1793 0.1793 0.1795 0.1795	RUN 414. 414. 414. 414. 414. 414. 414. 414
Q= 3.77 PS1 P0= 400.0 CM ALPHA CN 3.96 0.2837 2.96 0.1971 1.95 0.1103 1.43 0.0497 0.93 0.0264 0.42 -0.0212 -0.09 -0.0675 -0.60 -0.1023 -1.10 -0.1442 -1.60 -0.1876	RE PER IHG PTS= CM -2.4253 -1.7032 -0.913 -0.9767 -0.3120 0.0925 0.4809 0.7466 1.0904 1.4461 1.7293 2.4604	IN.= .48E0 .2659 PSI CS -0.0114 -0.0094 -0.0104 -0.0096 -0.0075 -0.0068 -0.0085 -0.0063 -0.0064 -0.0049	CY 0.0889 0.0731 0.0796 0.0733 0.0532 0.0456 0.0594 0.0404 0.0404 0.0289 0.0363 0.0260	90. DEG. RU CR 0.0024 0. 0.0032 0. 0.0028 0. 0.0036 0. 0.0031 0. 0.0019 0. 0.0033 0. 0.0028 0. 0.0029 0.	.2338 0 .2319 0 .2301 0 .2306 0 .2284 0 .2297 0 .2297 0 .2298 0 .2297 0	POJ/PT 014036 CPB 0.0510 0.0507 0.0506 0.0506 0.0503 0.0501 0.0501 0.0501	S = 1 09107 CAF 0.1829 0.1808 0.1794 0.1793 0.1793 0.1793 0.1795 0.1758	RUN 414. 414. 414. 414. 414. 414. 414. 414

MC	DEL 946.2	CON	FIG. 2.45	50 M	ACH 4.50	D	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .488	06 TO=	90. DI	EG.F	POJ/P	TS =	•
ዮር)= 400.0 CM	HG PTS=	.2659 PS	SI .		RUN NO.	01403	69108	
ALPHA	N CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.03	0.3645	-3.0433	-0.0093	0.0671	0.0043	0.2440	0.0506	0.1934	415.
3.03	0.2711	-2.2512	-0.0066	0.0473	-0.0002	0.2421	0.0507	0.1915	415.
2.02	0.1778	-1.4687	-0.0058	0.0382	0.0035	0.2404	0.0505	0.1990	415.
1.50	0.1238	-1.0161	-0.0093	0.0710	0.0037	0.2370	0.0503	0.1867	
0.99	0.0828	-0.6805	-0.0055	0.0371	0.0034	0.2375	0.0502	0.1873	415.
0.48	0.0419	-0.3494	-0.0037		0.9037				415.
-0.02	-0.0052	0.0466	-0.0059		0.0027				415.
	-0.0419	0.3432	-0.0001	-0.0087					415.
	-0.0874	0.7234	-0.0018		0.0039				415.
		1.0402		-0.0537					
	-0-1797			-0.0028					415.
	-0.2632		0.0071	-0.0684					
-4.06	-0.3629	3.0356	0.0080	-0.0763	0.0029	0.2374	0.0504	0.1870	415.
	DEL 946.2		FIG. 2.49		ACH 4.50		PHI =	45.	
Q=	3.77 PSI	RE PER	IN -= -48E	=06 TO=	90. DE	G.F	POJ/P	rs = :	10.
PO	= 400.0 CM	HG PTS=	.2659 PS	I		RUN NO.	01403	69109	
ALPHA	CN CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.03	0.3603	-3:0210	-0.0154	0.1142	0.0031	0.2429	0.0508	0.1921	416.
3.03	0.2660	-2.2217	-0.0158	0.1192	0.0005	0.2382	0.0508	0.1874	416.
2.02	0.1757	-1.4667	-0.0121		-0.0009				416.
1.50	0.1251	-1.0440	-0.0067	0.0328	0.0031	0.2371	0.0505	0.1866	416.
0.99	0.0699	-0.5682	-0.0171	0.1371-	-0.CO04	0.2395	0.0503	0.1891	416.
0.48	0.0311	-0.2514	-0.0133	0.1043	0.0012	0.2370	0.0503	0.1868	416.
	-0.0077		-0.0095		0.0015				416.
-0.53	-0.0425		-0.0016	-0.0071					416.
	-0.0892		-0.0002	-0.0201					416.
	-0.1368		-0.0039		0.0030				416.
	-0,1752	1.4412	0.0013	-0.0312	0.0033	0.2338	0.0502	0.1837	416.
	-0.2675 -0.3652	2.2108		-0.0436 -0.0886	0.0025	0.2321	0.0503	0.1818	416. 416.

MODEL 946.2	CONF	IG. 2:45	0 Mi	NCH 4.50	0	?HI =	45.	
Q= 3.77 PSI	RE PER	IN.= .48E	06 TO=	90. DI	EG.F	POJ/P	TS = 2	20.
PÓ= 400.0 CH	HG PTS=	.2659 PS	1		RUN NO.	01403	69110	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.03 0.3546	-2.9800	-0.0220	0.1628	G.0013	0.2329	0.0507	0.1823	417.
3.03 0.2628	-2.2048	-0.0187	0.1335	0.0012	0.2326	0.0508	0.1818	417.
2.01 0.1690	-1.4163	-0.0195	0.1440	0.0023	0.2309	0.0506	0.1803	417.
1.49 0.1114	-0.9229	-0.0256			0.2304			417.
0.99 0.0780	-0.6652	-020130			0.2307			417.
0.49 0.0290	-0.2509	-0.0194			0.2256		-	417.
-0.02 -0.0074	0.0425	-0.0099			0.2274			417.
-0.54 -0.0489	0.3843				0.2250			417.
-1.04 -0.0965		-0.0093			0.2287			417.
-1.55 -0.1447	1.1907	-			0.2309			417.
-2.04 -0.1772		-0.0027	-0.0092					417.
-3.05 -0.2675		-0.0010	-0.0227					417.
-4.06 -0.3648	3.0191	0.0055	-0.0852-	-0.0006	0.2232	0.0505	0.1727	417.
MODEL 946.2	CONF	IG. 2.45	O H/	NCH 4.50	0	PHI =	45•	
Q= 3.77 PSI	RE PER	IN.= .48E	06 TO=	90. DI	EG.F	P0J/P1	rs = 4	·G.
PO= 400.0 CH	HG PTS=	.2659 PS	I		RUN NO.	01403	69111	
ALPHA CN	CH	cs	CY	CR	CAT	СРВ	CAF	RUN
4.03 0.3434	-2,8931	-0-0294	0-2117	0.0045	0.2379	0.0507	0-1872	418.
3.02 0.2518	-2.1234	_			0.2332			418.
2.01 0.1610	-1.3633				0.2344			418.
1.48 0.1067								
0.99 0.0587	-0.9122	-0.0253	0.1708	0.0020	0.2309	0.0504	0.1805	418.
	-0.9122 -0.5012				0.2309			
0.48 0.0270		-0.0286	0.2087	0.0023	0.2286	0.0503	0.1783	418. 418. 418.
	-0.5012	-0.0286 -0.0177	0.2087 0.1050	0.0023 0.0039		0.0503 0.0503	0.1783 0.1771	418.
0.48 0.0270	-0.5012 -0.2575 0.1930	-0.0286 -0.0177	0.2087 0.1050 0.2174	0.0023 0.0039 0.0010	0.2286	0.0503 0.0503 0.0503	0.1783 0.1771 0.1868	418. 418.
0.48 0.0270 -0.03 -0.0255	-0.5012 -0.2575 0.1930 0.4947	-0.0286 -0.0177 -0.0287	0.2087 0.1050 0.2174 0.1102	0.0023 0.0039 0.0010 0.0044	0.2286 0.2274 0.2372	0.0503 0.0503 0.0503 0.0503	0.1783 0.1771 0.1868 0.1783	418. 418. 418.
0.48 0.0270 -0.03 -0.0255 -0.54 -0.0631	-0.5012 -0.2575 0.1930 0.4947 0.8066	-0.0286 -0.0177 -0.0287 -0.0181	0.2087 0.1050 0.2174 0.1102 0.0728	0.0023 0.0039 0.0010 0.0044 0.0041	0.2286 0.2274 0.2372 0.2287	0.0503 0.0503 0.0503 0.0503 0.0503	0.1783 0.1771 0.1868 0.1783 0.1804	418. 418. 418. 418.
0.48 0.0270 -0.03 -0.0255 -0.54 -0.0631 -1.04 -0.1019	-0.5012 -0.2575 0.1930 0.4947 0.8066 1.2179	-0.0286 -0.0177 -0.0287 -0.0181 -0.0143	0.2087 0.1050 0.2174 0.1102 0.0728 0.0824	0.0023 0.0039 0.0010 0.0044 0.0041 0.0056	0.2286 0.2274 0.2372 0.2287 0.2307	0.0503 0.0503 0.0503 0.0503 0.0503 0.0503	0.1783 0.1771 0.1868 0.1783 0.1804 0.1811	418. 418. 418. 418.
0.48 0.0270 -0.03 -0.0255 -0.54 -0.0631 -1.04 -0.1019 -1.55 -0.1507	-0.5012 -0.2575 0.1930 0.4947 0.8066 1.2179 1.5359	-0.0286 -0.0177 -0.0287 -0.0181 -0.0143 -0.0149	0.2087 0.1050 0.2174 0.1102 0.0728 0.0824 0.0683	0.0023 0.0039 0.0010 0.0044 0.0041 0.0056 0.0034	0.2286 0.2274 0.2372 0.2287 0.2307 0.2314	0.0503 0.0503 0.0503 0.0503 0.0503 0.0503	0.1783 0.1771 0.1868 0.1783 0.1804 0.1811 0.1771	418. 418. 418. 418. 418.

and a straight and the transfers of the terms of the terms of the terms of the second
							•				
H	ODEL 9	46.2	CO	NFIG.	2.450	M	4CH 4.5	0	PHI =	45.	
Q	= 3.77	PSI	RE PE	R IN.=	.48E0	6 TG=	90. D	EG.F	POJ/P	TS = 1	.00.
ρ	0= 400	.0 CMH	IG PTS	= .26	124 es			RUN ÑO	01403	69112	
ALPH	A (:N	CM	ε	s	CY	CR	CAT	CPB	CAF	RUN
4.0	2 0.3	118	-2.648	1 -0-0	555	0-4012	0-0040	0.2468	0.0508	0-1961	419.
3.0		195	-1.867					0.2451			
	1 0.1		-1.103					0.2433			
	9 0.0		-0.656					0.2412			
	8 0.0		-0.326					0.2417			
	8 ~0.0			7 -0.0				0.2454			
	4 -0.0			7 -0.0				0.2370			
	3 -0.0			9 -0.0				0.2375			
	5 -0.1			4 ~0.0				0.2366			
	6 ~0.1			2 -0:0				0.2361			
-	5 -0.2		1.715					0.2348			
	6 -0.3		2.466					0.2316			
-4.0	7 -0.3	1989	3.246	3 -0.0	224	0.0996	-0.0017	0.2327	0.0504	0.1823	419.
	ODEL 9 = 3.77				2•450		ACH 4.50		PHI =		
Ų	- 3.11	P31	KC PE	K 114	• 40EU	10-	90. U	EU•P	PUJ/P	15 =	•
Р	0= 400	.0 CMH	IG PTS	= •26	59 PSI			RUN NO	01403	69113	
ALPH	Å C	:N	CM	C	S	CY	CR	CAT	CPB	CAF	RUN
4.0	0 0.3	592	-2.983	4 -0.0	040	0.0260	0.0048	0.2414	0.0508	0-1906	420.
3.0		671	-2.204	-				0.2431			
1.9		742	-1.431					0.2391			
1.4		241	-1.017					0.2357			
0.9		796	-0.650					0.2471			
0.4			-0.327		-			0.2365			
	6 -0-0			6 -0.0				0.2374			
	6 -0.0		_	5 -0.0	-			0.2371			
	6 -0.0	_		4 -0.0				0.2335			
	B -0.1			7 -0.0				0.2345			
	7 -0-1		1.436					0.2340			
	8 -0.2			4 -0.0				0.2354			
-4.0	9 -0.3	641	3.024	6 0.0	. 880i	-0.0782	U- 0048	ŭ.2369	0.0505	0.1863	420•

THE THE PROPERTY OF THE PROPER

	MOD	EL 946.2	CONI	FIG. 2.	450 ' M/	ACH 4.50		'PHI =	90.	
	Q=	3.77 PSI	RE PER	IN.= .4	8E06 TO=	90. DEG	.F	P0J/P	rs = 10	0•
	P0=	400.0 CP	IHG PTS≃	-2659	PSI	R	UN NO.	01403	59114	
A	LPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
	4.00	0.3574	-2.9673	-0.0085		0.0030 0				421.
	3.00		-2.1831			0.0018 0				421.
	1.99		-1.4226			0.0006 0				421.
	1.47		-1.0121			0.0031 0				421.
	0-96		-0.6588			0.0025 0				421.
	0.46		-0.3215			0.0020 0				421.
		-0.0058	0.0482			0.0033 0				421.
		-0.0480		-0.0066		0.0040 0				421.
		-0.0917		-0.0012		0.0041 0				421.
		-0.1355		-0.0101		0.0028 0				421.
		-0.1746		-0.0017		0.0029 0				421.
		-0.2660		-0.0023		0.0030 0				421.
_	4.09	-0.3628	3.0090	-0.0001	-0.0211	0.0024 0	1.2299	0.0001	0.1793	421.
		EL 946.2	CONI RE PER	FIG. 2. IN.= .4	-	ACH 4.50 90. DEG	F	= IH9		O . .
	Q=		RE PER	IN.= .4	•8E06 T0≖	90. DEG			rS = 2	0.
A	Q=	3.77 PSI	RE PER	IN.= .4	•8E06 T0≖	90. DEG		'P0J/P	rS = 2	RUN
	Q= P0=	3.77 PST : 400.0 CF	RE PER	IN.= .4 .2659	PSI CY	90. DEG	EUN NO.	POJ/P . 014030 CPB	rS = 26 69115 CAF	,
	Q= PO= LPHA	3.77 PSI 400.0 CP CN 0.3619	RE PER	IN.= .4 .2659 CS -0.0128	8E06 TO≠ PSI CY 0.0595	90. DEG	CAT	P0J/P1 . 014030 CPB 0.0514	rS = 26 59115 CAF 0.1832	RUN
	Q= PO= LPHA 4.00	3.77 PSI 400.0 CP CN 0.3619 0.2675	RE PER HHG PTS= CM -3.0050	IN.= .4 .2659 CS -0.0128	PSI CY 0.0595 0.0845	90. DEG R CR 0.0063 0	CAT 0.2347 0.2335	POJ/P1 . 014030 CPB 0.0514 0.0514	rS = 26 69115 CAF 0.1832 0.1821	RUN 422.
	Q= PO= LPHA 4.00 3.00	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739	RE PER HHG PTS= CM -3.0050 -2.2046	IN.= .4 .2659 CS -0.0128 -0.0151	PSI CY 0.0595 0.0845 0.1005	90. DEG R CR 0.0063 0	CAT 0.2347 0.2335 0.2279	POJ/P1 . 014030 . CPB 0.0514 0.0514 0.0509	TS = 26 59115 CAF 0.1832 0.1821 0.1770	RUN 422. 422.
	Q= PO= LPHA 4.00 3.00 1.99	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254	RE PER HHG PTS= CM -3.0050 -2.2046 -1.4241	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156	PSI CY 0.0595 0.0845 0.1005 0.0764	90. DEG R CR 0.0063 0 0.0020 0	CAT 0.2347 0.2335 0.2279 0.2303	POJ/P1 . 014030 . CPB 0.0514 0.0514 0.0509 0.0506	TS = 26 59115 CAF 0.1832 0.1821 0.1770 0.1797	RUN 422. 422. 422.
	Q= PO= LPHA 4.00 3.00 1.99 1.47	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254	RE PER SHG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156 -0.0130	PSI CY 0.0595 0.0845 0.1005 0.0764 0.1366	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0	CAT 0.2347 0.2335 0.2279 0.2303 0.2270	POJ/P1 . 014030 . CPB 0.0514 0.0514 0.0509 0.0506	CAF 0.1832 0.1821 0.1770 0.1797 0.1764	RUN 422. 422. 422. 422. 422. 422.
	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793	RE PER SHG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156 -0.0130 -0.0190 -0.0163	PSI CY 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0001 0 0.0027 0 0.0034 0	CAT .2347 .2335 .2279 .2303 .2270 .2265	POJ/P 014030 CPB 0.0514 0.0504 0.0506 0.0506 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1741	RUN 422. 422. 422. 422. 422. 422.
	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95 0.45 0.06	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036 -0.00474	RE PER HG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921	IN.= .4 .2659 CS -0.0128 -0.0156 -0.0136 -0.0196 -0.0136 -0.0136	PSI CY 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903 0.0035	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0034 0 0.0041 0	CAT -2347 -2335 -2279 -2303 -2270 -2265 -2244	POJ/P 014030 CPB 0.0514 0.0504 0.0506 0.0506 0.0503 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1761 0.1764	RUN 422. 422. 422. 422. 422. 422. 422.
	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95 0.45 0.06	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036	RE PER HG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921 0.7455	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0136 -0.0190 -0.0136 -0.0136 -0.0099	PSI CY 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903 0.0035	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0041 0 0.0041 0	CAT -2347 -2335 -2279 -2303 -2270 -2265 -2244 -2267	POJ/P 014030 CPB 0.0514 0.0504 0.0506 0.0506 0.0503 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1764 0.1764 0.1775	RUN 422. 422. 422. 422. 422. 422. 422. 422
-	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.45 0.45 0.66 0.56	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036 -0.0474 -0.0904 -0.1349	RE PER HG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921 0.7455 1.1106	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0136 -0.0136 -0.0136 -0.0054 -0.0095 -0.0072	PSI CY 0.0595 0.0845 0.1005 0.0764 0.0136 0.01120 0.0703 0.0035 0.0484 0.0240	90. DEG R CR 0.0053 0 0.0020 0 0.0007 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0024 0 0.0041 0 0.0042 0	CAT -2347 -2335 -2279 -2303 -2270 -2265 -2244 -2267	POJ/P . 014030 . CPB 0. 0514 0. 0514 0. 0506 0. 0506 0. 0503 0. 0503 0. 0503 0. 0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1764 0.1775 0.1636	RUN 422. 422. 422. 422. 422. 422. 422. 422
-	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95 0.45 0.45 0.56 1.57 2.07	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036 -0.00474 -0.0904 -0.1349 -0.1740	RE PER SHG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921 0.7455 1.1106 1.4314	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156 -0.0130 -0.0163 -0.0054 -0.0099 -0.0072 -0.0090	PSI CY 3 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903 0.0035 0.0036 0.0046	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0041 0 0.0041 0 0.0042 0 0.0043 0	CAT -2347 -2335 -2279 -2303 -2270 -2265 -2244 -2267 -2278 -2139	POJ/PT CPB 0.0514 0.0514 0.0509 0.0506 0.0503 0.0503 0.0503 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1741 0.1764 0.1775 0.1636 0.1808	RUN 422. 422. 422. 422. 422. 422. 422. 422
	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95 0.45 0.06 0.56 1.57 2.07	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036 -0.00474 -0.0904 -0.1349 -0.1740 -0.2654	RE PER SHG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921 0.7455 1.1106 1.4314 2.1913	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156 -0.0136 -0.0196 -0.0096 -0.0096 -0.0096	PSI CY 3 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903 0.0035 0.00443 0.0240 0.0443	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0041 0 0.0041 0 0.0042 0 0.0043 0 0.0043 0 0.0043 0	CAT 0.2347 0.2335 0.2279 0.2303 0.2270 0.2265 0.2244 0.2267 0.2278 0.211	POJ/P3 014030 CPB 0.0514 0.0514 0.0506 0.0506 0.0503 0.0503 0.0503 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1764 0.1763 0.1636 0.1808 0.1766	RUN 422 • 422 •
	Q= PO= LPHA 4.00 3.00 1.99 1.47 0.95 0.45 0.06 0.56 1.57 2.07	3.77 PSI 400.0 CP CN 0.3619 0.2675 0.1739 0.1254 0.0793 0.0386 -0.0036 -0.00474 -0.0904 -0.1349 -0.1740	RE PER SHG PTS= CM -3.0050 -2.2046 -1.4241 -1.0265 -0.6485 -0.3183 0.0288 0.3921 0.7455 1.1106 1.4314 2.1913	IN.= .4 .2659 CS -0.0128 -0.0151 -0.0156 -0.0130 -0.0163 -0.0054 -0.0099 -0.0072 -0.0090	PSI CY 3 0.0595 0.0845 0.1005 0.0764 0.1366 0.1120 0.0903 0.0035 0.00443 0.0240 0.0443	90. DEG R CR 0.0063 0 0.0020 0 0.0007 0 0.0007 0 0.0027 0 0.0027 0 0.0041 0 0.0041 0 0.0042 0 0.0043 0	CAT 0.2347 0.2335 0.2279 0.2303 0.2270 0.2265 0.2244 0.2267 0.2278 0.211	POJ/P3 014030 CPB 0.0514 0.0514 0.0506 0.0506 0.0503 0.0503 0.0503 0.0503 0.0503	CAF 0.1832 0.1821 0.1770 0.1797 0.1764 0.1761 0.1764 0.1763 0.1636 0.1808 0.1766	RUN 422. 422. 422. 422. 422. 422. 422. 422

MO	DEL 946.2	CONF	ig. 2.450) M	ACH 4.50	ı	9HI =	90-	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	G.F	POS/F	TS = 40	•
·PO	= 400.0 CH	HG PTS=	.2659 PSI			RUN NO.	01403	69116	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.00	0.3584	-2.9738	-0.0260	0.1435	0.0051	0.2309	0.0511	0.1798	423.
3.01	0.2663	-2.1947	-0.0223		0.0077				423.
1.99	0.1719	-1.4043	-0.0229		0.0077				423.
1.47	0.1243	-1.0160	-0.0217		0.0064				423.
0.96	0.0789	-0.6450	-0:0250		0.0027				423.
	0.0398	-0.3329			0.0009				423.
	-0.0055	0.0455			0.0047				423.
	-0.0469	0.3861			0.0067				423.
	-0.0907	0.7445			0.0054				423。
	-0.1353		-0.0175		0.0055				423.
	-0.1736	1.4251			0.0056				423.
	-0.2650		-0.0141		0.0026				423.
-4.09	-0.3609	2.9919	-0.0076	-0.0071	0.0020	0.2277	0.0509	0.1768	423.
	DEL 946.2		IG. 2.450		ACH 4.50		PH1. =	90. TS = 100	
U -	. 5.11 .51	KC FER	114 4-000	0 10-	30. DE	941	F03/F	13 - 100	•
PÜ	= 400.0 CM	HG PTS=	.2659 PSI		i	RUN NO.	01403	69117	
ALPHA	CN	CM	CŞ.	CY	CR	CAT	CPB	CAF	RUN
4.00	0.3575	-2.9613	-0.0582	0.3608	0.0091	0.2426	.0.0517	0.1910	424.
3.00	0.2624	-2.1555	-0.0617	0.4011	0.0098	0.2370	0.0517	0.1854	424.
1.99	0.1703	-1.3883	-0.0594	0.3888	0.0092	0.2388	0.0512	0.1876	42%.
1.47	0.1203	-0.9757	-0.0612	0.4091	0.0054	0.2398	0.0504	0.1894	424.
0.97	0.0820	-0.6649	-0.0614	0.4138	0.0061	0.2393	0.0508	0.1884	424.
0.45	0.0328	-0.2619	-0.0602	0.4101	0.0054	0.2416	0.0504	0.1913	424.
-0.56	-0.0501	0.4117	-0.0594	0.4039-	-0.0007	0.2407	0.0502	0.1905	424.
-0.05	-0.0025	0.0235	-0.0618	0.4228	0.0049	0.2383	0.0505	0.1878	424.
-1.05	-0.0854	0.6973	-0.0580		0.0038				424.
-1.57	-0.1361	1.1135	-0.0512		0.0019				424.
-2.07	-0.1752	1.4357	-0.0556	0.3638	0.0027	0.2303	0.0503	0-1799	424.
			0.0000						
	-0.2666 -0.3641	2.1938	-0.0493 -0.0469	0.2984-	0.0029	0.2365	0.0505	0.1859	424. 424.

MOD	EL 946.2	CONF	IG. 3.000	НА	CH 4.50)	PHI =	•	
Q=	3.77 PSI	RE PER	IN.= .48E0	5 TO=	90. DI	G.F	901/9	rs =	•
P0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO.	01403	69118	
ALPHA	CN	CM	cs.	CY	CR	CAT	СРВ	CAF	RUN
4.17	0.4189	-3.6323	-0.0212	0.1869-	0.0008	0.2683	0.0497	0.2186	425.
3.17	0.3137	-2.7121		0-1640-					
2.16	0.2128	-1.8326	-0.0165	0.1462-	0.0006	0.2605	0.0498	0.2109	425.
1.64	9.1451	-1.2336	-0.0158	0.1407-	0.0006	0.2595	0.0493	0.2102	425.
1.13	0.1033	-0.8845	-0.0144	0.1277	0.0026	0.2578	0.0491	0.2086	
0.61	0.0585	-0.5084	-0.0162	0.1443-					
0.12	0.0123	-0.1116		0.1247-					
-0.39	-0.0381	0.3371	-0.0127	0.1127					
	-0.0814		-0.0129	0.1145-					
	-0.1247		-0.0130	0.1168-					
	-0.1723		-0.0102	0.0913-					
•	-0.2675		-0.0090	0.0817					
-3.91	-0.3771	3.2593	-0.0054	0.0478	0.0006	0.2562	0.0495	0.2068	425.
	EL 946.2	CONF			CH 4.50		PHI =	• rs =	10.
0=	3.77 PSI	RE PER	FIG. 3.000 IN.= .48E0			EG.F		rs =	10.
0=	3.77 PSI	RE PER	IN.= .48E0			EG.F	POJ/P	rs =	10.
0=	3.77 PSI	RE PER	IN.= .48E0			EG.F	P0J/P	rs =	10 . RUN
Q= PC=	3.77 PSI 400.0 CM	RE PER HG PTS= CM	IN.= .48E0	5 TO=	90. DE	EG.F RUN. NO.	POJ/P 014030 ČPB	rs = 6 911 9 Caf	RUN 426•
Q= PO= Alpha	3.77 PSI 400.0 CM	RE PER HG PTS= CM	IN.= .48E00 .2659 PSI CS -0.0194	5 TO=	90. DE	EG.F RUN. NO. CAT D.2789	POJ/P 014030 ČPB 0.0499	TS = 69119 CAF 0-2291	RUN 426• 426•
Q= PO= ALPHA 4.17	3.77 PSI 400.0 CM CN 0.4130	RE PER HG PTS= CM -3.6008 -2.6786	IN.= .48E00 .2659 PSI CS -0.0194	CY 0.1724 0.1541 0.1365	90. DE CR 0.0024 0.0037 0.0026	EG.F RUN. NO. CAT 0.2789 0.2714 0.2698	POJ/P 014030 CPB 0.0499 0.0500 0.0498	(S = 69119 CAF 0-2291 0-2213 0-2200	RUN 426• 426• 426•
0= PO= ALPHA 4.17 3.17	3.77 PSI 400.0 CM CN 0.4130 0.3079	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298	IN.= .48E00 .2659 PSI CS -0.0194 -0.0175 -0.0155 -0.0141	CY 0.1724 0.1541 0.1365 0.1256	90. DE CR 0.0024 0.0037 0.0026 0.0020	CAT 0.2789 0.2714 0.2698 0.2713	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0496	TS = 69119 CAF 0.2291 0.2213 0.2200 0.2218	RUN 426. 426. 426. 426.
Q= PG= ALPHA 4.17 3.17 2.16 1.64 1.13	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298	IN.= .48E00 .2659 PSI CS -0.0194 -0.0175 -0.0155	CY 0.1724 0.1541 0.1365 0.1256 0.1209-	90. DE	CAT 0.2789 0.2714 0.2698 0.2713 0.2685	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0496	CAF 0.2291 0.2213 0.2200 0.2218 0.2190	RUN 426. 426. 426. 426. 426.
Q= PQ= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.8197 -0.4705	IN.= .48E00 .2659 PSI CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128	CY 0.1724 0.1541 0.1365 0.1256 0.1209- 0.1149	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0005 0.0027	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0494 0.0494	CAF 0.2291 0.2213 0.2200 0.2218 0.2190 0.2175	RUN 426. 426. 426. 426. 426. 426.
Q= PQ= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.8197 -0.4705 -0.0960	IN.= .48E00 .2659 PS1 CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128 -0.0123	CY 0.1724 0.1541 0.1365 0.1256 0.1259 0.1149 0.1094-	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0005 0.0027	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668	POJ/P 014030 ČPB 0.0499 0.0500 0.0498 0.0494 0.0493 0.0491	CAF 0.2291 0.2213 0.2200 0.2218 0.2175	RUN 426. 426. 426. 426. 426. 426. 426.
Q= PO= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12 -0.39	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092 -0.0383	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.8197 -0.4705 -0.0960 0.3075	IN.= .48E00 .2659 PS1 CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128 -0.0123 -0.0109	CY 0.1724 0.1541 0.1365 0.1256 0.1259 0.1149 0.1094- 0.0983	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0027 0.0023 0.0023	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668 0.2650 0.2693	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0494 0.0493 0.0491 0.0489	CAF 0.2291 0.2218 0.2200 0.2218 0.2175 0.2159	RUN 426. 426. 426. 426. 426. 426. 426. 426.
Q= PO= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12 -0.39 -0.89	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092 -0.0383 -0.0802	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.4705 -0.4705 -0.960 0.3075 0.6575	IN.= .48E00 .2659 PS1 CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128 -0.0123 -0.0109 -0.0095	CY 0.1724 0.1541 0.1365 0.1256 0.1209- 0.1149 0.1094- 0.0983 0.0854	90. DE CR 0.0024 0.0037 0.0020 0.0020 0.0027 0.0023 0.0022 0.0023	CAT 0.2789 0.2714 0.2698 0.2685 0.2668 0.2650 0.2693 0.2676	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0494 0.0493 0.0491 0.0489 0.0489	CAF 0.2291 0.2213 0.2203 0.2175 0.2159 0.2186	RUN 426. 426. 426. 426. 426. 426. 426. 426.
Q= PO= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12 -0.39 -0.89 -1.40	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092 -0.0383 -0.0802 -0.1307	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.4705 -0.0960 0.3075 0.6575 1.1009	IN.= .48E00 .2659 PS1 CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128 -0.0123 -0.0109 -0.0095 -0.0097	CY 0.1724 0.1541 0.1365 0.1256 0.1209- 0.1149 0.1094- 0.0983 0.0854 0.0886	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0005 0.0027 0.0023 0.0022 0.0023	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668 0.2650 0.2693 0.2676 0.2660	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0494 0.0493 0.0491 0.0489 0.0489 0.0489	CAF 0.2291 0.2213 0.2218 0.2175 0.2159 0.2175	RUN 426. 426. 426. 426. 426. 426. 426. 426.
Q= PC= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12 -0.39 -0.89 -1.40 -1.90	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092 -0.0383 -0.0802 -0.1307 -0.1739	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.8197 -0.4705 -0.0960 0.3075 0.6575 1.1009 1.4706	IN.= .48E00 .2659 PSI CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0123 -0.0123 -0.0109 -0.0095 -0.0097	CY 0.1724 0.1541 0.1365 0.1256 0.1209- 0.1149 0.1094- 0.0983 0.0854 0.0886 0.0918	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0027 0.0023 0.0022 0.0023 0.0004	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668 0.2650 0.2673 0.2660 0.2642	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0496 0.0494 0.0493 0.0491 0.0489 0.0489 0.0489	CAF 0.2291 0.2213 0.2200 0.2175 0.2159 0.2171 0.2151	RUN 426. 426. 426. 426. 426. 426. 426. 426.
Q= PO= ALPHA 4.17 3.17 2.16 1.64 1.13 0.62 0.12 -0.39 -1.40 -1.90 -2.91	3.77 PSI 400.0 CM CN 0.4130 0.3079 0.2055 0.1521 0.0944 0.0526 0.0092 -0.0383 -0.0802 -0.1307	RE PER HG PTS= CM -3.6008 -2.6786 -1.7901 -1.3298 -0.8197 -0.4705 -0.0960 0.3075 0.6575 1.1009 1.4706 2.3214	IN.= .48E00 .2659 PS1 CS -0.0194 -0.0175 -0.0155 -0.0141 -0.0135 -0.0128 -0.0123 -0.0109 -0.0095 -0.0097	CY 0.1724 0.1541 0.1365 0.1256 0.1209- 0.1149 0.1094- 0.0983 0.0854 0.0886 0.0918	90. DE CR 0.0024 0.0037 0.0026 0.0020 0.0027 0.0023 0.0022 0.0023 0.0004 0.0036	CAT 0.2789 0.2714 0.2698 0.2713 0.2685 0.2668 0.2650 0.2673 0.2660 0.2642	POJ/P 014030 CPB 0.0499 0.0500 0.0498 0.0496 0.0494 0.0493 0.0489 0.0489 0.0489 0.0489 0.0489	CAF 0.2291 0.2213 0.2200 0.2175 0.2159 0.2171 0.2153 0.2171	RUN 426. 426. 426. 426. 426. 426. 426. 426.

M	odel	. 94	6.2			CONI	FIG	•	3.	000		н	ACH	4.	50			PHI =	=		•		
Q	= 3.	77	PSI	RI	E	PER	IN	. =	.4	BE06	•	T0=	9	0- 1	DEG	.F		POJ/F	215	=		20.	
P	0= 4	00.	G C1	4HG	P	TS=	• 3	265	9 1	PSI					R	UN NO	١.	01403	869	120	ł		
ALPH.	A	CN	ŧ	(CM			CS	•		C١	′		CR	-	CAT		СРВ	1	CAF	:		RUN
4.1	6 0	.39	85	-3	.4	880	-0	.02	15		0.1	911	-0.	001	3 0	.2722	. 0	.0504	0	-22	18	3	427.
3.1	7 0	-29	63	-2	•5	921	~0	.01	88		0.1	661	0.	002	5 0	.2689	0	.0504	0	.21	85	j	427.
2.1	5 0	.19	97	-1.	.7	59:2	-0	.01	92		0.1	695	0.	0033	3 0	.2672	0	.0501	. 0	-21	71		427.
1.6	4 0	-13	119	-1	. i	561	-0	.01	69		0.1	511	-0.	001	1 0	.2646	0	.0498	0	-21	48	3	427.
1.13	3 0	.10	000	-0	•9	014	-0.	.01	64		0.1	456	-0.	001	6 0	-2686	O	-0498	0	-21	88	}	427 .
0.63	2 0	-04	67	-0	. 4	419	-0	.01	34		0.1	182	0.	002	8 0	.2671	0	.0495	0	.21	77	,	427.
0.1	1 0	.00	106	-0.	•0	399	-0.	.01	44									.0495					427.
-0.3	9 -0	.04	85	0.	• 3	831	-0	.01	30		0.1	168	-0.	0009	90	.2609	0	.0495	0	-21	14	•	427.
-0.9	0 -0	.08	146	0.	• 6	806	-0	.01	.25									.0489					427.
-1.4						138												.0489					427.
-1.9						761												.0489					427.
-2.9						361												.0489					427.
-3.9	1 -0	-38	116	3.	-2	582	-0	.00	74		0.0	673	0.	0026	6 0	-2612	0	-0492	0	-21	20)	427.
М	ODEL	. 94	6.2		(CONF	IG.	•	3.0	000		н	ACH	4.5	50			PHI =	:		•		
Q:	= 3,	77	PSI	RE	E 1	PER	IN.	=	. 4	3E06	•	TO=	9	0. (DEG.	.F		POJ/P	TS	=		40.	
Pi	0= 4	00.	0 CF	HG	Ρ	TS=	• 2	265	9 [PSI					R	סא אט	•	01403	69	121			
ALPH	A	CN	ì	(CM			CS	,		CY	•		CR	•	CAT		СРВ	(CAF			RUN
4.1	7 0	-38	155	-3.	. 3	967	-0.	.02	19		0.1	957	0-	0013	3 0	.2727	Ω	.0506	O.	-22	21		428.
3.10		-28				230												.0506					428.
2.1		-18	-	-		376												-0503					428.
1.6	_	-12				365												.0499					428.
1.1		-08				836												-0497					428.
0.6	-	.02				825												.0497					428.
0.1				_		087												.0494					428.
-0.3						349												.0494					428.
-0.90				0.	8	689	-0.	01	13									.0489					428.
-1.40	0 -0	-14	53	1.	. 1	774	-0.	.00	92		0.0	814	٥.	0050	0.0	2668	0	.0489	0.	-21	79	,	428.
-1.9	1 -0	-18	72	1.	.5	400	-0.	.00	94									.0487					428.
-2.9	1 -0	-28	66			980												.0487					428.
-3.9	2 –0	. 30	PIG	3.	-3	158	-0.	.00	62		0.40	575	0.	2021	ı o.	2632	O	.0489	n.	.21	43		428.

A STATE OF THE PARTY OF THE PAR

MOD	EL 946.2	CONF	FIG. 3.000) M	ACH 4.5	0	PHI =	•	-
Q= :	3.77 PSI	RE PER	IN.= .48E0	6 Ť0=	90. D	EG.F	POJ/P	rs = 100.	
P0=	400.0 CM	HG PYS=	.2659 PSI			RUN NO	01403	69122	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.15	0-3361	-3.0023	-0.0203	0.1830	0.0008	0-2864	0.0507	0.2357	429.
	0.2352	-2.1162	-0.0184	0.1611	0.0009	0.2772	0.0507	0.2265	429.
	0.1357		-0.0149			0.2872			429.
	0.0810		-0.0149			0.2727			429•
_	0.0476		-0.0129			0.2781			429.
	-0.0057		-0.0115			0.2707			429.
	-0.0562		-0.0101			0.2707			429 c
	-0.0966		-0.0095			0-2733			429.
	-0-1399		-0.0089			0.2687			429.
	-0.1918		-0.0090			0.2702			429.
	-0.2322		-0.0077			0.2671			429.
	-0.3260		-0.0057			0.2695			429.
-3.96	-0.4399	3.6777	-0.0037	0.0361	G. 0029	0.2668	0.0489	0.2179	429.
MOD	FL 946•2	CON	FIG. 3.000) м	ACH 4.5	0	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. D	EG.F	POJ/P	rs = .	
P0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO	01403	69123	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
3.94	0.3979	-3.4430	-0.0157	0.1486	-0-0017	0.2385	0-0502	0.1883	430.
2.94	0.2963	•	-0.0170			0.2381			430.
1.93	0.1923		-0.0118			0.2274			430.
1.41	0.1311		-0.0162			0.2239			430.
0.91	0.0848		-0.0133			0.2303			430.
0.39			-0.0109			0.2265			430.
	-0.0116		-0.0137			0.2272			430.
	-0.0566		-0.0118			0,2246	•		430.
	-0.1029		-0.0067			0.2222			430.
	-0.1527	-	-0.0064			0.2213			430.
	-0.1898		-0.0023			0.2216			430.
	-0.2916	2.4998	0.0008	0.0059	-0.0047	0.2198	0.0492	0.1706	430.
-4.15	-0.3972	3.4199	0.0075	-0.0503	-0.0031	0.2223	0.0499	0.1724	430.

MOD	EL 946.2	.CON	FIG. 3.00	AH O	CH 4.50	•	PHI =	45.	
Ø≖	3.77 PSI	RE PER	IN48E	06 T0≃	90. DE	G.F	POJ\P	TS =	10.
P0=	400.0 CM	HG PTS=	。2659 PS	I	1	RUN NO.	01403	69124	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	ลบห
3.94	0.3958	-3.4438	-0.0239	0.2087-	0.0022	0.2448	0.0504	0.1944	431.
2.94	0.2914	-2.5311	~0.0204	0.1754-	0.0031	0.2444	0.0506	0.1938	431.
1.92	0.1907	-1.6600	-0.0186	0.1603-	0.0045	0.2367	0.0502	0.1865	431.
1.41	0-1345	-1.1.750	-0.0179		0.0018				
0.90	0.0877	-0.7763	-0.0123		0.0022				
0.39	0.0400	-0.3658	-0.0120		0.0032				
	-0.0138		-0.0178		0.0068				
	-0.0512		-0.0094		0.0077				
	-0.1061		-0.0141		0.0081				
	-0-1511		-0.0122		0.0085				
	-0.1884		-0:0038		0.0032				
	-0.2886		-0.0003		0.0034				
-4.15	-0.3969	3.4001	0.0049	-0.0427-	0.0036	0.2314	0.0498	0.1816	431.
	EL 946.2	CON!	ig. 3.00		CH 4.50 90. DE(PHI =	45. TS =	20.
Q=		RE PER		06 TO=	90. DE	G.F		TS =	20•
Q= P0=	3.77 PSI 400.0 CM	RE PER	IN.= .48E	106 TO=	90. DEC	G.F RUN NO.	POJ/P	TS = 69125	
Q=	3.77 PSI	RE PER	IN.= .48E	06 TO=	90. DE	G.F	POJ/P	TS =	20• RUN
Q= PO= Alpha	3.77 PSI 400.0 CM	RE PER HG PTS=	IN.= .48E .2659 PS	06 TO=	90. DEC	G.F RUN NO. CAT	POJ/P 014030 CPB	TS = 69125 CAF	RUN
Q= PO= ALPHA 3.94	3.77 PSI 400.0 CM CN 0.3960	RE PER HG PTS= CM -3.4635	IN.= .48E .2659 PS CS -0.0344	06 TO= I CY 0.2888-	90. DEC - F CR D. 0021 (G.F RUN NO. CAT D.2497	POJ/P 01403 CPB 0.0510	TS = 69125 CAF 0.1987	RUN 432.
Q= PO= ALPHA 3.94 2.93	3.77 PSI 400.0 CM CN 0.3960 0.2906	RE PER HG PTS= CM -3.4635 -2.5416	IN.= .48E .2659 PS CS -0.0344 -0.0318	06 T0= I CY 0.2888- 0.2660-	90. DEC CR D. 0021 (G.F RUN NO. CAT 0.2497 0.2419	POJ/P 014030 CPB 0.0510 0.0509	TS = 69125 CAF 0.1987 0.1910	RUN 432 • 432 •
Q= PO= ALPHA 3.94 2.93 1.92	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269	06 T0= I CY 0.2888- 0.2660- 0.2216-	90. DEC	G.F RUN NO. CAT 0.2497 0.2419 0.2312	POJ/P 014030 CPB 0.0510 0.0509 0.0505	TS = 69125 CAF 0.1987 0.1910 0.1808	RUN 432 • 432 • 432 •
Q= PO= ALPHA 3.94 2.93 1.92 1.41	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246	CY 0.2888- 0.2660- 0.2216- 0.1958-	90. DEG	G.F RUN NO. CAT 0.2497 0.2419 0.2312 0.2364	POJ/P 01403 CPB 0.0510 0.0509 0.0505 0.0499	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864	RUN 432 • 432 • 432 • 432 •
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.91	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253	06 T0= I CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082-	90. DEC CR D. 0021 (0.0029 (0.0050 (0.0017 (0.0014 (G.F RUN NO. CAT 0.2497 0.2419 0.2312 0.2364 0.2384	POJ/P 014030 CPB 0.0510 0.0509 0.0505 0.0499 0.0496	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864 0.1888	RUN 432. 432. 432. 432. 432.
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.91	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214	06 T0= I CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706-	90. DEG	G.F RUN NO. CAT 0.2497 0.2419 0.2312 0.2364 0.2384	POJ/P 01403 CPB 0.0510 0.0509 0.0505 0.0499 0.0496 0.0493	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864 0.1888 0.1896	RUN 432. 432. 432. 432. 432. 432.
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.91 0.40 -0.11	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864 0.0390	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783 -0.3758 -0.0031	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214	CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706- 0.1267-	90. DEC	G.F RUN NO. CAT 0.2497 0.2419 0.2312 0.2364 0.2384 0.2389	POJ/P 01403 CPB 0.0510 0.0509 0.0505 0.0499 0.0493 0.0493	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864 0.1888 0.1896	RUN 432. 432. 432. 432. 432. 432. 432.
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.91 0.40 -0.11 -0.62	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864 0.0390 -0.0045	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783 -0.3758 -0.0031 0.4301	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214 -0.0169	CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706- 0.1267- 0.1433-	90. DEG CR D. 0021 (0. 0029 (0. 0017 (0. 0014 (0. 0062 (0. 0015 (CAT 0.2497 0.2312 0.2364 0.2384 0.2389 0.2349	POJ/P . 01403 . CPB 0.0510 0.0509 0.0509 0.0499 0.0493 0.0493 0.0491	TS = 69125 CAF 0.1987 0.1808 0.1864 0.1888 0.1896 0.1856	RUN 432. 432. 432. 432. 432. 432. 432. 432.
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.91 0.40 -0.11 -0.62 -1.13	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864 0.0390 -0.0045	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783 -0.3758 -0.0031 0.4301 0.8049	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214 -0.0169 -0.0181	CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706- 0.1267- 0.1433- 0.0977-	90. DEG CR D. 0021 (0. 0029 (0. 0017 (0. 0014 (0. 0062 (0. 0015 (0. 0015 (0. 0015 (0. 0015 (0. 0015 (0. 0026 (0.	CAT 0.2497 0.2419 0.2312 0.2364 0.2389 0.2349 0.2349 0.2326	POJ/P . 01403 . CPB 0.0510 0.0509 0.0505 0.0499 0.0496 0.0493 0.0491 0.0491	TS = 69125 CAF 0.1987 0.1808 0.1864 0.1888 0.1896 0.1856 0.1835	RUN 432. 432. 432. 432. 432. 432. 432. 432.
Q= PO= ALPHA 3.94 2.93 1.92 1.41 0.40 -0.11 -0.62 -1.13 -1.63	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864 0.0390 -0.0045 -0.0547 -0.0988	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783 -0.3758 -0.0031 0.8049 1.2535	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214 -0.0169 -0.0181 -0.0131	CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706- 0.1267- 0.1433- 0.0977- 0.1326- 0.0447-	90. DEG CR 0.0021 (0.0029 (0.0050 (0.0017 (0.0014 (0.0062 (0.0015 (0.0062 (0.0015 (0.0027 (0.0018 (0.0027 (0	CAT 0.2497 0.2419 0.2312 0.2364 0.2384 0.2389 0.2349 0.2336 0.2331 0.2338	POJ/P 01403 CPB 0.0510 0.0509 0.0505 0.0499 0.0493 0.0493 0.0491 0.0491	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864 0.1888 0.1896 0.1855 0.1835 0.1840 0.1819	RUN 432. 432. 432. 432. 432. 432. 432. 432.
Q= P0= ALPHA 3.94 2.93 1.92 1.41 0.91 0.40 -0.11 -0.62 -1.13 -1.63 -2.13 -3.14	3.77 PSI 400.0 CM CN 0.3960 0.2906 0.1909 0.1351 0.0864 0.0390 -0.0045 -0.0547 -0.0988 -0.1506	RE PER HG PTS= CM -3.4635 -2.5416 -1.6786 -1.1999 -0.7783 -0.3758 -0.0031 0.4301 0.4301 0.8049 1.2535 1.5764 2.4597	IN.= .48E .2659 PS CS -0.0344 -0.0318 -0.0269 -0.0246 -0.0253 -0.0214 -0.0169 -0.0181 -0.0169	CY 0.2888- 0.2660- 0.2216- 0.1958- 0.2082- 0.1706- 0.1267- 0.1433- 0.0977- 0.1326- 0.0447-	90. DEG CR 0.0021 (0.0029 (0.0050 (0.0017 (0.0015 (0.0026 (0.0026 (0.0026 (0.0026 (0.0026 (0.0027 (0.0027 (0.0028 (0.0033 (0.003 (0.003 (0.003 (0.003 (0.003 (0.003 (0.003 (0.003 (0.003 (0.003 (0.0	CAT 0.2497 0.2419 0.2312 0.2364 0.2384 0.2389 0.2349 0.2326 0.2331 0.2338	POJ/P 01403 CPB 0.0510 0.0509 0.0505 0.0499 0.0493 0.0491 0.0491 0.0491 0.0491	TS = 69125 CAF 0.1987 0.1910 0.1808 0.1864 0.1888 0.1896 0.1856 0.1846 0.1849	RUN 432. 432. 432. 432. 432. 432. 432. 432.

HOD	EL 946.2	CON	FIG. 3.00	O HACI	1 4.50	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .488	106 T0≃ 9	O. DEG.F	P0J/P1	S = 40).
P0=	400.0 CM	HG PTS=	.2659 PS	SI .	RUN NO.	. 014036	9126	
ALPHA	CN	СН	cs	CY	CR CAT	CP8	CAF	RUN
3.94	0.3829		-0.0459		0008 0.2504			433.
2.93			-0.0425		0009 0-2470			433.
1.92	0.1809		-0.0374		0014 0.2436			433.
1.40			-0.0368		0016 0.2429			433.
	0.0753		-0.0368		0006 0-2392			433.
0.39			-0.0355		0043 0-2411			433.
	-0.0165		-0.0295		0002 0-2386			433.
	-0.0616	_	-0.027	0.2102 0.		0.0490		433.
	-0.1069		-0.0216		0009 0.2366			433.
	-0.1606		-0.0274		0001 0.2374			433.
	-0.2072		-0.0260		0011 0-2364			433.
	-0.2983		-0.0135		0013 0.2386			433•
-4.15	-0.4033	3.4262	-0.0074	0.0372 0.	0003 0.2410	0.0496	0.1914	433.
	EL 946.2 3.77 PSI		FIG. 3.00 IN.= .486		1 4.50 10. DEG.F	= IH9	45. 'S = 100) .
Q=		RE PER	IN.= -486	06 TO= 9	00. DEG.F		'S = 100) .
Q=	3.77 PSI	RE PER	IN.= -486	06 TO= 9	00. DEG.F	F0J/P1	'S = 100). RUN
Q= PO= Alpha	3.77 PSI 400.0 CM	RE PER HG PTS= CH	IN.= .488	CY CY	RUN NO.	POJ/P1 014036 CPB	S = 100 9127 CAF	RUN
Q= PO= ALPHA 3.93	3.77 PSI 400.0 CM CN 0.3483	RE PER HG PTS= CH -3.0890	IN.= .486 .2659 PS CS -0.0771	06 TO= 9	RUN NO. CR CAT 0013 0-2610	POJ/P1 - 014036 - CP8 - 0.0504	S = 100 9127 CAF 0.2106	RUN 434.
Q= PO= ALPHA 3.93 2.93	3.77 PSI 400.0 CM	RE PER HG PTS= CH -3.0890 -2.2152	IN.= .486 .2659 PS CS -0.0771	CY 0.6185-0. 0.5873-0.	RUN NO. CR CAT .0013 0.2610	POJ/PT - 014036 - CPB - 0.0504 - 0.0506	S = 100 9127 CAF 0.2106 0.2114	RUN 434. 434.
Q= PO= ALPHA 3.93 2.93 1.91	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726	CY 0.6185-0. 0.5873-0. 0.5684 0.	RUN NO. CR CAT .0013 0-2610 0021 0-2620 .0022 0-2560	POJ/PT 014036 CPB 0.0504 0.0506 0.0504	S = 100 9127 CAF 0.2106 0.2114 0.2056	RUN 434 • 434 • 434 •
Q= PO= ALPHA 3.93 2.93 1.91 1.40	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0.	RUN NO. CR CAT .0013 0-2610 .0021 0-2620 .0022 0-2560 .0004 0-2579	POJ/PT 014036 CPB 0.0504 0.0506 0.0504 0.0504	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080	RUN 434 • 434 • 434 •
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5032	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539	POJ/PT 014036 CP8 0.0504 0.0506 0.0504 0.0499 0.0496	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080 0.2043	RUN 434. 434. 434. 434.
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917	RE PER HG PTS= CH -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539 0003 0-2530	POJ/PT 014036 CP8 0.0504 0.0506 0.0504 0.0499 0.0496	CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2036	RUN 434 • 434 • 434 •
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028 0.2804	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0602	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4608 0. 0.4118-0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539 0003 0-2530	POJ/PT 014036 CP8 0.0504 0.0506 0.0504 0.0499 0.0496 0.0493 0.0491	CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2036 0.2000	RUN 434. 434. 434. 434. 434.
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12 -0.63	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018 -0.0440	RE PER HG PTS= CH -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028 0.2804 0.6974	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0602 -0.0557	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4608 0. 0.4118-0. 0.4197-0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539 0003 0-2530 0-2491	POJ/PT 014036 CP8 0.0504 0.0506 0.0504 0.0499 0.0499 0.0491 0.0491	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2043 0.2036 0.2000 0.2023	RUN 434. 434. 434. 434. 434. 434.
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12 -0.63 -1.13	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018 -0.0440 -0.0927	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028 0.2804 0.6974 1.1187	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0602 -0.0557 -0.0564	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4608 0. 0.4118-0. 0.4127-0. 0.4320-0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539 0003 0-2530 0-2491 0010 0-2512	POJ/PT 014036 CP8 0.0504 0.0506 0.0506 0.0499 0.0499 0.0498 0.0498	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2036 0.2036 0.2000 0.2023 0.2014	RUN 434. 434. 434. 434. 434. 434. 434.
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12 -0.63 -1.13 -1.65	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018 -0.0440 -0.0927 -0.1414	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5034 0.2804 0.6974 1.1187 1.4468	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0602 -0.0557 -0.0564 -0.0571	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4118-0. 0.4197-0. 0.4320-0. 0.3060-0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2530 0-2491 0010 0-2512 0052 0-2503	POJ/PT 014036 CP8 0.0504 0.0506 0.0504 0.0499 0.0499 0.0493 0.0498 0.0489 0.0488	CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2043 0.2036 0.2000 0.2023 0.2014	RUN 434. 434. 434. 434. 434. 434. 434.
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12 -0.63 -1.13 -1.65 -2.14 -3.15	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018 -0.0440 -0.0927 -0.1414 -0.1811 -0.2271 -0.3273	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028 0.2804 0.6974 1.1187 1.4468 1.8492	IN.= .486 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0602 -0.0557 -0.0564 -0.0571 -0.0444	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4118-0. 0.4118-0. 0.4320-0. 0.3060-0. 0.3053-0.	RUN NO. CR CAT 0013 0-2610 0021 0-2620 0022 0-2560 0004 0-2579 0019 0-2539 0003 0-2530 6-2491 0010 0-2512 0052 0-2503 0018 0-2535	CPB 0.0504 0.0506 0.0504 0.0499 0.0496 0.0493 0.0489 0.0488 0.0488	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2036 0.2000 0.2023 0.2023 0.2024 0.2047 0.2047	RUN 434. 434. 434. 434. 434. 434. 434. 434
Q= P0= ALPHA 3.93 2.93 1.91 1.40 0.89 0.39 -0.12 -0.63 -1.13 -1.65 -2.14 -3.15	3.77 PSI 400.0 CM CN 0.3483 0.2481 0.1442 0.0917 0.0484 0.0018 -0.0440 -0.0927 -0.1414 -0.1811 -0.2271	RE PER HG PTS= CM -3.0890 -2.2152 -1.3275 -0.8644 -0.5032 -0.1028 0.2604 0.6974 1.1187 1.4468 1.8492 2.7146	IN.= .488 .2659 PS CS -0.0771 -0.0737 -0.0726 -0.0696 -0.0594 -0.0557 -0.0564 -0.0571 -0.0444 -0.0437	CY 0.6185-0. 0.5873-0. 0.5684 0. 0.5533 0. 0.4520 0. 0.4608 0. 0.4118-0. 0.4197-0. 0.43060-0. 0.3063-0. 0.2814-0.	RUN NO. CR CAT .0013 0.2610 .0021 0.2620 .0022 0.2560 .0004 0.2579 .0019 0.2539 .0010 0.2512 .0052 0.2503 .018 0.2535 .0016 0.2495	POJ/PT 014036 CPB 0.0504 0.0506 0.0504 0.0499 0.0496 0.0493 0.0491 0.0489 0.0488 0.0488	S = 100 9127 CAF 0.2106 0.2114 0.2056 0.2080 0.2043 0.2043 0.2043 0.2036 0.2023 0.2023 0.2014 0.2047 0.2007 0.2030	RUN 434 • 434 • 434 • 434 • 434 • 434 • 434 • 434 •

MO	DEL 94	6.2	CON	FIG.	3.000	ĸ	ACH 4.5	0	PHI =	90-	
Q=	3.77	PSI R	E PER	IN.=	.48E0	6 T0±	90. D	EG.F	POJ/P	rs =	•
PO	= 400.	O CMHG	PTS≈	. 26	59 PSI			RUN NO	01403	69128	
ALPHA	. CN	1	CM	ε:	s	CY,	ÇR	CAT	CPB	CAF	RUN
4.06	0.40	64 -3	.5224	-0.0	001	-0.0064	0.0006	0.2658	0.0500	0.2359	435.
3.06	0.30	37 -2	.6228	0.0	004	-0.0101	-0.	0.2630	0.0500	0.2129	435.
2.04	0.19	85 -1	.7059	0.0	010	-0.0148	0.0019	0.2572	0.0499	0.2073	3 435.
1.53	0.14	40 -1	.2361	-0.0	053	0.0513	-0.0001	₹-2581	0.0498	0.2084	435.
1.02	0.09	49 -0	.8124	-0.0	043	0.0403	0.0006	0-2590	0.0496	0.2094	435.
0.51	0.04	58 ~0	-3922	0.0	025	-0.0292			0.0494		
0.01	0.00	68 -0	.0540	-0.0				0.2491			
	-0.04		.4085					0.2527			
	-0.09			-0.0				0.2463			
	-0.14			-0.0				0-2496			
	-0.19			-0.0				0.2554			
	-0.29			-0.0				0.2542			
-4.03	-0.39	67 3	.4321	0.0	045	-0.0416	-0.0010	0.2496	0.0498	0.1998	3 435.
	DEL 94				3.000		ACH 4.5		PH[=	90. rs =	10.
Q=	3.77	PSI R	E PER	IN.=	.48E0			EG•F	POJ/P	rs =	10.
Q=	3.77		E PER	IN.=				EG•F	_	rs =	10-
Q=	3.77 = 400.	PSI R	E PER	IN.=	.48E0			EG•F	POJ/P	rs =	10. RUN
Q= P0	3.77 = 400.	PSI R	E PER PTS=	IN.=	.48E0 59 PSI	6 TO=	90. D	EG.F RUN NO.	POJ/P1 014030 CP8	rs = 59129 Caf	RUN
Q= PO ALPHA	3.77 = 400. CN	PSI R 0 CMHG 62 -3	E PER PTS= CM .5225	IN.= .26	•48E0 59 PSI S	6 TO= CY 0.0573	90. Di	EG.F RUN NO. CAT 0.2589	POJ/P1 - 014036 - CP8 - 0-0498	rs = 59129 CAF 0-2091	RUN 436.
Q= PO ALPHA 4.06	3.77 = 400. CN 0.40 0.39	PSI R 0 CMHG 62 -3 12 -2	E PER PTS= CM .5225	IN.= .26: C: -0.00	.48E0 59 PSI S 088	6 TO= CY 0.0573 0.0423	90. Di	EG.F RUN NO. CAT	POJ/P1 - 014036 - CP8 - 0.0498 - 0.0499	CAF 0.2091	RUN 436. 436.
Q= PO ALPHA 4.06 3.06	3.77 = 400. CN 0.40 0.39 0.19	PSI R 0 CMHG 62 -3 12 -2 68 -1	PTS= CM .5225 .5995	IN.= -269 -0.00 -0.00	.48E0 59 PSI S 088 069	CY 0.0573 0.0423 0.0386	90. Di CR 0.0013 0.0013 -0.0006	EG.F RUN NO. CAT 0.2589 2.2588	POJ/P1 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0499	CAF 0.2091 0.2089	RUN 436. 436. 436.
Q= PO ALPHA 4.06 3.06 2.05	3.77 = 400. CN 0.40 0.30 0.19 0.14	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1	E PER PTS= CH -5225 -5995 -6909	IN.= -269 -0.00 -0.00 -0.00	•48E0 59 PSI S 088 069 064 153	CY 0.0573 0.0423 0.0386 0.1308	90. Di CR 0.0013 0.0013 -0.0006	EG.F RUN NO. CAT 0.2589 0.2588 0.2545	POJ/P1 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497	CAF 0.2091 0.2091 0.2089 0.2047	RUN 436. 436. 436. 436.
Q= PO ALPHA 4.06 3.06 2.05 1.53	3.77 = 400. CN 0.40 0.39 0.19 0.14 0.09	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0	E PER PTS= CM .5225 .5995 .6909 .2279 .7989	IN.= -269 -0.00 -0.00 -0.00 -0.00	•48E0 59 PSI S 088 069 064 153 129	CY 0.0573 0.0423 0.0386 0.1308- 0.1087-	90. D	CAT 0.2589 7.2588 0.2545 0.2511	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0495	CAF 0.2091 0.2089 0.2047 0.2015	RUN 436. 436. 436. 436. 436.
Q= PO ALPHA 4.06 3.06 2.05 1.53 1.01	3.77 = 400. CN 0.40 0.39 0.19 0.14 0.09	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 56 -0	E PER PTS= CH .5225 .5995 .6909 .2279 .7989	IN.= -26	.48E0 59 PSI S 088 069 064 153 129	CY 0.0573 0.0423 0.0386 0.1308 0.1087 0.1119 0.0720	90. D CR 0.0013 0.0013 -0.0006 -0.0013 -0.0006	CAT 0.2589 0.2589 0.2545 0.2511 0.2520 0.2573 0.2522	POJ/P7 014030 CP8 0.0498 0.0499 0.0497 0.0495 0.0493 0.0492	CAF 0.2091 0.2081 0.2047 0.2047 0.2015 0.2025 0.2080	RUN 436. 436. 436. 436. 436. 436. 436.
Q= P0 ALPHA 4.06 3.06 2.05 1.53 1.01 0.51	3.77 = 400. CN 0.40 0.39 0.19 0.14 0.09	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 56 -0 74 -0	E PER PTS= CM .5225 .5995 .6909 .2279 .7989 .3921 .0604	IN.= -26: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	.48E0 59 PSI S 088 069 064 153 129 133 094	CY 0.0573 0.0423 0.0386 0.1308 0.1087 0.1119 0.0720 0.1099	90. D CR 0.0013 0.0013 -0.0006 -0.0013 -0.0006 -0.0011 -0.0018	CAT 0.2589	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0495 - 0.0493 - 0.0492	CAF 0.2091 0.2080 0.2047 0.2015 0.2025 0.2080 0.2030	RUN 436. 436. 436. 436. 436. 436. 436. 436.
Q= P0 ALPHA 4.06 3.06 2.05 1.53 1.01 0.51 -0.50 -1.00	3.77 = 400. CN 0.40 0.39 0.19 0.14 0.09 0.04 0.00 -0.04	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 56 -0 74 -0 79 0 55 0	E PER PTS= CM .5225 .5959 .2279 .2279 .3921 .0604 .4093 .8178	IN.= -26 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	.48E0 59 PSI S 088 069 064 153 129 133 094 126	CY 0.0573 0.0423 0.0386 0.1308- 0.1119- 0.0720- 0.10990.0176	90. D CR 0.0013 0.0013 -0.0001 -0.0013 -0.0006 -0.0011 -0.0018 0.0002	CAT 0.2589 0.2588 0.2545 0.2510 0.2573 0.2522 0.2457 0.2478	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0495 - 0.0492 - 0.0491	CAF 0.2091 0.2089 0.2047 0.2015 0.2025 0.2030 0.1965	RUN 436. 436. 436. 436. 436. 436. 436. 436.
Q= P0 ALPHA 4.06 3.06 2.05 1.53 1.01 0.51 -0.50 -1.51	3.77 = 400. CN 0.40 0.30 0.19 0.14 0.09 -0.04 -0.09 -0.14	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 56 -0 74 -0 79 0 55 0	E PER PTS= CM .5225 .5995 .2279 .2279 .3921 .0604 .4093 .8178 .2449	IN.= -26 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	.48E0 59 PSI S 088 069 064 153 129 133 094 126 001	CY 0.0573 0.0423 0.0386 0.1308 0.1308 0.1087 0.1119 0.0720 0.1099 -0.0176 0.0149	90. D CR 0.0013 0.0013 -0.0001 -0.0013 -0.0016 -0.0018 0.0002 -0.0042	CAT 0.2589 7.2588 0.2545 0.2511 0.2521 0.2573 0.2522 0.2457 0.2478	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0493 - 0.0492 - 0.0492 - 0.0492	CAF 0.2091 0.2089 0.2047 0.2025 0.2025 0.2030 0.1965 0.1987	RUN 436. 436. 436. 436. 436. 436. 436. 436.
Q= P0 ALPHA 4.06 3.06 2.05 1.53 1.01 0.51 0.51 0.51 -0.50 -1.51 -2.01	3.77 = 400. 0.40 0.30 0.19 0.14 0.09 0.04 0.00 -0.04 -0.09	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 74 -0 79 0 55 0 53 1	E PER PTS= CM .5225 .5995 .5909 .2279 .7989 .3921 .0604 .4093 .8178 .2449	IN.= -26: -0.0(-0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0: -0.0:	•48E0 59 PSI S 0888 069 064 153 129 133 094 126 001	CY 0.0573 0.0423 0.0386 0.1308 0.1087 0.1119 0.0720 0.1099 -0.0176 0.0149 -0.0233	90. Di CR 0.0013 0.0013 -0.0001 -0.0013 -0.0016 -0.0018 0.0002 -0.0042 -0.0016	CAT 0.2589 7.2588 0.2545 0.2511 0.2520 0.2573 0.2522 0.2457 0.2443 0.2443	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0495 - 0.0492 - 0.0491 - 0.0492 - 0.0493	CAF 0.2091 0.2089 0.2047 0.2015 0.2025 0.2080 0.1987 0.1958	RUN 436. 436. 436. 436. 436. 436. 436. 436.
PO ALPHA 4.06 3.06 2.05 1.53 1.01 0.51 0.50 -1.50 -1.51 -2.01 -3.03	3.77 = 400. CN 0.40 0.30 0.19 0.14 0.09 -0.04 -0.09 -0.14	PSI R 0 CMHG 62 -3 12 -2 68 -1 30 -1 32 -0 56 -0 74 -0 79 0 55 0 53 1 13 1	E PER PTS= CM .5225 .5995 .2279 .7989 .3921 .0604 .4018 .2449 .6424	IN.= -26 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00 -0.00	•48E0 59 PSI S 088 069 064 153 129 133 094 1001 034 006	CY 0.0573 0.0423 0.0386 0.1308 0.1087 0.1119 0.0720 0.1099 -0.0176 0.0149 -0.0233 -0.0120	90. Di CR 0.0013 -0.0013 -0.0001 -0.0013 -0.0016 -0.0012 -0.0016 -0.0002 -0.0042 -0.0016	CAT 0.2589 7.2588 0.2545 0.2511 0.2521 0.2573 0.2522 0.2457 0.2478	POJ/P7 - 014036 - CP8 - 0.0498 - 0.0499 - 0.0497 - 0.0495 - 0.0492 - 0.0492 - 0.0492 - 0.0493 - 0.0493 - 0.0495	CAF 0.2091 0.2089 0.2047 0.2015 0.2025 0.2080 0.1965 0.1958 0.1958	RUN 436. 436. 436. 436. 436. 436. 436. 436.

MODEL 946.2	CONF	IG. 3.000	, MACH	4.50	PHI =	90.	
Q= 3.77 PS1	RE PER	IN.= .4890	5 TO= 90	. DEG.F	P9J/PT	S → 20.	
PO= 400.0 CM	HG PTS=	.2659 PSI		RUN NO	014036	\$130	
ALPHA CN	CM	cs	CY C	R CAT	CPB	CAF	RUN
4.06 0.4083	-3.5406	-0.0146	0.0944 0.0	020 0.2577	0.0499	0.2078	437.
3.06 0.3049	-2.6324	-0.0141	0.0905 0.0	001 0.2533	0.0500	0-2033	437.
2.04 0.1990	-1.7087	-0.0136		001 0.2505			437•
1.53 0.1444	-1.2393			007 9.2514			437.
1.02 0-0961	-0.8253			001 0.2507			437.
0.51 0.0470	-0.4035			018 0.2472			437.
0.0065	-0.0501			022 0.2495			437.
-0.50 -0.0450		-0.0213		029 0.2447			437.
-1.01 -0.0964	0.8280			030 0.2499			437.
-1.51 -0.1432		-0.0164		041 0.2492			437 •
-2.01 -0.1884	1.6193			053 0.2455			437.
-3.02 -0.2904		-0.0077		065 0.2441			437.
-4.03 -0.3970	3.4379	-0.0029	-0.0007-0.0	028 0.2455	0.0498	0.1321	437.
MODEL 946.2 Q= 3.77 PSI	CONF RE PER	IG. 3.000 IN.= .48E0			= 1H9	90. [S = \ 40.	
	RE PER			. DEG.F RUN NO.		rs = \\ 40.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90	. DEG.F	P0J/P1	rs = \\ 40.	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN	RE PER HG PTS=	IN.# .48E00 .2659 PSI	6 TO= 90	. DEG.F	POJ/P1 014036 CP8	S = 40. 9131 CAF	
Q= 3.77 PSI Pd= 400.0 CM	RE PER	IN.# .48E00 .2659 PSI CS -0.0290	6 TO= 90 CY C 0.1999 G.0	DEG.F RUN NO. R CAT	POJ/P1 014036 CP8 0.0497	S = 40. 9131 CAF 0.2056	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080	RE PER HG PTS= CM -3.5401	IN.# .48E00 .2659 PSI CS -0.0290 -0.0285	CY C 0.1999 G.0 0.1969 0.0	. DEG.F RUN NO. R CAT	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498	S = 40. 9131 CAF 0.2056 0.2100	KUN 438∙•
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053	RE PER HG PTS= CM -3.5401 -2.6370	.2659 PSI CS -0.0290 -0.0285 -0.0261	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0	. DEG.F RUN NO. R CAT 039 0.2553 033 0.2558	POJ/PT 014036 CP8 0.0497 0.0498 0.0497	S = 40. S9131 CAF 0.2056 0.2100 0.2087	KUN 438. 438.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001	RE PER HG PTS= CH -3.5401 -2.6370 -1.7202	CS -0.0290 -0.0285 -0.0261 -0.0170	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0	. DEG.F RUN NO. R CAT 039 0.2553 033 0.2558 039 0.2585	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0497 - 0.0495	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008	438. 438. 438.
Q= 3.77 PSI PD= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464	RE PER HG PTS= CM -3.5401 -2.6370 -1.7202 -1.2585	CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0	. DEG.F RUN NO. R CAT 039 0.2553 033 0.2558 039 0.2585 027 0.2503	POJ/PT 014036 CP8 0.0497 0.0498 0.0497 0.0495 0.0495	CAF 0.2056 0.2100 0.2087 0.2008 0.2050	438. 438. 438. 438.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.02 0.0965	RE PER HG PTS= CM -3.5401 -2.6370 -1.7202 -1.2585 -0.8283	CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0	RUN NO. R CAT 039 0.2553 033 0.2598 039 0.2585 027 0.2503 027 0.2542	POJ/PT 014036 CP8 0.0497 0.0498 0.0497 0.0495 0.0490	CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077	438. 438. 438. 438. 438.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.02 0.0965 0.51 0.0482	RE PER HG PTS= CM -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412	CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0	RUN NO. R CAT 039 0.2553 033 0.2558 039 0.2585 027 0.2503 027 0.2542 008 0.2567	POJ/PT 014036 CP8 0.0497 0.0498 0.0497 0.0495 0.0490 0.0490	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 9.2024	RUN 438. 438. 438. 438. 438.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.02 0.0965 0.51 0.0482 0.01 0.0054	RE PER HG PTS= CH -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412 0.4014	CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351 -0.0212	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0 0.2328 0.0	RUN NO. R CAT 039 0.2553 033 0.2558 039 0.2585 027 0.2503 027 0.2542 008 0.2567 003 0.2515	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0495 - 0.0490 - 0.0490 - 0.0490 - 0.0490	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 0.2024 0.2006	RUN 438. 438. 438. 438. 438. 438.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.62 0.0965 0.51 0.0482 0.01 0.0054 -0.50 -0.0469	RE PER HG PTS= CH -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412 0.4014 0.8104	IN.# .48E00 .2659 PSI CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351 -0.0212 -0.0315	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0 0.2328 0.0 0.1795-0.0	RUN NO. R CAT 039 0.2553 033 0.2558 039 0.2585 027 0.2503 027 0.2542 008 0.2567 003 0.2515 009 0.2496	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0495 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0489	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 9.2024 0.2006 0.1999	438. 438. 438. 438. 438. 438. 438.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.62 0.0965 0.51 0.0482 0.01 0.0054 -0.50 -0.0469 -1.00 -0.0944	RE PER HG PTS= CM -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412 0.4014 0.8104 1.2535	IN.# .48E00 .2659 PSI CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351 -0.0212 -0.0315 -0.0263	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0 0.2328 0.0 0.1795-0.0 0.0693-0.0 0.2091-0.0	R CAT 039 0.2553 033 0.2598 039 0.2585 027 0.2503 027 0.2542 008 0.2567 003 0.2515 009 0.2486 015 0.2486 015 0.2486	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0495 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 0.2024 0.2006 0.1999 0.1946 0.2059	438. 438. 438. 438. 438. 438. 438. 438.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.02 0.0965 0.51 0.0482 0.01 0.0054 -0.50 -0.0469 -1.00 -0.0944 -1.51 -0.1459	RE PER CH -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412 0.4014 0.8104 1.2535 1.6498	IN.# .48E00 .2659 PSI CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351 -0.0212 -0.0315 -0.0263 -0.0263	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0 0.1795-0.0 0.0693-0.0 0.2091-0.0 0.1205 0.0	RUN NO. R CAT 039 0.2553 033 0.2598 039 0.2585 027 0.2503 027 0.2542 008 0.2567 003 0.2515 009 0.2486 015 0.2486 015 0.2436 015 0.2550 004 0.2505	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0495 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 0.2024 0.2006 0.1999 0.1946 0.2059 0.2012	438. 438. 438. 438. 438. 438. 438. 438.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 4.06 0.4080 3.06 0.3053 2.04 0.2001 1.53 0.1464 1.02 0.0965 0.51 0.0462 0.01 0.0054 -0.50 -0.0469 -1.00 -0.0944 -1.51 -0.1459 -2.01 -0.1918	RE PER CH -3.5401 -2.6370 -1.7202 -1.2585 -0.8283 -0.4146 -0.0412 0.4014 0.8104 1.2535 1.6498 2.5207	CS -0.0290 -0.0285 -0.0261 -0.0170 -0.0275 -0.0351 -0.0212 -0.0315 -0.0263 -0.0263 -0.0265	CY C 0.1999 G.0 0.1969 0.0 0.1931 0.0 0.0830 0.0 0.1916 0.0 0.2677 0.0 0.1295 0.0 0.1795-0.0 0.0693-0.0 0.2091-0.0 0.1205 0.0	R CAT 039 0.2553 033 0.2598 039 0.2585 027 0.2503 027 0.2542 008 0.2567 003 0.2515 009 0.2486 015 0.2486 015 0.2486	POJ/PT - 014036 - CP8 - 0.0497 - 0.0498 - 0.0495 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490 - 0.0490	S = 40. 9131 CAF 0.2056 0.2100 0.2087 0.2008 0.2050 0.2077 0.2024 0.2006 0.1999 0.1946 0.2059 0.2012	438. 438. 438. 438. 438. 438. 438. 438.

1	HOD	EL 946.2	CON	FIG. 3.000	M	ACH 4.51	0	PHI =	90.	
1	Q=	3.77 PSI	RE PER	IN.= .48E0	6 10=	90. DI	EG.F	P0J/P	7S = :	100.
1	P0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO.	01403	69132	
ALP	НА	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.1	06	0.4080	-3.5385	-0.0698	0.5105	0.0047	0.2672	0.0494	0.217	8 439.
3.6	96	0.3044	-2.6279	-0:0678	0.4886	0:0048	0.2555	0.0496	0.205	9 439.
2.	04	0.2008	-1.7293	-0.0674			0.2645			
1.5	53	0.1424	-1,2215	-0.0664	0.4744	0.0016	0.2564	0.0490	G.207	4 439.
1.0	_	0.0941		-0.0697			0.2544			
0.	51	0.0457		-0.0729			0.2480			
	01			-0.0604			0.2502			
		-0.0485		-0.0579			0.2509			
		-9.0992		-0.0714			0.2594			
	_	-0.1467		-0.0745			0.2559			
		-0.1973		-0.0706			0.2478			
		-0.2947		-0.0630			0.2581			
-4.	03	-0.4020	3.4829	-0.0567	0.4072	-0.0020	0.2535	0.0499	0.203	6 439.
		EL 946.2		FIG. 1.000		ACH 4.50		PHI =	•	
(Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	G.F	601/b.	TS =	•
1	P0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO.	01403	69133	
ALPI	ΗA	CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.0	9	0.3155	-2.4467	-0.0083	0.0700-	-0.0054	0.2013	0-0512	0-150	440.
	9	0.2361		-0.0084			0.1950			
-	7	0.1550		-0.0069			0.1904			
1 - 5	56	0.1100	-0.8303	-0.0068	0.0560-	-0.0008	0.1964	0.0505	0.3460	440.
1.0	94	0.0780	-0.5990	-0.0053	0.0409-	-0.0006	0.1903	0.0503	0.1400	440.
0.5		0.0403		-0.0053			0.1916			
0.0	03	-0.0017		-0.0061			0.1915			
-0.4	48	-0.0294	0.2095	-0.0062			0.1868			
-0.9	98	-0.0714		-0.0063	0.0509-	-0.0031	0.1910	0.0499	0.1411	L 440.
	_	-0.1091	0.8336	-0.0063			0.1909			
-1.9	98	-0.1395		-0.0056			0.1875			
	_	-0.2192		-0.0049			0.1873			
-4.0	01	-0.3032	2.3529	-0.0003	0.0029-	-0.0010	0.1900	0.0504	0.1396	440.

THE PROPERTY OF THE PROPERTY O

MODEL 946.2	CONF	FIG000	HA	CH 4.5	0	PHI =	•	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 10=	90. DI	EG.F	P0J/P	TS =	10.
PO= 400.0 C	MHG PTS=	.2659 PSI			RUN NO	. 01403	69134	
ALPHA CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
4.09 0.3068	-2.3896	-0.0065	0.0522-	0.0022	0.2017	0.0516	0.1501	441.
3.09 0.2258	-1.7459	-0.0066	0.0530-	0.0019	0.1970	0.0515	0-1454	441.
2.07 0.1505	-1.1630	-0.0059	0.0473-	0.0016	0.1922	0.0511	0.1411	441.
1.56 0.1055	-0.8158		0.0336-					
1.05 0.0663	-0.5089		0.0346-					
0.54 0.0344	~0.2819		0.0281-					
0.03 -0.0076		-0.0036	0.0289-					
-0.48 -0.0338		-0.0037	0.0317-					
-0.99 -0.0702		-0.0029	0.0236-					
-1.49 -0.1107		-0.0022	0.0181-					
-2.01 -0.1498		-0.0022	0.0181-					
-3.01 -0.2237	1-6994		0.0123~					
-4.01 -0.3048	2.3442	0.0007	-0 •0052-	0.0016	0.1917	0.0502	0.1415	441.
MODEL 946.2 Q= 3.77 PSI	CONF	IG. 1.000		CH 4.50		PHI =	• rs =	20•
	RE PER	IN.= .48E0	6 TO=		EG•F		rs =	20•
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO=		EG•F	P0J/P	rs =	20• RUN
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER MHG PŢS= CM	IN.= .48E0 .2659 PS1 CS	6 TO=	90. DE	EG•F RUN NO. CAT	POJ/P1 014936 CPB	rs = 69135 Caf	RUN
Q= 3.77 PSI PO= 400.0 C	RE PER	IN.= .48E0 .2659 PS1 CS ~0.0102	6 T0=	90. DE CR 0.0021	EG.F RUN NO. CAT 0.2036	POJ/P1 014930 CPB 0.0515	TS = 69135 CAF 0.1521	RUN 442.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.08 0.2981	RE PER MHG PTS= CM -2.3264	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087	6 TO= CY 0.0817~	90. DE	EG.F RUN NO. CAT 0.2036 0.2047	POJ/P1 . 014036 CPB 9.0515 0.0515	TS = 69135 CAF 0.1521 0.1532	RUN 442. 442.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.08 0.2981 3.08 0.2184	RE PER MHG PTS= CH -2.3264 -1.6959	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080	6 TO= CY 0.0817~	90. DE	EG.F RUN NO. CAT 0.2036 0.2047 0.1985	POJ/P1 . 014936 . CPB 0.0515 0.0515 0.0512	FS = 69135 CAF 0.1521 0.1532 0.1473	RUN 442 • 442 •
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.0071	CY 0.0817- 0.0695- 0.0641-	90. DE CR 0.0021 0.0018 0.0046 0.0013	CAT 0.2036 0.2047 0.1985 0.1957	POJ/P1 . 014936 . CPB 0.0515 0.0515 0.0512 0.0508	FS = 69135 CAF 0.1521 0.1532 0.1473 0.1449	RUN 442 • 442 • 442 •
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.0071 -0.0064	CY 0.0817~ 0.0695~ 0.0641~ 0.0586~	90. DE	CAT 0.2036 0.2047 0.1985 0.1957 0.1942	POJ/P1 . 014036 CPB 0.0515 0.0515 0.0512 0.0508 0.0506	TS = 69135 CAF 0.1521 0.1532 0.1473 0.1449 0.1436	RUN 442. 442. 442. 442.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.0071 -0.0064	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0513-	90. DE	CAT 0.2036 0.2047 0.1985 0.1957 0.1942 0.1938 0.1937	POJ/P1 014036 CPB 0.0515 0.0515 0.0512 0.0508 0.0506 0.0504	FS = 69135 CAF 0.1521 0.1523 0.1473 0.1449 0.1436 0.1434	RUN 442 • 442 • 442 • 442 • 442 • 442 •
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149 -0.48 -0.0440	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826 0.1059 0.3077	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.6071 -0.0064 -0.0041 -0.0057 -0.0058	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0513- 0.0331- 0.0473-	90. DE CR 0.0021 0.0018 0.0046 0.0013 0.0037 0.0003 0.0027	CAT 0.2036 0.2047 0.1985 0.1957 0.1942 0.1938 0.1937 0.1934	POJ/P1 . 014036 CPB 0.0515 0.0515 0.0512 0.0508 0.0506 0.0504 0.0502 0.0501	TS = 69135 CAF 0.1521 0.1532 0.1473 0.1449 0.1436 0.1435 0.1435	RUN 442. 442. 442. 442. 442. 442. 442.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149 -0.48 -0.0440 -0.99 -0.0846	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826 0.1059 0.3077 0.5257	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.6071 -0.0064 -0.0041 -0.0057 -0.0058 -0.0043	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0513- 0.0331- 0.0473- 0.0467- 0.0349-	90. DE CR 0.0021 0.0018 0.0046 0.0037 0.0037 0.0027 0.0024	CAT 0.2036 0.2047 0.1985 0.1957 0.1942 0.1938 0.1937 0.1934 0.1918	POJ/P1 . 014036 . CPB 0.0515 0.0515 0.0518 0.0508 0.0506 0.0504 0.0502 0.0502	CAF 0.1521 0.1532 0.1473 0.1449 0.1434 0.1435 0.1435 0.1435	RUN 442. 442. 442. 442. 442. 442. 442.
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149 -0.48 -0.0440 -0.99 -0.0846 -1.49 -0.1094	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826 0.1059 0.3077 0.6257 0.7838	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.6071 -0.0064 -0.0057 -0.0058 -0.0058 -0.0043 -0.0043	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0531- 0.0473- 0.0467- 0.0349- 0.0347	90. DE CR 0.0021 0.0018 0.0046 0.0013 0.0037 0.00027 0.00227 0.0024	CAT 0.2036 0.2047 0.1985 0.1957 0.1938 0.1937 0.1934 0.1918	POJ/P1 . 014936 . CPB 9.0515 0.0515 0.0512 0.0506 0.0506 0.0504 0.0502 0.0502 0.0502	CAF 0.1521 0.1532 0.1473 0.1446 0.1434 0.1435 0.1434 0.1436	RUN 442. 442. 442. 442. 442. 442. 442. 442
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149 -0.48 -0.0440 -0.99 -0.0846 -1.49 -0.1094 -1.99 -0.1456	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826 0.1059 0.3077 0.4257 0.7838 1.0695	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.0071 -0.0064 -0.0057 -0.0058 -0.0043 -0.0043 -0.0043	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0513- 0.0473- 0.0473- 0.0349- 0.0347	90. DE CR 0.0021 0.0018 0.0046 0.0037 0.0037 0.0027 0.0024 0.0003	CAT 0.2036 0.2047 0.1985 0.1957 0.1942 0.1938 0.1937 0.1934 0.1943 0.1943	POJ/PT - 014036 - CPB - 0.0515 - 0.0515 - 0.0512 - 0.0508 - 0.0504 - 0.0502 - 0.0502 - 0.0502 - 0.0502	CAF 0.1521 0.1532 0.1473 0.1449 0.1436 0.1435 0.1436 0.1436 0.1436	RUN 442. 442. 442. 442. 442. 442. 442. 442
Q= 3.77 PSI P0= 400.0 CM ALPHA CN 4.08 0.2981 3.08 0.2184 2.07 0.1416 1.55 0.0982 1.04 0.0562 0.53 0.0314 0.02 -0.0149 -0.48 -0.0440 -0.99 -0.0846 -1.49 -0.1094	RE PER MHG PTS= CM -2.3264 -1.6959 -1.1042 -0.7730 -0.4345 -0.2826 0.1059 0.3077 0.6257 0.7838 1.0695 1.6910	IN.= .48E0 .2659 PSI CS -0.0102 -0.0087 -0.0080 -0.6071 -0.0064 -0.0057 -0.0058 -0.0058 -0.0043 -0.0043	CY 0.0817- 0.0695- 0.0641- 0.0586- 0.0531- 0.0473- 0.0467- 0.0349- 0.0347	90. DE CR 0.0021 0.0018 0.0046 0.0037 0.0037 0.0027 0.0024 0.0003 0.0033 0.0030	CAT 0.2036 0.2047 0.1985 0.1957 0.1942 0.1938 0.1937 0.1934 0.1943 0.1940 0.1908	POJ/PT - 014036 - CPB - 0.0515 - 0.0515 - 0.0512 - 0.0508 - 0.0504 - 0.0502 - 0.0502 - 0.0502 - 0.0501 - 0.0502	TS = 69135 CAF 0.1521 0.1532 0.1473 0.1449 0.1436 0.1436 0.1436 0.1416 0.1441 0.1449 0.1440	RUN 442. 442. 442. 442. 442. 442. 442. 442

HODEL 946.	2 CONFI	G. 1.000	МА	CH 4.50)	PHI =	•	
Q= 3.77 PS	I RE PER I	N.= .48E06	T0=	90. Da	GcF	POJ/P	TS = 40.	
PO= 400.0	CMHG PTS=	.2659 PSI			RUN NO	01403	69136	
ALPHA CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.08 0.2864	-2.2454 -	0.0091	0-0762-	0.0027	0.2100	0.0515	0-1585	443.
3.08 0.2069					0.2038			443.
2.06 0.1300					0.2021			443.
1.55 0.0793					0.2008			443.
1.04 0.0459					0.1991			443.
0.53 0.0197					0.1943			443.
0.02 -0.0209					0.2016			443.
-0.49 -0.0557					0.1954			443.
-0.99 -0.0847					0.1936			443.
-1.50 -0.1339					0.1937			443.
-1.99 -0.1544					0.1930			443.
-3.00 -0.2297					0.1911			443.
-4.02 -0.3209					0-1941			443.
NODĒL 946.	2 CONFI	G. 1.000	МА	CH 4.50)	PKI =	•	
Q= 3.77 PS	I RE PER I	N.= .48E06	T0=	90. DE	G.F	POJ/P1	rs = 100.	
PO= 400.0	CHHG PTS=	.2659 PSI			RUN NO.	01403	59137	
ALPHA CN	CM	CS	CY	CR	CAT	CPB	CAF	RUN
4.08 0.2399	-1.8833 -	0-0090 (0-0755-	0-0031	0.2162	0-0517	0-1646	444.
3.07 0.1617	-1.2681 -				0.2158			444.
2.06 0.0878					0.2096			444.
1.54 0.0400					0.2113			444.
1.03 0.0080					0.2080			444.
0.52 -0.0254					0.2048			444.
0.01 -0.0645					0.2077			444.
-0.49 -0.0893	0.6140 ~				0.2029			444.
-0.99 -0.1241	0.8761 ~				0.2055			444.
-1.50 -0.1632					0.2010			444.
-2.01 -0.1953					0.2007			444.
-3.01 -0.2720	2.0145 -				0.2003			444.
-4.03 -0.3574	2.6965				0.2016			444.

THE PARTY OF THE P

MOD	EL 946.2	CON	IG. 1.000	H	ACH 4.5	0	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	P0J/P1	rs =	•
90 -	400.0 CM	HG PTS=	.2659 PSI			RUN- NO	01403	59138	
ALPHA	CN	CM	cs	CY	CR	CAT	CPB	CAF	RUN
4.13	0.3149	-2.4218	-0.0170	0.1376	0.0033	0.2169	0.0512	0.1657	445.
3.13	0.2347		-0.0170	0.1364	0.0027	0.2153	0.0515	0-1638	445.
2.11	0.1544	-1.1695	-0.0170	0.1362	0.0009	0.2110	0.0512	0.1598	445.
1.60	0.1129	-0.8506	-0.0166	0.1320	0.0012	0.2118	0.0508	0.1610	445.
1.08	0.0792	-0.6052	-0.0118	0.0865	0.0009	0.2110	0.0505	0.1605	445.
0.57	0.0441	-0.3451	-0.0116	0.0831	0.0032	0.2117	0.0503	0.1614	445.
0.07	0.0048	-0.0372	-0.0114	0.0876-	·0.0002	0.2050	0.0502	0.1549	445.
-0.44	-0.0323		-0.0154	0.1251-	-0.0005	0.2103	0.0502	0.1601	445.
-0.94	-0.0673	0.5121	-0.0153			0.2094			445.
	-0.1066	0.8121	-0.0171			0.2132			445.
-1.97	-0.1505	1.1599	-0.0225			0.2157			445.
	-0.2132	1.6209	-0.0094			0.2106			445.
-3.97	-0.2967	2.2774	-0.0082	0.0661	0.0019	0.2194	0.0511	0.1683	445.
	DEL 946.2		FIG. 1.000		ACH 4.50		PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. D	EG.F	POJ/P	rs = 10	0•
P0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO	01403	69139	
ALPHA	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.13	0.3085	-2.3772	-0.0209	0.1622	0.0027	0.2143	0.0518	0.1625	446.
3.12			-0.0184			0.2067			446.
2.11		-1.1682				0.2097			446.
1.59			~U.U.I.I.4						
									446.
	0.1086	-0.8261	-0.0174 -0.0206 -0.0188	0.1565	0.0013	0.2092	0.0511	0.1581	446. 446.
1.08	0.1086 0.0719	-0.8261 -0.5503	-0.0206	0.1565 0.1414	0.0013 0.0010	0.2092	0.0511	0.1581 0.1578	
1.08	0.1086 0.0719	-0.8261 -0.5503 -0.2586	-0.0206 -0.0188	0.1565 0.1414 0.1897	0.0013 0.0010 0.0007	0.2092 0.2084	0.0511 0.0507 0.0504	0.1581 0.1578 0.1559	446.
1.08 0.57 0.06	0.1086 0.0719 0.0338	-0.8261 -0.5503 -0.2586 -0.0520	-0.0206 -0.0188 -0.0238	0.1565 0.1414 0.1897 0.0703	0.0013 0.0010 0.0007 -0.0002	0.2092 0.2084 0.2064	0.0511 0.0507 0.0504 0.0503	0.1581 0.1578 0.1559 0.1564	446. 446.
1.08 0.57 0.06 -0.44	0.1086 0.0719 0.0338 0.0045	-0.8261 -0.5503 -0.2586 -0.0520 0.2660	-0.0206 -0.0188 -0.0238 -0.0114	0.1565 0.1414 0.1897 0.0703 0.1313	0.0013 0.0010 0.0007 -0.0002 0.0002	0.2092 0.2084 0.2064 0.2067	0.0511 0.0507 0.0504 0.0503 0.0503	0.1581 0.1578 0.1559 0.1564 0.1543	446. 446. 446.
1.08 0.57 0.06 -0.44 -0.94	0.1086 0.0719 0.0338 0.0045 -0.0361	-0.8261 -0.5503 -0.2586 -0.0520 0.2660 0.5222	-0.0206 -0.0188 -0.0238 -0.0114 -0.0178	0.1565 0.1414 0.1897 0.0703 0.1313 0.1050	0.0013 0.0010 0.0007 -0.0002 0.0002 -0.0026	0.2092 0.2084 0.2064 0.2067 0.2047	0.0511 0.0507 0.0504 0.0503 0.0503	0.1581 0.1578 0.1559 0.1564 0.1543 0.1579	446. 446. 446. 446. 446.
1.08 0.57 0.06 -0.44 -0.94 -1.45	0.1086 0.0719 0.0338 0.0045 -0.0361 -0.0702	-0.8261 -0.5503 -0.2586 -0.0520 0.2660 0.5222 0.7972	-0.0206 -0.0188 -0.0238 -0.0114 -0.0178 -0.0167	0.1565 0.1414 0.1897 0.0703 0.1313 0.1050 0.0866	0.0013 0.0010 0.0007 -0.0002 0.0002 -0.0026 0.0022	0.2092 0.2084 0.2064 0.2067 0.2047 0.2082	0.0511 0.0507 0.0504 0.0503 0.0503 0.0503	0.1581 0.1578 0.1559 0.1564 0.1543 0.1579 0.1601	446. 446. 446. 446.
1.08 0.57 0.06 -0.44 -0.94 -1.45 -1.95	0.1086 0.0719 0.0338 0.0045 -0.0361 -0.0702 -0.1070	-0.8261 -0.5503 -0.2586 -0.0520 0.2660 0.5222 0.7972 1.0297	-0.0206 -0.0188 -0.0238 -0.0114 -0.0178 -0.0167 -0.0128	0.1565 0.1414 0.1897 0.0703 0.1313 0.1050 0.0866 0.0913	0.0013 0.0010 0.0007 -0.0002 0.0002 -0.0026 0.0022 0.0013	0.2092 0.2084 0.2064 0.2067 0.2047 0.2082 0.2104	0.0511 0.0507 0.0504 0.0503 0.0503 0.0503 0.0503	0.1581 0.1578 0.1559 0.1564 0.1543 0.1579 0.1601 0.1562	446. 446. 446. 446. 446.

1	10D	EL 946.2	CON	FIG. 1.000	M	ACH 4.50	D	PHI =	45.	
()=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	POJ/P	TS =	20.
i	°0=	400.0 CM	HG PTS=	.2659 PSI			RUN NO	01403	69140	
ALP	łΑ	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.	13	0.3053	-2.361.6	-0.0260	0.1952	0.0028	0.2191	0.0519	0.1672	447.
3.		0.2271		-0.0241		0.0022				
2.1	11	0-1506	-1.1621	-0.0236	0.1685	0.0010	0.2042	0.0517	0.1525	
1.5	8	0.1065	-0.8226	-0.0247	0.1765	0.0014	0.2066	0.0511	0.1555	447.
1.0	8	0.0723	~0.5685	-0.0214	0.1470	6.0005	0.2043	0.0507	0.1535	447.
0.	57	0.0330	-0.2749	-0.0253	0.1767	0.0002	0.2023	0.0505	0.1518	447.
	-	0.0055	-0.0744	-0.0146		-0.0013				
		-0.0276		-0.0103		-0.0009				
		-0.0673		-0.0137		-0.0012				
		-0.1061		-0.0139		0.0016				
	_	-0.1493		-0.0219		-0.0018				
		-0.2191		-0.0159		0.0014				
-3.9	8	-0.3041	. 2.3235	-0.0152	0.1047	0.0014	0.2082	0.0511	0.1572	447.
		EL 946.2	-	FIG. 1.000		ACH 4.50		PHI =		
		EL 946.2 3.77 PSI	-	FIG. 1.000 IN.= .48E0		1CH 4.50		PHI =		40•
ť	}=		RE PER	IN.= .48E0		90. DE		P0J/P	TS =	
ť	}= }0=	3.77 PSI	RE PER	IN.= .48E0		90. DE	G.F	P0J/P	TS =	
I ALPI)= 20= 4A	3.77 PSI 40G.0 CM	RE PER HG PTS=	IN.= .48E00 .2659 PSI CS	6 TO=	90. DE	EG.F RUN NO.	POJ/P3 . 014030 CPB	TS = 69141 CAF	40. RUN
1)= PO= fA	3.77 PSI 400.0 CM	RE PER HG PTS= CM -2.2902	IN.= .48E0	6 TO= CY 0.2536	90. DE	EG.F RUN NO. CAT 0.2137	POJ/P3 014030 CPB 0.0525	TS = 69141 CAF 0.1613	40. RUN 448.
ALPI)= PO= HA	3.77 PSI 40G.0 CM CN 0.2953	RE PER HG PTS= CM -2.2902 -1.6879	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336	CY 0.2536 0.2433	90. DE CR 0.0054	EG.F RUN NO. CAT 0.2137 0.2151	POJ/P1 O14030 CPB 0.0525 0.0524	TS = 69141 CAF 0.1613 0.1627	40. RUN 448. 448.
4.1 3.1)= PO= HA L2 L2	3.77 PSI 40G.0 CM CN 0.2953 0.2182	RE PER HG PTS= CM -2.2902 -1.6879	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340	CY 0.2536 0.2433 0.2466	90. DE CR 0.0054 0.0048	EG.F RUN NO. CAT 0.2137 0.2151 0.2092	POJ/P3 014030 CPB 0.0525 0.0524 0.0519	TS = 69141 CAF 0.1613 0.1627	40. RUN 448. 448.
4.3 3.1 2.1)= PO= HA L2 L2 L0	3.77 PSI 40G.0 CM CN 0.2953 0.2182 0.1386	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340	CY 0.2536 0.2433 0.2466 0.2436	90. DE CR 0.0054 0.0048 0.0042	CAT 0.2137 0.2151 0.2092 0.2116	POJ/P3 014030 CPB 0.0525 0.0524 0.0519 0.0514	TS = 69141 CAF 0.1613 0.1627 0.1573 0.1603	40. RUN 448. 448. 448.
4.3 3.1 2.1)= PO= HA L2 L2 L0 59	3.77 PSI 40G.0 CM CN 0.2953 0.2182 0.1386 0.0953	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.4136	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341	CY 0.2536 0.2433 0.2466 0.2436 0.3028	90. DE CR 0.0054 0.0048 0.0042 0.0039	CAT 0.2137 0.2151 0.2092 0.2116 0.2007	POJ/P3 O14030 CPB 0.0525 0.0524 0.0519 0.0514 0.0509	CAF 0.1613 0.1627 0.1573 0.1603 0.1498	40. RUN 448. 448. 448. 448.
4-1 3-1 2-1 1-9)= PO= HA 12 10 59 08	3.77 PSI 400.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.4136 -0.2138	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018	CAT 0.2137 0.2151 0.2092 0.2116 0.2007	POJ/P3 O14030 CPB 0.0525 0.0524 0.0519 0.0514 0.0509 0.0506	TS = 69141 CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565	40. RUN 448. 448. 448. 448. 448.
4-1 3-1 2-1 1-9 1-0)= +A 12 12 10 59 08	3.77 PSI 40G.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537 9.0251	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.4136 -0.2138 0.0970	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395 -0.0318	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264 0.2425	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018 0.0034	CAT 0.2137 0.2151 0.2092 0.2116 0.2007 0.2071 0.2064	POJ/P3 . 014030 . CPB 0.0525 0.0524 0.0514 0.0509 0.0506 0.0504	TS = 69141 CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565 0.1560	40. RUN 448. 448. 448. 448. 448.
ALPH 4-1 3-1 1-2 1-6 0-5 0-6)= +A 12 12 10 59 98 57	3.77 PSI 40G.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537 0.0251 -0.0146	RE PER HG PTS= CM -2.2902 -1.6879 -0.7426 -0.4136 -0.2138 0.0970 0.3136	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395 -0.0318 -0.0331	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264 0.2425 0.1810 0.1218	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018 0.0034 0.0025 0.0029	CAT 0.2137 0.2137 0.2151 0.2092 0.2116 0.2007 0.2007 0.2064 0.2069 0.2060	POJ/P3 CPB 0,0525 0-0524 0-0519 0-0514 0-0506 0-0504 0-0504 0-0504	CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565 0.1566	40. RUN 448. 448. 448. 448. 448. 448. 448.
ALPI 4-1 3-1 1-5 1-6 0-5 0-6 -0-6)= PO= HA 12 12 10 10 10 10 10 10 10 10 10 10 10 10 10	3.77 PSI 400.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537 0.0251 -0.0146 -0.0452 -0.0779 -0.1156	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.2138 0.0970 0.3136 0.5516 0.8376	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395 -0.0318 -0.0274 -0.0215 -0.0229	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264 0.2425 0.1810 0.1218 0.1392	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018 0.0034 0.0025 0.0029 0.0051 0.0042	CAT 0.2137 0.2137 0.2151 0.2092 0.2116 0.2007 0.2007 0.2064 0.2069 0.2060 0.2083	POJ/P3 CPB 0,0525 0-0524 0-0519 0-0514 0-0504 0-0504 0-0504 0-0504 0-0504	CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565 0.1566 0.1557 0.1580	40. RUN 448. 448. 448. 448. 448. 448. 448. 448. 448.
ALPI 4-1 3-1 1-5 1-6 0-5 0-6 -0-6)= PO= HA 12 12 10 10 10 10 10 10 10 10 10 10 10 10 10	3.77 PSI 400.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537 9.0251 -0.0146 -0.0452 -0.0779	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.2138 0.0970 0.3136 0.5516 0.8376 1.0831	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395 -0.0318 -0.0274 -0.0215 -0.0229 -0.0207	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264 0.2425 0.1810 0.1218 0.1392 0.1175	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018 0.0034 0.0025 0.0029 0.0051 0.0042 0.0040	CAT 0.2137 0.2151 0.2092 0.2116 0.2007 0.2064 0.2069 0.2060 0.2083 0.2044	POJ/P3 O14036 CPB 0.0525 0.0524 0.0519 0.0506 0.0506 0.0506 0.0504 0.0504 0.0503 0.0503	TS = 69141 CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565 0.1566 0.1557 0.1580 0.1541	40. RUN 448. 448. 448. 448. 448. 448. 448. 448. 448.
ALPH 4-1 3-1 1-2 1-3 1-3 1-3 1-3 1-3 1-3 1-3 1-3 1-3 1-3)= +A 12 10 10 10 10 10 10 10 10 10 10 10 10 10	3.77 PSI 400.0 CM CN 0.2953 0.2182 0.1386 0.0953 0.0537 0.0251 -0.0146 -0.0452 -0.0779 -0.1156	RE PER HG PTS= CM -2.2902 -1.6879 -1.0709 -0.7426 -0.4136 -0.2138 0.0970 0.3136 0.5516 0.8376 1.0831 1.7343	IN.= .48E00 .2659 PSI CS -0.0344 -0.0336 -0.0340 -0.0341 -0.0395 -0.0318 -0.0274 -0.0215 -0.0229	CY 0.2536 0.2433 0.2466 0.2436 0.3028 0.2264 0.2425 0.1810 0.1218 0.1392 0.1175 0.1479	90. DE CR 0.0054 0.0048 0.0042 0.0039 0.0018 0.0034 0.0025 0.0029 0.0051 0.0042	CAT 0.2137 0.2151 0.2092 0.2116 0.2007 0.2071 0.2064 0.2069 0.2063 0.2044 0.2088	POJ/P7 014030 CPB 0.0525 0.0524 0.0519 0.0514 0.0509 0.0506 0.0504 0.0504 0.0503 0.0503	CAF 0.1613 0.1627 0.1573 0.1603 0.1498 0.1565 0.1560 0.1557 0.1580	40. RUN 448. 448. 448. 448. 448. 448. 448. 448. 448. 448.

HUU	EL 946.2	COMF	IG. 1.000	H#	CH 4.50)	PHI =	45.	
Q= :	3.77 PS1	RE PER	IN.= .48E0	=01 &	90. DE	G.F	P0J/P	rs = 1	109.
90≖	400.0 CM	HG PTS=	.2659 PSI			RUN NO.	01403	5 <u>9</u> 142	
ALPHA	CN	СН	£\$	CY	CR	CAT	CPB	CAF	RUN
4.12	0.2644	-2.0558	-0.0652	0.4944	0.0049	0.2243	0.0519	0.1724	449.
3.11	0.1868	-1.4484	-0.0637	0.4769	0.0043	0.2197	0.0521	0.1676	5 449.
	0.1112	-0.8727	~0.0623	0.4590	0.0032	0.2168	0.0518	0.1690	449.
	0.0753	.0.6085	-0.0553		0.0035				
1.07	0.0350	-0.2971	-0.0581	0.4229	0.0032	0.2153	0.0510	0.1643	449.
	-0.0002	-0.0327	-0.0559	0.4002	0.0029	0.2145	0.0508	9.1637	7 449.
0.06	-0.0384	0.2563	-C.0588	0.4259	0.0021	0.2153	0.0507	0.1646	6 449.
-0.45	-0.0800	0.5844	-0.0564	0.3977	0.0024	0.2146	0.0507	0.1639	449.
	-0.1141	0.8385	-0.0532	0.3681	0.0015	0.2167	0-0506	0.1661	L 449.
-1.46	-0.1514		-0.0531	0.3680	-0.	0.2188	0.0504	0.1684	4 449.
-1.96	-0.1848	1.3769	-0.0525	0.3668-	-0.0003	0.2165	0.0504	0.1661	ľ 449.
-2.97	-0.2578	1-9285	-0.0473	0.3213	0.0042	0.2163	0.0505	0.1658	8 449.
-3.98	-0.3402	2.5726	-0.0451	0.3088	0.0054	0.2147	0-0511	0.1636	449.
	EL 946.2		16. 1.000		ACH 4.50		PHI =	90.	
			FIG. 1.000 IN.= .48E0		90. DE		PHI =		•
Q=		RE PER	IN.= .48E0			G•F		rs =	
Q=	3.77 PSI	RE PER	IN.= .48E0			G•F	POJ/P	rs =	• RUN
Q= PO= Alpha	3.77 PSI 400.0 SMI CN	RE PER HG PTS=	IN.= .48E00 .2659 PSI	6 TO=	90. DE	EG•F RUN NO	POJ/P	TS = 69102 CAF	
Q= PO= ALPHA 3.91	3.77 PSI 400.0 SMI CN 0.3038	RE PER HG PTS= CH -2.3516	IN.= .48E00 .2659 PSI CS -0.0123	6 TO= CY 0.1225-	90. DE CR -0.0047	G.F RUN NO. CAT 0.1711	POJ/P 017030 CPB	TS = 69102 CAF 0-1204	4 449.
Q= PO= ALPHA 3.91 2.91	3.77 PSI 400.0 SMI CN 0.3038 0.2232	RE PER HG PTS= CH -2.3516 -1.7132	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112	6 TO= CY 0.1225- 0.1133-	90. DE	CAT 0-1711 0-1701	POJ/P 017030 CPB 0.0508 0.0509	rs = 69102 CAF 0.1204 0.1192	4 449. 2 449.
Q= PO= ALPHA 3.91 2.91 1.90	3.77 PSI 400.0 CMI CN 0.3038 0.2232 0.1416	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745	IN.= .48E00 .2659 PSI CS -0.0123	6 TO= CY 0.1225- 0.1133- 0.1407-	90. DE CR -0.0047 -0.0065	CAT 0-1711 0-1701 0-1709	POJ/P 017030 CPB 0.0538 0.0509 0.0508	CAF 0.1204 0.1192 0.1201	4 449. 2 449. 1 449.
Q= PO= ALPHA 3.91 2.91 1.90 1.38	3.77 PSI 400.0 CMI CN 0.3038 0.2232 0.1416 0.1015	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130	CY 0.1225- 0.1133- 0.1407- 0.1273-	90. DE CR -0.0047 -0.0065 -0.0039 -0.0039	CAT 0.1711 0.1701 0.1709 0.1690	POJ/P 017030 CPB 0.0538 0.0509 0.0508 0.0505	TS = 69102 CAF 0.1204 0.1192 0.1201 0.1186	4 449. 2 449. 1 449. 5 449.
Q= PO= ALPHA 3.91 2.91 1.90	3.77 PSI 400.0 CMI CN 0.3038 0.2232 0.1416	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143	CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701-	90. DE CR -0.0047 -0.0065 -0.0039	CAT 0.1711 0.1701 0.1709 0.1690 0.1701	POJ/P 017030 CPB 0.0508 0.0509 0.0508 0.0505 0.0503	TS = 69102 CAF 0.1204 0.1192 0.1203 0.1183	4 449. 2 449. 1 449. 5 449. 8 449.
Q= PO= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074	6 T0= CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701- 0.1426-	90. DE CR -0.0047 -0.0065 -0.0039 -0.0039	CAT 0.1711 0.1701 0.1709 0.1690 0.1701 0.1698	POJ/P 017030 CPB 0.0508 0.0509 0.0508 0.0505 0.0503 0.0502	CAF 0.1204 0.1192 0.1201 0.1183 0.1191 0.1191	4 449. 2 449. 1 449. 5 449. 8 449.
Q= PO= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36 -0.14	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622 0.0253	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919 0.0844	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074 -0.0146	CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701- 0.1426- 0.1432-	90. DE CR -0.0047 -0.0055 -0.0039 -0.0038 -0.0044 -0.0043	CAT 0.1711 0.1701 0.1709 0.1690 0.1698 0.1698	POJ/P . 01703 CPB 0.0508 0.0509 0.0505 0.0503 0.0502 0.0501	CAF 0.1204 0.1192 0.1203 0.1183 0.1191 0.1191	4 449. 2 449. 1 449. 5 449. 8 449. 7 449.
Q= P0= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36 -0.14 -0.65	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622 0.0253 -0.0109	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919 0.0844 0.3542	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074 -0.0146 -0.0147	CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701- 0.1426- 0.1432- 0.2299-	90. DE CR -0.0047 -0.0065 -0.0039 -0.0038 -0.0044	CAT 0.1711 0.1701 0.1709 0.1690 0.1698 0.1698 0.1698	POJ/P 01703 CPB 0.0508 0.0509 0.0508 0.0505 0.0503 0.0502 0.0501 0.0500	CAF 0.1204 0.1192 0.1203 0.1183 0.1191 0.1193	4 449. 2 449. 1 449. 5 449. 8 449. 7 449. 3 449.
Q= P0= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36 -0.14 -0.65 -1.16	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622 0.0253 -0.0109 -0.0470	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919 0.0844 0.3542 0.6350	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074 -0.0146 -0.0147 -0.0233	CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701- 0.1426- 0.1432- 0.2299- 0.1110-	90. DE CR -0.0047 -0.005 -0.0039 -0.0038 -0.0044 -0.0043	CAT 0.1711 0.1701 0.1709 0.1690 0.1698 0.1695 0.1693 0.1658	POJ/P O1703 CPB O.0508 O.0509 O.0505 O.0503 O.0502 O.0501 O.0501	CAF 0.1204 0.1292 0.1192 0.1193 0.1194 0.1195	449. 2 449. 1 449. 5 449. 7 449. 7 449. 3 449.
Q= PO= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36 -0.14 -0.65 -1.16 -1.67	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622 0.0253 -0.0109 -0.0470 -0.0840	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919 0.0844 0.3542 0.6350 0.9212	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074 -0.0146 -0.0147 -0.0233 -0.0119	CY 0.1225- 0.1133- 0.1407- 0.1273- 0.1426- 0.1432- 0.2299- 0.1110- 0.2282-	90. DE CR -0.0047 -0.0065 -0.0039 -0.0038 -0.0044 -0.0043 -0.0042	CAT 0.1711 0.1701 0.1709 0.1690 0.1698 0.1695 0.1693 0.1658 0.1672	POJ/P 01703 CPB 0.0508 0.0509 0.0505 0.0503 0.0502 0.0501 0.0501 0.0501	CAF 0.1204 0.1204 0.1203 0.1180 0.1191 0.1192 0.1195 0.1170	449. 2 449. 1 449. 5 449. 8 449. 7 449. 3 449. 7 449.
Q= PO= ALPHA 3.91 2.91 1.90 1.38 0.86 0.36 -0.14 -0.65 -1.16 -1.67 -2.17	3.77 PSI 400.0 CM CN 0.3038 0.2232 0.1416 0.1015 0.0622 0.0253 -0.0109 -0.0470 -0.0840 -0.1217	RE PER HG PTS= CH -2.3516 -1.7132 -1.0745 -0.7690 -0.4698 -0.1919 0.0844 0.3542 0.6350 0.9212 1.1915	IN.= .48E00 .2659 FSI CS -0.0123 -0.0112 -0.0143 -0.0130 -0.0074 -0.0146 -0.0147 -0.0233 -0.0119 -0.0235	6 T0= CY 0.1225- 0.1133- 0.1407- 0.1273- 0.0701- 0.1426- 0.1432- 0.2299- 0.21110- 0.2282- 0.1556-	90. DE CR -0.0047 -0.0065 -0.0039 -0.0038 -0.0044 -0.0043 -0.0044 -0.0047	CAT 0.1711 0.1701 0.1709 0.1690 0.1701 0.1698 0.1695 0.1693 0.1672 0.1695	POJ/P 017030 CPB 0.0508 0.0509 0.0508 0.0503 0.0502 0.0501 0.0501 0.0501 0.0502	CAF 0.1204 0.1192 0.1201 0.1192 0.1193 0.1193 0.1194 0.1197 0.1197	449. 2 449. 5 449. 6 449. 7 449. 3 449. 7 449. 6 449.

H	DEL 946.2	CONI	FIG. 1.000) HACH 4.	se	PHI =	90.	
Q=	: 3.77 PSI	RE PER	JN.= .48E0	6 70≈ 90°	DEG.F	POJ/PŤS	= 10.	
PO)= 400.0 CH	HG PTS=	.2659 PS1		RUN NO	. 0170369	103	
ALPH	N CN	СН	cs	CY ER	CAT	СРВ	CAF	RUN
3.91			-0.0153	0.1248-0.002				450.
2.97			-0.9171	0.1416-0.007				450.
1.90			-0.0174	0.1436-0.003				450.
1.38			-0.0261	0.2316-0.003				450.
0.88			-0.0118 -0.0148	0.0862-0.002				450. 450.
0.36	0.0281 5 -0.0065		-0.0148	0.1131-0.003				450.
	5 -0.0065 5 -0.0434		~0.0207	0.1722-0.002				450.
	-0.0788		-0.0279	0.2447-0.003				450.
	7 -0.1173		-0.0108	0.0709-9.000				450 .
	-0.1534		-0.0167	0.1305-0.002				450.
	-0.2358		-0.0169	0.1312-G.001				450.
-4.19	-0.3188	2.4578	-0.0130	0.0970-0.002				450.
	DEL 946.2		FIG. 1.000			PHI =	90.	
Q=	3.77 PSI	RE PER	IN.≈ .48E0	6 TO= 90.	DEG.F	POJ/PTS	= 20.	
PO)= 400.0 CM	HG PTS∓	.2659 PSI		RUN NO	. 0170369	104	
ALPHA	CN CN	CM	os.	CY CR	CAT	СРВ	CAF	RUN
3.92	0.3172	-2.484B	-0.0197	0.1381-0.001	4 0.1955	0.0508 0	-1447	451.
2.91			-0.0201	0.1412-0.001				451.
1.90	0.1519	-1.1748	-0.0190	0.1258-0.002	0.1937	0.0507 0	.1430	451.
1.38	0.1095	-0.8493	-0.0248	0-1842-0-001	2 0-1920	0.0505 0	.1414	451.
0.87	0.0764	-0.6063	-0.0277	0.2132-0.002	3 0.1917	0.0504 0	.1414	451.
0.37		-0.2870	-0.0235	0.1670-0.001	5 0.1898	0.0503 0	.1395	451.
-	-0.0006		-0.0251	0.1768-0.000				451.
	-0.0391		-0.0381	0.3112-0.002				451.
	-0.0768		-0.0266	0.2004-0.000				451 •
	-0.1136		-0.0171	0.1029-0.020				451.
-2.16								
2 2 2	-0.1490		-0.0196	0.1286-0.001				451.
	7 -0.2290 7 -0.3159	1.7405	-0.0196 -0.0214 -0.0174	0.1286-0.001 0.1457-0.002 0.1133-0.001	0.1959	0.0503 0	-1456	451. 451.

MODEL 946.2	CONF	1G. 1,000	• н/	NGH 4251	0	PHI =	90.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	901/9	is = 40	•
PG= 400.0 E	HG PTS=	.2659 PSI			RUN NO.	01703	69105	
ALPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
3.92 0.3199	-2.5147	-0.0328	0.2243	0.0013	0.2005	0.0510	0.1496	452.
2.91 0.2345	-3.8307	-0.0317	0.2119	0.0001	0.1981	0.0510	0.1471	452.
1.90 0.1538	-1.1964	-0.0320	0.2109	0.0015	0-1973	0.0507	0.1466	452.
1.38 0.1129	-0.8843	-0.0307	0.1973	0.0009	0.1969	0.0505	0.1464	452.
0.88 0.0737	-0.5830	-0.0322			0.1981			452.
0.36 0.0375	-0.3087				0.1977			452 -
-0.15 -0.0018	-0.0044				0.2017			452•
-0.66 -0.0379		-0.0297			0.1956			452.
-1.16 -0.0748		-0.0297			0.1966			452.
-1.66 -0.1110		-0.0327			0.2021			452.
-2.16 -0.1471	1.0983				0.2076			452.
	1.7242				0.2053			452.
-4.19 -0.3140	2.4164	-0.0306	0.1974	0.0016	0.2043	0.0508	0.1535	452.
MODEL 946.2 Q= 3.77 PSI		IG. 1.000 IN.= .48E0		4CH 4.5		PHI =	90, TS = 100	
Q= 3.77 PSI	RE PER	IN.= .48E0		4CH 4.5i	EG.F	POJ/P	TS = 100	•
	RE PER	IN.= .48E0			EG.F		TS = 100	•
Q= 3.77 PSI	RE PER	IN.= .48E0			EG.F	POJ/P	TS = 100	• 、 RUN
Q= 3.77 PSI PO= 400.0 CH ALPHA CN	RE PER HHG PTS=	IN ₀ = .48E0 .2659 PSI CS	6 10=	90. D	EG.F KUN NO. CAT	POJ/P • 017036 CP8	TS = 100 69106 CAF	RUN
Q= 3.77 PSI PO= 400.0 C	RE PER	IN.= .48E0 .2659 PSI CS -0.0664	6 TU= CY 0.4524	90. D	EG.F RUN NO	POJ/P • 017030 CPB 0.0506	TS = 100 69106 CAF 0.1603	
Q= 3.77 PSI PO= 400.0 CH ALPHA CN 3.92 0.3221	RE PER HHG PTS= .H -2.5338	IN ₀ = .48E0 .2659 PSI CS -0.0664 -0.0668	6 TU= CY 0.4524 0.4550	90. D	EG.F KUN NO. CAT 0.2110	POJ/P - 017030 - CP8 - 0.0506 - 0.0508	TS = 100 69106 CAF 0.1603 0.1622	RUN 453•
Q= 3.77 PSI PO= 400.0 CH ALPHA CN 3.92 0.3221 2.91 0.2376	RE PER HHG PTS= .H -2.5338 -1.8541	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -2.0700	6 Tu= CY 0.4524 0.4550 0.4836	90. D CR 0.0009 -0.0003 0.0004	EG.F KUN NO. CAT 0.2110 0.2129	POJ/P . 017030 CP8 0.0506 0.0508 0.0505	TS = 100 69106 CAF 0.1603 0.1622 0.1617	RUN 453. 453.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567	RE PER HHG PTS= .H -2.5338 -1.8541 -1.2241	IN ₀ = .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858	CY 0.4524 0.4550 0.4836 0.6432	90. D CR 0.0009 -0.0003 0.0004 -0.0009	EG.F KUN NO. CAT 0.2110 0.2129 0.2122	POJ/P . 01703 CP8 0.0506 0.0508 0.0505 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604	RUN 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CP ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151	RE PER HHG PTS= -2.5338 -1.8541 -1.2241 -0.9069	IN ₀ = .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802	CY 0.4524 0.4550 0.4836 0.6432	90. Di CR 0.0009 -0.0003 0.0004 -0.0009 -0.0008	EG.F KUN NO. CAT 0.2110 0.2129 0.2122 0.2107	POJ/P . 017030 CP8 0.0506 0.0508 0.0505 0.0503 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600	RUN 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012	RE PER HHG PTS= -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732	6 TU= CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0008 -0.0007	EG.F RUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2103 0.2155 0.2079	POJ/P - 01703 - CP8 - 0.0506 - 0.0508 - 0.0503 - 0.0503 - 0.0503 - 0.0503 - 0.0502	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600 0.1654 0.1576	RUN 453. 453. 453. 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012 -0.65 -0.0372	RE PER HHG PTS= .M -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316 0.2666	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732 -0.0619	6 TU= CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112 0.3963	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0008 -0.0007 0.0013 0.0027	EG.F RUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2103 0.2155 0.2079 0.2102	POJ/P - 01703 - CP8 - 0.0506 - 0.0508 - 0.0503 - 0.0503 - 0.0503 - 0.0502 - 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600 0.1654 0.1576 0.1599	RUN 453. 453. 453. 453. 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012 -0.65 -0.0372 -1.15 -0.0742	RE PER HHG PTS= .H -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316 0.2666 0.5476	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732 -0.0619 -0.0691	6 TU= CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112 0.3963 0.4688	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0013 0.0027 0.0013	EG.F KUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2155 0.2079 0.2102 0.2129	POJ/P - 01703 - CP8 - 0.0506 - 0.0508 - 0.0503 - 0.0503 - 0.0503 - 0.0502 - 0.0503 - 0.0503 - 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600 0.1654 0.1576 0.1599 0.1626	RUN 453. 453. 453. 453. 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012 -0.65 -0.0372 -1.15 -0.0742 -1.66 -0.1126	RE PER HHG PTS= -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316 0.2666 0.5476 0.8374	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732 -0.0619 -0.0691 -0.0692	CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112 0.3963 0.4688 0.4725	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0013 0.0027 0.0034 0.0034	EG.F KUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2155 0.2079 0.2102 0.2129 0.2140	POJ/P - 01703 - CP8 - 0.0506 0.0508 0.0505 0.0503 0.0501 0.0502 0.0503 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600 0.1654 0.1576 0.1599 0.1626 0.1638	RUN 453. 453. 453. 453. 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012 -0.65 -0.0372 -1.15 -0.0742 -1.66 -0.1126 -2.16 -0.1480	RE PER 4HG PTS= -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316 0.2666 0.5476 0.8374 1.1089	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732 -0.0619 -0.0691 -0.0692 -0.0693	CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112 0.3963 0.4688 0.4725 0.4731	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0003 0.0027 0.0034 0.0034 0.0029	EG.F KUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2103 0.2155 0.2079 0.2129 0.2129 0.2140 0.2151	POJ/P - 01703 - CP8 - 0.0506 - 0.0508 - 0.0503 - 0.0503 - 0.0501 - 0.0502 - 0.0503 - 0.0503 - 0.0502 - 0.0503 - 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1600 0.1654 0.1576 0.1599 0.1626 0.1638 0.1655	RUN 453. 453. 453. 453. 453. 453. 453. 453.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.92 0.3221 2.91 0.2376 1.90 0.1567 1.38 0.1151 0.86 0.0759 0.37 0.0389 -0.14 0.0012 -0.65 -0.0372 -1.15 -0.0742 -1.66 -0.1126	RE PER HG PTS= -2.5338 -1.8541 -1.2241 -0.9069 -0.6056 -0.3229 -0.0316 0.2666 0.5476 0.8374 1.1089 1.7214	IN.= .48E0 .2659 PSI CS -0.0664 -0.0668 -0.0700 -0.0858 -0.0802 -0.0689 -0.0732 -0.0619 -0.0691 -0.0692 -0.0693	CY 0.4524 0.4550 0.4836 0.6432 0.5860 0.4709 0.5112 0.3963 0.4688 0.4725 0.4731 0.4749	90. D: CR 0.0009 -0.0003 0.0004 -0.0009 -0.0013 0.0027 0.0034 0.0034 0.0029 0.0017	EG.F KUN NO. CAT 0.2110 0.2129 0.2122 0.2107 0.2155 0.2079 0.2102 0.2129 0.2140	POJ/P - 01703 - CP8 - 0.0506 - 0.0508 - 0.0503 - 0.0503 - 0.0502 - 0.0503 - 0.0502 - 0.0503 - 0.0502 - 0.0503 - 0.0503	TS = 100 69106 CAF 0.1603 0.1622 0.1617 0.1604 0.1604 0.1654 0.1576 0.1599 0.1626 0.1638 0.1655 0.1699	RUN 453. 453. 453. 453. 453. 453. 453. 453.

MOD	EL 946.2	CONF	IG. 4.00	O HA	CH 4.50	O	PHI =	•	
Q=	3.77 PSI	RE PER	IN.= .48E	=01 60	90. DE	EG.F	POJ/P	rs =	•
P0=	: 400.0 CM	HG PTS=	.2659 PS	3 1		RUN NO.	. 01703	69107	
ALPHA	CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
4.11	0.2620	-1.8029	0.0032	-0.0464-	-0.0066	0.1541	0.0522	0.1020	454.
3.10	0.1937	-1.3128	0.0048	-0.0590-	0.0055	0.1508	0.0523	0.0985	454.
2.09	0.1282	-0.8571	0.0065	-0.0727-	0.0039	0.1475	0.0520	0.0955	454.
1.57	0.0932	-0.6208	0.0059	-0.0679-	0800.0	0.1461	0.0517	0.0944	454.
1.06	0.0641	-0.4343	0.0076	-0.0800-	0.0021	0.1444	0.0515	0.0929	454.
0.55	0.0248	-0.1389	0.0084	-0.0896-					454.
0.04	0.	0.0132	0.0069	-0.0728-					454.
	-0.0278	0.1858	0.0093	-0.0934-					454.
	-0.0513	0.3183	0.0093	~0.0949-	v ·				454.
	-0.0862	0.5664	0.0094	-0.0941-					454.
	-0.1167	0.7823	0.0086	-0.0843-					454.
_		1.2235	0.0103	-0.0980-					454.
	-0.1808 -0.2536	1.7464	0.0144	~0.1308-					454.
-4.01	-0.2730	141404	0.0144	041300	0.0002	002110	0.0,2,	*******	
MOD	EL 946.2	CON	IG. 4.00	n Ma	ICH 4.50	n	PHI =	_	
nul	DEC 740.2	CON	100 4500	10 12	1311 Te31	•		•	
Q=	3.77 PSI	RE PER	IN.= .485	06 TO=	90. Di	EG.F	P0J/P	TS =	10.
P0=	400.0 CH	HG PTS=	.2659 PS	11		RUN NO	. 01703	69108	
ALPHA	CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.10	0.2546	-1.7592	0.0027	-0.0409-	-0. 0053	0-1619	0.0526	0.1093	455.
3.09	0.2340	-1.2692	0.0051	-0.0600-					455
			0.0031	-0.0537-					455.
2.07	0.1208	-0.8169							455.
1.56	0.0815	-0.5365	0.0062	-0.0653-					455.
1.05	0.0538	-0.3587	0.0063	-0.0647-					
0.55	0.0232	-0.1542	0.0079	-0.0791-					455.
	-0.0160	0.1469	0.0079	-0.0773-					455.
	-0.0481	0.3663	0.0095	-0:0934-					455.
	-0.0586	0.3672	,0.0096	-0.0926-					455.
	-0.0864	0.5494	0.0112	-0.1055-					455.
	-0.1198	0.7683	0.0112	-0.1037-					455.
-3.00	-0.1796	1.1860	0.0113	-0.1027-				_	455.
-4-01	-0.2566	1.7518	0.0130	-0.1162-	-0.0024	0.1576	0.0523	0.1053	455.

ASSESSORES AND ASSESS

MODE	L 946.2	CONF	FIG. 4.000	HA	CH 4.50	0	PHI =	•	
Q= 3.	.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DI	EG.F	P0J/P	TS =	20.
P0= 4	400.0 CMH	G PTS=	.2659 PSI			RUN NO	01703	69109	
ALPHA	CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
4.05	0.2487	-1.7306	-0.0017	-0.0026-	0.0045	0-1685	0.0526	0.1159	456.
3.09 (0-1804	-1.2404		-0.0071-					
2.08	0.1178	-0.8175		-0.0288-					
	0.0814	-0.5699	0.0018	-0.0287-	0.0034	0.1617	0.0520	0.1097	456.
	0.0509	-0.3601	-0.0036	0.0261-	0.0031	0.1615	0.0518	0.1097	456.
	0.0246	-0.1959		0.0363-	0.0022	0.1568	0.0517	0.1052	454.
0.02 -			-0.0051	0.0365-					
-0.48 -C			-0.0051	0.0349-					
-0.98 -0			-0.0057	0.0410-					
-1.48 -0			-0.0057	0.0410-					
-2.00 -0			-0.0048	0.0338-					
-3.00 -0			-0.0056	0.0387-					
-4.01 -0	3.2580	1.7413	-0.0063	0.0445-	0.0021	0.1595	0.0521	0.1073	456.
	. 946.2	CONF	FIG. 4.000 IN.= .48E00		CH 4.50		PHI =	• rs =	40.
Q= 3.		RE PER	IN.= .48E0				POJ/P	rs =	40.
Q= 3.	.77 PSI	RE PER	IN.= .48E0			G.F	POJ/P	rs =	40• RUN
Q= 3. PO= 4	.77 PS1 400.0 CMH	RE PER G PTS=	IN.= .48E00 .2659 PSI CS	5 TO=	90. DE	EG.F RUN NO. CAT	POJ/P? 017036 CPB	FS = 59110 CAP	RUN
Q= 3. PO= 4 ALPHA 4.09 (.77 PS1 400.0 CMH CN 0.2358	RE PER G PTS= CM -1.6464	IN.= .48E00 .2659 PSI CS -0.0082	CY 0.0725-	90. DE CR 0.0012	G.F RUN NO. CAT 0.1734	POJ/P1 017036 CPB	TS = 59110 CAP 0-1208	RUN 457•
Q= 3. PO= 4 ALPHA 4.09 (3.09 (.77 PS1 400.0 CMH CN 0.2358 0.1718	RE PER G PTS=	IN.= .48E00 .2659 PSI CS -0.0082 -0.0089	CY 0.0725-0	90. DE CR 0.0012 0.0008	EG.F RUN NO. CAT 0.1734 0.1715	POJ/P 017036 CPB 0.0526 0.0527	TS = 59110 CAP 0.1208 0.1188	RUN 457 • 457 •
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (6.00))	.77 PS1 400.0 CMH CN 0.2358 0.1718 0.1092	RE PER G PTS= CM -1.6464 -1.1967	IN.= .48E00 .2659 PSI CS -0.0082 -0.0089 -0.0073	CY 0.0725-0 0.0761-0	90. DE CR 0.0012 0.0008 0.0003	EG.F RUN NO. CAT 0.1734 0.1715 0.1681	POJ/PT 017036 CPB 0.0526 0.0527 0.0524	TS = 59110 CAP 0.1208 0.1188 0.1158	RUN 457 • 457 •
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (0.00)))	.77 PS1 400.0 CMH CN 0.2358 0.1718 0.1092 0.0698	RE PER G PTS= CM -1.6464 -1.1967 -0.7674	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087	CY 0.0725 0.0761 0.0619 0.0717	90. DE CR 0.0012 0.0008 0.0003 0.0001	CAT 0.1734 0.1715 0.1681 0.1684	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0521	TS = 59110 CAP 0.1208 0.1188 0.1158 0.1163	RUN 457 • 457 • 457 •
Q= 3. PO= 4 ALPHA 4.09 (3.09 (3.09 (3.07 (.77 PS1 400.0 CMH CN 0.2358 0.1718 0.1092 0.0698	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0071	CY 0.0725-0 0.0761-0	90. DE CR 0.0012 0.0008 0.0003 0.0001	CAT 0.1734 0.1715 0.1681 0.1684 0.1697	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0521 0.0518	CAP 0.1208 0.1188 0.1158 0.1163 0.1163	RUN 457 • 457 • 457 • 457 •
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.05 (.77 PS1 .400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0201	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 -0.1879	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0071	CY 0.0725 0.0761 0.0619 0.0717 0.0572	90. DE CR 0.0012 0.0008 0.0003 0.0001 0.0001	CAT 0.1734 0.1715 0.1681 0.1684 0.1697 0.1690	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0521 0.0518 0.0518	CAP 0.1208 0.1188 0.1158 0.1158 0.1173	RUN 457 • 457 • 457 • 457 • 457 •
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.05 (0.54 (.77 PS1 .400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0201 0.0119	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 -0.1879 0.0308	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0071 -0.0063	CY 0.0725 0.0761 0.0619 0.0717 0.0572 0.0473	90. DE CR 0.0012 0.0008 0.0003 0.0001 0.0001 0.0010	CAT 0.1734 0.1715 0.1681 0.1684 0.1697 0.1690 0.1675	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0521 0.0518 0.0518	CAP 0.1208 0.1188 0.1158 0.1163 0.1173 0.1173	RUN 457. 457. 457. 457. 457. 457.
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.54 (0.03 - -0.48 - -0.99 -	.77 PS1 .400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0306 0.0201 0.0119 0.0526 0.0789	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 -0.1879 0.0308 0.3438 0.5046	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0081 -0.0063 -0.0086 -0.0094 -0.0109	CY 0.0725 0.0761 0.0619 0.0717 0.0572 0.0473 0.0691	90. DE CR 0.0012 0.0008 0.0003 0.0001 0.0001 0.0010 0.0006 0.0004	CAT 0.1734 0.1715 0.1684 0.1697 0.1697 0.1675 0.1674	POJ/P3 0.07036 CPB 0.0526 0.0527 0.0524 0.0518 0.0518 0.0518 0.0516	CAP 0.1208 0.1188 0.1158 0.1163 0.1173 0.1173 0.1158	RUN 457. 457. 457. 457. 457. 457. 457.
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.05 (0.03 (-0.48 (-0.99 (-1.48 (.77 PS1 400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0201 0.0119 0.0526 0.0789 0.1009	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 -0.1879 0.0308 0.3438 0.5046 0.6251	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0063 -0.0086 -0.0094 -0.0109 -0.0093	CY 0.0725 0.0761 0.0619 0.0717 0.0572 0.0473 0.0691 0.0740	90. DE CR 0.0012 0.0008 0.0001 0.0001 0.0010 0.0006 0.0004	CAT 0.1734 0.1715 0.1681 0.1697 0.1697 0.1697 0.1675 0.1674 0.1672	POJ/P3 0.07036 CPB 0.0526 0.0527 0.0524 0.0518 0.0518 0.0518 0.0516 0.0515	CAP 0.1208 0.1188 0.1158 0.1163 0.1173 0.1178 0.1178 0.1159	RUN 457. 457. 457. 457. 457. 457. 457.
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.05 (0.54 (0.03 (-0.48 (-0.99 (-1.48 (-1.99 (.77 PS1 400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0201 0.0119 0.0526 0.0789 0.1009 0.1330	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 0.0308 0.3438 0.5046 0.6251 0.8476	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0063 -0.0086 -0.0094 -0.0109 -0.0093 -0.0085	CY 0.0725 0.0761 0.0619 0.0717 0.0572 0.06473 0.0691 0.0740 0.0860 0.0732 0.0653	90. DE CR 0.0012 0.0008 0.0001 0.0001 0.0006 0.0006 0.0008 0.0014 0.0003	CAT 0.1734 0.1715 0.1681 0.1684 0.1697 0.1675 0.1672 0.1652 0.1680	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0518 0.0518 0.0516 0.0515 0.0514 0.0515	CAP 0.1208 0.1188 0.1158 0.1163 0.1173 0.1158 0.1159 0.1157 0.1138 0.1164	RUN 457. 457. 457. 457. 457. 457. 457. 457.
Q= 3. PO= 4 ALPHA 4.09 (3.09 (2.07 (1.54 (1.05 (0.03 (-0.48 (-0.99 (-1.48 (.77 PS1 .400.0 CMH CN 0.2358 0.1718 0.1092 0.0698 0.0306 0.0201 0.0119 0.0526 0.0789 0.1009 0.1330 0.1913	RE PER G PTS= CM -1.6464 -1.1967 -0.7674 -0.4924 -0.1979 -0.1879 0.0308 0.3438 0.5046 0.6251 0.8476 1.2363	IN.= .48E06 .2659 PSI CS -0.0082 -0.0089 -0.0073 -0.0087 -0.0063 -0.0086 -0.0094 -0.0109 -0.0093	CY 0.0725 0.0761 0.0619 0.0717 0.0572 0.0691 0.0740 0.0860 0.0732	90. DE CR 0.0012 0.0008 0.0001 0.0001 0.0006 0.0006 0.0008 0.0014 0.0003 0.0001	CAT 0.1734 0.1715 0.1681 0.1684 0.1697 0.1675 0.1672 0.1652 0.1680 0.1675	POJ/P3 017036 CPB 0.0526 0.0527 0.0524 0.0518 0.0518 0.0516 0.0515 0.0514 0.0515 0.0515	CAP 0.1208 0.1188 0.1158 0.1163 0.1173 0.1158 0.1159 0.1157 0.1138 0.1164 0.1159	RUN 457. 457. 457. 457. 457. 457. 457. 457.

HOI	DEL 946.2	CON	ig. 4.000	H.	ICH 4.50	o	PHI ≖	•	
7 =	3.77 PS1	RE PER	IN.= .48E0	6 TO=	90. DE	EG.F	POJ/P	rs = 1	100-
Р0:	= 400.0 CF	HG PTS=	.2659 PSI			RUN NG	01703	69111	
ALPHA	CN	CM	cs	CY	CR	CAT	СРВ	CAF	RUN
4.09	0.1993	-1.3796	-0.0081	0.0747-	0.0017	0.1882	0.0524	0.1359	458.
3.08	0.1338	-0.9210	-0.0088	0.0770-	0.0012	0.1863	0.0526	0.1337	458.
	0.0741	-0.5243	-0.0038	0.0741-	8000.0	0.1630	0.0523	0.1306	
1.56	0.0376	-0.2695	-0.0039	0.0313-	-0.0006	0.1844	0.0518	0.1326	
1.04	-0.0015	0.0272	-0.0086	0.0706-	-0.001e	0.1844	0.0518	0.1327	458.
	-0.0178	0.0899	-0.0101	0.0825-	-0.	0.1854	0.0518	0.1337	458.
	-0.0485	0.2954	-0.0101	0.9810	0.0008	0.1868	0.0517	0.1351	458.
-0.49	-0.0806	0.5179	-0.0100	0.0800-	-0.0015	0.1895	0.0515	0.1379	
-0.99	-0.1140	G.7538	-0.0069	0.0539-	-0.0006	0.1834	0.0514	0.1320	458.
	-0.1389	0.8975	-0.0091	0.0712-	-0.0003	0.1832	0.0513	0.1319	458.
	-0.1651	1.0666	-0.0091	0.0712	0.0011	0.1828	0.0510	0.1318	458.
-3.01	-0.2263		-0.0098	0.0785	0.0022	0.1838	0.0509	0.1329	458.
	-0.2961	1.9968	-0.0098	0.0754	0.G014	0.1835	0.0511	0.1324	458
МО	DEL 946.2	CON	ig. 4.000) Н	ICH 4.50	0	PHI =	45.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 TO=	90. DE	EG.F	POJ/P	rs =	•
PO	= 400.0 CF	HG PTS=	.2659 PSI			RUN NO	01703	69112	
ALPHA	CN	CM	cs	ξY	CR	CAT	CPB	CAF	RUN
4.27	0.2714	-1.8664	0.0078	-0.0953	0.0022	0.1759	0.0531	0.1228	459.
3.26		-1.3836	0.0097	-0.1086	0.0017	0.1759	0.0531	0.1228	459.
2.24		-0.9239	0.0100	-0.1087	0.0012	0.1746	0.0526	0.1220	459.
1.72		-0.6436	0.0084	-0.0917-	-0.0003	0.1756	0.0522	0.1234	459.
1.22		-0.4810	0.0120	-0.1222	0.0001	0.1748	0.0520	0.1228	459.
0.71		-0.2678	0.0127	-0.1290					
0.20		-0.0827	0.0095	-0.0990-					
	-0.0164	0.1053	0.0179	-0.1657-					
	-0.0495	0.3313		-0.1682-					
	-0.0768	0.5077	0.0186	-0.1679-					
	-0.1082	0.7241		-0.1712-					
	-0.1686	1.1295	0.02.2	-0:2137 -0:2468	0.0008	0.1777	0.0520	0.1257	459.

MODEL 946.2	CONF	IG. 4.000	HACH 4.	50	PHI =	45.	
Q= 3.77 PSI	RE PER	IN.= .48E0	5 T0= 90• 1	DEG.F	PÖJ/PTS	= 10.	
PO= 400.0 C	MHG PTS=	.2659 PSI		RUN NO.	91703691	14	
ALPHA CN	CM	CS	CY CR	CAT	CPB C	CAF R	ИL
4.26 0.2655	-1.8291	0.0034	-0.0678 0.001	6 0.1719 0	.0525 0.	.1194 460	0.
3.26 0.1978	-1.3427		-0.0813 0.001				
2.24 0.1316	-0.8821		-0.0933-0.		0.0525 0.		
1.72 0.0968	-0.6460		-0.1144 0.000				
1.21 0.0689	-0.4648		-0.1423 0.000				
0.70 0.0359	-0.2378		-0.1203-0.001				
0.20 0.0120	-0.0857		-0.1114-0.000				
-0.30 -0.0207	0.1357		-0.1592-0.000				
-0.81 -0.0517	0.3437		-0.1599-0.000 -0.1541-0.001				
-1.33 -0.0842 -1.83 -0.1105	0.5646 0.7283		-0.1847-0.001				
-2.84 -0.1734	1.1622		-0.1887-0.002				
-3.85 -0.2455	1.6836		-0.2373-0.000				
MODEL 946.2	CONF	IG. 4.000	MACH 4.	50	PHI =	45.	
MODEL 946.2 Q= 3.77 PSI		IG. 4.000 IN.= .48E0		-	PHI = POJ/PTS		
_	RE PER	IN.= .48E0	6 TO= 90.	DEG.F		= 20.	
Q= 3.77 PSI	RE PER	IN.= .48E0	6 TO= 90.	DEG.F	POJ/PTS 01.703691	= 20.	אט
Q= 3.77 PSI PO= 400.0 C ALPHA CN	RE PER HHG PTS= CH	IN.= .48E0 .2659 PSI	6 TO= 90.	DEG.F RUN NO. CAT	POJ/PTS 01.703691 CPB (= 20. LE5 CAF RI	
Q= 3.77 PSI PO= 400.0 C	RE PER	IN.= .48E0 .2659 PSI CS -0.0003	6 TO= 90.	DEG.F RUN NO. CAT. 6 0.1809 (POJ/PTS 01.703691 CPB (= 20. LE5 CAF RI S1282 46	1.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607	RE PER MHG PTS= CH -1.7871	.2659 PSI CS -0.0003 0.0022	6 TO= 90. CY CR -0.0459 0.001	DEG.F RUN NO. CAT. 6 0.1809 (POJ/PTS 01.703691 CPB 0 0.0527 0	= 20. LE5 CAF RI 1282 46.	l.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924	RE PER MHG PTS= CH -1.7871 -1.3016	CS -0.0003 0.0022 0.0041	6 TO= 90. CR -0.0459 0.001	CAT. 6 0.1809 (5 0.1794 (6 0.1765 (6	POJ/PTS 01.703691 CPB C 0.0527 0.0527 0.0527 0.0526 0.0526 0.0526	= 20. LES CAF RI LES2 46 LES7 46 LES39 46	l. l.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268	RE PER MHG PTS= CM -1.7871 -1.3016 -0.8423	CS -0.0003 0.0022 0.0041 0.0034 0.0061	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0706-0.000	CAT. 6 0.1809 (6 0.1794 (6 0.1765 (2 0.1760 (1 0.1753 (0	POJ/PTS 01.703691 CPB 0 0.0527 0.0527 0.0526 0.0528 0.0523 0.0521	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46	l. l.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905	RE PER MHG PTS= CM -1.7871 -1.3016 -0.8423 -0.5910	CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068	CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0796-0.000 -0.0996-0.001	CAT. 6 0.1809 (6 0.1794 (6 0.1765 (2 0.1760 (1 0.1753 (1 0.1762 (1	POJ/PTS 01.703691 CPB 0 0.0527 0.0527 0.0526 0.0528 0.0521 0.0521 0.0521 0.0519	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46 1232 46	1. 1. 1.
Q= 3.77 PSI P0= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014	RE PER MHG PTS= CH -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411	IN.= .48E0 .2659 PSI CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0796-0.000 -0.0996-0.001 -0.0939-0.000 -0.0123-0.002	CAT. 6 0.1809 (5 0.1794 (6 0.1765 (1 0.1763 (1 0.1762 (2 0.1769 (POJ/PTS 01.703691 CPB 0 0.0527 0.0 0.0527 0.0 0.0526 0.0 0.0523 0.0 0.0521 0.0 0.0519 0.0 0.0518 0.0	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46 1243 46 1252 46	l. l. l.
Q= 3.77 PSI P0= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014 -0.31 -0.0237	RE PER MHG PTS= CM -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411 0.1526	IN.= .48E0 .2659 PSI CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011 0.0165	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0706-0.001 -0.0939-0.000 -0.0123-0.002 -0.1821-0.001	CAT. 6 0.1809 (5 0.1794 (6 0.1765 (7 0.1765 (7 0.1763 (7 0.1762 (7 0.1769 (8 0.1803 (POJ/PTS 01.703691 CPB 0 0.0527 0.0527 0.0526 0.0528 0.0521 0.0521 0.0518	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46 1243 46 1252 46	l. l. l.
Q= 3.77 PSI P0= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014 -0.31 -0.0237 -0.82 -0.0662	RE PER MHG PTS= CH -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411 0.1526 0.4781	IN.= .48E0 .2659 PSI CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011 0.0165 0.0062	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0706-0.000 -0.0939-0.000 -0.0123-0.002 -0.1821-0.001 -0.0694-0.000	CAT. 6 0.1809 (5 0.1794 (6 0.1765 (2 0.1760 (1 0.1762 (2 0.1769 (8 0.1803 (8 0.1754 (POJ/PTS 01.703691 CPB 0 0.0527 0.0527 0.0526 0.0528 0.0521 0.0518	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46 1243 46 1252 46 1252 46 1285 46	l. l. l. l.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014 -0.31 -0.0237 -0.82 -0.0662 -1.33 -0.0942	RE PER MHG PTS= CH -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411 0.1526 0.4781 0.6547	CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011 0.0165 0.0062 0.0093	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0939-0.000 -0.0123-0.002 -0.1821-0.001 -0.0694-0.000 -0.0993-0.001	CAT. 6 0.1809 0 5 0.1765 0 2 0.1765 0 1 0.1762 0 2 0.1769 0 8 0.1803 0 8 0.1754 0 0 0.1777 0	POJ/PTS 01.703691 CPB 0 0.0527 0 0.0527 0 0.0528 0 0.0521 0 0.0519 0 0.0518 0 0.0518 0 0.0518 0	= 20. L15 L15 L1282 46 L1267 46 L1237 46 L1232 46 L1243 46 L1252 46 L1253 46 L1253 46 L1253 46 L1253 46	1. 1. 1. 1. 1.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014 -0.31 -0.0237 -0.82 -0.0662 -1.33 -0.0942 -1.82 -0.1142	RE PER MHG PTS= CH -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411 0.1526 0.4781 0.6547 0.7613	CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011 0.0165 0.0062 0.0093 0.0169	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0939-0.000 -0.0123-0.002 -0.1821-0.001 -0.0694-0.000 -0.0993-0.001 -0.1684-0.002	CAT. 6 0.1809 0 5 0.1765 0 2 0.1760 0 1 0.1762 0 2 0.1769 6 8 0.1803 0 8 0.1803 0 0 0.1777 0	POJ/PTS 01.703691 CPB 0.0527 0.0527 0.0526 0.0523 0.0521 0.0521 0.0518 0	= 20. 115 1282 46. 1267 46. 1239 46. 1237 46. 1232 46. 1252 46. 1252 46. 1252 46. 1255 46. 1258 46.	1. 1. 1. 1. 1.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.27 0.2607 3.26 0.1924 2.24 0.1268 1.72 0.0905 1.22 0.0610 0.69 0.0274 0.20 -0.0014 -0.31 -0.0237 -0.82 -0.0662 -1.33 -0.0942	RE PER MHG PTS= CH -1.7871 -1.3016 -0.8423 -0.5910 -0.4007 -0.1652 0.0411 0.1526 0.4781 0.6547	CS -0.0003 0.0022 0.0041 0.0034 0.0061 0.0068 -0.0011 0.0165 0.0062 0.0093 0.0169 0.0224	6 T0= 90. CY CR -0.0459 0.001 -0.0676 0.000 -0.0796 0.000 -0.0939-0.000 -0.0123-0.002 -0.1821-0.001 -0.0694-0.000 -0.0993-0.001	CAT. 6 0.1809 (6 0.1765 (6 0.1765 (6 0.1765 (6 0.1765 (6 0.1765 (6 0.1769 (6 0.1769 (6 0.1803 (6 0.1767 (6 0.1767 (7 0.1766 (6 0.1766 (6 0.1767 (7 0.1766 (6	POJ/PTS 01.703691 CPB 0.0527 0.0527 0.0526 0.0523 0.0521 0.0518 0	= 20. 115 1282 46 1267 46 1239 46 1237 46 1232 46 1243 46 1252 46 1252 46 1252 46 1258 46 1258 46	1. 1. 1. 1. 1. 1.

;	HODEL 946.2	CON	FIG. 4.0	00 H	ACH 4.5	o .	PHI =	45.	
9	Q= 3.77 P\$I	RE PER	IN.= .48	E06 T0≈	90: D	EG.F	90.1/9	TS ≃	40.
1	PO= 400.0 CH	HG PTS=	.2659 P	SI		RUN NO	. 01703	69116	
ALPI	HA CN	CH	cs	CY	CR	CAT	CP8	CAF	RUN
								•	
4.		-1.7440	-0,0092	0.0141	0.0043	0.1697	0.0530	0.1166	
3.			-0.0062	-0-0070					
2 - 2			-0.0023	-0.0414					
1.			-0.0020	-0.0425					
1-3			-0.0023	-0.0360					_
	71 0.0166		-0.0048				0.0519		
	19 -0.0135		~0.0094				0.0518		
	31 -0.0367		0.0051	-0.0932					
	32 -0.0640		0.0078	-0.1179					
	32 -0.0981	0.6629		-0.1015					
	32 -0.1187		0.0151	-0.1801					
_	34 -0.1865	1.2510		-0-2044-					
-3.8	35 -0.2539	1.7295	0.0247	-0.2451-	-0-0003	0.1740	0.0525	0-1215	462.
1	10DEL 946.2	CONI	FIG. 4.00	00 H	ACH 4.50	0	PHI =	45.	•
(Q= 3.77 PSI	RE PER	IN.= .488	E06 T0=	90. D	EG.F	POJ/P1	rs = 1	.00-
£	0= 400.0 CM	IHG PTS=	•2659 PS	13	•	RUN NO	01703	59117	
ALPI	IA CN	СМ	cs	CY	CR	CAT	СРВ	CAF	RUN
4.2	26 0.2271	-1.5512	-0.0365	0.2150	0-0026	0-1698	0.0528	0.2170	463.
3.2			-0.0336				C-0530		
2.2			-0.0260				0.0527		
1.			-0.0353				0.0528		
1.2	21 0.0334	-0.2158	-0.0179				0.0523		
0.7	70 -0.0074	0.0913	-0.0243				0.0520		
	9 -0.0278		-0.0203				0.0518		
-0.3	31 -0.0621		-0.0170				0.0517		
-0.8	32 -0.0879	0.5952	-0.0117				0.0516		
-1.3	33 -0-1216	0.8258	-0.0110				0.0515		
-1.8	34 -0.1553	1.0586	-0.0081	-0-0118					
-2.8	35 -0.2109	1.4212	-0.0040	-0.0462	0.0005	0.1786	0.0516	0.1269	463.
-3.8	86 -0-2842	1.9520	0.0034	-0.1040-	0.0014	0.1829	0-0519	0.1310	463.

THE STATE OF THE S

MODEL 946.2	CGN	FIG. 4.00	90 H	ACH 4.50	0	PHI =	90,	
Q= 3.77 PSI	RE PER	IN.= .488	=06 TO=	90. DI	EG.F	P0J/P	TS =	•
PO= 400.0 C	MHG PTS=	.2659 PS	SI .		RÙN NO	. 01703	69113	
GLPHA CN	CH	cs	CY	CR	CAT	CPB	CAF	RUN
4.03 0.2549	-1.7495	0.0023	-0.0455	0.0052	0.1686	0-0528	0.1157	464.
3.03 0.1863	-1.2560	0.0037	-0.0572					
2.02 0.1216	-0.8088	0.0053	-0.0708					
1.49 0.0884	-0.5868		-0.0567					
0.98 0.0567	-0.3749		-0.6873					
0.45 0.0258	-0.1710		-0.0297					
-0.03 0.0052	-0.0430		-0.0318					
-0.54 -0.0327	0.2182	0.0014	-0.0321					
-1.05 -0.0628	0.4172	0.0058	-0.0770-					
-1.57 -0.0960		-0.0041		-0.0020				
-2.05 -0.1237	0.8276	0.0046	-0.0649 -0.0809-					
-3.06 ~0.1877	1.2677	0.0061 0.0076	-0.0843-					
-4.08 -0.2593	1.7800	0.0076	-0.0843-	C209 40-	0.7183	0.0522	0.1208	404.
MODEL 946.2		FIG. 4.00		እርዘ 4•50 ዓበ. በ፡		90.1/P		10.
MODEL 946.2 Q= 3.77 PSI		FIG. 4.00 IN.≃ .488		4.50 90. Di		PHI =		10.
	RE PER	IN.= .488	:06 T 0=		EG.F		TS =	10.
Q= 3.77 PSI	RE PER	IN.= .488	:06 T 0=		EG.F	50 1\ b.	TS =	lo. RUN
Q= 3.77 PSI PO= 400.0 C	RE PER	IN.= .488 .2659 PS	:06 T0≈	90. D	EG.F RUN NO. CAT	POJ/P ³ • 017030 • CPB	TS = 69119 CAF	RUN
Q= 3.77 PSI PO= 400.0 CI ALPHA CN	RE PER MHG PTS= CM	IN.= .486 .2659 PS CS -0.0007	606 TO=	90. Di	CAT	POJ/P CPB 0.0526	TS = 69119 CAF 0.1117	RUN 465 •
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.03 0.2547	RE PER MHG PTS= CM -1.7478	IN.= .486 .2659 PS CS -0.0007 0.0022	E06 T0= GI CY -0.0366	90. Di CR 0.0040 0.0023	CAT 0.1643 0.1636	POJ/P . 017036 CPB 0.0526 0.0528	TS = 69119 CAF 0.1117 0.1198	RUN 465 • 465 •
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862	RE PER MHG PTS= CM -1.7478 -1.2555	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006	CY -0.0366 -0.0326 -0.0326 -0.0056	90. Di CR 0.0040 0.0023 0.0018 0.0019	CAT 0.1643 0.1636 0.1661 0.1674	POJ/P 017036 CPB 0.0526 0.0528 0.0526 0.0523	TS = 69119 CAF 0.1117 0.1108 0.1135	RUN 465 • 465 • 465 •
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039	CY -0.0366 -0.0636 -0.0326 -0.0056 -0.0753	90. Da CR 0.0040 0.0023 0.0018 0.0019 0.0001	CAT 0.1643 0.1636 0.1661 0.1674 0.1611	POJ/P 017030 CPB 0.0526 0.0528 0.0526 0.0523 0.0521	TS = 69119 CAF 0.1117 0.1198 0.1152 0.1091	RUN 465. 465. 465. 465.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734	IN.= .486 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046	CY -0.0366 -0.0366 -0.0326 -0.0056 -0.0753 0.0103	90. De CR 0.0040 0.0023 0.0018 0.0019 0.0001	CAT 0.1643 0.1661 0.1661 0.1674 0.1611	POJ/P 017030 CPB 0.0526 0.0528 0.0526 0.0523 0.0521 0.0519	TS = 69119 CAF 0.1117 0.1198 0.1152 0.1191 0.1180	RUN 465. 465. 465. 465. 465.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087	CY -0.0366 -0.0366 -0.0326 -0.0056 -0.0753 0.0103 0.0519	90. De CR 0.0040 0.0023 0.0018 0.0019 0.0001 0.0002 0.0004	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669	POJ/P 017030 CPB 0.0526 0.0528 0.0526 0.0523 0.0521 0.0519 0.0517	TS = 69119 CAF 0.117 0.1198 0.1152 0.1091 0.1180 0.1152	RUN 465. 465. 465. 465. 465. 465.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027 -0.54 -0.0344	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214 0.2336	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087 0.0114	CY -0.0366 -0.0366 -0.0366 -0.0056 -0.0753 0.0103 0.0519 -0.1489	90. Di CR 0.0040 0.0023 0.0019 0.0001 0.0002 0.0004 0.0017	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669	POJ/P 017030 CPB 0.0526 0.0528 0.0523 0.0521 0.0519 0.0517 0.0516	TS = 69119 CAF 0.1117 0.1135 0.1152 0.1152 0.1152 0.1152	RUN 465. 465. 465. 465. 465. 465.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027 -0.54 -0.0344 -1.05 -0.0653	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214 0.2336 0.4373	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087 0.0114 -0.0014	CY -0.0366 -0.0366 -0.0366 -0.0366 -0.0056 -0.0753 0.0103 0.0519 -0.1489 -0.0224	90. De CR 0.0040 0.0023 0.0019 0.0001 0.0002 0.0004 0.0017 0.0011	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669 0.1669	POJ/P 017030 CPB 0.0526 0.0528 0.0523 0.0521 0.0519 0.0517 0.0516	TS = 69119 CAF 0.1117 0.1135 0.1152 0.1152 0.1152 0.1152 0.1152	RUN 465. 465. 465. 465. 465. 465. 465. 465.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027 -0.54 -0.0344 -1.05 -0.0653 -1.55 -0.0946	RE PER MHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214 0.2336 0.4373 0.6317	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087 0.0114 -0.0014 -0.0027	CY -0.0366 -0.0636 -0.0326 -0.0056 -0.0753 0.0103 0.0519 -0.1489 -0.0224 -0.0096	90. Di CR 0.0040 0.0023 0.0018 0.0019 0.0001 0.0002 0.0004 0.0017 0.0011	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669 0.16692 0.1677 0.1705	POJ/P O17036 CPB 0.0526 0.0528 0.0526 0.0521 0.0517 0.0516 0.0516	TS = 69119 CAF 0.1117 0.1198 0.1135 0.1152 0.1189 0.1152 0.1162 0.1189	RUN 465. 465. 465. 465. 465. 465. 465. 465.
Q= 3.77 PSI PO= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027 -0.54 -0.0344 -1.05 -0.0653 -1.55 -0.0946 -2.05 -0.1238	RE PER HHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214 0.2336 0.4373 0.6317 0.8299	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087 0.0114 -0.0027 0.0030	CY -0.0366 -0.0636 -0.0326 -0.0056 -0.0753 0.0103 0.0519 -0.1489 -0.0224 -0.0096 -0.0643-	90. De CR 0.0040 0.0023 0.0018 0.0019 0.0002 0.0004 0.0017 0.0011 0.0006 0.0030	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669 0.1669 0.1677 0.1705 0.1686	POJ/P O17036 CPB 0.0526 0.0528 0.0526 0.0523 0.0521 0.0519 0.0516 0.0516 0.0516	TS = 69119 CAF 0.1117 0.1198 0.1152 0.1091 0.1189 0.1175 0.1162 0.1189 0.1170	RUN 465. 465. 465. 465. 465. 465. 465. 465.
Q= 3.77 PSI P0= 400.0 CI ALPHA CN 4.03 0.2547 3.03 0.1862 2.01 0.1222 1.50 0.0866 0.99 0.0566 0.48 0.0265 -0.03 0.0027 -0.54 -0.0344 -1.05 -0.0653 -1.55 -0.0946	RE PER HHG PTS= CM -1.7478 -1.2555 -0.8136 -0.5723 -0.3726 -0.1734 -0.0214 0.2336 0.4373 0.6317 0.8299	IN.= .488 .2659 PS CS -0.0007 0.0022 -0.0006 -0.0033 0.0039 -0.0046 -0.0087 0.0114 -0.0014 -0.0027 0.0030 0.0032	CY -0.0366 -0.0636 -0.0326 -0.0056 -0.0753 0.0103 0.0519 -0.1489 -0.0224 -0.0096	90. De CR 0.0040 0.0023 0.0018 0.0019 0.0002 0.0004 0.0017 0.0011 0.0005 0.0030	CAT 0.1643 0.1636 0.1661 0.1674 0.1611 0.1699 0.1669 0.1697 0.1697 0.1705 0.1686 0.1740	POJ/P 017036 CPB 0.0526 0.0528 0.0526 0.0521 0.0519 0.0516 0.0516 0.0516 0.0516	TS = 69119 CAF 0.1117 0.1198 0.1152 0.1091 0.1152 0.1170 0.1162 0.1170 0.1222	RUN 465. 465. 465. 465. 465. 465. 465. 465.

HODEL 946.2	CONFIC	G. 4.005	AM	CH 4.50)	PHI =	904	
Q= 3.77 PS1	RE PER IN	N.= .49E06	10=	90. DE	:G.F	P03/P	rs =	20-
PO= 400.0 C	MHG PTS= .	.2659 PSI			RUN NO-	01703	59120	
ALPHA CN	CH	CS	CY	CR	CAT	CPB	CAF	RUN
4.03 0.2576	-1.7709 -0	0.9066 -0	0.0048	0.0041	0-1662	0.0530	0-1131	466.
3.05 0.1883	-1.2721 -0	0.0051 -0	0.0144	0.0024	0.1625	0.0532	0-1093	466.
2.01 0.1228	-0.8168 -0				0.1605			
1.49 0.0880	-0.5835 -0				0.1603			
0.99 0.0572	-0.3774 -				0.1676			
0.47 0.0263	-G.1719 -C				0.1674			
-0.05 0.0005	0.0017 -0				0.1640			
-0.54 -0.0338	0.2304 (0.1622			
-1.04 -0.0831	0.4230 -0				0-1635			
-1.56 -0.0955	0.6385 -0				0.1649			
-2.05 -0.1232	0.8183 -0				0.1660			
-3.06 -0.1896	1,2880 -0				0.1699			
-4.08 ~0.2588	1.7824 0	0.0060 -0	0.1083-	0.9014	0.1719	0.0525	0.1194	466.
HODEL 946.2 Q= 3.77 PSI		G. 4.000		CH 4.50		PHI =	90. S =	40•
Q= 3.77 PS1		4.= .48E06		90. DE		POJ/PI	rs =	40•
Q= 3.77 PS1	RE PER IN	4.= .48E06		90. DE	G.F	POJ/PI	rs =	40• 9UN
Q= 3.77 PSI PO= 400.0 C	RE PER IN	4.= .48E06 .2659 PSI CS	TG≃ CY	90. DE	G.F RUN NO.	POJ/P1 017036 CPB	rs = 69121 Caf	RUN
Q= 3.77 PSI 90= 400.0 C ALPHA CN	RE PER IN MHG PTS= .	4.= .48E06 .2659 PSI CS	TG= CY 0.6440	90. DE CR 0.0061	G.F RUN NO. CAT 0.1682	POJ/P1 - 017036 - CPB - 0.0527	TS = 59121 CAF 0.1154	RUN 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580	RE PER IN MHG PTS= . CM -1.7773 -0	4.= .48E06 .2659 PSI CS 0.0154 (TG= CY 0.6440 0.1001	90. DE CR 0.0061 0.0056	G.F RUN NO. CAT 0.1682 0.1632	POJ/P1 - 017036 - CPB - 0.0527 - 0.0530	TS = 59121 CAF 0.1154 0.1102	RUN 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887	RE PER IN MHG PTS= . CM -1.7773 -0 -1.2752 -0	CS 0.0154 0.0210 0.0167	TG= CY 0.6440 0.1001 0.0654	90. DE CR 0.0061 0.0056 0.0039	G.F RUN NO. CAT 0.1682	POJ/P1 - 017036 - CPB - 0.0527 9.0530 0.0525	S = 59121 CAF 0.1154 0.1102 0.1145	RUN 467. 457. 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0	CS 0.0154 0.0210 0.0167 0.0280	TG= CY 0.6440 0.1001 0.0654 0.1826	90. DE CR 0.0061 0.0056 0.0039 0.0026	CAT 0.1682 0.1632 0.1669	POJ/P1 - 017036 - CPB - 0.0527 9.0530 0.0525 0.0525	S = 59121 CAF 0.1154 0.1102 0.1145 0.1130	RUN 467. 457. 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0	CS 0.015% 0.0210 0.0167 0.0280 0.0278	TG= CY 0.6440 0.1001 0.0654 0.1826	90. DE CR C. 0061 0. 0056 0. 0039 0. 0026 0. 0040	CAT 0.1682 0.1632 0.1669 0.1655	POJ/P1 O17036 CPB 0.0527 9.0530 0.0525 0.0525	CAF 0.1154 0.1102 0.1145 0.1130 0.1131	RUN 467 • 457 • 467 • 467 •
Q= 3.77 PSI 90= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0 -0.3668 -0	CS 0.0154 0.0210 0.0167 0.0280 0.0278 0.0278	TG= CY 0.6440 0.1001 0.0654 0.1826 0.1835 0.1833	90. DE CR 0.0061 0.0056 0.0039 0.0026 0.0040 0.0034	CAT 0.1682 0.1682 0.1669 0.1655	POJ/P1 O17036 CPB 0.0527 9.0530 0.0525 0.0525 0.0522 0.0519	CAF 0.1154 0.1145 0.1130 0.1131 0.1190	RUN 467. 467. 467. 467. 467.
Q= 3.77 PSI 90= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009 -0.54 -0.0342	RE PER IN CH -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0 -0.3668 -0 -0.1618 -0 0.0106 -0 0.2339 -0	CS 0.0154 0.0210 0.0210 0.0280 0.0278 0.0278 0.0305	TG= CY 0.6440 0.1001 0.0654 0.1835 0.1833 0.2104 0.0789	90. DE CR C. 0061 O. 0056 U. 0039 O. 0026 O. 0040 O. 0034 O. 0030 U. 0030	CAT 0.1682 0.1632 0.1669 0.1655 0.1652 0.1709 0.1692 0.1658	POJ/P1 - 017036 - CPB - 0.0527 - 0.0530 - 0.0525 - 0.0525 - 0.0522 - 0.0519 - 0.0517	CAF CAF C.1154 C.1154 C.1165 C.1145 C.1131 C.1176 C.1176	RUN 467. 467. 467. 467. 467.
Q= 3.77 PSE 90= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009 -0.54 -0.0342 -1.04 -0.0642	RE PER IN CM -1.7773 -0 -1.2775 -0 -0.8209 -0 -0.5643 -0 -0.3663 -0 -0.1678 -0 0.0106 -0 0.2339 -0 0.4318 -0	CS 0.0154 0.0210 0.0210 0.0210 0.0280 0.0278 0.0278 0.0278 0.0278 0.0278	TG= CY 0.6440 0.1001 0.0654 0.1826 0.1835 0.1833 0.2104 0.0789 0.1361	90. DE CR C.0061 0.0056 0.0039 0.0026 0.0040 0.0034 0.0030 0.0043 0.0019	CAT 0.1682 0.1632 0.1655 0.1655 0.1652 0.1692 0.1698 0.1658	POJ/P1 - 017036 - CPB - 0.0527 9.0530 0.0525 0.0525 0.0522 0.0519 0.0517 0.0517	CAF CAF C.1154 C.1154 C.1165 C.1131 C.1131 C.1131 C.1141 C.1141	RUN 467. 467. 467. 467. 467. 467. 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009 -0.54 -0.0342 -1.04 -0.0642 -1.56 -0.0974	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0 -0.1618 -0 0.0196 -0 0.2339 -0 0.4318 -0 0.6572 -0	CS 0.0154 0.0210 0.0210 0.0210 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278 0.0278	TG= CY 0.6440 0.1001 0.0654 0.1826 0.1835 0.1833 0.2104 0.0789 0.1361	90. DE CR C. 0061 O. 0056 U. 0039 O. 0026 O. 0040 O. 0030 U. 0030 U. 0043 O. 0019 O. 0033	CAT 0.1682 0.1632 0.1655 0.1655 0.1709 0.1652 0.1658 0.1731 0.1683	POJ/P1 - 017036 - CPB - 0.0527 9.0530 0.0525 0.0525 0.0522 0.0519 0.0517 0.0516 0.0518	CAF CAF C.1154 C.1154 C.1165 C.1154 C.1131 C.1131 C.1141 C.1141 C.1214 C.1165	RUN 467. 457. 467. 467. 467. 467. 467.
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009 -0.54 -0.0342 -1.04 -0.0642 -1.56 -0.0974 -2.06 -0.1283	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0 -0.3662 -0 -0.1618 -0 0.0196 -0 0.2339 -0 0.4318 -0 0.6572 -0 0.8662 -0	CS 0.0154 0.0210 0.0167 0.0280 0.0278 0.0278 0.0305 0.0175 0.0232 0.0159 0.0173	TG= CY 0.0440 0.1001 0.0654 0.1826 0.1835 0.1833 0.2104 0.0789 0.1361 0.0622	90. DE CR 0.0061 0.0056 0.0039 0.0026 0.0040 0.0030 0.0043 0.0019 0.0033 0.0006	CAT 0.1682 0.1632 0.1669 0.1655 0.1652 0.1709 0.1692 0.1698 0.1731 0.1683	POJ/P1 - 017036 - CPB - 0.0527 9.0530 0.0525 0.0525 0.0522 0.0517 0.0517 0.0516 0.0518	CAF 0.1154 0.1102 0.1145 0.1130 0.1131 0.1190 0.1174 0.1141 0.1165 0.1591	RUN 467 - 457 - 467 - 467 - 467 - 467 - 467 - 467 - 467 -
Q= 3.77 PSI PO= 400.0 C ALPHA CN 4.03 0.2580 3.03 0.1887 2.01 0.1233 1.49 0.0862 0.97 0.0561 0.47 0.0260 -0.03 -0.0009 -0.54 -0.0342 -1.04 -0.0642 -1.56 -0.0974	RE PER IN CM -1.7773 -0 -1.2752 -0 -0.8209 -0 -0.5643 -0 -0.1618 -0 0.0196 -0 0.2339 -0 0.4318 -0 0.6572 -0	CS 0.0154 0.0210 0.0167 0.0280 0.0278 0.0278 0.0278 0.0230 0.0175 0.0232 0.0159 0.0173 0.0115	CY 0.6440 0.1001 0.0654 0.1826 0.1835 0.1833 0.2104 0.0789 0.1361 0.0622 0.0758-	90. DE CR C. 0061 0.0056 0.0039 0.0036 0.0034 0.0033 0.0033 0.0033 0.0033	CAT 0.1682 0.1632 0.1655 0.1655 0.1709 0.1652 0.1658 0.1731 0.1683	POJ/P1 017036 CPB 0.0527 0.0530 0.0525 0.0525 0.0522 0.0517 0.0517 0.0518 0.0518 0.0519	CAF CAF C.1154 O.1159 O.1176 O.1176 O.1176 O.1176 O.1176 O.1176 O.1176 O.1176	RUN 467 - 457 - 467 - 467 - 467 - 467 - 467 - 467 - 467 -

HU	DEL 946.2	CON	-1G. 4.0CO), 87	ICH 4.5	0	PHI =	90.	
Q=	3.77 PSI	RE PER	IN.= .48E0	6 70=	90. D	EG.F	P0J/P1	TS = 100.	
20	= 400.0 CH	HG PTS=	.2659 PSI	I		RUN NO-	01703	69122	
ALPHA	CN	CM	cs	CA	CR	CAT	CPB	CAF	RUN
4.04	0.2588	-1.7806	-0.0490	0.2752	0:0057	0.1785	0.0527	0.1.258	468.
3.03	0.1895	-1.2801	-0.0504	0.2948	0.0040	0.1778	0.0530	0-1242	468.
2.01	0-1232	-0.8166	-0.0531	0.3279	0.0028	0.1758	0.0528	0.1230	468.
1.50	0.0869	-0.5681	-0.0502	0.3014	0.0041	D.1799	0.0528	0.1271	468.
0.99	0.0545	-0.3473	-0.0559	0.3621	0.0010	0.1783	C.0522	0.1261	468.
0.47	0.0221	-0.1301	-0.0672	0.4764	0.0029	0.1798	0.0518	0.1280	468.
-0.03	-0.0041	0.0379	-0.G585	0.3882	0.0025	0.1794	0.0516	0.1278	468.
-0.54	-0.0373	0.2635	-0.0455	0.2593	0.0014	0.1789	0.0515	0.1274	468.
-1.04	-0.0681	0.4678	-0.0469	0.2733	8.0002	0-1816	0.0515	0.1301	468.
-1.55	-0.0982	0.6670	-0.0496	0.3004	0.0009	0.1815	0.0517	0-1297	468.
-2.05	-0.1307	0.8907	-0.0481	0.2849	0.0035	0.1885	0.0521	0.1365	468.
-3.07	-0.1938	1.3247	-0.0437	0.2397	-0.0007	0.1879	0.0524	0.1355	468.
-4.08	-0.2678	1.8630	-0.0380	0.1935	-0.0031	0,1886	0.0529	0.1356	468•

Appendix B Data from Test II

TABLE B-I. SCHEDULE FOR TEST II

Run No.	${ m M}_{\infty}$	Configuration ¹	ය (deg)	φ (deg)	P_{oj}/P_{∞}
1-6 7-12 13-19 20 21 22-28 29-35 36-42 43-49 50 51 52 53 54 55	1.75 2.0 2.5 2.0 1.75 3.0 3.5 4.0 4.5 1.75 2.05 2.55 3.05 4.05 4.55	0.00	Range c (1) ² Range α (1) 0	.	Range PR (1) ³ Range PR (2) ⁴ 0 0 Range PR (2) Range PR (2) Range PR (2) Range PR (1) Range PR (3) ⁶ Range PR (3) ⁶

¹ Figure 2 gives configuration nomenclature.

 $^{^2}$ Range α (1) is -4, -3, -2, -1.5, -1, -0.5, 0, 0.5, 1, 2, 3, and 4 degrees.

³Range PR (1) is $P_{oj}/P_{\infty} = 10$, 15, 20, 40, 70, and 80.

⁴Range PR (2) is $P_{oj}/P_{\infty} = 0$, 10, 15, 20, 40, 70, and 100.

⁵ Tunnel-off and jet force only data were obtained for the test section environment which corresponds to these Mach numbers.

⁶Range PR (3) is $P_{oj}/P_{\infty} = 10$, 15, 20, 40, 70, and 100.




FIGURE B-1. JET NORMAL FORCE COEFFICIENT VARIATION WITH PRESSURE RATIO




FIGURE B-2. SHADOWGRAPH FROM TEST II, P of P = 10



FIGURE B-3. SHADOWGRAPH FROM TEST II, P JP∞ = 15

FIGURE B-4. SHADOWGRAPH FROM TEST II, $P_{oj}/P_{\infty} = 20$




FIGURE B-5. SHADOWGRAPH FROM TEST II, P $_{\rm oj}/{\rm P_{\infty}}=40$

FIGURE B-6. SHADOWGRAPH FROM TEST II, $P_{oj}/P_{\infty} = 70$




FIGURE B-7. SHADOWGRAPH FROM TEST II, $P_{oj}/P_{\infty} = 100$

MODEL 9	46.3	CONFIG.	•0000	HACH 1.7	5	PHI =	0.	
Q= 8.21	PSI RE	PER IN.º	.48E06 1	0= 90. DI	EG.F	POJ/PT	S = .	
PO= 106	•O CMHG	PTS= 3.830	8 PSI		RUN NO.	025116	9108	
ALPHA C	K	CM PO	J PTS	POJ/PTS	CAT	CPB	CAF	RUN
4.16 0.19	998 -1.1	666 4.20	42 3.8308	1.0975	0.3459	0.1777	0.1681	21.
3.12 0.14		•				0.1721		21.
2.07 0.09						0.1696		21.
1.55 0.0						0.1697		21.
1.03 0.0						0.1700		21.
						0.1705		
0.49 0.03								21.
-0.03 -0.00		019 4.28				0.1708		21.
-0.56 -0.03		649 4.28				0.1713		21.
-1.08 -0.04		790 4.57				0.1711		21.
-1.61 -0.0		163 4.37				0.1710		21.
-2.12 -0.0		317 4.40			0.3407	0.1720	0.1687	21.
-3.17 -0.14	434 0.8	145 4.43	15 3.8308	1.1568	0.3453	0.1736	0,1717	21.
-4.21 -0.19	956 1.1	265 4.48	83 3.8308	1.1716	0.3596	0.1784	0.1812	21.
MODEL 94	46.3	CONFIG.	•0000	MACH 1.7	5	PHI =	0.	
Q= 8.21	PSI RE	PER IN.=	.48E06 1	0= 90. DI	EG.F	POJ/PT	S = 10.	
P0≈ 106	.O CMHS	PTS= 3.830	8 PSI		RUN NO.	024116	9102	
ALPHA C	N	CM PO	J PTS	POJ/PTS	CAT	СРВ	CAF	RUN
4.15 0.18	614 -1.0	582 38.26	40 3.8308	9.9886	0.3535	0.1776	0.1759	1.
3.10 0.17						0.1754		1.
2.06 0.0								i.
1.52 0.0						0.1743		i.
1.00 0.0		A				0.1743		î.
0.48 0.00						0.1751		1.
-0.05 -0.0		222 38.06				0.1745		
								1.
-0.58 -0.04					-	0.1743		1.
-1.10 -0.00		717 38.00				0.1730		1.
-1.62 -0.00		118 38.12				0.1727		1.
-2.14 -0.11		365 38.12				0.1729		1.
-3.18 -0.16		303 37.98				0.1734		1.
-4.23 - 0.21	154 1.2	563 38.17	90 3.8308	9.9663	0.3575	0.1758	0.1817	1.

The transfer of the second second of the sec

HODEL 946.3	CONI	FIG00	00	MACH 1.75		PHI =	0.	
Q= 8.21 PSI	RE PER	IN.= .40	E06 10	= 90. DE	G•F	POJ/P	TS =	15.
P0= 106.0 C	MHG PTS=	3.8308 P	SI		RUN NO.	. 02411	69103	
ALPHA CN	CM	POJ	PTS	POJ/PTS	CAT	CPB	SAF	RUN
4.14 0.1707	-0.9949	57.3250	3.8308	14.9640				
3.10 0.1185	-0.6773	57:3250	3.8308	14.9640				
2.05 0.0685 1.52 0.0420	-0.3797 -0.2242	57.2110 57.3530	3.8308 3.8308	14.9350 14.9720				
0.99 0.0188	-0.2242		3.8308	15.0760				
0.46 -0.0073	0.0639		3.8308	14.9500				
-0.C6 -0.0305	0.1952	57.4670	3.8308	15.0010				
-0.59 -0.0534	0.3221	56.8700	3.8308	14.8460				
-1.11 -0.0788	0.4742	57.2680	3.8308	14.9500				
-1.63 -0.1031	0.6144	57.2680	3.8308	14.9500				
-2.15 -0.1270	0.7543	57.2400	3.8308	14.9420				
-3.20 -0.1763	1.0402		3.8308	14.9350	0.3434	9.1757	0.1677	7 2.
-4.24 -0.2285	1.3547	57.2680	3.8308	14.9500	0.3612	0.1780	0.1832	2.
MODEL 946.3		FIG00		MACH 1.75		PHI =	0.	
MODEL 946.3 Q= 8.21 PS1		FIG00		MACH 1.75 □= 90. DE		PHI =		20.
	RE PER	IN.= .48	E06 T0)= 90• ŅE	G•F		TS =	20.
Q= 8.21 PSI	RE PER	IN.= .48	E06 T0)= 90• ŅE	G•F	POJ/P	TS =	20. RUŅ
Q= 8.21 PSI PO= 106.0 C	RE PER MHG PTS≈ CM	IN.= .48	EO6 TO)≖ 90• DE	G.F RUN NO.	POJ/P: . 02411 (. CPB	TS = 69104 CAF	RUŅ
Q= 8.21 PSI PO= 106.0 C ALPHA CN	RE PER MHG PTS≈ CM	IN.= .48 3.8308 P	EO6 TO	POJ/PTS 19.9180	G.F RUN NO. CAT 0.3519 0.3533	POJ/P: . 024110 CPB 0.1767 0.1765	TS = 69104 CAF 0.1852 0.1769	RUN 2 3. 3.
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557	RE PER MHG PTS≈ CM -0.9369 -0.6240 -0.2953	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.5000	PTS 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9700	G.F RUN NO. CAT 0.3519 0.3533 0.3490	POJ/P . 024110 CPB 0.1767 0.1765 0.1764	TS = 69104 CAF 0.1852 0.1769 0.1726	RUN 2 3. 3. 3.
Q= 8.21 PSI PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.5000 76.3290	PTS 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9700 19.9250	G.F RUN NO. CAT 0.3519 0.3533 0.3490 0.3575	POJ/P . 024110 CPB 0.1767 0.1765 0.1764 0.1750	TS = 69104 CAF 0.1852 0.1769 0.1726	RUN 2 3. 3. 3. 3.
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.5000 76.3290 76.3290	PTS 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9700 19.9250 19.9250	G.F RUN NO. CAT 0.3519 0.3533 0.3490 0.3575 0.3342	POJ/P: . 024110 CPB 0.1767 0.1765 0.1764 0.1750 0.1752	TS = 69104 CAF 0.1852 0.1769 0.1726 0.1825	RUN 2 3. 3. 3. 3. 3. 3. 3. 3.
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.5000 76.3290 76.3290 76.3580	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9700 19.9250 19.9250 19.9330	G.F RUN NO. CAT 0.3519 0.3573 0.3575 0.3342 0.3559	POJ/P. . 024110 . CPB 0.1767 0.1765 0.1764 0.1750 0.1752 0.1755	TS = 69104 CAF 0.1852 0.1726 0.1825 0.1825	RUN 2 3. 3. 3. 3. 3. 3. 3.
Q= 8.21 PS1 P0= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 ~0.0422	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0920 0.1537 0.2787	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.3290 76.3290 76.3580 76.1590	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9700 19.9250 19.9250 19.9330 19.8810	G.F RUN NO. CAT 0.3519 0.3575 0.3575 0.3342 0.3559 0.3559	POJ/P. . 024110 . CPB 0.1767 0.1765 0.1764 0.1750 0.1755 0.1759	CAF 0.1852 0.1726 0.1825 0.1825 0.1826 0.1864	RUN 2 3. 3. 3. 3. 3. 3. 3. 3.
Q= 8.21 PS1 P0= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 ~0.0422 -0.60 -0.0654	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537 0.2787 0.4101	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.3290 76.3290 76.3580 76.1590 75.8460	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9250 19.9250 19.9250 19.9330 19.8810 19.7990	G.F RUN NO. CAT 0.3519 0.3533 0.3575 0.3342 0.3559 0.3423 0.3391	POJ/P 024110 . CPB 0.1767 0.1765 0.1764 0.1750 0.1755 0.1759 0.1760	CAF 0.1852 0.1756 0.1726 0.1825 0.1825 0.1804 0.1664	RUN 2 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Q= 8.21 PS1 P0= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 ~0.0422 -0.60 -0.0654 -1.12 -0.0922	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537 0.2787 0.4101 0.5748	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.3290 76.3290 76.3580 76.3580 76.1590 75.8460 76.4430	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9250 19.9250 19.9330 19.8810 19.7990 19.9550	G.F RUN NO. CAT 0.3519 0.3533 0.3490 0.3575 0.3342 0.3559 0.3423 0.3391 0.3372	POJ/P 024110 . CPB 0.1767 0.1765 0.1764 0.1750 0.1759 0.1759 0.1760 0.1750	CAF 0.1852 0.1769 0.1825 0.1590 0.1804 0.1664 0.1630	RUN 2 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 ~0.0422 -0.60 -0.0654 -1.12 -0.0922 -1.64 -0.1155	RE PER MHG PTS≈ CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537 0.2787 0.4101 0.5748 0.7081	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.3290 76.3290 76.3580 76.3580 76.1590 75.8460 76.4430 76.3860	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9250 19.9250 19.9330 19.8810 19.7990 19.9550 19.9400	G.F RUN NO. CAT 0.3519 0.3533 0.3590 0.3559 0.3559 0.3423 0.3559 0.3478	POJ/P 024116 . CPB 0.1767 0.1765 0.1764 0.1750 0.1759 0.1759 0.1750 0.1757	CAF 0.1852 0.1769 0.1825 0.1590 0.1804 0.1664 0.1630 0.1621	RUN 2 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 -0.0422 -0.60 -0.0654 -1.12 -0.0922 -1.64 -0.1155 -2.17 -0.1398	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537 0.2787 0.4101 0.5748 0.7081 0.8483	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.5000 76.3290 76.3290 76.3580 76.1590 75.8460 76.3860 76.3860 76.3860	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9250 19.9250 19.9330 19.8810 19.7990 19.9550 19.9400 19.8880	G.F RUN NO. CAT 0.3519 0.3533 0.3490 0.3575 0.3342 0.3559 0.3423 0.3372 0.3478 0.3478	POJ/P. 024110 CPB 0.1767 0.1765 0.1764 0.1750 0.1752 0.1759 0.1759 0.1757 0.1764	CAF 0.1852 0.1769 0.1726 0.1825 0.1590 0.1664 0.1664 0.1621 0.1721	RUN 2 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3
Q= 8.21 PS1 PO= 106.0 C ALPHA CN 4.13 0.1619 3.08 0.1097 2.02 0.0557 1.51 0.0310 0.98 0.0056 0.45 -0.0197 -0.07 ~0.0422 -0.60 -0.0654 -1.12 -0.0922 -1.64 -0.1155	RE PER MHG PTS= CM -0.9369 -0.6240 -0.2953 -0.1486 0.0020 0.1537 0.2787 0.4101 0.5748 0.7081 0.8483	IN.= .48 3.8308 P POJ 76.3010 76.3860 76.3290 76.3290 76.3580 76.3580 76.1590 75.8460 76.4430 76.3860	PTS 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308 3.8308	POJ/PTS 19.9180 19.9400 19.9250 19.9250 19.9330 19.8810 19.7990 19.9550 19.9400 19.8880	G.F RUN NO. CAT 0.3519 0.3533 0.3490 0.3575 0.3342 0.3559 0.3423 0.3371 0.3371 0.3478 0.3494	POJ/P. O24110 CPB 0.1767 0.1765 0.1764 0.1750 0.1759 0.1769 0.1760 0.1757 0.1764	CAF 0.1852 0.1769 0.1804 0.1664 0.1630 0.1621 0.1721	RUN 2 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3

MODEL 946.3	CONFIG00	000 HACH 1	•75	PHI = 0	•
Q= 8.21 PS1	RE PER IN.= .48	3E06 T0≈ 90.	DEG.F	POJ/PTS =	40.
PC= 106.0 C	MHG PTS= 3.8308 F	129	RUN NO.	0241169105	
ALPHA CN	ĈE POJ	PTS POJ/P	TS CAT	CPB GAS	. RUN
	-0.6524 152.7400			0.1838 0.169	
3.04 0.0621	-0.3015 152.8600			0.1767 0.174	
1.98 0.0056	0.0549 152.8900			0.1768 0.163	
	0.2252 152.9400			0.1751 0.187	
0.94 -0.0459	0.3671 152.9100 0.5383 152.8000			0.1770 0.159	
	0.6844 152.9100			0.1767 0.176	
-0.63 -0.1227	0.8389 152.9400			0.1767 0.162	
-1.16 -0.1491	1.0057 152.8600			0.1775 0.168	
-1.68 -0.1720	1.1310 152.8300			0.1785 0.187	
-2.20 -0.1974				0.1789 0.176	•
-3.25 -0.2499					
-4.30 -0.3029	1.9210 152.7200			0.1799 0.176	
				?	
MODEL 946.3	CONFIG00	100 MACH 1	.75	PHI = 0.	
	CONFIG00				
Q= 8.21 PSI		iEg6 TO≈ 90.	DEG.F		
Q= 8.21 PSI	RS PER IN. ≠ .48	iEg6 TO≈ 90.	DEG.F RUN NO.	POJ/PTS =	70.
Q= 8.21 PSI PO= 106.0 C ALPHA CN	RE PER IN.= .48 MHG PTS= 3.8308 P CH POJ	8Eg6 TO≈ 90. SI PTS POJ/P	DEG.F RUN NO. TS CAT	POJ/PTS = . 0241169106 .CPB CAF	70. RUN
Q= 8.21 PSI PO= 106.0 C	RE PER IÑ.= .48 MHG PTS= 3.8308 P	Eg6 T0≈ 90. SI PTS POJ/P 3.8308 69.77	DEG.F RUN NO. TS CAT 90 0.3448	POJ/PTS = 0241269106	70. : RUN
Q= 8.21 PSI PO= 106.0 C ALPHA CN 4.03 0.0453 2.98 -0.0173	RE PER IÑ.= .48 MHG PTS= 3.8308 P CH POJ -0.1709-267.3100	EQ6 T0≈ 90. SI PTS POJ/P 3.8308 69.7? 3.8308 69.86	DEG.F RUN NO. TS CAT 90 0.3448 10 0.3568	POJ/PTS = . 0241169106 .CPB CAF 0.1885 0.156	70. RUN 2 5.
Q= 8.21 PSI PO= 106.0 C ALPHA CN 4.03 0.0453 2.98 -0.0173	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200	FIS POJ/P 3.8308 69.77 3.8308 69.86 3.8308 69.77	DEG.F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489	POJ/PTS = . 0241169106 .CPB CAF 0.1865 0.156 0.1814 0.175	70. RUN 2 5. 55 5.
Q= 8.21 PSI P0= 106.0 C ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400	PTS POJ/P 3.8308 69.77 3.8308 69.86 3.8308 69.87 3.8308 69.83	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3393 90 0.3525	POJ/PTS = .0241169106 .CPB	70. RUN 2 5. 5 5. 9 5. 3 5.
Q= 8.21 PSI PO= 106.0 C ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200	PTS POJ/P 3.8308 69.77 3.8308 69.86 3.8308 69.87 3.8308 69.83 3.8308 69.80	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3393 90 0.3525 10 0.3409	POJ/PTS = .0241169106 .CPB	70. RUN 2 5. 5. 9 5. 3 5. 2 5.
Q= 8.21 PSI P0= 106.0 CM ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.13 -0.1817	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.3906	PTS POJ/P 3.8308 69.77 3.8308 69.87 3.8308 69.87 3.8308 69.80 3.8308 69.80 3.8308 69.80	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3393 90 0.3525 10 0.3409 20 0.3466	POJ/PTS = .0241269106 .CPB	70. RUN 2 5. 5. 9 5. 3 5. 2 5. 0 5.
Q= 8.21 PSI P0= 106.0 CM ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.13 -0.1817 -0.70 -0.2095	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.3900 1.4839 267.3100	PTS POJ/P 3.8308 69.77 3.8308 69.77 3.8308 69.80 3.8308 69.83 3.8308 69.83 3.8308 69.83 3.8308 69.83	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3548 90 0.3489 90 0.3393 90 0.3525 10 0.3409 20 0.3466 90 0.3606	POJ/PTS = .0241269106 .CPB	70. RUN 2 5. 5. 9 5. 3 5. 2 5. 1 5.
Q= 8.21 PSI P0= 106.0 CI ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.17 -0.1817 -0.70 -0.2095 -1.22 -0.2367	RE PER IN.= .48 MHG PTS= 3.8308 P CH POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.3906 1.4839 267.3100 1.6551 267.5100	PTS POJ/P 3.8308 69.77 3.8308 69.77 3.8308 69.80 3.8308 69.83 3.8308 69.83 3.8308 69.83 3.8308 69.86 3.8308 69.86	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3525 10 0.3409 20 0.3466 90 0.3606 10 0.3414	POJ/PTS = .0241269106 .CPB	70. RUN 2 5. 55 5. 9 5. 3 5. 2 5. 1 5. 17 5.
Q= 8.21 PSI P0= 106.0 CR ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.13 -0.1817 -0.70 -0.2095 -1.22 -0.2367 -1.74 -0.2635	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.3906 1.4839 267.3100 1.6551 267.5100 1.8221 267.6200	PTS P0J/P 3.8308 69.86 3.8308 69.86 3.8308 69.80 3.8308 69.83 3.8308 69.80 3.8308 69.83 3.8308 69.83 3.8308 69.83	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3393 90 0.3525 10 0.3406 90 0.3606 10 0.3414 10 0.3505	POJ/PTS = . 0241169106 .CPB	70. RUN 2 5. 55 5. 9 5. 2 5. 1 5. 17 5. 18 5.
Q= 8.21 PSI P0= 106.0 C ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.17 -0.1817 -0.70 -0.2095 -1.22 -0.2367 -1.74 -0.2635 -2.27 -0.2874	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.6200 1.4839 267.3100 1.6551 267.5100 1.8221 267.6200 1.9637 267.4200	PTS PDJ/P 3.8308 69.77 3.8308 69.86 3.8308 69.80 3.8308 69.83 3.8308 69.80 3.8308 69.80 3.8308 69.80 3.8308 69.80 3.8308 69.80 3.8308 69.80	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3525 10 0.3409 20 0.3466 10 0.3666 10 0.3614 10 0.3505 90 0.3487	POJ/PTS = .0241169106 .CPB	70. RUN 2 5. 5 5. 9 5. 2 5. 1 5. 1 5. 5 5. 8 5.
Q= 8.21 PSI P0= 106.0 CR ALPHA CN 4.03 0.0453 2.98 -0.0173 1.92 -0.0727 1.40 -0.1031 0.87 -0.1328 0.35 -0.1592 -0.13 -0.1817 -0.70 -0.2095 -1.22 -0.2367 -1.74 -0.2635	RE PER IN.= .48 MHG PTS= 3.8308 P CM POJ -0.1709 267.3100 0.2474 267.6200 0.6006 267.3100 0.8066 267.4200 1.0062 267.5400 1.1739 267.6200 1.3037 267.3906 1.4839 267.3100 1.6551 267.5100 1.8221 267.6200	PTS PDJ/P 3.8308 69.77 3.8308 69.86 3.8308 69.80 3.8308 69.83 3.8308 69.80 3.8308 69.80 3.8308 69.83 3.8308 69.83 3.8308 69.83 3.8308 69.83 3.8308 69.83 3.8308 69.83	DEG. F RUN NO. TS CAT 90 0.3448 10 0.3568 90 0.3489 90 0.3393 90 0.3525 10 0.3409 20 0.3466 90 0.3666 10 0.3614 10 0.3505 90 0.3423	POJ/PTS = . 0241169106 .CPB	70. RUN 2 5. 5 5. 9 5. 2 5. 1 5. 1 5. 1 5. 2 5. 3 5. 5 5. 5 5. 5 5. 5 5. 6 5.

MOD	EL 946.3	CON	FIG00	CO	HAÇK 1.75	5	PHI =	8.	
Q=	8.21 PSI	RE'PER	IN.= .48	E06 T0	≈ 90. DE	G.F	SOJ/P.	rs ×	80.
P0=	106.0 C	KHG PTS=	3.8308 P	SI		RUN-ND.	02411	59107	
AL PHA	CN	Сн	POJ	PTS	P0J/PTS	ĊÁT	CPB	CAF	. RUN
4.01	0.0172	G.0257	305.6600		79.7900				
2.95	-0.0433	0.4251 3	305.8000	3.8308	79.8270	C-3493	0.1818	0.1675	6.
1.91	-0.0997	0.7954	305.5400	3.8306	79.7600	0.3626	0.1784.	0.1843	6.
1.38	-0.1308	1.0131 3	305.6900	3,8308	79.7980	0.3488	0.1786	0.1702	6.
0.85	-0.1598	1.1994	305.6600	3.8308	79.7900				
0-33	-0.1859	1.3650 3	305.6000	3.8308	79.7750	0.3450	0.1802	0.1648	6.
-0.20	-0.2130	1.5390 3	305.6300	3.8308	79.7830				
-0.72	-9.2409	1.7203 3	305.6300	3.8308	79.7830	0.3591	0.1820	0.1771	6.
-1.25	-0.2684	1.8960 3	305.6000	3.8308	79.7750	0.3399	0.1823	0.1576	6.
-1,77	-0.2941	2.0527 3	305.6600	3.8308	79.7900	0.3449	0.1810	0.1639	
	-0.3217		305.7400	3.8308	79.8120	0.3423	0.1805	0.1617	6.
-3.34	-G.3707	2.5101 3		3.8308					
-4.39	-0.4222	2.8160	305.6000	3.8308	79.7750	0.3495	0.1810	0.1685	6.
-	EL 946.3				MACH 2.00		PHI =	0.	
-	EL 946.3 8.13 PSI		FIG00 IN.= .48		MACH 2.00 = 90. DE		PH1 =		•
Q=	8.13 PSI		IÑ.= .48	E06 T0		EG.F		rs =	٠
Q=	8.13 PSI	RE PER	IÑ.= .48	E06 T0		EG.F RUN NO	POJ/P	rs =	• RUN
Q= P0=	8.13 PSI 118.0 C CN	RE PER	IN.= .48 2.9016 P POJ	EO6 TO	* 90. DE	EG.F RUN NO. CAT 0.3151	POJ/P' ., 02511; CPB 0.1568	TS = 59107 CAF 0.1582	20.
Q= PO= Alpha	8.13 PSI 118.0 C CN 0.2052	RE PER MHG PTS= CM	IN.= .48 2.9016 P POJ	EO6 TO SI PTS	POJ/PTS 1.2139 1.2237	EG.F RUN NO. CAT 0.3151 0.3213	POJ/P colored CPB 0.1568 0.1515	TS = 59107 CAF 0.1582 0.1698	20.
Q= PO= Alpha 4.19	8.13 PSI 118.0 C CN 0.2052 0.1517	RE PER MHG PYS= CM -1.1872	IN.= .48 2.9016 P POJ 3.5224	E06 T0 SI PTS 2.9016	POJ/PTS 1.2139 1.2237	EG.F RUN NO. CAT 0.3151 0.3213	POJ/P' ., 02511; CPB 0.1568	TS = 59107 CAF 0.1582 0.1698	20.
Q= PO= Alpha 4.19 3.13	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992	RE PER MHG PTS= CM -1.1872 -0.8706	IN.= .48 2.9016 P POJ 3.5224 3.5509	E06 T0 SI PTS 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139	CAT 0.3151 0.3213 0.3142 0.3138	POJ/P CPB 0.1568 0.1515 0.1516 0.1525	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614	2 20. 20. 20. 20.
Q= PO= Alpha 4.19 3.13 2.09	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224	PTS -2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2139	CAT 0.3151 0.3213 0.3142 0.3138 0.3162	POJ/P° CPB 0.1568 0.1515 0.1516 0.1525 0.1527	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614 0.1635	20. 20. 20. 20.
Q= PO= ALPHA 4.19 3.13 2.09 1.55 1.03	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5224	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2139 1.2139 1.2139 1.2139	CAT 0.3151 0.3213 0.3142 0.3138 0.3162 0.3186	POJ/P° CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536	TS = 59107 CAF 0.1582 0.1625 0.1614 0.1635	2 20. 20. 20. 20. 20.
Q= PO= ALPHA 4.19 3.13 2.09 1.55 1.03 0.50	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725	IN.= .48 2.9016 P POJ 3.5224 3.5224 3.5224 3.5224 3.5224 3.5509 3.5509	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2139 1.2139 1.2139 1.2139 1.2237	CAT 0.3151 0.3213 0.3142 0.3138 0.3162 0.3186 0.3133	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542	TS = 59107 CAF 0.1582 0.1625 0.1625 0.1614 0.1635 0.1650	2 20. 20. 20. 20. 20. 20.
Q= PO= ALPHA 4.19 3.13 2.09 1.55 1.03 0.50 -0.02	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482 0.0237 -0.0002 -0.0262	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725 -0.1340 -0.0012 0.1478	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5224 3.5509 3.5509 3.5509	E06 T0 SI PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2139 1.2237 1.2237	CAT 0.3151 0.3151 0.3142 0.3138 0.3162 0.3186 0.3133 0.3164	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542 0.1542	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614 0.1635 0.1650 0.1650	2 20. 20. 20. 20. 20. 20. 20. 20.
Q= PO= ALPHA 4.19 3.13 2.09 1.55 1.03 0.50 -0.02	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482 0.0237 -0.0002 -0.0262	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725 -0.1340 -0.0012	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5509 3.5509 3.5509 3.5793	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2139 1.2237 1.2237 1.2237 1.2237	CAT 0.3151 0.3151 0.3113 0.3142 0.3138 0.3164 0.3125	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542 0.1546 0.1556	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614 0.1635 0.1650 0.16592 0.1619	20. 20. 20. 20. 20. 20. 20. 20.
Q= PO= ALPHA 4.19 3.13 2.09 1.55 1.03 0.50 -0.02 -0.55 -1.07	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482 0.0237 -C.0002 -0.0262	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725 -0.1340 -0.0012 0.1478 0.2788 0.4249	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5224 3.5509 3.5509 3.5509	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2237 1.2237 1.2237 1.2237 1.2237	CAT 0.3151 0.3213 0.3142 0.3138 0.3162 0.3186 0.3133 0.3164 0.3125 0.3142	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542 0.1546 0.1556 0.1559	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614 0.1630 0.1650 0.16592 0.1619	2 20. 20. 20. 20. 20. 20. 20. 20. 20.
Q= PO= Alpha 4.19 3.13 2.09 1.55 1.03 0.50 -0.02 -0.55 -1.07 -1.60 -2.11	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482 0.0237 -0.0002 -0.0262 -0.0497 -0.0750 -0.0985	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725 -0.1340 -0.0012 0.1478 0.2788 0.4249 0.5551	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5509 3.5509 3.5509 3.5793	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2237 1.2237 1.2237 1.2237 1.2235 1.2335 1.2042	CAT 0.3151 0.3213 0.3142 0.3138 0.3162 0.3186 0.3133 0.3162 0.3162 0.3162 0.3163	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542 0.1546 0.1559 0.1559	TS = 59107 CAF 0.1582 0.1698 0.1625 0.1614 0.1635 0.1650 0.1650 0.1569	2 20. 20. 20. 20. 20. 20. 20. 20. 20. 20.
Q= PO= Alpha 4.19 3.13 2.09 1.55 1.03 0.50 -0.02 -0.55 -1.07 -1.60 -2.11	8.13 PSI 118.0 C CN 0.2052 0.1517 0.0992 0.0717 0.0482 0.0237 -0.0002 -0.0262 -0.0497 -0.0750 -0.0985	RE PER MHG PTS= CM -1.1872 -0.8706 -0.5615 -0.4011 -0.2725 -0.1340 -0.0012 0.1478 0.2788 0.4249	IN.= .48 2.9016 P POJ 3.5224 3.5509 3.5224 3.5509 3.5509 3.5509 3.5793	PTS 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016 2.9016	POJ/PTS 1.2139 1.2237 1.2139 1.2139 1.2237 1.2237 1.2237 1.2237 1.2237 1.2237 1.2237	CAT 0.3151 0.3213 0.3142 0.3138 0.3162 0.3186 0.3133 0.3164 0.3125 0.3142 0.3096 0.3185	POJ/P CPB 0.1568 0.1515 0.1516 0.1525 0.1527 0.1536 0.1542 0.1546 0.1556 0.1559	CAF 0.1582 0.1698 0.1625 0.1614 0.1635 0.1650 0.1563 0.1563	2 20. 20. 20. 20. 20. 20. 20. 20.

HODEL	946.3	CONF	FIG	0000	MACH 2.0	0 .	PHI =	0.	
Q= 8.	13 PSI	RE PER	IN.= .	48E06 T	0= 90. Di	EG.F	POJ/P	TS = 1	0.
bõ= T	18.0 CMH	> 512=	2.4019	h21		אטא אט.	. 024116	23108	
ALPHA	CN.	CM	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
4.17 0	.1888 -	1.0992	28.861	2.9016	9.9466	0.3278	0.1562	0.1716	7.
			28.776			0.3172			7.
		1.4507	28.9180			0.3149			7.
1.54 0		3.3039	28.805			0.3124			7.
		0.1616	28.833			0.3091			7.
0.49 0		0.0330	28.805			0.3115			7.
-0.04 -0		0.1009	28.890			0.3139			7.
-0.56 -0		2668	28.748			0.3190			7.
-1.09 -0		3.3857	28.947			0.3179			7.
-1.62 -0		0.5031	28.947			0.3239			7.
-2.13 -0				2.9016		0.3080			7.
-3.19 ~0				2.9016		0.3225			7.
-4.23 -0			28.776			0.3349			7.
	•								
MODEL	946.3	CONF	FIG(0000	MACH 2.0	0	PHI =	0.	
						•			•
Q= 8.	13 PSI	RE PER	IN.= .4	48E06 T	0= 90. DI	EG.F	POJ/P1	rs = 1	5.
PO= 1	18.0 CMH	S PTS=	2.9016	PSI	•	RUN NO	. 024116	59109	
ALPHA	CN	CH	POJ	PTS	POJ/PTS	CAT	СРВ	CAF	RUN
4.15 0	.1788 -1	L.0340	43.377	2.9016	14.9490	0-3295	0.1542	0-1753	8.
			43.2640						8.
2.05 0	_		43.4340						8.
1.53 0			43.349						8.
			43.3200	· - - -					8.
0.48 -0			43.3200						8.
-0.05 -0			43.3200						8.
-0.57 -0			43.3490						8,
-1.09 -0			43.320		14.9300				8.
-1.62 -0			43.3490				_		8.
-2.14 -0			43.3490		14.9390				8.
-2.14 -0 -3.19 -0		L.0449	43.320						8.
-4.24 -0		L.3644	43.3200		14.9300				8.
-4 a 2 4 -U	• 43U i	L+2044	72.2601	7 4 7 7 7 7 0	エサップコリリ	ロチンドスロ	ひ・エンソイ	0.1001	0.

HO	DEL 946.3	CON	FIG00	90	MACH 2.00	PHI =	0.	
Q=	8.13 PSI	RE PER	IN.= .48	E06 T0	= 90. DEG.F	P0J/P1	rs = 20.	
PO:	= 118.0 C	HG PTS=	2.9016 P	SI	RUN	NO. 02411	59110	
ALPHA	CN	CH	POJ	PTS	POJ/PTS C	AT CPB	-CAF	RUN
4.14		-0.9897		2.9016	19.9420 0.3			9.
3.09	0.1156	-0.6512	57.8080	2.9016	19.9220 0.3			9.
₹.04	0.0629	-0:3365	57.8650	2.9016	19.9420 0.3			9.
	0.0369		57.9500	2.9016	19.9710 0.3			9.
	0.0116	-0.0333		2.9016	19.9130 0.3			9.
	-0.0123		57.8080	2.9016	19.9220 0.3			9.
	-0.0368		57.8060	2,9016	19,9220 0,3			9.
	-0.0614	0.3841	57.7790	2.9016				9,
	-0.0859		57.8080	2.9016				9.
	-0.1112		57.9500		19.9710 0.3			9.
	-0.1340		57.8650	2.9016				9.
	-0.1864		57.8930		19.9520 0.3			9.
-4.25	-0.2403	1.4333	57-8550	2.9016	19.9420 0.3	228 Q.1600	0.1028	9.
мо	DEL 946.3	CON	FIG00	00	MACH 2:00	= 1H9	0.	
Q=	8.13 PSI	RE PER	IN.= .48	E06 T0	= 90. DEG.F	POJ/P1	rs = 40.	
P0:	= 118.0 C	MHG PTS=	2.9016 P	SI	RUN	NO. 024116	59111	
ALPHA	CN	CM	POJ	PTS	POJ/PTS C	AT CP8	CAF	RUN
4.12	0.1423	-0.8258	115.3900	2.9016	39.7670 0.3	311 0.1558	0-1753	10.
3.06			115.4200	2.9016	39.7760 0.3			10.
2.02		-0.0913		2.9016	39.7760 0.3			10.
1.49			115.5000	2.9016	39.8060 0.3			10,
	-0.0247		115.4200	2.9016	39.7760 0.2			10.
	-0.0522		115.5600	2.9016	39.8250 0.3			10.
	-0.0767		115.4700	2.9016	39.7960 0.3			10.
-0.0Y	-0.1024	0.6784	115.3900	2:9016	39:7670 0.3	212 0.1566	0.1646	10.
	-0.1024 -0.1273			2.9016 2.9016				10.
-1.13		0.8250	115.3900 115.5300		39.8160 0.3	264 0.1568	0.1696	
-1.13 -1.66	-0.1273	0.8250 0.9678	115:3900	2.9016	39.8160 0.3	264 0.1568 182 0.1563	0.1696 0.1620	10.
-1.13 -1.66 -2.19	-0.1273 -0.1522	0.8250 0.9678 1.1186	115.3900 115.5300 115.5600	2.9016	39.8160 0.3 39.8250 0.3	264 0.1568 182 0.1563 262 0.1565	0.1696 0.1620 0.1697	10. 10.

MOVEL 946.3	CONFIG0	000 MACH 2.00	PHI = 0.	
Q= 8.13 PS1	RE PER IN.= .4	8EC6 TO= 90. DEG.	POJ/PTS = 70.	
PO= 118.0 C	CHHG PTS= 2.9016	PSI RU:	ł NG. 0241169112	
ALPHA CN	CH POJ	PTS POJ/PTS (CAT CPB CAF R	RŲN
4.06 0.0882	-0.4841 202.3100		3246 0.1609 0.1637 1	11.
3.01 0.0252	-0.0677 202.3400			11.
1.96 -0.0334	0.3110 202.4000			11.
1.44 -0.0612	0.4895 202.2300			ll.
0.92 -0.0897	0.6750 202.4300			11.
0.39 -0.1172	0.8475 202.3100			1.
-0.14 -0.1424	1.0010 202.4300			11.
-0.66 -0.1692	1-1655 202-4000			ll.
-1.19 - 0.1948	1.3200 202.3400			ll.
-1.71 -0.2204				ll.
-2.23 -0.2479				1.
-3.28 -0.2996	1.9502 202.2300			11.
-4.33 -0.3546	2.2806 202.3100	2.9016 69.7240 0.3	377 0.1627 0.1750 1	11.
HODEL 946.3 Q= 8.13 PSI			PHI = 0. = POJ/PTS = 100.	
4- 0-73 1.21	RE PER IN	0500 10- 90. DEG.	- PUJ/P15 = 100.	
PC= 118.0 C	MHG PTS= 2.9016.	PŞI RUM	NO. 0241169113	
ALPHA CN	CH DOT	PTS POJ/PTS (CAT CPB CAF R	RUN
4.02 0.0274	-0.0830 289.4400	2.9016 99.7490 0.3	3258 0.1641 0.1617 1	.2.
2.97 -0.0355	0.3409 299.5800			2.
1.92 ~0.0958	0.7431 289.2700			2.
1.39 -0.1255				2.
0.86 -0.1543	1.1335 289.4400			.2.
0.34 -0.1851	1.3402 289.4400			2.
-0.19 -0.2110	1.5024 289.2700		· · · · · · · · · · · · · · · · · · ·	2.
-0.70 -0.2363	1.6564 289.5200			2.
-1.23 -0.2630	1.8221 289.2700			2.
-1.76 -0.2905	1.9921 287.4400			2.
-2.28 -0.3183	2.1674 289.3500			2.
-3.33 -0.3689	2.4602 289.2700			2.
-4.38 -0.4217				

THE REPORT OF THE PROPERTY OF

HODE	EL 946.3	CONF	1G000	0 . F	MCH 2.50		PRI =	0.	
Q= 7	7.39 PSI	RE PER	IN.= .48E	06 TO=	90. DE	G.F	FOJ/PT	s * •	
		HG PTS=							
ALPHA	CN	CH	POJ		POJPPTS			ÇAF	RUN
ALFIIA	411	-						0 1544	13.
4.11	0.2188	-1.3271		1,6893	1.1435	0.2841	0.1262	0.1500 0.1500	13.
3.C7	0.1609	-0.9656	1.9317	1.6893	1.1267	U. 2167	0 1247	0.1511 0.1511	13.
2.02	0-1037	-0,6137	1.9033	1.6393	1.1267	0.2120	0.1240	0.1511	13.
	0.0743	-0.4345	1.9033	1.6893	1.0762	0.2(0U	0.6677 0.1767	0.1508	13.
0.93	0.0498	-0.2973	1.8180	1.6893	1.1267	0.2122	0.1249	9441 B	13.
0.44	0.0224	-0.1322	1.9033	1.6893	1.1261	0.2710	0.1267	0.1407	13.
	-0.0034	0.0193	1.9317	1.6893	1.1267	6 4774	0.1261	0.1508	19.
	-0.0299	0:1742	1.9033	1.6893	1.1603	0.2722	0.1290	0.1452	13.
-1.12	-0.0573	0.3402	1.9601	1.6893	1.1603	0.2811	0.1200	0.1523	13.
	-0.0831	0.4908	1.9601	1.6893		0.2011	6 1200	0.120	13.
-2.16	-0.1088	0.6428	1.9601	1.6893		0.2793	0.125E	ADA!	13.
-3.21	-0.1643	0.9835	2.0169	1.6893		0.2835	0 1217	0.1518	13.
-4.25	-0.2271	1.3886	2.0169	1.6893	1.1939	0.2050	4.1311	0.1510	204
мор)EL 946.3	CON	FIG00	00 ~	HACH 2.50)	PHI =	0.	•
Q=	7.39 PSI	RE PER	IN.= .48	E06 T0	= 90. DE	EG.F	P01/P	TS = 10.	•
PO=	= 150.0 0	HHG PTS=	1.6893 P	SI		RUN NO.	02511	69101	
					POJ/PTS	CÁT	CDR	CAF	RUN
ALPHA	-CN	CM	P0J	PTS	PUJ/P13	LAI	CPP	UNI	1,011
					0 3720	0 2764	0.1223	0.1531	14.
	0.2126	-1.3085	16.8450	1.6893	10.0060	0 2713	0.1253	0.1459	14.
3.07	0.1502	-0.9109	16.9020	1.6893	TO-DODD	0.2113	041275	0.1423	14.
2.03					A - A 7 7 A	A 767R	0.1255		
		-0.5584	16.8450	1.6893	9:9720	0.2678	0.1255	0.1414	14.
1.50		-0.3896	16.8450	1.6893	9.9720	0.2665	0.1251	0.1414	14. 14.
1.50 0.98	0.0649	-0.3896 -0.2242	16.8450 16.8450	1.6893	9.9720 9.9720	0.2665	0.1251	0.1414 0.1411	14.
0.98	0.0649 0.0379 0.0134	-0.3896 -0.2242 -0.0870	16.8450 16.8450 16.9300	1.6893 1.6893 1.6893	9.9720 9.9720	0.2665 0.2666 0.2638	0.1251 0.1255 0.1262	0.1414 0.1411 0.1375	14. 14.
0.98 0.46 -0.07	0.0649 0.0379 0.0134 -0.0140	-0.3896 -0.2242 -0.0870 0.0798	16.8450 16.8450 16.9300 16.9020	1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220	0.2665 0.2666 0.2638 0.2701	0.1251 0.1255 0.1262 0.1274	0.1414 0.1411 0.1375 0.1428	14. 14. 14.
0.98 0.46 -0.07 -0.59	0.0649 0.0379 0.0134 -0.0140 -0.0402	-0.3896 -0.2242 -0.0870 0.0798 0.2337	16.8450 16.8450 16.9300 16.9020 16.8170	1.6893 1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220 10.0060 9.9552	0.2665 0.2666 0.2638 0.2701 0.2680	0.1251 0.1255 0.1262 0.1274 0.1278	0.1414 0.1411 0.1375 0.1428 0.1402	14. 14. 14. 14.
0.98 0.46 -0.07 -0.59 -1.07	0.0649 0.0379 0.0134 -0.0140 -0.0402 -0.0675	-0.3896 -0.2242 -0.0870 0.0798 0.2337 0.3993	16.8450 16.8450 16.9300 16.9020 16.8170 16.7030	1.6893 1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220 10.0060 9.9552 9.8879	0.2665 0.2666 0.2638 0.2701 0.2680	0.1251 0.1255 0.1262 0.1274 0.1278 0.1280	0.1414 0.1411 0.1375 0.1428 0.1402 0.1416	14. 14. 14. 14.
0.98 0.46 -0.07 -0.59 -1.07	0.0649 0.0379 0.0134 -0.0140 -0.0402 -0.0675 -0.0941	-0.3896 -0.2242 -0.0870 0.0798 0.2337 0.3993 0.5554	16.8450 16.8450 16.9300 16.9020 16.8170 16.7030 16.8170	1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220 10.0060 9.9552 9.8879	0.2665 0.2666 0.2638 0.2701 0.2680 0.2696	0.1251 0.1255 0.1262 0.1274 0.1278 0.1280 0.1278	0.1414 0.1411 0.1375 0.1428 0.1402 0.1416 0.1483	14. 14. 14. 14. 14.
0.98 0.46 -0.07 -0.59 -1.07 -1.64 -2.16	0.0649 9.0379 0.0134 -0.0140 -0.0675 -0.0941 -0.1202	-0.3896 -0.2242 -0.0870 0.0798 0.2337 0.3993 0.5554 0.7115	16.8450 16.8450 16.9300 16.9020 16.8170 16.7030 16.8170 16.7880	1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220 10.0060 9.9552 9.8879 9.9552	0.2665 0.2666 0.2638 0.2701 0.2680 0.2696 0.2761	0.1251 0.1255 0.1262 0.1274 0.1278 0.1280 0.1278	0.1414 0.1411 0.1375 0.1428 0.1492 0.1416 0.1483 0.1491	14. 14. 14. 14.
0.98 0.46 -0.07 -0.59 -1.07 -1.64 -2.16	0.0649 9.0379 0.0134 -0.0140 -0.0402 -0.0675 -0.0941	-0.3896 -0.2242 -0.0870 0.0798 0.2337 0.3993 0.5554 0.7115	16.8450 16.8450 16.9300 16.9020 16.8170 16.7030 16.8170	1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	9.9720 9.9720 10.0220 10.0060 9.9552 9.8879 9.9552 9.9383 9.9720	0.2665 0.2666 0.2638 0.2701 0.2680 0.2696 0.2761 0.2770	0.1251 0.1255 0.1262 0.1274 0.1278 0.1278 0.1279 0.1279	0.1414 0.1411 0.1375 0.1428 0.1402 0.1416 0.1483	14. 14. 14. 14. 14. 14.

	-MO	DEL	946.3		CON	FIG.	.00	00	į	IACH 2	.50		PHI	=	0.		
	Q=	7.39	9 PS I	R	E FER	IN.=	. 43	E05	10:	- 90.	DS	EG.F	P0:14	PTS	S =	15.	
													•				
	20	= 150	0.0 C	HHG	PTS=	1.68	93 P	SI				RUN NO	. 0251	169	9102		
i	LPHA	. (CN		CH	P	លរ	P1	s	POJ/P	TS	CAT	CPE	3	CAF		RUN
	4.12		2024		2362	25.2		1.68				0.2634					15.
	3,07		1429		8621	25.3		1.68				0.2792					15.
	2.02		C833		4893	25.3						0.2788					15.
	1.50		0563		3265	25.3		1.65				0.2759					15.
	0.95	-			1754	25.3						0.2753					15.
		0.0			0207	25.4						0.2786					15。
		-0.0			1322	25.2		1.68				0.2780					15.
		-0.0			2956	25.2						0.2805					15,
		-0-0				25.3						0.2822					15.
		-0.			6167	25.3						0.2809					15.
		-0.1				25.3						0.2779					15.
		-0.			1048	25.3						0.2791					15.
-	4.25	-0.2	2446	1.	4991	25.3	390	1.65	193	15.00	00	0.2871	0.129	1 0	.1580)	15.
	но	DEL 9	946 <u>.</u> 3		CONI	FIG.	.00	00	2	IAÇH 2	.50	3	ЙНІ	=	0.		
	Q=	7.39	9 P\$I	R	E PER	18.=	-48	E06	T0=	90.	DE	G.F	POJA	PTS	, <u>=</u>	20.	
	PO	= 150	0.0 C	MHG	PTS=	1.68	93 P	SI				RUN NO	. 0251	169	103		
,	LPHA	. (CN		CM	P	อง	PΊ	s	P0J/P	TS	CAT	CPE	3	CAF		RUN
	4.11	0.1	1963	-1.	2005	33.8	330	1.68	93	20.02	80	0.2875	G-123	0 0	1645	5	16.
	3.06		1351		8098	33.7		1.68				0.2871					16.
	2.02		2776		4559	33.8		1.68	-			0.2829					16.
	1.49		0506			33.8		1.68			_	0.2793					16.
	0.97		0241		1356	33.8		1.68				0.2786					16.
		-0.0			0257	33.8		1.68				0.2796					16.
•		-0.0			1737	33.8		1.68				0.2759					16.
		-0.0			3470	33.7		1.68				0.2915					16.
		-0-0			4840	33.8		1.68				0.2701					16.
		-0.1			6432	33.7						0.2757					16.
		-0.1			8020	33.7		1.68				0.2865					16.
		-0.			1498	33.7		1.68				0.2816					16.
		-0.2		_		33.7		1.68				0.2881					16.

HCDEL 94	6.3 COP	NFIG00	00	MACH 2.50	;	PHI =	0.	
Q= 7.39	PSI RE PER	R IN.= .48	E06 TC	= 90. DE	G.F	POJ/P	rs =	40.
PC= 150.	O CMHG PTS:	= 1.6893 P	SI		RUN NO.	02511	59104	
ALPHA CN	CH	POJ	PTS	PCJ/PTS	CAT	CPB	CAF	RUN
4.10 0.17			1.6893					
3.04 0.11				39.8710				
1.99 0.05		67.3530	1.6893					
7 0.02			1.6893					
	0.0134			39.8370				
0.43 -0.02	70 0.1788	67.2670	1.6893					
	39 0.3447			39.8710				
-0.62 -0.07				39.8540				
-1.14 -0.10			1,6893	39.8710	0.2817	0.1286	0.1531	17.
-1.67 -0.13				39.8540				
-2.18 -0.15								
-3.23 -0.21		67.2960		39.8370				
-4.27 -0.27	56 1.7060	67.0400	1.6893	39.6860	0.2834	0.1284	0.1551	17.
						_		
	6.9 CO! PSI RE PER					PHI =		70.
Q= 7.39		R IN.= .48	E06 TC	= 90. DE	G.F		rs = .	70•
Q= 7.39	PSI RE PER O CMHG PTS:	R IN.= .48	E06 TC	= 90. DE	G.F RUN NO.	POJ/P	rs = .	
Q= 7.39 PO= 150. ALPHA CN 4.06 0.13	PS1 RE PER 0 CMHG PTS= CM 94 -0.8751	R IN.= .48 = 1.6893 P POJ 112.0000	E06 TC SI PTS 1.6893	= 90. DE POJ/PTS 69.8540	G.F RUN NO. CAT 0.2900	POJ/P 025110 CPB 0-1262	7S = 59105 CAF 0.1637	RUN 7 18.
Q= 7.39 PO= 150. ALPHA CN 4.06 0.13	PSI RE PER O CMHG PTS: CM 94 -0.8751 67 -0.4677	R IN.= .48 = 1.6893 P POJ 112.0000 118.1200	E06 TC SI PTS 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210	G.F RUN NO. CAT 0.2900 0.2803	POJ/P* . 02511(CPB 0.1262 0.1233	7S = 59105 CAF 0.1637 0.1570	RUN 7 18. 0 18.
Q= 7.39 PO= 150. ALPHA CN 4.06 0.13	PSI RE PER O CMHG PTS: CM 94 -0.8751 67 -0.4677	R IN.= .48 = 1.6893 P POJ 112.0000	E06 TC SI PTS 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550	G.F RUN NO. CAT 0.2900 0.2803 0.2774	POJ/P* . 025110 . CPB 0.1262 0.1233 0.1231	7S = 59105 CAF 0.1637 0.1570 0.1543	RUN 7 18. 18. 18.
Q= 7.39 PO= 150.0 ALPHA CN 4.06 0.13 3.01 0.07	PSI RE PER O CMHG PTS: CM 94 -0.8751 67 -0.4677 72 -0.0838	R IN.= .48 = 1.6893 P POJ 112.0000 118.1200	E06 TC SI PTS 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2760	POJ/P 025110 CPB 0.1262 0.1233 0.1231 0.1245	7S = 59105 CAF 0.1637 0.1570 0.1543	RUN 7 18. 18. 18. 18.
Q= 7.39 PO= 150.0 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823	POJ 112.0000 118.1200 118.0900 118.0900	PTS 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050	G.F RUN NG. CAT 0.2900 0.2803 0.2774 0.2760 0.2761	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253	7S = 59105 CAF 0.1637 0.1570 0.1543 0.1515	RUN 7 18. 18. 18. 18. 18. 18.
Q= 7.39 PO= 150.0 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.94 -0.01 0.92 -0.04 0.39 -0.06	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648	POJ 112.0000 118.1200 118.0900 118.0900 118.0900 118.0900	PTS 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050	G.F RUN NG. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260	7S = 69105 CAF 0.1637 0.1576 0.1543 0.1515 0.1506 0.1495	RUN 7 18. 18. 18. 18. 18. 18. 18.
Q= 7.39 PO= 150.6 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132	POJ 112.0000 118.1200 118.0900 118.0900 118.0900 118.0900 118.1200	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050 69.9050	G.F RUN NG. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755 0.2779	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275	7S = 69105 CAF 0.1637 0.1576 0.1543 0.1515 0.1506 0.1495 0.1506	RUN 7 18. 18. 18. 18. 18. 18. 18.
Q= 7.39 PO= 150.6 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620	POJ 112.0000 118.1200 118.0900 118.0900 118.0900 118.0900 118.0900 118.0900	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050 69.9210 69.8710	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755 0.2779 0.2750	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1283	7S = 59105 CAF 0.1637 0.1543 0.1515 0.1506 0.1495 0.1504	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18
Q= 7.39 PO= 150.6 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11 -1.17 -0.14	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620 69 0.9365	POJ 112.0000 118.1200 118.0900 118.0900 118.0900 118.0900 118.1200 118.1200 118.1700	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050 69.9210 69.8710 69.9550	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2761 0.2765 0.2759 0.2759 0.2750	POJ/P . 025110 . CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1283 0.1292	7S = 59105 CAF 0.1637 0.1570 0.1543 0.1515 0.1504 0.1495	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18
C= 7.39 PO= 150. ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11 -1.17 -0.14 -1.69 -0.17	PSI RE PER 0 CMHG PTS: CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620 69 0.9365 38 1.0989	POJ 112.0000 118.1200 118.0900 118.0900 118.0900 118.1200 118.1200 118.1200 118.1200 118.0300 118.1700	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050 69.9210 69.8710 69.8880	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755 0.2779 0.2750	POJ/P 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1283 0.1283 0.1292	CAF 0.1637 0.1570 0.1543 0.1506 0.1498 0.1467 0.1468	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18
Q= 7.39 PO= 150.6 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11 -1.17 -0.14 -1.69 -0.17 -2.22 -0.20	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620 69 0.9365 38 1.0989 20 1.2756	POJ 112.0000 118.1200 118.1700 118.0900 118.0900 118.0900 118.1200 118.1700 118.0300 118.1700 118.1700	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9050 69.9050 69.9050 69.9210 69.8750 69.8880 69.9380	G.F RUN NG. CAT 0.2900 0.2803 0.2774 0.2761 0.2755 0.2779 0.2750 0.2751 0.2730	POJ/P 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1283 0.1291 0.1291	CAF 0.1637 0.1570 0.1543 0.1508 0.1495 0.1407 0.1439 0.1439	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18
Q= 7.39 PO= 150.0 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11 -1.17 -0.14 -1.69 -0.17 -2.22 -0.20 -3.26 -0.25	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620 69 0.9365 38 1.0989 20 1.2756 87 1.6301	POJ 112.0000 118.1200 118.1700 118.0900 118.1200 118.1200 118.1200 118.1200 118.1200 118.1200 118.1200 118.0300 118.1200	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9550 69.9050 69.9050 69.8710 69.8710 69.8880 69.9380 69.9050	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755 0.2779 0.2750 0.2751 0.2730 0.2762 0.2749	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1282 0.1291 0.1282 0.1274	CAF 0.1637 0.1570 0.1543 0.1506 0.1495 0.1495 0.1467 0.1458 0.1467	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18
Q= 7.39 PO= 150.6 ALPHA CN 4.06 0.13 3.01 0.07 1.97 0.01 1.44 -0.01 0.92 -0.04 0.39 -0.06 -0.13 -0.09 -0.66 -0.11 -1.17 -0.14 -1.69 -0.17 -2.22 -0.20	PSI RE PER 0 CMHG PTS= CM 94 -0.8751 67 -0.4677 72 -0.0838 10 0.0929 03 0.2823 89 0.4648 38 0.6132 91 0.7620 69 0.9365 38 1.0989 20 1.2756 87 1.6301	POJ 112.0000 118.1200 118.1700 118.0900 118.0900 118.0900 118.1200 118.1700 118.0300 118.1700 118.1700	PTS 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893 1.6893	= 90. DE POJ/PTS 69.8540 69.9210 69.9050 69.9050 69.9050 69.9210 69.8750 69.8880 69.9380	G.F RUN NO. CAT 0.2900 0.2803 0.2774 0.2760 0.2761 0.2755 0.2779 0.2750 0.2751 0.2730 0.2762 0.2749	POJ/P . 025110 CPB 0.1262 0.1233 0.1231 0.1245 0.1253 0.1260 0.1275 0.1282 0.1291 0.1282 0.1274	CAF 0.1637 0.1570 0.1543 0.1506 0.1495 0.1495 0.1467 0.1458 0.1467	RUN 18. 18. 18. 18. 18. 18. 18. 18. 18. 18

	DEL 946.3	CON	FIGOC	000	MACH 2.5	0	PHI =	0.	
Q=	7.39 PSI	RE PÉR	IN.= .48	SEČ6 TO	2= 90. DI	EG.F	P0J/P	TS =	100.
P0=	= 150.0 C	MHG PTS=	1.6893 P	12		RUN NO	. 02511	69106	
ALPHA	CN	CH	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
	0.1023		168.7100	1.6893	99.8710				
	0.0371		168.6500	1.6893	99.8370				
	-0.0239		168.5900	1.6893	99.8040.				
	-0.0545		168.6800	1.6893	99.8540				
	-0.0814		168.5900	1.6893	99.8040				
	-0.1103		168.6800	1.6893	99.8540				
	-0.1377		168.5900	1.6893	99.8040				
	-0.1658		168.6500	1.6893	99.8370				
-1.20	-0.1919		168.5700	1.6893	99.7870				
	-0.2205		168.5900	1.6893	99.8040				
-2.25	-0.2482	1.6112	168.5700	1.6893					
					99.7870				
-4.34	-0.3657	2.3480	168.5700	1.6893	99.7870	0.2779	0.1270	0.1509	9 19.
	EL 946.3		FIG00	-	MACH 3.00		PHI =	-	
			FIG00 IN.= .48	-	MACH 3.00		PHI =	-	•
Q≃	6.34 PSI	RE PER		E06 T0		G.F		TS =	•
Q≃	6.34 PSI	RE PER	IN.= .48	E06 T0		G.F	POJ/P	TS =	• Run
Q= PO= ALPHA	6.34 PSI = 192.0 C	RE PER MHG PŢS= CM	IN.= .48 1.0058 P	E06 TO	= 90. 0E	EG.F RUN NO CAT	POJ/P	TS = 59101 CAF	RUN
Q= P0=	6.34 PSI = 192.0 C CN 0.2284	RE PER	IN.= .48	E06 T0	= 90. DE	EG.F RUN NO CAT 0.2246	POJ/P	TS = 59101 CAF 0.1234	RUN 4 22.
Q= PO= ALPHA 3.97 2.94	6.34 PSI = 192.0 C CN 0.2284 0.1638	RE PER MHG PTS= CM -1.4583 -1.0290	IN.= .48 1.0058 P POJ 1.2659 1.2659	PTS 1.0058 1.0058	= 90. DE POJ/PTS 1.2587 1.2587	CAT 0.2246 0.2272	POJ/P • 026116 CPB 0.1012 0.0989	TS = 59101 CAF 0.1234 0.1283	RUN 4 22. 3 22.
Q= PO= ALPHA 3.97	6.34 PSI = 192.0 C CN 0.2284	RE PER MHG PTS= CM -1.4583	IN.= .48 1.0058 P POJ 1.2659	E06 T0 SI PTS 1.0058	POJ/PTS 1.2587 1.2587 1.2587	CAT 0.2246 0.2272 0.2263	POJ/P • 026110 CPB 0-1012	TS = 59101 CAF 0.1234 0.1263 0.1275	RUN 4 22. 3 22. 5 22.
Q= PO= ALPHA 3.97 2.94 1.90	6.34 PSI = 192.0 C CN 0.2284 0.1638 0.1043	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659	PTS 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587	CAT 0.2246 0.2272 0.2263 0.2228	POJ/P • 026116 CPB 0.1012 0.0989 0.0988	TS = 59101 CAF 0.1234 0.1283 0.1275 0.1230	RUN 4 22. 3 22. 5 22.
Q= PO= ALPHA 3.97 2.94 1.90 1.37	6.34 PSI = 192.0 C CN 0.2284 0.1638 0.1043 0.0729	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659	F06 T0 SI PTS 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2587	CAT 0.2246 0.2272 0.2263 0.2228 0.2228	POJ/P* . 026110 CPB 0.1012 0.0989 0.0988 0.0998	TS = 59101 CAF 0.1234 0.1283 0.1275 0.1230 0.1220	RUN 4 22. 5 22. 6 22. 7 22.
Q= PO= ALPHA 3.97 2.94 1.37 0.85 0.33	6.34 PSI = 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659	E06 TC SI PTS 1.0058 1.0058 1.0058 1.0058	= 90. DE POJ/PTS 1.2587 1.2587 1.2587 1.2699 1.2699	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2255	POJ/P . 026116 CPB 0.1012 0.0989 0.0988 0.0998 0.1009 0.1014	TS = 59101 CAF 0.1234 0.1263 0.1275 0.1230 0.1220	RUN 4 22. 5 22. 6 22. 7 22. 8 22.
Q= PO= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19	6.34 PSI = 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659 1.2772	E06 T0 SI PTS 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2699	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2228 0.2238	POJ/P* . 026110 CPB 0.1012 0.0989 0.0988 0.0998 0.1009	TS = 59101 CAF 0.1234 0.1241 0.1220 0.1241	RUN 4 22. 5 22. 6 22. 7 22. 8 22.
Q= PO= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19 -0.72	6.34 PSI 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135 0.0600	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2772 1.2772	FOS TO SI PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2699 1.2812	CAT 0.2246 0.2272 0.2228 0.2228 0.2228 0.2238 0.2238	POJ/P . 026116 CPB 0.1012 0.0989 0.0988 0.0998 0.1009 0.1014 0.1017	TS = 59101 CAF 0.1234 0.1283 0.1275 0.1230 0.1241 0.1221 0.1175	RUN 4 22. 5 22. 6 22. 7 22. 8 22. 8 22.
Q= P0= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19 -0.72 -1.24	6.34 PSI 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182 -0.0099 -0.0385	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135 0.0600 0.2338	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659 1.2772 1.2772 1.2772	E06 T0 SI PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2699 1.2812 1.2587	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2255 0.2238 0.2202 0.2301	POJ/P . 026116 CPB 0.1012 0.0989 0.0988 0.1009 0.1014 0.1017 0.1023	TS = 59101 CAF 0.1234 0.1283 0.1275 0.1230 0.1220 0.1221 0.1175 0.1278	RUN 22. 3 22. 5 22. 6 22. 6 22. 7 22. 8 22.
Q= P0= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19 -0.72 -1.24 -1.75	6.34 PSI 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182 -0.0099 -0.0385 -0.0675	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135 0.0600 0.2338 0.4184	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659 1.2772 1.2772 1.2785 1.2659	FTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2699 1.2699 1.2692	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2255 0.2238 0.2202 0.2301 0.2283	POJ/P . 026116 CPB 0.1012 0.0989 0.0988 0.0989 0.1009 0.1014 0.1017 0.1023 0.1024	TS = 59101 CAF 0.1234 0.1263 0.1275 0.1220 0.1241 0.1221 0.1179 0.1276 0.1255	RUN 22. 3 22. 5 22. 6 22. 6 22. 6 22. 7 22. 8 22. 8 22.
Q= PO= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19 -0.72 -1.24 -1.75 -2.26	6.34 PSI 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182 -0.0099 -0.0385 -0.0675 -0.0923	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135 0.0600 0.2338 0.4184 0.5625 0.7554 1.1269	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2659 1.2772 1.2772 1.2772 1.2885 1.2659 1.2998	FTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2699 1.2691 1.2781 1.2781	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2238 0.2238 0.2238 0.2238 0.2283 0.2283	POJ/P . 026110 CPB 0.1012 0.0989 0.0988 0.1009 0.1014 0.1017 0.1023 0.1024 0.1028	TS = 59101 CAF 0.1234 0.1263 0.1275 0.1220 0.1241 0.1275 0.1278 0.1275	RUN 22. 3 22. 5 22. 6 22. 6 22. 6 22. 7 22. 8 22. 8 22. 8 22.
Q= PO= ALPHA 3.97 2.94 1.90 1.37 0.85 0.33 -0.19 -0.72 -1.75 -2.26 -3.30	6.34 PSI 192.0 C CN 0.2284 0.1638 0.1043 0.0729 0.0453 0.0182 -0.0099 -0.0385 -0.0675 -0.0923 -0.1218	RE PER MHG PTS= CM -1.4583 -1.0290 -0.6493 -0.4483 -0.2779 -0.1135 0.0600 0.2338 0.4184 0.5625 0.7554	IN.= .48 1.0058 P POJ 1.2659 1.2659 1.2659 1.2772 1.2772 1.2772 1.2785 1.2659 1.2659 1.3111	F06 T0 SI PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 1.2587 1.2587 1.2587 1.2587 1.2699 1.2699 1.2691 1.2612 1.2587 1.2924 1.3036 1.3261	CAT 0.2246 0.2272 0.2263 0.2228 0.2228 0.2238 0.2201 0.2283 0.2282 0.2282	POJ/P . 026110 CPB 0.1012 0.0989 0.0988 0.0998 0.1009 0.1014 0.1017 0.1023 0.1024 0.1028 0.1031	TS = 59101 CAF 0.1234 0.1263 0.1275 0.1220 0.1241 0.1275 0.1275 0.1251 0.1251	RUN 22. 3 22. 5 22. 6 22. 6 22. 6 22. 7 22. 8 22. 8 22. 8 22. 8 22.

				·•				
HODEL 94	6.3 CON	FIG00	00	MACH 3.00)	8HI =	0.	
Q= 6.34	PSI RE PER	IN.= .48	EQ6 TO	= 90. DS	G.F	P0J/P	rs =	10.
PO= 192.	O CMHG PTS=	1.C058 P	SI		RUN NO	. 02611	59102	
ALPHA CN	CH CH	POJ	PTS	POJ/PTS	CAT	CP8	CAF	. RUN
3.96 0.21	46 -1.3650	10.2970	1.0058	10.2380	0.2439	0.0997	0.1442	23.
2.92 0.15	09 -0.9467	10.2740	1.0058	10.2160	0.2376	0.0988	0.1388	23.
1.88 0.08	96 -0.5520	10.2860	1.0058	10.2270	0.2349	0.0996	0.1353	23.
	06 -0.3673			10.2276				
	48 -0.2097							
0.32 0.00	63 -0.0344	10-2860	1.0058	10.2270	0.2354	0.1019	0-1374	23.
-0.20 -0.02 -0.73 -0.05	218 0.1424 508 0.3239	10.2030	1.0050	10-2040	0.2543	0.1021	0 1 3 0 3	23.
1 2/ 0.03	00 0.3239	10.2140	1.0056	10.2100	0.2703	0.1019	0.1303	£3•
-1.24 -0.07	148 N*3090	10.2800	1.0058	10.2210	0.2331	0.1013	0.1316	23.
-1.76 -0.10	84 U.6863	10.2970	1.0058	10.2380	0.2385	0.1004	0.1380	23.
-2.28 -0.13	798 0,5086 084 0.6863 055 0.8538	10.2740	1.0058	10,2160	0.2412	0.0996	0.1416	23.
-3.31 -0.19	1.2283	10.2860	1.0058	10.2270	0.2402	0.0998	.0.1404	23.
-4.36 -0.26	1.2283 1.6770	10.2860	1.0058	10.2270	0.2410	0.1025	0.1385	23.
	6.3 CON							
	6.3 CON PS1 RE PER							
Q= 6.34		R IN.= .48	EOō TO	= 90. DE	G.F	P0J/P	rs =	
Q= 6.34	PS: RE PER	R IN.= .48 = 1.0058 P	EOÃ TO	= 90. DE	EG.F RUN-NO	POJ/P	TS = 69103	
Q= 6.34 PO= 192. ALPHA CN	PS: RE PER O CMHG PTS=	R IN.= .48 = 1.0058 P POJ	goā to Şi Pts	≖ 90. DE	EG.F RUN- NO CAT	POJ/P [*] • 026110 • CPB	TS = 69103 CAF	15. RUN
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20	PS1 RE PER 0 CMHG PTS= 1 CM 075 —1.3152	R IN.= .48 = 1.CO58 P POJ 15.2810	EOA TO \$1 PTS 1.0058	= 90. DE	EG.F RUN: NO: CAT 0.25C3	POJ/P ¹ • 026116 • CPB • 0•0999	TS = 69103 CAF 0.1504	15. RUN 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14	PS1 RE PER 0 CMHG PTS= 1 CM 075 -1.3152 29 -0.8890	R IN.= .48 = 1.0058 P POJ 15.2810 15.3040	EOG TO SI PTS 1.0058 1.0058	= 90. DE POJ/PTS 15:1940 15:2170	EG.F RUN: NO CAT 0.25C3 0.25C3	POJ/PT - 026116 - CPB - 0.0999 - 0.0989	TS = 69103 CAF 0.1504 0.1514	15. RUN 24. 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062	R IN.= .48 = 1.0058 P POJ 15.2810 15.3040 15.3270	FOG TO SI PTS 1.0058 1.0058 1.0058	 90. 08 POJ/PTS 15.1940 15.2170 15.2390 	EG.F RUN-NO- CAT 0.25C3 0.25C3 0.2494	POJ/P . 026116 . CPB 0.0999 0.0989 0.1000	TS = 69103 CAF 0.1504 0.1514 0.1494	RUN 24. 24. 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05	PS: RE PER .0 CMHG PTS= .0 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .339 -0.3174	POJ 15.2810 15.3040 15.3270 15.3380	FOG TO \$I PTS 1.0058 1.0058 1.0058	= 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449	POJ/P . 026116 . CPB 0.0999 0.0989 0.1000 0.1011	TS = 69103 CAF 0.1504 0.1514 0.1494 0.1438	RUN 24. 24. 24. 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02	PS1 RE PER .0 CMHG PTS= 1 CM 075 -1.3152 129 -0.8890 129 -0.5062 139 -0.3174 168 -0.1520	POJ 15.2810 15.3040 15.3380 15.3040	FOG TO \$I PTS 1.0058 1.0058 1.0058	= 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449	POJ/P . 026116 . CPB 0.0999 0.0989 0.1000 0.1011	TS = 69103 CAF 0.1504 0.1514 0.1494 0.1438	RUN 24. 24. 24. 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00	PS1 RE PER .0 CMHG PTS= 1 CM 075 -1.3152 029 -0.8890 129 -0.5062 139 -0.3174 168 -0.1520 104 0.0135	POJ 15.2810 15.3040 15.3270 15.3380 15.3040 15.3380	PTS 1.0058 1.0058 1.0058 1.0058 1.0058	= 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2170 15.2500	CAT 0.25 C3 0.25 C3 0.2494 0.2449 0.2449 0.2449	POJ/P . 026116 . CPB 0.0999 0.1099 0.1010 0.1011 0.1020 0.1019	CAF 0.1504 0.1514 0.1494 0.1438 0.1420 0.1573	RUN 24. 24. 24. 24. 24. 24. 24. 24. 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .33 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011	POJ 15.2810 15.3040 15.3380 15.3380 15.3380 15.3380	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2170 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449 0.2449 0.2440 0.2593	POJ/P . 026110 CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1019	CAF 0.1504 0.1514 0.1494 0.1426 0.1427 0.1389	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .33 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011	POJ 15.2810 15.3040 15.3380 15.3380 15.3380 15.3380	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2170 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449 0.2449 0.2440 0.2593	POJ/P . 026110 CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1019	CAF 0.1504 0.1514 0.1494 0.1426 0.1427 0.1389	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .33 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011	POJ 15.2810 15.3040 15.3380 15.3380 15.3380 15.3380	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2170 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449 0.2449 0.2440 0.2593	POJ/P . 026110 CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1019	CAF 0.1504 0.1514 0.1494 0.1426 0.1427 0.1389	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .33 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011	POJ 15.2810 15.3040 15.3380 15.3380 15.3380 15.3380	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2170 15.2500	CAT 0.25C3 0.25C3 0.2494 0.2449 0.2449 0.2440 0.2593	POJ/P . 026110 CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1019	CAF 0.1504 0.1514 0.1494 0.1426 0.1427 0.1389	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00 -0.21 -0.02 -0.72 -0.05 -1.25 -0.08 -1.77 -0.11 -2.28 -0.13	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .339 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011 .65 0.3636 .037 0.5281 .13 0.6986 .94 0.8743	POJ 15.2810 15.3040 15.3270 15.3380 15.3380 15.3380 15.3150 15.3270 15.3270 15.3270	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2390 15.2500 15.2280 15.2280 15.2390 15.2390 15.2390	CAT 0.25C3 0.25C3 0.25C3 0.2494 0.2449 0.2440 0.2593 0.2404 0.2468	POJ/P . 026116 CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1015 0.1014 0.1005 0.0996	CAF 0.1504 0.1514 0.1494 0.1438 0.1420 0.1461 0.1461	RUN 4 24. 5 24. 6 24. 7 24. 7 24. 7 24. 7 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00 -0.21 -0.02 -0.72 -0.05 -1.25 -0.08 -1.77 -0.11 -2.28 -0.13 -3.33 -0.19	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .339 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011 .65 0.3636 .05281 .13 0.6986 .13 0.6986 .14 0.8743 .17 0.6986 .18 0.8743 .18 0.8	POJ 15.2810 15.3040 15.3270 15.3380 15.3380 15.3350 15.3150 15.3270 15.3270 15.3270 15.3270 15.3270	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2500 15.2500 15.2280 15.2280 15.2390 15.2390 15.2380 15.2380	CAT 0.25C3 0.25C3 0.25C3 0.2494 0.2449 0.2440 0.2593 0.2404 0.2468 0.2467 0.2485 0.2341	POJ/P . 026116 . CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1015 0.1014 0.1005 0.0996 0.0987 0.0996	CAF 0.1504 0.1514 0.1494 0.1438 0.1420 0.1462 0.1468 0.1468	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24. 7 24. 7 24. 7 24. 7 24. 7 24.
Q= 6.34 PO= 192. ALPHA CN 3.97 0.20 2.92 0.14 1.88 0.08 1.36 0.05 0.83 0.02 0.32 -0.00 -0.21 -0.02 -0.72 -0.05 -1.25 -0.08 -1.77 -0.11 -2.28 -0.13 -3.33 -0.19	PS1 RE PER .0 CMHG PTS= 1 CM .075 -1.3152 .29 -0.8890 .29 -0.5062 .339 -0.3174 .68 -0.1520 .04 0.0135 .98 0.2011 .65 0.3636 .037 0.5281 .13 0.6986 .94 0.8743	POJ 15.2810 15.3040 15.3270 15.3380 15.3380 15.3350 15.3150 15.3270 15.3270 15.3270 15.3270 15.3270	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	# 90. DE POJ/PTS 15.1940 15.2170 15.2500 15.2500 15.2280 15.2280 15.2390 15.2390 15.2380 15.2380	CAT 0.25C3 0.25C3 0.25C3 0.2494 0.2449 0.2440 0.2593 0.2404 0.2468 0.2467 0.2485 0.2341	POJ/P . 026116 . CPB 0.0999 0.0989 0.1000 0.1011 0.1020 0.1015 0.1014 0.1005 0.0996 0.0987 0.0996	CAF 0.1504 0.1514 0.1494 0.1438 0.1420 0.1462 0.1468 0.1468	RUN 4 24. 5 24. 6 24. 6 24. 7 24. 7 24. 7 24. 7 24. 7 24. 7 24. 7 24.

更有一个,这个人们就是他的,我们可以在这个人,一个人们是这个人的,我们就是一个人的,我们是一个人的,我们就是一个人的,我们是一个人的,我们就是一个人的人的人,也

HODEL 9	146.3 CC	ONFIG0	000	MACH 3.00)	PHI =	0.	
Q= 6.34	PSI RE PE	R IN.= .4	BEO6 TÒ	= 90. DE	G.F	POJ/P	TS =	40.
PO= 192	.0 CMHG PTS	5= 1.0058 I	PSI		RUN NO	. 02611	69104	
ALPHA C	IN CM	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
	827 -1.1670		1.0058	40.0530				
	.233 -0.7844 9568 -0.3399		1.0058 1.0058	40.1430 40.0750				
	296 -0.1712		1.0058	40.1320				
	030 -0.0089			40.1090				
0.29 -0.0			1.0058	40.1650				
-0.22 -9.0			1.0058	40-1650				
-0.74 -0.C			1.0058	40.1650				
-1.26 -0.1			1.0058	40.1880				
-1.78 -0.1			1.0058	40.1650				
-2.30 -0.1	632 1.0265	43.3510	1.0058	40.1200	0.2467	0.0986	0.1481	25.
-3.33 ~0.2	230 1.4130	40.4080	1.0058	40.1770	0.2511	0.1002	0.1509	9 25 .
-4.38 -0.2	890 1.8566	40.3740	1.0058	40.1430	0.2510	0.1010	0.1500	25.
HODEL 9		ONFIGOC		MACH 3.00		PHI =	0.	,
HODEL 9 Q= 6.34		ONFIG00		MACH 3.00 = 90. DE		PKI =		20•
Q= 6.34		ER IN.= .48	3EG6 TO	= 90. DE	G.F		rs =	
Q= 6.34 PO= 192	PSI RE PE	ER IN.= .48	3EG6 TO	= 90. DE	G.F	POJ/P	rs =	
Q= 6.34 PO= 192 ALPHA C	PSI RE PE	ER IN.= .46 S= 1.CO58 F POJ	3EG6 TO	= 90. DE	G.F RUN NO. CAT	POJ/PT . 026116	S = 59105 CAF	20 • RUN
Q= 6.34 PO= 192 ALPHA C 3.95 0.2	PSI RE PE 0 CMHG PTS	FR IN.= .48 FR IN.= .48 FOJ POJ 20.3560	3E06 TO PSI PTS	= 90. DE	G.F RUN NO. CAT 0.2505	POJ/PT . 026116 CPB 0.1001	TS = 59105 CAF	20. RUN 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1	PSI RE PE -0 CMHG PTS N CM	FR IN.= .48 FR IN.= .48 FOJ POJ 20.3560 20.3340	PTS 1.0058	= 90. DE POJ/PTS 20.2400	G.F RUN NO. CAT 0.2505 0.2532	POJ/P1 . 026116 CPB 0.1001 0.0992	TS = 59105 CAF 0.1504	20. RUN 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1	PSI RE PE 0.0 CMHG PTS 0.0 CM 0.050 -1.3090 0.414 -0.8910 0.805 -0.4991	POJ 0 20.3560 3 20.3340 20.3790	PTS 1.0058 1.0058	= 90. DE POJ/PTS 20.2400 20.2180	CAT 0.2505 0.2532 0.2398	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004	CAF 0.1504 0.1393	20. RUN 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0	PSI RE PE -0 CMHG PTS -0 CM -1.3090 414 -0.8910 805 -0.4991 -529 -0.3265 -244 -0.1490	POJ 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2600	CAT 0.2505 0.2532 0.2398 0.2442 0.2452	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1014 0.1023	CAF 0.1504 0.1540 0.1393 0.1428 0.1429	20. RUN 26. 26. 26. 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0	PSI RE PE -0 CMHG PTS -0 CM -1.3090 414 -0.8910 529 -0.3265 244 -0.1490 023 0.0145	POJ 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400	CAT 0.2505 0.2532 0.2398 0.2442 0.2452 0.2451	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1014 0.1023 0.1018	CAF 0.1504 0.1540 0.1393 0.1428 0.1429 0.1433	20. RUN 26. 26. 26. 26. 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0	PSI RE PE -0 CMHG PTS -0 CM -1.3090 414 -0.8910 805 -0.491 529 -0.3265 244 -0.1490 023 0.0145 318 0.2022	POJ 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400	G.F RUN NO. CAT 0.2505 0.2532 0.2398 0.2442 0.2452 0.2451	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1014 0.1023 0.1018 0.1013	CAF 0.1504 0.1540 0.1428 0.1428 0.1423 0.1443	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0 -0.73 -0.0	PSI RE PE -0 CMHG PTS -0 CM -1.3090 414 -0.8910 805 -0.4991 529 -0.3265 244 -0.1490 023 0.0145 318 0.2022 590 0.3678	POJ 20.3560 20.3340 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3680	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400 20.2400	G.F RUN NO. CAT 0.2505 0.2539 0.2442 0.2445 0.2445 0.2451 0.2425 0.2425	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1014 0.1023 0.1018 0.1013 0.1013	CAF 0.1504 0.1540 0.1429 0.1428 0.1429 0.1431 0.1412	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0 -0.73 -0.0 -1.25 -0.0	PSI RE PE -0 CMHG PTS -0 CMHG PTS -0 CMHG PTS -0 CMHG PTS -0 -0 -0 -0 -0 -0 -0 -0 -0 -0 -0 -0 -0 -	POJ 20.3560 20.3340 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400 20.2400 20.2400	G.F RUN NO. CAT 0.2505 0.2532 0.2538 0.2442 0.2452 0.2451 0.2425 0.2425 0.2425	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1014 0.1013 0.1013 0.1013 0.1005	CAF 0.1504 0.1540 0.1429 0.1429 0.1423 0.1412 0.1412	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26. 26
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0 -0.73 -0.0 -1.25 -0.0 -1.77 -0.1	PSI RE PE -0 CMHG PTS -0.000 -1.3090 -0.414 -0.8910 -0.4910 -0.365 -0.4991 -0.365 -0.365 -0.365 -0.365 -0.367 -0.3	POJ 20.3560 20.3340 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3680 20.3680 20.3680	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400 20.2510 20.2400	CAT 0.2505 0.2532 0.2532 0.2442 0.2452 0.2451 0.2425 0.2425 0.2425	POJ/PT . 026116 CPB 0.1001 0.0992 0.1004 0.1013 0.1013 0.1013 0.1013 0.1005 0.0994	CAF 0.1504 0.1504 0.1428 0.1428 0.1433 0.1412 0.1412 0.1393	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26. 26
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0 -0.21 -0.0 -1.25 -0.0 -1.77 -0.1 -2.29 -0.1	PSI RE PE 0.0 CMHG PTS N CM 050 -1.3090 414 -0.8910 805 -0.4991 529 -0.3265 244 -0.1490 023 0.0145 318 0.2022 590 0.3678 590 0.3678 137 0.7056 427 0.8914	POJ 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400 20.2400 20.2400	CAT 0.2505 0.2532 0.2398 0.2442 0.2452 0.2451 0.2425 0.2425 0.2425 0.2425	POJ/PT CPB 0.1001 0.0992 0.1004 0.1014 0.1023 0.1018 0.1013 0.1013 0.1005 0.0994 0.0986	CAF 0.1504 0.1540 0.1393 0.1428 0.1412 0.1412 0.1412 0.1412 0.14183	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26. 26.
Q= 6.34 PO= 192 ALPHA C 3.95 0.2 2.92 0.1 1.87 0.0 1.36 0.0 0.82 0.0 0.32 -0.0 -0.21 -0.0 -0.73 -0.0 -1.25 -0.0 -1.77 -0.1	PSI RE PE -0 CMHG PTS N CM -0.8910 805 -0.4991 529 -0.3265 244 -0.1490 023 0.0145 318 0.2022 590 0.3678 875 0.5678 137 0.7056 427 0.8914 031 1.2792	POJ 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560 20.3560	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	POJ/PTS 20.2400 20.2180 20.2620 20.2400 20.2400 20.2400 20.2400 20.2510 20.2400	G.F RUN NO. CAT 0.2505 0.2532 0.2532 0.2452 0.2452 0.2451 0.2425 0.2425 0.2425 0.2425 0.2425	POJ/PT CPB 0.1001 0.0992 0.1004 0.1014 0.1023 0.1018 0.1013 0.1013 0.1005 0.0994 0.0986 0.0996	CAF 0.1504 0.1540 0.1393 0.1428 0.1432 0.1412 0.1412 0.1412 0.1412 0.1443 0.1430 0.1483	20. RUN 26. 26. 26. 26. 26. 26. 26. 26. 26. 26.

MODEL 946.3	CONF	IG000	00	MACH 3.0C	PHI = 0.	
Q= 6.34 PSI	RE PER	IN .= .488	06 TO	= 90. DEG.F	POJ/PTS =	70.
PO= 192.0 CM	HG PTS=	1.0058 PS	51	RUN I	NO., 025ļ169106	
ALPHA CN	CH	POJ	PTS	POJ/PTS CA	T CPB CAF	RUN
2.87 0.0909 1.84 0.0310	0.1636 0.3514 0.5107 0.6964 0.8509 1.0457 1.2071	70.4060 70.4060 70.4620 70.5070 70.5070 70.4850 70.5190 70.5300 70.4510 70.4730 70.4850 70.4850 70.5980	1.0058	70.003/ 70.059 4 70.104 .55 70.1040 0.25 70.1150 0.23 70.1260 0.25 70.1260 0.25 70.0480 0.26 70.0700 0.24 70.0810 0.25	24 0.1010 0.1514 14 0.1010 0.1505 77 0.1030 0.1447 57 0.1031 0.1536 22 0.1025 0.1497 39 0.1019 0.1520 24 0.1017 0.1307 56 0.1014 0.1552 22 0.1003 0.1519 49 0.0986 0.1464 76 0.0983 0.1493 11 0.0992 0.1519 48 0.1001 0.1447	27. 27. 27. 27. 27. 27. 27. 27. 27. 27.
-4.40 -0.3176	2.0435	70.4400	1.0058		20 0.1006 0.1414	
MCDEL 946.3	CONF	FIG000	00	MACH 3.00	PHI = 0.	
MCDEL 946.3 Q= 6.34 PSI	CONF RE PER	FIG000	00 E06 TO	MACH 3.00 = 90. DEG.F	PHI = 0. POJ/PTS = 10	
MCDEL 946.3	CONF RE PER	FIG000	00 E06 TO	MACH 3.00 = 90. DEG.F	PHI = 0. POJ/PTS = 10 NO. 0261169107	
MCDEL 946.3 Q= 6.34 PSI PO= 192.0 CM ALPHA. CN 3.89 0.1265 2.86 0.0615 1.81 0.0048 1.30 -0.0274	CGNF RE PER IHG PTS= CM -0.8188 1 -0.3846 1 -0.0271 1 0.1941 1 0.3596 1 0.5360 1 0.7189 1 1.0872 1 1.2376 1 1.4313 1 1.8058 1	FIG000 IN.= .488 1.0058 PS POJ 100.6100 100.5800 100.6100 100.7000 100.6900 100.6900 100.6600 100.6600	PTS 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058 1.0058	MACH 3.00 = 90. DEG.F RUN POJ/PTS CA 100.0300 0.24 100.0300 0.24 100.0300 0.24 100.1200 0.25 100.1100 0.24 100.0300 0.24 100.1200 0.24 100.1200 0.24 100.1100 0.24 100.1100 0.24 100.0300 0.24	PHI = 0. POJ/PTS = 10 NO. 0261169107	20. RUN 28. 28. 28. 28. 28. 28. 28. 28.

MODEL 946.3	CONI	FIG000C	MACH 3.5	O PHI =	0.	
Q= 5.43 PSI	RE PER	IN.=48E06	TO= 90. D	EG.F POJ/P	TS = .	
PO= 251.0 C	HHG PTS=	-6329 PSI		RUN NO. 02611	69108	
ALPHA CN	CH	POJ	PTS POJ/PTS	CAT CPB	CAF	RUN
4:00 0.2428	-1.5975			0.1885 0.0800		29.
2.97 0.1753	-1.1353			0.1942 0.0788		29.
2.45 0.1426	-0.9172	0.7234 0.	6329 1.1430	0.1940 0.0783		29.
1.93 0.1088	-0.5902 -0.5019			0.1928 0.0781 0.1874 0.0761		29.
0.90 0.0494	-0.3088			0.1883 0.0781		29.
0.38 0.0232	-0.1541			0.1871 0.0781		29. 29.
-0.15 -0.0084	0.0564			0.1858 0.0786		29.
-0.66 -0.0367	0.0359			0.1899 0.0788		29.
-1.18 -0.0667				0.1835 0.0791		29.
-1.69 -0.0955				0.1916 0.0791		29.
-2.20 -0.1228	0.7793			0.1935 0.0794		29.
-3.23 -0.1843		0.7686 G.		0.1867 0.0800		29.
-4.27 -0.2540	1.6688	0.7912 0.		0.1893 C.0814		29.
MODEL 946.3	CON	FIG0000	MACH 3.50	C PHI =	0.	
					0. TS = 10.	
Q= 5.43 PSI	RE PER		MACH 3.50 TO≃ 90. DI		TS = 10.	
Q= 5.43 PSI	RE PER	IN.= .48E06	MACH 3.50 TO≃ 90. DI	EG.F POJ/P	TS = 10. 69109	RUN
Q= 5.43 PSI PO= 251.0 C ALPHA CN	RE PER MHG PTS=	IN.= .48E06 .6329 PSI POJ	MACH 3.50 TO≖ 90. DI PTS POJ/PTS	EG.F POJ/P RUN NO. 026110 CAT CPB	TS = 10. 69109 CAF	
Q= 5.43 PSI PO= 251.0 C	RE PER	IN.= .48E06 .6329 PSI POJ 1	MACH 3.50 TO≖ 90. DI PTS POJ/PTS 6329 10.0190	EG.F POJ/P RUN NO. 026110 CAT CPB 0.2087 0.0799	TS = 10. 69109 CAF 0.1288	30.
Q= 5.43 PSI PO= 251.0 C ALPHA CN 3.99 0.2296	RE PER MHG PTS= CM -1.5040	IN.= .48E06 .6329 PSI POJ 6.3409 0.0 6.3070 0.0	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657	EG.F POJ/P RUN NO. 026110 CAT CPB	TS = 10. 69109 CAF 0.1288 0.1296	
Q= 5.43 PSI PO= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620	RE PER MHG PTS= CM -1.5040 -1.0441	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3070 0.6 6.3296 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010	EG.F POJ/P' RUN NO. 026110 CAT CPB 0.2087 0.0799 0.2082 0.0786	TS = 10. 69109 CAF 0.1288 0.1296 0.1263	30. 30. 30.
Q= 5.43 PSI PO= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993	RE PER MHG PTS= CM -1.5040 -1.0441 -0.6280	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3070 0.6 6.3296 0.6 6.3070 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9657	EG.F POJ/P RUN NO. 026110 CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784	TS = 10. 69109 CAF 0.1288 0.1296. 0.1263 0.1241	30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122	RE PER MHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9657 6329 10.0010	EG.F POJ/P RUN NO. 026110 CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.127	30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3070 0.6 6.3296 0.6 6.3070 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9657 6329 10.0010	EG.F POJ/P RUN NO. 026110 CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.1271 0.1252	30. 30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122 -0.15 -0.0161 -0.67 -0.0472	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036 0.3032	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3183 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9121 6329 10.0190 6329 9.9835	CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786 0.2021 0.0789	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.1271 0.1252 0.1230	30. 30. 30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122 -0.15 -0.0161 -0.67 -0.0472 -1.18 -0.0739	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036 0.3032 0.4665	IN.= .48E06 .6329 PSI POJ 6.3409 0.6 6.3070 0.6 6.3296 0.6 6.3296 0.6 6.3296 0.6 6.3731 0.6 6.3409 0.6 6.3183 0.6 6.3409 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9121 6329 10.0190 6329 9.9835 6329 10.0190	CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786 0.2021 0.0789 0.2018 0.0789 0.2038 0.0790	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.1271 0.1252 0.1230 0.1248 0.1225	30. 30. 30. 30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122 -0.15 -0.0161 -0.67 -0.0472 -1.18 -0.0739 -1.70 -0.1028	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036 0.3032 0.4665 0.6520	POJ 0.6.329 PSI POJ 0.6.3409 0.6.3070 0.6.3296 0.6.3296 0.6.3296 0.6.3296 0.6.3409 0.6.3409 0.6.3409 0.6.3409 0.6.3409 0.6.3070 0.66.3070 0.66.3070 0.66.3070 0.66.3070 0.66	MACH 3.50 TO= 90. Di PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9121 6329 10.0190 6329 9.9835 6329 10.0190 6329 9.9657	CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786 0.2021 0.0789 0.2018 0.0789 0.2018 0.0789 0.2018 0.0790 0.2015 0.0790 0.2055 0.0786	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.1251 0.1230 0.1248 0.1225 0.1269	30. 30. 30. 30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122 -0.15 -0.0161 -0.67 -0.0472 -1.18 -0.0739 -1.70 -0.1028 -2.21 -0.1322	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036 0.3032 0.4665 0.6520 0.8439	IN.= .48E06 .6329 PSI POJ 6.3409 0.6.3070 0.6.3296 0.6.3070 0.6.3296 0.6.3409 0.6.3409 0.6.3183 0.6.36370 0.6.3522 0.6	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 9.9121 6329 10.0190 6329 9.9855 6329 10.0190 6329 9.9855 6329 10.0190 6329 9.9657 6329 10.0370	CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786 0.2021 0.0789 0.2018 0.0789 0.2018 0.0789 0.2018 0.0789 0.2015 0.0790 0.2055 0.0786 0.2021 0.0786	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.127 0.1252 0.1230 0.1248 0.1225 0.1269 0.1235	30. 30. 30. 30. 30. 30.
Q= 5.43 PSI P0= 251.0 C ALPHA CN 3.99 0.2296 2.96 0.1620 1.92 0.0993 1.41 0.0699 0.89 0.0410 0.37 0.0122 -0.15 -0.0161 -0.67 -0.0472 -1.18 -0.0739 -1.70 -0.1028	RE PER HHG PTS= CM -1.5040 -1.0441 -0.6280 -0.4398 -0.2578 -0.0758 0.1036 0.3032 0.4665 0.6520 0.8439	POJ 1 1 1 1 1 1 1 1 1	MACH 3.50 TO= 90. DI PTS POJ/PTS 6329 10.0190 6329 9.9657 6329 10.0010 6329 9.9835 6329 10.0190 6329 9.9835 6329 10.0190 6329 9.9657 6329 10.0370 6329 10.0370 6329 10.0010	CAT CPB 0.2087 0.0799 0.2082 0.0786 0.2047 0.0784 0.2024 0.0783 0.2064 0.0786 0.2021 0.0789 0.2018 0.0789 0.2018 0.0789 0.2018 0.0790 0.2015 0.0790 0.2055 0.0786	TS = 10. 69109 CAF 0.1288 0.1296 0.1263 0.1241 0.127 0.1232 0.1230 0.1248 0.1225 0.1269 0.1235 0.1157	30. 30. 30. 30. 30. 30. 30.

		206	<i>DE</i> 1 - 1012		J				
DON	EL 946.3	CONF	IGQC	00 .	MACH 3.50	3	PHI 🚎	0.	
Q=	5.43 PSI	RE PER	IN.= .48	E06 T0	= 90 _e .DE	Ğ.F	POJ/P	rs = 15	•
20≠	251.0 C	HHG PTS=	.6329 P	12		RUN NO.	. 026]1	59110	
ALPHA	CN	CH	P0J	PTS	POJ/PTS	GAT	CPB	CAF	RUN
3.99	0.2202	-1.4275	9.4605	0.6329	14.9490	0.2130	0.0802	0.1328	31.
2.96	0.1548	-0.9887	9.4718	0.6329	14.9660	9.2104	0.0789	0.1315	31.
1.92	0.0894	-0.5439	9.5057	0.6329	15.0200	0.2100	0.0786	0.1314	31.
	0.0611	-0.3742	9.4831		14.9840				31.
		-0.1974	9.5170	0-6329	15.0380				31.
	0.0050		9.5283						31.
	-0.0228	0.1540	9.4944		15.0020				31.
	-0.0533		9.5283						31.
	-0.0333		9.4944						31.
					14.9840				. 31.
	-0.1393		9.5283						31.
	-0.2020	1.3141	9.4944		15.0020				31.
-4.28	-0.2717	1.8024	9.4718	0.6329	14.9660	0.2127	0.0799	0. 328	31.
									•
		CON	-					0. TC = 20	
		CON	-					•	
Q=	5.43 PSİ		IN.= .48	E06 T0	= 90. Di	EG.F	POJ/P	TS ≠ 20	
Q=	5.43 PSİ : 251.0 C	RE PER	IN.= .48	E06 T0	= 90. Di	EG.F RUN NO	POJ/P	TS ≃ 20 6911i	· .
Q= PO= ALPHA	5.43 PSÍ : 251.0 C CN	RE PER MHG PTS≭ CH	1N.= .48 .6329 P	EO6 TO SI PTS	= 90. DI	EG.F RUN AO CAT	POJ/P • 026]} CPB	TS = 20 6911i CAF	RUN
Q= PO= ALPHA 3:99	5.43 PSI : 251.0 C CN : 0.2152	RE PER MHG PTS≭ CH -1.3969	IN.= .48 .6329 P POJ 12.6590	E06 T0 SI PTS 0.6329	= 90. Di	EG.F RUN AD ĈAT 0-2174	POJ/P - 026]} CPB 0.0804	TS = 20 69111 CAF C.1369	RUN 32.
Q= PO= ALPHA 3:99 2:95	5.43 PSI 251.0 C CN 0.2152 0.1498	RE PER MHG PTS* CH -1.3969 -0.9546	IN.= .48 .6329 P POJ 12.6590 12.6480	E06 T0 SI PTS 0.6329 0.6329	= 90. Di	EG.F RUN NO CAT 0.2174 0.2179	POJ/P - 02611 - CPB - 0.0304 - 0.0794	TS = 20 69111 CAF C.1369 0.1385	RUN 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861	RE PER MHG PTS* CH -1.3969 -0.9546 -0.5333	IN.= .48 .6329 P POJ 12.6590 12.6480 12.6590	PTS 0.6329 0.6329 0.6329	* 90. Di	EG.F RUN NO CAT 0.2174 0.2179 0.2144	POJ/P . 02611 CPB 0.0304 0.0794 0.0786	TS = 20 69111 CAF C.1369 0.1385 0.1358	RUN 32. 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91 1.40	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583	RE PER MHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601	IN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6590	PTS 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100	POJ/P . 02611 CPB 0.0804 0.0794 0.0786	TS = 20 69111 CAF 0.1369 0.1385 0.1358 0.1313	RUN 32. 32. 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91 1.40 0.88	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294	RE PER MHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744	IN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6590 12.6710	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	# 90. Di POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119	POJ/P . 02613 CPB 0.0804 0.0794 0.0786 0.0788	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329	RUN 32. 32. 32. 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017	RE PER HHG PTS= CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024	IN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6710 12.6590	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119	POJ/P . 02613 CPB 0.0304 0.0794 0.0786 0.0788 0.0790 0.0791	TS = 20 69111 CAF 0.1369 0.1385 0.1358 0.1313 0.1329 0.1473	RUN 32. 32. 32. 32. 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278	RE PER HHG PTS= CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870	FN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6590 12.6710 12.6590 12.7040	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095	POJ/P . 02613	TS = 20 69111 CAF 0.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307	RUN 32. 32. 32. 32. 32. 32. 32.
Q= PO= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15 -0.67	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577	RE PER HHG PTS= CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766	FN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6590 12.6710 12.6590 12.7040 12.6710	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030 20.0030 20.0740 20.0210	CAT 0.2174 0.2144 0.2100 0.219 0.2264 0.2095 0.2093	POJ/P . 02613	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1358 0.1329 0.1473 0.1307 0.1307	RUN 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 3.99 2.95 1.91 1.40 0.36 -0.15 -0.67 -1.19	5.43 PSI 251.0 C CN -0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577 -0.0861	RE PER HHG PTS= CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766 0.5561	FN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6590 12.6710 12.6710 12.6710 12.6590	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030 20.00740 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095 0.2093 0.2112	POJ/P O2613 CP8 O.0304 O.0794 O.0788 O.0790 O.0791 O.0788 O.0788 O.0788	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307 0.1307 0.1325	RUN 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15 -0.67 -1.19 -1.70	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577 -0.0861 -0.1144	RE PER HHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766 0.5561 0.7390	IN.= .48 .6329 P POJ 12.6590 12.6480 12.6590 12.6710 12.6590 12.6710 12.6590 12.6590	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030 20.0740 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095 0.2093 0.2112 0.2057	POJ/P O2613 CPB O.0804 O.0794 O.0788 O.0790 O.0791 O.0788 O.0788 O.0788	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307 0.1307 0.1307 0.1325 0.1276	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15 -0.67 -1.19 -1.70 -2.22	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577 -0.0861 -0.1144	RE PER HHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766 0.5562 0.7390 0.9298	IN.= .48 .6329 P POJ 12.6590 12.6590 12.6590 12.6710 12.6710 12.6710 12.6590 12.6590 12.6710	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.0030 20.0740 20.0030 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095 0.2093 0.2112 0.2057 0.2160	POJ/P - 02613 CPB 0.0804 0.0794 0.0788 0.0790 0.0791 0.0788 0.0788 0.0788 0.0788	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307 0.1307 0.1307 0.1325 0.1276 0.1379	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15 -0.67 -1.19 -1.70 -2.22	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577 -0.0861 -0.1144	RE PER MHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766 0.5561 0.7390 0.9298 1.3208	IN.= .48 .6329 P POJ 12.6590 12.6590 12.6590 12.6710 12.6710 12.6710 12.6590 12.6710 12.6590 12.6710	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	# 90. Di POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.00740 20.0030 20.0030 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095 0.2093 0.2112 0.2057 0.2160 0.2135	POJ/P - 02613 - CPB - 0.0304 - 0.0794 - 0.0788 - 0.0790 - 0.0781 - 0.0788 - 0.0781 - 0.0781 - 0.0781	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307 0.1307 0.1325 0.1276 0.1379 0.1347	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.
Q= P0= ALPHA 3.99 2.95 1.91 1.40 0.88 0.36 -0.15 -0.67 -1.19 -1.70 -2.22 -3.25	5.43 PSI 251.0 C CN 0.2152 0.1498 0.0861 0.0583 0.0294 0.0017 -0.0278 -0.0577 -0.0861 -0.1144	RE PER HHG PTS* CH -1.3969 -0.9546 -0.5333 -0.3601 -0.1744 -0.0024 0.1870 0.3766 0.5562 0.7390 0.9298	IN.= .48 .6329 P POJ 12.6590 12.6590 12.6590 12.6710 12.6710 12.6710 12.6590 12.6590 12.6710	PTS 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329 0.6329	# 90. Di POJ/PTS 20.0030 19.9850 20.0030 20.0030 20.00740 20.0030 20.0030 20.0030 20.0030 20.0030	CAT 0.2174 0.2179 0.2144 0.2100 0.2119 0.2264 0.2095 0.2093 0.2112 0.2057 0.2160 0.2135	POJ/P - 02613 - CPB - 0.0304 - 0.0794 - 0.0788 - 0.0790 - 0.0781 - 0.0788 - 0.0781 - 0.0781 - 0.0781	TS = 20 69111 CAF C.1369 0.1385 0.1358 0.1313 0.1329 0.1473 0.1307 0.1307 0.1307 0.1325 0.1276 0.1379	RUN 32. 32. 32. 32. 32. 32. 32. 32. 32.

ŀ	IODEL	946.3	<u>-</u>	CONI	FIG.	•0	000		HA	АСН	3.5	0		PH	1 =		٠0.		
()= 5 .	.43 PSI	RE	PER	IN.=	.4	8 <u></u> E06	•	T 0≖	90). D	EG.F		PO	J/P	TS	=	40.	
F	0= 2	51.0 C	MHG P	rs=	. 63	29	PSI					RUN	10	- 02	611	69]	12		
AL PH	A	CN	c	ж	P	OJ		PTS	F	,01\	PTS	С	AT	С	PB		CAF		RUN
3.9		. 2002	-1.30		25.8			632				0.2							33.
2.9		.1337	-0.85 -0.44		25.8			632				0.2							33. 33.
1.3		0.0427.			25.9			632				0.2							33.
0.8		.0150	-0.09		25.9			632				0.2							33.
		.0155	0.10		25.9			632				-0.2							33.
		.0433	0.28		25.9			632				0.2							33.
-0.6	8 -0	.0711	0.45	35	25.9			632	9 4	0.9	700	0.2	141	0.0	786	9.	1354	•	33.
-1.2	0 -0	.1000	0.63	391	25.9			632		0.9	700	0.2	265	0.0	786	0.	1478	3	33.
		.1288	0.82		25.9			632				0.2							33.
	-	.1577	1.00		25.9			632				0.2							33.
		.2198	1.42		25.9			632				0.2							33.
-4.3	0 -0	.2878	1.89	158	25.9	400	0.	632	9 4	10.9	880	0.2	166	0.0	793	0.	1373	3	33.
		. 946.3 .43 PSI		CONI PER	FIG. In.=		000 8E06				3.5	C EG.F			J/P [.]	ts	0. =	70.	
C	= 5.	43 PSI	RE	PER	IN .=	.4	8E06					EG.F		۲0	J/P	_	=	70.	
C	= 5.		RE		IN .=		8E06 PSI					EG.F			J/P	_	=	70.	
C	= 5. 0= 2	43 PSI	RE 4HG P	PER	IN.=	.4	8E06 PSI	PTS	ro=	90		EG.F RUN		P0	J/P	591	=	70.	RUN
P	= 5. 0= 2 A 6 0	43 PSI 251.0 CI CN	RE 4HG P	PER TS=	IN.=	4 29 QJ	8E06 PSI		ro= P	,07\ ,	PTS	EG.F RUN	NO. AT	P0 02 C	J/P [*] 611 <i>6</i> PB	591	= 13 Caf		RUN 34•
P ALPH	= 5. 0= 2 A 6 0	.43 PSI :51.0 CI CN	RE 4HG P	PER TS= M	IN .= .63 P 44.1 44.1	29 QJ 830 380	8E06	PTS 632 632	FO =	90 /01/	PTS	EG.F RUN C.	NO. AT 061	P0 02 C	J/P [*] 611 (PB 800	591 0.	= 13 CAF 1261		
ALPH 3.9 2.9	0= 2 A 6 0 3 0	43 PSI 51.0 CI CN 0.1769 0.1104	RE 4HG P -1.15 -0.70 -0.31	PER TS= :M :38 :88 :14	IN.= .63 p 44.1 44.1 44.2	29 0J 830 380 280	8E06 PSI 0.	PTS 632 632 632	=01 P 69 69 69	90 903/ 59.8 59.8	PTS 130 420 850	EG. F RUN C. 0.2: 0.2:	NO. AT 061 036 000	P0 02 C	J/P [*] 611 (PB 800 798 796	0. 0. 0.	= 13 CAF 1261 1238 1204	L B	34. 34. 34.
ALPH 3.9 2.9 1.9	0= 2 A 6 0 3 0 0 0 8 0	43 PSI 51.0 CI CN 0.1769 0.1104 0.0499	RE 4HG P -1.15 -0.70 -0.31 -0.13	PER TS= M 38 14 32	IN.= .63 P 44.1 44.1 44.2 44.1	29 0J 830 380 280 830	8E06	PTS 632 632 632 632	FO 6	90 90J/ 59.8 59.8 59.8	PTS 130 420 850	EG. F RUN C. 0.20 0.20	NO. AT 061 036 000 988	P0 02 C 0.0 0.0	J/P [*] 611 (PB 800 798 796 795	0. 0. 0.	= 13 CAF 1261 1238 1204 1193		34. 34. 34.
3.9 2.9 1.9 1.3 0.8	0= 2 A 6 0 3 0 0 0 8 0 6 -0	43 PSI 51.0 CI CN 0.1769 0.1104 0.0499 0.0216	RE 4HG P -1.15 -0.70 -0.31 -0.13	PER TS= M i38 i88 14 i32 i74	IN.= .63 P 44.1 44.2 44.1 44.2	29 0J 830 380 280 830 510	8E06	PTS 632 632 632 632 632	10= P 9 6 9 6 9 6	90 90J/ 59.8 59.8 59.8	PTS 130 420 850 130 200	EG. F RUN C: 0.2: 0.2: 0.2: 0.1:	NO. AT 061 036 000 988 996	P0 02 C 0.0 0.0 0.0	J/P [*] 611 (PB 800 798 796 795 791	0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1193 1205	133	34. 34. 34. 34.
3.9 2.9 1.9 1.3 0.8	0= 2 A 6 0 3 0 0 0 8 0 6 -0 4 -0	43 PSI 51.0 CI CN 9.1769 9.1104 9.0216 9.0216 9.0361	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05	PER TS= M 38 14 32 174	IN .= .63 P 44.1 44.1 44.2 44.1 44.2	29 0J 830 380 280 830 510 390	8E06	PTS 632 632 632 632 632 632	10= P 9 6 9 6 9 6 9 6	90 903/ 69.8 69.8 69.8 69.8	PTS 130 420 850 130 200	EG. F RUN C. 0.20 0.20 0.20 0.10 0.10	NO. AT 061 036 000 988 996 016	P0 02 0.0 0.0 0.0 0.0	J/P ² 611 PB 800 798 796 795 791 786	0. 0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1193 1205	i 3 4 3	34. 34. 34. 34. 34.
ALPH 3.9 2.9 1.9 1.3 0.8 0.3	0= 2 A 6 0 3 0 0 0 8 0 6 -0 4 -0 8 -0	43 PSI 51.0 CI CN 0.1769 0.1104 0.0499 0.0216 0.0361 0.0361	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23	PER TS= M 38 14 32 74 144 38	IN .= .63 P 44.1 44.1 44.2 44.1 44.2 44.2	.4 29 0J 830 380 830 510 390 060	8E06	PTS 632 632 632 632 632 632 632	FO = FO = FO = FO = FO = FO = FO = FO =	90 903/ 59.8 59.8 59.8 59.9	PTS 130 420 850 130 200 030 490	EG.F RUN C. 0.2(0.2(0.1) 0.1(0.2(0.2(NO. AT 061 036 000 988 996 016 014	P0 02 C 0.0 0.0 0.0 0.0 0.0	J/P ² 611 (PB 800 798 796 795 791 786 786	0. 0. 0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1193 1205 1229		34. 34. 34. 34. 34. 34.
ALPH 3.9 2.9 1.9 1.3 0.8 0.3 -0.1	0= 2 A 6 0 0 0 8 0 8 0 6 -0 8 -0 9 -0	43 PSI 51.0 CI CN 0.1769 0.1104 0.0499 0.0216 0.0078 0.0361 0.0644 0.0933	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23 0.41	PER TS= M i38 i38 i32 i74 i34 i38 i38	IN.= -63 P 44.1 44.2 44.1 44.2 44.2 44.2	.4 29 0J 830 380 280 830 510 390 060 390	8E06	PTS 632 632 632 632 632 632 632 632	FO 69 69 69 69 69 69 69 69 69 69 69 69 69	90 903/ 69.8 69.8 69.8 69.9	PTS 130 420 850 130 200 030 490	EG.F RUN C. 0.2(0.2(0.1) 0.1(0.2(0.2(0.2(NO. AT 061 036 000 988 996 016 014 043	P0 02 0.0 0.0 0.0 0.0 0.0	J/P ⁻ 6110 PB 800 798 796 795 791 786 786 781	0. 0. 0. 0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1205 1229 1227 1262	1 3 3 5 7	34. 34. 34. 34. 34. 34.
ALPH 3.9 2.9 1.9 1.3 0.8 0.3 -0.1 -0.6	= 5. 0= 2 A 6 0 0 0 8 0 6 -0 4 -0 8 -0 9 -0 1 -0	43 PSI 51.0 CI CN 1.1769 1.1104 1.0499 1.0216 1.0361 1.0644 1.0933 1.1205	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23 0.41 0.59	PER TS= M 38 132 174 138 132 174 138 138 138 138 138 138 138 138 138 138	IN.= -63 P 44.1 44.2 44.1 44.2 44.2 44.2 44.2	-4 29 0J 830 380 280 830 510 060 390 940	8E06	PTS 632 632 632 632 632 632 632 632 632	10= P 9 6 9 6 9 6 9 6 9 6 9 6 6 6 6 6	90 903/ 69.8 69.8 69.9 69.8 69.9	PTS 130 420 850 130 200 030 490 030	EG. F RUN C. 0.2 0.2 0.2 0.1 0.1 0.2 0.2	NO. AT 061 036 000 988 996 016 014 043	P0 02 0.0 0.0 0.0 0.0 0.0 0.0	J/P ⁻ 6110 PB 800 798 796 795 791 786 786 781 780	0. 0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1193 1205 1227 1262		34. 34. 34. 34. 34. 34. 34.
3.9 2.9 1.9 1.3 0.8 0.3 -0.1 -0.6	= 5. 0= 2 A 6 0 0 0 8 0 6 -0 4 -0 9 -0 1 -0 3 -0	43 PSI 51.0 CF CN 1.1769 1.104 1.0499 1.0216 1.0078 1.0361 1.0644 1.0933 1.205 1.1516	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23 0.41 0.59	PER TS= M 38 88 14 32 74 38 83 65 20	IN.= .63 P 44.1 44.2 44.1 44.2 44.2 44.2 44.1	-44 29 0J 830 380 280 830 510 060 390 940 170	8E06	PTS 632 632 632 632 632 632 632 632 632	FO = FO = FO = FO = FO = FO = FO = FO =	90 POJ/ 69.8 69.7 69.8 69.9 69.9 69.8 69.8 69.8 69.8	PTS 130 420 850 130 200 030 490 031 031 0310	EG. F RUN C. 0.2(0.2(0.1(0.2(0.2(0.2(0.2(0.2(0.2(0.2(0.2	NO. AT 061 036 000 988 996 014 043 042 050	P0 02 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	J/P [*] 6116 PB 800 798 795 791 786 786 781 780 774	0. 0. 0. 0. 0. 0. 0.	= 13 CAF 1261 1238 1204 1193 1205 1227 1262 1261	3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	34. 34. 34. 34. 34. 34. 34.
ALPH 3.9 2.9 1.9 0.8 0.3 -0.1 -0.6 -1.7	= 5. 0= 2 A 6 0 0 0 8 0 6 -0 8 -0 9 -0 1 -0 3 -0 4 -0	43 PSI 51.0 CI CN 1.1769 1.1104 1.0499 1.0216 1.0361 1.0644 1.0933 1.1205	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23 0.41 0.59	PER TS= M 38 88 14 32 74 44 38 83 65 20 76	IN.= -63 P 44.1 44.2 44.1 44.2 44.2 44.2 44.2	-4 29 0J 830 380 280 830 510 390 940 170 620	8E06	PTS 632 632 632 632 632 632 632 632 632	FO = FO = FO = FO = FO = FO = FO = FO =	90 90J/ 99.8 99.8 99.9 99.9 99.9 99.9 99.8 99.8	PTS 130 420 850 130 200 030 490 030 310 670	EG. F RUN C. 0.2 0.2 0.2 0.1 0.1 0.2 0.2	NO. AT 061 036 000 988 996 014 042 050	PO 02 C 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0	J/P 6110 PB 800 798 795 791 786 786 781 780 774	0. 0. 0. 0. 0. 0. 0.	= 13 CAF 1261 1236 1204 1205 1227 1262 1261 1276 1325	3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	34. 34. 34. 34. 34. 34. 34.
3.99 1.99 1.93 0.88 0.33 -0.11 -0.66 -1.27 -2.3.2	= 5. 0= 2 A 6 0 0 0 8 0 0 0 8 -0 4 -0 9 -0 1 -0 8 -0 4 -0 8 -0	43 PSI 51.0 CF CN 1.1769 1.104 1.0499 1.0216 1.0078 1.0078 1.0644 1.0933 1.205 1.1516 1.1793	RE 4HG P -1.15 -0.70 -0.31 -0.13 0.05 0.23 0.41 0.59 0.76	PER TS= M 388 142 744 383 655 2076	IN.= .63 P 44.1 44.2 44.1 44.2 44.2 44.2 44.2 44.2	-4 29 0J 830 380 280 830 510 390 940 170 620 720	8E06	PTS 632 632 632 632 632 632 632 632 632 632	FO = FO = FO = FO = FO = FO = FO = FO =	90 903/ 99.8 99.8 99.8 99.9 99.8 99.8 99.8 99.	PTS 130 420 850 130 200 030 490 030 310 670 330 950	EG. F RUN C. 0.2(0.2(0.1(0.2(0.2(0.2(0.2(0.2(0.2(0.2(0.2	NO. AT 061 036 0988 996 014 043 042 050 100	P0 02 C C 0.00 0.00 0.00 0.00 0.00 0.00 0	J/P ² 6110 PB 800 798 796 795 791 786 786 781 780 774 775	0. 0. 0. 0. 0. 0. 0. 0.	= 13 CAF 1261 1228 1204 1123 1227 1261 1276 1325 1336		34. 34. 34. 34. 34. 34. 34. 34.

TO SECTION OF THE PROPERTY OF

MCDEL 946.3	CUNI	FIG00	00	MACH 3.50	PHI =	0.	
Q= 5.43 PSI	RE PER	IN.= .48	E06 T0	≖ 90. DEG.	F POJ/P	TS = 10	0.
P0= 251.0 CM	HG PTS=	.6329 P	SI	RU	N NO. 02611	69114	
ALPHA CN	CM	POJ	PTS	POJ/PTS	CAT CPB	CAF	RUN
3.95 0.1482	-0.9480	63.2280	0.6329	99.9070 0.	2141 0.0803	.0,1338	35∔
2.91 0.0800	~0.4855	63.2170	0.6329	99.8890 0.	2095 0.0805	0.1290	35.
1.89 0.0223	-0.1132	63.2740	0.6329		2111 0.0796		35.
1.36 -0.0066	0.0689	63.2510			2131 0.0795		35.
0.84 -0.0371	0.2707	63.2850			2118 0.0786		35.
0.32 -0.0665		63.1720			2096 0.0786		35.
-0.19 -0.0915		63.2400			2073 0.0786		35.
-0.71 -0.1294		63.2400			2249 0.0779		35.
							35.
-1.22 -0.1481	0.9659	63.2280			2121 0.0776		
-1.74 -0.1792					2129 0.0771		35.
-2.25 -0.2048					2127 0.0773		35.
-3.29 -0.2668		63.2400			2133 0.0776		35.
-4.32 -0.3327	2.1940	63.2400	0.6329	99.9250 0.	2148 0.0786	0.1361	35.
MODEL 946.3							
MODEL 946.3 Q= 4.54.PSI				MACH 4.00 = 90. DEG.			•
	RE PER	IN.= .48	E06 T0	≠ 90. DEG.		TS =	•
Q= 4.54 PSI	RE PER	IN.= .48	E06 T0	≠ 90. DEG.	F POJ/P	TS =	• RUN
Q= 4.54 PSI PO= 320.0 CF ALPHA CN	RE PER 1HG PTS= CM	IN.= .48 .4057 P POJ	EO6 TO SI PTS	≠ 90. DEG. RU POJ/PTS	F POJ/P	TS = 69115 CAF	
Q= 4.54 PSI PO= 320.0 CP ALPHA CN 3.90 0.2402	RE PER 4HG PTS= CM -1.6226	IN.= .48 .4057 P POJ 0.5158	E06 T0 SI PTS 0.4057	≠ 90. DEG. RU POJ/PTS 1.2713 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628	TS = 69115 CAF 0.1051	RUN
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731	RE PER HHG PTS= CM -1.6226 -1.1565	IN.= .48 .4057 P POJ 0.5158 0.5158	E06 T0 SI PTS 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619	TS = 69115 CAF 0.1051 0.1100	RUN 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212	E06 T0 SI PTS 0.4057 0.4057 0.4057	= 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619	TS = 69115 CAF 0.1051 0.1100 0.1090	RUN 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266	PTS 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077	RUN 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.81 0.0473	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266 0.5266	PTS 0.4057 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069	RUN 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.31 0.0473 0.30 0.0187	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266 0.5266 0.5266	E06 T0 SI PTS 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 1.2713 0. 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618 1682 0.0616	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1066	RUN 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CP ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5266 0.5266 0.5266 0.5266	E06 T0 SI PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 1.2713 0. 1.2713 0. 1.2713 0. 1.27846 0. 1.2980 0. 1.2980 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618 1682 0.0616 1765 0.0618	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1066 0.1148	RUN 36. 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126 -0.73 -0.0420	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850 0.2740	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5266 0.5266 0.5266 0.5266 0.5266	E06 T0 SI PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 1.2713 0. 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0618 1682 0.0616 1765 0.0618 1723 0.0619	TS = 69115 CAF 0.1051 0.1090 0.1097 0.1069 0.1066 0.1148 0.1104	RUN 36. 36. 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126 -0.73 -0.0420 -1.24 -0.0726	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850 0.2740 0.4778	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5266 0.5266 0.5266 0.5266 0.5266 0.5375	E06 T0 SI PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0618 1682 0.0618 1765 0.0618 1765 0.0618 1763 0.0619	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1066 0.1148 0.1104 0.1111	RUN 36. 36. 36. 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126 -0.73 -0.0420 -1.24 -0.0726 -1.76 -0.1013	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850 0.2740 0.4778 0.6596	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266 0.5266 0.5266 0.5266 0.5275 0.5484	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.3248 0. 1.3248 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618 1682 0.0618 1765 0.0618 1723 0.0619 1731 0.0619 1676 0.0619	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1066 0.1148 0.1104 0.1111 0.1057	RUN 36. 36. 36. 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126 -0.73 -0.0420 -1.24 -0.0726 -1.76 -0.1013 -2.27 -0.1318	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850 0.2740 0.4778 0.6596 0.8665	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266 0.5266 0.5266 0.5266 0.5375 0.5375 0.5484 0.5266	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.3248 0. 1.3248 0. 1.3516 0. 1.2980 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618 1682 0.0616 1765 0.0618 1723 0.0619 1731 0.0619 1759 0.0624	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1048 0.1148 0.1104 0.1111 0.1057 0.1135	RUN 36. 36. 36. 36. 36. 36. 36.
Q= 4.54 PSI PO= 320.0 CM ALPHA CN 3.90 0.2402 2.87 0.1731 1.85 0.1092 1.33 0.0760 0.61 0.0473 0.30 0.0187 -0.22 -0.0126 -0.73 -0.0420 -1.24 -0.0726 -1.76 -0.1013	RE PER 4HG PTS= CM -1.6226 -1.1565 -0.7242 -0.4970 -0.3094 -0.1246 0.0850 0.2740 0.4778 0.6596	IN.= .48 .4057 P POJ 0.5158 0.5158 0.5212 0.5266 0.5266 0.5266 0.5266 0.5275 0.5484	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	# 90. DEG. RU POJ/PTS 1.2713 0. 1.2713 0. 1.2846 0. 1.2980 0. 1.2980 0. 1.2980 0. 1.3248 0. 1.3248 0. 1.3248 0. 1.3516 0. 1.2980 0. 1.3649 0.	F POJ/P IN NO. 02611 CAT CPB 1679 0.0628 1719 0.0619 1709 0.0619 1691 0.0615 1687 0.0618 1682 0.0618 1765 0.0618 1723 0.0619 1731 0.0619 1676 0.0619	TS = 69115 CAF 0.1051 0.1100 0.1090 0.1077 0.1069 0.1066 0.1148 0.1104 0.1104 0.1057 0.1135 0.1118	RUN 36. 36. 36. 36. 36. 36. 36.

MO	DEL 946.3	CON	FİG000	00	MACH 4.00	ס	PHI =	0.	
Q=	4.54 PSI	RE PER	IN.= .488	06 TO	= 90. DE	G.F	POJ/P	TS =	10.
PO	= 320.0 C	MKG PTS=	.4057 PS	I	-	RUN NO	- 02611	69116	
AL-PHA	CN	CH	POJ	PTS	POJĮPTS	CAT	CPB	CAF	RUN
3.90		-1.5756	4.1317	0.4057	10.1830				
2.87		-1.0688	4.1371	0.4057	10.1970				
1.84		-0.6612	4.1480	0.4057	10.2240				
	0.0686	-0.4502	4.1371	0.4057	10.1970				
0.81		-0.2653	4.1480	0.4057					
0.30	0.0106 -0.0180	-0:0749	4.1480	0.4057	10.2240				
	-0.0180	0.1128 0.3123	4.1425 4.1425	0.4057					37. 37.
	-0.0486	0.5088	4.1262	0.4057					37.
	-0:1066	0.6906	4.1371	0.4057					37.
	-0.1359	0.8869		0.4057					
	-0.2017	1.3383			10.2240				
	-0.2747	1.8628		0.4057					
MG	DEL 946.3	CONI	F1G000	0	MACH 4.60)	PHI =	0.	
	DEL 946.3 4.54 PSI		F1G000 IN.= .48E		MACH 4.60		PHI =		15.
Q=	4.54 PSI	RE PER		06 TO	= 90. DE	G.F		rs =	15.
Q=	4.54 PSI = 320.0 C	RE PER	IN.= .48E	06 TO	= 90. DE	G.F RUN NO	PO J/P1	rs =	15. Run
Q= PO	4.54 PSI = 320.0 C	RE PER MHG PTS=	IN.= .48E .4057 PS	06 TO	= 90. DE	G.F RUN NO	POJ/P1 026116 CPB	TS = :59117 CAF	
Q= PO ALPHA	4.54 PSI = 320.0 C CN 0.2269	RE PER MHG PTS≖ CM	IN.= .48E .4057 PS POJ 6.1514	06 T0 I PTS	90. DE POJ/PTS	G.F RUN NO CAT C.1884	POJ/P1 - 026116 - CPB - 0.0630	TS = 59117 CAF 0.1255	RUN
Q= PO ALPHA 3.90 2.87 1.83	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514	06 T0 I PTS 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610	CAT C.1884 0.1886 0.1814	POJ/PT . 026116 . CPB 0.0630 0.0622 0.0619	TS = 59117 CAF 0.1255 0.1264 0.1195	RUN 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677	06 T0 I PTS 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020	CAT C.1884 0.1886 0.1814 0.1872	POJ/PT . 026116 . CPB 0.0630 0.0622 0.0619 0.0619	TS = 59117 CAF 0.1255 0.1264 0.1195 0.1253	RUN 38. 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32 0.80	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405	06 T0 PTS 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350	CAT C.1884 0.1886 0.1814 0.1872 0.1779	POJ/PT O26116 CPB 0.0630 0.0622 0.0619 0.0619 0.0619	TS = 59117 CAF 0.1255 0.1264 0.1195 0.1253 0.1160	RUN 38. 38. 38. 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32 0.80 0.29	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568	06 T0 PTS 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350 15.1750	CAT C.1884 0.1886 0.1814 0.1872 0.1779 0.1875	POJ/PT O26116 CPB 0.0630 0.0622 0.0619 0.0619 0.0619 0.0619 0.0618	TS = 59117 CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257	RUN 38. 38. 38. 38. 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32 0.80 0.29 -0.22	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.4267 -0.0542 0.1524	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568	06 T0 PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350 15.1750	CAT C.1884 0.1884 0.1814 0.1872 0.1779 0.1875 0.1857	POJ/PT . 026116 CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239	RUN 38. 38. 38. 38. 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32 0.80 0.29 -0.22 -0.73	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233 -0.0513	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542 0.1524 0.3270	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568 6.1568	06 T0 PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350 15.1750 15.1750 15.1750	CAT C.1884 0.1884 0.1814 0.1872 0.1779 0.1875 0.1857	POJ/PT . 026116 CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618 0.0618	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239 0.1209	RUN 38. 38. 38. 38. 38. 38.
Q= PO ALPHA 3.90 2.87 1.83 1.32 0.29 -0.22 -0.73 -1.25	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233 -0.0513 -0.0813	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542 0.1524 0.3270 0.5220	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568 6.1568 6.1568	06 TO PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350 15.1750 15.1750 15.1750	C.1884 0.1884 0.1886 0.1814 0.1872 0.1779 0.1875 0.1857 0.1857	POJ/PT CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618 0.0618 0.0618	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239 0.1209 0.1231	RUN 38. 38. 38. 38. 38. 38.
Q= P0 ALPHA 3.90 2.87 1.83 1.32 0.80 0.22 -0.73 -1.25 -1.76	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233 -0.0513 -0.0813 -0.1112	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542 0.1524 0.3270 0.5220 0.7229	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568 6.1622 6.1568 6.1514	06 T0 1 PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1750 15.1750 15.1750 15.1750 15.1750	CAT C.1884 0.1886 0.1814 0.1872 0.1779 0.1875 0.1857 0.1828 0.1848	POJ/PT - 026116 CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618 0.0619 0.0618	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239 0.1209 0.1231 0.1199	RUN 38. 38. 38. 38. 38. 38. 38.
Q= P0 ALPHA 3.90 2.87 1.83 1.32 0.80 0.29 -0.22 -0.73 -1.25 -1.76 -2.27	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233 -0.0513 -0.0813 -0.1112 -0.1392	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542 0.3270 0.5220 0.7229 0.9046	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568 6.1622 6.1568 6.1514 6.1622	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1350 15.1750 15.1750 15.1750 15.1880 15.1750	CAT C.1884 0.1886 0.1814 0.1872 0.1779 0.1875 0.1857 0.1858 0.1848 0.1818	POJ/PT - 026116 CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618 0.0618 0.0618 0.0618 0.0618	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239 0.1231 0.1199 0.1231	RUN 38. 38. 38. 38. 38. 38. 38. 38.
Q= P0 ALPHA 3.90 2.87 1.83 1.32 0.80 0.29 -0.22 -0.73 -1.25 -1.76 -2.27 -3.30	4.54 PSI = 320.0 C CN 0.2269 0.1565 0.0933 0.0646 0.0340 0.0073 -0.0233 -0.0513 -0.0813 -0.1112	RE PER MHG PTS= CM -1.5332 -1.0379 -0.6142 -0.4267 -0.2226 -0.0542 0.1524 0.3270 0.5220 0.7229	IN.= .48E .4057 PS POJ 6.1514 6.1405 6.1514 6.1677 6.1405 6.1568 6.1568 6.1568 6.1568 6.1568	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 15.1610 15.1350 15.1610 15.2020 15.1750 15.1750 15.1750 15.1750 15.1750	CAT C.1884 0.1886 0.1814 0.1872 0.1779 0.1875 0.1857 0.1828 0.1818 0.1838 0.1903	POJ/PT - 026116 CPB 0.0630 0.0622 0.0619 0.0619 0.0618 0.0618 0.0618 0.0619 0.0619 0.0619	CAF 0.1255 0.1264 0.1195 0.1253 0.1160 0.1257 0.1239 0.1209 0.1231 0.1199 0.1217	RUN 38. 38. 38. 38. 38. 38. 38. 38.

SERVICE TRANSPORTED FOR THE PROPERTY OF THE PR

THE REPORT OF THE PROPERTY OF

MODEL 946.3	CON	FIG00	00	HACH 4.00	3	PHI =	- 0.	
Q= 4.54 PS1	RE PER	IN.= .48	EÖ6 TO	≠ 90. DE	G.F	POJ/P	rs = 20	• .
PO= 320.0 C	MHG PTS=	.4057 P	SI		RUN NO.	. 02611	9118	
ALPHA CN	CH	PÓJ	PŢS.	-POJ/PTS	CAT	CP8	CAF	RUN
3.89 0.2216	-1.4951	8.1765	0.4057	20.1530	0.1886	0.0633	0.1253	39.
2.86 0.1525	-1.0101	8.1765	0.4057	20:1530	0.1888	0.0624	0.1264	39.
1.84 0.0913	-0.6024	8.1765	C.4057	20.1530	0.1865	0.0619	0.1246	39.
1.33 0.0613	-0.4046	8.1873	0.4057	20.1800	0.1873	0.0621	0.1252	39.
0.80 0.C333	-0.2272	2-1819	0.4057	20.1660	0.1869	0.0619	0.1250	39.
0.29 0.0027	-0.0219	8.1765	0.4057	20.1530	0.1858	0.0621	0.1218	39.
-0.22 -0.0260	0.1656	8.1819	0.4057	20.1660	0.1858	0.0619	0.1239	39.
-0.74 -0.0569	0.3606	8.1873	0.4057	20.1800	0.1829	0.0619	0.1210	39.
-1.25 -0.0840	0.5395	8.1982	0.4057	20.2060	0.1862	0.0619	0.1243	39.
-1.76 -0.1133	0.7330	8~1873	0.4057	20.1800	0.1857	0.0618	0.1239	39.
-2.28 -0.1426	0.9251	8.1819	0.4057					39.
-3.30 -0.2077	1.3736	8.1765	0.4057	20.1530	0.1892	0.0624	0.1268	39.
-4.33 - 0.2788	1.8804	E.1765	C-4057	20.1530	0.1858	0.0628	0.1240	39.
MODEL 945.3	CON	FIG00	00	MACH 4-00)	PHI =	0.	
MODEL 941.3 Q= 4.54 PSI		FIG00	-					•.
	RE PER	IN.= .48	E06 T0		G.F		rs = 40	••
Q= 4.54 PSI	RE PER	IN.= .48	E06 T0		EG.F RUN NO	₽ĠŢ/₽1	rs = 40	•. Run
Q= 4.54 PSI PO= 320.0 C	RE PER	IN.= .48	E06 T0	≖ 90. DE	EG.F RUN NO. CAT	PØJ/P1 - 026114 CPB	TS = 40 59119 CAF	
Q= 4.54 PSI PO= 320.0 C ALPHA CN	RE PER MHG PTS= CM	IN.= .48 .4057 P.	EO6 TO SI PTS	≖ 90. DE	EG.F RUN NO: CAT 0.1840	POJ/P1 - 026114 CPB 0-0633	TS = 40 59119 CAF 0.1207	RUN
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083	RE PER MHG PTS= CH -1.4085	IN.= .48 .4057 P. POJ 16.2720	E06 T0 SI PTS 0.4057	90. DE	EG.F RUN NO CAT 0.1840 0.1880	POJ/P1 - 026116 - CPB - 0.0633 - 0.0627	TS = 40 59119 CAF 0.1207 0.1253	RUN 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372	RE PER MHG PTS= CM -1.4085 -0.9103	IN.= .48 .4057 P POJ 16.2720 16.2770	E06 T0 SI PTS 0.4057 0.4057	POJ/PTS 40.1050 40.1180	CAT 0.1840 0.1880 0.1857	POJ/P1 - 026114 CPB 0.0633 0.0627 0.0624	CAF 0.1207 0.1253 0.1234	RUN 40. 40. 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072	IN.= .48 .4057 P. POJ 16.2720 16.2770 16.2720	PTS 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1180 40.1050	CAT 0.1840 0.1880 0.1857	POJ/PT - 026116 CPB 0.0633 0.0627 0.0624 0.0624	CAF 0.1207 0.1253 0.1234 0.1253	RUN 40. 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255	IN.= .486 .4057 P POJ 16.2720 16.2770 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057	PDJ/PTS 40.1050 40.1050 40.1050 40.1050	CAT 0.1840 0.1857 0.1848	POJ/P1 CPB 0.0633 0.0627 0.0624 0.0624 0.0624	CAF 0.1207 0.1253 0.1234 0.1253 0.1224	RUN 40. 40. 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231	IN.= .486 .4057 P POJ 16.2720 16.2770 16.2720 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1180 40.1050 40.1050 40.1050	CAT 0.1840 0.1857 0.1877 0.1848 0.1818	POJ/P1 - 026116 CPB 0.0633 0.0627 0.0624 0.0624 0.0624 0.0624	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194	RUN 40. 40. 40. 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644	IN.= .486 .4057 P. POJ 16.2720 16.2770 16.2720 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050	CAT 0.1840 0.1857 0.1877 0.1878 0.1818 0.1850	POJ/PT - 026116 CPB 0.0633 0.0627 0.0624 0.0624 0.0624 0.0624	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228	RUN 40. 40. 40. 40. 40. 40.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107 -0.23 -0.0400	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644 0.2565	IN.= .486 .4057 P. POJ 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050	CAT 0.1840 0.1857 0.1877 0.1878 0.1818 0.1858 0.1818	POJ/P1 - 026116 - CPB - 0.0633 - 0.0627 - 0.0624 - 0.0624 - 0.0624 - 0.0622 - 0.0622	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228 0.1199	RUN 40. 40. 40. 40. 40. 40.
Q= 4.54 PSI P0= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107 -0.23 -0.0400 -0.74 -0.0673	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644 0.2565 0.4253	IN.= .480 .4057 P. POJ 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050	CAT 0.1840 0.1880 0.1857 0.1848 0.1818 0.1850 0.1821 0.1867	POJ/PT - 026116 CPB 0.0633 0.0624 0.0624 0.0624 0.0624 0.0622 0.0619	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228 0.1199 0.1247	RUN 40. 40. 40. 40. 40. 40.
Q= 4.54 PSI P0= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107 -0.23 -0.0400 -0.74 -0.0673 -1.26 -0.0973	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644 0.2565 0.4253 0.6246 0.8153 1.0322	IN.= .480 .4057 P. POJ 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720 16.2770	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 49.1050 40.1180 40.1050 40.1050 40.1050 40.1050 40.1180 40.1180	CAT 0.1840 0.1880 0.1857 0.1877 0.1848 0.1850 0.1821 0.1867 0.1874	POJ/P1 - 026116 - 026116 - 08624 - 0.0624 - 0.0624 - 0.0624 - 0.0622 - 0.0619 - 0.0618	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228 0.1199 0.1247 0.1257	RUN 40. 40. 40. 40. 40. 40. 40.
Q= 4.54 PSI P0= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107 -0.23 -0.0400 -0.74 -0.0673 -1.26 -0.0973 -1.77 -0.1266 -2.28 -0.1585 -2.80 -0.1885	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644 0.2565 0.4253 0.6246 0.8153 1.0322 1.2301	IN.= .48 .4057 P POJ 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720 16.2770 16.2770 16.2660 16.2720 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050 40.1180 40.1180 40.1050 40.11320	CAT 0.1840 0.1887 0.1877 0.1848 0.1850 0.1857 0.1874 0.1857 0.1864	POJ/P7 - 026116 CPB 0.0633 0.0627 0.0624 0.0624 0.0622 0.0618 0.0618 0.0618	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228 0.1199 0.1247 0.1257 0.1239 0.1245	RUN 40. 40. 40. 40. 40. 40. 40.
Q= 4.54 PSI P0= 320.0 C ALPHA CN 3.89 0.2083 2.86 0.1372 1.83 0.0766 1.32 0.0486 0.80 0.0180 0.29 -0.0107 -0.23 -0.0400 -0.74 -0.0673 -1.26 -0.0973 -1.77 -0.1266 -2.28 -0.1585	RE PER MHG PTS= CM -1.4085 -0.9103 -0.5072 -0.3255 -0.1231 0.0644 0.2565 0.4253 0.6246 0.8153 1.0322	IN.= .480 .4057 P POJ 16.2720 16.2720 16.2720 16.2720 16.2720 16.2720 16.2770 16.2770 16.2660 16.2720	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 40.1050 40.1050 40.1050 40.1050 40.1050 40.1050 40.1180 40.1180 40.1050 40.11320	CAT 0.1840 0.1887 0.1877 0.1848 0.1850 0.1857 0.1874 0.1857 0.1864	POJ/P7 - 026116 CPB 0.0633 0.0627 0.0624 0.0624 0.0622 0.0618 0.0618 0.0618	CAF 0.1207 0.1253 0.1234 0.1253 0.1224 0.1194 0.1228 0.1199 0.1247 0.1257 0.1239 0.1245	RUN 40. 40. 40. 40. 40. 40. 40. 40.

MODEL 946.3	CON	FIG00	- 000	MACH 4.00	G	PHI =	0.	
Q= 4.54 PSI	RE PER	IN.= .48	E06 T	0= 90. DI	EĠ•È	POJ/P	TS =	70-
PO= 320.0 C	MHG PTS=	.4057 P	SI		RUN NO	- 02611:	691 <i>2</i> 0	
ALPHA CN	Сн	POJ	PTS	POJ/PTS	CAT	CP8	CAF	RUN
3.88 0.1864	-1.2517	28.4280	0.4057	70.0670	0.1933	0.0631	0.1302	41.
2.85 0.1172	-0.7741	28.4060	0.4057	70.0130		_		
1.82 0.0573	-0.3797	28.4060	C-4057	70:0130				
1.31 0.0300	-0.2036	28.4280	0.4057					
0.78 -0.0007	-0.0000	28.3840	0.4057	69.9600				
0.28 -0.0300	0.1934	28.4170	0.4057	70.0400				
-0.24 -0.0593	0.3826	28.4110	0.4057	70.0279				
~0.75 -0.0879	0.5675	28:4170	0.4057	70.0490				
-1.26 -0.1179	0.7639	28.4110	0.4057	70.0270				
-1.77 -0.1446	0.9325	26.4170	0.4057	70.0400				
-2.29 -0.1739	1.1260	28°-3950	0.4057	69.9860				
-3.32 -0.2391		28.4110	0.4057					
-4.34 -0.3055	2.0447	28.3950	0.4057	69.9860	0.1877	0.0624	0.1254	41.
HODEL 946.3		FIG00		MACH 4.00		PHI =	٥.	•
HODEL 946.3 Q= 4.54 PSI		FIG00 IN:= .48		MACH 4.00			9. TS = 1	,
•	RE PER	IN-= .48	E06 T	0= 90. DE	EG.₽		TS = 1	, 00.
Q= 4.54 PSI	RE PER	IN-= .48	E06 T	0= 90. DE	EG.₽	P0J/P	TS = 1	ÇO.
Q= 4.54 P\$î P0= 320.0 C	RE PER MHG PTS=	IN.= .48 .4057 P POJ	E06 T SI PTS	0= 90. DE POJ/PTS	EG.F RUN NO. CAT	POJ/PT - 026110 - CP8	TS = 1 59121 CAF	RUN
Q= 4.54 PSI PO= 320.0 C ALPHA: CN	RE PER MHG PTS= CM	IN.= .48 .4057 P POJ 40.5190	E06 T	0= 90. DE POJ/PTS 99.8680	EG.F RUN NO. CAT 0.1901	POJ/P1 • 026110 CP8 • 0•0634	TS = 1 69121 CAF 0.1267	RUN 42.
Q= 4.54 PSI PO= 320.0 C ALPHA: CN 3.87 0.1651	RE PER MHG PTS= CM -1.1038	IN.= .48 .4057 P POJ	PTS 0.4057 0.4057	0= 90. DE POJ/PTS	EG.F RUN NO. CAT 0.1901 0.1803	POJ/P1 - 026110 - CPB - 0.0634 - 0.0630	TS = 1 69121 CAF 0.1267 0.1173	RUN 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347	IN.= .48 .4057 P POJ 40.5190 40.5240	PTS 0.4057 0.4057	0= 90. D8 POJ/PTS 99.8680 99.8810 104.5600	EG.F RUN NO. CAT 0.1901 0.1803 0.1831	POJ/PT . 026110 CPB 0.0634 0.0630 0.0628	TS = 1 69121 CAF 0.1267 0.1173 0.1203	RUN 42. 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367	RE PER MHG PTS= CM -1.1038 -0.6188	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240	PTS 0.4057 0.4057 0.4057	0= 90. DE POJ/PTS 99.8680 99.8810	CAT 0.1901 0.1803 0.1831 0.1889	POJ/P? . 026116 CPB 0.0634 0.0630 0.0628 0.0628	TS = 1 69121 CAF 0.1267 0.1173 0.1203 0.1260	RUN 42. 42. 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240	E06 T SI PTS 0.4057 0.4057 0.4057 0.4057	90. DE POJ/PTS 99.8680 99.8810 104.5600 99.8810	CAT 0.1991 0.1803 0.1831 0.1889 0.1833	POJ/P? . 026116 CPB 0.0634 0.0630 0.0628 0.0628 0.0624	S = 1 S9121 CAF 0.1267 0.1173 0.1203 0.1260 0.1210	RUN 42. 42. 42. 42. 42.
Q= 4.54 PS1 PO= 320.0 C ALPHA CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350	E06 T SI PTS 0.4057 0.4057 0.4057 0.4057	90. DE POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9080	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854	POJ/P? . 026116 CPB 0.0634 0.0630 0.0628 0.0628 0.0624 0.0624	CAF 0.1267 0.1173 0.1203 0.1260 0.1210 0.1230	RUN 42. 42. 42. 42. 42. 42.
Q= 4.54 PS1 P0= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350 40.5240	E06 T SI PTS 0.4057 0.4057 0.4057 0.4057 0.4057	90. D8 POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9080 99.8810 99.9350	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854 0.1812	POJ/P7 . 026116 . CPB . 0.0634 0.0638 0.0628 0.0628 0.0624 0.0624	CAF 0.1267 0.1267 0.1273 0.1203 0.1210 0.1230 0.1230	RUN 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350 40.5240 40.5460	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	90. D8 POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9080 99.8810	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854 0.1812	POJ/P7 . 026116 . CPB . 0.0634 0.0639 0.0628 0.0628 0.0624 0.0624 0.0621 0.0619	CAF 0.1267 0.1267 0.1273 0.1203 0.1210 0.1230 0.1230 0.1291	RUN 42. 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI P0= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779 -0.76 -0.1020	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087 0.6529	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350 40.5240 40.5360	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	90. D8 POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9080 99.8810 93.9350 99.8950	CAT 0.1901 0.1803 0.1831 0.1883 0.1854 0.1812 0.1819 0.1827	POJ/P7 . 026116 . CPB . 0.0634 0.0639 0.0628 0.0624 0.0624 0.0621 0.0619 0.0616	CAF 0.1267 0.1267 0.1273 0.1203 0.1210 0.1230 0.1291 0.1210	RUN 42. 42. 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI P0= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779 -0.76 -0.1020 -1.27 -0.1359	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087 0.6529 0.3869	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350 40.5260 40.5300 39.9870	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	90. D8 POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.98810 97.9350 99.8950 98.5560	CAT 0.1901 0.1803 0.1831 0.1889 0.1889 0.1819 0.1819 0.1819	POJ/P7 . 026116 CPB 0.0634 0.0639 0.0628 0.0628 0.0624 0.0621 0.0619 0.0616 0.0618	CAF 0.1267 0.1267 0.1203 0.1260 0.1210 0.1230 0.1210 0.1211 0.1297	RUN 42. 42. 42. 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI P0= 320.0 C ALPHA: CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779 -0.76 -0.1020 -1.27 -0.1359 -1.27 -0.1339	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087 0.6529 0.8680	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5240 40.5240 40.5240 40.5300 39.9870 40.5080	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9850 99.8850 99.8950 98.5560 99.8410	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854 0.1812 0.1812 0.1815 0.1817	POJ/P7 - 026116 CPB 0.0634 0.0630 0.0628 0.0628 0.0624 0.0621 0.0619 0.0618 0.0618	CAF 0.1267 0.1173 0.1203 0.1260 0.1210 0.1230 0.1211 0.1217 0.1217	RUN 42. 42. 42. 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779 -0.76 -0.1020 -1.27 -0.1359 -1.27 -0.1339 -1.79 -0.1626	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087 0.6529 0.8680 1.0555	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5240 40.5240 40.5300 39.9870 40.5080 40.5240	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	90. DE POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9350 99.8950 98.5560 99.8410 99.8810 99.8810	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854 0.1812 0.1819 0.1815 0.18797 0.1843	POJ/P? CPB 0.0634 0.0630 0.0628 0.0624 0.0624 0.0621 0.0619 0.0618 0.0619 0.0619 0.0619	CAF 0.1267 0.1173 0.1203 0.1260 0.1210 0.1201 0.1211 0.1197 0.1218 0.1224	RUN 42. 42. 42. 42. 42. 42. 42. 42. 42. 42.
Q= 4.54 PSI PO= 320.0 C ALPHA CN 3.87 0.1651 2.84 0.0953 1.81 0.0367 1.30 0.0074 0.78 -0.0213 0.27 -0.0519 -0.25 -0.0779 -0.76 -0.1020 -1.27 -0.1359 -1.27 -0.1339 -1.79 -0.1626 -2.30 -0.1919	RE PER MHG PTS= CM -1.1038 -0.6188 -0.2347 -0.0426 0.1450 0.3474 0.5087 0.6529 0.8680 1.0555 1.2462	IN.= .48 .4057 P POJ 40.5190 40.5240 42.4240 40.5240 40.5350 40.5240 40.5300 39.9870 40.5080 40.5240	PTS 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057 0.4057	90. DE POJ/PTS 99.8680 99.8810 104.5600 99.8810 99.9350 99.8950 98.5560 99.8410 99.8810 99.8810	CAT 0.1901 0.1803 0.1831 0.1889 0.1833 0.1854 0.1812 0.1819 0.1819 0.1815 0.1797 0.1843 0.1870	POJ/P? O26116 CPB 0.0634 0.0630 0.0628 0.0624 0.0624 0.0619 0.0616 0.0618 0.0619 0.0619 0.0619	CAF 0.1267 0.1173 0.1203 0.1260 0.1210 0.1200 0.1211 0.1210 0.1214 0.1251	RUN 42. 42. 42. 42. 42. 42. 42. 42. 42. 42.

SCHOOL OF THE STATE AS A STATE OF THE STATE

	MODE	L 946.3	CO	NFIG	C000	MACH 4.5	0	PHI =	0.	
	Q= 3	.77 PSI	RE PE	R IN	48E06 T	C= 90• Q!	EG.F	POJ/P	TS =	•
	P0=	400.0 C	MHG PTS	= .2661	PSI		RUN NO.	02611	69122	
ALF	PHA	CN-	CH	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
		0.2408	-1.6462				0.1894			43.
		0.1700	-1.1341				0.18Cl			43.
		0.1078	-0.7127				0.1875			43.
		0.0766	-0.5034				0.1898			43.
		0.0487	-0.3228				0.1921			43.
		0.0191	-0.1297				0.1898			43.
		0.0120	0.0785				0.1785			43.
		0.0455	0.3111				0.1822			43.
		0,0727	0.4797				0.1830			43.
-		0.0990	0.6457				9.1882			43.
		0.1325	0.8760				0.1890			43.
		0.1947	1.3049				0.1872			43.
-4	- 25	9.2639	1.8076	0.414	6 0.2661	1.5579	0.1762	0.0497	0.1265	43.
		L 946.3		NFIG		MACH 4.5		PHI =	0. TS = 1	0.
	P0=	400.0 C	MHG PTS	= .2661	PŞI		RUN NO	. 02611	69123	
ALI	PO≖ PHA	400.0 C	MHG PTS Ch	= .2661 POJ	•	POJ/PTS	_	. 026110 CPB	69123 CAF	RUN
	PHA			POJ 2.600	PTS 1 0.2661	9.7692	CAT 0.2002	CPB 0.0492	CAF 0.1510	44.
3.	PHA -88	EN	СМ	POJ 2.600	PTS 1 0.2661 7 2.2661	9.7692 9.7491	CAT 0.2002 0.1879	CPB 0.0492 0.0485	CAF 0.1510 0.1395	44. 44.
3. 2.	PHA -88 -86	CN 0.2352 0.1636 0.1014	-1.6064 -1.0982 -0.6751	POJ 2.600 2.594 2.602	PTS 1 0.2661 7 2.2661 7 0.2661	9.7692 9.7491 9.7793	CAT 0.2002 0.1879 0.1939	CPB 0.0492 0.0485 0.0479	CAF 0.1510 0.1395 0.1459	44. 44.
3. 2.	PHA -88 -86	CN 0.2352 0.1636	CH -1.6064 -1.0982	POJ 2.600 2.594 2.602 2.608	PTS 1 0.2661 7 7.2661 7 6.2661 1 0.2661	9.7692 9.7491 9.7793 9.7994	CAT 0.2002 0.1879 0.1939 0.1824	CPB 0.0492 0.0485 0.0479 0.0479	CAF 0.1510 0.1395 0.1459 0.1345	44. 44. 44.
3. 2. 1.	.88 .86 .83	CN 0.2352 0.1636 0.1014	-1.6064 -1.0982 -0.6751	POJ 2.600 2.594 2.602 3.2608 2.597	PTS 1 0.2661 7 0.2661 17 0.2661 10 0.2661 14 0.2661	9.7692 9.7491 9.7793 9.7994 9.7592	CAT 0.2002 0.1879 0.1939 0.1824 0.1727	CPB 0.0492 0.0485 0.0479 0.0479	CAF 0.1510 0.1395 0.1459 0.1345 0.1307	44. 44. 44. 44.
3 . 2 . 1 . 0 .	.88 .86 .83 .33 .81	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127	-1.6064 -1.0982 -0.6751 -0.4833 -0.2881	POJ 2.600 2.594 2.602 3.2608 2.597 2.597	PTS 1 0.2661 7 0.2661 1 0.2661 1 0.2661 4 0.2661 4 0.2661	9.7692 9.7491 9.7793 9.7994 9.7592 9.7592	CAT 0.2002 0.1879 0.1939 0.1824 0.1787 0.1869	CPB 0.0492 0.0485 0.0479 0.0479 0.0479	CAF 0.1510 0.1395 0.1459 0.1345 0.1307 0.1332	44. 44. 44. 44. 44.
3 . 2 . 1 . 0 .	.88 .86 .83 .33 .81	CN 0.2352 0.1636 0.1014 0.0726 0.0431	-1.6064 -1.0982 -0.6751 -0.4833 -0.2881 -0.0869	POJ 2.600 2.594 2.602 2.608 2.597 2.597 2.602	PTS 1 0.2661 7 0.2661 1 0.2661 1 0.2661 4 0.2661 4 0.2661 7 0.2661	9.7692 9.7491 9.7793 9.7994 9.7592 9.7592 9.7793	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477	CAF 0.1510 0.1395 0.1459 0.1345 0.1307 0.1332 0.1294	44. 44. 44. 44. 44.
3 · 2 · 1 · · · · · · · · · · · · · · · ·	.88 .86 .83 .33 .81 .30	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168 0.0464	-1.6064 -1.0982 -0.6751 -0.4833 -0.2851 0.1084 0.2998	POJ 2.600 2.594 2.602 2.608 2.597 2.597 2.602	PTS 1	9.7692 9.7491 9.7793 9.7994 9.7592 9.7592 9.7793	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771 0.1839	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477	CAF 0.1510 0.1395 0.1459 0.1345 0.1307 0.1332 0.1294 0.1362	44. 44. 44. 44. 44. 44.
3 · 2 · 1 · · · · · · · · · · · · · · · ·	.88 .86 .83 .33 .81 .30	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168	-1.6064 -1.0982 -0.6751 -0.4833 -0.2881 -0.086 0.1084 0.2998	POJ 2.600 2.594 2.608 2.597 2.597 2.597 2.602 2.602	PTS 1 0.2661 7 p.2661 1 0.2661 1 0.2661 4 0.2661 7 0.2661 7 0.2661 7 0.2661 9 0.2661	9.7692 9.7491 9.7793 9.7592 9.7592 9.7793 9.7793 9.7290	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1879 0.1771 0.1839 0.1802	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477 0.0477	CAF 0.1510 0.1395 0.1459 0.1345 0.1345 0.1332 0.1294 0.1362 0.1324	44. 44. 44. 44. 44. 44. 44.
3: 2: 1: 0: 0: -0: -1:	.88 .86 .83 .33 .81 .30 .21 -	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168 0.0464	-1.6064 -1.0982 -0.6751 -0.4833 -0.2851 0.1084 0.2998	POJ 2.600 2.594 2.608 2.597 2.597 2.597 2.602 2.602	PTS 1 0.2661 7 p.2661 1 0.2661 1 0.2661 4 0.2661 7 0.2661 7 0.2661 7 0.2661 9 0.2661	9.7692 9.7491 9.7793 9.7592 9.7592 9.7793 9.7793 9.7290 9.7793	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771 0.1839 0.1802 0.1824	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477 0.0477 0.0477	CAF 0.1510 0.1395 0.1459 0.1345 0.1307 0.1332 0.1294 0.1362 0.1324 0.1345	44. 44. 44. 44. 44. 44. 44.
3. 2. 1. 0. 0. -0. -1.	.88 .86 .83 .33 .81 .30 .21 - .72 -	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168 0.0464 0.0751	-1.6064 -1.0982 -0.6751 -0.4833 -0.2881 -0.086 0.1084 0.2998	POJ 2.600 2.594 2.608 2.597 2.597 2.602 2.602 2.589 2.602 2.602	PTS 1	9.7692 9.7491 9.7793 9.7994 9.7592 9.7793 9.7793 9.7290 9.7793 9.7893	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771 0.1839 0.1802 0.1824 0.1770	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477 0.0477 0.0477 0.0477 0.0478	CAF 0.1510 0.1395 0.1459 0.1345 0.1307 0.1332 0.1294 0.1362 0.1324 0.1345 0.1286	44. 44. 44. 44. 44. 44. 44. 44.
3. 2. 1. 0. 0. -0. -1. -1. -2.	.88 .86 .83 .33 .81 .30 .21 - .72 - .24 - .75 -	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168 0.0464 0.0751 0.1031 0.1365 0.2011	-1.6064 -1.0982 -0.6751 -0.4833 -0.2851 -0.0869 0.1084 0.2996 0.4869 0.6688 0.9036 1.3512	POJ 2.600 2.594 2.602 2.608 2.597 2.597 2.602 2.589 2.602 2.602 2.602	PTS 1	9.7692 9.7491 9.7793 9.7994 9.7592 9.7592 9.7793 9.7793 9.7793 9.7893 9.7893	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771 0.1839 0.1802 0.1824 0.1770 0.1828	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477 0.0477 0.0477 0.0479 0.0485 0.0490	CAF 0.1510 0.1395 0.1459 0.1345 0.1332 0.1294 0.1324 0.1324 0.1324 0.1328 0.1286 0.1338	44. 44. 44. 44. 44. 44. 44. 44.
3. 2. 1. 0. 0. -0. -1. -1. -2.	.88 .86 .83 .33 .81 .30 .21 - .72 - .24 - .75 -	CN 0.2352 0.1636 0.1014 0.0726 0.0431 0.0127 0.0168 0.0464 0.0751 0.1031 0.1365	-1.6064 -1.0982 -0.6751 -0.4833 -0.2851 -0.0869 0.1084 0.2998 0.6688 0.9036	POJ 2.600 2.594 2.602 2.608 2.597 2.597 2.602 2.589 2.602 2.602 2.602	PTS 1	9.7692 9.7491 9.7793 9.7994 9.7592 9.7592 9.7793 9.7793 9.7793 9.7893 9.7893	CAT 0.2002 0.1879 0.1939 0.1824 0.1767 0.1869 0.1771 0.1839 0.1802 0.1824 0.1770	CPB 0.0492 0.0485 0.0479 0.0479 0.0477 0.0477 0.0477 0.0477 0.0479 0.0485 0.0490	CAF 0.1510 0.1395 0.1459 0.1345 0.1332 0.1294 0.1324 0.1324 0.1324 0.1328 0.1286 0.1338	44. 44. 44. 44. 44. 44. 44. 44.

MODEL 946.3	CONF	1G000	0	MACH 4.50	0	PHI =	0.	
Q= 3.77 PSI	RE PER	IN.= .48E	06 TO	= 90 <u>.</u> DE	EG.F	POJ/P	15 =	15.
PO= 400.0 CM	HG PTS=	.2661 PS	51		RUN NO	. 02611	69124	
ALPHA CH	CM	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
	-1.5730	3.9242		14.7440				
	-1.0759	3.9081	0.2661					
	-0.6545	3.9322	0.2661					
	-0.4743	3.9322	0.2661	14.7740				
	-0.2838	3.5322	0.2661					
	-0.0745	3.9295	0.2661					
-0.21 -0.0184 -0.73 -0.0480	0.1144 0.3057	3.9376 3.9295	0.2661	14.7950 14.7640				
-1.23 -0.0775	0.505	3.9215	C-2661					
-1.74 -0.1070	0.5010			14.7740				
-2.26 -0.1374	0.8992	3.9349		14.7850				
-3.28 -0.2043	1.3717			14.774C				
-4.30 -0.2743	1.8774		0.2661					
MQDEL 946.3	CONF			MACH 4.50		PHI =	0.	
MQDEL 946.3 Q= 3.77 PSI				MACH 4.50				20.
	RE PER		06 TO		EG.F		rs =	20•
Q= 3.77 PSI	RE PER	IN.= .488	06 TO		EG.F	POJ/P	rs =	20• RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN	RE PER	IN.= .48E .2661 PS POJ	06 TO 51 PTS	≠ 90. DE	EG.F RUN- NO: CAT	POJ/P ² • 001120 CPB	TS = 59101 CAF	RUN
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312	RE PER HG PTS=	IN.= .488 .2661 PS POJ 5.3178	06 TO 51 PTS	= 90. DE POJ/PTS 19.9810	EG.F RUN- NO CAT 0.1778	POJ/P • 001120 CPB 0•0501	TS = 59101 CAF 0.1277	RUN - 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029	RE PER HG PTS= CH -1.5896 -1.0885 -0.7040	IN. = .488 .2661 PS POJ 5.3178 5.3232 5.0423	PTS 0.2661 0.2661 0.2661	= 90. DE POJ/PTS 19.9810	EG.F RUN- NO. CAT 0.1778 0.1686	POJ/P . 001120 CPB 0.0501 0.0495	TS = 59101 CAF 0.1277 0.1190	RUN 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.34 0.1029 1.84 0.0989	RE PER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701	IN. = .488 .2661 PS FOJ 5.3178 5.3232 5.0423 5.3178	PTS 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810	CAT 0.1778 0.1686 0.1729 0.1714	POJ/P - 001126 CPB 0.0501 0.0495 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224	RUN 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.34 0.1029 1.84 0.0989 1.33 0.0686	RE FER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701 -0.4649	IN.= .488 .2661 PS FOJ 5.3178 5.3232 5.0423 5.3178 5.3178	PTS 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 19.9810	CAT 0.1778 0.1686 0.1729 0.1714 0.1691	POJ/P CPB 0.0501 0.0495 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201	RUN 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.34 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398	RE FER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817	FOJ 5.3178 5.3232 5.0423 5.3178 5.3178 5.3178 5.3259	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 19.9810 20.0110	CAT 0.1778 0.1686 0.1729 0.1714 0.1691 0.1669	POJ/P O01120 CPB 0.0501 0.0495 0.0490 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179	RUN 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103	RE FER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 19.9810 20.0110 19.9710	CAT 0.1778 0.1686 0.1714 0.1691 0.1669 0.1691	POJ/P O01126 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179 0.1203	RUN 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.34 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169	RE PER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865 0.0890	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 29.0010 18.9450 19.9810 19.9810 20.0110 19.9710 20.0210	CAT 0.1778 0.1686 0.1714 0.1691 0.1691 0.1729	POJ/P O01126 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0488 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179 0.1203 0.1239	RUN 46. 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.34 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169 -0.72 -0.0480	RE PER HG PTS= CH -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2617 -0.0865 0.0890 0.2954	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285 5.3098	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 20.0110 19.9710 20.0210 19.9510	CAT 0.1778 0.1686 0.1714 0.1691 0.1669 0.1691 0.1729 0.1766	POJ/P O01126 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0488 0.0490 0.0492	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1179 0.1203 0.1239 0.1214	RUN 46. 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169 -0.72 -0.0480 -1.24 -0.0815	RE PER HG PTS= CM -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865 0.0890 0.2954 0.5263	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285 5.3098 5.3178	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 20.0110 19.9710 20.0210 19.9510 19.9810	CAT 0.1778 0.1686 0.1729 0.1714 0.1669 0.1691 0.1729 0.1726 0.1804	POJ/P O01126 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0498 0.0490 0.0492 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1204 0.1179 0.1203 0.1239 0.1214 0.1314	RUN 46. 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169 -0.72 -0.0480 -1.24 -0.0815 -1.75 -0.1095	RE PER HG PTS= CM -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865 0.0890 0.2954 0.5263 0.7048	IN.= .488 .2661 PS POJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285 5.3098 5.3178 5.3071	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 20.0110 19.9710 20.0210 19.9510 19.9810 19.9410	CAT 0.1778 0.1686 0.1729 0.1714 0.1691 0.1669 0.1691 0.1726 0.1736	POJ/P* CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0480 0.0490 0.0490 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179 0.1203 0.1239 0.1234 0.1314	RUN 46. 46. 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169 -0.72 -0.0480 -1.24 -0.0815 -1.75 -0.1095 -2.26 -0.1382	RE PER HG PTS= CM -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865 0.0890 0.2954 0.5263 0.7048 0.8953	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285 5.3178 5.3271 5.3205	PTS 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 20.0110 19.9710 20.0210 19.9510 19.9510 19.9910 19.9910	CAT 0-1778 0-1686 0-1729 0-1714 0-1691 0-1669 0-1729 0-1726 0-1736 0-1736	POJ/P* CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179 0.1239 0.1214 0.1314 0.1314 0.1223	RUN 46. 46. 46. 46. 46. 46. 46. 46. 46.
Q= 3.77 PSI PO= 400.0 CM ALPHA CN 3.89 0.2312 2.86 0.1603 1.84 0.1029 1.84 0.0989 1.33 0.0686 0.81 0.0398 0.30 0.0103 -0.21 -0.0169 -0.72 -0.0480 -1.24 -0.0815 -1.75 -0.1095	RE PER HG PTS= CM -1.5896 -1.0885 -0.7040 -0.6701 -0.4649 -0.2817 -0.0865 0.0890 0.2954 0.5263 0.7048	FOJ 5.3178 5.3232 5.0423 5.3178 5.3259 5.3152 5.3285 5.3098 5.3178 5.3205 5.3152	PTS 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661 0-2661	POJ/PTS 19.9810 20.0010 18.9450 19.9810 20.0110 19.9710 20.0210 19.9510 19.9810 19.9410	CAT 0.1778 0.1686 0.1729 0.1714 0.1691 0.1669 0.1729 0.1726 0.1729 0.1713 0.1681	POJ/P* - 001120 CPB 0.0501.0:0495 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490 0.0490	TS = 59101 CAF 0.1277 0.1190 0.1239 0.1224 0.1201 0.1179 0.1239 0.1214 0.1314 0.1314 0.1246 0.1223 0.1187	RUN 46. 46. 46. 46. 46. 46. 46. 46.

	J.,		UNIX	311461				
MODEL 946.	3 CON	FIG00	00 .	HACH 4.50)	= 1H9	6.	
Q= 3.77 PS	I RE PER	IN.= .48	E06 10	= 90. DE	G.F	POJ/P	rs ×	40.
PO= 400.9	CMHG PTS=	.2661 P	SI		RUN NO.	. 00112	59102	
ALPHA CN	CM	POJ	PTS	POJ/PTS	CAT	CPB	CAF	RUN
3.88 0.2145	-1.4663	10.6010	0.2661	39.8310	0.1796	0.0501	0.1295	47.
2.85 0.1428	-0.9569	10.5880	0.2661	39.7810	0.1901	0.0497	0.1403	47.
1.83 0.0861		10.6040	0.2661	39.8410				
1.32 0.0574	-0.3939	10.6040	0.2661	39.8410	0.1816	0.0488	.0.1327	47.
0.81 0.0271	-0.1940	10.5960	0.2661	39.8110	0.1793	0.0490	0.1303	47.
0.29 -0.0025		10.5960	0.2661	39.8110	0.1815	0.0490	0.1325	47.
-0.22 -0.0320	0.1961	10.5880	0-2661	39.7810	0.1542	0.0488	0.1154	47.
-0.73 -0.0616		10.6090	0.2661	39.8610	0.1966	0.0488	0.1418	47.
-1.24 -0.0927		10.5770	0.2661					
-1.75 -0.1215		10.6040						
-2.27 -0.1541		10.5960	0.2661					
-3.29 -0.2147		10:5900		39.7910				
-4.31 -0.2871		10.5900						
MODEL 946.		FIG00		MACH 4.50		PHI =		
Q= 3.77 PS	I RE PER	IN.= .48	E06 TO	MACH 4.50	G.F	POJ/P	15 = '	70.
	I RE PER	IN.= .48	E06 TO		G.F		15 = '	70.
Q= 3.77 PS	I RE PER	IN.= .48	E06 TO		G.F	POJ/P	15 = '	70. RUN
Q= 3.77 PS PO= 400.0 ALPHA CN	I RE PER CMHG PTS=	IN.= .48	SEO6 TO	90. DE	EG.F RUN-NO: CAT	POJ/P . 001120 CPB	TS = ` 69103 · CAF	` RUN
Q= 3.77 PS PO= 400.0 ALPHA CN	I RE PER CMHG PTS= CM -1.2932	IN.= .48 ,2661 P	EO6 TO SI -PTS	90. DE	EG.F RUN-NO CAT 0.1937	POJ/P . 001120 CPB 0.0501	TS = ` 69103 · CAF 0.1436	` RUN 48•
Q= 3.77 PS PO= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237	I RE PER CMHG PTS= CM -1.2932 -0.8194	IN.= .48 ,2661 P POJ 18.5480	9E06 T0 9SI -PTS 0.2661	90. DE POJ/PTS 69.6910	CAT 0.1937 0.1965	POJ/P . 001120 CPB 0.0501 0.0495	TS =	RUN 48. 48.
Q= 3.77 PS PO= 400.0 ALPHA CN 3.87 0.1914	I RE PER CMHG PTS= CM -1.2932 -0.8194 -0.4319	IN.= .48 ,2661 P POJ 18.5480 18.5620	PTS 0.2661 0.2661	90. DE POJ/PTS 69.6910 69.7420	CAT 0.1937 0.1965 0.1949	POJ/P . 001120 . CPB 0.0501 0.0495 0.0492	TS = 69103 · CAF 0.1436 0.1470 0.1457	RUN 48. 48. 48.
Q= 3.77 PS PO= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655	I RE PER CMHG PTS= CM -1.2932 -0.8194 -0.4319 -0.2371	IN.= .48 .2661 P POJ 18.5480 18.5620 18.5590	PTS 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7310 69.7420	CAT 0.1937 0.1965 0.1949 0.1865	POJ/P . 001120 CPB 0.0501 0.0495 0.0492 0.0490	TS =	RUN 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359	I RE PER CMHG PTS= CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.5620	PTS 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7310 69.7420 69.7720	CAT 0.1937 0.1965 0.1949 0.1865 0.1798	POJ/P . 001120 CPB 0.0501 0.0495 0.0492 0.0490 0.0490	TS = 69103 CAF 0.1436 0.1470 0.1457 0.1375	RUN 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072	I RE PER CMHG PTS= CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.5620 18.5750	PTS 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7310 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1798 0.1911	POJ/P . 001120 CP8 0.0501 0.0495 0.0492 0.0490 0.0490	TS = 69103 CAF 0.1436 0.1470 0.1457 0.1375 0.1308 0.1421	RUN 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216	I RE PER CMHG PTS= CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.5620 18.5750 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1798 0.1911	POJ/P . 00112 CPB 0.0501 0.0495 0.0492 0.0490 0.0490 0.0490	TS = 69103 CAF 0.1436 0.1470 0.1375 0.1378 0.1421 0.1363	RUN 48. 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216 -0.23 -0.0543	I RE PER CMHG PTS = CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594 0.5267	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.55750 18.5620 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1798 0.1911 0.1873 0.1910	POJ/P . 00112 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0490 0.0488	TS = 69103 CAF 0.1436 0.1470 0.1375 0.1375 0.1308 0.1421 0.1363 0.1422	RUN 48. 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216 -0.23 -0.0543 -0.73 -0.0807 -1.25 -0.1079	I RE PER CMHG PTS = CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594 0.5267 0.6954	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.5620 18.5620 18.5620 18.5620 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1949 0.1845 0.1911 0.1873 0.1910 0.1888	POJ/P O0112 CPB 0.0501 0.0495 0.0492 0.0490 0.0490 0.0498 0.0488	TS = 69103 CAF 0.1436 0.1477 0.1375 0.1378 0.1421 0.1363 0.1422 0.1402	RUN 48. 48. 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216 -0.23 -0.0543 -0.73 -0.0807	I RE PER CMHG PTS = CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594 0.5267 0.6954 0.9279	IN.= .48 ,2661 P POJ 18.5480 18.5620 18.5590 18.5520 18.5620 18.5620 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1911 0.1873 0.1910 0.1888 0.1895	POJ/P O0112 CPB 0.0501 0.0495 0.0490 0.0490 0.0490 0.0498 0.0486 0.0486	TS = 69103 CAF 0.1436 0.1470 0.1375 0.1375 0.1363 0.1421 0.1363 0.1422 0.1402	RUN 48. 48. 48. 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0= 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216 -0.23 -0.0543 -0.73 -0.0807 -1.25 -0.1079 -1.76 -0.1414	I RE PER CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594 0.5267 0.6954 0.9279 1.1039	IN.= .48 ,2661 P POJ 18.5480 18.5520 18.5520 18.5620 18.5620 18.5620 18.5620 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1798 0.1911 0.1873 0.1918 0.1918 0.1932	POJ/P* CPB 0.0501 0.0495 0.0492 0.0490 0.0490 0.0490 0.04986 0.0486	TS = 69103 CAF 0.1436 0.1470 0.1457 0.1375 0.1308 0.1421 0.1460 0.1409 0.1446	RUN 48. 48. 48. 48. 48. 48. 48. 48. 48.
Q= 3.77 PS P0 400.0 ALPHA CN 3.87 0.1914 2.84 0.1237 1.82 0.0655 1.31 0.0359 0.80 0.0072 0.29 -0.0216 -0.23 -0.0543 -0.73 -0.0807 -1.25 -0.1079 -1.76 -0.1414 -2.27 -0.1685	CMHG PTS= CM -1.2932 -0.8194 -0.4319 -0.2371 -0.0517 0.1367 0.3594 0.5267 0.6954 0.9279 1.1039 1.5369	IN.= .48 .2661 P POJ 18.5480 18.5620 18.5590 18.5620 18.5620 18.5620 18.5620 18.5620 18.5620	PTS 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661 0.2661	POJ/PTS 69.6910 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420 69.7420	CAT 0.1937 0.1965 0.1949 0.1865 0.1798 0.1911 0.1873 0.1918 0.1885 0.1932 0.1840	POJ/P CPB 0.0501 0.0495 0.0492 0.0490 0.0490 0.0496 0.0486 0.0486 0.0486	TS = 69103 CAF 0.1436 0.1470 0.1457 0.1375 0.1308 0.1421 0.1363 0.1422 0.1409 0.1446	RUN 48. 48. 48. 48. 48. 48. 48. 48. 48. 48.

HODEL 946.3	CONFIG0	000 MACH 4.5	PHI =	0.
Q= 3.77 PSI	RE PER IN. = .4	8E06 TC= 90. D	EG.F POJ/P1	S = 100 ₂
P0= 400.0 C	HHG PTS= .2661 1	PSI	RUN NO. 001126	9104
ALPHA CN	CK POJ	PTS POJ/PTS	CAT CPB	CAF RUN
3.86 0.1755	-1.1796 26.5330	0.2661 99.6920	0.1955 0.0501	0.1455 49.
2.84 0.1070	-0.6977 26.5380	0.2661 99.7130	0.1984 0.0494	0.1490 49.
1.81 0.0472	-0.3008 26.5330	0.2661 99.6920	0.1893 0.0492	0.1401 49.
1.30 0.0192	-0.1223 26.5220	0.2661 99.6520	0.1946 0.0492	0.1454 49.
0.80 -0.0088	0.0596 26.5380		0.1938 0.0490	
	0.2777 26.5330		0.1914 0.0490	
-0.23 -0.0679	0.4497 26.5220		0.1907 0.0490	
-0.74 -0.0966	0.6333 26.5360		0.1854 0.0486	
-1.26 -0.1246	0.8118 26.5330		0.1908 0.0488	
-1.77 -0.1549	1.0136 26.5170		0.1870 0.0485	
	1.1972 26.5380		0.1937 0.0486	
	1.6319 26.5360		0.1905 0.0488	
-4.32 -0.3198.	2.1770 26.5360	0.2661 99.7030	0.1931 0.0490	0.1441 49.
MODEL 946.3	CONFIGO	000 HACH 1.7	5 PHI =	0.
Q= 8.21 PSI	RE PER IN. = .48	BE06 T0≖ 9G• DI	G.F POJ/P1	'S = •
P0= 106.0 C	MHG PTS= 3.8308 I	PSI	RUN NO. 024116	9101
ALPHA CN	CH POJ	PTS POJ/PTS	CAT CPB	CAF RUN
-0.02 -0.0230	0.1779 38.1790	3.8308 9.9663	0.0045 0.4666-	0.4621 50.
-0.03 -0.0401	0.3090 57.2400		0.0048 0.4666-	
-0.04 -0.0572	0.4395 76.4140		0.0037 0.4666-	- · · · - - -
-0.09 -0.1257	0.9637 152.8300		0.0042 0.4666-	
-0.16 -0.2281	1.7467 267.3900		0.0045 0.4666-	
-0.18 -0.2631	2.0126 305.6600	· · · · · · · · · · · · · · · ·	0.0045 0.4666-	

HODEL 0// 3	courte on	00 84611 2 00	PHI =	0.
MODEL 946.3	CONFIG00	00 MACH 2.00	rn: 4	U •
Q= 8.13 PSI	RE PER IN. = .48	E06 TO= 90. DE	G.F POJ/PT	S≠ •
PO= 118.0 C	HHG PTS= 2.9016 P	12	RUN NO. 024116	9201
ALPHA CN	CM POJ	PTS PQJ/PTS	CAT CPB	CAF RUN
-0.01 -0.0158	0.1246 28.6910	2.9016 9.6878	0.0065 0.2115-	0-2050 51.
-0.02 -0.0287	0.2224 43.2920		0.0053 0.1964-	
-0.03 -0.0416	0.3216 57.9210		0.0056 0.1571-	
-0.06 -0.0939	0.7217 115.5600		0.0057 0.1462-	
	1.3297 202.4600			
-0.17 -0.2526	1.9347 289.3200			
MODEL 946.3	CONFIG00	00 MACH 2.50	PHI =	0.
Q= 7.39 PS1	RE PER IN. = .48	E06 TO= 90. DE	G.F POJ/PT	S = .
PO= 150.0 C	HHG PTS= 1.6893 P	S 1	RUN NO. 024116	9301
ALPHA CN	CM POJ	PTS POJ/PTS	CAT CPB	CAF RUN
-0.01 -0.0105	0.0839 16.8450	1.6893 9.9720	0.0055-0.0857	0.0912 52.
-0.01 -0.0194	0.1525 25.2540		0.0072-0.0861	
-0.02 -0.0271	0.2106 33.6620	1.6893 19.9270	0.0073-0.0872	0.0945 52.
-0.04 -0.0607	0.4689 67.4090	1.6893 39.9050	0.0064-0.0885	0.0948 52.
-0.07 -0.1109	9.8530 117.7200	1.6893 69.6860	0.0072-0.0892	0,0964 52.
-0.10 -0.1615	1.2403 168.5700	1.6893 99.7870	0.0065-0.0901	0.0966 52.

H	ODEL 946.3	CON	FIG00	QO	MACH 3.00)	PHI =	0.	
Q	= 6.34 PSI	RE PER	IN.= .48	E06 T0	= 90. DE	G.F	POJ/P1	'S =	•
P	0= 192.0 C	MHG PŢS=	1.0058 P	SI		RUN NO.	024116	9401	
ALPH	A CN	CM	POJ	PTS	POJ/PYS	CAT	СРВ	CAF	RUN
-0.	-0.0066	0.0497	10.0820	1.0058	10.0240	0.0001-	0.6152	0.6153	5à.
-0.0	1 -0.0123	0.0934	15.0330	1.0058	14,9470	0.0011-	0.6288	0.6299	53.
	1 -0.0184		20.1300		20.0150	0.0003-	0.5985	0.5988	53.
-0.0	2 -0.0411	0.3135	40.0460	1.0058	39.8170	0.0007-	0.6288	0.6295	53.
-0.0	4 -0.0765				69.7440	0.0013-	0.6460	0.6473	53.
	6 -0.1129								
н	ODEL 946.3	CON	rigco	00	MACH 3.50		PHI =	0.	
Q	= 5.43 PSI	RE PER	IN.= .48	EÓ6 TO	= 90. DE	G.F	POJ/PT	'S =	•
P	0= 251.0 C	MHG PTS=	.6329 P	SI		ŔĽN NO.	024116	9501	
ALPK	A CN	CM	POJ .	PTS	POJ/PTS	CAT	CPB	CAF	RUN
-0.	-0.0055	0.0428	6.3183	0.6329	9.9835	0.00C1-	0.4387	0.4388	54.
-0.	-0.0099		9.5057						
-0.0	1 -0.0138	0.1045	12.6480	0.6329	19.9850	0.0002-	0.4304	0.4305	54.
-0.0	1 -0.0303	0.2304	25.1940	0.6329	39.8090	0.0005-	0.4449	0.4454	54.
-0.0	3 -0.0557	0.4255	44.1490	0.6329	69.7600	0.0010-	0.4369	0.4379	54.
-0.0	4 -0.0816	0.6231	63.1940	0.6329	99.8530	0.0014-	0.4287	0.4301	54.

HO	DEL 946.3	CON	FIG00	00	MACH 4.00	3	PHI ≖	0.		
Q=	4.54 PSI	RE PER	IN.= .48	E06 T0	= 9ō• D8	G.F	POJ/P1	= 21	•	
PC	= 320.0 CM	HG PTS=	.4957 P	SI		RUN NO.	024136	59601		
ALPHA	CN	CH	POJ	PTS	POJ/PTS	CAT	СРВ	CAF		RUN
-0.	-0.0046	0.0352	4.0557	0.4057	9.9961	0.0001-	0.3029	0.3030		55.
-0.	-0.0073	0.0556	6.0754	0.4057	14.9740	0.0001-	0.2867	G-2868		55.
-0.	-0.0113	0.0877	8.1005	0.4057	19.9660	0.0902-	0.3044	0.3046		55.
-0.01	-0.0238	0.1816	16.1410	0.4057	39.7840	G-0004~	0.3280	0.3284		55.
-0.02	-0.0437	0.3339	28.3350	0.4057	69.8390	0.0007~	0.3096	0.3103		55.
	-0.0629	C-4803	40.4370							55.
MŌ	DEL 946.3	CON	FIG00	00	MACH 4.50		PHI =	0.		
Q=	3.77 PSI	RE PER	ÎN.= .48	E06 T0	≖ 90. DE	G.F	POJ/P1	rs 💌	•	
PO	= 400.0 CM	HG PTS=	.2661 P	SI		RUN NO.	024116	9701		
ALPHA	CN	CM	POJ	PTS	POJ/PTS	CAT	СРВ	CAF		RUN
-0.	-0.0032	0.0240	2.6562	0.2661	9.9803	0.0001-	0.2194	0.2195		5ê.
-0.	-0.0064	0.0489	3.9911	0.2661	14.9960	0.0001-	0.2120	0.2121		56.
-0.	-0.0087		5.3098	0.2661		-				56.
	-0.0191		19.5930		39.8010	-				56.
	-0.0349		18.5320							56.
								.,		

UNCLASSIFIED

Security Classification			
	TROL DATA - R		
(Security cleasification of title, body of obstract and indexing the control of t	annotation must be e		oversil report is classified). ECURITY CLASSIFICATION
Advanced Systems Laboratory			
Research and Engineering Directorate		UNCIA	asified
U. S. Army Missile Command Redstone Arsenal, Alabama 35809		NA	
Regione Arsenai, Alabama 55009		<u> </u>	
e narva: Hill			
EXPERIMENTAL INVESTIGATION OF REAC	CTION JETS ON	A BODY	OF REVOLUTION
WITH AND WITHOUT FINS IN SUPERSONIC			
	~~~		
4. DESCRIPTIVE NOTES (Type of report and inclusive detes)			
Technical Memorandum  5- AUTHOR(5) (First name, middle initial, last name)		<del></del>	
Troy A. Street			
S. REPORT DATE	7e. TOTAL NO. O	r DAGES	78. NO. OF REFS
		FFAGES	0
May 1970	311		1
- CONTINUE OF BURNINGS	ME ORIGINATOR'S	- REPURT NUM	DER(J)
A DECIFICANO AMAN ADRIGADO A COM			
A. PROJECT NO. (DA) 1M2623XXA206	RD-TM-7	′0~3	
AMC Management Structure Code No.	65 621:22 222	7 NOIS 44	
522C.11.148	this report)	TT NO(3) (ALNY O	thet numbers that may be sestimed
	AD	_	
10. DISTRIBUTION STATEMENT			<del></del>
This document is subject to special export co	introle and acc	h tranomit	tal to foreign
•	•		_
governments or foreign nationals may be made	ae omy with pr	ior approva	at of this Command,
ATTN: AMSMI-RD	1		
III SUFFERMENTANT NOTES	12. SPONSORING N	HLITARY ACTI	AIII
None	Dama 57	. 1	
None	Same as N	U ₄ I	
13. ABSTRACT			
An experimental investigation of a so	nic, underexpa	nded, trans	sverse jet ejecting
from a body of revolution into free streams of	of Mach number	range 1.7	5 to 4.5 has-been
conducted. The jet was rolled, in 15-degree		-	
of attack range of -4 to +10 degrees with a je	•	_	•
variations up to 100. Forces and moments w			<del>-</del>
	ere measured	and the tall	ouzateu uata ale
presented in the appendices.			
		المراجع والمراجع والمراجع	
DD PORM 1473 REPLACES DO FORM 1473, 1 JAN 44,	WHICH IS		
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		TINC	LASSIFIED

UNCLASSIFIED
Security Classification

305

# UNCLASSIFIED Security Classification

Security Classification						<u> </u>
34.	LIH	KA	LIN	X B	LIN	K C
KEY WORDS	ROLE	WT	ROLE	· WT	RGLE	WT
	1					
Transverse jet	l	i	ł .			
Tansverse jet	1	}	<b>i</b> .	}		
- Body of revolution	1		ļ			١.
Free stream	1	l	ì	l	1	] [
Mach number range 1.75 to 4.5	1	1		]		ì
Angle of attack	1	1	ļ	Ì	1	}
	1	-	1	].		
	1	]	İ	}		1
	}	l	1	ļ		
	1	•	[	ſ		
	1	1	į	ł		
•	1	İ	1	}	· ]	
			1	ļ	1	1
·	1	İ	ļ	[		l
	}	1	l		]	ŀ
		<b>!</b>	<u> </u>			I
	1	1	I	1		Ī
,	1	l ł	İ	l	]	
	1	]	l	l		l
	1	1	l	l		
		ĺ	•	l	1 :	· ·
	j	]	<b>j</b> .	ĺ		
			ļ			
	1	l			1	
	1	<u> </u>			]	ļ
	}	1	İ			
	1	1	!			
	)	ľ				
			1		Į į	
•	1				1	
•	1	1				
				i.		
	İ	j	<b>i</b>			-
		l			1 1	
	1	1			}	
	1	l			<b>i</b> . I	
	1	1				
	1	}				
	]	ļ			]	
		•				
	1	Ì			! I	
					}	
	1		l i		( i	
	}				i 1	
					[ [	
	1				į l	
					)	
			,			
	1				1	
	j j		ļ		]	
					[ {	
					}	
					l l	

UNCLASSIFIED
Security Classification

306